



Freq
[FFT]

strt: 0 Hz
Stop: 6.4 kHz

Resoltn: 400 lines

Date: 10-45-91 Time: 08:46:00 PM

Config 1

A: Freq Resp


X: 768

Hz

Y: 152.157

↳ Female on Bottom

↳ Accur. @ Center



Config 1 Final

Start: 0 Hz
Stop: 6.4 kHz

Resoltn: 400 lines


10-45-91 Time: 08:55:00 PM

Config 1

↳ made on bottom

↳ No spacers

↳ 2 bolts
only



★

Freq
[FFT]

Strt: 0 Hz
Stop: 6.4 kHz

Resoltn: 400 lines

Date: 10-45-91 Time: 08:48:00 PM

A: Freq Resp


X: 864

Hz

Y: 79.8075

LinMag

/div



Config 2

↳ Female on Bottom

↳ Auer & Center


Config 2 Final

Strt: 0 Hz
Stop: 6.4 kHz
e: 10-45-91 Time: 08:58:00 PM

Resoltn: 400 lines

Config 2

↳ male on bottom
↳ no spacers
↳ 2 bolts only



↳ 848

Loc1/HP-IB 35665 Adrs: 11

Prnt Adrs: 4

Plot Adrs: 5

Disk Adrs: 5

Date: 10-45-91 Time: 08:17:00 PM

Weldes Config

A: Freq Resp

X: 7.16


kHz

Y: 6.77172

↳ accelerometer
@ center

↳ w/ tabs

LinMag


800
e-3
/div

Weldes Test

1/HP-IB 35665 Adrs: 11
Prnt Adrs: 4
Date: 10-45-91 Time: 08:14:00 PM

Plot Adrs: 5
Disk Adrs: 5

Wendes Config



↳ accelerometer
@ center

↳ w/ tabs

Strt: 1 kHz
Stop: 13.8 kHz
Date: 10-45-91 Time: 08:09:00 PM

Resoltn: 400 lines

We Werdes Config

↳ Accelerometer
@ center

↳ w/ Tabs.

