Form 1: Product Number Accountability

1. Part Number QM_X_123456	2. Part Name WING_MIR_REENF	3. Serial Number Run 3, Bin 17	4. FAI Report Number QIF 1
5. Part Revision Level 1.02	6.Drawing Number #1	7. Drawing revision level	8. Additional Changes none
9. Manufacturing Process Reference	10. Organization Name Origin International	11. Supplier Code North_Fab	12. P.O. Number PO123456
13. Detail FAI ☑	14. Full FAI ☑ Partial FAI □	Baseline Part Number including revision number	
Assembly FAI □	Reason for Partial FAI:		
a) if above part number is a cb) if above part number is an			
INDEX of part numbers or sub-assembly numbers required to make the assembly noted above.			
15. Part Number	16. Part Name	17. Part Serial Number	18. FAI Report Number
		 	+
		 	1
		_	
1) Signature dicates that all documented for disposition		ted for; meet drawing require	ments or are properly
2) Also indicate if the FAI is complete per Section 5.4: ☐ FAI Complete ☐ FAI Not Complete			
19. Signature			22. Date
21. Reviewed By			22. Date
23. Customer Approval			24. Date