

- 1. Connect CS20 to PC USB interface.
- 2. Get into 1.burn file, and double click to open SYCS30Tools.exe.
- 3. As shown in the below figure,
 - Click the search button 1 and 2,
 - Get into the 2. Paraments file, choose test_320.pb and test_640.pb,
 - Click the burn button 3, wait burning success
 Then click the burn button 4, wait burning success
 - After show all burning success, click the read button.



- 4. After the internal parameters are burned, the steps for burning the firmware (people counting firmware) are as follows:
 - (1) When user open this tool in the first time, double-click setup.exe of 3.0 firmware burning tool folder (to install the burning driver).
 - (2) Double click the commonBurnerAP v1.0.19.exe as the below figure
 - (3) Click the Browse button, Choose the .src file , Click the burning button , finish the firmware burning



5. After the prompt of successful burning firmware, use the people counting tool according to the people counting documentation