CMPE 491, CMPE/ENEE 691 Hardware Security Spring 2023

University of Maryland Baltimore County Tutorial: Setting Up Synopsys Tools

- 1. Login to **cadence2.cs.umbc.edu** (make sure you are on the UMBC VPN for a reliable connection).
- 2. Type "bash" to enter into the Bash Shell.
- 3. To run TetraMax (Test Pattern Generator), run the following command:
 - I. source /umbc/software/scripts/env_synopsys_txs.sh
 - II. Then, type "tmax"
- 4. To run **Design_vision** (Synthesis Tool), run the following command:
 - I. source /umbc/software/scripts/env_synopsys_dc.sh
 - II. Then, type "design_vision"
- 5. To run **HSpice and Wave Viewer (Transistor Level Simulator)**, run the following command:
 - I. source /umbc/software/scripts/env_synopsys_hspice.sh
 - II. Then, type "hspice" or "wv"
- 6. To run VCS (RTL/Gate-Level/Digital Simulator), run the following command:
 - I. source /umbc/software/scripts/env_synopsys_vcs.sh
 - II. Then, type "vcs"