

MISCELLANEOUS INVOICE

Tax Invoice

Issued 03/04/2017 on behalf of:

The Owners - SP 13385 ABN 38890236706

Keppelgate

37 Paul Street

BONDI JUNCTION NSW 2022

for Lot 36 Unit 36

Jonathon Samuel Kresner

Mr J S Kresner Keppelgate Unit 36/37 Paul Street **BONDI JUNCTION NSW 2022**

Lot 36: Level 8 repair jammed chute loading hopper

GST

Total

12.80

140.80

Amount Payable:

\$12.80

Contact your participating financial institution to make a BPAY payment from your cheque or savings account. Enter the biller code and your DEFT reference number. To use the QR code, use the reader within your

\$140.80

Cheques should be made payable to 'The Owners - SP 13385'



*Registration is required for payments from cheque or savings accounts. Please complete a registration form available at www.deft.com.au or call 1800 672 162. You do not need to re-register for the internet service if already registered for phone payment. Registration is not required for credit card payments.

Mr J S Kresner

Strata Plan 13385 Lot 36

Unit 36



*442 217636778 000033528



Biller code 96503





Pay over the Internet by DEFT Online from your *pre-registered bank account at www.deft.com.au



Pay by DEFT Phonepay from your *pre-registered bank account. Call 1300 301 090 or International +612 8232 7395



Credit card payments can be made over the Internet. Log onto www.deft.com.au or call 1300 301 090 and follow the instructions. A surcharge will be applicable if you use this option.



Pay by mailing this payment slip with your cheque to:

DEFT Payment Systems GPO Box 4690, Sydney NSW 2001



Pay in person at any post office by O POST cash, cheque or Eftpos

Payments made at Australia Post will incur a \$2.75 DEFT processing fee.

mobile banking app. More info: www.bpay.com.au O'Neill Strata Management Pty Ltd

DEFT Reference No.

217636778 000033528

Amount Due

\$140.80

Due Date

3/04/2017

Amount Paid

\$

Ryburn Industries Pty. Ltd.

UNIT 31/36 RALPH STREET, ALEXANDRIA NSW 2015 TEL (02) 8338 9100 FAX (02) 8338 9500

WASTE DISPOSAL & GARBAGE HANDLING EQUIPMENT "SANISTREL" - "DISPOSAPAD" - "IMPERIAL" - "RYBURN" - "KOHLMAN*HILL"



Strata Plan 13385 C/- O'Neill Strata Management P/L PO Box 887 BONDI JUNCTION NSW 1355

TAX INVOICE #: 00025522

Delivered to:

Strata Plan 13385 Keppelgate 37 Paul Street **BONDI JUNCTION**

ORDER NO.			TERMS		DATE	PG
Contract + 041065			Nett 30 Days		24/02/2017	7 1
QTY.		DESCRIPTION		Unit Price	EXTENDED	CODI
1	Service Contract (PAID) Additional Labour (1 Man)			\$128.00	\$128.00	GST GST
	ATTENTION! Please note equipment problems and/or recommendations listed on Work Report Sheet attached to this Invoice.					
	Strata Plan: 13385 A/C Code: 163400 A/C Name: 163400			M. Alkinson		
	Approarbage compactor maintenance as per service report attached Data Papitional charges are explained thereon Payment Ref:37.5					
ACCOUNT DETAILS FOR EFT National Australia Bank Ryburn Industries Pty Ltd BSB: 082 302 A/C #: 52562-2339		GST \$12.80	SALE AMOUNT \$128.00	SALE AMOUNT GST TOTAL	\$128.00 \$12.80 \$140.80	
		Customer ABN:		BALANCE DUE	\$140.80	

Ryburn Industries Pty Ltd ABN 71 000 621 241

SERVICE REPORT

Strata Plan 13385 Keppelgate 37 Paul St Bondi

Type of Compactor:

L5

No. of Compactors:

1

PREVENTATIVE MAINTENANCE ON 'L' SERIES CAROUSEL GARBAGE COMPACTOR(S)

On February 15th, 2017 Ryburn attended site and a comprehensive service program was carried out on your garbage compactor(s) in accordance with our published Schedule of Works. Please do not hesitate to contact our office should you require a full list of those Ryburn maintenance procedures.

Additional Work Carried Out:

- Found that Builders accessing a power point in the room had accidentally knocked over a milk crate and broom stick which had jammed between the wall & the compactor carousel preventing it from rotating.
- Cleared obstruction and removed accumulated waste from garbage chute.
- Completed full Preventative Maintenance Program.

*NOTE: OUR TECHNICIAN FOUND LARGE PIECES OF TIMBER & BROKEN KITCHEN CABINETS (OR SIMILAR) IN THE BINS AND CHUTE.

> HE ALSO FOUND A LOT OF EVIDENCE OF VERMIN AND WE STRONGLY RECOMMEND USE OF A PEST CONTROL SERVICE.

20/02/17

- Site attendance to repair jammed chute loading hopper on Level 8.
- Also removed accumulated build up from behind hinges.
- Checked all other feed door & frame assemblies for correct operation.

THIS WAS OUR EIGHTH SERVICE ATTENDANCE AS PART OF THE CURRENT THREE YEAR CONTRACT AGREEMENT. THE NEXT PREVENTATIVE MAINTENANCE IS SCHEDULED FOR JUNE, 2017.