 Choosing Analyses ADE L (2) 					
Analysis	○ tran	● d: 1	⊚ ac	o noise	
	⊘ xf	sens	dcmatch	acmatch	
	stb	○ pz	○ sp	envlp	
	pss	pac	pstb	pnoise	
	o pxf	psp	o qpss	O qpac	
	qpnoise	qpxf	o qpsp	O hb	
	hbac	hbnoise	hbsp		
		DC Analys	sis		
Save DC Operating Point					
Hysteresis S	_				
Sweep Var	riable				
Tomnor	aturo				
Temperature ✓ Design Variable Variable Name VDS 3					
	nent Paramet	er	Select Desig	n Variable	5
Model F				,	
					\Box
Sweep Rar	nge				
Start-St	top _c	Y-04			٦l
Center-		Statt 0	4 Stop	1.8 5	4
Sweep Typ	ne				
Automatic					
Add Specific	c Points 🔛				
Enabled 👱				Options	
	<u>o</u> k	<u>6</u> Cancel	Defaults	Apply <u>H</u> e	elp)