
Create Label
Mode
Manual
Auto
1
Label (Pattern)
vdd gnd A Z
Label Layer/Purpose
Use current entry layer
Use same layer as shape, select purpose
drawing
Auto (Using stampLabelLayers section from technology file)
Select layer
ref drawing
Label Options
Font
stick
Height
0.3
2
Justification
centerCenter
Drafting
Attach
Overbar
Expand
Keep Label
Scan Line
Label Selected Objects
Auto Zoom Out
Auto Step
Step
Custom
X
0
Y
0
Snap Mode
orthogonal
Rotate
Sideways
Upside Down
Hide
3
Cancel
Help


4
pmos2v
0.44/0.18
6
7
nmos2v
0.22/0.18
5