

MERIDIAN ENGINEERING

SAFETY INSPECTION REPORT

Report SI-2048

Riverside Warehouse

Inspection date: 2026-08-12

Page 1 of 3

Scope

Quarterly inspection of loading bays and fire exits.

MERIDIAN ENGINEERING

SAFETY INSPECTION REPORT

Report SI-2048

Riverside Warehouse

Page 2 of 3

Findings

Bay 2 guard rail requires repainting.

All fire exits were unobstructed.

MERIDIAN ENGINEERING

SAFETY INSPECTION REPORT

Report SI-2048

Riverside Warehouse

Page 3 of 3

Sign-off

Inspector: Morgan Lee

Next inspection: 2026-11-12