



Joint angle: hip_flexion_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Time (s)

Joint angle: hip_adduction_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Joint angle: hip_rotation_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Joint angle: knee_angle_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle



IK correction




Joint angle: ankle_angle_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle



IK correction




Joint angle: subtalar_angle_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Joint angle: mtp_angle_r (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle



IK correction



0

50

100


150

200


Time (s)

Joint angle: hip_flexion_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Joint angle: hip_adduction_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Joint angle: hip_rotation_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Time (s)

Joint angle: knee_angle_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle




IK correction




Time (s)

Joint angle: ankle_angle_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle



IK correction



0

50

100


150

200


Time (s)

Joint angle: subtalar_angle_l (S003_marker_newton_treadmill_overground)


Warm-start angle



Solved angle



IK correction




Joint angle: mtp_angle_l (S003_marker_newton_treadmill_overground)

Warm-start angle



Solved angle



IK correction

