

Body Shop Report **Victor Ford**

Complete On: 7/16/2024

Report Created By:

Joe Lohr

224-358-6930

jlohr@autorisknow.com

Electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

adas