

OSHA Report City Volkswagen of Evanston

Complete On: 8/23/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

The fire extinguishers have not had their annual inspection and are not properly identified and fully charged.

Date of occurrence: August 23, 2024

Found this outdated inspection in temporary showroom



Fire Extinguisher missing or not properly mounted in dispensing area

Date of occurrence: August 23, 2024

Found extinguishers not mounted



Used Batteries not stored on acid resistant matts

Date of occurrence: August 23, 2024

need to install acid resistant mat under used battery racks



Batteries not being stored properly

Date of occurrence: August 23, 2024

found loose batteries around service



There is not clear access of at least 36" to all electrical panels.

Date of occurrence: August 23, 2024

Found items around breaker panels



There are other miscellaneous electrical issues to note.

Date of occurrence: August 23, 2024

Found a couple outlet boxes pulled off wall



Electrical Plugs Outlets not properly covered. Plate cover missing or broke

Date of occurrence: August 23, 2024


found covers missing or damaged



The fire extinguisher signs above the unit are not posted properly.

Date of occurrence: August 23, 2024

Jim will add these today



The first aid kit is not properly stocked given the dealership work environment.

Date of occurrence: August 23, 2024

Upstairs service first aid kit could use more inventory



All hoses and cutting tips for the welder / cutting torches are not in good condition without any cracks or breaks.

Date of occurrence: August 23, 2024

gauge cover missing on Oxy Acetylene gauges



There is no proper spacing on grinders; Tool rest 1/8" from grinding wheel. Tongue plate 1/4" from grinding wheel.