

OSHA Report City Chevrolet of Grayslake

Complete On: 8/20/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

All secondary containers filled with chemicals are not properly labeled.

Date of occurrence: August 20, 2024

Found a few spray bottles not labeled with contents



The eye wash equipment is not readily accessible.

Date of occurrence: August 20, 2024

detail area eye wash is blocked



The eye wash container water supply has not been changed out properly based on manufacturer recommendations per solution used.

Date of occurrence: August 20, 2024

needs a new replacement bottle



The extinguishers are not mounted properly. (36"-60")

Date of occurrence: August 20, 2024

Extinguisher in compressor room needs mounting and signage



The fire extinguisher signs above the unit are not posted properly.

Date of occurrence: August 20, 2024

needs signage above unit in service



All hoses and cutting tips for the welder / cutting torches are not in good condition without any cracks or breaks.

Date of occurrence: August 20, 2024

found damaged gauge / valve assembly on torches



All flammable materials (oily shop rags) are not properly stored.

Date of occurrence: August 20, 2024


found oily shop rag on floor near oil storage.



Hoists are not being maintained within mfg. specs, and inspected and serviced AND documented under the mfg. suggested frequency. Usually annually.

Date of occurrence: August 20, 2024

Hoists inspection is overdue. 2019



There is no proper spacing on grinders; Tool rest 1/8” from grinding wheel. Tongue plate 1/4” from grinding wheel.

Date of occurrence: August 20, 2024

need tool rest adjustment and eye shield on grinders



Air compressors are not marked with Automatic on/off signage.

Date of occurrence: August 20, 2024


need sign alerting of automatic start / stop



All vacant holes are not properly sealed off on electrical panel box.

Date of occurrence: August 20, 2024

need to seal off vacant hole. electric closet off parts dept.



All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Date of occurrence: August 20, 2024

found electric cords with damage, 1. extension cord detail, 2 large fan cord service, 3. garage door cord service



The fluorescent tubes are not stored properly.

Date of occurrence: August 20, 2024

need to store properly



There are other miscellaneous electrical issues to note.

Date of occurrence: August 20, 2024


found these exposed wires above alignment rack



Miscellaneous issues.

Date of occurrence: August 20, 2024

sinkhole in parking lot outside tire storage needs tarp to prevent water collection sign needs mounting



Ladders not stored properly, needs chained off on any ladder over 8 ft.

Date of occurrence: August 20, 2024

ladders are supposed to have a safety chain when stored against wall



Fire Extinguisher missing or not properly mounted in dispensing area

Date of occurrence: August 20, 2024


needs to be mounted



Electrical Plugs Outlets not properly covered. Plate cover missing or broke

Date of occurrence: August 20, 2024

junction box in electrical room missing cover plate cover missing on outlet in wash area off service. plate cover damaged



Electrical Plugs Outlets not properly covered. Plate cover missing or broke

Date of occurrence: August 20, 2024

found damaged outlet near alignment rack



Used batteries are not being stored in acid resistance leak proof containers and or on mat.

Date of occurrence: August 20, 2024

Need acid resistant mat under used batteries. Found loose used batteries on service floor

