

OSHA Report City Chrysler Dodge Jeep Ram Fiat of Brookfield

Complete On: 8/22/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

All secondary containers filled with chemicals are not properly labeled.

Date of occurrence: August 22, 2024

Found a couple of secondary containers without labels



Batteries not being stored properly

Date of occurrence: August 22, 2024

Found loose batteries in shop floor area



There is no proper spacing on grinders; Tool rest 1/8" from grinding wheel. Tongue plate 1/4" from grinding wheel.

Date of occurrence: August 22, 2024

Tounge plates are missing from grinder. Noticed new grinder that has not been installed yet.



There is not clear access of at least 36” to all electrical panels.

Date of occurrence: August 22, 2024

found equipment blocking electrical panels



Ladders not stored properly, needs chained off on any ladder over 8 ft.

Date of occurrence: August 22, 2024


found 1 ladder unchained



The fluorescent tubes are not stored properly.

Date of occurrence: August 22, 2024

Found Fluorescent lights unboxed



Storage Containers not capped and or sealed properly

Date of occurrence: August 22, 2024

found this storage drum uncapped and collecting water also some used fuel tanks



Miscellaneous issues.

Date of occurrence: August 22, 2024

used tires sitting outside should be tarped to prevent water collection

