

OSHA Report City Volkswagen of Chicago

Complete On: 8/21/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

All secondary containers filled with chemicals are not properly labeled.

Date of occurrence: August 21, 2024


found secondary containers not labeled with contents



The fire extinguishers have not had their annual inspection and are not properly identified and fully charged.

Date of occurrence: August 21, 2024

found fire extinguisher behind toolbox on North Wall



Fire Extinguisher missing or not properly mounted in dispensing area

Date of occurrence: August 21, 2024

found Fire extinguishers sitting on floor



The fire extinguisher signs above the unit are not posted properly.

Date of occurrence: August 21, 2024

fire extinguishers need signage



The fire extinguisher signs above the unit are not posted properly.

Date of occurrence: August 21, 2024

fire extinguishers need signage



All hoses and cutting tips for the welder / cutting torches are not in good condition without any cracks or breaks.

Date of occurrence: August 21, 2024


Found oxy acetylene gauge missing protective cover.



Hoists are not being maintained within mfg. specs, and inspected and serviced AND documented under the mfg. suggested frequency. Usually annually.

Date of occurrence: August 21, 2024

Found hoist inspection sticker due for inspection.



There is no proper spacing on grinders; Tool rest 1/8" from grinding wheel. Tongue plate 1/4" from grinding wheel.

Date of occurrence: August 21, 2024

missing tounge plate



There is not clear access of at least 36" to all electrical panels.

Date of occurrence: August 21, 2024

found access to electrical panels obstructed



All vacant holes are not properly sealed off on electrical panel box.

Date of occurrence: August 21, 2024


need to plug open holes in breaker panels



All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Date of occurrence: August 21, 2024

found damaged cords in equipment area north wall and alignment area east wall



The fluorescent tubes are not stored properly.

Date of occurrence: August 21, 2024

Found loose fluorescent tubes upstairs on parts shelf



Miscellaneous issues.

Date of occurrence: August 21, 2024

Floor drain cover missing in service area NE garage door area



Ladders not stored properly, needs chained off on any ladder over 8 ft.

Date of occurrence: August 21, 2024


found ladders in East building



Electrical issues misc.

Date of occurrence: August 21, 2024

box pulled off wall strip plugged into strip in service area north wall



Electrical Plugs Outlets not properly covered. Plate cover missing or broke

Date of occurrence: August 21, 2024

found a few boxes with exposed wires, no covers



Used Batteries not stored on acid resistant matts

Date of occurrence: August 21, 2024

Need acid resistant mat under used batteries

