

OSHA Report **Brilliance** **Honda**

Complete On: 8/15/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

Hoists are not being maintained within mfg. specs, and inspected and serviced AND documented under the mfg. suggested frequency. Usually annually.

Date of occurrence: August 15, 2024

Hoists were due for inspection March 2024



Used batteries are not being stored in acid resistance leak proof containers and or on mat.

Date of occurrence: August 15, 2024

Found several used batteries around shop floor and one outside.



All vacant holes are not properly sealed off on electrical panel box.

Date of occurrence: August 15, 2024

found vacant hole in panel box (detail area) service drive up also open hole in electric junction box in Service



Ladders not stored properly, needs chained off on any ladder over 8 ft.

Date of occurrence: August 15, 2024

Found ladders without secure chains



All secondary containers filled with chemicals are not properly labeled.

Date of occurrence: August 15, 2024

Found several spray bottles with no label of contents.



The eye wash equipment is not readily accessible.

Date of occurrence: August 15, 2024

quick access to eyewash station is impeded North Service Wall



Miscellaneous issues.

Date of occurrence: August 15, 2024

noticed water hose with damage

