

Body Shop Report **Roger Williams Chrysler Dodge Jeep Ram**

Complete On: 7/23/2024

Report Created By:

Tom Dortch

815-404-8681

tomdortch@autorisknow.com

No signs posted warning of "Automatic Start" feature of the compressors.

1405, need automatic start/stop sign



Fire extinguishers are not easily accessible.

1405: fire extinguisher blocked



Holes not filled or blanks being used on electrical panels

1015 middle building, blank spaces in panel



Fire extinguishers are not easily accessible.

1015 middle building, extinguisher in center of shop not easily accessible; cords hanging on opposite end extinguisher



Eye wash equipment has not been tested, cleaned and documented weekly.

1015 eye wash pressure is too low for caps to open

