
#### PART NAMES AND FUNCTIONS

## Rear View



DC SWITCHING POWER SUPPLY



9615PS

8) Fuse: 5A

9) Input power cable: 110VAC

# Notice

- 1) Store this unit in a dry well-ventilated and clean place.
- 2) Cut off input supply when maintenance.
- 3) Be careful to the heat when the power supply is high current outputing, pay attention to ventilation.
- 4) Cauting: If this unit have any trouble, the output may rise over max. Rated voltage! Care for load to prevent against damage.
- 5) The ground terminal of power cord must be grounded reliably to ensure using safety.

Thank you for purchase of the 9615PS DC switching power supply. In order to use of its utility fully, please read this manul before using and keep the manual well for reference when you have any doubt in using.

### General

The series are DC Switching power supply with accuracy 3 digtal meter . The output voltage can be adjusted from 0 to 30V and the output current is from 0 to 3A.

# Specifications

1) Input Voltage: AC 110V±10% 60Hz±2Hz

2) Output Voltage: 0~30V (conti.adj.)

3) Output current: 0~3A(conti.adj.)

4) Supply Regulation: CV≤2×10<sup>-4</sup>+5mV

5) Load Regulation: CV≤2×10<sup>3</sup>+5mV

6) Ripple: 200mVp-p

7) Protection: Current Limit

8) Meters Indicator accuracy:

3digital meters accuracy: Voltmeter: LCD+/-1%+2Digits Ammeter: LCD+/-1%+2Digits

9) Operation Ambient

Temperature: 0°C~40°C

Humidity:<RH80%


Atmosphere Pressure: 86kPa~104kPa

10) Operating Time: 8hr.conti.

11) Size:155×73×180mm

#### PART NAMES AND FUNCTIONS

### Front View



- 1) Power switch: Turns the unit on and off
- 2) Current Adjustment Knob
- 3) Voltage Adjustment Knob
- 4) 3 Digital Meter: Displays the voltage or current
- 5) Current indication
- 6) Output Positive Terminal
- 7) Output Negative Terminal