


Phase-jump method stress map



Reference guide: 0.05 Hz RMSE. Gray cells denote non-finite (diverged) values.