

# Frequency Step Method Atlas (fixed policy)

C0-continuous frequency-step atlas: true frequency changes abruptly without an artificial phase jump. Curves expose transient tracking, overshoot and settling.



### Critical Frequency Step Summary

