





Holdout (frozen port_relocation_v1.1)

Kundur holdout: 28/29 detected, 0 false positives / 445 controls

synthetic: 200/200 detected, 0 false positives / 200 controls

IEEE-68: 0/0 detected, 0 false positives / 0 controls

Kundur miss: a real-pair coalescence
into a complex pair (not a zero crossing)