
extra alarm or next event lost
no observed harm
harm 33/54
harm 51/54
Spurious evidence after reset (nats)
10^8
10^6
10^4
10^2
carry: gain = 0 (not on log axis)
alarm threshold
Load events
Line events