INSPECTION RSDBV-02

HINT:

The SRS wire harness is integrated with the cowl wire harness assembly. All the connectors in the system are a standard yellow color.

1. VEHICLES NOT INVOLVED IN COLLISION

Do a diagnostic system check. (See page DI-377)

2. VEHICLES INVOLVED IN COLLISION

- (a) Do a diagnostic system check. (See page DI-377)
- (b) Check for breaks in all wires of the SRS wire harness, and for exposed conductors.
- (c) Check to see if the SRS wire harness connectors are cracked or chipped.

Author: Date: 1467

2002 4RUNNER (RM887U)