## REAR HEATER CONTROL ASSEMBLY ON-VEHICLE INSPECTION

AC0EO-01

**INSPECT HEATER CONTROL LEVER OPERATION** 

Move the control lever left and right check for stiffness and binding the full range of the lever.

2002 4RUNNER (RM887U)

Author: Date: 1869