
DI57O-03

Back Door Power Window Motor Circuit

WIRING DIAGRAM



2002 4RUNNER (RM887U)

Author: Date: 746

INSPECTION PROCEDURE

1 Check back door power window motor (See page BE-65).

NG

Replace back door power window motor.

OK

2 Check harness and connector between back door power window motor and back door ECU (See page IN-28).

NG

Repair or replace harness or connector.

OK

Proceed to next circuit inspection shown on problem symptoms table (See page DI-556).

2002 4RUNNER (RM887U)

Author: Date: 747