Quansheng UV-K5 - Manufacturing Defects

Adding a capacitor to address external PTT busy lockout issue


47052
out
24.Q17
NPN Dig
509
1nF
510
0R0
2012
10
3003
2030
516

Quansheng UV-K5 - Manufacturing Defects

Adding a capacitor to address external PTT busy lockout issue



Quansheng UV-K5 - Manufacturing Defects

Adding a capacitor to address external PTT busy lockout issue