Quansheng UV-K5 - Basic Hardware Mods

What are some common manufacturing defects we can fix?


2202




R51-V1.6
ZH18
XHR

Quansheng UV-K5 - Basic Hardware Mods

What are some common manufacturing defects we can fix?







Quansheng UV-K5 - Manufacturing Defects

Adding a capacitor to address external PTT busy lockout issue