

Wall Mount Computer Station wmcs

Assembly Instructions



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Hardware & Parts List

Wall Mount Computer Station

























































Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Wall Mount Computer Station

Step 1

Install Togglers



A: Drill a 1/2" hole. Slide Metal Anchor of Toggler through hole. Minimum clearance behind wall is 1-7/8".

Qty:3


B: Pull end of Toggler until Metal Anchor is flush against inside of wall. Push Plastic Collar into wall to lock in place.





C: Snap exposed material off, flush with Plastic Collar.



NOTE: Extra Toggle Bolts are provided








Step 2

Upright Pole Brackets

Attach Upright Pole Brackets to the wall using (4) four 50mm Furniture Bolts.















Support:

Wall Mount Computer Station

Step

3

Upright Pole

Secure Bottom Pole Holder using (2) 3/8 - 16 x 1" Socket Head Bolts.



Qty:2




Step

4

LCD Monitor

Attach LCD Monitor using (4) 8mm Phillips Machine Screws.















Support:


Wall Mount Computer Station

Step

5

LCD Bracket

Slide LCD Bracket.



Step 6

6

Upright Pole

Secure Top Pole Holder using (2) 3/8 - 16 x 1" Socket Head Bolts.


















Support: Local: 310

Wall Mount Computer Station

Step 7

Keyboard Bracket

3/8 -16 x 1" Socket Head Bolt Attach Keyboard Bracket to Pole at the desired height/side using (1) Clamp Bracket and (2) 3/8-16 x 1" Socket Head Bolts.




Step

0

Keyboard Platform

Attach the Keyboard Platform to Keyboard Bracket using (4) 1/4-20 Phillips Head Bolts.















Support:

Wall Mount Computer Station

DCPU Holder Configurations

There are three possible configurations.

NOTE: L pieces are shown in two colors to help you differenciate their placement.



Short Side Setup: CPU width is 1.3" to 4"





Long Side Setup: CPU width is 4" to 6"





Longest Side Setup: CPU width is 6" to 11.250"












Support:


Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Wall Mount Computer Station



Step 10 Secure Second L Panel.











Fast Shipping

Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Wall Mount Computer Station

Step 1


Attach CPU Holder At the desired Height.

Use (4) Clamps and (4) 3/8-16 x 1" Socke Head Bolts.









Step 1

Attach Velcro Pads to both your CPU and CPU Holder.

Once in place, adjust Holder and tighten Velcro Pads Thumb Nuts to keep CPU secure.









How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support: Local: 310-353-7100 Toll Free: 888-929-0322

Fax: 310-353-7109 Support@VersaTables.com

Lifetime Warranty

Assembled in USA