


Deluxe Diagnostic Fusion Cart

Assembly Instructions



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Fast Shipping Support@VersaTables.com

Hardware & Parts List

Deluxe Diagnostic Fusion Cart









































Additional Tools Required
















Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Exploded View

Deluxe Diagnostic Fusion Cart













Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Deluxe Diagnostic Fusion Cart

















Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Deluxe Diagnostic Fusion Cart

DCPU Holder Configurations

There are three possible configurations.

NOTE: L pieces are shown in two colors to help you differenciate their placement.



Short Side Setup: CPU width is 1.3" to 4"





Long Side Setup: CPU width is 4" to 6"





Longest Side Setup: CPU width is 6" to 11.250"













Support:

Deluxe Diagnostic Fusion Cart















Support: Local: 310-353-7100 Toll Free: 888-929-0322


Fax: 310-353-7109 Support@VersaTables.com

Deluxe Diagnostic Fusion Cart



Use (4) Clamps and (4) 3/8 1/6 x 1" Socket Head Bolts.





Step (Attach Velcro Pads to both your CPU and CPU Holder.

Once in place, adjust Holder and tighten Thumb Nuts to keep CPU secure. Velcro Pads




















Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109


Support@VersaTables.com

Quantity Discounts Assembled in USA

Deluxe Diagnostic Fusion Cart



Lay Keyboard Surface Upside Down and attach Keyboard Arm.





3/4 Phillips Pan Head Screw









Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Deluxe Diagnostic Fusion Cart
Attach Keyboard Arm
Slide Keyboard Arm onto Upright Extension and
Tighten T-Knob

Step 8

Step

Assemble Keyboard Surface.

Slide Monitor Arm onto Upright Extension and tighten T-Knob.













Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Deluxe Diagnostic Fusion Cart




ADDITIONAL ACCESSORY and is acquired separately from the cart.

Step 10 Utility / Prir

Utility / Printer Platform

Attach the Utility / Printer Platform to Utility Bracket using (4) 1/4-20 Phillips Head Bolts.

NOTE: Steps 10 and 11 are OPTIONAL. The Utility / Printer Platform is an





1/4-20 Phillips Head Bolt









Support: Local: 310-353-7100 Toll Free: 888-929-0322

Fax: 310-353-7109 Support@VersaTables.com


Deluxe Diagnostic Fusion Cart



Utility / Printer Bracket

Attach the Utility / Printer Bracket to Cart at the desired height using (1) Clamp Bracket and 3/8 -16 x 1" (2) 3/8-16 x 1" Socket Head Bolts. Socket Head Bolt













Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com