

Universal Spider Monitor Arm - Dual Arm Assembly Instructions UTMM-S2



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

Hardware and Parts List

Universal Spider Monitor Arm - Dual Arm










Exploded View













Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Assembly Step-byStep

Universal Spider Monitor Arm - Dual Arm

Step 1


Wood Grommet

Remove Wood Grommet.



Step 2 16" Pole

Insert 16" Pole to Grommet cutout. From underneath the surface screw on Lock Nut, teeth facing upward. Then turn the Pole to tighten and place cutout where desired.













Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com


Assembly Step-byStep

Universal Spider Monitor Arm - Dual Arm

Step

Monitor Arm

Slide Monitor Arm on to 16" Pole and tighten in place with 'T' knob.



Step

4

LCD Monitor


Attach LCD monitor to the Vesa Plate with (8) 8mm Phillips Machine Screws.

8mm Phillips Machine Screw



Qty:8

8mm Phillips Machine Screw



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com