


#### Sunrise Desk

## **Assembly Instructions**



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.













Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

### Sunrise Desk


#### Hardware Included





Read the entire instruction manual before you start installation and assembly. If you have any questions regarding any of the instructions please contact Support@VersaDesk.com.

### **Assembly Step-by-Step**














Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

# **Assembly Step-by-Step**

### Sunrise Desk
















Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

## **Assembly Step-by-Step**

### Sunrise Desk







**MAINTENANCE:** Check that the bracket which holds the monitor(s) is secure and safe to use at regular intervals (at least every 3 months).

#### **Operation Instruction:**

- △ Upward movement
- **▽** Downward movement

Press the " $\Delta$ " or " $\nabla$ " and do not release until the workstation reaches the desired height. If the motor continuosly operates for a relativily long period of time, the overheat protection will activiate. The control panel will work normally again after approximatley 20 minutes.

#### Note:

- 1. Overload protection mode: while operating, if the load is over weight capacity, the system will enter into an overload protection mode. This will protect the system from damages caused by exceeding weight. When this happens, the workstation will move downward approximately 30mm and stop with the current height displayed.
- 2. Please reset the system when the adjustable mechanism cannot work or experiences unusual operation.
- 3. Reset mode: while the unit is powered on, keep pressing the " $\nabla$ " button and the workstation will move into a fully lowered position. Don't release it until the workstation moves upward for approximately 5mm and automatically stops.









Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com