

# Universal Spider Monitor Arm - Quad Monitor Assembly Instructions UTMM-S4



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100
Toll Free: 888-929-0322
Fax: 310-353-7109

Support@VersaTables.com

# **Hardware & Parts List**

#### Universal Spider Monitor Arm - Quad Monitor










### **Exploded View**













Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

## **Assembly Step-byStep**

#### Universal Spider Monitor Arm - Quad Monitor

Step

1


**Wood Grommet** 

Remove Wood Grommet.



Step 2 16" Pole

Insert 16" Pole to Grommet cutout. From underneath the surface screw on Lock Nut, teeth facing upward. Then turn the Pole to tighten and place cutout where desired.













Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com

## **Assembly Step-byStep**


#### Universal Spider Monitor Arm - Quad Monitor

Step 3


Step

8mm Phillips Machine Screw **Monitor Arm** 

Slide Monitor Arms on to 32" Pole and tighten in place with 'T' knob.



Attach LCD monitor to the Vesa Plate with (16) 8mm Phillips Machine Screws.



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support: Local: 310-353-7100 Toll Free: 888-929-0322

Fax: 310-353-7109 Support@VersaTables.com