

Art Drawing Table Pole Mount Spider Monitor Arm - ATPMSMA Assembly Instructions



How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

Assembly Step-byStep

ATPMSMA















Step 1


3/8" Acorn Nut

Bottom Pole Suport

Place Bottom Pole Support to right or left of the art table frame using (2) 3/8" Hex Bolts, (2) #10 Washers, and (2) 3/8" Acorn Nut.



Qty:2













Support: Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Discounts Assembled in USA


Fax: 310-353-7109
Support@VersaTables.com

ATPMSMA

Step 2


34" pole

Slide 34" Pole into Bottom Support Bracket. Tightly secure Pole with T-knob.



Step 3 Spider Arm

Slide Spinder Arm and secure its position by tightening T-knob.







Quantity Disc ounts



Fast Shipping

Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109 Support@VersaTables.com

ATPMSMA

Step


4

Attach Monitor

Attach LCD Monitor using (4) 8mm Phillips Machine Screws.







How can we improve our assembly instructions? Your comments and suggestions are important to us. Please e-mail us at: support@versatables.com.











Support:

Local: 310-353-7100 Toll Free: 888-929-0322 Fax: 310-353-7109

Support@VersaTables.com