27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, October 13, 2026 Rules: 2-2



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00044 Request Received 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/12/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/12/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	290	39	86.6%	3,676	500	86.4%	3,676	500	86.4%
Central Division	86.0%	59	7	88.1%	678	40	94.1%	678	40	94.1%
East Division	82.0%	141	16	88.7%	1,986	288	85.5%	1,986	288	85.5%
West Division	86.0%	90	16	82.2%	1,012	172	83.0%	1,012	172	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/12/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**104,108**	**31,705**	**70%**	**1,308,219**	**372,672**	**72%**	**1,308,219**	**372,672**	**72%**
Northeast Corridor	***81%***	***43,435***	***10,182***	***77%***	***576,960***	***147,404***	***74%***	***576,960***	***147,404***	***74%***
Acela	83%	6,263	1,254	80%	120,038	24,177	80%	120,038	24,177	80%
Northeast Regional	79%	37,172	8,928	76%	456,922	123,227	73%	456,922	123,227	73%
Richmond / Newport News / Norfolk	77%	2,144	606	72%	123,348	38,705	69%	123,348	38,705	69%
Flag_Subroute	%	7,220	0	100%	7,220	0	100%	7,220	0	100%
Springfield Shuttles	89%	830	204	75%	10,180	2,871	72%	10,180	2,871	72%
Roanoke	79%	1,978	207	90%	45,096	11,627	74%	45,096	11,627	74%
On Spine Northeast Regional	80%	25,000	7,911	68%	271,078	70,024	74%	271,078	70,024	74%
State Supported	***80%***	***47,293***	***16,699***	***65%***	***580,052***	***151,329***	***74%***	***580,052***	***151,329***	***74%***
Borealis	80%	741	274	63%	8,638	1,780	79%	8,638	1,780	79%
Capitol Corridor	90%	4,285	1,207	72%	51,975	11,495	78%	51,975	11,495	78%
Carolinian	70%	1,443	63	96%	15,721	3,267	79%	15,721	3,267	79%
Cascades	75%	1,987	977	51%	33,774	8,914	74%	33,774	8,914	74%
Downeaster	82%	2,077	1,106	47%	24,358	7,170	71%	24,358	7,170	71%
Empire	78%	7,693	1,446	81%	79,924	16,612	79%	79,924	16,612	79%
Adirondack	72%	617	0	100%	5,492	1,116	80%	5,492	1,116	80%
Ethan Allen Express	70%	688	303	56%	7,535	2,405	68%	7,535	2,405	68%
Maple Leaf	70%	964	378	61%	10,516	2,493	76%	10,516	2,493	76%
New York - Albany	85%	3,856	389	90%	38,635	6,175	84%	38,635	6,175	84%
New York - Niagara Falls	75%	1,568	376	76%	17,746	4,423	75%	17,746	4,423	75%
Gold Runner	73%	2,879	1,566	46%	34,260	11,955	65%	34,260	11,955	65%
Heartland Flyer	70%	215	209	3%	2,735	2,411	12%	2,735	2,411	12%
Hiawatha	90%	1,785	81	95%	23,037	1,739	92%	23,037	1,739	92%
Illinois	78%	2,946	838	72%	34,379	11,856	66%	34,379	11,856	66%
Carl Sandburg / Illinois Zephyr	85%	504	0	100%	5,487	1,315	76%	5,487	1,315	76%
Illini / Saluki	85%	940	233	75%	11,380	4,422	61%	11,380	4,422	61%
Lincoln Service	70%	1,502	605	60%	17,512	6,119	65%	17,512	6,119	65%
Keystone	92%	6,186	670	89%	99,142	10,632	89%	99,142	10,632	89%
Lincoln / Missouri	70%	846	95	89%	10,570	5,816	45%	10,570	5,816	45%
Mardi Gras Service	80%	390	104	73%	2,729	902	67%	2,729	902	67%
Michigan	70%	2,593	973	62%	27,473	5,641	79%	27,473	5,641	79%
Blue Water	70%	622	597	4%	6,250	1,517	76%	6,250	1,517	76%
Pere Marquette	85%	300	40	87%	3,779	271	93%	3,779	271	93%
Wolverine	70%	1,671	336	80%	17,444	3,853	78%	17,444	3,853	78%
Missouri	80%	203	146	28%	3,678	775	79%	3,678	775	79%
Pacific Surfliner	85%	7,416	5,454	26%	85,272	38,748	55%	85,272	38,748	55%
Pennsylvanian	80%	963	449	53%	11,506	3,600	69%	11,506	3,600	69%
Piedmont	80%	1,014	9	99%	12,681	1,707	87%	12,681	1,707	87%
Vermonter	75%	1,631	1,032	37%	18,200	6,309	65%	18,200	6,309	65%
Long Distance	***70%***	***13,380***	***4,824***	***64%***	***151,207***	***73,939***	***51%***	***151,207***	***73,939***	***51%***
Auto Train	70%	626	626	0%	8,365	6,384	24%	8,365	6,384	24%
California Zephyr	70%	1,106	87	92%	11,061	3,884	65%	11,061	3,884	65%
Cardinal	70%	351	128	64%	3,715	1,948	48%	3,715	1,948	48%
City Of New Orleans	75%	839	602	28%	9,114	6,207	32%	9,114	6,207	32%
Coast Starlight	70%	1,060	158	85%	13,960	6,829	51%	13,960	6,829	51%
Crescent	70%	955	62	94%	10,792	1,338	88%	10,792	1,338	88%
Empire Builder	70%	1,068	624	42%	12,013	5,596	53%	12,013	5,596	53%
Floridian	60%	1,627	1,362	16%	19,228	12,997	32%	19,228	12,997	32%
Lake Shore Ltd	73%	1,015	392	61%	13,499	3,672	73%	13,499	3,672	73%
Palmetto	70%	1,039	60	94%	10,803	2,163	80%	10,803	2,163	80%
Silver Meteor	70%	1,193	40	97%	11,400	4,811	58%	11,400	4,811	58%
Southwest Chief	60%	946	497	47%	11,347	8,802	22%	11,347	8,802	22%
Sunset Ltd	70%	341	177	48%	3,588	1,310	63%	3,588	1,310	63%
Texas Eagle	70%	1,214	9	99%	12,322	7,998	35%	12,322	7,998	35%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FGI 00046 000000000047 "UNCLASSIFIED" 10/13/2026~~

Train Index Dates Through October 12, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	76,881	1,275,774	603	76,881	1,275,774	603

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	4,071	383,473	106	4,071	383,473	106
INFRASTRUCTURE PLANNED	135	8,419	383,473	220	8,419	383,473	220
FLEET RELIABILITY	90	9,970	1,275,774	78	9,970	1,275,774	78
TRAIN OPERATIONS	424	54,421	1,275,774	427	54,421	1,275,774	427

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00044 Request Received 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/12/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/12/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	290	39	86.6%	3,676	500	86.4%	3,676	500	86.4%
Central Division	86.0%	59	7	88.1%	678	40	94.1%	678	40	94.1%
East Division	82.0%	141	16	88.7%	1,986	288	85.5%	1,986	288	85.5%
West Division	86.0%	90	16	82.2%	1,012	172	83.0%	1,012	172	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-00044 [illegible]

Scheduled Departure Date: **10/12/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/12/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	290	39	86.6%	3,676	500	86.4%	3,676	500	86.4%
Central Division	86.0%	59	7	88.1%	678	40	94.1%	678	40	94.1%
CDL	95.0%	1	0	100.0%	17	2	88.2%	17	2	88.2%
CHI	86.0%	27	7	74.1%	323	26	92.0%	323	26	92.0%
CHM	-	1	0	100.0%	6	1	83.3%	6	1	83.3%
DAL	-	-	-	-	2	0	100.0%	2	0	100.0%
FTW	92.5%	1	0	100.0%	10	1	90.0%	10	1	90.0%
GRR	95.5%	1	0	100.0%	12	0	100.0%	12	0	100.0%
KCY	92.0%	2	0	100.0%	24	0	100.0%	24	0	100.0%
MKE	92.0%	6	0	100.0%	70	3	95.7%	70	3	95.7%
MOE	97.5%	2	0	100.0%	17	0	100.0%	17	0	100.0%
MSP	96.5%	1	0	100.0%	12	0	100.0%	12	0	100.0%
NOL	94.5%	5	0	100.0%	42	1	97.6%	42	1	97.6%
OKC	97.0%	1	0	100.0%	12	1	91.7%	12	1	91.7%
PNT	88.0%	3	0	100.0%	35	1	97.1%	35	1	97.1%
PTH	93.0%	1	0	100.0%	12	0	100.0%	12	0	100.0%
QCY	91.0%	2	0	100.0%	24	2	91.7%	24	2	91.7%
SAS	90.5%	1	0	100.0%	12	1	91.7%	12	1	91.7%
STL	89.0%	4	0	100.0%	48	1	97.9%	48	1	97.9%
East Division	82.0%	141	16	88.7%	1,986	288	85.5%	1,986	288	85.5%
ALB	88.5%	8	1	87.5%	96	9	90.6%	96	9	90.6%
ATL	-	-	-	-	4	1	75.0%	4	1	75.0%
BON	87.5%	5	1	80.0%	60	8	86.7%	60	8	86.7%
BOS	85.5%	10	0	100.0%	193	5	97.4%	193	5	97.4%
BRK	92.5%	5	1	80.0%	60	6	90.0%	60	6	90.0%
BTN	82.0%	1	0	100.0%	12	1	91.7%	12	1	91.7%
CLT	91.5%	5	0	100.0%	55	7	87.3%	55	7	87.3%
GFD	88.0%	2	0	100.0%	24	3	87.5%	24	3	87.5%
GRO	-	-	-	-	5	0	100.0%	5	0	100.0%
HAR	79.5%	13	1	92.3%	134	19	85.8%	134	19	85.8%
HFD	-	2	1	50.0%	16	3	81.3%	16	3	81.3%
LOR	84.0%	-	-	-	11	5	54.5%	11	5	54.5%
MIA	89.5%	2	0	100.0%	24	6	75.0%	24	6	75.0%
MTR	79.0%	1	0	100.0%	12	4	66.7%	12	4	66.7%
NFK	84.5%	1	0	100.0%	23	4	82.6%	23	4	82.6%
NFL	93.5%	2	0	100.0%	24	3	87.5%	24	3	87.5%
NHV	78.0%	5	1	80.0%	60	16	73.3%	60	16	73.3%
NPN	93.0%	-	-	-	21	2	90.5%	21	2	90.5%
NYP	75.5%	37	5	86.5%	558	98	82.4%	558	98	82.4%
PGH	93.0%	1	1	0.0%	12	2	83.3%	12	2	83.3%
PHL	48.0%	9	2	77.8%	64	36	43.8%	64	36	43.8%
RGH	95.0%	4	0	100.0%	38	2	94.7%	38	2	94.7%
RNK	83.5%	1	0	100.0%	23	2	91.3%	23	2	91.3%
SAB	98.0%	1	0	100.0%	12	0	100.0%	12	0	100.0%
SAV	96.0%	1	0	100.0%	12	0	100.0%	12	0	100.0%

Information Management

Initial Terminal Performance By Terminal

27-FOI-00044 [illegible]

Scheduled Departure Date: **10/12/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/12/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	290	39	86.6%	3,676	500	86.4%	3,676	500	86.4%
East Division	82.0%	141	16	88.7%	1,986	288	85.5%	1,986	288	85.5%
SFA	88.0%	-	-	-	11	3	72.7%	11	3	72.7%
SPG	92.5%	5	0	100.0%	66	8	87.9%	66	8	87.9%
TWO	73.0%	1	0	100.0%	12	2	83.3%	12	2	83.3%
WAS	84.0%	19	2	89.5%	344	33	90.4%	344	33	90.4%
West Division	86.0%	90	16	82.2%	1,012	172	83.0%	1,012	172	83.0%
ARN	92.0%	1	0	100.0%	12	0	100.0%	12	0	100.0%
BFD	79.0%	7	1	85.7%	84	20	76.2%	84	20	76.2%
EMY	72.0%	1	0	100.0%	13	6	53.8%	13	6	53.8%
EUG	86.5%	2	0	100.0%	23	1	95.7%	23	1	95.7%
GAC	-	-	-	-	2	1	50.0%	2	1	50.0%
GTA	90.0%	3	1	66.7%	30	9	70.0%	30	9	70.0%
LAX	89.5%	10	1	90.0%	108	10	90.7%	108	10	90.7%
OKJ	74.5%	13	5	61.5%	138	43	68.8%	138	43	68.8%
PDX	86.0%	5	1	80.0%	60	5	91.7%	60	5	91.7%
SAC	88.5%	16	0	100.0%	175	24	86.3%	175	24	86.3%
SAN	90.5%	13	3	76.9%	126	19	84.9%	126	19	84.9%
SEA	85.0%	8	2	75.0%	95	12	87.4%	95	12	87.4%
SJC	89.0%	7	1	85.7%	84	18	78.6%	84	18	78.6%
SLO	90.0%	3	1	66.7%	30	3	90.0%	30	3	90.0%
SPK	90.0%	1	0	100.0%	11	0	100.0%	11	0	100.0%
VAC	97.0%	-	-	-	21	1	95.2%	21	1	95.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	319	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
3	216	12	1	91.7%	12	1	91.7%	12	8	33.3%	12	8	33.3%
4		12	0	100.0%	12	0	100.0%	12	10	16.7%	12	10	16.7%
5		11	1	90.9%	11	1	90.9%	11	4	63.6%	11	4	63.6%
6		11	6	45.5%	11	6	45.5%	11	4	63.6%	11	4	63.6%
7		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
8	57	11	3	72.7%	11	3	72.7%	11	8	27.3%	11	8	27.3%
11		12	1	91.7%	12	1	91.7%	12	4	66.7%	12	4	66.7%
14		12	3	75.0%	12	3	75.0%	12	7	41.7%	12	7	41.7%
19		12	1	91.7%	12	1	91.7%	11	2	81.8%	11	2	81.8%
20		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
21		12	1	91.7%	12	1	91.7%	12	6	50.0%	12	6	50.0%
22		12	1	91.7%	12	1	91.7%	12	9	25.0%	12	9	25.0%
23		9	0	100.0%	9	0	100.0%	9	2	77.8%	9	2	77.8%
24		8	0	100.0%	8	0	100.0%	8	2	75.0%	8	2	75.0%
25		8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
26	35	9	0	100.0%	9	0	100.0%	9	4	55.6%	9	4	55.6%
27		11	3	72.7%	11	3	72.7%	11	2	81.8%	11	2	81.8%
28		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
40	420	12	3	75.0%	12	3	75.0%	12	9	25.0%	12	9	25.0%
41	73	12	3	75.0%	12	3	75.0%	12	8	33.3%	12	8	33.3%
42		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
43	138	12	5	58.3%	12	5	58.3%	12	4	66.7%	12	4	66.7%
48	267	12	4	66.7%	12	4	66.7%	12	4	66.7%	12	4	66.7%
49		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
51		5	2	60.0%	5	2	60.0%	6	3	50.0%	6	3	50.0%
52	637	11	3	72.7%	11	3	72.7%	12	8	33.3%	12	8	33.3%
53	160	11	5	54.5%	11	5	54.5%	12	10	16.7%	12	10	16.7%
55	62	8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
56	64	8	1	87.5%	8	1	87.5%	8	3	62.5%	8	3	62.5%
58	131	12	0	100.0%	12	0	100.0%	12	10	16.7%	12	10	16.7%
59	17	12	0	100.0%	12	0	100.0%	12	9	25.0%	12	9	25.0%
63	50	12	8	33.3%	12	8	33.3%	12	12	0.0%	12	12	0.0%
64	31	12	2	83.3%	12	2	83.3%	12	5	58.3%	12	5	58.3%
66		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
67		8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
68		12	4	66.7%	12	4	66.7%	12	3	75.0%	12	3	75.0%
69		12	5	58.3%	12	5	58.3%	12	2	83.3%	12	2	83.3%
71		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
72		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
73		7	0	100.0%	7	0	100.0%	7	1	85.7%	7	1	85.7%
74		7	2	71.4%	7	2	71.4%	7	2	71.4%	7	2	71.4%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		12	1	91.7%	12	1	91.7%	11	1	90.9%	11	1	90.9%
76		12	2	83.3%	12	2	83.3%	11	2	81.8%	11	2	81.8%
77		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
78		12	2	83.3%	12	2	83.3%	13	3	76.9%	13	3	76.9%
79		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
80		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
89		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
90		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
94		10	2	80.0%	10	2	80.0%	10	2	80.0%	10	2	80.0%
97		12	7	41.7%	12	7	41.7%	12	4	66.7%	12	4	66.7%
98		12	3	75.0%	12	3	75.0%	12	5	58.3%	12	5	58.3%
128	49	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
169		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
230		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
232		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
233		12	3	75.0%	12	3	75.0%	12	6	50.0%	12	6	50.0%
234		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
235		12	1	91.7%	12	1	91.7%	12	4	66.7%	12	4	66.7%
236		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
237	49	12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
238		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
239		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
240		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
241		12	3	75.0%	12	3	75.0%	12	3	75.0%	12	3	75.0%
243		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
244		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
245		12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
280		12	3	75.0%	12	3	75.0%	12	5	58.3%	12	5	58.3%
281		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
283		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
284	65	12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
290	30	12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
291		12	7	41.7%	12	7	41.7%	12	3	75.0%	12	3	75.0%
300		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
301		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
302	48	12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
305	16	12	0	100.0%	12	0	100.0%	12	6	50.0%	12	6	50.0%
306		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
307	73	12	1	91.7%	12	1	91.7%	12	5	58.3%	12	5	58.3%
311	30	12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
316		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
318		12	0	100.0%	12	0	100.0%	12	6	50.0%	12	6	50.0%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
319	34	12	0	100.0%	12	0	100.0%	12	10	16.7%	12	10	16.7%
329		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
330		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
331		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
332		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
334		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
335		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
336		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
337		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
338		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
339		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
341	43	11	3	72.7%	11	3	72.7%	11	1	90.9%	11	1	90.9%
342		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
350	19	12	0	100.0%	12	0	100.0%	12	7	41.7%	12	7	41.7%
351		11	0	100.0%	11	0	100.0%	11	2	81.8%	11	2	81.8%
352		12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
353		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
354	37	12	3	75.0%	12	3	75.0%	11	3	72.7%	11	3	72.7%
355		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
364	35	12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
365	50	12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
370		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
371		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
380		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
381		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
382		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
383		12	0	100.0%	12	0	100.0%	12	6	50.0%	12	6	50.0%
390		11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
391		12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
392	38	12	1	91.7%	12	1	91.7%	12	10	16.7%	12	10	16.7%
393		11	2	81.8%	11	2	81.8%	11	5	54.5%	11	5	54.5%
417		8	3	62.5%	8	3	62.5%	8	3	62.5%	8	3	62.5%
425	16	8	0	100.0%	8	0	100.0%	8	2	75.0%	8	2	75.0%
448	311	12	6	50.0%	12	6	50.0%	12	3	75.0%	12	3	75.0%
449		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
470	41	8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
471	20	8	1	87.5%	8	1	87.5%	8	2	75.0%	8	2	75.0%
473		8	2	75.0%	8	2	75.0%	8	0	100.0%	8	0	100.0%
474	17	8	4	50.0%	8	4	50.0%	8	4	50.0%	8	4	50.0%
475		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
478		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
479		8	1	87.5%	8	1	87.5%	8	5	37.5%	8	5	37.5%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
486		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
494		9	2	77.8%	9	2	77.8%	8	3	62.5%	8	3	62.5%
495		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
500		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
502	20	12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
503	39	12	3	75.0%	12	3	75.0%	12	7	41.7%	12	7	41.7%
504		12	1	91.7%	12	1	91.7%	12	5	58.3%	12	5	58.3%
505		12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
506		12	1	91.7%	12	1	91.7%	11	3	72.7%	11	3	72.7%
507		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
508	16	12	1	91.7%	12	1	91.7%	12	4	66.7%	12	4	66.7%
509	30	12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
511		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
517	47	12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
518	Cncld	12	0	100.0%	12	0	100.0%	11	4	63.6%	11	4	63.6%
520		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
521		8	1	87.5%	8	1	87.5%	7	0	100.0%	7	0	100.0%
522		8	1	87.5%	8	1	87.5%	8	0	100.0%	8	0	100.0%
523	53	8	2	75.0%	8	2	75.0%	8	2	75.0%	8	2	75.0%
524		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
525		8	2	75.0%	8	2	75.0%	7	1	85.7%	7	1	85.7%
526	22	8	5	37.5%	8	5	37.5%	7	2	71.4%	7	2	71.4%
527	24	8	0	100.0%	8	0	100.0%	8	2	75.0%	8	2	75.0%
528	38	8	1	87.5%	8	1	87.5%	8	2	75.0%	8	2	75.0%
529	104	8	0	100.0%	8	0	100.0%	8	4	50.0%	8	4	50.0%
530	19	8	1	87.5%	8	1	87.5%	8	2	75.0%	8	2	75.0%
531	23	8	1	87.5%	8	1	87.5%	8	2	75.0%	8	2	75.0%
532		8	2	75.0%	8	2	75.0%	8	0	100.0%	8	0	100.0%
534		8	2	75.0%	8	2	75.0%	8	0	100.0%	8	0	100.0%
535		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
536		8	2	75.0%	8	2	75.0%	8	0	100.0%	8	0	100.0%
537		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
538		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
539	35	8	4	50.0%	8	4	50.0%	8	5	37.5%	8	5	37.5%
540		8	1	87.5%	8	1	87.5%	8	0	100.0%	8	0	100.0%
541		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
542		8	3	62.5%	8	3	62.5%	8	1	87.5%	8	1	87.5%
543	27	8	1	87.5%	8	1	87.5%	8	6	25.0%	8	6	25.0%
544		8	3	62.5%	8	3	62.5%	8	3	62.5%	8	3	62.5%
545		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
547	24	8	1	87.5%	8	1	87.5%	8	3	62.5%	8	3	62.5%
548		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
549		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
550		8	2	75.0%	8	2	75.0%	8	2	75.0%	8	2	75.0%
551		8	2	75.0%	8	2	75.0%	8	2	75.0%	8	2	75.0%
562	37	10	1	90.0%	10	1	90.0%	10	5	50.0%	10	5	50.0%
564	63	10	0	100.0%	10	0	100.0%	10	5	50.0%	10	5	50.0%
566	60	10	0	100.0%	10	0	100.0%	10	5	50.0%	10	5	50.0%
567	52	10	1	90.0%	10	1	90.0%	10	2	80.0%	10	2	80.0%
572	50	10	3	70.0%	10	3	70.0%	10	7	30.0%	10	7	30.0%
573	39	10	1	90.0%	10	1	90.0%	10	5	50.0%	10	5	50.0%
579	32	10	0	100.0%	10	0	100.0%	10	5	50.0%	10	5	50.0%
580	17	10	1	90.0%	10	1	90.0%	10	3	70.0%	10	3	70.0%
581	74	10	3	70.0%	10	3	70.0%	10	6	40.0%	10	6	40.0%
584	35	10	0	100.0%	10	0	100.0%	10	8	20.0%	10	8	20.0%
587	82	10	3	70.0%	10	3	70.0%	9	5	44.4%	9	5	44.4%
588	51	10	1	90.0%	10	1	90.0%	10	3	70.0%	10	3	70.0%
591	35	10	1	90.0%	10	1	90.0%	10	5	50.0%	10	5	50.0%
593	35	9	4	55.6%	9	4	55.6%	8	2	75.0%	8	2	75.0%
595	No OS	7	2	71.4%	7	2	71.4%	7	4	42.9%	7	4	42.9%
600		10	0	100.0%	10	0	100.0%	10	2	80.0%	10	2	80.0%
601		8	3	62.5%	8	3	62.5%	8	1	87.5%	8	1	87.5%
605		8	3	62.5%	8	3	62.5%	7	1	85.7%	7	1	85.7%
607		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
609		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
622		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
626		10	2	80.0%	10	2	80.0%	10	2	80.0%	10	2	80.0%
640		8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
641		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
642		8	0	100.0%	8	0	100.0%	8	2	75.0%	8	2	75.0%
643		10	5	50.0%	10	5	50.0%	10	3	70.0%	10	3	70.0%
644		8	1	87.5%	8	1	87.5%	8	2	75.0%	8	2	75.0%
645		10	3	70.0%	10	3	70.0%	10	2	80.0%	10	2	80.0%
646		8	2	75.0%	8	2	75.0%	8	1	87.5%	8	1	87.5%
647		10	1	90.0%	10	1	90.0%	10	0	100.0%	10	0	100.0%
648		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
649		10	1	90.0%	10	1	90.0%	10	2	80.0%	10	2	80.0%
650	32	10	2	80.0%	10	2	80.0%	10	1	90.0%	10	1	90.0%
651		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
652		10	1	90.0%	10	1	90.0%	10	0	100.0%	10	0	100.0%
653		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
654		8	3	62.5%	8	3	62.5%	8	3	62.5%	8	3	62.5%
655		10	2	80.0%	10	2	80.0%	10	1	90.0%	10	1	90.0%
656		10	3	70.0%	10	3	70.0%	10	2	80.0%	10	2	80.0%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
657		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
658		10	0	100.0%	10	0	100.0%	10	0	100.0%	10	0	100.0%
680		8	1	87.5%	8	1	87.5%	8	0	100.0%	8	0	100.0%
681	27	8	0	100.0%	8	0	100.0%	7	5	28.6%	7	5	28.6%
682		8	2	75.0%	8	2	75.0%	8	1	87.5%	8	1	87.5%
683	47	8	0	100.0%	8	0	100.0%	8	8	0.0%	8	8	0.0%
684	39	8	1	87.5%	8	1	87.5%	8	5	37.5%	8	5	37.5%
685		8	2	75.0%	8	2	75.0%	8	4	50.0%	8	4	50.0%
686	85	8	1	87.5%	8	1	87.5%	8	6	25.0%	8	6	25.0%
687	52	8	2	75.0%	8	2	75.0%	8	5	37.5%	8	5	37.5%
688		8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
699		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
701		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
702	22	12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
703		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
704		12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
710		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
711		12	2	83.3%	12	2	83.3%	10	1	90.0%	10	1	90.0%
712		12	5	58.3%	12	5	58.3%	12	4	66.7%	12	4	66.7%
713		12	4	66.7%	12	4	66.7%	11	1	90.9%	11	1	90.9%
714	122	12	4	66.7%	12	4	66.7%	11	5	54.5%	11	5	54.5%
715	25	12	2	83.3%	12	2	83.3%	12	6	50.0%	12	6	50.0%
716	32	12	8	33.3%	12	8	33.3%	12	4	66.7%	12	4	66.7%
717	42	12	4	66.7%	12	4	66.7%	12	5	58.3%	12	5	58.3%
718	54	12	8	33.3%	12	8	33.3%	12	5	58.3%	12	5	58.3%
719		12	3	75.0%	12	3	75.0%	12	3	75.0%	12	3	75.0%
750		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
757	16	11	1	90.9%	11	1	90.9%	11	5	54.5%	11	5	54.5%
761		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
765	77	10	0	100.0%	10	0	100.0%	10	4	60.0%	10	4	60.0%
769	59	10	1	90.0%	10	1	90.0%	10	5	50.0%	10	5	50.0%
770	74	10	1	90.0%	10	1	90.0%	10	5	50.0%	10	5	50.0%
774	154	10	0	100.0%	10	0	100.0%	10	7	30.0%	10	7	30.0%
777	129	10	0	100.0%	10	0	100.0%	10	8	20.0%	10	8	20.0%
782		10	8	20.0%	10	8	20.0%	10	6	40.0%	10	6	40.0%
785	140	10	3	70.0%	10	3	70.0%	10	4	60.0%	10	4	60.0%
786	42	10	2	80.0%	10	2	80.0%	9	5	44.4%	9	5	44.4%
790	51	10	0	100.0%	10	0	100.0%	10	3	70.0%	10	3	70.0%
821	18	12	1	91.7%	12	1	91.7%	12	10	16.7%	12	10	16.7%
822	68	12	1	91.7%	12	1	91.7%	12	12	0.0%	12	12	0.0%
1082		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1087		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1088		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1099		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1103		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1107		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1109		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1111		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1116		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1118		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1124		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1126		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1127		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1129		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1135		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1138		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1140		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1142		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1143	33	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1144		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1146		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1147		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1150		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1151	24	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1152	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1153		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1155	34	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1156		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1160	27	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1161	39	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1162	18	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1163		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1164		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1165		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1167		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1168		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1194		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1195		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1333		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
1340	45	12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
2101		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2103		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
2105		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
2106	41	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/12/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2114		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2115		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
2116		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
2118		8	2	75.0%	8	2	75.0%	7	1	85.7%	7	1	85.7%
2120		8	3	62.5%	8	3	62.5%	8	1	87.5%	8	1	87.5%
2122		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2123		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
2133		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2148		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2149	121	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
2150	49	8	0	100.0%	8	0	100.0%	8	2	75.0%	8	2	75.0%
2151	44	8	0	100.0%	8	0	100.0%	8	3	62.5%	8	3	62.5%
2152		8	0	100.0%	8	0	100.0%	8	0	100.0%	8	0	100.0%
2155		8	0	100.0%	8	0	100.0%	7	1	85.7%	7	1	85.7%

Amtrak Endpoint OTP Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2106	NYP	41	DDA	44	DDA	44	XCY-MET	AM	HBD - no exceptions, Other, XCY-EDISON
2149	WAS	121	CAR	90	CAR	48	BOS-BOS	AM	Door, 3650|NG|NB, DP BOS 48" LATE DUE TO DOOR ISSUES, GAP FILLER CUT IN
2150	BOS	49	DDA	24	DDA	24	XCY-NWK	AM	HBD - no exceptions, Other, XCY-EDISON
2151	WAS	44	ENG	22	ENG	22	XCY-XHM	AM	Unrecoverable penalty (PCS), 2147, MULTIPLE FAULTS ON PC2147
128	NYP	49	DCS	47	DCS	47	NWK-NYP	AM	Power switch failure, Other, XBH-XBH, HELD AT BERGEN DUE TO 23SW FAILURE AT BERGEN.
425	SPG	16							
470	HFD	41	CON	26	CON	26	NHV-NHV	AM	Hold for connecting train
471	NHV	20	CON	18	CON	18	HFD-HFD	AM	Hold for connecting train, DP HFD 18" LATE A/C OF LATE TURN OF 426
474	SPG	17	SVS	18	SVS	18	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Train 474 will be delayed departing NHV a/c late from yard for congestion
1143	WAS	33	DSR	23	ENG	14	NYP-NWK	AM	Other electrical failure, 642|EX|ES, BROKEN PANTOGRAPH ALARM ON ENG.642
1151	RNK	24	PTI	24	PTI	24	CVS-LYH	NS	Meet 1156, Control Point, Red Hill
1152	NYP	19	MTI	29	MTI	29	TRE-MET	AM	Disabled train ahead, Other, XCY-EDISON, AM2150 DISABLED AHD
1155	NFK	34	CAR	39	CAR	35	PHL-PHL	AM	Door, entire train, Could not get doors closed on entire train. Mechanical assisted.
1160	BOS	27	ENG	26	ENG	17	BRP-NHV	MN	HEP 621
1161	WAS	39	SMW	32	DMW	20	BRP-STM	MN	Unable to contact dispatcher / MW foreman Mobile unit 803 did not answer radio for 7 minutes. Eventually district Q relayed permission through working limits at RESTRICTED SPEED, Milepost, 36.6, 35.1
1162	BOS	18	HLD	19	CTI	16	BRP-NHV	MN	Cross Traffic Stop signal, metro north, Control Point, 261
52	LOR	637	ITI	573	ITI	573	SFA-SFA	FR	Late departure at initial terminal due to late arrival of inbound equipment 53
53	SFA	160	TSV	125	TSV	121	LOR-LOR	CS	DRUMMAC loading cars onto carriers
650	NYP	32	SVS	35	SVS	35	PHL-XHM	AM	Scheduled wyeing of the train
681	BRK	27	DSR	9	FTI	9	BON-WOB	MT	Meet L059, Control Point, Crawford

Amtrak Endpoint OTP Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
683	BRK	47	PTI	47	PTI	39	SAO-ORB	CS	Cross over or go around 686, Control Point, Ocean Park
684	BON	39	PTI	27	PTI	19	FRE-POR	CS	Meet 681, Control Point, mountain
686	BON	85	DCS	71	DCS	67	POR-ORB	CS	Cab signal or ATS failure (wayside) Random penalty and ensuing issues. Proceeded as failed train not exceeding 59 mph per 1305.5, Other, around PLD 15
687	BRK	52	ITI	38	ITI	38	BON-BON	MT	Late departure at initial terminal due to late arrival of inbound equipment 686, 686 arrived into BON at 5:40 pm
63	TWO	50	FTI	8	PTI	6	ROC-BUF	CS	Meet 48, Control Point, 380
64	NYP	31	CTI	49	CTI	22	POU-CRT	MN	Follow mn, 890, Milepost, 72, 35
237	ALB	49	ITI	31	ITI	31	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 284, LATE TURN OFF AM284
284	NYP	65	FTI	52	FTI	26	AMS-XHF	CS	Follow csx W068, Milepost, 177, 169
290	NYP	30	PTI	37	PTI	16	POU-CRT	MN	Follow 284, 770, Milepost, 73.6, 33.3
48	NYP	267	CAR	251	CAR	247	CHI-CHI	AM	HEP 25087, Car was causing HEP issues. Couldn't load without power. Eventually the car was bad ordered taken out to the yard. Loaded after train was tied back up.
448	BOS	32	FTI	42	FTI	35	PIT-SPG	CS	Meet IO13, Control Point, 123
43	PGH	138	SVS	81	SVS	81	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
55	WAS	62	RTE	59	RTE	59	HLK-X1X	AM	Dispatcher hold Control Point, CPR1
56	SAB	64	SYS	43	SYS	43	SPG-SPG	AM	Other late crew Waiting for engineer of Amt 55 to turn for Amt 56, Other, SPG Sta
40	CHI	420	WTR	178	POL	154	SAV-DNK	CS	Right of Way police hold Vehicle fatality near tracks SCHP investigation
41	MIA	73	FTI	167	PTI	50	SAV-XJG	CS	Meet P052-11, Siding, N Ludowici
26	MOE	35	MBO	33	MBO	33	BAS-GUF	CS	For maritime traffic Bridge, Bay St. Louis
523	SJC	53	DCS	39	DCS	35	HAY-FMT	UP	Restrictive signal(s) from known wayside signal failure Flag from RV021 to FO 30. Hand line switches at FO 30., Red, Control Point, NI021
526	SAC	22	MBO	30	MBO	30	MTZ-SUI	UP	For maritime traffic Control Point, Vista
527	SJC	24	DCS	22	DCS	20	HAY-FMT	UP	CTC system failure Milepost, 20, 30

Amtrak Endpoint OTP Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
528	SAC	38	DCS	32	DCS	32	FMT-HAY	UP	Restrictive signal(s) from known wayside signal failure Authority 6-82 Authority 6-83, Stop, Stop, Control Point, Shinn, Control Point, FO30
529	SJC	104	DCS	67	DCS	67	HAY-FMT	UP	Restrictive signal(s) from known wayside signal failure Flagged through block (S. Hayward from Shinn). Taking multiple switches in hand at Nile's junction. Flagged through Shinn., Red, Control Point, NI019
530	SAC	19	RTE	16	RTE	16	FMT-HAY	UP	Line manual or spring switch Control Point, FO030
531	OKJ	23	MBO	31	MBO	31	SUI-MTZ	UP	For maritime traffic Bridge, Benicia
539	SJC	35	PTI	15	CTI	12	HAY-FMT	UP	Meet Altamont Commuter Express, ACE 02, Control Point, CPNI 030 Niles Junction
543	SJC	27	PTI	17	PTI	15	GAC-SCC	UP	Meet Shuffle, 544, Siding, expressway
547	SJC	24	DCS	24	DCS	17	SUI-SUI	UP	PTC- Unplanned PTC system /server outage Instructed by PTC help desk to reboot PTC by switching breakers, Other, SUI
502	SEA	20	FTI	17	FTI	8	TUK-SEA	BN	Meet BNSF engine unknown, Control Point, Bailey
503	EUG	39	ADA	28	FTI	15	KEL-VAN	BN	Meet up 4001, Control Point, ridge field S
508	SEA	16	PTI	15	PTI	10	SLM-ORC	UP	Meet 507, Control Point, Coalca
509	PDX	30	INJ	26	INJ	26	TAC-TAC	ST	Injured or sick passenger Passenger fell ill and was transported to a local hospital.
517	PDX	17	DSR	8	DCS	7	XTW-TAC	ST	PTC- I-ETMS Red Fence/Signal Status Unknown Control Point, Portland Ave
518	VAC	Trn Cancelled	PTI	38	PTI	17	KEL-CTL	BN	Meet amt507, Control Point, centralia south
58	CHI	131	SYS	91	SYS	84	JAN-JAN	CC	Crew rest
59	NOL	17	DSR	86	DSR	14	MEM-MKS	CC	Per bulletin Milepost, 6.8, 7, 60, 1, Milepost, 12, 12.7, 25, 1, Milepost, 13.7, 14.30, 60, 1, Milepost, 21, 23.5, 25, 1, Milepost, 34, 34.30, 60, 1, Milepost, 46.2, 46.5, 60, 1, Milepost, 55.40, 55.8, 60, 1, Milepost, 59.1, 59.5, 30, 1, Milepost, 60.40, 61.80, 25, sdg, Milepost, 62.1, 62.5, 60, 1,
8	CHI	57	FTI	206	FTI	55	MAL-GGW	BN	Meet Tuck and duck, bn 7566, Siding, tampico

Amtrak Endpoint OTP Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	18	DSR	35	DSR	15	GLE-FTW	BN	Per bulletin Milepost, 407.9, 407.1, 30, main, Milepost, 385.5, 385.3, 30, main, Milepost, 396.7, 396.1, 30, main, Milepost, 389.7, 389.0, 25, main, Milepost, 384.2, 383.4, 25, main, Milepost, 383.1, 381.7, 40, main, Milepost, 382.7, 382.5, 30, main, Milepost, 380.8, 379.5, 40, main, Milepost, 346.5
822	OKC	68	FTI	48	FTI	48	FTW-GLE	BN	Meet bnsf 8360, Siding, valley view, Z
341	MKE	43	OTH	33	ITI	22	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 1340
350	PNT	19	PTI	42	PTI	19	XB0-XA5	MI	Meet Siding, albion, 353
354	PNT	37	FTI	30	FTI	14	XH6-XPI	NS	Follow Followed 60A, on M1 and M2 up to 485, 60A, Control Point, 494, Control Point, 485
364	PTH	35	DSR	23	FTI	22	XH6-XPI	NS	Follow Milepost, 501, 485, BNSF 9032
365	CHI	50	PTI	44	PTI	44	XH6-XTF	NS	Train49 equipment failed during the equipment move blocking mains 4/5 holding us and 302 out of the station yard move, Milepost, 519, 521
562	SAN	37	CTI	19	DSR	13	XRJ-FUL	BN	Per bulletin Milepost, 144.5, 144.6, 25, 1, Milepost, 155.7, 156.7, 25, 1
564	SAN	63	DMW	30	DMW	30	SNC-SNP	SC	Held for or routed around MW work or equipment Control Point, pier
566	SAN	60	PTI	62	PTI	57	SNC-SNP	SC	Meet 769, Control Point, serra
567	LAX	52	DCS	23	RTE	20	OSD-OSD	SN	Dispatcher hold Held at OSD due to all trains flagging at Songs. Train 562 had just hit lantern, Other, oceanside
572	SAN	50	CTI	28	CTI	11	OSD-OSD	SN	Meet Waited for coaster to leave OSD pocket track and another to arrive., coaster, Control Point, Pacific
573	LAX	39	CTI	36	CTI	23	OSD-X98	SN	Meet Metrolink, 608, Control Point, don
579	LAX	32	PTI	36	PTI	29	OSD-X98	SC	Follow 777, Control Point, songs
580	SAN	17	DCS	12	DCS	10	SNP-X98	SC	Restrictive signal(s) from known wayside signal failure CP PIER, Control Point, pier
581	LAX	74	ITI	30	ITI	30	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 770
584	SAN	35	DSR	16	DCS	15	X98-OSD	SN	Restrictive signal(s) from unknown cause Stop , Control Point, eastbrook
587	LAX	82	SYS	53	SYS	53	SAN-SAN	SN	Other late crew Waited for 774 equipment, Other, SAN

Amtrak Endpoint OTP Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
588	SAN	51	PTI	42	PTI	42	SNC-SNP	SC	Meet Signal issues near the Pier area again, trains flagging through, 591, Siding, Serra
591	LAX	35	PTI	20	PTI	20	OSD-X98	SN	Meet 786, Control Point, songs
593	LAX	35	PTI	36	PTI	34	OSD-X98	SN	Meet 588, Control Point, SONGS
595	LAX	No OS Rpt	PTI	48	PTI	45	OSD-X98	SN	Meet 790, Control Point, song
757	SLO	16	PTI	27	PTI	27	GTA-X3G	UP	Meet 774, Siding, S Ellwood
765	SLO	77	DCS	39	PTI	34	X3G-LPS	UP	Meet 786, Siding, Sudden
769	GTA	59	PTI	48	PTI	35	OSD-X98	SN	Meet 564, Control Point, songs
770	SAN	74	PTI	52	PTI	40	SNC-SNP	SC	Meet 573, Control Point, Serra
774	SAN	154	PTI	109	PTI	99	SNC-SNP	SC	Meet 777, 579, Control Point, serra
777	SLO	129	DCS	53	SYS	30	OSD-X98	SN	Copy authority / restriction Control Point, songs
785	GTA	140	SVS	75	SVS	75	LAX-LAX	SC	Pick up equipment Equipment swap TUK Amtrak 587 Equipment, Milepost, 0.0, 0.0
786	SAN	42	DCS	51	PTI	20	GUA-LPS	UP	Meet 14, Siding, Tangier
790	SAN	51	CTI	31	CTI	28	SNC-SNP	SC	Meet metrolink, Control Point, serra
702	BFD	22	FTI	34	FTI	11	XSC-XSK	BN	Cross Traffic Obstructed from entering BNSF account westbound BNSF freight hand-lining through UP crossing., BNSF 8275 West, Control Point, Keddie Jct
714	BFD	122	TEN	110	TEN	110	OKJ-OKJ	UP	Set out defective locomotive C2124 reported with traction motor oil leak. Instructed to switch out locomotives, replaced defective locomotive with C2006., C2124
715	OKJ	25	PTI	32	PTI	12	WAC-COC	BN	Meet AMTK 702, Control Point, West Angiola
716	BFD	32	PTI	86	PTI	49	TRK-MCD	BN	Wait for station track amt 714/717, Siding, Fluhr
717	OKJ	42	PTI	41	PTI	23	MDR-MCD	BN	Meet Shuffle, 714, Control Point, merced xover
718	BFD	54	PTI	30	TEN	15	OKJ-OKJ	UP	Fixing alerter C2009
3	LAX	216	FTI	211	DCS	67	NDL-BAR	BN	Restrictive signal(s) from known wayside signal failure Flagging W Danby & E Danby restricted speed, PTC Holding @ 641, Restricting, Control Point, W Danby
1	LAX	319	FTI	437	FTI	100	XIC-XTH	UP	Follow mtuwc, Milepost, 646.0, 620.2
302	CHI	48	PTI	52	PTI	52	XTF-CHI	AM	Meet 49/449, Control Point, Lumber

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
305	STL	16	PTI	22	PTI	16	BNL-LCN	UP	Meet 306, Siding, athol
307	STL	73	TRS	76	TRS	76	LCN-SPI	UP	Vehicle on track ahead Milepost, 183.4, 183.4
392	CHI	38	FTI	40	FTI	22	RTL-GLM	CC	Meet Main 2 empty at Gilman, Control Point, N Paxton, Z 194
311	KCY	30	POL	23	POL	23	JEF-SED	UP	Right of Way police hold Trespasser. Possible suicide intent. Wait for local police and RMCC release.
319	KCY	34	FTI	28	PTI	17	JEF-SED	UP	Meet Amtrak 316, Siding, Dow
1340	CHI	45	DMW	46	DMW	46	CBS-MKE	CP	Hold for defect repair Control Point, Peawaukee

Amtrak Initial Terminal Details

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/12/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	10/11	293	279	Late train arrival
ALB	448	10/11	293	14	Planned set out / pick out of locomotives, cars or section of train Other, ALB
BON	687	10/12	38	38	Late departure at initial terminal due to late arrival of inbound equipment 686, 686 arrived into BON at 5:40 pm
BOS	2149	10/12	48	48	Door, 3650|NG|NB, DP BOS 48" LATE DUE TO DOOR ISSUES, GAP FILLER CUT IN
BRK	680	10/12	1		
HAR	656	10/12	1	1	Passenger and/or baggage
HFD	473	10/12	2	2	Issue with automatic road crossing protection, Milepost, HFD, HFD, COPY FORM "D" FOR STOP AND PROTECT NORTH COLONY STREET (MP 19.4) AND BRITTANIA (MP 19.5)
NHV	474	10/12	18	18	Planned set out / pick out of locomotives, cars or section of train, Train 474 will be delayed departing NHV a/c late from yard for congestion
NYP	43	10/12	81	81	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	49	10/12	2	2	Cab signal failure, 704|DX|DM, DELAYED 15" AT F INTERLOCKING DUE TO ACSES STOP BY-PASS FUNCTION NOT ACCEPTING CODES.
NYP	97	10/12	21	21	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C IT WAS NECCESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND SERVICE CARS
NYP	237	10/12	31	31	Late departure at initial terminal due to late arrival of inbound equipment, 284, LATE TURN OFF AM284
NYP	655	10/12	17	17	Late departure at initial terminal due to late arrival of inbound equipment, 650, LATE ACCOUNT LATE TURN FROM AM650. ALSO DELAYED DUE TO A LATE SHOPPED ENGINE SSYD.
PGH	42	10/12	2	2	High passenger count AMTK 40 loading at same time and 1 PGH station services member
PHL	643	10/12	4	4	PTC - Stop Bypass Permission Required, Control Point, ., Stop bypass on e/ 600.
PHL	657	10/12	5	5	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	1144	10/12	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
WAS	1128	10/12	16	16	Removal of passenger by police, UNRULY PAX
WAS	1140	10/12	12	12	Other electrical failure, 665|EX|ES, NEC'Y TO CHANGE HEADLIGHT
WAS	1168	10/12	7	7	Delay in Block, CNDR WAITED TIL DEP TIME TO REPORT A HOT CAR
CHI	5	10/12	6	6	Air / Brake 145, 5
CHI	7	10/12	3	3	Seals replaced 381

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/12/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	10/12	79	79	Late departure at initial terminal due to late arrival of inbound equipment 40, 40 , 7 hrs late arrival into chicago on 10/12
CHI	48	10/12	153	153	Set out defective car 25090
CHI	307	10/12	22	22	HEP ID4620
CHI	341	10/12	29	7	North gate would not answer radio to clear train. Now will be behind Metra until Roundout
CHI	341	10/12	29	22	Late departure at initial terminal due to late arrival of inbound equipment 1340
CHI	354	10/12	9	9	Door ID4017, Door is damaged with an active alarm sounding the whole journey. We could see outside thru the crack on the right. The door was “adjusted” closed a bit more but not enough to satisfy the alarm. Mechanical said they cannot touch it or they will be fired
BFD	717	10/12	5	5	Hold for thruway bus
GTA	782	10/12	6	6	Meet A14, Control Point, S. Ellwood
LAX	572	10/12	1	1	Door 6408
OKJ	526	10/12	3	3	Meet 11, Control Point, North Jack London
OKJ	540	10/12	1	1	Meet 540, Control Point, ni007
OKJ	714	10/12	110	110	Set out defective locomotive C2124 reported with traction motor oil leak. Instructed to switch out locomotives, replaced defective locomotive with C2006., C2124
OKJ	716	10/12	5	5	Wait for station track amt 714, Control Point, okj
OKJ	718	10/12	11	6	Meet Late spot at OKJ waiting on train traffic., 715, 542, Control Point, Magnolia
OKJ	718	10/12	11	5	Meet Late departure waiting for Amtrak 545 to arrive., 545, Control Point, N. Jack London
PDX	502	10/12	1		
SAN	581	10/12	30	30	Late departure at initial terminal due to late arrival of inbound equipment 770
SAN	587	10/12	53	53	Other late crew Waited for 774 equipment, Other, SAN
SAN	785	10/12	18	18	Late departure at initial terminal due to late arrival of inbound equipment 774
SEA	503	10/12	3	3	Dispatcher hold Control Point, king street
SEA	517	10/12	30		
SJC	544	10/12	1	1	Meet CalTrain/JPBX, JPBX 928 South, Control Point, Shark
SLO	786	10/12	4	4	Engine switch left on isolate. No load at departure time. Other, SBA Sub

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	99.4	94.8	342	3
CDOT	95.0	91.7	87.5	92.4	24	2
MARC	95.0	79.3	85.8	90.2	58	12
SEPTA	95.0	92.8	90.0	91.5	221	16
NJT-NED	95.0	89.4	90.3	88.6	180	19
NJT-SED	95.0	100.0	98.6	97.2	24	0

Operating Highlights

Train 448(11) - West of Springfield, MA - Freight Train Interference

13OCT26: Train 448(11) was delayed on the CSX Berkshire Subdivision at MP 123.3 due to meeting CSX Train I013-12.

Train	Delay	Comment
448(11)	35"	

Train 448(11) - Albany-Rensselaer Station, NY - Engine Swap

12OCT26: Train 448(11) was delayed at Albany-Rensselaer Station, NY due to delays involving the regular engine swap and equipment manipulation.

Train	Delay	Comment
448(11)	53"	

Train 90(12) North of Rocky Mount, NC - Freight Train Interference

12OCT26: Train 90(12) with E/377 and 7 cars was delayed on the CSX North End A subdivision at MP 51.4 due to meeting 3 different CSX freights.

Train	Delay	Comment
90(12)	31"	

Train 52(11) North of Florence, SC - Freight Train Interference

12OCT26: Train 52(11) with E/360, E/384, E/516 and 50 cars was delayed on the CSX South End A subdivision due to meeting CSX M491 at CP South Latta, CP North Hamill and CP South Beard.

Train	Delay	Comment
52(11)	37"	

27-FOI-00046 000000008947 "UNCLASSIFIED" 10/19/2026

Train 284(12) East of Syracuse, NY - Freight Train Interference

12OCT26: Train 284(12) with E/08x, E/7xx and 5 cars was delayed on the CSX Mohawk subdivision due to meeting several CSX freights at MP 283, 198, 177, 178, 177 and then following CSX W068 from MP 177 to MP 169. They were further delayed on the Metro North Hudson Line due to following MNRR 870 from MP 72 to MP 34. Then meeting Metro North Traffic at CP 33 and then following MNRR 870 again from MP 34 to MP 15.

This also caused delay to train 237(12) due to turning off the late 284(12).

Train	Delay	Comment
284(12)	31"	MNRR commuter
284(12)	52"	CSX Freights
237(12)	31"	late turn 284(12)

Train 650(12) West of Philadelphia, PA - Engine Failure

12OCT26: Train 650(12) with E/637, CC/9646 and 4 cars was delayed upon departure at Philadelphia due to wying the equipment.

Train	Delay	Comment
650(12)	35"	
655(12)	17"	Turn off 650(12)

Train 55(12) North of Springfield, MA - Passenger Train Interference

12OCT26: Train 55(12) with E/119 and 5 cars was delayed on the CSX Berkshire QB subdivision at MP 98.6 due to be held out of the diamond north of Springfield by Train 449(12). Train 55(12) received a rule 241 at sweeney track 3 to 2 south. Train 56(12) was also incurred a delay departing.

Train	Delay	Comment
55(12)	59"	
56(12)	46"	

Train 686(12) South of Portland, ME - Engine Failure

12OCT26: Train 686(12) with E/130 and CC/90220 was stopped due to a work area restriction on the CSX Portland PLD subdivision at MP 17.4. When the train attempted to proceed, it experienced a PTC fault that required a system reboot. After the reboot was completed, the train resumed operation.

The delay to Train 686(12) also impacted Train 683(12), which was delayed while meeting Train 686(12).

Train 687(12) was delayed due to late turn off 686(12).

Train	Delay	Comment
686(12)	1'07"	
683(12)	39"	
687(12)	38"	

Train 2106(12) Metropark, NJ - Engine Failure

12OCT26: Next Gen 2106(12) set 21, PC/2122 and PC/2129, was stopped for inspection after a hot box detector alarm indicated a possible issue on axle 9. The crew inspected both sides of the train and found no exceptions.

Train	Delay	Comment
2106(12)	44"	

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Train 43(12) New York, NY - Servicing

12OCT26: Train 43(12) with E/648 and 7 cars delayed departing New York due to the late release from the yard.

Train	Delay	Comment
43(12)	1'21"	

New York to Philadelphia Main Line - Bridge Strike

12OCT26: At 1130A-ET A vehicle struck the bridge at McClellan St., MP 12.37, New York to Philadelphia Main Line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1146A-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
2149(12)	02"	
1- NJT	02"	

Train 2149(12) Metropark, NJ - Gap Filler Issues/Car Failure

12OCT26: Next Gen train 2149(12) set 11 PC/2116, PC/2117 was delayed at MP 23.2/Metropark on the New York to Philadelphia main line due to having gap filler issues on two cars.

Train	Delay	Comment
2149(12)	37"	

Train 1155(12) Philadelphia, PA - Car Failure

12OCT26: Train 1155(12) E/659 and 8 cars was delayed in Philadelphia due to needing mechanical assistance to help get the doors closed on the entire consist.

Train	Delay	Comment
1155(12)	35"	

Train 1160(12) East of New York, NY - Engine Failure

12OCT26: Train 1160(12) with E/621 and 8 cars with 449 customers onboard reported that they were having HEP trainline supply fault on the Hellgate. The crew reported they were unable to reset and were operating dark into New Haven. New Haven mechanical met the train upon arrival and reset the breaker on E/621. They were able to restore HEP and departed with E/621 only.

Train	Delay	Comment
1160(12)	09"	NHV ADDING ENGINE

Train 41(10) South of Savannah, GA - Passenger Train Interference

12OCT26: Train 41(10) with E/182, E/11 and 10 cars was delayed on the CSX Nahunta subdivision at MP 533.4 due to meeting 52(11). Train 52(11) was also delayed meeting 53(11) at the same location.

Train	Delay	Comment
41(10)	50"	
52(11)	20"	

27-FOI-00046 000000008947 "UNCLASSIFIED" 10/19/2026

Train 52(11) South of Jesup, GA - Freight Train Interference

12OCT26: Train 52(11) with E/6260, E/3804, E/5516 and 50 cars was delayed on the CSX Nahunta subdivision at MP 533.4 due to meeting CSX IO97.

Train	Delay	Comment
52(11)	30"	

Train 53(11) South of Savannah, GA - Passenger Train Interference

12OCT26: Train 53(11) with E/352, E/380 and 49 cars was delayed meeting 52(11) at MP 540.1/Backswamp on the CSX Nahunta subdivision.

Train	Delay	Comment
53(11)	35"	

Train 2149(12) Boston, MA - Car Failure

12OCT26: Next Gen 2149(12) set 11 PC/2116, PC/2117 was delayed departing Boston due to not being able to close the doors. The crew was trouble shooting with the Road Foreman. High Speed mechanical was on scene assisting. Engineer reported they were getting a door light signal. As of 632A-ET It was determined to de-prepare the set. As of 647A-ET, High Speed reported that they were waiting on a technician to arrive and test ACSES.

Train	Delay	Comment
2149(12)	48"	

Train 52(12) and 53(12) - Cancelled - Miscellaneous Amtrak Responsible

11OCT26: Trains 52(12) and 53(12) are cancelled in their entirety due to late operation of 53(10).

Train	Delay	Comment
52(12)	cancelled	
53(12)	cancelled	

Maintenance of Way Highlights

27-FOI-00046 0000008847 "UNCLASSIFIED" 10/19/2026

MBTA Downeaster Track Work - Scheduled M/W Work - TW 26-094 - 9/12-10/11

21AUG26: To support the MBTA bridge replacement at MP 8.99 the below service adjustments have been made:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound
• Trains 693 and 695 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 699 (13Sep, 20Sep, 4Oct, 10Oct-11Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 1689 (12Sep, 19Sep, 26Sep-27Sep, 3Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

o Please note Trains 691 and 697 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct) will operate NORMAL.

Southbound
• Trains 690, 692, 694, 696, and 698 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

WBS#: B.TR.100150.7065

Train	Delay	Comment
696(03)	35"	HHL-WOB
695(03)	30"	BON-HHL

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046, 00000008947 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), will originate at HFD as a deadhead train that will operate deadhead between NHV and HFD.

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Train 58(12) North of Fulton, KY - Passenger Train Interference

13OCT26: Train 58(12), with 149 customers onboard, was delayed at Fillmore siding/MP366.2, 38 miles north of Fulton, KY/MP404.6 on the CN Cairo subdivision meeting Amtrak train 59(12). Once the route was clear, train 58(12) continued north.

Train	Delay	Comment
58(12)	30"	

Train 6(11) Denver, CO - Engine HVAC Failure

12OCT26: Train 6(11), with engines 147, 45, and deadhead 205, 8 cars, and 160 passengers onboard, was delayed departing Denver, CO/MP0.0 on the BNSF Front Range subdivision due to HVAC failure on the leader engine 147. Engines 147 and 45 were flat switched. Once the equipment was made up complete, train 6(11) departed Denver, CO.

Train	Delay	Comment
6(11)	1'32"	

Train 22(12) South of Texarkana, AR - Signal Issue

12OCT26: Train 22(12), with 120 customers onboard, was delayed at mile post 2.4, 2.4 miles south of Texarkana, AR/MP0.0 on the UP Little Rock subdivision due to hand-lining the switch at that location. Once the route was open, train 22(12) continued north.

Train	Delay	Comment
22(12)	35"	

Train 26(12) North of Bay Saint Louis, MS - Drawbridge Opening

12OCT26: Train 26(12), with 99 customers onboard, was delayed at the Bay St Louis Bridge/MP752.5 on the CSX N.O.&M. subdivision while it was open for maritime traffic. Once the route was clear, train 26(12) continued north.

Train	Delay	Comment
26(12)	33"	

27-FOI-00046 00000008947 UNCLASSIFIED 10/19/2026

Train 41(12) Chicago, IL - Late Turn of Equipment

12OCT26: Train 41(12) with 250 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late turn of equipment off late arriving train 40(10). Train 41(12) was made up of the cars of train 49/449(11) and the locomotives off train 40(10). Once the equipment was made up complete, train 41(12) shoved into the depot, boarded customers and departed Chicago Union Station.

Train 48/448(12), 264 customers to board, was also delayed departing Chicago Union Station, due to late equipment. After the initial make-up of the cars off train 40(10) and the locomotives off train 49/449(11), Chicago Mechanical shopped coach car 25090 off the 448(12) portion for brake issues. The car needed to be held out in Chicago. Twenty-three customers out of Chicago were accommodated on the 48(12) portion of the train. For fifty-three customers out of Cleveland, OH through Syracuse, NY, were notified and advised to book the next available train. Once train 48/448(12) was made up complete, the equipment shoved into the depot, boarded customers, and departed Chicago Union Station.

Train	Delay	Comment
41(12)	1'19"	
48/448(12)	2'33"	

Train 1340(12) West of Milwaukee, WI - M of W Work

12OCT26: Train 1340(12), with 210 customers onboard, was delayed at the Pewaukee control point/MP104.2, 19.64 miles west of Milwaukee, WI/MP85.4, on the CPKC Watertown subdivision holding for track inspectors to repair a defective switch. The conductor reported that hand-lining the switch did not work. Once the track inspector made repairs to the switch, train 1340(12) continued east.

Train 7/27(12), with 249 customers onboard, was also delayed holding for the switch repair at Pewaukee.

Train	Delay	Comment
7/27(12)	57"	
1340(12)	48"	

Train 714(12) Oakland, CA - Third Party Contractor Engine Failure

12OCT26: Train 714(12) was delayed departing Oakland Jack London Square, CA, on the Union Pacific Niles Subdivision due to a locomotive change. Locomotive C2124 was removed from service after a traction motor oil leak was identified and was replaced with locomotive C2006. Once the replacement locomotive was coupled, the equipment was flagged, inspected, and released for service.

Train 716(12) incurred delays while following Train 714(12) between Oakland Jack London Square and Bakersfield, CA. Train 716(12) experienced additional delay while holding at Fluhr Siding (MP 1062.9) on the BNSF Stockton Subdivision while awaiting access to Merced Station as 714(12) was meeting Amtrak Train 717(12).

Train	Delay	Comment
714(12)	1'50"	
716(12)	27"	following OKJ-BFD
716(12)	49"	Fluhr SIding
717(12)	23"	meeting 714(12)

27-FOI-00046 00000008947 UNCLASSIFIED 10/19/2026

Train 765(12) Lompoc-Surf, CA - Passenger Train Interference

12OCT26: Train 765(12), carrying 175 customers onboard, was delayed south of Lompoc-Surf Station while holding at Sudden Siding (MP 313.4) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 786(12).

Train	Delay	Comment
765(12)	34"	

Train 3(11) East of Albuquerque, NM - Commuter Train Interference

12OCT26: Train 3(11), carrying 131 customers onboard, was delayed east of Albuquerque, NM, on the NMRX Glorieta Subdivision due to commuter train interference. The train followed NMRX 104 from Madrid (MP 858) and later met NMRX 1102 at East Alameda (MP 894.7).

Train	Delay	Comment
3(11)	33"	

Suisun Bay Bridge East of Martinez, CA - Drawbridge Opening for Maritime Traffic

12OCT26: The Suisun Bay Bridge (MP 33.2) on the Union Pacific Martinez Subdivision, 2 miles east of the Martinez, CA station, opened for maritime traffic.
Train 531(12) and Train 526(12) were delayed awaiting the bridge closure.

Train	Delay	Comment
531(12)	31"	
526(12)	30"	

Train 22(12) Fort Worth, TX - Servicing

12OCT26: Train 22(12) with 116 customers was delayed at Fort Worth on the BNSF Fort Worth subdivision due to adding C/34099, C/33011, and C/34057 to the rear of the consist from the big game train. Once the cars were added to the consist, 22(12) departed Fort Worth at 319PM-CT, 56 minutes late.

Train	Delay	Comment
22(12)	33"	

Train 3(10) East of Barstow, CA - Routing

12OCT26: Train 3(10) was delayed east of Barstow, CA, on the BNSF Needles Subdivision due to signal problems. The delay occurred at Control Point Daggett (MP 737.7), where crews were required to manually line switches and route the train through crossovers and frogs because of signal system issues. Train 3(10) operated through the affected area under restricted conditions until the route was properly lined and authorized for movement. Once clear of the affected territory, the train resumed normal operations.

Train	Delay	Comment
3(10)	34"	

Train 4(11) Albuquerque, NM - Commuter Train Interference

12OCT26: Train 4(11), carrying 190 customers onboard, was delayed in Albuquerque, NM, at Marquette (MP 902.06) on the NMRX Glorieta Subdivision while meeting a commuter train.

Train	Delay	Comment
4(11)	27"	

27-FOI-00046 00000008947 "UNCLASSIFIED", 10/19/2026

Train 3(10) Needles, CA - Freight Train Interference

12OCT26: Train 3(10) was delayed west of Needles, CA, on the BNSF Needles Subdivision due to freight interference. The delay occurred while following a BNSF freight train through Fenner Siding at MP 622.6. Train 3(10) was required to operate behind the slower-moving freight movement until sufficient track capacity became available. Once the freight train cleared the route, Train 3(10) resumed normal operations and continued westbound service.

Train	Delay	Comment
3(10)	38"	

Train 3(10) West of Needles, CA - Signal

12OCT26: Train 3(10) was delayed west of Needles, CA, at MP 634.8 on the BNSF Needles Subdivision due to signal problems. The delay was caused by restrictive signals resulting from a known wayside signal failure between West Danby and East Danby. As a result, the train operated at restricted speed through the affected territory and was held by PTC at MP 641 near Control Point West Danby. Once the signal issue was addressed and dispatcher authorization was received, Train 3(10) resumed normal operations.

Train	Delay	Comment
3(10)	1'07"	

Train 7/27(11) West of Minot, ND - Freight Train Interference

12OCT26: Train 7/27(11) was delayed 10 miles west of Minot, ND, on the BNSF Glasgow Subdivision due to freight interference. The delay occurred while meeting freight train BNSF 6920 at CP 106. Train 7/27(11) held for the freight movement to clear the route before continuing westbound service. Once the meet was completed and authorization was received from the dispatcher, the train resumed normal operations.

Train	Delay	Comment
7/27(11)	34"	

Capitol Corridor Delays South of Fremont, CA - Signal issues

12OCT26: Capitol Corridor trains were delayed south of Hayward, CA, on the UPRR Niles Subdivision due to signal issues. The delay was caused by restrictive signals resulting from a known wayside signal failure between Niles Junction and Cherry Street. Additionally, hand-lined switches were required between MP 29.7 and MP 34.5 to safely route the train through the affected territory. Once crews completed the required hand-switch operations and navigated the area under the applicable signal restrictions, Train 523(12) resumed normal operations.

Train	Delay	Comment
523(12)	35"	
528(12)	51"	
527(12)	31"	
528(12)	24"	Meet 527(12)
529(12)	44"	RECREW/HOS
529(12)	1'07"	
530(12)	10"	

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Train 49/449(11) Chicago, IL - Engine Failure

12OCT26: Train 49/449(11) equipment with E/375-131 and 14 cars became disabled with computer issues inside the interlocking at CP Lumber and blocking both mains 4 and 5 while YC6 was in the process of operating from the station to the yard. Mechanical and the trainmaster responded to the scene to assist. Trains 302(12) and 365(12) were delayed holding for open track. Mechanical arrived, swapped out a power supply for the PTC computer on E/131, and the equipment was able to clear CP Lumber into the yard.

Train	Delay	Comment
302(12)	52"	
365(12)	44"	
Metra 809	40"	
Metra 816	19"	

Train 4(11) East of Kingman, AZ - Freight Train Interference

12OCT26: Train 4(11), carrying 195 customers onboard, was delayed east of Kingman, AZ on the BNSF Seligman Subdivision due to following BNSF 7578 from MP 484.1 to MP 453.8

Train	Delay	Comment
4(11)	45"	

Train 1(12) West of New Orleans, LA - Freight Train Interference

12OCT26: Train 1(12) with 118 customers was delayed six miles west of New Orleans on the CN McComb subdivision due to meeting unknown freight at East Bridge Jct./MP 906.4.

Train	Delay	Comment
1(12)	36"	

Train 24(12) West of Bay Saint Louis, MS - Passenger Train Interference

12OCT26: Train 24(12) with 91 customers was delayed on the CSX NO&M subdivision 12 miles west of Bay Saint Louis due to meeting train 23(12) at Claiborne/MP 766.3.

Train	Delay	Comment
24(12)	35"	

Train 3(10) Kingman, AZ - Freight Train Interference

12OCT26:Train 3(10) carrying 175 customers onboard, was delayed west of Kingman, AZ on the BNSF Seligman Subdivision due to meeting a BNSF freight at Griffith siding at MP 528.8.

Train	Delay	Comment
3(10)	40"	

Train 23(12) East of Bay Saint Louis, MS - Freight Train Interference

12OCT26: Train 23(12) with 119 customers was delayed on the CSX NO&M subdivision eight miles east of Bay Saint Louis at Harbin/MP 746.8 due to meeting M602.

Train	Delay	Comment
23(12)	34"	

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

UPRR Yuma Sub Track Washout E/Palm Springs

12OCT26: At 10:55 a.m. PT on October 11, 2026, UPRR reported a track washout approximately 50 miles east of Palm Springs, AZ, at MP 636.8 on the Sunset Limited Route. A freight train was in the affected area, and a ballast train was dispatched from Tucson to support emergency track repairs.

Following repair efforts, the track was reopened at 6:46 p.m. PT. However, significant freight and passenger train congestion remained in the territory after the outage. As a result, Train 1(10)/421(09) and Train 2/422(11) were expected to experience delays while rail traffic was restored to normal operations through the affected segment.

Train	Delay	Comment
2/422(11)	17"	Held PSN
1(10)/421(09)	1'22"	YUM-XIC
2/422(11)	26"	PSN-XTH
2/422(11)	1'02"	XTH-CIC
1(10)/421(09)	2'57"	XIC-XTH
1(10)/421(09)	40"	
2/422(11)	1'55"	XIC-YUM
2/422(11)	1'46"	YUM-XZS
2/422(11)	1'44"	XZS-MRC

Train 4(11) West of Kingman, AZ - Freight Train Interference

12OCT26: Train 4(11), carrying 193 customers onboard, was delayed west of Kingman, AZ on the BNSF Seligman Subdivision due to meeting a BNSF freight at Griffith siding at MP 528.8.

Train	Delay	Comment
4(11)	47"	

27-FOI-00046 00000008947 UNCLASSIFIED 10/19/2026

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

12OCT26: Pacific Surfliners scheduled and experienced delays due to high-tide conditions affecting the Metrolink Orange Subdivision east of San Clemente Pier between CP Pier (MP 205.14) and CP SONGS (MP 209.18). The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. Single-track operations between CP Serra (MP 199.9) and CP SONGS contributed to additional train meets and cascading delays throughout the corridor.

The following equipment adjustments were implemented to mitigate service impacts:

-Equipment from Train 572(12) was turned at San Diego, CA, to operate Train 785(12) between San Diego and Los Angeles.
-Equipment from Train 774(12) was turned at San Diego to operate Train 587(12).
-Upon arrival in Los Angeles, CA, the Train 587(12) equipment was reassigned to operate Train 785(12) between Los Angeles and Goleta, CA.

WBS#: B.TR.100150.7263

Train	Delay	Comment
769(12)	48"	
564(12)	48"	
566(12)	1'09"	
770(12)	1'12"	
777(12)	1'20"	
579(12)	36"	
774(12)	2'40"	
581(12)	38"	
581(12)	30"	late turn 770(12)
580(12)	14"	
587(12)	53"	late turn 774(12)
587(12)	38"	
785(12)	18"	late depart SAN equip swap
785(12)	55"	
785(12)	1'15"	equip swap at LAX
782(12)	20"	
584(12)	32"	
591(12)	44"	
593(12)	49"	
595(12)	1'12"	
588(12)	1'00"	
786(12)	18"	
790(12)	27"	late inbound 785(12) at LAX
790(12)	43"	
794(12)	18"	

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Cascades Fraser Bridge Blocking Event

11OCT26: A Fraser Bridge malfunction at BNSF Westminster Subdivision MP 143.4 on the Canadian side is blocking Cascades service between Vancouver, British Columbia, and Seattle, Washington. BNSF's estimated time for reopening the bridge is 0000 on October 12, 2026.

As a result, the following service adjustments were implemented:

Trains 516/519(11) were canceled in their entirety, and alternate transportation was arranged for affected passengers. Three buses were secured to accommodate 516(11) customers. Two buses were secured for 519(11) customers.

Trains 517/518(11) were canceled between Vancouver, BC, and Seattle, WA, and alternate transportation was arranged for affected passengers. Four buses were secured to accommodate 517(11) customers and three buses secured for 518(11) customers.

These service disruptions were necessary due to the operational impacts of the Fraser Bridge blockage and the inability of rail traffic to move across the affected bridge segment.

12OCT26: BNSF's updated estimate for bridge reopening was moved to 0600 on October 12, 2026 with possibility this could be later.

Significant congestion is expected due to numerous freight trains tied down in the Greater Vancouver Terminal area. The following service adjustments are necessary:

Trains 516/519(12) were cancelled in their entirety. Four buses were secured for 516(12); Two buses were secured for 519(12).
Trains 517/518(12) was cancelled between Vancouver, BC to Seattle, WA and will originate and terminate in Seattle, WA, respectively. Three buses were secured to accommodate 517(11) customers. Three buses were secured for 518(12) affected customers.

13OCT26: The updated estimate for the Fraser River Bridge reopening was once again pushed back to 7:00 AM PT on October 13, 2026 as crews continue to work on repairs. Further Cascades service adjustments were made:

Train 516(13) was cancelled entirely with alternate bus transportation secured.
Train 517(13) was cancelled between Vancouver, BC to Seattle, WA and will originate and terminate in Seattle, WA. Alternate bus transportation was secured.

WBS#: B.TR.100150.7259

Train	Delay	Comment
518(11)	XCLD SEA-VAC	
519(11)	CANCELED	
517(11)	27"	XCLD VAC-SEA
517(12)	27"	Orig Sea
516(12)	Canceled	
518(12)	Term SEA	
519(12)	Canceled	
516(11)	CANCELED	
516(13)	Canceled	
517(13)	Orig SEA	

Tropical Storm Isaias- Weather

07OCT26: Tropical Storm Isaias formed in the southern Gulf and was forecast to strengthen into a hurricane before making landfall near Mobile Bay. Damaging winds, flooding rain, storm surge, and tornadoes were expected across portions of the U.S. Gulf Coast, particularly Alabama, eastern Mississippi, eastern Louisiana, and the western Florida Panhandle. Due to the anticipated storm impacts, Crescent and Mardi Gras service will be modified.
Crescent
Train 19(07) will terminate at the Atlanta, GA station. Alternate transportation will be provided by 3 buses.
Trains 19(08-10) will terminate at the Atlanta, GA station. No alternate transportation will be provided.
Train 20(08) will originate at the Atlanta, GA station. Alternate transportation will be provided by 3 buses.
Trains 20(09-11) will originate at the Atlanta, GA station. No alternate transportation will be provided.
Train 19(11) is expected to operate through to the New Orleans, LA Union Passenger Terminal.
Train 20(12) is expected to originate at the New Orleans, LA Union Passenger Terminal.
Mardi Gras
Train 23(08) will operate as scheduled from the Mobile, AL station to the New Orleans, LA Union Passenger Terminal.
Trains 23(09-11) will be canceled. No alternate transportation will be provided.
Train 24(08) will be canceled. Alternate transportation will be provided by 2 buses.
Trains 24(09-11) will be canceled. No alternate transportation will be provided.
Trains 25(08-11) and 26(08-10) will be canceled. No alternate transportation will be provided.
Train 26(11) is expected to operate from the New Orleans, LA Union Passenger Terminal to the Mobile, AL station, restoring full service on October 12, 2026.

WBS Number: B.TR.100150.7249 has been issued for all service adjustments related to Tropical Storm Isaias.

WBS#: B.TR.100150.7249

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

29SEP26: Train 821(29) was delayed beginning the 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	

Maintenance of Way Highlights

27-FOI-00046 000000008947 "UNCLASSIFIED" 10/19/2026

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

Metra C&M Subdivision - Scheduled M/W Work 26-055

27-FOI-00048 0000000008947 "UNCLASSIFIED" 10/19/2026

16MAY26: Metra has track work scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 518(12) Passenger Issue at Centralia, Washington – Improper Conduct

12OCT26, Passenger on PNR 384228, traveling from Portland, OR to Centralia, WA was reportedly refusing to move from a four-seater when asked by the Conductor. There was a family of five traveling on PNR D97851, the gentleman with the family stated it was ok and opted to sit in the lounge so they could sit together. Once arriving at Centralia, WA Ms. Erving was blocking the way for passengers to detrain standing on the platform near the trackside taking selfies.

Delay: 518(12) 01"

Consist Deviations

27-FOI-00046 00000008947 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
1099 (12)	BOS	b/c in lieu of coach	upgrade to jy where available. and email sent to cct to notifiy pax boarding NWK-WIL overcap	12	81534
1164 (13)	NPN	We are oversold due to business class operating as a coach. Please re-accommodate overbooked passengers.			
506 (12)	PDX	Operates with Talgo Equipment instead of planned AIRO Equipment due to Service Disruption.	YES	16	XXXXX
517 (12)	SEA	Operates with Talgo Equipment instead of planned AIRO Equipment due to Service Disruption.	YES	13	XXXXX
519 (12)	VAC	Operates with Talgo Equipment instead of planned AIRO Equipment due to Service Disruption.	YES	11	XXXXX

Reverse Consists

Train Number	Station	Reason
1195 (12)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1099 (12)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1163 (12)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1150 (12)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
1144 (12)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
1143 (12)	SPG	Consist reversed | Business class seat orientation may have changed | At Front