CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, October 03, 2026 Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00044 [illegible] 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/02/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/02/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	332	39	88.3%	659	75	88.6%	659	75	88.6%
Central Division	86.0%	59	1	98.3%	118	3	97.5%	118	3	97.5%
East Division	82.0%	181	26	85.6%	359	46	87.2%	359	46	87.2%
West Division	86.0%	92	12	87.0%	182	26	85.7%	182	26	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/2/26

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**115,243**	**39,515**	**66%**	**226,167**	**63,575**	**72%**	**226,167**	**63,575**	**72%**
Northeast Corridor	***81%***	***47,262***	***16,986***	***64%***	***99,001***	***23,170***	***77%***	***99,001***	***23,170***	***77%***
Acela	83%	10,740	4,060	62%	22,815	5,756	75%	22,815	5,756	75%
Northeast Regional	79%	36,522	12,926	65%	76,186	17,414	77%	76,186	17,414	77%
Richmond / Newport News / Norfolk	77%	11,076	5,931	46%	21,207	8,051	62%	21,207	8,051	62%
Springfield Shuttles	89%	1,128	88	92%	2,052	167	92%	2,052	167	92%
Roanoke	79%	4,375	1,823	58%	8,345	1,948	77%	8,345	1,948	77%
On Spine Northeast Regional	80%	19,943	5,084	75%	44,582	7,248	84%	44,582	7,248	84%
State Supported	***80%***	***54,755***	***16,058***	***71%***	***103,406***	***27,916***	***73%***	***103,406***	***27,916***	***73%***
Borealis	80%	575	287	50%	1,163	287	75%	1,163	287	75%
Capitol Corridor	90%	4,720	1,149	76%	9,193	2,118	77%	9,193	2,118	77%
Carolinian	70%	1,329	555	58%	2,462	863	65%	2,462	863	65%
Cascades	75%	2,976	629	79%	5,514	995	82%	5,514	995	82%
Downeaster	82%	2,152	367	83%	3,909	1,646	58%	3,909	1,646	58%
Empire	78%	6,438	1,547	76%	12,791	2,979	77%	12,791	2,979	77%
Adirondack	72%	431	98	77%	816	98	88%	816	98	88%
Ethan Allen Express	70%	613	81	87%	1,212	290	76%	1,212	290	76%
Maple Leaf	70%	913	156	83%	1,707	344	80%	1,707	344	80%
New York - Albany	85%	2,899	605	79%	6,117	1,193	80%	6,117	1,193	80%
New York - Niagara Falls	75%	1,582	607	62%	2,939	1,054	64%	2,939	1,054	64%
Gold Runner	73%	2,975	1,462	51%	5,857	2,325	60%	5,857	2,325	60%
Heartland Flyer	70%	172	172	0%	317	317	0%	317	317	0%
Hiawatha	90%	2,141	0	100%	3,964	0	100%	3,964	0	100%
Illinois	78%	3,315	1,183	64%	5,978	1,816	70%	5,978	1,816	70%
Carl Sandburg / Illinois Zephyr	85%	518	224	57%	865	301	65%	865	301	65%
Illini / Saluki	85%	1,170	415	65%	2,258	434	81%	2,258	434	81%
Lincoln Service	70%	1,627	544	67%	2,855	1,081	62%	2,855	1,081	62%
Keystone	92%	9,726	1,447	85%	20,105	2,594	87%	20,105	2,594	87%
Lincoln / Missouri	70%	961	414	57%	1,742	1,091	37%	1,742	1,091	37%
Mardi Gras Service	80%	310	39	87%	581	39	93%	581	39	93%
Michigan	70%	2,322	868	63%	4,444	1,266	72%	4,444	1,266	72%
Blue Water	70%	342	0	100%	817	215	74%	817	215	74%
Pere Marquette	85%	332	0	100%	619	0	100%	619	0	100%
Wolverine	70%	1,648	868	47%	3,008	1,051	65%	3,008	1,051	65%
Missouri	80%	354	108	69%	520	108	79%	520	108	79%
Pacific Surfliner	85%	10,233	4,843	53%	17,824	7,431	58%	17,824	7,431	58%
Pennsylvanian	80%	1,017	51	95%	1,984	305	85%	1,984	305	85%
Piedmont	80%	1,622	78	95%	2,163	170	92%	2,163	170	92%
Vermonter	75%	1,417	859	39%	2,895	1,566	46%	2,895	1,566	46%
Long Distance	***70%***	***13,226***	***6,471***	***51%***	***23,760***	***12,489***	***47%***	***23,760***	***12,489***	***47%***
Auto Train	70%	712	429	40%	1,392	861	38%	1,392	861	38%
California Zephyr	70%	496	336	32%	1,238	583	53%	1,238	583	53%
Cardinal	70%	260	173	33%	794	626	21%	794	626	21%
City Of New Orleans	75%	753	341	55%	1,295	804	38%	1,295	804	38%
Coast Starlight	70%	1,240	626	50%	2,239	683	69%	2,239	683	69%
Crescent	70%	1,153	110	90%	1,969	341	83%	1,969	341	83%
Empire Builder	70%	1,507	877	42%	1,917	1,191	38%	1,917	1,191	38%
Floridian	60%	1,463	1,270	13%	2,700	2,165	20%	2,700	2,165	20%
Lake Shore Ltd	73%	1,183	472	60%	2,197	831	62%	2,197	831	62%
Palmetto	70%	931	277	70%	1,637	414	75%	1,637	414	75%
Silver Meteor	70%	928	254	73%	1,680	933	44%	1,680	933	44%
Southwest Chief	60%	900	773	14%	1,696	1,569	7%	1,696	1,569	7%
Sunset Ltd	70%	721	192	73%	721	192	73%	721	192	73%
Texas Eagle	70%	979	341	65%	2,285	1,296	43%	2,285	1,296	43%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00046 00000000957 "UNCLASSIFIED" 10/10/2026~~

Train Index Dates Through October 02, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	11,814	223,694	528	11,814	223,694	528

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	489	71,163	69	489	71,163	69
INFRASTRUCTURE PLANNED	135	1,376	71,163	193	1,376	71,163	193
FLEET RELIABILITY	90	1,899	223,694	85	1,899	223,694	85
TRAIN OPERATIONS	424	8,050	223,694	360	8,050	223,694	360

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00044 [illegible] 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/02/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/02/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	332	39	88.3%	659	75	88.6%	659	75	88.6%
Central Division	86.0%	59	1	98.3%	118	3	97.5%	118	3	97.5%
East Division	82.0%	181	26	85.6%	359	46	87.2%	359	46	87.2%
West Division	86.0%	92	12	87.0%	182	26	85.7%	182	26	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-00044 [illegible]

Scheduled Departure Date: **10/02/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/02/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	332	39	88.3%	659	75	88.6%	659	75	88.6%
Central Division	86.0%	59	1	98.3%	118	3	97.5%	118	3	97.5%
CDL	95.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%
CHI	86.0%	28	1	96.4%	56	2	96.4%	56	2	96.4%
FTW	92.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
GRR	95.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
KCY	92.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%
MKE	92.0%	6	0	100.0%	12	0	100.0%	12	0	100.0%
MOE	97.5%	2	0	100.0%	4	0	100.0%	4	0	100.0%
MSP	96.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
NOL	94.5%	4	0	100.0%	8	1	87.5%	8	1	87.5%
OKC	97.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
PNT	88.0%	3	0	100.0%	6	0	100.0%	6	0	100.0%
PTH	93.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
QCY	91.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%
SAS	90.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
STL	89.0%	4	0	100.0%	8	0	100.0%	8	0	100.0%
East Division	82.0%	181	26	85.6%	359	46	87.2%	359	46	87.2%
ALB	88.5%	8	1	87.5%	16	1	93.8%	16	1	93.8%
BON	87.5%	5	0	100.0%	10	0	100.0%	10	0	100.0%
BOS	85.5%	19	1	94.7%	38	1	97.4%	38	1	97.4%
BRK	92.5%	5	1	80.0%	10	2	80.0%	10	2	80.0%
BTN	82.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
CLT	91.5%	5	0	100.0%	9	1	88.9%	9	1	88.9%
GFD	88.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%
GRO	-	-	-	-	1	0	100.0%	1	0	100.0%
HAR	79.5%	13	3	76.9%	26	6	76.9%	26	6	76.9%
HFD	-	2	0	100.0%	4	0	100.0%	4	0	100.0%
LOR	84.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
MIA	89.5%	2	0	100.0%	4	0	100.0%	4	0	100.0%
MTR	79.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%
NFK	84.5%	2	1	50.0%	4	1	75.0%	4	1	75.0%
NFL	93.5%	2	0	100.0%	4	1	75.0%	4	1	75.0%
NHV	78.0%	5	0	100.0%	10	1	90.0%	10	1	90.0%
NPN	93.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%
NYP	75.5%	52	6	88.5%	103	12	88.3%	103	12	88.3%
PGH	93.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
PHL	48.0%	5	3	40.0%	10	6	40.0%	10	6	40.0%
RGH	95.0%	4	1	75.0%	6	1	83.3%	6	1	83.3%
RNK	83.5%	2	0	100.0%	4	1	75.0%	4	1	75.0%
SAB	98.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
SAV	96.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
SFA	88.0%	1	1	0.0%	2	1	50.0%	2	1	50.0%
SPG	92.5%	5	0	100.0%	10	0	100.0%	10	0	100.0%
TWO	73.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/02/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/02/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	332	39	88.3%	659	75	88.6%	659	75	88.6%
East Division	82.0%	181	26	85.6%	359	46	87.2%	359	46	87.2%
WAS	84.0%	33	8	75.8%	66	9	86.4%	66	9	86.4%
West Division	86.0%	92	12	87.0%	182	26	85.7%	182	26	85.7%
ARN	92.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
BFD	79.0%	7	0	100.0%	14	2	85.7%	14	2	85.7%
EMY	72.0%	1	1	0.0%	2	2	0.0%	2	2	0.0%
EUG	86.5%	2	0	100.0%	4	0	100.0%	4	0	100.0%
GTA	90.0%	3	1	66.7%	6	2	66.7%	6	2	66.7%
LAX	89.5%	11	1	90.9%	21	2	90.5%	21	2	90.5%
OKJ	74.5%	13	3	76.9%	26	5	80.8%	26	5	80.8%
PDX	86.0%	5	0	100.0%	9	0	100.0%	9	0	100.0%
SAC	88.5%	16	2	87.5%	32	4	87.5%	32	4	87.5%
SAN	90.5%	12	1	91.7%	25	2	92.0%	25	2	92.0%
SEA	85.0%	8	1	87.5%	15	1	93.3%	15	1	93.3%
SJC	89.0%	7	2	71.4%	14	6	57.1%	14	6	57.1%
SLO	90.0%	3	0	100.0%	6	0	100.0%	6	0	100.0%
SPK		1	-	100.0%	2	-	100.0%	2	-	100.0%
VAC	97.0%	2	0	100.0%	4	0	100.0%	4	0	100.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1				0.0%			0.0%	1	0	100.0%	1	0	100.0%
2		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
3	149	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
4	170	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
5	No OS	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
6	54	2	2	0.0%	2	2	0.0%	2	2	0.0%	2	2	0.0%
7	49	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
8		1	0	100.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%
11	25	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
14		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
19		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
20		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
21		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
22		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
23		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
24		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
25		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
26		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
27	37	2	2	0.0%	2	2	0.0%	2	2	0.0%	2	2	0.0%
40	71	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
41	80	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
42		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
43		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
48	22	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
49		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
50	78	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
52		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
53	146	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
55	55	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
56	43	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
58	28	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
59		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
63	35	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
64		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
66		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
67	45	1	0	100.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%
68		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
69	80	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
71		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
72		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
73		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
74		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
76		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
77		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
78	27	2	0	100.0%	2	0	100.0%	3	1	66.7%	3	1	66.7%
78		2	0	100.0%	2	0	100.0%	3	1	66.7%	3	1	66.7%
79		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
80	28	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
84		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
85		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
86	23	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
89		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
90	20	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
93	29	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
94		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
95	136	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
97		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
98		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
110		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
111		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
112		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
113		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
119	95	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
125	146	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
129	55	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
130		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
131	52	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
134		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
136		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
137		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
138		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
141		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
148		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
151	73	2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
170		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
171	82	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
172	56	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
173	64	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
174		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
175	46	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
176	69	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
177	16	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
178	31	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
181		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
182		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
183		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
184		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
185		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
186		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
190		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
192		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
193	20	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
196		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
197	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
198		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
230		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
232		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
233	54	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
234		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
235	29	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
236		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
237		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
238		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
239		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
240		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
241		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
243		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
244		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
245		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
280		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
281		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
283	31	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
284		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
290		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
291		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
300	52	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
301		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
302	17	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
305		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
306		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
307		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
311		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
316	33	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
318		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

Amtrak On Time Performance

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
319	60	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
329		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
330		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
331		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
332		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
334		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
335		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
336		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
337		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
338		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
339		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
341		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
342		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
350		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
351	16	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
352	110	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
353		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
354		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
355	16	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
364	58	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
365		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
370		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
371		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
380		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
381		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
382	30	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
383	53	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
390		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
391		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
392	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
393	23	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
417		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
425		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
448	49	2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
449		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
470		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
471		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
473		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
474		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
475		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
478		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
479		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
486		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
494		3	2	33.3%	3	2	33.3%	2	0	100.0%	2	0	100.0%
495	39	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
500	17	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
502		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
503	32	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
504		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
505		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
506		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
507		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
508		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
509		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
511		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
516		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
517		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
518		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
519		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
520		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
521	Cncld	2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
522		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
523	22	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
524		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
525	24	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
526		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
527	20	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
528	39	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
529	21	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
530		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
531		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
532		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
534		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
535		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
536		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
537		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
538		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
539	27	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
540		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
541		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
542		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
543	26	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
544		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
545		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
547	27	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
548		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
549		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
550		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
551		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
562	52	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
564		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
566	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
567		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
572	27	2	2	0.0%	2	2	0.0%	2	2	0.0%	2	2	0.0%
573	20	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
579	18	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
580		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
581		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
584		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
587		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
588		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
591		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
593		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
600		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
601		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
605		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
607		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
609		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
626	44	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
639		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
640		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
641		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
642	46	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
643	17	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
644	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
645		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
646		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
647		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
648		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
649	22	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
650		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
651		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
652		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
653		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
654		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
655		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
656	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
657		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
658		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
680		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
681		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
682		2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
683	20	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
684		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
685		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
686		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
687		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
688	41	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
701		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
702		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
703		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
704	79	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
710		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
711		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
712	26	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
713		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
714	25	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
715	24	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
716	73	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
717		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
718		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
719	63	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
757	59	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
761	52	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
765	48	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
769	47	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
770		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
774	59	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
777	71	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
782		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
785		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
786	21	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
790		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
794	20	2	0	100.0%	2	0	100.0%	3	2	33.3%	3	2	33.3%
794		2	0	100.0%	2	0	100.0%	3	2	33.3%	3	2	33.3%
821	43	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
822	31	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
1333	20	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

Amtrak On Time Performance

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1340		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
1689		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
2102		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
2103		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2104		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2105		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2107		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2108		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2109		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2112		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2113	16	2	1	50.0%	2	1	50.0%	1	1	0.0%	1	1	0.0%
2115	91	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2116		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2118	Cncld	2	1	50.0%	2	1	50.0%	1	0	100.0%	1	0	100.0%
2119	31	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
2120	57	2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
2123		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2124		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2126	24	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2127	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2128		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2131	Cncld	2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
2150		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2151	50	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2152		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2154	24	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2155	Cncld	2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
2156		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2158		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2159	54	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
2160		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2162	71	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
2163	20	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
2165	24	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2167	23	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2171		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2190		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2193		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2113	WAS	16	DET	19	DET	19	BAL-XNY	AM	Catenary maintenance , Control Point, Carroll interlocking, held for northbound train ahead a/c single tracking on 3trk a/c 2trk o/s at carroll interlocking a/c broken runner in the catenary.
2115	WAS	91	MTI	98	MTI	92	BWI-XNY	AM	Disabled train ahead, Milepost, 132, ., 2155 disabled on No. 3 track
2118	NYP	Trn Cancelled							
2119	WAS	31	MTI	35	MTI	22	BWI-XNY	AM	Disabled train ahead, Milepost, 132, ., 2155 disabled on No. 3 track
2120	NYP	57	MTI	30	MTI	21	WAS-WAS	AM	Disabled train ahead, Other, SOUTH OF LANDOVER, 2155 disabled south of Landover on 3 track
2126	NYP	24	SMW	34	SMW	21	BWI-BAL	AM	Scheduled in track usage program, Milepost, 103, 98.5, followed 544, 544 opr 1 trk a/c A trk o/s, 544 held for 2 south bound Amtrak trains at Charles
2127	WAS	19	PTI	15	PTI	6	PHL-XPV	AM	Meet, 2120, Control Point, PENN, 2120 COMING INTO THE STATION
2131	WAS	Trn Cancelled							
2151	WAS	50	DSR	31	DSR	23	NHV-STM	MN	Per bulletin Speed restrictions also train congestion, Control Point, 248, 15, 2/4
2154	BOS	24	DET	29	DET	18	XNY-BWI	AM	Catenary failure, Control Point, ., STOPPED AT MP 125.1 A/C BROKEN CARBON STRIP PASSING THROUGH CARROLL INTERLOCKING.
2155	WAS	Trn Cancelled	DSR	12	CAR	10	STM-STM	MN	HEP 2142, Pantograph fault head POWER CAR 2142
2159	WAS	54	MTI	36	MTI	36	BAL-XNY	AM	Disabled train ahead, Milepost, 132, ., 2155 disabled on No. 3 track
2162	BOS	71	MTI	46	MTI	46	WAS-WAS	AM	Disabled train ahead, Milepost, CP AVEUNE, WAS, AM2155 BROKEN DOWN AT CP AVENUE.
2163	WAS	20	MTI	14	MTI	14	BAL-XNY	AM	Disabled train ahead, Milepost, 132, ., heavy congestion south a/c earlier 2155 disabled on No. 3 track
2165	WAS	24	ENG	22	ENG	22	XSH-NYP	AM	Traction motor, 2129|NG|NP, HELD IN HAROLD A/C LOST OF TRACTION POWER
2167	WAS	23	OTH	21	PTI	14	XPV-BWI	AM	Follow, 173, Milepost, 79.3, 95.7

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
67	NPN	45	DMW	26	DMW	26	PHL-WIL	AM	Waiting for MW clearance, Control Point, PHIL, WAITED FOR MW CLEARANCE PHIL TO HOOK
86	NYP	23	CTI	18	CTI	11	WDB-ALX	CS	Meet Stop Signal on # 3 track and waited for the train to Xover in front., VRE, 31002, Control Point, Beltway
93	NFK	29	SVS	31	SVS	31	WAS-WAS	AM	Routine inspections, CONGESTION ON LOWER LEVEL, DELAYED H/E M/U DUE TO TRAINS 19 AND 138 H/E CHANGE
95	NFK	136	MTI	102	MTI	54	NCR-XNY	AM	Disabled train ahead, Milepost, 132, ., received transfer from disabled 2155
119	WAS	95	MTI	96	MTI	96	BWI-XNY	AM	Disabled train ahead, Milepost, 132, ., 2155 disabled on No. 3 track
125	NPN	146	CAR	43	ENG	32	PHL-PHL	AM	Air / Brake, 642|EX|ES, CUT ENG 642 AND ADDED ENG 620 A/C MAIN RES ISSUE
129	WAS	55	CTI	33	CTI	23	BAL-BWI	AM	Follow, MARC, 451, Milepost, 95.7, 106.3
131	WAS	52	MTI	48	MTI	48	BWI-XNY	AM	Disabled train ahead, Milepost, 132, ., 2155 disabled on No. 3 track
151	RNK	73	PTI	39	FTI	30	XVG-ALX	CS	Follow M407, Milepost, 110.0, 105.0
171	RNK	82	MTI	46	DMW	16	BRP-STM	MN	Waiting for MW clearance Crossed into working limits from beginning into STM., Milepost, 36, 34.8
172	BOS	56	ENG	34	ENG	34	PHL-PHL	AM	Other electrical failure, 633|EX|ES, Met by mechanical a/c main circuit breaker would not close.
173	WAS	64	PTI	26	SMW	20	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 2 track a/c 3 track o/s between Ragan & Davis
175	WAS	46	CTI	25	SVS	24	NYP-NYP	AM	Routine inspections, HELD IN STATION A/C OUT OF DATE FIRE EXTINGUISHER
176	BOS	69	MTI	71	MTI	71	WAS-WAS	AM	Disabled train ahead, Milepost, CP AVENUE, WAS, HELD DUE TO 2155 BROKEN DOWN AT CP AVENUE.
177	PHL	16	CTI	17	CON	10	NHV-NHV	MN	Hold for connecting train 417
178	BOS	31	POL	30	POL	30	KIN-PVD	AM	Fire department hold, . No. 178 stopped eastbound on track Non. 2 at Cranston. JWC actd
193	WAS	20	PTI	15	PTI	6	XHM-PHL	AM	Follow, 2127, Control Point, MANTUA, HELD FOR 2127 AHEAD

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
197	WAS	19	OTH	11	SMW	11	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 2 track a/c 3 track o/s between Ragan & Davis
495	NHV	39	TRS	31	TRS	26	WFD-WFD	AM	Vehicle on track ahead, Milepost, WFD, WFD, stopped at WFD waiting for clearance a/c vehicle on track @ Ward St.
53	SFA	146	TRS	132	TRS	132	XV7-XSE	CS	Trespasser strike Freight train struck treaspaser fatality, Control Point, north smithfield
80	NYP	28	CTI	31	DSR	11	GRO-BNC	NS	Per bulletin Milepost, 2.4, 7.2, 25, 1
626	NYP	44	SVS	27	SVS	27	PHL-XHM	AM	Unplanned Wye
642	NYP	46	SVS	48	SVS	48	PHL-XHM	AM	Unplanned Wye, Wye'd on the outbound a/c broken speedometer on cc9644.
643	HAR	17	SMW	13	SMW	13	PHL-PAO	AM	Diversions around M/W work, Control Point, Zoo, 1 trk o/s.
644	NYP	19	PTI	26	PTI	8	NWK-NYP	AM	Follow, AM112, Other, NWK-NYP
649	HAR	22	SVS	21	SVS	21	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND A/C BAD CAB CAR
656	NYP	19	OTH	10	PTI	6	TRE-NWK	AM	Follow, AM2124, Other, TRE-NWK
683	BRK	20	DSR	5	PTI	5	EXR-DHM	CS	Meet 684, Control Point, Rockingham
688	BON	41	OTH	24	OTH	24	HHL-WOB	MT	Engineer missed platform, then had PTC issues when reversing back through Crawford interlocking to get back to platform.
63	TWO	35	DSR	14	DSR	4	AMS-UCA	CS	Per MW foreman Milepost, 228.9, 233.4, 79, 1
69	MTR	80	CUI	94	CUI	94	XLQ-XLQ	CN	Canada
233	ALB	54	CON	22	CON	22	NYP-NYP	AM	Hold for connecting train, HELD F/PSGRS OFF AM172
235	ALB	29	CTI	22	CTI	17	CRT-POU	MN	Follow Metro North, 839, Milepost, 39, 73.8
283	NFL	31	FTI	27	FTI	27	ROM-SYR	CS	Meet csx unknow, Control Point, 278
48	NYP	22	FTI	56	FTI	49	ERI-BUF	CS	Follow CSX i10401, Control Point, 39
448	BOS	27	FTI	27	SVS	20	ALB-ALB	AM	Engine swap added 108
78	RGH	27	TEN	25	PTI	13	HPT-GRO	NS	Wait for station track 79, Control Point, pomona
90	NYP	20	FTI	52	FTI	22	FAY-SSM	CS	Meet CSX???, Control Point, S. Beard
55	WAS	55	WTR	67	WTR	29	MPR-RPH	NE	Wet / slippery rail Milepost, 76, 46

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
56	SAB	43	SYS	40	SYS	40	SPG-SPG	AM	Other late crew Other, SPG Sta
40	CHI	71	RTE	171	RTE	143	SAV-DNK	CS	Dispatcher hold Broken rail, Milepost, 475.0, 475.0
41	MIA	80	FTI	102	FTI	55	SAV-XJG	CS	Follow csx lo97, Milepost, 493.0, 533.0
5	EMY	No OS Rpt	WTR	729	WTR	246	LNK-HAS	BN	Trees down Milepost, 69.7, 69.7
6	CHI	54	FTI	139	DCS	34	WNN-XW6	UP	Restrictive signal(s) from unknown cause Held at 545, Track occupancy. Track inspector checking for issues., Red, Other, 545
521	SJC	Trn Cancelled							
523	SJC	22	SYS	11	SYS	11	DAV-FFV	UP	Blocked by or assisting another, disabled Amtrak train RESCUED PAX FROM DISABLED AMT 521, 49 PAX TOTAL., Milepost, 56.09, 56.09
525	OKJ	24	PTI	17	PTI	13	DAV-FFV	UP	Meet Cleared into siding for 520, then reversed back out., 520, Control Point, Fairfield
527	SJC	20	PTI	30	PTI	25	FMT-GAC	UP	Meet Wait for 528 behind ACE., 528, Control Point, CO035
528	SAC	39	ITI	45	ITI	45	SJC-SJC	UP	Late arriving into SJC on train 523. Turned as 528 did class 2 air test. Boarded passenger and had to wait for Caltrain traffic to clear up for departure 510, Late arriving into SJC on train 523 turned as 528. Did class 2 boarded passengers and waited for Caltrain traffics to clear up before getting
529	SJC	21	PTI	32	PTI	20	FMT-GAC	UP	Meet Amtk530north, Control Point, s albrae
539	SJC	27	CTI	12	PTI	12	GAC-SCC	UP	Meet Amt 538, Siding, Expressway
543	SJC	26	CTI	15	CTI	15	GAC-SCC	UP	Meet Ace, Ace8, Control Point, CO044
547	SJC	27	MBO	16	MBO	16	SUI-MTZ	UP	For maritime traffic Other, Benicia
50	NYP	78	PTI	54	SMW	20	NWK-NYP	AM	Scheduled in track usage program, Other, NWK-NYP, SINGLE TRACKING IN THE SOUTH TUBE A/C NORTH TUBE O/O/S
500	SEA	17	MBO	13	MBO	13	PDX-VAN	BN	For maritime traffic Bridge, Columbia River Bridge
503	EUG	32	ADA	22	ADA	18	TAC-TAC	ST	Wheelchair

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
58	CHI	28	DSR	121	DSR	27	MKS-MEM	CC	Per bulletin Milepost, 64.1, 63.65, 60, main, Milepost, 62.5, 62.1, 60, main, Milepost, 59.5, 59.1, 60, main, Milepost, 55.8, 55.1, 60, main, Milepost, 39.0, 38.2, 30, main, Milepost, 31.6, 31.2, 30, main, Milepost, 23.5, 21.0, 25, main, Milepost, 12.7, 12.0, 25, 1
11	LAX	25	DCS	64	DBS	28	OKJ-SJC	UP	Debris strike Bicycle, Milepost, 23, 23
7	SEA	49	FTI	107	SVS	59	HAV-SBY	BN	Pick up equipment Pick up car 32000 at Inverness industry track
27	PDX	-4	FTI	25	FTI	17	WIH-BNG	BN	Follow Crew inspecting train, BN 3274, Control Point, East Bingen, Other, Bingen Station
821	FTW	43	DSR	51	DSR	34	GLE-FTW	BN	Per bulletin Milepost, 409.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 407.9, 407.1, 30, m, Milepost, 405.9, 405, 60, m, Milepost, 404.2, 403.8, 60, m, Milepost, 403.2, 402.7, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.5, 400.1, 60, m, Milepost, 399.9, 399.2, 60, m, Milepost, 39
822	OKC	31	FTI	29	FTI	29	GLE-ADM	BN	Meet BN8566, BN Freight, Siding, Thackerville, Siding, Marietta
351	CHI	16	FTI	27	FTI	13	XH6-XTF	NS	Follow up5407, ns4838, Milepost, 511, 515
352	PNT	110	FTI	128	FTI	116	XH6-XPI	NS	Meet NS 9909 in emergency, 352 stopped at 485 for an hour and the remaining time stopped in Porter siding till NS 9909 repaired and on the move, NS 9909, Siding, Porter
355	CHI	16	PTI	24	PTI	21	XA5-XB0	CC	Wait for station track 352, 364, Control Point, Baron
364	PTH	58	FTI	64	FTI	42	XH6-XPI	NS	31N in emergency 31N, Control Point, 482
562	SAN	52	CTI	41	CTI	18	OSD-SOL	SN	Meet NCTD, Cst 623, Control Point, Ponto
566	SAN	19	CTI	18	CTI	13	OSD-SOL	SN	Meet coaster, Control Point, longboard
572	SAN	27	DSR	16	DSR	12	XRJ-FUL	BN	Per dispatcher (radio/phone) Per Dispatcher slow roll by disabled train on track one we were on track three to assist, Control Point, sante FE spring, 10, 3
573	LAX	20	ITI	12	ITI	12	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 562
579	LAX	18	FTI	10	FTI	10	FUL-XRJ	BN	Meet bnsf, unk, Control Point, San Pedro

Amtrak Endpoint OTP Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
757	SLO	59	DCS	70	DCS	36	VEC-CPN	UP	Restrictive signal(s) from known wayside signal failure Flag from Ventura station to 386. Then hand operate switch at 386., Restricting proceed, Milepost, 386.0, 385.0
761	GTA	52	PTI	40	PTI	40	CML-OXN	UP	Meet 770, Control Point, N CAMARILLO
765	SLO	48	PTI	48	PTI	27	X3G-LPS	UP	Meet Meet Amtrak 786, 786, Siding, Sudden
769	GTA	47	DMW	31	DMW	31	VEC-CPN	UP	Waiting for MW clearance Control Point, North Seacliff
774	SAN	59	PTI	90	PTI	53	CPN-VEC	UP	Meet amtk, Siding, seaclif
777	SLO	71	DCS	47	PTI	29	CML-OXN	UP	Meet Two-step @ S OXN, 790, Control Point, S OXN
786	SAN	21	DCS	25	ENG	17	VNC-BUR	SC	HEP HEP shutdown, put train into penalty and shot off PTC Restarted HEP and got everything back up and running. This same motor has done this to me and my crew twice and other crews as well. Had to go restricted speed to BUR, C2116
794	LAX	20	PTI	29	PTI	17	VEC-OXN	UP	Follow AMTK 11, Control Point, South Ventura
704	BFD	79	TRS	80	TRS	80	TRK-MCD	BN	Vehicle on track ahead Dispatcher didn't say where car was located, somewhere between W. Fluhr and MCD, Other, 1058.0
712	BFD	26	PTI	35	PTI	15	MCD-MDR	BN	Shuffle 715, Siding, Sharon
714	BFD	25	PTI	33	PTI	13	HNF-COC	BN	Meet 719, Siding, Guernsey
715	OKJ	24	PTI	19	FTI	10	WAC-COC	BN	Meet SF5522, Control Point, Allensworth
716	BFD	73	TSV	53	TSV	53	EMY-EMY	UP	Routine inspections Repair window
719	OKJ	63	TRS	69	TRS	69	MCD-MCD	BN	Vehicle on track ahead Other, Merced Station
3	LAX	149	FTI	146	SYS	112	LAJ-LAJ	BN	Crew rest We needed our 8 hours crew rest, signed up at 0805
4	CHI	170	DCS	120	DCS	67	LSV-RAT	BN	Restrictive signal(s) from unknown cause Yellow/ 7222, 7126, 7012, Red/ E Levy, 7174, 7102, E Colmor, 7062, 7042, Milepost, 722.7, 699.5
300	CHI	52	DMW	36	DMW	34	STL-XQT	TR	Hold for defect repair Switch out of correspondence maintenance worker came out to repair it, Control Point, Gratiot
302	CHI	17	DMW	20	DMW	16	JOL-JOL	UP	Held for or routed around MW work or equipment Control Point, x036

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
382	CHI	30	CTI	25	CTI	14	LAG-XUA	BN	Follow NAR track 2 empty, metra, Other, LAG-CICERO
383	QCY	53	RTE	45	RTE	37	GBB-MAC	BN	Yard track 1, freight trains issues Other, GBB yard
392	CHI	19	FTI	26	FTI	15	DQN-CEN	CC	Meet 408, Milepost, 255, 254
393	CDL	23	FTI	27	FTI	23	EFG-CEN	CC	Meet M396/CN2767, Siding, Tonti
316	STL	33	DCS	32	DCS	29	WAH-KWD	UP	Wayside detector failure including false actuation Wayside detector gave hbd alarm for 21 axles on our 32 axle train. Inspection discovered none over 130 degrees well short of needing action. Held to 30 mph until next detector., Milepost, 28, 12
319	KCY	60	DCS	29	DCS	21	JOL-DWT	UP	Error message: Red Fence switch alignment unknown. talked to UP help desk to troubleshoot. Restricted Speed mp 70.00 to mp 73.00, Milepost, 70.00, 73.00
1333	MSP	20	DCS	30	DCS	20	CBS-POG	CP	Restrictive signal(s) from unknown cause Had to stop and Hand line the switch dodge west going from main 2 to the Main. Restricted speed to next signal, Stop, Control Point, Dodge West

Amtrak Initial Terminal Details

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/2/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	10/01	20	20	Engine swap added 108
BOS	2193	10/02	13	13	Other electrical failure, 2015|LH|LP, AM2193 will dp BOS late, ET now insp pantographs
BRK	682	10/02	1		
HAR	646	10/02	1	1	Passenger and/or baggage
HAR	650	10/02	1	1	Passenger and/or baggage
HAR	652	10/02	1	1	Door, 9646
NFK	94	10/02	4	4	Re-crew / job briefing Waiting on Orders in Norfolk, Control Point, NFK
NYP	63	10/02	2	2	Cross Traffic, NJT, NJ3821, Other, NYP
NYP	69	10/02	2	2	Cross Traffic, NJT, NJ6410, Other, NYP
NYP	233	10/02	22	22	Hold for connecting train, HELD F/PSGRS OFF AM172
NYP	291	10/02	6	6	Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240
NYP	2119	10/02	2	2	Passenger and/or baggage, LOADING
NYP	2131	10/02	(Trn Cxld)		Engine Issue
PHL	151	10/02	15	15	Waiting for MW clearance, Control Point, PHIL-HOOK, HELD FOR LATE CLEARING MW
PHL	601	10/02	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	605	10/02	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD
RGH	77	10/02	1		
SFA	52	10/02	20	20	Late departure at initial terminal due to late arrival of inbound equipment 53
WAS	112	10/02	4	4	Per dispatcher (radio/phone), Control Point, K INTERLOCKING, 15, 25, CANCELLED TSRB & RECIEVED FORM D
WAS	134	10/02	2	2	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE
WAS	174	10/02	3	3	Wheelchair, LATE LIFT
WAS	176	10/02	71	71	Disabled train ahead, Milepost, CP AVENUE, WAS, HELD DUE TO 2155 BROKEN DOWN AT CP AVENUE.
WAS	196	10/02	25	25	Other late crew, LATE CNDR
WAS	2118	10/02	(Trn Cxld)		Engine Issue
WAS	2120	10/02	21	21	Disabled train ahead, Other, SOUTH OF LANDOVER, 2155 disabled south of Landover on 3 track

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/2/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2162	10/02	46	46	Disabled train ahead, Milepost, CP AVEUNE, WAS, AM2155 BROKEN DOWN AT CP AVENUE.
CHI	41	10/02	3	3	Mobility Impaired
EMY	6	10/02	1		
GTA	782	10/02	11	11	AMP PER DS. SHE SAID IT IS THE TIME FOR COMPUTER TO LINE UP TRAIN. Other, GOLETA
LAX	572	10/02	9	9	Late departure at initial terminal due to late arrival of inbound equipment 770, Equipment swap so 770 could leave on time from Los Angeles
OKJ	526	10/02	3	3	Meet 11, Control Point, North Jack London
OKJ	710	10/02	7	7	Door C8006, No door light while doors closed
OKJ	716	10/02	(Trn Cxld)		Third Party Car Failure
SAC	525	10/02	8	8	Train cancelled, then not Initially canceled so as to deadhead to rescue dead 521. Plans changed at the last moment.
SAC	704	10/02	3	3	Door C9025, Can't get a door light, DRUMMAC mechanical checking doors and cables. Took 3 min delay
SAN	573	10/02	12	12	Late departure at initial terminal due to late arrival of inbound equipment 562
SEA	11	10/02	84	60	Toilet 32037, Mechanical repair main line clog
SEA	11	10/02	84	24	Restrictive signal(s) from unknown cause Instructed to hand line power switch 13 and flagged lead 1 king 5 to due switch failure, Stop, Control Point, King street
SJC	528	10/02	45	45	Late arriving into SJC on train 523. Turned as 528 did class 2 air test. Boarded passenger and had to wait for Caltrain traffic to clear up for departure 510, Late arriving into SJC on train 523 turned as 528. Did class 2 boarded passengers and waited for Caltrain traffics to clear up before getting
SJC	530	10/02	2	2	Loading problem Would not load. Ended up having issues all the way to Sac. Possible cable issue? Sometimes does not load until run 4. Other times run 1., C2006

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	43.1	66.4	90.2	58	33
SEPTA	95.0	93.5	90.2	91.5	214	14
NJT-NED	95.0	No Data	No Data	88.6	No Data	No Data
NJT-SED	95.0	90.0	95.5	97.2	20	2

Operating Highlights

Train 40(02) South of Jesup, GA - Deer Strike

03OCT26: Train 40(02) operating with engines 111, 37, and 156 customers onboard struck a deer 40 miles south of Jesup, GA on the CSX Nahunta subdivision at milepost 587.0. No damage was reported.

Train	Delay	Comment
40(02)	02"	

Train 40(02) Savannah, GA - Servicing

03OCT26: Train 40(02) operating with engines 111, 37, and 135 customers onboard was delayed departing Savannah, GA on the CSX Savannah subdivision due to fuel vendor showing up and and requesting train be moved forward to fuel.

Train	Delay	Comment
40(02)	41"	

Train 89/52(02) Charleston, SC - Freight Train Interference

02OCT26: Due to CSX freight S888-27 clearing Charleston on the CSX Charleston subdivision while working the yard, train 89(02) operating with engine 385, 42 customers, and train 52(02) operating with engines 360, 352, and 299 customers onboard were both delayed. Train 89(02) held in the Charleston station awaiting clearance to proceed and train 52(02) held at milepost 393.8.

Train	Delay	Comment
89(02)	49"	
52(02)	50"	

Train 98(02) South of Charleston, SC - Freight Train Interference

02OCT26: Train 98(02) operating with engines 328, 348, and 192 customers onboard was delayed 1 mile south of Charleston, SC on the CSX Charleston subdivision holding at 388.2 waiting for CSX M491-02 to finish working the yard.

Train	Delay	Comment

27-FOI-00046 0000008957 "UNCLASSIFIED" 10/19/2026

Train 68(02) Rhinecliff, NY - Debris

02OCT26: Train 68(02) operating with engines 705, and 192 customers onboard struck rocks and debris just outside Rhinecliff, NY station located at milepost 89.1 on the Amtrak Hudson Line. The crew inspected the equipment upon arrival in the station and found no damage.

Train	Delay	Comment
68(02)	02"	

Train 19(02) Washington D.C. - Servicing

02OCT26: Train 19(02) operating with engines 369, 330, and 159 customers onboard was delayed departing Washington D.C. due to high congestion in the station causing delays to headend changes.

Train	Delay	Comment
19(02)	31"	

Train 69(02) North of Rouses Point, VT - Customs and Immigration

02OCT26: Train 69(02) operating with engine 94 and 133 customers onboard was delayed north of Rouses Point, VT at the Canadian Border awaiting officials to finish their inspections and clearances.

Train	Delay	Comment
69(02)	1'34"	

27-FOI-00046 0000008957 "UNCLASSIFIED" 10/19/2026

Train 2155(02) North of Washington, DC - Engine Failure

02OCT26: Train 2155(02) operating with Northeast Regional 10 and 212 customers, was stopped at milepost 130.7, 6 miles north of Washington, DC on the Amtrak PW Line, at 2:36 PM-ET due to multiple faults on power car 2142. The crew attempted troubleshooting without success. Customers were transferred to Train 95(02). Train 2155(02) was terminated where it stood, and Engine 625 was dispatched from Washington, DC Union Station to tow the equipment back to Washington. Single track conditions existed through the area, and all train traffic was stopped during the customer transfer. Trains scheduled to operate through the area were significantly delayed.

As a result of the incident, Trains 2118(02) and 2131(02) were canceled in their entirety.

WBS#: B.TR.100151.0855

Train	Delay	Comment
2155(02)	Terminated XBO	
2118(02)	Cancelled	
2131(02)	Cancelled	
95(02)	1'42"	
131(02)	48"	
2159(02)	36"	
2115(02)	1'38"	
176(02)	1'11"	
178(02)	35"	
119(02)	1'36"	
171(02)	20"	
2119(02)	13"	
125(02)	18"	
2162(02)	46"	Turn of late equipment
2120(02)	21"	Turn of late equipment
9433	32"	MARC
9428	1'08"	MARC
9532	50"	MARC
9435	1'18"	MARC
9430	38"	MARC
9634	36"	MARC
9537	1'12"	MARC
9439	43"	MARC
9641	48"	MARC

Train 125(02) North of Trenton, NJ - Main Res Pressure Loss - Engine Failure

02OCT26: Train 125(02) operating with engine 642, 7 cars, and 460 customers onboard was stopped at milepost 44.0, 12 miles north of Trenton, NJ on the Amtrak NYP Line due to a loss of main res pressure. The equipment was inspected and a leak could be heard. The train was able to advance to Trenton station. The local road foreman met the train upon arrival. The main res was cut out behind engine 642. Train 125(02) departed Trenton at 1:22 PM-ET.

The train was met in Philadelphia by mechanical and engine 642 was replaced with engine 620. Once the replacement was made and all necessary procedures followed, Train 125(02) departed Philadelphia and advanced south.

Train	Delay	Comment
125(02)	27"	TRE
125(02)	32"	PHL

PW Line Carroll Interlocking Catenary Damage - New Carrollton, MD - Catenary or Wayside Failure

02OCT26: Train 2154(02) operating with 161 customers on board was delayed after operating through Carroll Interlocking, milepost 127.0, on the Amtrak PW Line due to a broken pantograph alarm. The equipment was inspected by the crew and a broken carbon strip was found. The pantographs were reconfigured and the train was back on the move.

The train was met by High Speed Rail and ET upon arrival in Philadelphia, where the train was approved to continue northbound.

Catenary damage was found at Carroll Interlocking. ET responded to the scene and took track two out of service to make repairs. This caused single track conditions through the area. Trains that operated through the area while the repairs were being made experienced delays.

Train	Delay	Comment
2154(02)	18"	MP 127.0
2154(02)	09"	PHL
2158(02)	21"	
134(02)	05"	
2112(02)	08"	
2113(02)	19"	
2151(02)	23"	
185(02)	06"	
184(02)	33"	
94(02)	02"	
2116(02)	05"	

Train 172(02) Philadelphia, PA - Engine Failure

02OCT26: Train 172(02) operating with engine 633, 10 cars, and 493 customers onboard was delayed departing Philadelphia, PA on the Amtrak PW line due to MCB issues with engine 633. Mechanical responded to the train to assist with the problem. The pantographs were able to be reconfigured and the MCB was able to be closed. Train 172(02) departed Philadelphia at 9:47 AM-ET.

Train 233(02) was held in New York for 24 connections from Train 172(02).

Train	Delay	Comment
172(02)	34"	
233(02)	22"	Held for Connections

Train 151(02) North of Alexandria, VA - Freight Train Interference

02OCT26: Train 151(02) operating with engine 199, 5 cars, and 143 customers onboard was delayed beginning at milepost 110.0, 5 miles north of Alexandria, VA on the CSX RF&P subdivision due to following CSX freight train M407 from milepost 110.0 to milepost 105.0. Once the freight train cleared, Train 151(02) advanced to the next station.

Train	Delay	Comment
151(02)	30"	

Train 41(30) South of Savannah, GA - Freight Train Interference

02OCT26: Train 41(30) operating with 57, 315, 11 cars, and 176 customers onboard was delayed beginning at milepost 493.0, 2 miles south of Savannah, GA on the CSX Savannah subdivision due to following CSX freight train IO97 from milepost 493.0 to milepost 533.0. Once the freight train cleared, Train 41(30) advanced to the next station.

Train	Delay	Comment
41(30)	55"	

27-FDI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train 642(02) Philadelphia, PA - Cab Car Failure

02OCT26: Train 642(02) operating with cab car 9644, 4 cars, engine 611, and 292 customers on board was delayed departing Philadelphia, PA on the Amtrak PH Line due to the speedometer failing on cab car 9644 upon departure from the station. The train reversed back into the station and reconfigured the pantographs. The train then went around the wye so that engine 611 was in the lead.

The equipment was not able to be fixed in New York and as a result the equipment had to be wyed in Philadelphia on Train 649(02).

Train	Delay	Comment
642(02)	48"	

Train 495(02) Wallingford, CT - Vehicle on the Tracks - Trespasser Incident

02OCT26: Train 495(02) operating with cab car 9635, 1 car, engine 120, and 19 customers on board was stopped at milepost 13.1 on the Amtrak MRS Line due to a reported vehicle on the tracks at milepost 12.3. Local law enforcement responded and the vehicle was removed from the tracks allowing Train 495(02) to resume operation.

Train	Delay	Comment
495(02)	31"	

Train 97(01) South of Savannah, GA - Freight Train Interference

02OCT26: Train 97(01) operating with engines 115, 319, 10 cars, and 205 customers on board was stopped at MP 539.8, 49 miles south of Savannah, GA on the CSX Nahunta Subdivision on single main track due to freight train M493-02, which experienced a hot bearing alarm. Following inspection, freight train M493-02 proceeded at 10 mph. Train 97(01) resumed operation at 8:31AM-ET after meeting freight train M690-02.

Train	Delay	Comment
97(01)	40"	

Maintenance of Way Highlights

MBTA Downeaster Track Work - Scheduled M/W Work - TW 26-094 - 9/12-10/11

21AUG26: To support the MBTA bridge replacement at MP 8.99 the below service adjustments have been made:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound
• Trains 693 and 695 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 699 (13Sep, 20Sep, 4Oct, 10Oct-11Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 1689 (12Sep, 19Sep, 26Sep-27Sep, 3Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

o Please note Trains 691 and 697 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct) will operate NORMAL.

Southbound
• Trains 690, 692, 694, 696, and 698 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

WBS#: B.TR.100150.7065

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046, 000000008957 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Frederick Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) will operate as a deadhead train that will operate as a deadhead between NHV and HFD.

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train 6(02) East of Elko, NV - Routing

03OCT26: Train 6(02) was delayed just east of Elko, NV/ MP557 on the UPRR Lakeside Subdivision, at Elko yard, due to being routed into the siding for an unknown reason.

Train	Delay	Comment
6(02)	32"	

Train 3(01) West of Albuquerque, NM - Freight Train Interference

03OCT26: Train 3(01) was delayed west of Albuquerque, NM on the BNSF Gallup Subdivision, following multiple unspecified freight trains between MP38 to MP140.

Train	Delay	Comment
3(01)	1'43"	

Train 383(02) Galesburg, IL - Routing

03OCT26: Train 383(02) was delayed at Galesburg, IL station/MP162.6 on the BNSF Ottumwa subdivision due to BNSF 1416 with mechanical issues stopped on the main track. Train 383(02) was routed through the yard to avoid waiting on the main to be cleared.

Train	Delay	Comment
383(02)	37"	

Train 719(02) Merced, CA - Vehicle on Tracks

03OCT26: Train 719(02) was delayed at Merced, CA/MP1055.9 on the BNSF Stockton Subdivision, due to a reported vehicle on the tracks at MP1062.4. Train 704(02) and 718(02) were also delayed, holding at W. Fluhr/ MP1063.8 and Turlock-Denair, CA station. Once the vehicle was removed and tracks were inspected, all train traffic resumed through the area.

Train	Delay	Comment
719(02)	1'09"	
704(02)	1'20"	
718(02)	24"	

Train 3(01) East of Albuquerque, NM - Commuter Train Interference

03OCT26: Train 3(01) was delayed at W. Herzog/ MP876.96 on the NMRX Albuquerque Subdivision, 25.5 miles east of Albuquerque, NM station, meeting NMRX 1107 and was further delayed at Alameda/ MP894.8 meeting NMRX1104.

Train	Delay	Comment
3(01)	1'05"	

Train 4(01) West of Las Vegas, NM - Passenger Train Interference

02OCT26: Train 4(01) was delayed at Blanchard/MP794 on the BNSF Glorieta Subdivision, 24 miles west of Las Vegas, NM station, due to meeting Train 3(01).

27-FOI-00046 00000098957 "UNCLASSIFIED" 10/19/2026

Train 5(30) Salt Lake City, UT - Engine Failure

02OCT26: Train 5(30) E/68, E/149-9 cars, with 85 customers, was delayed at Salt Lake City, UT due to amperage issues on engine E/68. The crew worked with CNOC mechanical to troubleshoot. The issue was with a door control switch, and once the doors were put into bypass the issue resolved, allowing Train 5(30) to depart the station.

Train	Delay	Comment
5(30)	40"	

Train 352(02) West of New Buffalo, MI - Freight Train Interference

02OCT26: Train 352(02) was delayed beginning at MP485, 24.49 miles west of New Buffalo MI station on the Norfolk Southern Chicago 76 subdivision due to Norfolk Southern freight train 31N stopped ahead with trainline issues. Norfolk Southern mechanical arrived on scene to assist the traincrew with repairs. Train 352(02) pulled to Porter/MP482.2 while mechanical continued to work on repairs. Train 31N was repaired and pulled to clear a route for train 352(02). Train 352(02) was back on the move at 619PM ET. Train 364(02) was also delayed holding at MP487 and MP482.

Train	Delay	Comment
352(02)	1'56"	
364(02)	42"	

Train 716(02) Originated at Emeryville, CA - Third Party Contractor Car Failure

02OCT26: Train 716(2) CC/C8308, 7 cars, E/C2106, with 82 customers, was originated at Emeryville, CA due to a delayed mechanical release from Oakland Maintenance Facility. It was necessary to replace a window on car C/C9803, and to minimize customer delay the decision was made to originate the train at Emeryville. All passengers boarding at Oakland were accommodated om Train 536(02) into Emeryville. Once TASI mechanical completed the replacement, Train 716(02) proceeded to Emeryville station.

Train	Delay	Comment
716(02)	53"	

Train 4(30) West of Kewanee, IL - Switch Failure

02OCT26: Train 4(30), operating with engines 192/48, 9 coaches, and 248 customers, was delayed 3.5 miles west of Kewanee, IL, on BNSF Mendota subdivision, due to a switch failure. Maintenance responded and was able to repair the failing switch.

Train	Delay	Comment
4(30)	33"	

Train 11(01) South of Oakland, CA - Bicycle Strike

02OCT26: Train 11(01), E/316-E/318-9 cars, was delayed after going into emergency at MP 23.1, 16 miles south of Oakland, CA, on the UPRR Coast Subdivision after striking a bicycle on the tracks. There were no reported injuries to the crew or the 229 customers on board. After inspecting the equipment, the crew found no noticeable damage. Once a brake test was completed, Train 11(01) proceeded south.

Train	Delay	Comment
11(01)	28"	

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train 4(01) East of Gallup, NM - Freight Train Interference

02OCT26: Train 4(01) was delayed operating at MP 146, 11 miles east of Gallup, NM, on the BNSF Gallup Subdivision due to freight interference. The crew followed a BNSF freight from MP 146.7 to East Grants/ MP 94.4 where they were able to operate around. Once route was clear, Train 4(01) proceeded at track speed.

Train	Delay	Comment
4(01)	32"	

Train 11(02) Seattle, WA - Car Failure

02OCT26: Train 11(02) was delayed departing Seattle, WA on the BNSF Seattle Subdivision due to a late release from mechanical from a main line clog in C/32037. The crew held while mechanical worked to resolve issue. Once the issue was resolved, the train was released and the equipment was taken to the station for boarding. After all customers were boarded and a brake test was completed, Train 11(02) departed Seattle.

Train	Delay	Comment
11(02)	1'24"	

NCTD San Diego Subdivision East of Solana Beach, CA - Signal Issues

02OCT26: At 8:23A-PT, the NCTD reported signal issues at Del Mar/MP 243.92, 2 miles east of Solana Beach, CA, on the NCTD San Diego Subdivision. Multiple Pacific Surfliners were delayed operated through the affected at restricted speed and flagging. Commuter rail interference combined with the signal issues furthered delays as crews worked through the affected area. A NCTD signal maintainer responded to the scene, arriving at 8:40A-PT. With the assistance of the maintainer, local control was given to assist in lining routes to shorten delays. At 11:24A-PT, the NCTD reported that the signal were operating as intended.

Train	Delay	Comment
564(02)	10"	
566(02)	18"	
562(02)	38"	
769(02)	14"	
573(02)	10"	
573(02)	12"	Late turn of 562(02) SAN

Train 19(01) Birmingham, AL - Police Related

02OCT26: Train 19(01), operating with engines 336/333, 8 coaches and 155 customers, was delayed at Birmingham, AL, on NS AGS South subdivision, due to a fatal NS trespasser strike just south of the station. Initially all tracks were shut down pending investigation. Once local police and NS management determined that one of the tracks were unaffected, train 19(01) was able to depart the station.

Train	Delay	Comment
19(01)	56"	

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

UPRR Santa Barbara Subdivision North of Ventura, CA - Signal Issues

02OCT26: At 6:50A-PT, the UPRR reported signal issues at Seacliff/MP 386.3, 7 miles north of Ventura, CA, on the UPRR Santa Barbara Subdivision. Trains were delayed operating at restricted speed with crews needing to flag and hand throw switches through the affected area. A UPRR maintainer responded to scene and resolved issue. At 10:03A-PT, the tracks were reopened and normal operation commenced.

Train 769(02) was delayed holding at MP 385.6 beginning at 1:24P-PT for a maintenance of way(MOW) crew to work on signal issues. Once MOW crew cleared, Train 769(02) proceeded north.

Train	Delay	Comment
757(02)	56"	
774(02)	1'03"	
770(02)	1'33"	
761(02)	1'05"	
782(02)	11"	Turn of 761(02) GTA
769(02)	46"	

Train 58(02) South of Hammond, LA - Passenger Train Interference

02OCT26: Train 58(02), operating with engine 169, seven coaches, and 101 customers, was delayed 16 miles south of Hammond, LA, on CN McComb subdivision, due to meeting train 59(01) at Manchac siding (milepost 875.3).

Train	Delay	Comment
58(02)	34"	

Train 521(02) West of Fairfield-Vacaville, CA - Third Party Contractor Engine Failure

02OCT26: At 4:53A-PT, Train 521(02), E/C2005-4 cars-CC/C8303, was delayed at MP 56.5, 3 miles west of Fairfield-Vacaville, CA, on the UPRR Martinez Subdivision due to locomotive issues on E/C2005. An Amtrak trainmaster responded from Sacramento, CA and the crew contacted mechanical to troubleshoot. Head end power(HEP) remained up and active throughout the troubleshooting attempts while the 20 customers were on board. The crew was unable to resolve the issue and the customers were transferred to Train 523(02). Once all customers were transferred, the crew continued attempts to restart locomotive and deadhead the equipment to the Oakland Maintenance Facility for repairs. Due to the equipment issues on Train 521(02), the equipment from inbound Train 523(02) was turned in San Jose, CA for Train 528(02). Once the equipment arrived and was turned, Train 528(02) departed San Jose. The crew was able to restart E/C2005 at began deadheading the equipment at 9:13A-PT arriving into the Oakland Maintenance Facility at 11:00A-PT.

Train	Delay	Comment
521(02)	Term location	
523(02)	11"	Transfer 521(02) customers
528(02)	45"	Turn of 523(02) SJC

Train 22(02) North of Temple, TX - Temporary Speed Restrictions

02OCT26: Train 22(02), operating with engine 55, eight coaches, and 123 customers, was delayed 4.5 miles north of Temple TX, on BNSF Ft. Worth subdivision, due to operating under temporary speed restrictions due to BNSF track gangs performing work between Temple, TX and Cleburne, TX.

Train	Delay	Comment
22(02)	52"	

27-FO-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train 48/448(01) West of Buffalo, NY - Freight Train Interference

02OCT26: Train 48/448(01), operating with engines 1065/1012 coaches and 296 customers, was delayed 40 miles west of Buffalo, NY, on CSX Erie West subdivision, due to meeting and then following CSX10401 at control point 39 and following the freight for 40 miles to Buffalo, NY. Once the freight cleared and a route was madea available, train 48/448(01) was able to proceed.

Train	Delay	Comment
48/448(01)	49"	

Train 300(02) North of St. Louis, MO - Switch Failure

02OCT26: Train 300(02), operating with engine 4605, five coaches, and 123 customers, was delayed 0.02 miles north of Saint Louis, MO, on TRRA Merchants subdivision, due to a switch failure. Maintenance responded and was able to resolve the switch issue. Once resolved, train 300(02) then held for a freight to clear ahead of them.

Train	Delay	Comment
300(02)	34"	

Train 3(01) East of Lawrence, KS - Engine Failure

02OCT26: Train 3(01) was delayed at MP1.1, 36.8 miles east of Lawrence KS station on the BNSF Topeka subdivision due to engine 152 shutting down with no faults. Crew called in to troubleshoot with CNOC mechanical but where unable to resolved the issues and engine was set up as a control stand. Train 3(01) was back on the move at 1210AM CT. Train 3(01) arrived to Newton KS station at 344AM CT and added BNSF Freight engine 7818. Train 3(01) departed Newtown at 4:33AM CT with the freight engine added.

Train 3(01) had an extended delay at Albuquerque, NM completing daily inspections. There were 3 locomotives that needed to be inspected, including the freight unit, which gave some difficulty completing the tests.

Train	Delay	Comment
3(01)	45"	Adding Frt at DEN
3(01)	49"	Frt speeds NEW-ABQ
3(01)	42"	ABQ- Calendar day

Train 7/27(30) West of Libby, MT - Slide Fence

02OCT26: Train 7/27(30), E/368-E/353-11 cars, was delayed at MP 1353.4, 34 miles west of Libby, MT, on the BNSF Kootenai River Subdivision due to activating a slide fence. The crew stopped to inspect equipment. Once the equipment was inspected, a brake test was performed and Train 7/27(30) proceeded west.

Train	Delay	Comment
7/27(30)	07"	

Train 3(30) West of Flagstaff, AZ - Freight Train Interference

02OCT26: Train 3(30), operating with engines 167/198, nine coaches and 158 customers, was delayed 106 miles west of Flagstaff, AZ, on BNSF Seligman subdivision, due to following BNSF7157 from milepost 438.5 to milepost 480.5. Once the freight cleared and a route was made available, train 3(30) was able to resume normal speed.

Train	Delay	Comment
3(30)	1'24"	

Track Work Advisory 27-010 Heartland Flyer Service - M of W Work

02OCT26: 27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Heartland Flyer Service will be adjusted as follows:

· Train 821(18Oct), which normally operates between OKC and FTW, will be canceled in entirety and replaced by Bus.

· Train 822(18Oct), which normally operates between FTW and OKC, will be canceled in entirety and replaced by Bus.

ALTERNATE TRANSPORTATION

· Bus 3821 will provide alternate transportation between OKC and FTW

· Bus 3822 will provide alternate transportation between FTW and OKC

AFFECTED TRAINS (ORIGIN DATE)

Train 821(18Oct)

Train 822(18Oct)

STATION CODES

OKC – Oklahoma City, OK

FTW – Fort Worth, TX

WBS#: B.TR.100150.7234

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

BNSF Glasgow Subdivision West of Minot, ND - Freight Train Interference

30SEP26: The BNSF reported a freight derailment on the Glasgow subdivision just west of Minot at Shoo Tower/MP 0.63 with seven stack cars and 26 containers on the ground on the 6th Street overpass and blocking both main tracks. There were no hazmat cars involved in the derailment. The derailment ruptured a local gas line. Heavy equipment arrived on scene through 300PM-CT to aid in the cleanup efforts with 25 ballast cars enroute. Train 7/27(29) had access to the Minot depot. Train 7/27(29) arrived Minot at 951AM-CT, 51 minutes late and held for disposition. The rough estimated time for main track 2 to be opened was 800PM-CT. Customer service worked to source alternate bus transportation for a potential bus bridge with train 8/28(29) between Minot and Stanley. There were 197 customers on train 7/27(29) that were affected. Customer service recovery was initiated in Minot with Papa Johns pizza for lunch and a chicken dinner. There were 179 customers on train 8/28(29) that were affected.

BNSF advised that the estimated time of track opening was pushed back until midnight. As a result, a bus bridge was initially implemented between Minot and Stanley. Four buses were sourced at Minot for customers on train 7/27(29) between Minot and Stanley and staged at 500PM-CT. Four buses were sourced for customers on train 8/28(29) between Stanley and Minot and staged at 730PM-CT. All busses were released after an update was given for track opening to be 11:15PM-CT, account of the expected logistics involved regarding the wye and crew hours of service.

Train 8/28(29) was held just west of the derailment at CP189/MP18.9 for disposition. Main track #2 was opened at 10:32PM-CT with a 25mph speed restriction, and 7/27(29) departed Minot at 10:55PM-CT operating 13 hours and 11 minutes late. Train 8/28(29) was behind multiple freights and also had to wait and allow all stacked-up westbound trains to pass, including 7/27(29), before proceeding into Minot. Main track #1 returned to service October 1st at 12:00P-CT.

Due to the late operation of Train 7/27(29), service recovery was initiated with Jimmy Johns sandwiches and chips for dinner being provided to all customers upon arrival into Spokane, WA.

WBS#: B.TR.100150.7228

Train	Delay	Comment
8/28(01)	Canceled	
7/27(04)	Canceled	
8/28(29)	4'24"	
7/27(29)	12'13"	

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	

Maintenance of Way Highlights

27-FOIA-00046 700000008957 UNCLASSIFIED 10/18/2026

Union Pacific Brooklyn Subdivision Portland, OR - Portland Marathon TWA 27-003

04OCT26: The Portland Marathon occurred in Portland, OR, resulting in closure of rail operations at Southeast Stark Street (DOT #754542S) / MP 769.78 on the Brooklyn Subdivision, 1 mile south of the Portland, OR Union Station due to event-related roadway and crossing closure. As a result, the following operating plan was implemented:

Train 503(04) terminated in Portland.

Train 504(04) originated in Portland and operate 1-hour later.

Buses were secured to provide alternate transportation to customers traveling to and from all missed station stops.

WBS#: B.TR.100150.7209

Metrolink Orange Subdivision - Scheduled M/W Work 27-001

02OCT26: To accommodate the infrastructure work on the Metrolink Orange Subdivision beginning Friday, October 2nd at 10:00P-PT through Saturday, October 3rd at 6:00A-PT the following service adjustments were made affecting the Pacific Surfliner Service.

- Train 794(02-03OCT), which normally operates between San Luis Obispo, CA to San Diego, CA, terminated in Los Angeles, CA. Alternate bus 3594 was provided between Los Angeles and San Diego, making all station stops except San Juan Capistrano.
- Train 595(02-03OCT), which normally operates between San Diego, CA and Los Angeles, CA, was cancelled in its entirety. Customers were able to utilize bus 5811 as an alternative.

WBS#: B.TR.100150.7133

UPRR Coast Subdivision South of Oakland, CA - Scheduled M/W Work 27-009

02OCT26: The UPRR performed a switch removal at MP 14.992 on the Coast Subdivision beginning at 7A-PT on Saturday, October 3rd. To accommodate the infrastructure work, the following service adjustments were made.

- Train 11(02OCT), which normally operates between Oakland, CA and San Jose, CA on the UPRR Coast Subdivision detoured over the Niles Subdivision between Elmhurst/MP 14 and Newark/ MP 31 with no stops missed.

WBS#: B.TR.100150.7230

Coast Starlight - Scheduled M/W Work 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
11(22AUG)	32"	
14(22AUG)	23"	
11(12SEP)	29"	
14(12SEP)	50"	Detours/ ETI

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

27-FOIA-00046 00000008957 "UNCLASSIFIED" 10/19/2026

29JUL26: Amtrak / MDOT have coordinated schedules for the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

27-FOI-00046 0000P008957 UNCLASSIFIED 10/19/2026

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track and bridge projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3(1)	NEW	BNSF7818	E/152 not loading		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Bus 5874(01) Passenger Removal at Los Angeles, California – Improper Conduct

01OCT26, Passenger on PNR 260C6F, traveling from Bakersfield, CA to Los Angeles, CA was allegedly under the influence of an unknown substance. During the trip, the passenger became involved in an altercation with another passenger that escalated into a physical confrontation. The passenger allegedly assaulted and stabbed the other passenger. Amtrak Police responded to the incident and removed the suspect from the bus pending further investigation.

Delay: 5874(29) 4'20"

Consist Deviations

27-FOI-00046 00000008957 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
449 (02)	BOS	All Table Lounge in lieu of AMII lounge. no customer impact.			43397
448 (03)	CHI	All Table Lounge in lieu of AMII lounge. no customer impact.			43397
58 (02)	NOL	Operating with diner lounge in lieu of diner.			38016
89 (02)	NYP	AMII in Lieu of AMI coach. inventory reduced with no overages.	no impact	0	25044
90 (03)	SAV	AMII in Lieu of AMI coach. inventory reduced with no overages.	no impact	0	25044

Reverse Consists

Train Number	Station	Reason
94 (02)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
95 (02)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
171 (02)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
85 (02)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
190 (02)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
110 (02)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
137 (02)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
185 (02)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
174 (02)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
177 (02)	BOS	Consist reversed | Business class seat orientation may have changed | At Front