CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, October 04, 2026 Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00044

Initial Terminal Performance By Division

Scheduled Departure Date: **10/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/03/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	288	39	86.5%	947	114	88.0%	947	114	88.0%
Central Division	86.0%	59	0	100.0%	177	3	98.3%	177	3	98.3%
East Division	82.0%	147	20	86.4%	506	66	87.0%	506	66	87.0%
West Division	86.0%	82	19	76.8%	264	45	83.0%	264	45	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/3/26

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**104,589**	**27,818**	**73%**	**335,614**	**93,162**	**72%**	**335,614**	**93,162**	**72%**
Northeast Corridor	***81%***	***46,860***	***12,109***	***74%***	***148,018***	***36,180***	***76%***	***148,018***	***36,180***	***76%***
Acela	83%	7,760	1,217	84%	30,832	7,090	77%	30,832	7,090	77%
Northeast Regional	79%	39,100	10,892	72%	117,186	29,090	75%	117,186	29,090	75%
Richmond / Newport News / Norfolk	77%	10,922	752	93%	32,803	9,140	72%	32,803	9,140	72%
Springfield Shuttles	89%	900	272	70%	2,987	443	85%	2,987	443	85%
Roanoke	79%	4,069	2,286	44%	12,597	4,324	66%	12,597	4,324	66%
On Spine Northeast Regional	80%	23,209	7,582	67%	68,799	15,183	78%	68,799	15,183	78%
State Supported	***80%***	***45,064***	***10,134***	***78%***	***150,948***	***38,806***	***74%***	***150,948***	***38,806***	***74%***
Borealis	80%	637	162	75%	1,862	504	73%	1,862	504	73%
Capitol Corridor	90%	2,642	1,114	58%	11,997	3,235	73%	11,997	3,235	73%
Carolinian	70%	1,099	437	60%	3,629	1,325	63%	3,629	1,325	63%
Cascades	75%	2,852	635	78%	8,669	1,719	80%	8,669	1,719	80%
Downeaster	82%	2,097	659	69%	6,075	2,319	62%	6,075	2,319	62%
Empire	78%	5,849	814	86%	18,871	3,838	80%	18,871	3,838	80%
Adirondack	72%	360	0	100%	1,192	101	92%	1,192	101	92%
Ethan Allen Express	70%	456	217	52%	1,714	518	70%	1,714	518	70%
Maple Leaf	70%	819	26	97%	2,554	373	85%	2,554	373	85%
New York - Albany	85%	2,855	320	89%	9,077	1,525	83%	9,077	1,525	83%
New York - Niagara Falls	75%	1,359	251	82%	4,334	1,321	70%	4,334	1,321	70%
Gold Runner	73%	2,413	623	74%	8,483	3,068	64%	8,483	3,068	64%
Heartland Flyer	70%	213	207	3%	545	539	1%	545	539	1%
Hiawatha	90%	1,958	0	100%	5,986	0	100%	5,986	0	100%
Illinois	78%	2,754	618	78%	8,864	2,462	72%	8,864	2,462	72%
Carl Sandburg / Illinois Zephyr	85%	430	91	79%	1,310	397	70%	1,310	397	70%
Illini / Saluki	85%	978	40	96%	3,302	492	85%	3,302	492	85%
Lincoln Service	70%	1,346	487	64%	4,252	1,573	63%	4,252	1,573	63%
Keystone	92%	5,874	357	94%	26,225	2,985	89%	26,225	2,985	89%
Lincoln / Missouri	70%	807	341	58%	2,565	1,439	44%	2,565	1,439	44%
Mardi Gras Service	80%	251	120	52%	844	161	81%	844	161	81%
Michigan	70%	2,556	515	80%	7,102	1,859	74%	7,102	1,859	74%
Blue Water	70%	825	336	59%	1,649	551	67%	1,649	551	67%
Pere Marquette	85%	279	53	81%	907	53	94%	907	53	94%
Wolverine	70%	1,452	126	91%	4,546	1,255	72%	4,546	1,255	72%
Missouri	80%	400	0	100%	926	109	88%	926	109	88%
Pacific Surfliner	85%	9,357	3,162	66%	27,761	10,754	61%	27,761	10,754	61%
Pennsylvanian	80%	851	15	98%	2,868	324	89%	2,868	324	89%
Piedmont	80%	1,110	156	86%	3,352	338	90%	3,352	338	90%
Vermonter	75%	1,344	199	85%	4,324	1,828	58%	4,324	1,828	58%
Long Distance	***70%***	***12,665***	***5,575***	***56%***	***36,648***	***18,176***	***50%***	***36,648***	***18,176***	***50%***
Auto Train	70%	702	0	100%	2,094	861	59%	2,094	861	59%
California Zephyr	70%	1,251	681	46%	2,498	1,273	49%	2,498	1,273	49%
Cardinal	70%	308	224	27%	1,109	857	23%	1,109	857	23%
City Of New Orleans	75%	793	631	20%	2,096	1,435	32%	2,096	1,435	32%
Coast Starlight	70%	1,276	650	49%	3,531	1,342	62%	3,531	1,342	62%
Crescent	70%	859	145	83%	2,867	486	83%	2,867	486	83%
Empire Builder	70%	550	10	98%	2,474	1,201	51%	2,474	1,201	51%
Floridian	60%	1,754	1,183	33%	4,463	3,357	25%	4,463	3,357	25%
Lake Shore Ltd	73%	1,090	53	95%	3,333	924	72%	3,333	924	72%
Palmetto	70%	855	204	76%	2,526	638	75%	2,526	638	75%
Silver Meteor	70%	1,052	75	93%	2,739	1,010	63%	2,739	1,010	63%
Southwest Chief	60%	952	942	1%	2,655	2,518	5%	2,655	2,518	5%
Sunset Ltd	70%	0	0	-	724	194	73%	724	194	73%
Texas Eagle	70%	1,223	777	36%	3,539	2,080	41%	3,539	2,080	41%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00046 00000000050 "UNCLASSIFIED" 10/10/2026~~

Train Index Dates Through October 03, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	17,649	327,784	538	17,649	327,784	538

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	769	100,411	77	769	100,411	77
INFRASTRUCTURE PLANNED	135	2,177	100,411	217	2,177	100,411	217
FLEET RELIABILITY	90	2,712	327,784	83	2,712	327,784	83
TRAIN OPERATIONS	424	11,991	327,784	366	11,991	327,784	366

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00044

Initial Terminal Performance By Division

Scheduled Departure Date: **10/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/03/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	288	39	86.5%	947	114	88.0%	947	114	88.0%
Central Division	86.0%	59	0	100.0%	177	3	98.3%	177	3	98.3%
East Division	82.0%	147	20	86.4%	506	66	87.0%	506	66	87.0%
West Division	86.0%	82	19	76.8%	264	45	83.0%	264	45	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/03/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	288	39	86.5%	947	114	88.0%	947	114	88.0%
Central Division	86.0%	59	0	100.0%	177	3	98.3%	177	3	98.3%
CDL	95.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
CHI	86.0%	27	0	100.0%	83	2	97.6%	83	2	97.6%
FTW	92.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
GRR	95.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
KCY	92.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
MKE	92.0%	6	0	100.0%	18	0	100.0%	18	0	100.0%
MOE	97.5%	2	0	100.0%	6	0	100.0%	6	0	100.0%
MSP	96.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
NOL	94.5%	5	0	100.0%	13	1	92.3%	13	1	92.3%
OKC	97.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
PNT	88.0%	3	0	100.0%	9	0	100.0%	9	0	100.0%
PTH	93.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
QCY	91.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
SAS	90.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
STL	89.0%	4	0	100.0%	12	0	100.0%	12	0	100.0%
East Division	82.0%	147	20	86.4%	506	66	87.0%	506	66	87.0%
ALB	88.5%	8	0	100.0%	24	1	95.8%	24	1	95.8%
BON	87.5%	5	1	80.0%	15	1	93.3%	15	1	93.3%
BOS	85.5%	18	1	94.4%	56	2	96.4%	56	2	96.4%
BRK	92.5%	5	0	100.0%	15	2	86.7%	15	2	86.7%
BTN	82.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
CLT	91.5%	5	1	80.0%	14	2	85.7%	14	2	85.7%
GFD	88.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
GRO	-	-	-	-	1	0	100.0%	1	0	100.0%
HAR	79.5%	7	1	85.7%	33	7	78.8%	33	7	78.8%
HFD	-	-	-	-	4	0	100.0%	4	0	100.0%
LOR	84.0%	1	1	0.0%	3	1	66.7%	3	1	66.7%
MIA	89.5%	2	1	50.0%	6	1	83.3%	6	1	83.3%
MTR	79.0%	1	1	0.0%	3	2	33.3%	3	2	33.3%
NFK	84.5%	2	1	50.0%	6	2	66.7%	6	2	66.7%
NFL	93.5%	2	0	100.0%	6	1	83.3%	6	1	83.3%
NHV	78.0%	4	2	50.0%	14	3	78.6%	14	3	78.6%
NPN	93.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
NYP	75.5%	37	6	83.8%	140	18	87.1%	140	18	87.1%
PGH	93.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
PHL	48.0%	4	2	50.0%	14	8	42.9%	14	8	42.9%
RGH	95.0%	4	0	100.0%	10	1	90.0%	10	1	90.0%
RNK	83.5%	2	0	100.0%	6	1	83.3%	6	1	83.3%
SAB	98.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
SAV	96.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
SFA	88.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%
SPG	92.5%	6	1	83.3%	16	1	93.8%	16	1	93.8%
TWO	73.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/03/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	288	39	86.5%	947	114	88.0%	947	114	88.0%
East Division	82.0%	147	20	86.4%	506	66	87.0%	506	66	87.0%
WAS	84.0%	24	1	95.8%	90	10	88.9%	90	10	88.9%
West Division	86.0%	82	19	76.8%	264	45	83.0%	264	45	83.0%
ARN	92.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
BFD	79.0%	7	3	57.1%	21	5	76.2%	21	5	76.2%
EMY	72.0%	-	-	-	2	2	0.0%	2	2	0.0%
EUG	86.5%	2	0	100.0%	6	0	100.0%	6	0	100.0%
GTA	90.0%	3	1	66.7%	9	3	66.7%	9	3	66.7%
LAX	89.5%	10	0	100.0%	31	2	93.5%	31	2	93.5%
OKJ	74.5%	9	2	77.8%	35	7	80.0%	35	7	80.0%
PDX	86.0%	5	0	100.0%	14	0	100.0%	14	0	100.0%
SAC	88.5%	12	1	91.7%	44	5	88.6%	44	5	88.6%
SAN	90.5%	12	3	75.0%	37	5	86.5%	37	5	86.5%
SEA	85.0%	8	3	62.5%	23	4	82.6%	23	4	82.6%
SJC	89.0%	7	5	28.6%	21	11	47.6%	21	11	47.6%
SLO	90.0%	3	1	66.7%	9	1	88.9%	9	1	88.9%
SPK	90.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
VAC	97.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	546	3	1	66.7%	3	1	66.7%	3	3	0.0%	3	3	0.0%
4	146	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
5		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
6		2	2	0.0%	2	2	0.0%	3	2	33.3%	3	2	33.3%
7		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
11	17	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
14		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
19	22	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
20		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
21		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
22	113	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
23		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
24		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
25	39	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
26	17	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
27		3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
28		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
40	36	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
41		3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
42		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
43		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
48		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
49		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
51	57	1	0	100.0%	1	0	100.0%	2	2	0.0%	2	2	0.0%
52		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
53		3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
54		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
57		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
58	47	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
59	51	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
63	39	3	2	33.3%	3	2	33.3%	3	3	0.0%	3	3	0.0%
64		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
65		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
66		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
68		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
69		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
71		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
72		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
73		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
74	118	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
75	Cncld	3	0	100.0%	3	0	100.0%	2	0	100.0%	2	0	100.0%
76	Cncld	3	1	66.7%	3	1	66.7%	2	0	100.0%	2	0	100.0%

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
78		3	0	100.0%	3	0	100.0%	4	1	75.0%	4	1	75.0%
79	31	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
80		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
82		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
87		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
88		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
89	64	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
90		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
97		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
98		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
99		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
101		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
103		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
106		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
107		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
109		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
118		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
124		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
126		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
127		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
135		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
136		2	0	100.0%	2	0	100.0%	3	0	100.0%	3	0	100.0%
140		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
142		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
143		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
144		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
146	25	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
147	48	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
150		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
151		3	3	0.0%	3	3	0.0%	3	1	66.7%	3	1	66.7%
152		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
153		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
155		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
156	35	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
158		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
159		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
160		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
161	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
162	55	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
163	28	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
164	44	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%

Amtrak On Time Performance

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
165		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
167	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
168	33	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
178	50	2	0	100.0%	2	0	100.0%	3	2	33.3%	3	2	33.3%
179		2	0	100.0%	2	0	100.0%	3	0	100.0%	3	0	100.0%
194		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
195		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
198		2	0	100.0%	2	0	100.0%	3	0	100.0%	3	0	100.0%
230		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
232		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
233		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
234		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
235	35	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
236		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
237	37	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
238		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
239		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
240		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
241		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
243		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
244		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
245		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
280		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
281		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
283		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
284		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
290		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
291	22	3	3	0.0%	3	3	0.0%	3	1	66.7%	3	1	66.7%
300	21	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
301		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
302		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
305	24	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
306		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
307		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
311		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
316		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
318	25	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
319		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
330		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
331		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
332		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
334		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
336		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
337		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
338		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
339		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
341		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
342		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
343		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
350		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
351		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
352		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
353		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
354		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
355		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
364		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
365		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
370		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
371		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
380		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
381		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
382		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
383	22	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
390		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
391		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
392		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
393		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
400		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
405		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
448		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
449		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
450	21	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
460		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
461		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
463	16	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
464		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
467		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
488		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
499		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
500		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
502		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
503		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
504		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%

Amtrak On Time Performance

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
506		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
507	30	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
508	22	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
509		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
511		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
516	33	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
517	18	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
518		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
519		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
562		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
564		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
566	74	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
567		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
572	144	3	2	33.3%	3	2	33.3%	3	3	0.0%	3	3	0.0%
573		3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
579		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
580		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
581		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
584		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
587	Cncld	3	2	33.3%	3	2	33.3%	2	1	50.0%	2	1	50.0%
588		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
591		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
593		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
611		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
624		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
660		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
661		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
662		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
663		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
664		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
665		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
666		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
667		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
669		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
670		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
671		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
672	28	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
674		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
690		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
691		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
692	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
693		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
694		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
695	29	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
696	37	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
697		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
698		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
701		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
702		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
703	22	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
704		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
710		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
711	Cncld	3	0	100.0%	3	0	100.0%	2	0	100.0%	2	0	100.0%
712		3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
713	18	3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
714		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
715		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
716		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
717		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
718		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
719		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
720		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
723		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
724	36	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
727		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
728	23	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
729		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
732		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
733	29	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
734	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
736		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
737		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
738	34	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
741	Cncld	1	0	100.0%	1	0	100.0%			0.0%			0.0%
742		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
743		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
744	163	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
745		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
746	Cncld	1	1	0.0%	1	1	0.0%			0.0%			0.0%
747	51	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
748		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
749		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
751		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
757		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
761		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
765		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
769	69	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
770		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
774	84	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
777	20	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
782	55	3	3	0.0%	3	3	0.0%	3	1	66.7%	3	1	66.7%
785	133	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
786		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
790		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
794	44	3	1	66.7%	3	1	66.7%	4	3	25.0%	4	3	25.0%
821	64	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
822	46	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
1333	24	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
1340		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
1689	24	3	0	100.0%	3	0	100.0%	2	1	50.0%	2	1	50.0%
2203		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2207		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2208		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2211		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2219		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2224		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2226		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2250		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2252		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2254		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2255		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2256		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2258	37	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2259		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2260		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2262		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2263		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2265	17	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
2267		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2271		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2293		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak Endpoint OTP Details

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2258	BOS	37	ENG	38	ENG	19	NHV-XGX	AM	Radio failure, 2136|NG|NP, no radio data, capped at 79 MPH
2265	WAS	17	SMW	29	DSR	16	NHV-STM	MN	Per bulletin Milepost, 48.8, 33.6, 30, 1
146	SPG	25	SMW	22	DSR	9	STM-NHV	MN	Per bulletin Milepost, 41.7, 42.0, 15, 2
147	RNK	48	PTI	39	FTI	11	CVS-LYH	NS	Meet 28R, Control Point, Tye River
156	NYP	35	SMW	29	SMW	13	NWK-NYP	AM	Scheduled in track usage program, Other, SINGLE TRACKING IN THE SOUTH TUBE A/C NORTH TUBE O/O/S
161	WAS	21	PTI	11	WTR	6	OSB-NHV	AM	Wet / slippery rail, Milepost, osb, nhv, Wheelslip
162	BOS	55	CTI	29	DCS	19	WAS-XNY	AM	T.O.L, Control Point, K INTERLOCKING, TOL OVER 328 SW NOR. K TOWER COULD NOT VERIFY THE SWITCH WAS CLEAR. BACKED THE TRAIN INTO THE STA., TO TAKE THEM OUT 40 TRK
163	WAS	28	CTI	19	CTI	13	BRP-STM	MN	Meet mn, Control Point, 240
164	BOS	44	DCS	45	DCS	45	PVD-RTE	AM	Power switch failure, Milepost w/Letters, PVD, RTE, switch failure at XMF interlocking
167	PHL	19	DCS	41	DCS	41	RTE-PVD	AM	Power switch failure, Milepost w/Letters, RTE, PVD, switch failure at XMF interlocking
168	BOS	33	SMW	22	SMW	12	NWK-NYP	AM	Scheduled in track usage program, Other, NORTH TUBE O/O/S SINGLE TRACKING IN THE SOUTH TUBE
178	BOS	50	MTI	50	MTI	35	WAS-WAS	AM	Disabled train ahead, Milepost, CP AVEUNE, WAS, HELD DUE TO AM2155 BROKEN DOWN AT CP AVENUE.
450	SPG	21	SMW	13	SMW	13	NHV-NHV	AM	Scheduled in track usage program, Milepost, nhv, nhv, Held at NHV for AM195 a/c track outage
463	NHV	16	PTI	10	PTI	10	SPG-SPG	AM	Wait for station track, 460, Milepost, SPG, SPG, Held for AM460 to clear
79	CLT	31	PTI	49	PTI	27	RGH-RGH	NS	Meet Holding in station for AM 74's arrival., AM 74, Control Point, BOYLAN
672	NYP	28	SVS	31	SVS	31	PHL-XHM	AM	Unplanned Wye, WYE ON THE OUTBOUND A/C BAD EQUIPMENT
19	NOL	22	FTI	61	FTI	48	HBG-PIC	NS	Meet Cleared the main and waiting for NS130 at Derby… had to line the switch for the siding.., NS1107/130, Milepost, 129.7, 131.7
692	BON	26	ENG	15	ENG	15	POR-POR	CS	PTC- IETMS hard cutout 90214

Amtrak Endpoint OTP Details

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
695	BRK	29	DCS	30	DCS	30	BON-HHL	MT	Power switch failure Switch being repaired, congested rail, Control Point, CPF Vale
696	BON	37	DMW	35	DMW	35	HHL-WOB	MT	Hold for defect repair Foreman taking switch off power, Control Point, Vale
1689	BRK	24	WTR	12	FTI	10	EXR-DHM	CS	Meet LO 80, Control Point, Rockingham, westbound
63	TWO	39	FTI	11	CTI	7	CRT-POU	MN	Follow mnrr, local, Control Point, 46
235	ALB	35	ENG	38	ENG	18	YNY-YNY	MN	Was not getting valid TSR data after entering MNRR territory. Held in Yonkers while Engineer attempted to re-test the system. After retesting the system still had no valid TSR data from passing CP 19. Capped at 59 MPH, 97, 705
237	ALB	37	ENG	15	ENG	13	NYP-XSD	AM	Air / Brake, 717|DX|DM, ENGR REPORTED STOPPED MP3 AIR BLOWING, LOOSE HOSE
291	BTN	22	CCR	43	CCR	43	NYP-NYP	AM	Air / Brake / Wheel, 9705, Engineer reported brake issues on C/C 9705
74	RGH	118	SYS	76	SYS	48	HPT-GRO	NS	Blocked by or assisting another, disabled Amtrak train Connecting #Amt 74 equipment to #Amt 75 due to RNCX 1869 shutdown., Other, HPT
75	CLT	Trn Cancelled	DSR	12	DSR	9	BNC-GRO	NS	Per bulletin Milepost w/Letters, 5.7NC, 2.4NC, 25, 1
76	RGH	Trn Cancelled							
89	SAV	64	FTI	102	FTI	49	CHS-CHS	CS	Meet S888, Milepost, 387.7, 387.7
40	CHI	36	FTI	119	FTI	28	SAV-DNK	CS	Meet Unknown, Siding, Meinhard
25	NOL	39	DCS	35	DCS	35	BAS-XNO	CS	Restrictive signal(s) from unknown cause Stop signal/ s e Claiborne , Stop signal/ pearl river db, Milepost, 768.1, 775.4
26	MOE	17	DCS	42	DCS	39	XNO-BAS	CS	Restrictive signal(s) from unknown cause Multiple signals requiring dispatcher permission to pass signals displaying stop, Stop, Milepost, 781.8, 772.8
724	SAC	36	TEN	28	TEN	28	SJC-SJC	UP	Failure of diesel engine Started Fail, JPBX921
728	SAC	23	MBO	24	MBO	24	MTZ-SUI	UP	For maritime traffic Bridge, Suisun
733	SJC	29	PTI	23	PTI	16	GAC-SCC	UP	Meet Shuffle at Expressway, 734, Control Point, CO044

Amtrak Endpoint OTP Details

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
734	SAC	19	PTI	32	PTI	21	OAC-OKJ	UP	Wait for station track Dispatcher brought out 716 and had 736 on the inside track frogging us, 716, Control Point, NI008
738	SAC	34	DCS	38	DCS	23	RIC-MTZ	UP	Restrictive signal(s) from unknown cause Hand throw switches and flag to RV030., Red at RV027, Control Point, RV027
741	SJC	Trn Cancelled	DSR	5	PTI	3	BKY-EMY	UP	Meet amt 716, Control Point, RV006
744	ARN	163	SYS	65	TEN	62	SJC-SJC	UP	Failure of diesel engine Engine coolant failure resulting in shut down. Dead headed to SJC to use alternate equipment: Amtk746 equipment., C2013
746	SAC	Trn Cancelled							
747	SJC	51	PTI	38	PTI	35	HAY-FMT	UP	Meet 744, Control Point, Hayward
51	CHI	57	FTI	86	FTI	70	XTJ-XEF	UP	Cross Traffic IHB, cross traffic, unknown east, Milepost, 16.7, 16.7
507	EUG	30	FTI	36	FTI	33	ALY-EUG	UP	Meet UP 5793, Siding, Swain
508	SEA	22	FTI	24	FTI	16	ALY-SLM	UP	Meet Amtrak 14, Siding, Renard
516	VAC	33	ENG	33	ENG	33	SEA-SEA	BN	Air / Brake Would not release train brake do to bypass not in right direction, WS1404
517	PDX	18	ADA	8	FTI	5	KEL-VAN	BN	Meet BNSF 5775, Control Point, Felida
58	CHI	47	DSR	73	PTI	34	XSU-HMD	CC	Meet AMTK #59, Siding, Manchac
59	NOL	51	DSR	83	FTI	22	HMD-XSU	CC	Cross Traffic unknown, Control Point, East Bridge Jct.
11	LAX	17	DCS	93	CAR	60	SEA-SEA	BN	Toilet 32037, Mechanical repair main line clog
821	FTW	64	FTI	54	FTI	28	GLE-FTW	BN	Meet BN 6710, BN Freight, Siding, Justin
822	OKC	46	DSR	43	DSR	33	FTW-GLE	BN	Per bulletin Milepost, 350.7, 351.1, 50, mt1, Milepost, 354.7, 355.2, 60, mt2, Milepost, 355.1, 355.6, 60, mt2, Milepost, 355.6, 355.8, 40, mt2, Milepost, 356.3, 357.9, 60, mt2, Milepost, 357.3, 358.2, 50, mt2, Milepost, 358.2, 358.4, 50, mt2, Milepost, 358.3, 359.5, 30, mt2, Milepost, 361.0, 361.2,
566	SAN	74	PTI	41	PTI	41	SNC-SNP	SC	Meet 769, Control Point, serra
572	SAN	144	ENG	118	ENG	118	SOL-OLT	SN	Fuel issue C2118
587	LAX	Trn Cancelled							

Amtrak Endpoint OTP Details

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
769	GTA	69	CTI	40	CTI	40	OSD-X98	SN	Meet mtlk, Control Point, pulgas
774	SAN	84	SYS	80	SYS	80	SOL-OLT	SN	Blocked by or assisting another, disabled Amtrak train Rescued train 572., Control Point, Rose
777	SLO	20	PTI	39	PTI	22	OXN-VEC	UP	Meet AMTK 790, Control Point, South Ventura
782	SAN	55	PTI	57	PTI	18	GTA-GTA	UP	Wait for station track 14, Control Point, S ELLWOOD
785	GTA	133	ITI	81	ITI	73	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 572, Waiting for combined 572-774 train to arrive. Flagged and inspected by mechanical.
794	LAX	44	POL	31	POL	31	CML-CML	UP	Disruptive passengers in cab car making it difficult for engineer to hear radio and focus. Had assist from Camarillo police.
703	SAC	22	FTI	31	FTI	24	SKT-LOD	UP	Meet UP 2604, Siding, Lodi
711	OKJ	Trn Cancelled	PTI	29	PTI	16	TRK-MOD	BN	Meet 704, Control Point, w empire
713	OKJ	18	PTI	18	PTI	10	HNF-FNO	BN	Meet 702, Control Point, W Conejo
3	LAX	546	ENG	310	FTI	99	XIA-GLP	BN	Follow BNSF Unknown, Milepost, 38, 140
4	CHI	146	FTI	163	FTI	58	LAP-FMD	BN	Meet BNSF 5618, BNSF 4999, Control Point, Medil
22	CHI	113	FTI	131	DSR	32	TPL-MCG	BN	Per bulletin Fort Worth subdivision (BNSF), Milepost, 221.1, 221.3, 50, MT, Milepost, 222.1, 222.4, 25, MT, Milepost, 223.2, 228.6, 25, MT, Milepost, 225.0, 229.0, 25, MT, Milepost, 229.4, 230.7, 30, MT, Milepost, 232.5, 232.7, 60, MT, Milepost, 233.4, 235.2, 25, MT, Milepost, 236.0, 238.5, 30, MT,
300	CHI	21	FTI	29	FTI	12	LCN-BNL	UP	Meet UP 2584, Siding, Athol
305	STL	24	FTI	24	FTI	17	SPI-CRV	UP	Meet Freight, Siding, Auburn
383	QCY	22	DSR	13	CTI	7	LAG-NPV	BN	Follow Metra, Milepost, 13.7, 17.7
318	CHI	25	HLD	23	HLD	9	HEM-HEM	UP	High passenger count Over 100 people getting off
1333	MSP	24	FTI	45	FTI	36	XH8-MSP	CP	Follow UEOCEVO, Control Point, cp3690

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/3/2026

Terminal	Train	Date	Late	Delay	Cause
BON	697	10/03	2	2	Mobility Impaired
BOS	2265	10/03	8	8	Planned set out / pick out of locomotives, cars or section of train, late change of equipment
CLT	76	10/03	(Trn Cxld)		Engine Issue
HAR	666	10/03	2	2	Other electrical failure, 658|EX|ES, door bypass
LOR	53	10/03	51	51	DRUMMAC short staff
MIA	98	10/03	6	6	Late / wrong track bulletins from host railroad SFRTA received train sheet information late, Bulletins came late, then bulletins had the incorrect date, had to reissue new bulletins., SFRTA, Other, Mia
MTR	68	10/03	1		
NFK	128	10/03	10	10	Norfolk Mechanical left the train blue flagged. Had to wait for someone to come and remove it.
NHV	450	10/03	13	13	Scheduled in track usage program, Milepost, nhv, nhv, Held at NHV for AM195 a/c track outage
NHV	460	10/03	9	9	Scheduled in track usage program, Milepost, nhv, nhv, Held at NHV a/c track outage
NYP	43	10/03	7	7	Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE
NYP	63	10/03	2	2	Cross Traffic, NJT, NJ7821, Other, NYP-NYP, NJ7821 XING AHEAD
NYP	69	10/03	4	4	Meet, AM232, Other, NYP-NYP, HELD A/C AM232 XING AHEAD
NYP	127	10/03	7	7	Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE
NYP	291	10/03	43	43	Air / Brake / Wheel, 9705, Engineer reported brake issues on C/C 9705
NYP	2207	10/03	2	2	Passenger and/or baggage, LOADING
PHL	151	10/03	1	1	Planned set out / pick out of locomotives, cars or section of train, late release out of the yard
PHL	611	10/03	1	1	High passenger count
SPG	463	10/03	10	10	Wait for station track, 460, Milepost, SPG, SPG, Held for AM460 to clear
WAS	2252	10/03	5	5	Door, 3306|LH|LB, DOOR WAS NOT CLOSING ALL THE WAY.
BFD	713	10/03	3	3	Door C9301, Steps did not retract completely
BFD	717	10/03	1	1	Door C9804, Door would not close fully
BFD	719	10/03	9	9	Hold for thruway bus
GTA	782	10/03	18	18	Wait for station track 14, Control Point, S ELLWOOD
OKJ	712	10/03	3	3	Conductor's fault late out of OMF. Poor backward planning.

Amtrak Initial Terminal Details

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/3/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	718	10/03	8	5	Door C9803, Had to cut out door wasn't receiving a door light contacted Tasi .. they said to open and close wheel chair lift door
OKJ	718	10/03	8	3	PTC- IETMS recycle breaker to clear fault PTC fault caused for another air brake test, C8308
SAC	727	10/03	2	2	Wheelchair Lift has hydraulic fluid shooting out and it dumped the train right before on time departure
SAN	587	10/03	(Trn Cxld)		HEP Issue
SAN	593	10/03	20	20	Late departure at initial terminal due to late arrival of inbound equipment 782
SAN	785	10/03	73	73	Late departure at initial terminal due to late arrival of inbound equipment 572, Waiting for combined 572-774 train to arrive. Flagged and inspected by mechanical.
SEA	8	10/03	11	11	Toilet 34139
SEA	503	10/03	1		
SEA	516	10/03	33	33	Air / Brake Would not release train brake do to bypass not in right direction, WS1404
SJC	724	10/03	28	28	Failure of diesel engine Started Fail, JPBX921
SJC	728	10/03	11	11	Originating Engine was bad took over next train set from AMTK 727.
SJC	738	10/03	1		
SJC	744	10/03	62	62	Failure of diesel engine Engine coolant failure resulting in shut down. Dead headed to SJC to use alternate equipment: Amtk746 equipment., C2013
SJC	746	10/03	(Trn Cxld)		Third Party Engine Failure
SLO	794	10/03	1	1	Door C6451, Door 6 stuck in the pocket. Now it's locked.

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	100.0	70.9	90.2	15	0
SEPTA	95.0	84.8	89.5	91.5	105	16
NJT-NED	95.0	91.8	94.8	88.6	195	16
NJT-SED	95.0	100.0	97.1	97.2	24	0

Operating Highlights

Train 695(03) - North of Boston, MA - Switch Failure

03OCT26: Train 695(03) was delayed on the CSX Portland Subdivision at MP 106.7 due to switch failure ahead at CP Vale/MP 104.3.

Train	Delay	Comment
695(03)	30"	

Train 52(03) - North of Jesup, GA - Freight Train Interference

03OCT26: Train 52(03) was delayed on the CSX Nahunta Subdivision at MP 518.9 due to meeting CAX Train M492-03.

Train	Delay	Comment
52(03)	1'02"	

Train 40(03) - North of Kissimmee, FL - Trespasser Incident

03OCT26: 7:12pm Train 40(03) with E/57 and E/315, plus 10 cars, carrying 159 passengers, struck a trespasser at MP 805.09 on the Central Florida Rail Corridor (CFRC), Orlando Subdivision, at DOT Crossing 622407J, Garden Street, in the City of Kissimmee, Osceola County, FL. There were no reported injuries to crews or passengers. The trespasser was a confirmed fatality. There was no reported damage to the equipment. The weather at the time of the incident was 79° and partly cloudy. The crossing was designated with pavement markings, automated gate arms, and mast mounted flashing lights - all of which were functioning at the time of incident.
The initial first responders to the scene were Kissimmee Police and EMS. The investigation was then taken over by Florida Highway Patrol, which extended the delay, due to awaiting a FHP Detective to respond, which in turn, triggered the summons to the coroner.
The delay was considerably prolonged by on scene agencies contesting jurisdiction.

National Response Center Number: 1475288

Train	Delay	Comment
40(03)	5'45"	

27-FOI-00046 000000008956 "UNCLASSIFIED" 10/19/2026

Train 98(03) - North of Jesup, GA - Tree Strike

03OCT26: Train 98(03) with E218 and E118 plus 10 cars, carrying 181 passengers, struck a large tree near MP 517.6. The lead engine 319 shut down upon impact. HEP remained up and held on the trail engine 118. The crew consulted with CNOC Mechanical to work through the recycling procedure. The engine was restarted with all faults cleared, after which, Train 98(03) was able to continue north.

Train	Delay	Comment
98(03)	47"	

Train 53(03) Lorton, VA - Initial Terminal Delay

03OCT26: Train 53(03) operating with engines 352, 360, 43 cars, and 424 customers on board was delayed departing Lorton, VA on the CSX RF&P subdivision due to Drummac being short staffed. Once the train was loaded and boarded, Train 53(03) departed the station at 4:51 PM-ET.

Train	Delay	Comment
53(03)	51"	

Train 75(03) High Point, NC - Engine Failure

03OCT26: Train 75(03), operating with engine NC1869, 4 cars, engine NC102, and 92 customers, experienced an engine failure at the High Point, NC station on the NS Charlotte District after the lead engine shut down twice with an over-pressure fault. Train 75(03) was terminated at the High Point, NC station. The equipment was coupled to Train 74(03). Customers were transported to the Greensboro, NC station for reaccommodation on Train 77(03).

As a result of the incident, Train 76(03) was canceled, and alternate transportation was able to be arranged. Two buses were secured to operate between Charlotte and Raleigh. The buses made all stops. All other customers were reaccommodated on Train 78(03).

Train	Delay	Comment
75(03)	Term HPT	
76(03)	Cancelled	
74(03)	48"	Couple equipment

Train 291(03) New York, NY - Initial Terminal Delay - Cab Car Failure

03OCT26: Train 291(03) operating with cab car 9705, 5 cars, engine 702, and 204 customers onboard was delayed departing New York, NY on the Amtrak NYT Line due to brake issues on cab car 9705. Mechanical reported to the train and was able to rectify the issue. The train departed the station at 3:02 PM-ET.

Train	Delay	Comment
291(03)	43"	

Train 80(03) North of Rocky Mount, NC - Injured or Sick Passenger or Employee

03OCT26: Train 80(03) operating with engine 174, 7 cars, and 228 customers onboard was stopped at milepost 101.1, 18 miles north of Rocky Mount, NC on the CSX North End subdivision due to requesting medical assistance for a customer on the train. Emergency services responded to the train. The customer decided to not be transported to the hospital and stayed onboard the train. Once emergency services were clear of the train, Train 80(03) advanced to the next station.

Train	Delay	Comment

27-FOI-00046 90000008956 "UNCLASSIFIED" 10/19/2026

Train 40(02) Cary, NC - Passenger Removal - Police Related

03OCT26: Train 40(02) operating with engines 114, 37, 11 cars, and 140 customers onboard was delayed departing Cary, NC on the CSX Aberdeen subdivision due to having a passenger removed for the train by the police. It was reported that the passenger stated that he was poisoned. Once the passenger was removed from the train, Train 40(02) advanced to the next station.

Train	Delay	Comment
40(02)	30"	

Train 40(03) North of Hollywood, FL - Commuter Train Interference

03OCT26: Train 40(03) operating with engines 57, 315, 10 cars, and 126 customers onboard was delayed at milepost 1019.4, north of Hollywood, FL on SFRTA territory due to TriRail train P672 becoming disabled in a single-track area. Once the commuter train was able to recover and clear, Train 40(03) advanced to the next station.

Train	Delay	Comment
40(03)	51"	

Train 53(02) North of Jesup, GA - Freight Train Interference

03OCT26: Train 53(02) operating with engines 364, 354, 43 cars, and 406 customers onboard was delayed at milepost 540.1, 8 miles north of Jesup, GA on the CSX Nahunta subdivision due to a possible trespasser strike by CSX freight train I197-03. The freight crew walked the train and it was found there was no strike. Train 53(02) then followed CSX freight train IO31-02 once train traffic was able to resume. Once the freight trains cleared, Train 53(02) was able to advance south.

Train	Delay	Comment
53(02)	40"	

Train 53(03) - Charleston Station, SC - Trespasser Incident

04OCT26: 2:05am Trian 53(03) with E/352 and E/360, plus 14 passenger cars and 28 auto carriers, carrying 410 passengers, struck a trespasser, who was laying in the gauge. There were no reported injuries to crew or passengers. The trespasser was discovered underneath the train. HEP was temporarily dropped while crews worked to remove the woman from underneath the train. Once removed, the woman as transported to a local hospital while conscious and moving.
The location of the incident was within the limits of the City of North Charleston, Charleston County, SC. This incident did not occur at a grade crossing. The temperature at the time of the incident was 74° and cloudy.
After a swift investigation by the Charleston County Police Department, Train 53(03), was released and advanced to CP South Ravenel/MP 408.0, where it held for a relief engineer.

National Response Center Number: 1475293

Train	Delay	Comment
53(03)	1'15"	
53(03)	TBD	Hold for Recrew

Maintenance of Way Highlights

27-FOI-00046 0000008856 "UNCLASSIFIED" 10/19/2026

MBTA Downeaster Track Work - Scheduled M/W Work - TW 26-094 - 9/12-10/11

21AUG26: To support the MBTA bridge replacement at MP 8.99 the below service adjustments have been made:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound

- Trains 693 and 695 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

- Train 699 (13Sep, 20Sep, 4Oct, 10Oct-11Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

- Train 1689 (12Sep, 19Sep, 26Sep-27Sep, 3Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

o Please note Trains 691 and 697 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct) will operate NORMAL.

Southbound

- Trains 690, 692, 694, 696, and 698 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

WBS#: B.TR.100150.7065

Train	Delay	Comment
696(03)	35"	HHL-WOB
695(03)	30"	BON-HHL

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046, 00000008956 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) will operate as a deadhead train that will operate as a deadhead between NHV and HFD.

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

Train 6(02) West of Lincoln, NE - Freight Train Interference

04OCT26: Train 6(02) operating with engines 11, 182, and 162 customers onboard was delayed 20 miles west of Lincoln, NE on the BNSF Hastings subdivision holding at milepost 80.7 for a vehicle on the tracks ahead at crossing ID 073314X.

Train	Delay	Comment
6(02)	35"	

Train 58(03) Memphis, TN - Freight Train Interference

04OCT26: Train 58(03) operating with engine 136 and 125 customers onboard was delayed upon departure from Memphis, TN on the CN Memphis subdivision following CN 2924 from milepost 391.3 until milepost 329.1.

Train	Delay	Comment
58(03)	30"	

Train 307(03) North of Lincoln, IL - Freight Train Interference

04OCT26: Train 307(03) operating with engine ID4629 and 71 customers onboard was delayed north of Lincoln, IL on the UPRR Springfield subdivision holding at McLean Interlocking milepost 140 wait for UP8116 to pass.

Train	Delay	Comment
307(03)	40"	

Train 3(02) West of Flagstaff, AZ - Freight Train Interference

03OCT26: Train 3(02) with 155 customers was delayed on the BNSF Seligman subdivision starting 10 miles west of Flagstaff between East Bellemont/MP 354.5 and East Seligman/MP 427.9 due to following unknown BNSF freight.

Train	Delay	Comment
3(02)	30"	

Train 507(03) North of Eugene, OR - Freight Train Interference

03OCT26: Train 507(03) with 50 customers was delayed on the UPRR Brooklyn subdivision 12 miles north of Eugene due to meeting UP 5793 at Swain/MP 659.1.

Train	Delay	Comment
507(03)	33"	

Train 794(03) Camarillo, CA - Police Related

03OCT26: Train 794(03) with 396 customers was delayed on the UPRR Santa Barbara subdivision at Camarillo due to meeting police account of unruly customers.

Train	Delay	Comment
794(03)	31"	

Train 48(03) East of Hammond, IN - Freight Train Interference

03OCT26: Train 48(03) operating with engines 375, 90 and 105 customers onboard was delayed east of Hammond, IN on the Norfolk Southern Chicago District holding at milepost 482.5 waiting for a fatal trespasser strike involving NS23G-02 to clear between milepost 479 and 482.

Train	Delay	Comment
48(03)	2'35"	

Train 1(03) East of San Antonio, TX - Freight Train Interference

03OCT26: Train 1(03) operating with engines 78, 343, and 88 customers onboard was delayed east of San Antonio, TX on the UPRR Glidden subdivision holding at Kingsbury Main milepost 165.0 awaiting a BNSF vehicle strike to clear ahead. Around 9:00 p.m. central time BNSF 7574 fatally struck an occupied vehicle at Crossing ID 742701M. BNSF management was on scene at approximately 10:00 p.m. CT. The scene was fully released at 11:38 p.m. CT.

Train	Delay	Comment
1(03)	2'00"	

Train 1333(03) East of St. Paul, MN - Freight Train Interference

03OCT26: Train 1333(03) operating with engines 53, 518, and 169 customers onboard was delayed 15 miles east of St. Paul, MN on the CPKC River subdivision following UEOCEVO from milepost 395.8 until 429.5.

Train	Delay	Comment
1333(03)	36"	

Train 19(02) South of Hattiesburg, MS - Freight Train Interference

03OCT26: Train 19(02) operating with engines 369, 330, and 180 customers onboard was delayed 55 miles south of Hattiesburg, MS on the Norfolk Southern NO&NE District holding at milepost 131.8 meeting NSI107-03.

Train	Delay	Comment
19(02)	48"	

Train 50(03) East of Chicago, IL - Freight Train Interference

03OCT26: Train 50(03) operating with engine 15 and 119 customers onboard was delayed 2 miles east of Chicago, IL on the Norfolk Southern Chicago District holding at milepost 519.1 for freight traffic blocking a route.

Train	Delay	Comment
50(03)	41"	

Train 22(03) Fort Worth, TX - Routing

03OCT26: Train 22(03) operating with engine 311 and 62 customers onboard was delayed departing Fort Worth Station on the BNSF Fort Worth subdivision due to dispatch holding for other traffic in the area that was operating late.

Train	Delay	Comment

27-FOI-00048 0000008956 "UNCLASSIFIED" 10/19/2026

Train 25/26(03) East of New Orleans, LA - Signal

03OCT26: Train 26(03) operating with engines 361, 201, and 82 customers onboard was delayed operating through restrictive signals on the CSX NO&M subdivision from milepost 780.6 until milepost 767.9. Train 25(03) operating with engines 365, 154, and 110 customers onboard held at milepost 767.9 meeting train 26(03) and then operated through the same restrictive signals as 26(03).

Train	Delay	Comment
26(03)	39"	
25(03)	35"	

Train 741(03) Fremont, CA - Third Party Contractor Engine Failure

03OCT26: Train 741(03) with C/2013, six cars, and C/8306 was terminated at Fremont on the UPRR Niles subdivision due to C/2013 with a coolant pressure alarm and unable to continue. The train maintained head end power with 70 customers on board. All customers were offered Uber vouchers and any remaining customers were fare protected and rescued by train 745(03). As a result, train 746(03) was canceled entirely. Train 744(03) rescued train 741(03) equipment at Fremont and operated as a double draft to Oakland, where the 741(03) equipment was cut off to be mechanically assessed. At Oakland, C/2013 was removed and replaced with C/2014 and the equipment deadhead Oakland to Sacramento for service on October 4th.

Train	Delay	Comment
741(03)	Term FMT	
744(03)	1'02"	SJC - crew
746(03)	Canc SJC-SAC	
747(03)	38"	S/HAY - meet 744(03)
744(03)	1'28"	FMT - double draft / meet 745(03)
744(03)	13"	OMF - uncouple from 741(03)

Train 2/422(02) El Paso, TX - Injured or Sick Passenger or Employee

03OCT26: Train 2/422(02) operating with engines 349, 14, and 130 customers onboard was delayed departing El Paso, TX on the UPRR Lordsburg subdivision due to a medical emergency involving an unconscious customer. EMS cleared the customer to stay onboard and continue their journey.

Train	Delay	Comment
2/422(02)	30"	

27-FOI-00046 00000098956 "UNCLASSIFIED" 10/19/2026

Train 572(03) West of San Diego, CA - Engine Failure

03OCT26: Train 572(03) with C/2118 five units of C/6906, and 241 customers was disabled 12 miles west of Old Town on the NCTD San Diego subdivision due to C/2118 with a loss of head end power due to fuel power issues. The weather was 87 degrees and sunny. The crew worked with mechanical to troubleshoot and was unable to rectify the issue. As a result, train 774(03) tied on to train 572(03) and operated as a double draft to San Diego. Due to equipment issues. As a result, train 587(03) was canceled entirely with customers accommodated on train 591(03). Train 785(03) operated back to Los Angeles as a double draft, where the disabled equipment was removed and taken to the yard for a mechanical assessment.

Prior to arriving to Los Angeles, train 785(03) was delayed 11 miles east of Solana Beach on the NCTD San Diego subdivision on the single track at MP 252.6 due to a loss of head end power. The crew worked with San Diego mechanical and Siemens and was able to adjust the cable on C/2112 to restore head end power and continue west.

Train	Delay	Comment
785(03)	1'13"	SAN - late turn of equip 774(03)
572(03)	1'58"	
774(03)	1'24"	
785(03)	42"	E/SOL - loss of HEP
785(03)	24"	SAN-LAX - heavy train
587(03)	Canc SAN-LAX	

Train 11(03) Tacoma, WA - Engine Failure

03OCT26: At 1039AM-PT, Train 11(03), E/338-E/355-9 cars, was delayed departing Tacoma, WA on the Sound Transit Lakewood Subdivision due to a high voltage circuit fault on trail E/355 with head end power(HEP) dropping. The crew held at the Tacoma station to troubleshoot with mechanical. There were 231 customers on board and the ambient outside temperature was 56 degrees. With the assistance of mechanical, at 1100AM-PT the crew was able to restore HEP with E/338; however, the faults on E/355 were not resolved. E/355 was placed in running box car mode due to the coolant pressure sensor and transducer power supply both failed. With HEP restored, Train 11(03) departed Tacoma and a freight unit was sourced downline.

Train 11(03) was further delayed at MP 100.1, 2 miles south of Kelso-Longview Station, on the BNSF Seattle Subdivision adding BN3880. BNSF personnel were on site to assist. Once the freight was added, a brake test was performed and Train 11(03) proceeded south. At Portland, it was necessary to perform a calendar day inspection on BN 3880. Once the inspection was complete, 11(03) departed Portland at 427PM-PT, 2 hours, and 5 minutes late.

Train	Delay	Comment
11(03)	23"	TAC
11(03)	1'13"	S/KEL - adding BN 3880
11(03)	41"	PDX - BN 3880 calendar day inspection
11(03)	20"	KEL-KFS - operating freight speed

Train 3(01) West of Winslow, AZ - Freight Train Interference

03OCT26: Train 3(01), E/BN7818-E/152-E/29-9 cars with 163 customers, was delayed starting at West Winslow/MP 288.0, 3 miles west of Winslow, AZ, on the BNSF Seligman Subdivision due to freight interference. The crew held at MP 288 for eastbound BN5984 to clear route. Once the BNSF freight cleared, Train 3(01) held at Dennison/MP 300.3 for multiple BNSF freights. After route was clear, Train 3(01) advanced to East Flagstaff/MP 340.0 where they held for and unknown BNSF freight to clear and Train 4(02) to arrive with recrew on board.

Train	Delay	Comment
3(01)	27"	MP 288.0

27-FOI-00046 00000008956 UNCLASSIFIED 10/19/2026

Train 711(03) Emeryville, CA - Third Party Contractor Engine Failure

03OCT26: Due to mechanical issues with E/C2002 slated to operate on Train 714(03), Train 711(03), E/C2123-7 cars-CC/C6963, was terminated in Emeryville, CA to ensure ample time for the equipment could go into the yard for servicing and fueling to turn for Train 714(03). The 24 customers traveling between Emeryville and Oakland, CA were reaccommodated on Train 733(03). Mechanical was able to resolve the issue on E/C2002, therefore the equipment originally slated for Train 714(03), still operated as Train 714(03).

Train	Delay	Comment
711(03)	Term EMY	

Train 58(03) North of New Orleans, LA - Freight Train Interference

03OCT26:Train 58(03), operating with engine 136, seven coaches, and 121 customers, was delayed 4 miles north of New Orleans, LA, on CN McComb subdivision, due to holding for cross traffic BNSF6851 at Control Point East Bridge. Once the freight cleared and a route was made available, train 58(03) was able to proceed.

Train 58(03) was delayed 30 miles north meeting train 59(02)

Train	Delay	Comment
58(03)	24"	PTI
58(03)	34"	FTI

Train 11(02) Emeryville, CA - Engine Failure

03OCT26: Train 11(02), E/337-E/19-9 cars with 170 customers, was delayed starting at Emeryville, CA due to trail E/19 with electrical control issue. With no mechanical forces available in Oakland, CA, the crew held in Emeryville, CA to contact mechanical to troubleshoot. With the assistance of mechanical, the crew was able to resolve the issue with E/19. Train 11(02) was further delayed picking up an Amtrak Road Foreman in Oakland to ride from Oakland to San Jose, CA to ensure the locomotive issue was resolve and assist if necessary.

Train	Delay	Comment
11(02)	30"	

Train 4(02) East of Lamy, NM - Passenger Train Interference

03OCT26: Train 4(02) with 120 customers was delayed on the BNSF Glorieta subdivision 15 miles east of Lamy due to meeting 3(02) at Fox/MP 820.0.

Train	Delay	Comment
4(02)	30"	

Train 769(03) West of Oceanside, CA - Freight Train Interference

03OCT26: Train 769(03), operating with engine 2111, six coaches, and 438 customers was delayed 8 miles west of Oceanside, CA, on SCRRA San Diego subdivision, due to a disabled freight train (waiting on a recrew) causing single tracking conditions between milepost 209.16 and milepost 218. The single tracking caused major congestion in the area. Multiple trains were delayed operating through the affected area.

Train	Delay	Comment
769(03)	40"	
566(03)	1'01"	

27-FOJ-00046 000000068956 UNCLASSIFIED 10/19/2026

Train 724(03) San Jose, CA - Third Party Contractor Engine Failure

03OCT26: Train 724(03) with 2/C/C8064-4 CARS E/JPBX921 with 44 customers, was delayed departing San Jose, CA on the UPRR Coast Subdivision due to E/JPBX921 not starting. Mechanical in San Jose was unable to resolve the issue. Mechanical forces brought a part for repairs to San Jose to resolve issue arriving at 8:45A-PT. Due to the length of time anticipated for repair, equipment from inbound Train 723(03), E/JPBX920-4 cars-CC/C8312, was turned for Train 724(03). Once inbound Train 723(03) arrived and all customers detrained, the customers for Train 724(03) were boarded. After all customers were onboard, a brake test was performed and Train 724(03) departed. Mechanical still worked to resolve issue with E/JPBX921.

Train 728(03), with 25 customers, was delayed departing due to mechanical still working to resolve issues on E/JPBX921. The equipment from inbound Train 727(03), E/C2004-4 cars-CC/C8314, was turned for Train 728(03).

Train	Delay	Comment
724(03)	28"	
728(03)	11"	

Train 4(01) West of Fort Madison, IA - Freight Train Interference

03OCT26: Train 4(01), operating with engines 170/138, nine coaches and 212 customers, was delayed 31 miles west of Fort Madison, IA, on BNSF Marceline subdivision, due to meeting BNSF 5618 and BNSF 4999 at control Point Medil. Once the freights cleared and a route was made available, train 4(01) was able to proceed.

Train	Delay	Comment
4(01)	58"	

Train 51(02) East of Chicago, IL - Freight Train Interference

03OCT26: Train 51(02), operating with engine 58, five coaches and 134 customers, was delayed 17 miles east of Chicago, IL, on UP Villa Grove subdivision, due to holding for freight cross traffic on the Indiana Harbor Belt RR. Once the freight cleared and a route was made available, train 51(02) was able to proceed.

Train	Delay	Comment
51(02)	1'10"	

Train 7/27(02) Minot, ND - Engine Failure

03OCT26: Train 7/27(02), operating with engines 301, 205, 11 coaches and 162 customers, was delayed departing Minot, ND, on BNSF Glasgow subdivision, due to loading issues with trail engine 205. The crew reported that the engine stopped loading. Mechanical met the train and after troubleshooting efforts were unsuccessful, mechanical confirmed that the trailing engine could still provide Head End Power (HEP) but not tractive effort. BNSF freight locomotive 7389 was sourced to be added upon arrival into Havre, MT.

Train	Delay	Comment
7/27(02)	30"	MOT
7/27(02)	14"	HAV - adding BN 7389
7/27(02)	17"	HAV-LIB - operating freight speed

27-FOI-00046 0000008956 "UNCLASSIFIED" 10/19/2026

Train 516(03) Seattle, WA - Engine Failure

03OCT26: Train 516(03), operating with engines 1404, 10 coaches, and 128 customers, was delayed departing Seattle, WA, on BNSF Scenic subdivision, due to a stuck brake on engine 1404. Mechanical responded to troubleshoot and was able to resolve the issue. The brake bypass was in the wrong direction.

Train	Delay	Comment
516(03)	33"	

Train 3(02) West of La Junta, CO - Signal

03OCT26: Train 3(02), operating with engines 188/23, 9 coaches, and 187 customers, was delayed operating west of La Junta from milepost 55.9 to milepost 571.9, on BNSF Raton subdivision, due to operating under restricted. BNSF reported that their signals were affected by defective high water detector. Once cleared of the affected area, train 3(02) was able to resume normal speed.

Train	Delay	Comment
3(02)	55"	

Track Work Advisory 27-010 Heartland Flyer Service - M of W Work

02OCT26:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Heartland Flyer Service will be adjusted as follows:

· Train 821(18Oct), which normally operates between OKC and FTW, will be canceled in entirety and replaced by Bus.

· Train 822(18Oct), which normally operates between FTW and OKC, will be canceled in entirety and replaced by Bus.

ALTERNATE TRANSPORTATION

· Bus 3821 will provide alternate transportation between OKC and FTW

· Bus 3822 will provide alternate transportation between FTW and OKC

AFFECTED TRAINS (ORIGIN DATE)

Train 821(18Oct)

Train 822(18Oct)

STATION CODES

OKC – Oklahoma City, OK

FTW – Fort Worth, TX

WBS#: B.TR.100150.7234

27-FOI-00046 00000008956 UNCLASSIFIED 10/19/2026

Train 3(01) East of Lawrence, KS - Engine Failure

02OCT26: Train 3(01) was delayed at MP1.1, 36.8 miles east of Lawrence KS station on the BNSF Topeka subdivision due to engine 152 shutting down with no faults. Crew called in to troubleshoot with CNOC mechanical but where unable to resolved the issues and engine was set up as a control stand. Train 3(01) was back on the move at 1210AM CT. Train 3(01) arrived to Newton KS station at 344AM CT and added BNSF Freight engine 7818. Train 3(01) departed Newtown at 4:33AM CT with the freight engine added.

Train 3(01) had an extended delay at Albuquerque, NM completing daily inspections. There were 3 locomotives that needed to be inspected, including the freight unit, which gave some difficulty completing the tests.

Due to the late operation of Train 3(01), service recovery was initiated with all customers provided a snack pack and bottles of water. All sleeper car guests were provided regular lunch service from the dining car. All coach customers were offered beef stew and rice with a beverage. Customers with connections to the coast starlight were provided a bagged lunch for their bus connection consisting of a sandwich with chips and a beverage.

WBS#: B.TR.100150.7239

Train	Delay	Comment
3(01)	45"	NEW - add BN 7818
3(01)	42"	ABQ - Calendar day inspection
3(01)	2'09"	NEW-LAX - operating freight speed

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2026

BNSF Glasgow Subdivision West of Minot, ND - Freight Train Interference

30SEP26: The BNSF reported a freight derailment on the Glasgow subdivision just west of Minot at Shoo Tower/MP 0.63 with seven stack cars and 26 containers on the ground on the 6th Street overpass and blocking both main tracks. There were no hazmat cars involved in the derailment. The derailment ruptured a local gas line. Heavy equipment arrived on scene through 300PM-CT to aid in the cleanup efforts with 25 ballast cars enroute. Train 7/27(29) had access to the Minot depot. Train 7/27(29) arrived Minot at 951AM-CT, 51 minutes late and held for disposition. The rough estimated time for main track 2 to be opened was 800PM-CT. Customer service worked to source alternate bus transportation for a potential bus bridge with train 8/28(29) between Minot and Stanley. There were 197 customers on train 7/27(29) that were affected. Customer service recovery was initiated in Minot with Papa Johns pizza for lunch and a chicken dinner. There were 179 customers on train 8/28(29) that were affected.

BNSF advised that the estimated time of track opening was pushed back until midnight. As a result, a bus bridge was initially implemented between Minot and Stanley. Four buses were sourced at Minot for customers on train 7/27(29) between Minot and Stanley and staged at 500PM-CT. Four buses were sourced for customers on train 8/28(29) between Stanley and Minot and staged at 730PM-CT. All busses were released after an update was given for track opening to be 11:15PM-CT, account of the expected logistics involved regarding the wye and crew hours of service.

Train 8/28(29) was held just west of the derailment at CP189/MP18.9 for disposition. Main track #2 was opened at 10:32PM-CT with a 25mph speed restriction, and 7/27(29) departed Minot at 10:55PM-CT operating 13 hours and 11 minutes late. Train 8/28(29) was behind multiple freights and also had to wait and allow all stacked-up westbound trains to pass, including 7/27(29), before proceeding into Minot. Main track #1 returned to service October 1st at 12:00P-CT.

Due to the late operation of Train 7/27(29), service recovery was initiated with Jimmy Johns sandwiches and chips for dinner being provided to all customers upon arrival into Spokane, WA.

WBS#: B.TR.100150.7228

Train	Delay	Comment
8/28(01)	Canceled	
7/27(04)	Canceled	
8/28(29)	4'24"	
7/27(29)	12'13"	

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	

Maintenance of Way Highlights

27-FOIA-00046 700000008956 UNCLASSIFIED 10/18/2026

Union Pacific Brooklyn Subdivision Portland, OR - Portland Marathon TWA 27-003

04OCT26: The Portland Marathon occurred in Portland, OR, resulting in closure of rail operations at Southeast Stark Street (DOT #754542S) / MP 769.78 on the Brooklyn Subdivision, 1 mile south of the Portland, OR Union Station due to event-related roadway and crossing closure. As a result, the following operating plan was implemented:

Train 503(04) terminated in Portland.

Train 504(04) originated in Portland and operate 1-hour later.

Buses were secured to provide alternate transportation to customers traveling to and from all missed station stops.

WBS#: B.TR.100150.7209

Metrolink Orange Subdivision - Scheduled M/W Work 27-001

02OCT26: To accommodate the infrastructure work on the Metrolink Orange Subdivision beginning Friday, October 2nd at 10:00P-PT through Saturday, October 3rd at 6:00A-PT the following service adjustments were made affecting the Pacific Surfliner Service.

- Train 794(02-03OCT), which normally operates between San Luis Obispo, CA to San Diego, CA, terminated in Los Angeles, CA. Alternate bus 3594 was provided between Los Angeles and San Diego, making all station stops except San Juan Capistrano.
- Train 595(02-03OCT), which normally operates between San Diego, CA and Los Angeles, CA, was cancelled in its entirety. Customers were able to utilize bus 5811 as an alternative.

WBS#: B.TR.100150.7133

UPRR Coast Subdivision South of Oakland, CA - Scheduled M/W Work 27-009

02OCT26: The UPRR performed a switch removal at MP 14.992 on the Coast Subdivision beginning at 7A-PT on Saturday, October 3rd. To accommodate the infrastructure work, the following service adjustments were made.

- Train 11(02OCT), which normally operates between Oakland, CA and San Jose, CA on the UPRR Coast Subdivision detoured over the Niles Subdivision between Elmhurst/MP 14 and Newark/ MP 31 with no stops missed.

WBS#: B.TR.100150.7230

Coast Starlight - Scheduled M/W Work 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
11(22AUG)	32"	
14(22AUG)	23"	
11(12SEP)	29"	
14(12SEP)	50"	Detours/ ETI

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

27-FOIA-00046 00000008956 "UNCLASSIFIED" 10/19/2026

29JUL26: Amtrak / MDOT have coordinated schedules for the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

27-FOI-00046 0000008956 UNCLASSIFIED 10/19/2026

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track and project work multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3(1)	NEW	BNSF7818	E/152 not loading		
7(2)	HAV	BNSF7389	E/205 keeps shutting down	SPK	10/4/26
11(3)	KEL	BNSF3880	E/338 HEP issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

	Projected Need		Number Operated			
Train	Cars	Seats	Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
65 (03)	BOS	65(03) 82676 SHOPPED WITH NO REPLACEMENT. PLEASE SEE WAR REPORT FOR AFFECTED PAX			82676
3 (03)	CHI	Operating with t-dorm w/o H room. Schedule change has been performed. CNOC Customer service will need to reaccommodate the passengers.	n/a	1	39002
5 (03)	CHI	Operating with standard coach in lieu of bag coach. Inventory has been adjusted to reflect lower level seating.	n/a	0	34038
566 (03)	LAX	Operating with 90215 unable to accommodate passengers with BV reservations. CNOC Csv will need to reaccommodate any passengers impacted by this change.			90215
584 (03)	LAX	Operating with 90215 unable to accommodate passengers with BV reservations. CNOC Csv will need to reaccommodate any passengers impacted by this change.			90215
4 (05)	LAX	Operating with t-dorm w/o H room. Schedule change has been performed. CNOC Customer service will need to reaccommodate the passengers.	SVWR4/5OCT NO WAR DATA THIS TRAIN/DATE	0	39002
43 (03)	NYP	AMI in lieu of AMII, inventory increased.			82590
97 (03)	NYP	train operating with two VIIs in lieu of two VIs for the 9710 and 9711 cars. both cars schedule-changed with room reductions. check war report for displaced pax.			62508, 62523
42 (04)	PGH	AMI in lieu of AMII, inventory increased.			82590
579 (03)	SAN	Operating with 90215 unable to accommodate passengers with BV reservations. CNOC Csv will need to reaccommodate			90215

27-FOI-00046 00000008956 "UNCLASSIFIED" 10/19/2023

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		any passengers impacted by this change.			
82 (03)	WAS	business class in lieu of a coach, inv adjusted.			81513

Reverse Consists

Train Number	Station	Reason
195 (03)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
99 (03)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
87 (03)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
156 (03)	RNK	Consist reversed | Business class seat orientation may have changed | At Front
127 (03)	NYP	Consist reversed | Business class seat orientation may have changed | At Rear
150 (03)	PHL	Consist reversed | Business class seat orientation may have changed | At Front