# CNOC

## (CONSOLIDATED NATIONAL OPERATIONS CENTER)

# Amtrak Status Report

Monday, October 05, 2026 Rules: 0-0




*This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.*

## Information Management

27-FOI-00044

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/04/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 298 | 56 | 81.2% | 1,245 | 170 | 86.3% | 1,245 | 170 | 86.3% |
| Central Division | 86.0% | 53 | 5 | 90.6% | 230 | 8 | 96.5% | 230 | 8 | 96.5% |
| East Division | 82.0% | 160 | 26 | 83.8% | 666 | 92 | 86.2% | 666 | 92 | 86.2% |
| West Division | 86.0% | 85 | 25 | 70.6% | 349 | 70 | 79.9% | 349 | 70 | 79.9% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

# Customer On Time Performance

Endpoint Arrival Dates through 10/4/26



| Service | Day | | | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | Target | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score |
| **Amtrak System** | **80%** | **108,708** | **34,267** | **68%** | **449,726** | **128,955** | **71%** | **449,726** | **128,955** | **71%** |
| ***Northeast Corridor*** | ***81%*** | ***46,399*** | ***16,904*** | ***64%*** | ***196,864*** | ***53,627*** | ***73%*** | ***196,864*** | ***53,627*** | ***73%*** |
| Acela | 83% | 9,731 | 3,071 | 68% | 40,797 | 10,178 | 75% | 40,797 | 10,178 | 75% |
| Northeast Regional | 79% | 36,668 | 13,833 | 62% | 156,067 | 43,449 | 72% | 156,067 | 43,449 | 72% |
| Richmond / Newport News / Norfolk | 77% | 12,796 | 4,705 | 63% | 46,272 | 13,899 | 70% | 46,272 | 13,899 | 70% |
| Springfield Shuttles | 89% | 1,132 | 526 | 54% | 4,205 | 978 | 77% | 4,205 | 978 | 77% |
| Roanoke | 79% | 2,635 | 736 | 72% | 15,366 | 5,171 | 66% | 15,366 | 5,171 | 66% |
| On Spine Northeast Regional | 80% | 20,105 | 7,866 | 61% | 90,224 | 23,401 | 74% | 90,224 | 23,401 | 74% |
| ***State Supported*** | ***80%*** | ***49,897*** | ***10,272*** | ***79%*** | ***203,611*** | ***49,841*** | ***76%*** | ***203,611*** | ***49,841*** | ***76%*** |
| Borealis | 80% | 746 | 175 | 77% | 2,632 | 688 | 74% | 2,632 | 688 | 74% |
| Capitol Corridor | 90% | 3,431 | 1,861 | 46% | 15,739 | 5,219 | 67% | 15,739 | 5,219 | 67% |
| Carolinian | 70% | 1,368 | 0 | 100% | 5,091 | 1,370 | 73% | 5,091 | 1,370 | 73% |
| Cascades | 75% | 2,944 | 658 | 78% | 11,884 | 2,485 | 79% | 11,884 | 2,485 | 79% |
| Downeaster | 82% | 1,885 | 199 | 89% | 8,056 | 2,547 | 68% | 8,056 | 2,547 | 68% |
| Empire | 78% | 6,399 | 652 | 90% | 25,447 | 4,518 | 82% | 25,447 | 4,518 | 82% |
| Adirondack | 72% | 146 | 0 | 100% | 1,353 | 101 | 93% | 1,353 | 101 | 93% |
| Ethan Allen Express | 70% | 676 | 20 | 97% | 2,409 | 543 | 77% | 2,409 | 543 | 77% |
| Maple Leaf | 70% | 911 | 165 | 82% | 3,503 | 544 | 84% | 3,503 | 544 | 84% |
| New York - Albany | 85% | 3,078 | 312 | 90% | 12,219 | 1,847 | 85% | 12,219 | 1,847 | 85% |
| New York - Niagara Falls | 75% | 1,588 | 155 | 90% | 5,963 | 1,483 | 75% | 5,963 | 1,483 | 75% |
| Gold Runner | 73% | 3,324 | 543 | 84% | 11,983 | 3,640 | 70% | 11,983 | 3,640 | 70% |
| Heartland Flyer | 70% | 228 | 217 | 5% | 795 | 778 | 2% | 795 | 778 | 2% |
| Hiawatha | 90% | 2,211 | 0 | 100% | 8,271 | 0 | 100% | 8,271 | 0 | 100% |
| Illinois | 78% | 2,724 | 1,545 | 43% | 11,752 | 4,066 | 65% | 11,752 | 4,066 | 65% |
| Carl Sandburg / Illinois Zephyr | 85% | 568 | 12 | 98% | 1,897 | 417 | 78% | 1,897 | 417 | 78% |
| Illini / Saluki | 85% | 622 | 327 | 47% | 3,989 | 823 | 79% | 3,989 | 823 | 79% |
| Lincoln Service | 70% | 1,534 | 1,206 | 21% | 5,866 | 2,826 | 52% | 5,866 | 2,826 | 52% |
| Keystone | 92% | 6,612 | 94 | 99% | 33,088 | 3,119 | 91% | 33,088 | 3,119 | 91% |
| Lincoln / Missouri | 70% | 1,025 | 485 | 53% | 3,626 | 1,939 | 47% | 3,626 | 1,939 | 47% |
| Mardi Gras Service | 80% | 367 | 0 | 100% | 1,222 | 165 | 86% | 1,222 | 165 | 86% |
| Michigan | 70% | 2,628 | 249 | 91% | 9,802 | 2,113 | 78% | 9,802 | 2,113 | 78% |
| Blue Water | 70% | 660 | 0 | 100% | 2,336 | 554 | 76% | 2,336 | 554 | 76% |
| Pere Marquette | 85% | 338 | 0 | 100% | 1,247 | 53 | 96% | 1,247 | 53 | 96% |
| Wolverine | 70% | 1,630 | 249 | 85% | 6,219 | 1,506 | 76% | 6,219 | 1,506 | 76% |
| Missouri | 80% | 366 | 0 | 100% | 1,306 | 109 | 92% | 1,306 | 109 | 92% |
| Pacific Surfliner | 85% | 9,483 | 3,212 | 66% | 38,071 | 14,181 | 63% | 38,071 | 14,181 | 63% |
| Pennsylvanian | 80% | 995 | 217 | 78% | 3,885 | 541 | 86% | 3,885 | 541 | 86% |
| Piedmont | 80% | 1,622 | 0 | 100% | 5,017 | 351 | 93% | 5,017 | 351 | 93% |
| Vermonter | 75% | 1,539 | 165 | 89% | 5,944 | 2,012 | 66% | 5,944 | 2,012 | 66% |
| ***Long Distance*** | ***70%*** | ***12,412*** | ***7,091*** | ***43%*** | ***49,251*** | ***25,487*** | ***48%*** | ***49,251*** | ***25,487*** | ***48%*** |
| Auto Train | 70% | 722 | 722 | 0% | 2,816 | 1,583 | 44% | 2,816 | 1,583 | 44% |
| California Zephyr | 70% | 1,007 | 249 | 75% | 3,515 | 1,523 | 57% | 3,515 | 1,523 | 57% |
| Cardinal | 70% | 284 | 250 | 12% | 1,394 | 1,108 | 21% | 1,394 | 1,108 | 21% |
| City Of New Orleans | 75% | 790 | 659 | 17% | 2,897 | 2,105 | 27% | 2,897 | 2,105 | 27% |
| Coast Starlight | 70% | 641 | 566 | 12% | 4,218 | 1,946 | 54% | 4,218 | 1,946 | 54% |
| Crescent | 70% | 1,083 | 17 | 98% | 3,971 | 506 | 87% | 3,971 | 506 | 87% |
| Empire Builder | 70% | 1,147 | 741 | 35% | 3,626 | 1,942 | 46% | 3,626 | 1,942 | 46% |
| Floridian | 60% | 1,719 | 1,249 | 27% | 6,195 | 4,726 | 24% | 6,195 | 4,726 | 24% |
| Lake Shore Ltd | 73% | 983 | 562 | 43% | 4,322 | 1,486 | 66% | 4,322 | 1,486 | 66% |
| Palmetto | 70% | 897 | 50 | 94% | 3,440 | 688 | 80% | 3,440 | 688 | 80% |
| Silver Meteor | 70% | 925 | 525 | 43% | 3,670 | 1,535 | 58% | 3,670 | 1,535 | 58% |
| Southwest Chief | 60% | 891 | 540 | 39% | 3,549 | 3,061 | 14% | 3,549 | 3,061 | 14% |
| Sunset Ltd | 70% | 305 | 203 | 33% | 1,029 | 397 | 61% | 1,029 | 397 | 61% |
| Texas Eagle | 70% | 1,018 | 758 | 26% | 4,609 | 2,881 | 37% | 4,609 | 2,881 | 37% |

**Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"**

# Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FGI 00046 00000000055 "UNCLASSIFIED" 10/10/2026~~

## Train Index Dates Through October 04, 2026

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Service** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| Amtrak System | 585 | 24,568 | 433,410 | 567 | 24,568 | 433,410 | 567 |

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Department** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| INFRASTRUCTURE UNPLANNED | 107 | 1,014 | 131,772 | 77 | 1,014 | 131,772 | 77 |
| INFRASTRUCTURE PLANNED | 135 | 3,435 | 131,772 | 261 | 3,435 | 131,772 | 261 |
| FLEET RELIABILITY | 90 | 3,187 | 433,410 | 74 | 3,187 | 433,410 | 74 |
| TRAIN OPERATIONS | 424 | 16,932 | 433,410 | 391 | 16,932 | 433,410 | 391 |

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

## Information Management

27-FOI-00044

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/04/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 298 | 56 | 81.2% | 1,245 | 170 | 86.3% | 1,245 | 170 | 86.3% |
| Central Division | 86.0% | 53 | 5 | 90.6% | 230 | 8 | 96.5% | 230 | 8 | 96.5% |
| East Division | 82.0% | 160 | 26 | 83.8% | 666 | 92 | 86.2% | 666 | 92 | 86.2% |
| West Division | 86.0% | 85 | 25 | 70.6% | 349 | 70 | 79.9% | 349 | 70 | 79.9% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

27-FOI-00048

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/04/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 298 | 56 | 81.2% | 1,245 | 170 | 86.3% | 1,245 | 170 | 86.3% |
| Central Division | 86.0% | 53 | 5 | 90.6% | 230 | 8 | 96.5% | 230 | 8 | 96.5% |
| CDL | 95.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| CHI | 86.0% | 24 | 3 | 87.5% | 107 | 5 | 95.3% | 107 | 5 | 95.3% |
| FTW | 92.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| GRR | 95.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| KCY | 92.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| MKE | 92.0% | 5 | 0 | 100.0% | 23 | 0 | 100.0% | 23 | 0 | 100.0% |
| MOE | 97.5% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| MSP | 96.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| NOL | 94.5% | 4 | 0 | 100.0% | 17 | 1 | 94.1% | 17 | 1 | 94.1% |
| OKC | 97.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| PNT | 88.0% | 3 | 0 | 100.0% | 12 | 0 | 100.0% | 12 | 0 | 100.0% |
| PTH | 93.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| QCY | 91.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| SAS | 90.5% | 1 | 1 | 0.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| STL | 89.0% | 4 | 1 | 75.0% | 16 | 1 | 93.8% | 16 | 1 | 93.8% |
| East Division | 82.0% | 160 | 26 | 83.8% | 666 | 92 | 86.2% | 666 | 92 | 86.2% |
| ALB | 88.5% | 8 | 0 | 100.0% | 32 | 1 | 96.9% | 32 | 1 | 96.9% |
| BON | 87.5% | 5 | 1 | 80.0% | 20 | 2 | 90.0% | 20 | 2 | 90.0% |
| BOS | 85.5% | 18 | 1 | 94.4% | 74 | 3 | 95.9% | 74 | 3 | 95.9% |
| BRK | 92.5% | 5 | 0 | 100.0% | 20 | 2 | 90.0% | 20 | 2 | 90.0% |
| BTN | 82.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| CLT | 91.5% | 5 | 0 | 100.0% | 19 | 2 | 89.5% | 19 | 2 | 89.5% |
| GFD | 88.0% | 2 | 1 | 50.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| GRO | - | - | - | - | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| HAR | 79.5% | 7 | 1 | 85.7% | 40 | 8 | 80.0% | 40 | 8 | 80.0% |
| HFD | - | - | - | - | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| LOR | 84.0% | 1 | 1 | 0.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| MIA | 89.5% | 2 | 0 | 100.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| MTR | 79.0% | 1 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| NFK | 84.5% | 2 | 0 | 100.0% | 8 | 2 | 75.0% | 8 | 2 | 75.0% |
| NFL | 93.5% | 2 | 0 | 100.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| NHV | 78.0% | 5 | 2 | 60.0% | 19 | 5 | 73.7% | 19 | 5 | 73.7% |
| NPN | 93.0% | 2 | 1 | 50.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| NYP | 75.5% | 43 | 15 | 65.1% | 183 | 33 | 82.0% | 183 | 33 | 82.0% |
| PGH | 93.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| PHL | 48.0% | 4 | 2 | 50.0% | 18 | 10 | 44.4% | 18 | 10 | 44.4% |
| RGH | 95.0% | 4 | 0 | 100.0% | 14 | 1 | 92.9% | 14 | 1 | 92.9% |
| RNK | 83.5% | 2 | 0 | 100.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| SAB | 98.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| SAV | 96.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| SFA | 88.0% | 1 | 1 | 0.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| SPG | 92.5% | 7 | 0 | 100.0% | 23 | 1 | 95.7% | 23 | 1 | 95.7% |
| TWO | 73.0% | 1 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |

## Information Management

27-FOI-00044

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/04/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 298 | 56 | 81.2% | 1,245 | 170 | 86.3% | 1,245 | 170 | 86.3% |
| East Division | 82.0% | 160 | 26 | 83.8% | 666 | 92 | 86.2% | 666 | 92 | 86.2% |
| WAS | 84.0% | 29 | 0 | 100.0% | 119 | 10 | 91.6% | 119 | 10 | 91.6% |
| West Division | 86.0% | 85 | 25 | 70.6% | 349 | 70 | 79.9% | 349 | 70 | 79.9% |
| ARN | 92.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| BFD | 79.0% | 7 | 2 | 71.4% | 28 | 7 | 75.0% | 28 | 7 | 75.0% |
| EMY | 72.0% | 1 | 0 | 100.0% | 3 | 2 | 33.3% | 3 | 2 | 33.3% |
| EUG | 86.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| GTA | 90.0% | 3 | 1 | 66.7% | 12 | 4 | 66.7% | 12 | 4 | 66.7% |
| LAX | 89.5% | 11 | 2 | 81.8% | 42 | 4 | 90.5% | 42 | 4 | 90.5% |
| OKJ | 74.5% | 9 | 7 | 22.2% | 44 | 14 | 68.2% | 44 | 14 | 68.2% |
| PDX | 86.0% | 6 | 2 | 66.7% | 20 | 2 | 90.0% | 20 | 2 | 90.0% |
| SAC | 88.5% | 12 | 5 | 58.3% | 56 | 10 | 82.1% | 56 | 10 | 82.1% |
| SAN | 90.5% | 13 | 4 | 69.2% | 50 | 9 | 82.0% | 50 | 9 | 82.0% |
| SEA | 85.0% | 8 | 1 | 87.5% | 31 | 5 | 83.9% | 31 | 5 | 83.9% |
| SJC | 89.0% | 7 | 1 | 85.7% | 28 | 12 | 57.1% | 28 | 12 | 57.1% |
| SLO | 90.0% | 3 | 0 | 100.0% | 12 | 1 | 91.7% | 12 | 1 | 91.7% |
| SPK | 90.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| VAC | 97.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

# Amtrak On Time Performance

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 2 | 121 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 3 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 4 | 47 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 5 | 58 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 6 | | 3 | 2 | 33.3% | 3 | 2 | 33.3% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 7 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 8 | 102 | 3 | 2 | 33.3% | 3 | 2 | 33.3% | 3 | 2 | 33.3% | 3 | 2 | 33.3% |
| 11 | No OS | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 14 | 27 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 19 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 20 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 21 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 22 | 18 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 23 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 24 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 25 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 26 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 27 | | 3 | 1 | 66.7% | 3 | 1 | 66.7% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 28 | | 3 | 1 | 66.7% | 3 | 1 | 66.7% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 40 | 30 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 41 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 42 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 43 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 48 | 46 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 49 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 50 | 29 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 52 | 28 | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 53 | 326 | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 54 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 57 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 58 | 78 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 59 | 24 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 63 | 33 | 4 | 3 | 25.0% | 4 | 3 | 25.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 64 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 65 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 66 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 68 | 248 | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 69 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 71 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 72 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 73 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 74 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 1 | 66.7% | 3 | 1 | 66.7% |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 75 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 76 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 77 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 78 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 79 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 80 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 87 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 88 | 59 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 89 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 90 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 96 | 34 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 97 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 98 | 79 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 99 | 26 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 100 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 103 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 104 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 105 | | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 117 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 118 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 120 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 121 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 122 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 123 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 124 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 128 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 132 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 135 | 38 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 140 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 143 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 145 | | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 146 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 149 | 49 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 150 | 64 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 151 | 21 | 4 | 4 | 0.0% | 4 | 4 | 0.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 153 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 154 | 22 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 155 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 156 | 52 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 157 | 18 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 158 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 160 | 22 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 161 | 37 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 162 | 57 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 164 | 22 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 165 | 30 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 169 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 189 | 31 | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 195 | 17 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 230 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 232 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 233 | 21 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 234 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 235 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 236 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 237 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 238 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 239 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 240 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 241 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 243 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 244 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 245 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 280 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 281 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 283 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 284 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 290 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 291 | | 4 | 3 | 25.0% | 4 | 3 | 25.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 300 | 35 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 301 | 19 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 302 | 30 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 305 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 306 | 34 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 307 | 42 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 311 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 316 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 318 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 319 | 24 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 331 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 332 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 334 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 335 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 336 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 337 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 338 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 339 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 341 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 342 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 350 | 18 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 351 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 352 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 353 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 354 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 355 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 364 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 365 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 370 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 371 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 380 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 381 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 382 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 383 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 391 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 392 | 62 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 400 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 405 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 409 | 18 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 416 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 448 | | 4 | 3 | 25.0% | 4 | 3 | 25.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 449 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 450 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 460 | 32 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 461 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 464 | 32 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 465 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 488 | 48 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 497 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 499 | 36 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 500 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 502 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 503 | 84 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 504 | 39 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 505 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 506 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 507 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 508 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 509 | 20 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 511 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 516 | 26 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 517 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 518 | 31 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 519 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 562 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 564 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 566 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 567 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 572 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 573 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 579 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 580 | 59 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 581 | 76 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 584 | 36 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 587 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 3 | 1 | 66.7% | 3 | 1 | 66.7% |
| 588 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 591 | 44 | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 593 | Cncld | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 595 | 48 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 612 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 615 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 637 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 660 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 661 | 16 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 663 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 664 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 665 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 666 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 667 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 669 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 670 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 671 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 672 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 674 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 690 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 691 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 692 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 693 | 20 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 694 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 695 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 696 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 697 | | 2 | 2 | 0.0% | 2 | 2 | 0.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 698 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 701 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 702 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 703 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 704 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 710 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 711 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 712 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 713 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 714 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 715 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 716 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 717 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 718 | | 4 | 3 | 25.0% | 4 | 3 | 25.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 719 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 720 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 723 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 724 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 727 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 728 | 76 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 729 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 732 | 86 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 733 | 30 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 734 | 53 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 736 | 16 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 737 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 738 | 21 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 741 | 33 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 742 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 743 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 744 | 73 | 2 | 2 | 0.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 745 | 30 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 746 | 18 | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 747 | 39 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 748 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 749 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 751 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 757 | 17 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 761 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 765 | 21 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 769 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 770 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 774 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 777 | 52 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 782 | 116 | 4 | 4 | 0.0% | 4 | 4 | 0.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 785 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 786 | Cncld | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 3 | 2 | 33.3% | 3 | 2 | 33.3% |
| 790 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 821 | 28 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 822 | 27 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 4 | 0.0% | 4 | 4 | 0.0% |
| 1333 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 2 | 50.0% | 4 | 2 | 50.0% |
| 1340 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 1689 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 1 | 66.7% | 3 | 1 | 66.7% |
| 2203 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2208 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2209 | | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2212 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2213 | 20 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 2215 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2216 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2218 | 49 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 2219 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2222 | 19 | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 2223 | | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2224 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2226 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2227 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2252 | | 2 | 1 | 50.0% | 2 | 1 | 50.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2254 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2255 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2256 | 37 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 2258 | 31 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 2259 | 17 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 2260 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2263 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2265 | 19 | 2 | 2 | 0.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% | 2 | 2 | 0.0% |
| 2267 | 31 | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 2271 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| 2290 | | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| 2293 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 0 | 100.0% |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 2213 | WAS | 20 | CTI | 11 | CTI | 10 | BAL-BWI | AM | Follow, Marc, 9485, Milepost, 95.7, 106.3 |
| 2218 | NYP | 49 | CAR | 24 | SMW | 20 | NWK-NYP | AM | Scheduled in track usage program, Other, SOUTH TUBE SINGLE TRACKING |
| 2222 | NYP | 19 | SMW | 20 | SMW | 14 | NWK-NYP | AM | Scheduled in track usage program, Other, SINGLE TRACKING IN THE SOUTH TUBE |
| 2256 | BOS | 37 | SMW | 29 | SMW | 19 | NWK-NYP | AM | Scheduled in track usage program, Other, XPT-NYP, CONGESTION A/C SINGLE TRACKING IN THE SOUTH TUBE |
| 2258 | BOS | 31 | SMW | 24 | SMW | 20 | NWK-NYP | AM | Scheduled in track usage program, Other, SINGLE TRACKING IN THE SOUTH TUBE A/C NORTH TUBE O/O/S |
| 2259 | WAS | 17 | OTH | 25 | OTH | 9 | XGX-NHV | AM | Lost time - N.A.R. |
| 2265 | WAS | 19 | ENG | 24 | ENG | 24 | BOS-BOS | AM | Other electrical failure, 2123\|NG\|NP, HAD TO DE-PREPARE A/C SCREENS TO MONITOR PANTOGRAPHS NOT WORKING |
| 2267 | WAS | 31 | SMW | 10 | SMW | 6 | XSH-NYP | AM | Scheduled in track usage program, Other, XSH NYP |
| 88 | BOS | 59 | SMW | 30 | POL | 26 | NYP-NYP | AM | Removal of passenger by police, DUE TO A CUSTOMER THAT FELL BETWEEN CARS |
| 96 | BOS | 34 | SMW | 23 | SMW | 12 | NWK-NYP | AM | Scheduled in track usage program, Other, SINGLE TRACKING IN THE SOUTH TUBE A/C NORTH TUBE O/O/S |
| 99 | NPN | 26 | DSR | 22 | DSR | 13 | BRP-STM | MN | Per bulletin Control Point, 248, 30, 1,2 |
| 135 | WAS | 38 | DSR | 19 | DSR | 10 | BRP-STM | MN | Held at a stop signal Control Point, 243, 2, 3 |
| 149 | WAS | 49 | SMW | 28 | SMW | 21 | XSH-NYP | AM | Scheduled in track usage program, Other, HELD FOR AM140 AND AM2258 XING AHEAD |
| 150 | BOS | 64 | SVS | 46 | SVS | 46 | PHL-PHL | AM | Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD |
| 151 | RNK | 21 | PTI | 14 | PTI | 14 | CVS-LYH | NS | Meet p156, Control Point, Hamner |
| 154 | BOS | 22 | SMW | 19 | SMW | 14 | NWK-NYP | AM | Scheduled in track usage program, Other, XPT-XBH, HELD AT ALLIED A/C SINGLE TRACKING IN THE SOUTH TUBE |
| 156 | NYP | 52 | SMW | 61 | SMW | 55 | NWK-NYP | AM | Scheduled in track usage program, Other, SINGLE TRACKING SOUTH TUBE |
| 157 | WAS | 18 | OTH | 12 | DSR | 8 | BRP-STM | MN | Per bulletin Milepost, 42.0, 40.4, 15, 2 |
| 160 | BOS | 22 | CTI | 20 | CTI | 16 | BRP-NHV | MN | Cross over or go around mnrr, Control Point, 261 |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 161 | WAS | 37 | OTH | 10 | CTI | 9 | NYP-NWK | AM | Follow, NJT, NJ7847, Other, NYP-NWK, FOLLOWED NJ7847 |
| 162 | BOS | 57 | SMW | 39 | SMW | 28 | NWK-NYP | AM | Scheduled in track usage program, Other, XBH-XBH, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| 164 | BOS | 22 | DSR | 17 | SMW | 13 | NWK-NYP | AM | Scheduled in track usage program, Other, XPT-XBH, HELD AT ALLIED A/C SINGLE TRACKING IN THE SOUTH TUBE |
| 165 | WAS | 30 | SMW | 26 | SMW | 17 | WIL-XPV | AM | Diversions around M/W work, Control Point, RUTHBY , OPR A TRK RUTHBY TO IRON. TRAIN 128 OPR NORTH ON NO. 1 TRK. NOS 2 AND 3 TRKS O/S DAVIS TO BACON |
| 189 | WAS | 31 | CTI | 10 | CTI | 10 | NYP-NWK | AM | Follow, NJ, 7855,7657, Other, XBH NWK |
| 195 | WAS | 17 | PTI | 13 | PTI | 9 | MET-XHM | AM | Cross over or go around, AM2255, Other, MET-XMO, OPERATED NO.4 TRK A/C AM2255 ON NO.3 TRK |
| 409 | NHV | 18 | DMW | 5 | DMW | 5 | WFD-STS | AM | Held for or routed around MW work or equipment, Milepost w/Letters, WFD, STS, Metro North track outage |
| 460 | SPG | 32 | CON | 22 | CON | 22 | NHV-NHV | MN | Hold for connecting train |
| 464 | SPG | 32 | PTI | 14 | PTI | 14 | WND-WNL | AM | Meet, 465, Milepost w/Letters, WND, WNL, AM464 waited for AM465 to clear single track |
| 488 | GFD | 48 | CON | 43 | CON | 43 | NHV-NHV | AM | Hold for connecting train, late connection fo AM88 |
| 499 | SPG | 36 | ITI | 37 | ITI | 37 | GFD-GFD | MA | Late departure at initial terminal due to late arrival of inbound equipment, 488 |
| 52 | LOR | 28 | FTI | 126 | FTI | 62 | XJG-XSA | CS | Follow M492, Control Point, Doctortown, Control Point, Lodge |
| 53 | SFA | 326 | SYS | 163 | SYS | 147 | XOU-XSA | CS | Re-crew / job briefing Waiting on recrew engineer, Control Point, S Ravenell |
| 661 | HAR | 16 | WTR | 8 | RTE | 7 | NWK-PJC | AM | Late / wrong track bulletins from host railroad, AM, Other, XMW-XMW, HELD A/C CONFUSION AS TO WHETHER NO.4 TRK WAS IN SERVICE |
| 693 | BRK | 20 | PTI | 11 | PTI | 11 | EXR-DHM | CS | Meet 694, Control Point, rockingham |
| 63 | TWO | 33 | FTI | 19 | PTI | 15 | ROM-SYR | CS | Wait for station track 48, Control Point, 290 |
| 68 | NYP | 248 | DMW | 29 | DMW | 29 | POU-CRT | MN | Held for or routed around MW work or equipment Single track conditions, hold for multiple northbounds and/or track cars entering O.O.S. limits, Control Point, 72, Control Point, 51, Control Point, 46 |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 233 | ALB | 21 | CTI | 21 | CTI | 21 | CRT-POU | MN | Follow mnrr, 8819, Milepost, 58, 72 |
| 48 | NYP | 46 | POL | 155 | POL | 155 | XH6-XPI | NS | RR blocked by trespasser or vehicle strike by another train Held at CP 482 due to trespasser fatality involving NS 23G at MP 479.224. |
| 98 | NYP | 79 | PTI | 59 | DBS | 54 | JSP-SAV | CS | Debris strike Struck a tree at MP A517.7. Engine 319 shut down as a result of the strike. CNOC mechanical able to walk us through getting engine reset, Tree, Milepost, 517.9, 517.5 |
| 40 | CHI | 30 | FTI | 88 | SVS | 41 | SAV-SAV | CS | Fuel |
| 5 | EMY | 58 | DSR | 92 | DMW | 45 | DAV-MTZ | UP | Held for or routed around MW work or equipment Control Point, tolenas |
| 728 | SAC | 76 | PTI | 42 | PTI | 26 | HAY-OAC | UP | Meet Amtk 733 South, Control Point, Coliseum |
| 732 | SAC | 86 | TEN | 85 | TEN | 85 | OKJ-OKJ | UP | HEP Attempted to leave the yard on time. HEP lost while pulling the yard. Tasi restarted HEP and checked cables. Attempted to pull yard and HEP failed again. Tasi placed peanut cable extenders behind the loco., C2006 |
| 733 | SJC | 30 | DCS | 17 | DCS | 14 | OKJ-OAC | UP | Restrictive signal(s) from known wayside signal failure Flag to NI010, Red, Control Point, NI009 |
| 734 | SAC | 53 | PTI | 23 | PTI | 18 | SCC-GAC | UP | Meet Late train 733 was brought to expressway when Albrea would have been a better meet, 733, Control Point, CO044 |
| 736 | SAC | 16 | DCS | 27 | DCS | 20 | MTZ-SUI | UP | Restrictive signal(s) from unknown cause Single tracking, Red, Control Point, cordelia |
| 738 | SAC | 21 | DCS | 32 | DCS | 21 | OAC-OKJ | UP | Restrictive signal(s) from known wayside signal failure Flag from NI010 to Ni008., Red, Control Point, NI010 |
| 741 | SJC | 33 | PTI | 14 | TEN | 12 | MTZ-MTZ | UP | HEP JPBX922 |
| 744 | ARN | 73 | DCS | 29 | DCS | 21 | OAC-OKJ | UP | Power switch failure Control Point, Strong |
| 745 | SJC | 30 | PTI | 24 | PTI | 12 | FFV-SUI | UP | Follow 5, Control Point, rv054 |
| 746 | SAC | 18 | DCS | 18 | DCS | 16 | OAC-OKJ | UP | Restrictive signal(s) from known wayside signal failure Red/stop, Control Point, NI010, Control Point, NI009 |
| 747 | SJC | 39 | PTI | 24 | PTI | 10 | OKJ-OKJ | UP | Meet Held at OKJ until AMT 744 arrived at OKJ., AMT 744, Other, OKJ station |
| 50 | NYP | 29 | FTI | 110 | FTI | 41 | XTF-X40 | NS | Meet NS 7688, Control Point, CP 518 |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 503 | PDX | 84 | SVS | 78 | SVS | 47 | SEA-TUK | BN | Unplanned Wye Ditch lights switch broken had to wye to run from 1404, Other, stacy yard |
| 504 | SEA | 39 | SYS | 48 | SYS | 48 | PDX-PDX | BN | Late arrival of 503 |
| 509 | PDX | 20 | SVS | 17 | SVS | 17 | VAN-PDX | BN | Unplanned Wye Per RFE Steve Hyman, weyed train at T6 coming into PDX due to b/o cab car 90250, shoved to PDX |
| 516 | VAC | 26 | MBO | 18 | MBO | 18 | XF2-X1J | BN | For maritime traffic Bridge, Fraser River Bridge |
| 518 | VAC | 31 | DSR | 31 | DSR | 10 | XF2-X1J | BN | Per bulletin Other, 146.45, 25, east, Milepost, 150, 151.2, 25, 2 |
| 58 | CHI | 78 | DSR | 94 | FTI | 34 | XSU-HMD | CC | Cross Traffic bn6851, Control Point, east bridge jct |
| 59 | NOL | 24 | DSR | 83 | RTE | 33 | MEM-MKS | CC | Line manual or spring switch Scenic route. Lined 7 switches., Other, city y one, Other, city main one, Other, cypress t, Other, west jct main one |
| 11 | LAX | No OS Rpt | SVS | 292 | SVS | 156 | SLO-SLO | UP | Routine inspections Calendar Day Inspections on Motors and Mechanical 1 Inspection of train., Other, SLO station |
| 14 | SEA | 27 | DCS | 81 | DCS | 46 | SNS-SJC | UP | Restrictive signal(s) from unknown cause Instructed by dispatcher to not exceed restrictive speed between CO077 and CO070, Red, Control Point, co077 |
| 8 | CHI | 102 | FTI | 152 | RTE | 56 | FAR-DLK | BN | Dispatcher hold Control Point, moorehead jct |
| 821 | FTW | 28 | DSR | 46 | DSR | 35 | GLE-FTW | BN | Per bulletin Milepost, 409.5, 409.0, 60, mr, Milepost, 408.5, 406.7, 60, mt, Milepost, 407.9, 407.1, 30, mt, Milepost, 405.9, 405.5, 60, mt, Milepost, 404.2, 403.8, 60, mt, Milepost, 403.2, 402.7, 60, mt, Milepost, 401.7, 401.3, 60, mt, Milepost, 400.5, 400.1, 60, mt, Milepost, 399.9, 399.2, 60, mt, |
| 822 | OKC | 27 | DSR | 44 | DSR | 32 | FTW-GLE | BN | Per bulletin Milepost, 346.1, 346.5, 25, m1, Milepost, 353.7, 354.1, 60, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 369, 370.2, 60, m, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.6, 376.8, 60, m, Milepost, 373.9, 377.1, 25, m, Milepost, 377.5, 375.9, 60, m, Milepost, 3 |
| 350 | PNT | 18 | PTI | 33 | PTI | 20 | XB0-XA5 | MI | Meet 353, Siding, Albion |
| 580 | SAN | 59 | ITI | 42 | ITI | 42 | LAX-LAX | SC | Late departure at initial terminal due to late arrival of inbound equipment 777, Equipment swap with train #777 |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 581 | LAX | 76 | POL | 67 | POL | 67 | FUL-XRJ | BN | Right of Way police hold |
| 584 | SAN | 36 | RTE | 21 | RTE | 21 | LAX-XRJ | BN | Dispatcher hold Told by DS 15 account service disruption ahead, Control Point, soto |
| 591 | LAX | 44 | ITI | 21 | ITI | 21 | SAN-SAN | SN | Late departure at initial terminal due to late arrival of inbound equipment 580 |
| 593 | LAX | Trn Cancelled | | | | | | | |
| 595 | LAX | 48 | ITI | 41 | ITI | 41 | SAN-SAN | SN | Late departure at initial terminal due to late arrival of inbound equipment 782, We prep 782 q for 595 per alert till mechanical informed us to take 584 q instead |
| 757 | SLO | 17 | PTI | 22 | PTI | 22 | GTA-X3G | UP | Meet 774, Siding, Ellwood |
| 765 | SLO | 21 | DCS | 31 | DCS | 14 | GVB-SLO | UP | Restrictive signal(s) from unknown cause Red signal unknown reason UP Dispatcher toned up. Awaiting permission to move 1 mile forward into Station from dispatcher, Restricted , Milepost, 250.00, 250.00 |
| 777 | SLO | 52 | ENG | 35 | ENG | 35 | FUL-XRJ | BN | Failure of diesel engine Engine shut down mp 161. Code 0795 Failure of redundant component: 92 day timer started., C2116 |
| 782 | SAN | 116 | CTI | 83 | CTI | 83 | XRJ-FUL | BN | ML broke down ml, ml, 1752, Other, nwk |
| 786 | SAN | Trn Cancelled | PTI | 28 | PTI | 28 | GUA-LPS | UP | Meet 14, Siding, Tangair |
| 4 | CHI | 47 | FTI | 160 | FTI | 67 | LAP-FMD | BN | Follow Stop E baring behind BNSF 4418 on main 2 waited for 2 freights main 1 for 35 mts, Control Point, W Baring, BNSF 4418 |
| 2 | NOL | 121 | PTI | 132 | PTI | 120 | XHT-XAS | UP | Train 1 struck a vehicle at MP 212. Held train 2 at MP214 amtk1, Control Point, martinez park |
| 22 | CHI | 18 | DSR | 80 | RTE | 60 | FTW-FTW | TE | Dispatcher hold Other, FTW Station |
| 300 | CHI | 35 | DSR | 24 | CAR | 11 | BNL-PON | UP | Air / Brake / Wheel ID4305, ID4132, Hose at cpx102 |
| 301 | STL | 19 | PTI | 23 | PTI | 17 | JOL-BNL | UP | Meet amtk300, Control Point, cpx045 |
| 302 | CHI | 30 | FTI | 45 | FTI | 30 | SMT-XTF | CC | Cross Traffic unknown, Control Point, Corwith |
| 306 | CHI | 34 | ENG | 57 | ENG | 50 | XQT-XWR | UP | Alerter failure ID4633 |
| 307 | STL | 42 | FTI | 46 | FTI | 40 | BNL-LCN | UP | Meet UP 8116, Siding, McLean |
| 392 | CHI | 62 | OTH | 24 | PTI | 23 | RTL-GLM | CC | Meet amtrak 59, Control Point, nirth paxton |
| 319 | KCY | 24 | FTI | 51 | FTI | 39 | BNL-LCN | UP | Meet UP 6809, Milepost, 143.0, 143.0 |

# Amtrak Initial Terminal Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/4/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| ALB | 448 | 10/03 | 37 | 37 | Hold for connecting train 48 |
| BON | 697 | 10/04 | 3 | 3 | Restrictive signal(s) from unknown cause Red, Other, starter off track 9 |
| BOS | 2265 | 10/04 | 24 | 24 | Other electrical failure, 2123\|NG\|NP, HAD TO DE-PREPARE A/C SCREENS TO MONITOR PANTOGRAPHS NOT WORKING |
| GFD | 499 | 10/04 | 37 | 37 | Late departure at initial terminal due to late arrival of inbound equipment, 488 |
| HAR | 674 | 10/04 | 1 | 1 | Passenger and/or baggage |
| LOR | 53 | 10/04 | 14 | 14 | DRUMMAC not enough drivers |
| NHV | 464 | 10/04 | 14 | 4 | Held for or routed around MW work or equipment, Control Point, NHV, AM464 held for AM149 and AM2267 to pass a/c Metro North track outage |
| NHV | 464 | 10/04 | 14 | 10 | Hold for connecting train, late connection of AM164 |
| NHV | 488 | 10/04 | 58 | 15 | Held for or routed around MW work or equipment, Control Point, NHV, AM488 held for AM165 and AM2271 to clear a/c Metro North track work |
| NHV | 488 | 10/04 | 58 | 43 | Hold for connecting train, late connection fo AM88 |
| NPN | 124 | 10/04 | 1 | | |
| NYP | 19 | 10/04 | 5 | 5 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 43 | 10/04 | 15 | 15 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 49 | 10/04 | 36 | 36 | Removal of passenger by police, DELAYED DUE TO PSGR FALLING TRAIN SIDE AM88, IN DIESEL MODE HELD OUT TO PREVENT SMOKING CONDITIONS |
| NYP | 63 | 10/04 | 7 | 7 | Scheduled in track usage program, Other, SSYD-NYP, HELD AT "F" INT FOR LI TRAINS XING AHEAD DUE TO LINE 4 OOS |
| NYP | 97 | 10/04 | 74 | 1 | Passenger and/or baggage |
| NYP | 97 | 10/04 | 74 | 73 | Late departure at initial terminal due to late arrival of inbound equipment, 98 |
| NYP | 105 | 10/04 | 2 | 2 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 145 | 10/04 | 3 | 3 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 189 | 10/04 | 7 | 7 | Scheduled in track usage program, Other, NORTH TUBE O/O/S SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 235 | 10/04 | 1 | 1 | Passenger and/or baggage |
| NYP | 245 | 10/04 | 198 | 198 | Late departure at initial terminal due to late arrival of inbound equipment, 68 |
| NYP | 281 | 10/04 | 9 | 9 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C NJ6919 BLOCKING ROUTE DUE TO SINGLE TRACKING IN THE SOUTH TUBE |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/4/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| NYP | 2209 | 10/04 | 8 | 8 | Door, 0000, ISSUES WITH DOOR GAP FILLERS |
| NYP | 2219 | 10/04 | 3 | 3 | Scheduled in track usage program, Other, NYP-NYP, HELD A/C SINGLE TRACKING IN THE SOUTH TUBE |
| NYP | 2223 | 10/04 | 11 | 11 | Late departure at initial terminal due to late arrival of inbound equipment, 2212, DELAYED DUE TO SCHEDULE OUTAGE IN THE NORTH TUBE |
| NYP | 2233 | 10/04 | 1 | 1 | Passenger and/or baggage |
| PHL | 150 | 10/04 | 46 | 46 | Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD |
| PHL | 151 | 10/04 | 2 | 2 | Scheduled in track usage program, Control Point, PENN, ELEVATORS OUT ON NO. 4 AND 5 STATION TRACKS. |
| SFA | 52 | 10/04 | 194 | 194 | Late departure at initial terminal due to late arrival of inbound equipment 53 |
| CHI | 41 | 10/04 | 6 | 3 | Car Bad ordered on platform Coach car #25003 was bad ordered on a sold out train. I had to call CNOC central ops and customer service to figure out what the plan was for who was going with me and who was staying behind., Other, CHI station |
| CHI | 41 | 10/04 | 6 | 3 | Hold for connecting train Bags, bikes and passengers were sent out from train 8 because the system/someone thought they were going to be able to make our train., 8 |
| CHI | 48 | 10/04 | 6 | 6 | Wheelchair Sent WCHR passengers out around 920-925pm had 4 lifts 3 in 1st coach 1 in 5th coach |
| CHI | 341 | 10/04 | 3 | 3 | PTC |
| SAS | 22 | 10/04 | 174 | 30 | Air / Brake / Wheel 34018, Car set out due to brake failure prior to departure |
| SAS | 22 | 10/04 | 174 | 144 | Hold for connecting train 2 |
| STL | 311 | 10/04 | 1 | | |
| BFD | 703 | 10/04 | 4 | 4 | Door C9806, DOOR DOES NOT OPEN WHEN TRAIN-LINED, CALLED BFD MECH TO TAKE A LOOK, COULD NOT FIX. CONFIRMED THAT DOOR WAS CUT-OUT. TRAP DOOR DID NOT WORK AS WELL. |
| BFD | 715 | 10/04 | 3 | 3 | Hold for thruway bus Per CNOC West operations hold up to 5 minutes waiting for bus |
| GTA | 782 | 10/04 | 15 | 15 | Meet 14, Control Point, S ELLWOOD |
| LAX | 580 | 10/04 | 42 | 42 | Late departure at initial terminal due to late arrival of inbound equipment 777, Equipment swap with train #777 |
| LAX | 588 | 10/04 | 5 | 5 | Hold for connecting train HVAC issues on 786. Train cancelled. 400 of their pax transferred to our train, 786 |
| OKJ | 710 | 10/04 | 10 | 10 | Routine inspections TASI dropped flags 0750 |

# Amtrak Initial Terminal Details

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/4/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| OKJ | 714 | 10/04 | 1 | 1 | Dispatcher hold Held for late train 728, which was further delayed by signal issues south of OKJ<br>714 got the departure signal at 12:18:30<br>Wheels we're turning at 12:18:30 but captured as 12:19<br>This was an on time departure, Control Point, north Jack london |
| OKJ | 716 | 10/04 | 13 | 13 | Dispatcher hold Other, OKJ STATION |
| OKJ | 718 | 10/04 | 6 | 6 | Maintenance of way with track and time on track 2 okj Control Point, north jack london |
| OKJ | 732 | 10/04 | 85 | 85 | HEP Attempted to leave the yard on time. HEP lost while pulling the yard. Tasi restarted HEP and checked cables. Attempted to pull yard and HEP failed again. Tasi placed peanut cable extenders behind the loco., C2006 |
| OKJ | 736 | 10/04 | 6 | 6 | Dispatcher hold Held for late train 741, Control Point, north jack london |
| OKJ | 742 | 10/04 | 1 | | |
| PDX | 28 | 10/04 | 1 | | |
| PDX | 504 | 10/04 | 48 | 48 | Late arrival of 503 |
| SAC | 702 | 10/04 | 1 | | |
| SAC | 704 | 10/04 | 6 | 6 | Door C9001, Couldn't get a door light. Drummac working on doors. Still couldn't get a door light, all doors closed, had to run with door light cut out |
| SAC | 733 | 10/04 | 3 | 3 | Late departure at initial terminal due to late arrival of inbound equipment 000, Trainset coming from Auburn |
| SAC | 743 | 10/04 | 1 | | |
| SAC | 749 | 10/04 | 1 | 1 | Mobility Impaired Late arriving ada |
| SAN | 591 | 10/04 | 21 | 21 | Late departure at initial terminal due to late arrival of inbound equipment 580 |
| SAN | 593 | 10/04 | (Trn Cxld) | | Engine Issue |
| SAN | 595 | 10/04 | 41 | 41 | Late departure at initial terminal due to late arrival of inbound equipment 782, We prep 782 q for 595 per alert till mechanical informed us to take 584 q instead |
| SAN | 769 | 10/04 | 1 | 1 | Door 6803 |
| SEA | 8 | 10/04 | 99 | 99 | Routine inspections |
| SJC | 744 | 10/04 | 1 | | |

# Eastern Region

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## Commuter Services

| Service Type | OTP Goal | OTP Day | OTP MTD | OTP Prior Month | Trains Operated | Trains Late |
|---|---|---|---|---|---|---|
| MBTA | 95.0 | 97.6 | 99.1 | 94.8 | 166 | 4 |
| CDOT | 95.0 | 68.8 | 86.1 | 92.4 | 16 | 5 |
| MARC | 95.0 | 100.0 | 73.3 | 90.2 | 12 | 0 |
| SEPTA | 95.0 | 85.8 | 89.2 | 91.5 | 106 | 15 |
| NJT-NED | 95.0 | 69.4 | 90.4 | 88.6 | 193 | 59 |
| NJT-SED | 95.0 | 100.0 | 97.8 | 97.2 | 24 | 0 |

## Operating Highlights

### *Train 89(04) - South of Charleston, SC - Flash Flood Warnings*

05OCT26: Train 89(04) was delayed on the CSX Charleston Subdivision between MP 388 and MP 435 due to flash flood warnings. Train 89(04) operated at reduced speeds through the impacted area.

| Train | Delay | Comment |
|---|---|---|
| 89(04) | 32" | |

### *Train 488(04) - New Haven, CT - Hold for Connection*

04OCT26: Train 488(04) was delayed at its initial terminal due to being held for connections arriving on late operating Train 88(04).

| Train | Delay | Comment |
|---|---|---|
| 488(04) | 43" | |
| 499(04) | 37" | Turn off 488(04) |

### *Train 98(04) - South of Charleston, SC - Freight Train Interference*

04OCT26: Train 98(04) was delayed on the CSX Charleston Subdivision at MP 388.7 due to meeting CSX Train I138-04, which was still working on the main and clearing.

| Train | Delay | Comment |
|---|---|---|
| 98(04) | 55" | |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *Train 88(04) New York, NY - Customer Fell/Injured or Sick Passenger or Employee*

04OCT26: A customer fell down between tracks 6 and 7 on train 88(04). Amtrak Police and EMS responded. Amtrak Trainmaster was notified and the Power Director had to de-energized the 3rd rail so the customer could be brought to the platform. EMS treated the customer on the platform.

This also caused train 49(04) to be delayed departing New York due to the power being de-energized.

This also caused delay to train 488(04) at New Haven due to holding for connections off late 88(04).

| Train | Delay | Comment |
|---|---|---|
| 49(04) | 36" | |
| 88(04) | 26" | |
| 488(04) | 58" | nhv connection off 88(04) |

## *Train 52(04) Sanford, FL - Late Turn of Equipment/Servicing*

04OCT26: Train 52(04) was delayed departing Sanford due to late arrival of train 53(03) that arrived at 215P-ET 5 hours and 16 minutes late. They excepted cars until 4P-ET.

| Train | Delay | Comment |
|---|---|---|
| 52(04) | 3'14" | |

## *Train 97(04) New York, NY - Late Equipment Turn/Servicing*

04OCT26: Train 97(04) with E/659 and 12 cars was delayed departing New York due to needing a coach and diner off the late inbound 98(03) that arrived at 1159A-ET 1 hour and 19 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 97(04) | 1'13" | |

## *Train 40(03) North of Savannah, GA - Signal*

04OCT26: Train 40(03) with E/57, E/315 and 10 cars was delayed on the CSX Columbia S at MP 458.4 due to power switch failure making it necessary to shove back to go around.

| Train | Delay | Comment |
|---|---|---|
| 40(03) | 32" | |

## *Train 53(03) South of Jesup, GA - Freight Train Interference*

04OCT26: Train 53(03) with E/352, E/360 and 44 cars was delayed due to meeting CSX 138 at MP 566.9 on the CSX Nahunta A subdivision.

| Train | Delay | Comment |
|---|---|---|
| 53(03) | 31" | |

## *Train 41(02) South of Jesup, GA - Freight Train Interference*

04OCT26: Train 41(02) with E/324,E/320 and 10 cars was delayed due to following CSX I031 from MP A550.5 to MP A602.3.

| Train | Delay | Comment |
|---|---|---|
| 41(02) | 31" | |

27-FOI-00046 000000008956 "UNCLASSIFIED" 10/19/2026

## Train 150(04) Philadelphia, PA - Servicing

04OCT26: Train 150(04) with E/630 and 10 [illegible] delayed departing Philadelphia due to the late release from the yard.

| Train | Delay | Comment |
|---|---|---|
| 150(04) | 46" | |

## Train 53(03) - Charleston Station, SC - Trespasser Incident

04OCT26: 2:05am Trian 53(03) with E/352 and E/360, plus 14 passenger cars and 28 auto carriers, carrying 410 passengers, struck a trespasser, who was laying in the gauge. There were no reported injuries to crew or passengers. The trespasser was discovered underneath the train. HEP was temporarily dropped while crews worked to remove the woman from underneath the train. Once removed, the woman as transported to a local hospital while conscious and moving.
The location of the incident was within the limits of the City of North Charleston, Charleston County, SC. This incident did not occur at a grade crossing. The temperature at the time of the incident was 74° and cloudy.
After a swift investigation by the Charleston County Police Department, Train 53(03), was released and advanced to CP South Ravenel/MP 408.0, where it held for a relief engineer.

**National Response Center Number: 1475293**

| Train | Delay | Comment |
|---|---|---|
| 53(03) | 1'15" | |
| 53(03) | 2'27" | Hold for Recrew |

## Train 68(04) South of Plattsburgh, NY - Sticking Brakes/Car Failure

04OCT26: Train 68(04), operating with Engine 105 and 5 cars, was delayed on the Canadian Pacific Kansas City Canadian Subdivision at MP 141.2 due to sticking brakes on a coach car 82504. The crew worked with Albany Mechanical personnel to troubleshoot the issue, to no avail. It was determined the best course of action would be to set the defective coach out. Albany Mechanical was dispatched to the train's location to assist. The crew was instructed to proceed to Wadhams/Mp 131.8 siding and set out C/82504. The train was met by a recrew after the car was set out. A successful brake test was conducted and the train proceeded south.
Upon arrival at Albany, a cross platform equipment swap was conducted with the set from 235(04).

| Train | Delay | Comment |
|---|---|---|
| 68(04) | 5'11" | |
| 245(04) | 3'18" | Turn off late 68(04) EQ |
| 230(05) | xx" | Turn off Late 245(04) EQ |

# Maintenance of Way Highlights

27-FOI-00046 0000008855 "UNCLASSIFIED" 10/19/2026

## *MBTA Downeaster Track Work - Scheduled M/W Work - TW 26-094 - 9/12-10/11*

21AUG26: To support the MBTA bridge replacement at MP 8.99 the below service adjustments have been made:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound

- Trains 693 and 695 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

- Train 699 (13Sep, 20Sep, 4Oct, 10Oct-11Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

- Train 1689 (12Sep, 19Sep, 26Sep-27Sep, 3Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

o Please note Trains 691 and 697 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct) will operate NORMAL.

Southbound

- Trains 690, 692, 694, 696, and 698 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

**WBS#: B.TR.100150.7065**

| Train | Delay | Comment |
|---|---|---|
| 696(03) | 35" | HHL-WOB |
| 695(03) | 30" | BON-HHL |

## *NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095*

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule between Durham and Charlotte.

**WBS#: B.TR.100150.7085**

| Train | Delay | Comment |
|---|---|---|
| 77(03) | 50" | |
| 78(03) | 50" | Turn of Late 77(03) |

# *CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work*

27-FOI-00046, 00000008956 "UNCLASSIFIED" 10/19/2026

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

**WBS#: B.TR.100150.6692**

# Eastern Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | WAS | 9/13/26 |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Eastern Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

***Train674(04) Passenger Removal at Trenton, New Jersey - Improper Conduct***

04OCT26, Passenger on PNR 10CB97, traveling from Elizabeth, PA to New York, NY was removed by local Transit Police due to cursing and refusing to following orders of Amtrak policy, when asked to do so. Amtrak Police notified.

Delay: 674(04) NONE

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *Train 28(04) East of Pasco, WA - Freight Train Interference*

04OCT26: Train 28(04) with 104 customers was delayed on the BNSF Lakeside subdivision starting five miles east of Pasco between Pasco East/MP 140.2 and Eltopia/MP 128.1 due to following BN 7021.

| Train | Delay | Comment |
|---|---|---|
| 28(04) | 40" | |

## *Train 11(03) San Luis Obispo, CA - Servicing*

04OCT26: Train 11(03) with BN 3880, E/338, E/355, nine cars, and 172 customers was delayed on the UPRR Santa Barbara subdivision at San Luis Obispo due to performing a calendar day inspection on the locomotives. Once the inspection was complete, 11(03) departed San Luis Obispo at 1209AM-PT, 8 hours, and 32 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 11(03) | 2'36" | |

## *Train 786(04) Los Angeles, CA - Engine Failure*

04OCT26: Train 786(04) with C/2109, five cars, and C/6906 was terminated at Los Angeles due to C/2109 with non-functioning HVAC. Customers were accommodated on train 588(04). As a result, train 593(04) was canceled between San Diego and Los Angeles due to said equipment issues. Customers were accommodated on train 595(04).

| Train | Delay | Comment |
|---|---|---|
| 593(04) | Canc SAN-LAX | |
| 786(04) | Term LAX | |

## *Train 14(04) North of Paso Robles, CA - Passenger Train Interference*

04OCT26: Trian 14(04) with 259 customers was delayed on the UPRR Coast subdivision 34 miles north of Paso Robles at San Ardo/MP 179.5 due to meeting train 11(03). Train 11(03) was also delayed due to taking the switch in hand to enter the siding track.

| Train | Delay | Comment |
|---|---|---|
| 11(03) | 25" | |
| 14(04) | 54" | |

## *Train 352(04) Jackson, MI - Passenger Train Interference*

04OCT26: Train 352(04), with 278 customers onboard, was delayed at control point 75/MP75.7, 0.2 miles west of Jackson, MI/MP75.5, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(04). Once the route was clear, train 352(04) continued east.

| Train | Delay | Comment |
|---|---|---|
| 352(04) | 31" | |

27-FOI-00046 000000008955 "UNCLASSIFIED" 10/19/2026

## Train 581(04) West of Fullerton, CA - Commuter Train Interference

04OCT26: Train 581(04) with 312 customers was delayed on the BNSF San Bernardino subdivision at Buena Park/MP 160.3 due to a disabled Metrolink train stopped ahead at East Norwalk/MP 156.6. The disabled train was coupled to another Metrolink train to clear the route. Trains 782(04), 4(04), and 584(04) were also delayed holding for open track. It was necessary for train 782(04) to shove back to Los Nietos/MP 152.9 to get around the disabled Metrolink equipment that continued to have air issues.

| Train | Delay | Comment |
|---|---|---|
| 782(04) | 1'23" | |
| 581(04) | 1'10" | |
| 4(04) | 32" | |
| 584(04) | 30" | |
| 785(04) | 05" | |
| 595(04) | 41" | SAN - late turn of equip 584(04) |

## Train 5(02) West of Davis, CA - M of W Work

04OCT26: Train 5(02) with 140 customers was delayed on the UPRR Martinez subdivision 23 miles west of Davis at Tolenas/MP 52.0 due to MOW overstay.

| Train | Delay | Comment |
|---|---|---|
| 5(02) | 45" | |

## Train 306(04) North of St. Louis, MO - Alerter Failure

04OCT26: Train 306(04), with engine IDTX4633, 5 cars, and 163 customers, stopped at mile post 278.7, 8.8 miles north of St Louis, MO/MP1.5, on the UP Springfield subdivision due to an issue with the alerter on engine IDTX4633. After troubleshooting with assistance from CNOC Mechanical Desk, the alerter had to be cut out. The assistant conductor was moved to the engine to protect the engineer and train 306(04) continued north.

| Train | Delay | Comment |
|---|---|---|
| 306(04) | 50" | |

## Train 777(04) West of Fullerton, CA - Engine Failure

04OCT26: Train 777(04) with C/6900, five cars, C/2116, and 458 customers was delayed on the BNSF San Bernardino subdivision four miles west of Fullerton due to C/2116 with an IO41 fault and loss of head end power. The crew worked with Siemens to restore head end power and continued to Los Angeles. At Los Angeles, a swap of equipment took place due to the locomotive issue on C/2116. Train 777(04) customers transferred to train 580(04) equipment and 580(04) customers transferred to the 777(04) equipment. Train 777(04) departed Los Angeles at 348PM-PT, 35 minutes late and train 580(04) departed Los Angeles at 352PM-PT, 42 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 777(04) | 35" | |
| 580(04) | 42" | LAX - late turn of equipment 777(04) |
| 591(04) | 21" | SAN - late turn of equip 580(04) |

## Train 782(04) South of Camarillo, CA - Signal

04OCT26: Train 782(04) was delayed on the UPRR Santa Barbara subdivision starting one mile south of Camarillo due to signal issues between South Camarillo/MP 414.7 and Las Posas/MP 426.4.

| Train | Delay | Comment |
|---|---|---|

27-FOI-00046 00000098955 UNCLASSIFIED 10/19/2026

## Train 732(04) Oakland, CA - Third Party Contractor Engine Failure

04OCT26: Train 732(04) with C/8200, four cars, and C/2006 was late departing Oakland, CA on the UPRR Niles subdivision. When attempting to depart Oakland Maintenance Facility, C/2006 lost head end power. The train shoved back to the yard to have TASI mechanical troubleshoot the cause. Train 732(04) attempted to depart a second time, when the loss of HEP occurred again. TASI continued troubleshooting and once the issues were resolved by replacing a cable on C/2006, 732(04) departed Oakland at 223PM-PT, 1 hour, and 25 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 732(04) | 1'25" | |

## Train 8(04) Seattle, WA - Initial Terminal Delay

04OCT26: Train 8(04) with E/206, seven cars, and 109 customers was delayed departing Seattle due to a late release of equipment attributed to mechanical defects on E/206 that hampered wyeing the equipment and loading commissary. Once the equipment was released and set in the station, all customers were welcomed aboard, and 8(04) departed Seattle at 634PM-PT, 1 hour, and 39 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 8(04) | 1'39" | |

## Train 22(04)/422(02) South of McGregor, TX - Passenger Train Interference

04OCT26: Train 22(04)/422(02), with 167 customers onboard, was delayed at McGregor siding/MP243.3, 0.2 miles south of McGregor, TX/MP243.5, on the BNSF Fort Worth subdivision meeting Amtrak train 21(03). Once the route was clear, Train 22(04)/422(02) continued north.

| Train | Delay | Comment |
|---|---|---|
| 22(04)/422(02) | 35" | |

## Train 6(04) Colfax, CA - Freight Train Interference

04OCT26: Train 6(04), with 178 customers, was delayed departing Colfax, CA, on the UPRR Roseville Subdivision due to UP7399 losing an engine just east of the depot. The disabled freight train temporarily prevented 6(04) from proceeding. Once UP7399 cleared the area, 6(04) remained delayed while waiting for Train 5(02) to pass through the territory. After 5(02) cleared and 6(04) received a signal to proceed, the crew was required to hand-throw switches while departing the Colfax depot, resulting in additional delay.

| Train | Delay | Comment |
|---|---|---|
| 6(04) | 41" | |

## Train 302(04) South of Chicago, IL - Freight Train Interference

04OCT26: Train 302(04) was delayed at Corwith/MP6.6, 6 miles south of Chicago, IL, on the CN Joliet Subdivision, waiting on freight cross-traffic to clear ahead.

| Train | Delay | Comment |
|---|---|---|
| 302(04) | 30" | |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *UPRR Niles Subdivision South of Oakland, CA - Signal*

04OCT26: Trains were delayed on the UPRR Niles subdivision just south of Oakland due to a track occupancy light between Strong/MP 7.6 and East Oakland/MP 9.6 that was related to cables being damaged during excavation work. A new cable was dug in and cut over with repairs complete at 900PM-PT.

| Train | Delay | Comment |
|---|---|---|
| 728(04) | 27" | |
| 734(04) | 15" | |
| 733(04) | 17" | |
| 738(04) | 21" | |
| 741(04) | 12" | |
| 744(04) | 21" | |
| 745(04) | 14" | |
| 11(03) | 30" | |
| 747(04) | 20" | |
| 746(04) | 18" | |

## *Train 22(04)/422(02) Austin, TX - System*

04OCT26: Train 22(04)/422(02), with 148 customers, was delayed at Austin, TX/MP179.4, on the UPRR Austin Subdivision, due to the engineer unable to access the host railroad office building to obtain the bulletin orders due to a broken keypad on the door. Alternate arrangements were made to have the dispatchers send the bulletins to the Austin ticket agent to print out for the crew. The crew reported the wrong BNSF bulletins were sent and it was necessary to have the BNSF portion of orders resent and printed.

Train 22(04)/422(02) was further delayed at Dallas, TX/214.4 on the UP Dallas subdivision retrieving additional orders and holding a job briefing.

| Train | Delay | Comment |
|---|---|---|
| 22(04)/422(02) | 1'20" | |
| 22(04)/422(02) | 28" | DAL |

## *Train 503(04) Seattle, WA - Cab Car Failure*

04OCT26: Train 503(04) with 82 customers was delayed after departing Seattle, WA, on the BNSF Seattle Subdivision. An unplanned wye move was required due to a broken ditch light switch on cab car 90230. The train was wyed at Stacy Yard to operate from locomotive WS1404.

| Train | Delay | Comment |
|---|---|---|
| 504(04) | 48" | Turn off 503(04) |
| 503(04) | 31" | WYE into PDX |
| 503(04) | 47" | WYE departing SEA |

## *Train 821(04) North of Fort Worth, TX - Trespasser Incident*

04OCT26: Train 821(04), E/135-2 cars-E/203, with 97 customers, stopped in emergency at MP347.32, 1 mile north of Fort Worth, TX, on the BNSF Fort Worth Subdivision, due to a near miss with a trespasser. There were no reported injuries to passengers or crew. The crew inspected consist and took no exceptions. The crew performed Class II brake test and Train 821(04) was back on the move south to Fort Worth.

| Train | Delay | Comment |
|---|---|---|
| 821(04) | 11" | |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## Train 319(04) South of Bloomington-Normal, IL - Freight Train Interference

04OCT26: Train 319(04) with 364 customers delayed at MP143.3, 19 miles south of Bloomington-Normal, IL, on the UPRR Springfield Subdivision, due to UP 6809 actuated the hot box detector ahead. UPRR crew inspected consist and took no exceptions. UP 6809 proceeded at 30MPH to next detector. Train 319(04) was delayed following freight south to Elkhart/MP168.

| Train | Delay | Comment |
|---|---|---|
| 319(04) | 47" | |

## Train 11(03) East of Sacramento, CA - Police Related

04OCT26: Train 11(03) with 201 customers was delayed 12 miles east of Sacramento, CA, on the UPRR Martinez Subdivision due to a deceased individual found on the tracks near MP 93. The strike is believed to have involved a freight train that operated through the area earlier. Train 11(03) was held at Antelope, CA (MP 102.5), while the investigation was completed. The hold was subsequently released. Train 11(03) was then held, momentarily, for a recrew before resuming operations. Train 729(04) was delayed behind train 11(03).

| Train | Delay | Comment |
|---|---|---|
| 729(04) | 42" | |
| 11(03) | 2'14" | MP 101.7 |

## Train 6(04) West of Sacramento, CA - Passenger Train Interference

04OCT26: Train 6(04) was delayed on the UPRR Martinez subdivision one mile west of Sacramento at West Sacramento/MP 88.1 due to being held out for train 11(03), who was fueling.

| Train | Delay | Comment |
|---|---|---|
| 6(04) | 30" | |

## Train 21(03) West of Longview, TX - Freight Train Interference

04OCT26: Train 21(03), with 100 customers, was delayed west of Longview, TX/MP89.5, on the UPRR Mineola Subdivision, meeting UP 7184 at Greggton/MP93, UP3064 at Gladewater/MP104 and UP5587 at Fada/MP122.6.

| Train | Delay | Comment |
|---|---|---|
| 21(03) | 50" | |

## Train 4(02) East of La Plata, MO - Freight Train Interference

04OCT26: Train 4(02), with 183 customers, was delayed east of La Plata, MO/MP312.7, on the BNSF Marceline Subdivision, following eastbound freight traffic. BNSF reported single tracking between Gorin/MP276.7 and Fort Madison/MP232.9 due to dead on the law trains tied down and lack of BNSF crews. Train 4(02) was delayed through the affected area.

| Train | Delay | Comment |
|---|---|---|
| 4(02) | 1'07" | |

27-FOI-00046 00000008955 UNCLASSIFIED 10/19/2026

## Train 59(03) South of Memphis, TN - Routing

04OCT26: Train 59(03) was delayed south of Memphis, TN/MP391.8, on the CN Memphis Subdivision, lining seven switches departing Memphis due to CN dispatcher routing.

| Train | Delay | Comment |
|---|---|---|
| 59(03) | 33" | |

## Train 8/28(02) East of Fargo, ND - Switch Issue

04OCT26: Train 8/28(02) was delayed at Moorhead Jct/MP5.8, 3 miles east of Fargo, ND, due to a track indication on Main 1 and necessary to take switch in hand to proceed east. Train 8/28(02) was delayed through the affected area. Train 7/27(03) was delayed at MP250.1, 8 miles east of Fargo, meeting Train 8/28(02).

**WBS#: B.TR.100150.7244**

| Train | Delay | Comment |
|---|---|---|
| 8/28(02) | 56" | |
| 7/27(03) | 38" | |

## Train 8/28(02)/7/27(03) Fardo, ND - Police Related

04OCT26: Due to a reported barricaded person at Fargo, ND on the BNSF Prosper subdivision between Fargo Yard and Moorhead Junction, train 7/27(03) held at Detroit Lakes and train 8/28(02) held at Bison. Upon clearing the scene from local authorities, both trains were released.

| Train | Delay | Comment |
|---|---|---|
| 8/28(02) | 30" | |
| 7/27(03) | 40" | |

## Train 22(04)/422(02) San Antonio, TX - Car Failure

04OCT26: Train 22(04)/422(02), E/63 & 8 cars, with 135 customers, was delayed departing San Antonio, TX/MP209.5, on the UPRR Del Rio Subdivision, due to the 6th car, coach C/34018 failed to release brakes during the Class I brake test. As a result, it was necessary to set out C/34018 on No 1 track in San Antonio. Train 22(04)/422(02) which had been delayed approximately 2 hours due to Train 1(03)/421(02) vehicle strike west of San Antonio, was delayed an additional 30 minutes due to the mechanical issue and set out of C/34018. Train 22(04)/422(02) was over capacity in coach by 51 seats between St. Louis, MO and Chicago, IL. Train 21/421(04) departed Chicago with C/34085 on the rear deadhead to St. Louis where C/34085 was cut off and added to the rear of Train 22(04)/422(02) to alleviate the over capacity condition. There were 9 customers in lower level seating of C/34018 reaccommodated in available upper level seating between San Antonio and St. Louis, MO.

| Train | Delay | Comment |
|---|---|---|
| 22(04)/422(02) | 30" | SAS, s/o C/34018 |
| 22(04)/422(02) | 2'24" | SAS, late connecting 422(02) |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *Train 390/393(04) - Cancelled Due To Engine Failure*

04OCT26: Due to engine fault code I043 on engine E/IDTX4616 and engine shopped in Carbondale, IL, train 393(04) and train 390(04) were cancelled in their entirety. Engine ID4619 was added to train 391(04) to be added ahead of E/IDTX4616 in Carbondale. Train 390(04) had 5 buses sourced and the plan included 2 buses Carbondale to Chicago with one bus operating express and one bus making all stops in between. Another 3 buses were confirmed Champagne to Chicago with two buses operating express and lone bus making all stops. Four busses were secured as alternate transportation for Train 393(04) between Chicago and Carbondale.

**WBS#: B.TR.100150.7240**

| Train | Delay | Comment |
|---|---|---|
| 393(04) | Cancelled | |
| 390(04) | Cancelled | |

## *Train 1(03)/421(02) West of San Antonio, TX - Trespasser Incident*

04OCT26: At 2:53 a.m. train 1(03)/421(02), E/78-E/343 & 9 cars, with and 178 customers, struck an occupied vehicle on Main 1 at MP212.08, 2 miles west of San Antonio, TX, in Bexar County on the UPRR Del Rio Subdivision. The vehicle was located at crossing ID 764300Y which was configured with signs, signals, W10-1 warning signs, 2 gate arms, 2 quad gate configurations, 2 mounted flashing lights, and 2 bells. The strike was a fatality to the driver, and the crew did request relief. No injuries were reported by crew or customers onboard. Local authorities and medical examiner responded to the scene. Amtrak management responded to the scene at 3:50 a.m. A recrew was on duty at 5:10 a.m. to head out to the train. A hold was in effect on both Mains while investigation was ongoing. Train 1(03)/421(02) was delayed holding for completion of investigation by local authorities. Train 2/422(02), with 207 customers, was delayed at MP213.2 holding for open route ahead. The hold was released at approximately 6:35 am and Train 1(03)/421(02) was back on the move west. Train 2/422(02) was further delayed due to westbound UPRR 6179 ahead at MP210.23 with PTC issues. Train 2/422(02) advanced to MP207.6 and then shoved back from Tower 131 into the San Antonio depot. Train 22(04)/422(02), with 135 customers, was delayed departing San Antonio holding for late connecting Train 422(02) and then delayed an additional 30 minutes due to the 6th car, C/34018 brakes did not release during the Class I brake test and it was necessary to set out C/34018 on No track in San Antonio.

**WBS#: B.TR.100150.7241**

**National Response Center Number: 1475295**

| Train | Delay | Comment |
|---|---|---|
| 1(03)/421(02) | 3'56" | |
| 2/422(02) | 20" | W/SAS, UP 6179 PTC issues a/h |
| 2/422(02) | 2'00" | W/SAS, 1(03)/421(02) vehicle strike |
| 22(04)/422(02) | 2'24" | SAS, late connecting 422(02) |
| 22(04)/422(02) | 30" | SAS, s/o C/34018 |

# *Train 11(03) Tacoma, WA - Engine Failure*

27-FD-00046 00000008955 "UNCLASSIFIED" 10/19/2026

03OCT26: At 1039AM-PT, Train 11(03) with E/338, E/355, 9 cars was delayed departing Tacoma, WA on the Sound Transit Lakewood Subdivision due to a high voltage circuit fault on trail E/355 with head end power(HEP) dropping. The crew held at the Tacoma station to troubleshoot with mechanical. There were 231 customers on board and the ambient outside temperature was 56 degrees. With the assistance of mechanical, at 1100AM-PT the crew was able to restore HEP with E/338; however, the faults on E/355 were not resolved. E/355 was placed in running box car mode due to the coolant pressure sensor and transducer power supply both failed. With HEP restored, Train 11(03) departed Tacoma and a freight unit was sourced downline.

Train 11(03) was further delayed at MP 100.1, 2 miles south of Kelso-Longview Station, on the BNSF Seattle Subdivision adding BN3880. BNSF personnel were on site to assist. Once the freight was added, a brake test was performed and Train 11(03) proceeded south. At Portland, it was necessary to perform a calendar day inspection on BN 3880. Once the inspection was complete, 11(03) departed Portland at 427PM-PT, 2 hours, and 5 minutes late.

**WBS#: B.TR.100150.7243**

| Train | Delay | Comment |
|---|---|---|
| 11(03) | 23" | TAC |
| 11(03) | 1'13" | S/KEL - adding BN 3880 |
| 11(03) | 41" | PDX - BN 3880 calendar day inspection |
| 11(03) | 26" | KEL-SLO - operating freight speed |

# *Train 5(30) East Omaha, NE - Tornado Warnings Downed Trees Washout BNSF Hastings sub*

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

01OCT26: Due to a weather-related washout on the BNSF Hastings Subdivision between MP 64 and MP 65, 6(29) and 5(30) experienced significant delays. BNSF established a detour through Cobb Yard between Hall and Lincoln, requiring pilot crews to guide both trains through the affected area. 6(29), carrying 139 customers, was initially delayed 2 hours and 45 minutes and later held near MP 68.1 while awaiting pilots, whose arrival was delayed by flooded roadways.

5(30), carrying 183 customers, was additionally delayed west of Omaha when a tree blocked the tracks near MP 39. After BNSF crews removed the tree and inspected the track, the train was recrewed and proceeded to Lincoln, where pilots boarded for the detour route. The same pilots and relief crew later transferred to 6(29) to assist it through the washout area. 6(29) subsequently arrived at Lincoln, was recrewed, resolved a PTC issue, and continued west.

Later, 5(30) encountered a second tree obstruction west of Lincoln near MP 69.7, resulting in another delay of approximately two hours while BNSF crews cleared and inspected the track. The train resumed operation under weather-related speed restrictions but was projected to exceed Hours of Service limits. A relief crew was dispatched from Denver, and 5(30) departed Hastings at 3:39 p.m. CT operating 13 hours and 17 minutes late before proceeding to Kenesaw Siding to await the recrew. Train 5(30) was back on the move at 736PM CT with the re-crew on duty. Train 5(30) was delayed at McCook NE completing daily inspections.

As a result of the washout, multiple weather-related track obstructions, speed restrictions, and crew shortages, both 6(29) and 5(30) incurred substantial delays throughout the territory. The service disruptions also resulted in the cancellation of 6(3) and 5(5), with no alternate transportation provided.

02OCT26: Tracks open at the scene of the washout at 1230AM CT.

| Train | Delay | Comment |
|---|---|---|
| 5(30) | 33" | Flash Flood warnings |
| 5(30) | 4'06" | Downed Trees |
| 5(30) | 3'47" | Re-crew |
| 5(30) | 45" | Daily Inspections MCK |
| 5(05) | Cancelled | |
| 6(03) | Cancelled | |
| 5(30) | 28" | LNK Routing |
| 6(29) | 7'20" | Holding W/LNK |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *BNSF Glasgow Subdivision West of Minot, ND - Freight Train Interference*

30SEP26: The BNSF reported a freight derailment on the Glasgow subdivision just west of Minot at Shoo Tower/MP 0.63 with seven stack cars and 26 containers on the ground on the 6th Street overpass and blocking both main tracks. There were no hazmat cars involved in the derailment. The derailment ruptured a local gas line. Heavy equipment arrived on scene through 300PM-CT to aid in the cleanup efforts with 25 ballast cars enroute. Train 7/27(29) had access to the Minot depot. Train 7/27(29) arrived Minot at 951AM-CT, 51 minutes late and held for disposition. The rough estimated time for main track 2 to be opened was 800PM-CT. Customer service worked to source alternate bus transportation for a potential bus bridge with train 8/28(29) between Minot and Stanley. There were 197 customers on train 7/27(29) that were affected. Customer service recovery was initiated in Minot with Papa Johns pizza for lunch and a chicken dinner. There were 179 customers on train 8/28(29) that were affected.

BNSF advised that the estimated time of track opening was pushed back until midnight. As a result, a bus bridge was initially implemented between Minot and Stanley. Four buses were sourced at Minot for customers on train 7/27(29) between Minot and Stanley and staged at 500PM-CT. Four buses were sourced for customers on train 8/28(29) between Stanley and Minot and staged at 730PM-CT. All busses were released after an update was given for track opening to be 11:15PM-CT, account of the expected logistics involved regarding the wye and crew hours of service.

Train 8/28(29) was held just west of the derailment at CP189/MP18.9 for disposition. Main track #2 was opened at 10:32PM-CT with a 25mph speed restriction, and 7/27(29) departed Minot at 10:55PM-CT operating 13 hours and 11 minutes late. Train 8/28(29) was behind multiple freights and also had to wait and allow all stacked-up westbound trains to pass, including 7/27(29), before proceeding into Minot. Main track #1 returned to service October 1st at 12:00P-CT.

Due to the late operation of Train 7/27(29), service recovery was initiated with Jimmy Johns sandwiches and chips for dinner being provided to all customers upon arrival into Spokane, WA.

**WBS#: B.TR.100150.7228**

| Train | Delay | Comment |
|---|---|---|
| 8/28(01) | Canceled | |
| 7/27(04) | Canceled | |
| 8/28(29) | 4'24" | |
| 7/27(29) | 12'13" | |

## *Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions*

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

| Train | Delay | Comment |
|---|---|---|
| 822(29) | 32" | |
| 821(29) | 27" | |
| 821(30) | 34" | |
| 822(30) | 30" | |
| 822(01) | 30" | |
| 821(02) | 34" | |
| 822(02) | 29" | |
| 822(03) | 33" | |
| 821(03) | 25" | |
| 821(04) | 35" | |
| 822(04) | 32" | |

11JUL25: The following trains went into emergency when crossing over the Chenoa Diamond/MP102 on the UPRR Joliet Subdivision:
-Train 22(10JUL), E/56-7 Cars, experienced an air hose separation between C/31006 and C/34024. Delay - 45" 27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

09AUG25: Train 22(08AUG), E/58, E/514 and 9 cars, experienced an air hose separation at Car 34049. The crew was able to secure and continue. Delay - 45"

14AUG25: Train 305(14) E/4628 and 5 cars, experienced air hose separation and broken glad hand on car 4008. The crew was able to replace the hose and continue. Delay - 25"

02SEP25: Train 300(02) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 4"

03SEP25: Train 300(03) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 11"

15OCT25: Train 302(15) E/IDTX4617 and 5 cars, experienced air hose separation between the 3rd and 4th cars, C/ID4121 and C/ID4128. The crew was able to replace the hose and continue.
Delay - 10"

12NOV25: Train 302(15), E/IDTX4617 - 5 cars-EIDTX4626, experienced an air hose separation between 3rd and 4th cars, C/ID4008 and C/ID4130. The was able to secure hose and Train 302(15) was able to proceed north.
Delay - 10"

15NOV25: Train 307(15), E/IDTX4617 and 5 cars, experienced an air hose separation between the 2nd and 3rd cars, C/ID4130 and ID4008. The crew was able to replace the hose and continue.
Delay - 10"

12DEC25: At 7:45AM-CT, Train 300(12), E/63-6 Cars, went into emergency after striking unknown debris after crossing over the Chenoa diamond at MP102.3 and coming to a stop at MP94.4. The Chenoa Diamond is located 21.7 miles north of the Bloomington-Normal, IL station on the UPRR Joliet Subdivision. The strike caused the main reservoir hose on the B-End of C/ID4128 to rip off and go missing. There were no injuries reported to the crew or 277 passengers onboard and no damage to the equipment. The main reservoir was cutoff to the car and then the crew completed a brake test. At 8:00AM-CT, Train 300(12) was back on the move north. Delay ~ 20"

06FEB26: Train 306(06) operating with engine 4603, 5 coaches, and 250 passengers, went into emergency 9.6 miles south of Pontiac, IL, on UPRR Joliet subdivision, after an air hose on car 4116 snapped, causing the train to come to a stop. The crew found the broken air hose and replaced it. Once the hose was replaced and the crew performed their brake test, train 306(06) was able to proceed. Delay 43".

15JUN26: Train 302(15), E/IDTX4625 and 6 cars, with 200 customers, was delayed at MP101.9, 23 miles north of Bloomington-Normal, IL, on the UPRR Joliet Subdivision, due to an air hose separation while operating over the Chenoa diamond at MP102. The crew resecured air hose between the first and second cars, C/ID4001 and C/ID4301. There were no other exceptions to equipment reported. Train 302(15) was on the move north after crew secured hose and performed brake test.

16AUG26: Train 319(16), E/IDTX4624 & 7 cars, with 281 customers, went into emergency over the Chenoa diamond/MP102.3, 10 miles south of Pontiac, IL, on the UPRR Joliet Subdivision. Crew inspected consist and found parted air hose between the 6th and 7th cars, C/ID4310 and C/ID4121. There were no other exceptions to equipment reported. Train 319(16) was on the move south after crew secured hose and performed brake test.

04OCT26: Train 300(04), E/IDTX4605 & 5 cars, with 220 customers, went into emergency over the Chenoa diamond/MP102.3, 23 miles north of Bloomington-Normal, IL, on the UPRR Joliet Subdivision. Crew inspected consist and found parted main res hose between the 2nd and 3rd cars, C/ID4132 and C/ID4305. There were no other exceptions to equipment reported. Train 300(04) was on the move north after crew secured hose and performed brake test. Train 300(04) was further delayed at MP50.2, 23 miles north of Dwight, IL, due to actuated dragging equipment detector. The crew inspected consist and found low hoses between the 2nd and 3rd cars, C/ID4132 and C/ID4305. The crew tied up the hoses

| Train | Delay | Comment |
|---|---|---|
| 300(04) | 11" | MP102 |
| 300(04) | 10" | MP50.2 |

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

# Maintenance of Way Highlights

27-BOI-00946 00000908856 "UNCLASSIFIED" 10/19/2026

## *BNSF Fort Worth Subdivision Track Work - Texas Eagle Service TW 27-007*

05OCT26: BNSF will perform tie replacement work on the Fort Worth Subdivision north of Temple, TX/MP218.2, between MP230 and MP245 beginning Monday October 5th through Friday October 9th. The work curfew will be from 630AM until 1230PM on the scheduled work days. To accommodate this infrastructure work, Amtrak's Texas Eagle Service will be adjusted as follows:

- Train 22(05-09) will depart San Antonio, TX, 59 minutes later, depart Fort Worth, TX, 30 minutes later and resume normal schedule upon departure from Dallas, TX.
- Train 422(04, 07) will depart San Antonio, 59 minutes later, depart Fort Worth 30 minutes later and resume normal schedule upon departure from Dallas.

**WBS#: B.TR.100150.7225**

## *CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006*

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

**WBS#: B.TR.100150.7220**

## *Union Pacific Brooklyn Subdivision Portland, OR - Portland Marathon TWA 27-003*

04OCT26: The Portland Marathon occurred in Portland, OR, resulting in closure of rail operations at Southeast Stark Street (DOT #754542S) / MP 769.78 on the Brooklyn Subdivision, 1 mile south of the Portland, OR Union Station due to event-related roadway and crossing closure. As a result, the following operating plan was implemented:

Train 503(04) terminated in Portland.

Train 504(04) originated in Portland and operate 1-hour later.

Buses were secured to provide alternate transportation to customers traveling to and from all missed station stops.

**WBS#: B.TR.100150.7209**

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

## *UPRR Coast Subdivision South of Oakland, CA - Scheduled M/W Work 27-009*

02OCT26: The UPRR performed work which required MP 14.092 on the Coast Subdivision beginning at 7A-PT on Saturday, October 3rd. To accommodate the infrastructure work, the following service adjustments were made.

- Train 11(02OCT), which normally operates between Oakland, CA and San Jose, CA on the UPRR Coast Subdivision detoured over the Niles Subdivision between Elmhurst/MP 14 and Newark/ MP 31 with no stops missed.

**WBS#: B.TR.100150.7230**

## *Coast Starlight - Scheduled M/W Work 26-090*

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

**WBS#: B.TR.100151.0836**

| Train | Delay | Comment |
|---|---|---|
| 11(22AUG) | 32" | |
| 14(22AUG) | 23" | |
| 11(12SEP) | 29" | |
| 14(12SEP) | 58" | Detour/ FTI |
| 14(26SEP) | 18" | |
| 11(26SEP) | 36" | |
| 14(03OCT) | 25" | |

## *Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082*

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

**WBS#: B.TR.100150.6961**

27-FOI-00046 000000008955 "UNCLASSIFIED" 10/19/2026

## CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gang will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

**WBS#: B.TR.100150.6867**

| Train | Delay | Comment |
|---|---|---|
| 59(21) | Terminated MEM | |

## BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

**WBS#: B.TR.100150.6626**

## *Metra C&M Subdivision - Scheduled M/W Work 26-055*

27-FOI-00048 0000000008955 "UNCLASSIFIED" 10/19/2026

16MAY26: Metra has track work scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

**WBS#: B.TR.100150.6663**

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| 11(3) | KEL | BNSF3880 | E/338 HEP issues | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Western Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

## Consist Deviations

27-FOI-00046 00000008955 "UNCLASSIFIED" 10/19/2026

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 41 (04) | CHI | Due to non-working toilets in train 41(04) it will have to d/h in line. This has caused train 41(04) to be over capacity, | PASSENGERS NOTIFIED | 43 | 25003 |
| 782 (04) | GTA | no bike space or wifi | NONE | 0 | 90215 |
| 2209 (04) | NYP | legacy replaced with NG | YES SEATS WAS CHANGE | 140 | 3263 |
| 2227 (04) | NYP | legacy replaced with NG | YES SEATS WAS CHANGE | 250 | 3263 |
| 2219 (04) | NYP | legacy replaced with NG | YES | 200 | 3269 |
| 761 (04) | SAN | no bike space or wifi | NONE | 0 | 90215 |
| 593 (04) | SAN | no bike space or wifi | NONE | 0 | 90215 |
| 2216 (04) | WAS | legacy replaced with NG | YES SEATS WAS CHANGE | 198 | 3263 |
| 2208 (04) | WAS | legacy replaced with NG | YES, SEATS WAS CHANGE | 230 | 3269 |
| 2224 (04) | WAS | legacy replaced with NG | YES | 200 | 3269 |

## Reverse Consists

| Train Number | Station | Reason |
|---|---|---|
| 161 (04) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 87 (04) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 150 (04) | PHL | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 88 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 164 (04) | NPN | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 103 (04) | NYP | Consist reversed \| Business class seat orientation may have changed \| At Rear |
| 96 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 169 (04) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 128 (04) | NFK | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 135 (04) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |