CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, October 06, 2026 Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00044 [illegible] [illegible] 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/05/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	56	82.9%	1,572	219	86.1%	1,572	219	86.1%
Central Division	86.0%	57	3	94.7%	287	11	96.2%	287	11	96.2%
East Division	82.0%	178	39	78.1%	844	131	84.5%	844	131	84.5%
West Division	86.0%	92	14	84.8%	441	77	82.5%	441	77	82.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/5/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**103,263**	**37,278**	**64%**	**558,814**	**168,129**	**70%**	**558,814**	**168,129**	**70%**
Northeast Corridor	***81%***	***44,752***	***17,961***	***60%***	***244,073***	***72,654***	***70%***	***244,073***	***72,654***	***70%***
Acela	83%	11,843	4,117	65%	53,008	14,422	73%	53,008	14,422	73%
Northeast Regional	79%	32,909	13,844	58%	191,065	58,232	70%	191,065	58,232	70%
Richmond / Newport News / Norfolk	77%	8,657	3,641	58%	55,684	17,866	68%	55,684	17,866	68%
Springfield Shuttles	89%	648	261	60%	4,883	1,257	74%	4,883	1,257	74%
Roanoke	79%	2,917	1,161	60%	18,402	6,382	65%	18,402	6,382	65%
On Spine Northeast Regional	80%	20,687	8,781	58%	112,096	32,727	71%	112,096	32,727	71%
State Supported	***80%***	***45,513***	***13,329***	***71%***	***252,347***	***63,931***	***75%***	***252,347***	***63,931***	***75%***
Borealis	80%	633	276	56%	3,297	970	71%	3,297	970	71%
Capitol Corridor	90%	4,296	621	86%	20,765	6,246	70%	20,765	6,246	70%
Carolinian	70%	1,225	476	61%	6,434	1,846	71%	6,434	1,846	71%
Cascades	75%	2,518	606	76%	14,717	3,155	79%	14,717	3,155	79%
Downeaster	82%	1,440	446	69%	9,547	2,996	69%	9,547	2,996	69%
Empire	78%	5,691	1,699	70%	31,327	6,234	80%	31,327	6,234	80%
Adirondack	72%	608	204	66%	1,964	305	84%	1,964	305	84%
Ethan Allen Express	70%	516	318	38%	2,961	862	71%	2,961	862	71%
Maple Leaf	70%	721	282	61%	4,250	831	80%	4,250	831	80%
New York - Albany	85%	2,598	613	76%	14,888	2,467	83%	14,888	2,467	83%
New York - Niagara Falls	75%	1,248	282	77%	7,264	1,769	76%	7,264	1,769	76%
Gold Runner	73%	2,742	792	71%	14,978	4,460	70%	14,978	4,460	70%
Heartland Flyer	70%	148	145	2%	965	943	2%	965	943	2%
Hiawatha	90%	1,494	7	100%	9,852	7	100%	9,852	7	100%
Illinois	78%	2,953	768	74%	14,810	4,878	67%	14,810	4,878	67%
Carl Sandburg / Illinois Zephyr	85%	361	40	89%	2,285	457	80%	2,285	457	80%
Illini / Saluki	85%	866	456	47%	4,885	1,287	74%	4,885	1,287	74%
Lincoln Service	70%	1,726	272	84%	7,640	3,134	59%	7,640	3,134	59%
Keystone	92%	8,862	3,102	65%	42,243	6,221	85%	42,243	6,221	85%
Lincoln / Missouri	70%	730	333	54%	4,383	2,279	48%	4,383	2,279	48%
Mardi Gras Service	80%	290	39	87%	1,535	204	87%	1,535	204	87%
Michigan	70%	2,152	127	94%	12,040	2,247	81%	12,040	2,247	81%
Blue Water	70%	433	0	100%	2,794	554	80%	2,794	554	80%
Pere Marquette	85%	310	0	100%	1,568	53	97%	1,568	53	97%
Wolverine	70%	1,409	127	91%	7,678	1,640	79%	7,678	1,640	79%
Missouri	80%	167	0	100%	1,488	109	93%	1,488	109	93%
Pacific Surfliner	85%	7,537	2,856	62%	46,168	17,179	63%	46,168	17,179	63%
Pennsylvanian	80%	874	306	65%	4,791	850	82%	4,791	850	82%
Piedmont	80%	445	222	50%	5,560	573	90%	5,560	573	90%
Vermonter	75%	1,316	508	61%	7,447	2,534	66%	7,447	2,534	66%
Long Distance	***70%***	***12,998***	***5,988***	***54%***	***62,394***	***31,544***	***49%***	***62,394***	***31,544***	***49%***
Auto Train	70%	614	614	0%	3,430	2,197	36%	3,430	2,197	36%
California Zephyr	70%	456	202	56%	3,978	1,725	57%	3,978	1,725	57%
Cardinal	70%	352	159	55%	1,749	1,270	27%	1,749	1,270	27%
City Of New Orleans	75%	869	37	96%	3,776	2,152	43%	3,776	2,152	43%
Coast Starlight	70%	1,803	1,480	18%	6,028	3,433	43%	6,028	3,433	43%
Crescent	70%	1,102	139	87%	5,090	646	87%	5,090	646	87%
Empire Builder	70%	1,118	690	38%	4,750	2,634	45%	4,750	2,634	45%
Floridian	60%	1,447	578	60%	7,662	5,312	31%	7,662	5,312	31%
Lake Shore Ltd	73%	1,189	259	78%	5,526	1,756	68%	5,526	1,756	68%
Palmetto	70%	909	12	99%	4,373	700	84%	4,373	700	84%
Silver Meteor	70%	1,015	693	32%	4,688	2,230	52%	4,688	2,230	52%
Southwest Chief	60%	880	68	92%	4,434	3,134	29%	4,434	3,134	29%
Sunset Ltd	70%	358	290	19%	1,390	690	50%	1,390	690	50%
Texas Eagle	70%	886	767	13%	5,520	3,665	34%	5,520	3,665	34%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FGI 00046 00000000054 "UNCLASSIFIED" 10/10/2026~~

Train Index Dates Through October 05, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	33,249	543,569	612	33,249	543,569	612

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	2,603	167,299	156	2,603	167,299	156
INFRASTRUCTURE PLANNED	135	4,110	167,299	246	4,110	167,299	246
FLEET RELIABILITY	90	4,753	543,569	87	4,753	543,569	87
TRAIN OPERATIONS	424	21,783	543,569	401	21,783	543,569	401

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00044 [illegible] [illegible] 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/05/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	56	82.9%	1,572	219	86.1%	1,572	219	86.1%
Central Division	86.0%	57	3	94.7%	287	11	96.2%	287	11	96.2%
East Division	82.0%	178	39	78.1%	844	131	84.5%	844	131	84.5%
West Division	86.0%	92	14	84.8%	441	77	82.5%	441	77	82.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-00044 [illegible]

Scheduled Departure Date: **10/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/05/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	56	82.9%	1,572	219	86.1%	1,572	219	86.1%
Central Division	86.0%	57	3	94.7%	287	11	96.2%	287	11	96.2%
CDL	95.0%	1	0	100.0%	8	0	100.0%	8	0	100.0%
CHI	86.0%	25	2	92.0%	132	7	94.7%	132	7	94.7%
CHM	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
FTW	92.5%	1	0	100.0%	5	0	100.0%	5	0	100.0%
GRR	95.5%	1	0	100.0%	5	0	100.0%	5	0	100.0%
KCY	92.0%	2	0	100.0%	10	0	100.0%	10	0	100.0%
MKE	92.0%	6	0	100.0%	29	0	100.0%	29	0	100.0%
MOE	97.5%	2	0	100.0%	10	0	100.0%	10	0	100.0%
MSP	96.5%	1	0	100.0%	5	0	100.0%	5	0	100.0%
NOL	94.5%	5	0	100.0%	22	1	95.5%	22	1	95.5%
OKC	97.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
PNT	88.0%	3	0	100.0%	15	0	100.0%	15	0	100.0%
PTH	93.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
QCY	91.0%	2	1	50.0%	10	1	90.0%	10	1	90.0%
SAS	90.5%	1	0	100.0%	5	1	80.0%	5	1	80.0%
STL	89.0%	4	0	100.0%	20	1	95.0%	20	1	95.0%
East Division	82.0%	178	39	78.1%	844	131	84.5%	844	131	84.5%
ALB	88.5%	8	2	75.0%	40	3	92.5%	40	3	92.5%
BON	87.5%	5	0	100.0%	25	2	92.0%	25	2	92.0%
BOS	85.5%	19	1	94.7%	93	4	95.7%	93	4	95.7%
BRK	92.5%	5	0	100.0%	25	2	92.0%	25	2	92.0%
BTN	82.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
CLT	91.5%	4	1	75.0%	23	3	87.0%	23	3	87.0%
GFD	88.0%	2	1	50.0%	10	2	80.0%	10	2	80.0%
GRO	-	1	0	100.0%	2	0	100.0%	2	0	100.0%
HAR	79.5%	13	1	92.3%	53	9	83.0%	53	9	83.0%
HFD	-	2	0	100.0%	6	0	100.0%	6	0	100.0%
LOR	84.0%	1	1	0.0%	5	3	40.0%	5	3	40.0%
MIA	89.5%	2	1	50.0%	10	2	80.0%	10	2	80.0%
MTR	79.0%	1	0	100.0%	5	2	60.0%	5	2	60.0%
NFK	84.5%	2	1	50.0%	10	3	70.0%	10	3	70.0%
NFL	93.5%	2	1	50.0%	10	2	80.0%	10	2	80.0%
NHV	78.0%	5	2	60.0%	24	7	70.8%	24	7	70.8%
NPN	93.0%	2	0	100.0%	10	1	90.0%	10	1	90.0%
NYP	75.5%	51	18	64.7%	234	51	78.2%	234	51	78.2%
PGH	93.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
PHL	48.0%	5	2	60.0%	23	12	47.8%	23	12	47.8%
RGH	95.0%	2	0	100.0%	16	1	93.8%	16	1	93.8%
RNK	83.5%	2	0	100.0%	10	1	90.0%	10	1	90.0%
SAB	98.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
SFA	88.0%	1	0	100.0%	5	2	60.0%	5	2	60.0%
SPG	92.5%	5	2	60.0%	28	3	89.3%	28	3	89.3%

Information Management

27-FOI-0004

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/05/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	56	82.9%	1,572	219	86.1%	1,572	219	86.1%
East Division	82.0%	178	39	78.1%	844	131	84.5%	844	131	84.5%
TWO	73.0%	1	0	100.0%	5	1	80.0%	5	1	80.0%
WAS	84.0%	33	5	84.8%	152	15	90.1%	152	15	90.1%
West Division	86.0%	92	14	84.8%	441	77	82.5%	441	77	82.5%
ARN	92.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
BFD	79.0%	7	3	57.1%	35	9	74.3%	35	9	74.3%
EMY	72.0%	1	0	100.0%	4	2	50.0%	4	2	50.0%
EUG	86.5%	2	0	100.0%	9	0	100.0%	9	0	100.0%
GTA	90.0%	3	1	66.7%	15	5	66.7%	15	5	66.7%
LAX	89.5%	10	2	80.0%	52	6	88.5%	52	6	88.5%
OKJ	74.5%	13	3	76.9%	57	15	73.7%	57	15	73.7%
PDX	86.0%	5	0	100.0%	25	2	92.0%	25	2	92.0%
SAC	88.5%	16	2	87.5%	72	9	87.5%	72	9	87.5%
SAN	90.5%	13	2	84.6%	63	11	82.5%	63	11	82.5%
SEA	85.0%	8	1	87.5%	39	6	84.6%	39	6	84.6%
SJC	89.0%	7	0	100.0%	35	11	68.6%	35	11	68.6%
SLO	90.0%	3	0	100.0%	15	1	93.3%	15	1	93.3%
SPK	90.0%	1	0	100.0%	5	0	100.0%	5	0	100.0%
VAC	97.0%	2	0	100.0%	10	0	100.0%	10	0	100.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	194	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
3		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
4		5	0	100.0%	5	0	100.0%	5	4	20.0%	5	4	20.0%
5	99	4	0	100.0%	4	0	100.0%	5	3	40.0%	5	3	40.0%
7		4	0	100.0%	4	0	100.0%	5	2	60.0%	5	2	60.0%
8	17	4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
11	83	5	1	80.0%	5	1	80.0%	5	4	20.0%	5	4	20.0%
14	180	5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
19		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
20		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
21	73	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
22	389	5	1	80.0%	5	1	80.0%	5	4	20.0%	5	4	20.0%
23		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
24		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
25	20	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
26		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
27		4	1	75.0%	4	1	75.0%	5	2	60.0%	5	2	60.0%
28	31	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
40	526	5	1	80.0%	5	1	80.0%	5	5	0.0%	5	5	0.0%
41		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
42		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
43	35	5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
48		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
49		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
51	38	2	0	100.0%	2	0	100.0%	3	3	0.0%	3	3	0.0%
52	182	5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
53	89	5	3	40.0%	5	3	40.0%	5	4	20.0%	5	4	20.0%
55		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
56		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
58		5	0	100.0%	5	0	100.0%	5	4	20.0%	5	4	20.0%
59		5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
63	34	5	4	20.0%	5	4	20.0%	5	5	0.0%	5	5	0.0%
64	23	5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
66		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
67	64	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
68		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
69		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
71		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
72		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
75		5	0	100.0%	5	0	100.0%	4	0	100.0%	4	0	100.0%
76	26	5	1	80.0%	5	1	80.0%	4	1	75.0%	4	1	75.0%
77	115	5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%

Amtrak On Time Performance

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79	18	5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
80		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
84	64	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
85		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
86	18	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
89		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
90		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
93	20	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
94	36	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
95	77	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
97		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
98	44	5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
110	38	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
111		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
112		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
113	86	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
119	21	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
125	Cncld	3	1	66.7%	3	1	66.7%	2	2	0.0%	2	2	0.0%
128	23	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
129		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
130	49	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
131	16	3	1	66.7%	3	1	66.7%	3	3	0.0%	3	3	0.0%
134		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
137		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
138		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
139		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
141	51	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
148		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
151		5	5	0.0%	5	5	0.0%	5	2	60.0%	5	2	60.0%
166		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
169		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
170	85	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
171	23	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
172	33	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
173		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
174		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
175	134	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
176		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
177	104	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
181	44	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
182		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
183	32	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%

Amtrak On Time Performance

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184	44	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
185	39	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
186		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
190		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
192		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
193		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
196		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
197		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
230	25	5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
232		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
233	19	5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
234		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
235		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
236		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
237		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
238		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
239	48	5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
240		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
241		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
243		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
244		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
245	179	5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
280	114	5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
281		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
283		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
284		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
290	105	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
291		5	4	20.0%	5	4	20.0%	5	1	80.0%	5	1	80.0%
300		5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
301		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
302		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
305		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
306		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
307	37	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
311		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
316		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
318	32	5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
319	26	5	0	100.0%	5	0	100.0%	5	4	20.0%	5	4	20.0%
329		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
330		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
331		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
332		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
335		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
336		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
337		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
338		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
339		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
342		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
350	23	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
351		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
352		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
353		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
354	17	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
355		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
364		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
365		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
370		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
371		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
380		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
381		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
382		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
383		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
390		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
391		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
392	28	5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
393	50	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
417	39	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
425		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
448		5	3	40.0%	5	3	40.0%	5	1	80.0%	5	1	80.0%
449		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
470		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
471		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
473		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
474	71	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
475		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
478		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
479	21	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
486	66	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
494	18	4	2	50.0%	4	2	50.0%	3	1	66.7%	3	1	66.7%
495		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
500		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
502		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
503	54	5	2	60.0%	5	2	60.0%	5	3	40.0%	5	3	40.0%

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
505		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
506	101	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
507		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
508	16	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
509	172	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
511	51	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
516		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
517		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
518	42	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
519		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
520		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
521		3	0	100.0%	3	0	100.0%	2	0	100.0%	2	0	100.0%
522		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
523		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
524		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
525		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
526		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
527		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
528		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
529	28	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
530		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
531		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
532		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
534		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
535		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
536		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
537		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
538		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
539		3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
540		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
541		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
542		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
543	47	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
544		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
545		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
547		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
548		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
549		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
550		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
551		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
562	31	5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%

Amtrak On Time Performance

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
566		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
567		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
572		5	2	60.0%	5	2	60.0%	5	3	40.0%	5	3	40.0%
573		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
579		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
580		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
581	35	5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
584	39	5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
587		5	2	60.0%	5	2	60.0%	4	1	75.0%	4	1	75.0%
588		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
591		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
593		5	2	60.0%	5	2	60.0%	4	0	100.0%	4	0	100.0%
595		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
600	48	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
601		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
605		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
607		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
609		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
622		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
626		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
637		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
639	56	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
640	61	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
641	22	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
642	36	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
643	38	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
644	44	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
645	58	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
646		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
647		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
648		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
649		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
650		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
651		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
652		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
653	65	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
654	48	3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
655		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
656	19	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
657	47	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
658		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
681	21	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
682		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
683	26	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
684	25	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
685		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
686	32	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
687		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
688		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
699		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
701		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
702		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
703		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
704		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
710		5	2	60.0%	5	2	60.0%	5	0	100.0%	5	0	100.0%
711		5	1	80.0%	5	1	80.0%	4	0	100.0%	4	0	100.0%
712	35	5	3	40.0%	5	3	40.0%	5	3	40.0%	5	3	40.0%
713		5	3	40.0%	5	3	40.0%	5	1	80.0%	5	1	80.0%
714		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
715		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
716	72	5	3	40.0%	5	3	40.0%	5	2	60.0%	5	2	60.0%
717		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
718		5	3	40.0%	5	3	40.0%	5	1	80.0%	5	1	80.0%
719		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
757		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
761		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
765		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
769	25	5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
770		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
774	25	5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
777	43	5	0	100.0%	5	0	100.0%	5	4	20.0%	5	4	20.0%
782	30	5	5	0.0%	5	5	0.0%	5	3	40.0%	5	3	40.0%
785	28	5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
786		5	0	100.0%	5	0	100.0%	4	2	50.0%	4	2	50.0%
790		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
794		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
821	71	5	0	100.0%	5	0	100.0%	5	5	0.0%	5	5	0.0%
822	32	5	0	100.0%	5	0	100.0%	5	5	0.0%	5	5	0.0%
1333		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
1340	80	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
2102	45	3	0	100.0%	3	0	100.0%	2	1	50.0%	2	1	50.0%
2103		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2104	33	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2105		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2107		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2108		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2109	40	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2112		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2113		3	2	33.3%	3	2	33.3%	2	1	50.0%	2	1	50.0%
2115		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2116		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2118	28	3	2	33.3%	3	2	33.3%	2	1	50.0%	2	1	50.0%
2119		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2120		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
2123		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2124		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2126		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2127		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2128		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2131	Cncld	3	2	33.3%	3	2	33.3%	1	0	100.0%	1	0	100.0%
2150	34	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2151	43	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2152		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2154	17	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2155	31	3	0	100.0%	3	0	100.0%	2	1	50.0%	2	1	50.0%
2156	25	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2158		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2159	20	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
2160		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2162		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2163	22	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
2165	22	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2167		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2171		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2190		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2193	97	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2228	39	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2233		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2264		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2102	NYP	45	DMW	56	DMW	43	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP
2104	NYP	33	DMW	33	DMW	22	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP
2109	WAS	40	DMW	31	DMW	26	NYP-NYP	AM	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
2118	NYP	28	ENG	25	ENG	25	XHM-XCY	AM	Other electrical failure, 2148|NG|NP, STOPPED EAST OF ADAMS WITH MULTIPLE FAULTS
2131	WAS	Trn Cancelled							
2150	BOS	34	DMW	40	DMW	40	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
2151	WAS	43	DSR	19	DSR	19	NHV-STM	MN	Per bulletin Milepost, 48.6, 40.4, 12, 2
2154	BOS	17	DMW	19	DMW	19	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
2155	WAS	31	CTI	23	OTH	7	XGX-NHV	AM	Lost time - N.A.R., NO DELAY-XGX 2 MINUTES ADVANCE AND ARRIVED NHV ON TIME.
2156	BOS	25	DCS	24	DCS	24	NWK-NYP	AM	T.O.L, Other, XBH, HELD SINGLE TRACKING A/C TOL IN NORTH TUBE
2159	WAS	20	OTH	9	MBO	6	PVD-XGX	AM	For maritime traffic, Bridge, THAMES RIVER BRIDGE, THAMES RIVER BRIDGE OPEN FOR TUG BOAT.
2163	WAS	22	BSP	17	PTI	12	BAL-XNY	AM	Follow, 93, Control Point, BAL-XGV
2165	WAS	22	BSP	24	BSP	24	XGX-NHV	AM	Bridge strike, Bridge, WALLBACH ST
2193	NYP	97	DCS	106	DCS	106	XGX-XNH	AM	Power switch failure, Milepost w/Letters, XGX, NHV, delays due to the 21sw failure B/end at Guilford and followed AM177
2228	NYP	39	ENG	41	ENG	34	XHM-XCY	AM	Cab signal failure, 2121|NG|NP, TRAIN ELECTRONICALLY CUT CABS AND ACSES, JUST WEST OF CROYDON ON NO.2 TRK.
67	NPN	64	FTI	61	FTI	54	FBG-ASD	CS	Meet csx i 035, Control Point, cfp53.2
84	NYP	64	MTI	66	MTI	66	WAS-WAS	AM	Disabled train ahead, Other, NYP, LATE REL OF 113 IN SSYD DUE TO UNKNOWN HEP ISSUES WITH MTR 606

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
86	NYP	18	DET	18	DET	18	BAL-XPV	AM	Catenary failure, Control Point, Davis - Perry, Held for Southbound Amtrak trains. Emergency plate a/c power loss No.3 trk
93	NFK	20	PTI	33	PTI	12	BWI-NCR	AM	Follow, ., Control Point, ., HELD AT CARROLL FOR 2163 AHEAD.
94	BOS	36	PTI	27	DCS	20	NHV-OSB	AM	Power switch failure, Milepost w/Letters, NHV, OSB, AM94 behind AM2160 behind AM184 which is delayed due to 21sw being out of correspondence on the B/end at Guilford
95	NFK	77	CTI	64	DMW	30	NYP-NYP	AM	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
110	NYP	38	DMW	44	DMW	26	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
113	WAS	86	ENG	34	ENG	34	NYP-NYP	AM	HEP, 606|EX|ES, LATE F/SSYD A/C UNSPECIFIED MECHANICAL ISSUES
119	WAS	21	DMW	25	DMW	25	NYP-NYP	AM	Hold for defect repair, Other, NYP, LATE TURN OFF AM112 A/C BROKEN RAIL IN NORTH TUBE
125	NPN	Trn Cancelled	ENG	298	ENG	264	RVM-WBG	CS	Failure of diesel engine Oil leak. Engine to a stop at CA 39. Hold for rescue CSX Engine., 371
128	NYP	23	SMW	37	SMW	30	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XBH, SINGLE TRACKING ON NO.2 TRACK A/C 3 TRK O/O/S HUDSON TO LACK
130	NYP	49	DMW	57	DMW	48	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
131	WAS	16	SYS	21	SYS	21	NYP-NYP	AM	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING WITH ONLY 1 ENGINE
141	WAS	51	CTI	26	DMW	10	NYP-NWK	AM	Hold for defect repair, Other, NYP-NWK, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
170	BOS	85	DMW	67	DMW	59	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
171	RNK	23	SMW	19	SMW	17	XSH-NYP	AM	Scheduled in track usage program, Other, XM9, HELD F/AM56-AM2154 A/C 1 TRK OOS MANOR TO LEGGETT

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
172	BOS	33	DMW	13	DMW	13	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
175	WAS	134	CON	69	CON	66	PHL-PHL	AM	Hold for connecting train, HOLD FOR SB PAX FROM 2131
177	PHL	104	DCS	108	DCS	106	OSB-NHV	AM	Power switch failure, Milepost w/Letters, OSB, NHV, delays due to the 21sw failure B/end at Guilford and followed CD1691
181	WAS	44	ENG	49	ENG	49	PHL-WIL	AM	Set out defective locomotive, 602|EX|ES, PANTOGRAPH DAMAGE
183	WAS	32	DMW	25	DMW	25	NYP-NYP	AM	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
184	BOS	44	DCS	52	DCS	50	NHV-XGX	AM	Power switch failure, Milepost w/Letters, NHV, XGX, AM184 delayed due to 21sw being out of correspondence on the B/end at Guilford
185	WAS	39	DMW	42	DMW	42	NYP-NYP	AM	Hold for defect repair, Other, NYP, LATE TURN OFF AM110 A/C BROKEN RAIL IN NORTH TUBE
417	NHV	39	CTI	22	CTI	20	SPG-WNL	AM	Meet, CTRAIL, 4414, Milepost w/Letters, SPG, WNL, CSX 2A - trk 10 then waited for CT4414 to clear single track
474	SPG	71	ENG	60	ENG	60	NHV-NHV	AM	Air / Brake, 120|DX|BD, due to the brake issue on E/120
479	NHV	21	SMW	6	SMW	6	SPG-WNL	AM	Scheduled in track usage program, Milepost w/Letters, SPG, WNL, 30 MPH S/r MP 48.5 - 49.2
486	GFD	66	ENG	97	ENG	97	NHV-NHV	AM	Air / Brake, 120|DX|BD, AM486 departed late a/c brake issues on E/120, had to swap equipment with AM474
494	GFD	18	RTE	8	RTE	8	WNL-SPG	AM	Run via siding or slower track due to N.A.R., Milepost w/Letters, WNL, SPG, AM494 had to take CSX trk 10 - 2A, wait on csx signal
52	LOR	182	ITI	194	ITI	194	SFA-SFA	FR	Late departure at initial terminal due to late arrival of inbound equipment 53
53	SFA	89	FTI	87	CTI	43	XDD-XSF	FR	Meet CFRC, P310, CFRC, P312, CFRC, P314, Control Point, Blue Springs, Bridge, Lake Monroe, Control Point, VSMF
79	CLT	18	PTI	57	PTI	28	DNC-BNC	NS	Meet 76, Control Point, Mebane
600	NYP	48	DMW	54	DMW	48	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
639	PHL	56	DCS	57	DCS	57	NYP-NYP	AM	T.O.L, Other, J.O., CONGESTION AT J.O A/C T.OL
640	NYP	61	DMW	70	DMW	46	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP
641	HAR	22	DMW	31	DMW	31	NYP-NYP	AM	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
642	NYP	36	DMW	36	DMW	30	NWK-NYP	AM	Hold for defect repair, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
643	HAR	38	DMW	39	DMW	39	NYP-NYP	AM	Hold for defect repair, Other, NYP, LATE TURN OFF AM640 A/C BROKEN RAIL IN NORTH TUBE
644	NYP	44	ENG	29	ENG	16	PHL-XHM	AM	PTC - On Board Cab Signal or PTC Failure, 9645|CB|CC, OPERATE 79 MPH, CUT OUIT CABS
645	HAR	58	SVS	35	SVS	35	PHL-PAO	AM	Unplanned Wye
653	HAR	65	SVS	60	SVS	33	PHL-PHL	AM	Unplanned Wye
654	NYP	48	SVS	49	SVS	42	PHL-XHM	AM	Scheduled wyeing of the train
656	NYP	19	DCS	13	DCS	13	PHL-XHM	AM	Power switch failure, Control Point, Holmes, 12sw failure
657	HAR	47	SYS	48	SYS	48	NWK-PJC	AM	Blocked by or assisting another, disabled Amtrak train, STOPPED AT MIDWAY FOR PSNGR TRANSFER OFF DISABLED AM2131
681	BRK	21	SYS	8	SYS	8	POR-FRE	CS	PTC-caused slow-down or penalty stop
683	BRK	26	PTI	27	PTI	27	EXR-DHM	CS	Meet 684, Control Point, rockingham
684	BON	25	PTI	15	PTI	15	FRE-POR	CS	Meet 681, Control Point, mountain
686	BON	32	PTI	24	PTI	18	ORB-SAO	CS	Meet Waiting on late amt 683, amt 683, Siding, Surf
63	TWO	34	FTI	34	FTI	27	ROC-BUF	CS	Meet csxt, Control Point, 417
64	NYP	23	CTI	41	CTI	20	POU-CRT	MN	Cross Traffic metro north, 869, Control Point, 61
230	NYP	25	ITI	23	ITI	23	ALB-ALB	AM	Late departure at initial terminal due to late arrival of inbound equipment 245
233	ALB	19	CTI	10	PTI	8	RHI-HUD	AM	Meet 284, Control Point, 114
239	ALB	48	ITI	45	ITI	45	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 290, LATE TURN OFF AM290

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
245	ALB	179	ITI	198	ITI	198	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 68
280	NYP	114	ENG	92	ENG	38	NFL-NFL	CS	PTC - On Board Cab Signal or PTC Failure GPS signal not being picked up by PTC at mechanical facility, needed to bring it to NFL station in restricted mode and reset everything once at the NFL station, 9702
290	NYP	105	WTR	107	WTR	105	SAR-XSY	DH	Trees down Blocked by trees at CPF 485 not passive, Control Point, CPF 485
43	PGH	35	DMW	27	DMW	22	LEW-HGD	NS	NS rail gang has said that they would be in the clear at 4:00 PM. The rail gang did not clear up and the NS Allegheny TD had traffic lined up and was unable to get us around of the trains ahead due to the rail gang not clearing up. Milepost, 184, 202
76	RGH	26	DMW	27	DMW	27	GRO-GRO	NS	Held for or routed around MW work or equipment Milepost w/Letters, 2.68nc, 4.37nc
77	CLT	115	DMW	120	DMW	120	BNC-GRO	NS	Held for or routed around MW work or equipment Milepost, 12.1, 7.9
98	NYP	44	FTI	99	FTI	53	YEM-CHS	CS	Blocked from station track 13804, Control Point, SY
40	CHI	526	TRS	349	TRS	349	KIS-ORL	FR	Trespasser strike Trs strike at mp 804. Held by Florida highway patrol to complete investigation., Milepost, 804.5, 804.5
25	NOL	20	FTI	46	FTI	33	XNO-XEJ	NS	Meet unknown, Control Point, 5.9
5	EMY	99	FTI	140	FTI	85	WNN-XMS	UP	Train into emergency Siding, Humboldt, 7399
529	SJC	28	HLD	13	SYS	8	OKJ-OKJ	UP	Re-crew / job briefing
543	SJC	47	PTI	29	CTI	14	FMT-GAC	UP	Meet ace, 8, Siding, albrea
51	CHI	38	FTI	34	FTI	25	XTJ-XEF	UP	Meet unknown, Control Point, Dolton
503	EUG	54	CCR	33	PTI	23	ALY-EUG	UP	Meet Pull into Irving siding. Shove back after 14 went by., 14, Siding, Irving
506	SEA	101	POL	101	POL	96	XNI-TAC	ST	RR blocked by trespasser or vehicle strike by another train
508	SEA	16	PTI	20	PTI	18	OLW-XNI	BN	Meet amtk 509/ 511, Control Point, nisqualie
509	PDX	172	TRS	172	TRS	172	XA4-XTW	BN	Trespasser strike Milepost w/Letters, 29.4x, 29.4x
511	PDX	51	TRS	46	TRS	46	XA4-XTW	BN	509 trespasser strike. Follow 509 Control Point, pacific
518	VAC	42	MBO	33	MBO	33	XF2-X1J	BN	For maritime traffic Bridge, Fraser River Br

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
11	LAX	83	PTI	57	MBO	39	DAV-MTZ	UP	For maritime traffic Bridge, Suisun Bay
14	SEA	180	POL	90	POL	67	TAC-TAC	ST	RR blocked by trespasser or vehicle strike by another train Hold at TAC due to trespasser strike
8	CHI	17	FTI	154	DCS	45	FAR-DLK	BN	Restrictive signal(s) from known wayside signal failure Directed to hand line turnout switch, but then ok'd to back up behind signal after signal maintainers fixed it, Red/Stop, Control Point, Moorhead Jct
28	SPK	31	FTI	55	FTI	40	PSC-XPW	BN	Follow BN 7021, Control Point, Pasco East, Siding, Eltopia
821	FTW	71	DSR	56	DSR	35	GLE-FTW	BN	Per bulletin Milepost, 406.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 407.9, 407.1, 30, m, Milepost, 405.9, 405, 60, m, Milepost, 404.2, 403.8, 60, m, Milepost, 403.2, 402.7, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.5, 400.1, 60, m, Milepost, 399.9, 399.2, 60, m, Milepost, 39
822	OKC	32	DSR	32	DSR	26	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 355.5, 355.9, 50, 1, Milepost, 376.9, 377.1, 25, M, Milepost, 379.5, 380.8, 40, M, Milepost, 381.7, 383.1, 40, M, Milepost, 382.5, 382.7, 30, M, Milepost, 383.2, 383.4, 30, M, Milepost, 383.4, 384.2, 25, M, Milepost
350	PNT	23	RTE	31	RTE	31	DOA-KAL	AM	Line manual or spring switch Manually line switch @171, Control Point, 171
354	PNT	17	FTI	30	FTI	26	X1W-DET	CC	Cross Traffic CN508, Control Point, Vinewood
562	SAN	31	CTI	28	CTI	10	SOL-OLT	SN	Meet coaster, 625, Control Point, delmar
581	LAX	35	DCS	36	DCS	31	ANA-XFT	BN	Power switch failure Control Point, ful jct
584	SAN	39	CTI	45	CTI	14	OSD-SOL	SN	Follow Coaster, 648, Control Point, Longboard
769	GTA	25	CTI	10	CTI	8	VNC-CWT	SC	Meet Metrolink, 110, Control Point, Raymer
774	SAN	25	DCS	30	CTI	8	OSD-SOL	SN	Meet nctc, 635, Control Point, ponto
777	SLO	43	PTI	35	PTI	28	X3G-LPS	UP	Meet A11, Control Point, North Gaviota
782	SAN	30	PTI	57	PTI	33	CPN-VEC	UP	Meet 14, 769, Control Point, S SEACLIFF
785	GTA	28	PTI	25	PTI	15	CML-OXN	UP	Meet 794, Control Point, S. Oxnard
712	BFD	35	FTI	35	FTI	31	SKN-SKN	BN	Waiting for Freight trains to clear ahead going into Mormon yard. 6363, Control Point, Keddie Jct

Amtrak Endpoint OTP Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
716	BFD	72	PTI	20	FTI	18	HNF-COC	BN	Meet bnsf 3898, Control Point, calabrese
1	LAX	194	TRS	243	TRS	236	XAS-XHT	UP	Trespasser strike Control Point, CPSA214
21	SAS	73	FTI	156	DMW	35	CBR-MCG	BN	Held for track inspector inspecting track ahead of train. Siding, Blum
22	CHI	389	CON	144	CON	144	SAS-SAS	UP	Hold for connecting train 2
307	STL	37	FTI	31	PTI	24	PON-BNL	UP	Meet AMT306, Other, BALLARD
392	CHI	28	FTI	33	FTI	16	MAT-CHM	CC	Meet M 271, Control Point, N Tuscola
393	CDL	50	CTI	14	CTI	14	XCS-HMW	CC	Cross Traffic Metra, southshore, Control Point, kensington
318	CHI	32	PTI	62	PTI	21	PON-DWT	UP	Meet Held here to give amtk22 a running gap between us and them, amtk305, Siding, odell
319	KCY	26	DSR	20	PTI	10	JEF-SED	UP	Meet 316, Siding, shell
1340	CHI	80	FTI	83	FTI	63	MSP-XH8	CP	Meet Brought 445 out of the yard in front of us. Then held them due to “Emergency Services” at 7th street, blocking us in with the Westbound freight stopped in front of us., CP445 (CP 8174), Control Point, Division St.

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/5/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	230	10/05	23	23	Late departure at initial terminal due to late arrival of inbound equipment 245
ALB	240	10/05	10	10	Fire department hold Fire alarm in ALB train station. Held to finish boarding after the Fire Department cleared the station.
BOS	175	10/05	11	11	Late departure at initial terminal due to late arrival of inbound equipment, 170, late turn of AM170
CLT	78	10/05	94	94	Late departure at initial terminal due to late arrival of inbound equipment 77
GFD	479	10/05	38		
HAR	654	10/05	2	2	Scheduled wyeing of the train
LOR	53	10/05	63	63	Drumac did not have enough drivers
MIA	40	10/05	6	6	Onboard HBD alarm 324, Bad HBD sponsor
NFK	138	10/05	2	2	Restrictive signal(s) from unknown cause Stop, Control Point, bridge 5
NFL	280	10/05	38	38	PTC - On Board Cab Signal or PTC Failure GPS signal not being picked up by PTC at mechanical facility, needed to bring it to NFL station in restricted mode and reset everything once at the NFL station, 9702
NHV	474	10/05	60	60	Air / Brake, 120|DX|BD, due to the brake issue on E/120
NHV	486	10/05	97	97	Air / Brake, 120|DX|BD, AM486 departed late a/c brake issues on E/120, had to swap equipment with AM474
NYP	63	10/05	2	2	Passenger and/or baggage, BOARDING
NYP	97	10/05	5	5	Passenger and/or baggage, LOADING
NYP	113	10/05	34	34	HEP, 606|EX|ES, LATE F/SSYD A/C UNSPECIFIED MECHANICAL ISSUES
NYP	119	10/05	25	25	Hold for defect repair, Other, NYP, LATE TURN OFF AM112 A/C BROKEN RAIL IN NORTH TUBE
NYP	131	10/05	21	21	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING WITH ONLY 1 ENGINE
NYP	183	10/05	25	25	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
NYP	185	10/05	42	42	Hold for defect repair, Other, NYP, LATE TURN OFF AM110 A/C BROKEN RAIL IN NORTH TUBE
NYP	239	10/05	45	45	Late departure at initial terminal due to late arrival of inbound equipment, 290, LATE TURN OFF AM290
NYP	241	10/05	4	4	Late departure at initial terminal due to late arrival of inbound equipment, 280, LATE TURN OFF AM280
NYP	243	10/05	11	11	T.O.L, Other, J.O, CONGESTION AT J.O DUE TO T.O.L
NYP	291	10/05	10	10	Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/5/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	639	10/05	57	57	T.O.L, Other, J.O., CONGESTION AT J.O A/C T.OL
NYP	641	10/05	31	31	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
NYP	643	10/05	39	39	Hold for defect repair, Other, NYP, LATE TURN OFF AM640 A/C BROKEN RAIL IN NORTH TUBE
NYP	645	10/05	20	20	Hold for defect repair, Other, NYP, LATE TURN OFF AM644 A/C BROKEN RAIL IN NORTH TUBE
NYP	2107	10/05	12	12	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING A/C BROKEN RAIL IN NORTH TUBE
NYP	2109	10/05	26	26	Hold for defect repair, Other, NYP, HELD SINGLE TRACKING DUE TO BROKEN RAIL IN NORTH TUBE
NYP	2113	10/05	7	7	Hold for defect repair, Other, NYP, LATE TURN OFF AM2102 A/C BROKEN RAIL IN NORTH TUBE
PHL	151	10/05	3	3	PTC - Stop Bypass Permission Required, Control Point, PENN, STOP BYPASS PERMISSION COMING OFF OF 7 STATION TRACK
PHL	190	10/05	2	2	Passenger and/or baggage, LATE TRAVEL
SPG	125	10/05	6	6	Hold for connecting train, HELD FOR TRAIN 425 TO ARRIVE
SPG	417	10/05	19	19	Late departure at initial terminal due to late arrival of inbound equipment, 474, late turn of AM474
WAS	84	10/05	66	66	Disabled train ahead, Other, NYP, LATE REL OF 113 IN SSYD DUE TO UNKNOWN HEP ISSUES WITH MTR 606
WAS	136	10/05	7	7	Wheelchair, LATE ADA AT DEP TIME
WAS	174	10/05	2	2	Other electrical failure, 600|EX|ES, ENG- DOOR LIGHTS ON MTR 600, MTR WAS PUT IN BYPASS. ALL DOOR SECURED
WAS	198	10/05	28	28	Suspicious bag or bomb threat, LATE WYING EQUIPMENT DUE TO WAITING ON POLICE TO REMOVE UNATTENDED BAG
WAS	2118	10/05	8	8	Late departure at initial terminal due to late arrival of inbound equipment, 2155, LATE INBOUND 2155
CHI	48	10/05	40	40	Late departure at initial terminal due to late arrival of inbound equipment 40, Swapped equipment
CHI	393	10/05	1		
QCY	382	10/05	1	1	Mobility Impaired Unannounced wheel chair lift. PNR# 08F068 Andrus, Mary
BFD	703	10/05	5	5	Hold for thruway bus
BFD	711	10/05	6	6	Door C9301, Door closed but no door light. Engineer had to bypass.
BFD	713	10/05	7	7	Door C9809, Door switch lock error
GTA	782	10/05	5	5	Wait for station track 765, Control Point, S ELLWOOD

Amtrak Initial Terminal Details

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/5/2026

Terminal	Train	Date	Late	Delay	Cause
LAX	14	10/05	69	69	Late departure at initial terminal due to late arrival of inbound equipment 11, Departed at 11:00 as instructed, due to the service disruption text which was set to the pax.
LAX	562	10/05	7	7	Late release for swap C2116
OKJ	536	10/05	1		
OKJ	712	10/05	4	4	Wait for station track Late departure due train congestion and waited for a station track. Train 11, Train 529 and Train 528., 528, Other, Oakland Station
OKJ	716	10/05	(Trn Cxld)		Third Party Car Failure
SAC	523	10/05	3	2	Fuel
SAC	539	10/05	1	1	Wch lifts not working . Deployed the ramp from cafe car. C8804, C8205, C8026, C8009, C6964
SAN	567	10/05	5	5	Air / Brake / Wheel 6908, Hand brake stuck! Mechanical worked on it and finally got it released
SAN	581	10/05	2	2	Loading problem C2114
SEA	503	10/05	14	14	No ditch lights 90230

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	99.2	94.8	342	2
CDOT	95.0	58.3	79.2	92.4	24	10
MARC	95.0	93.0	78.8	90.2	57	4
SEPTA	95.0	87.4	88.5	91.5	214	27
NJT-NED	95.0	72.3	86.4	88.6	321	89
NJT-SED	95.0	100.0	98.3	97.2	24	0

Operating Highlights

Train 52(05) - South of Florence, SC - Freight Train Interference

06OCT26: Train 52(05) was delayed on the CSX Charleston Subdivision between MP 387 and MP 348 due to following CSX Train M410-05.

Train	Delay	Comment
52(05)	1'07"	

Train 125(05) - Williamsburg, VA - Engine Failure

05OCT26: Train 125(05) stopped at MP 39.3 on the CSX Peninsula Subdivision due to a hydrostatic oil leak and smokey conditions in the engine compartment. The engine shut down. HEP was dropped immediately. Amtrak Mechanical personnel and field management responded to the scene.
The train was terminated at its location. The host railroad sent CSXT 7084 to be used as a rescue motor. Once coupled to the disabled set, the set was pulled into Newport News with no HEP.
Service recovery was initiated with complimentary snacks and beverages.
Due to the status of Engine 371, Train 86(06) was cancelled NPN-WAS. No alternate transportation was provided.

Train	Delay	Comment
86(06)	Orig WAS	
125(05)	4'18"	

Train 2131(05) - East of Princeton Junction, NJ - Engine Failure

05OCT26: Train 2131(05) stopped at MP 40.4 due to a broken pantograph alarm. After inspection, the crew discovered the pantograph on the lead power car 2145 was broken. HEP was down until the crew managed to raise the pantograph on the rear power car 2148. Due to the condition of the broken pantograph and the location, Train 2131(05) was terminated at the scene. All 228 passengers were transferred to Train 657(05).
Train 175(05) was held at 30th Street Station in Philadelphia for those passengers ticketed for travel south of Philadelphia into Washington Union Terminal.

Train	Delay	Comment
657(05)	45"	
2131(05)	Terminated - MP 40.4	

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Guilford, CT - Switch Failure

05OCT26: The No. 21 switch on the East end of Guilford Interlocking/MP 90.4 on the Amtrak New Haven to Boston Line fell out of correspondence. Amtrak C&S personnel responded. The issue could not be resolved immediately. The switch was spiked and wedged and trains were permitted over at restricted speed.
The multiple attempts to rectify the issue and ensuing congestion on either side of the interlocking caused multiple Amtrak and CDOT trains to incur delay.

Train	Delay	Comment
184(05)	50"	
2160(05)	20"	
177(05)	1'46"	
94(05)	20"	
2193(05)	1'46"	
67(05)	49"	
178(05)	14"	held at NHV for recrew off 177(05)

Train 77(05) - West of Burlington, NC - M of W Work

05OCT26: Train 77(05) was delayed on the Norfolk Southern NC Line Subdivision at MP 10.1 due to late working/clearing MW work.
Train 78(05) was an initial terminal delay due to turning off the 77(05) equipment.

Train	Delay	Comment
77(05)	1'52"	MP 10.1
78(05)	1'34"	

Train 40(05) Tampa, FL - Hot Bearing Alarm/Car Failure

05OCT26: Train 40(05) with E/324, E/320 and 10 cars was delayed on the CSX Tampa Terminal A at MP 881.9 Tampa station due to a hot bearing alarm in the engine. The crew inspected the consist and took no exceptions.
Train 40(05) stopped again shortly after departing Tampa Station for a reoccurrence of the same alarm. The crew again inspected the consist using tempilstiks and did a roll by inspection. No exceptions were taken.

Train	Delay	Comment
40(05)	1'31"	

Train 53(05) Lorton, VA - Servicing

05OCT26: Train 53(05) was delayed departing Lorton due to Drummac being short staffed which delayed loading of the vehicles.

Train	Delay	Comment
53(05)	1'03"	

Train 486(05) New Haven, CT - Engine Failure

05OCT26: Train 486(05) with E/120, CC/9635 was delayed departing New Haven due to having brake issues and New Haven mechanical was on scene assisting. It was determined the equipment would go back to the yard and be swapped out with 474(05).

This also caused delay to train 474(05) due to making repairs to the equipment.

Train	Delay	Comment
486(05)	1'37"	
479(05)	38"	

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train 645(05) Philadelphia, PA - Cab Car Failure

05OCT26: Train 645(05) with CC/9645 E/620 and Empty cars was delayed in Philadelphia due to having cab signal/PTC failure on CC/9645. It was determined to wye upon departure.

Train	Delay	Comment
645(05)	35"	wying
645(05)	10"	PHL

New York to Philadelphia Main Line - Bridge Strike

05OCT26: At 244P-ET A vehicle struck the bridge at Suydam Ave., MP 31.80, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 330P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
2158(05)	07"	
2163(05)	10"	
650(05)	04"	
93(05)	06"	
647(05)	13"	
84(05)	08	
134(05)	05"	
97(05)	08"	

Train 290(05) South of Saratoga Springs, NY - Down Tree/Debris

05OCT26: Train 290(05) was delayed on the NS Freight 72HA at MP 484.8 due to a down tree ahead on CPKC Canadian subdivision at CP 160. CPKC estimated 30 minutes for the M/W crew to arrive and remove the tree.

Train	Delay	Comment
290(05)	1'45"	

New York to Philadelphia Main Line - Bridge Strike

05OCT26: At 1216P-ET A vehicle struck the bridge at Handy St., MP 31.90, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1247P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
125(05)	10"	
2108(05)	12"	
2115(05)	13"	
182(05)	12"	
119(05)	12"	

New Haven to Boston Main Line - Bridge Strike

05OCT26: At 1123A-ET A vehicle struck the bridge at Walbach St., MP 122.03, New Haven to Boston main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1242P-ET, the bridge was inspected and track 2 was released for normal service. As of 1246P-ET, Track 1 was taken out of service to repair the damage.

Train	Delay	Comment
2163(05)	03"	
85(05)	06"	
2165(05)	24"	

27-FOI-00046 | 000000098954 | "UNCLASSIFIED" | 10/19/2026

Train 53(04) South of DeLand, FL - Commuter Train Interference

05OCT26: Train 53(04) with E/364, E/354 and 15 cars was delayed on the CSX Orlando A subdivision due to meeting CFRC P310, P312 and P314.

Train	Delay	Comment
53(04)	43"	

Train 67(04) South of Fredericksburg, VA - Freight Train Interference

05OCT26: Train 67(04) with E/346 and 5 cars was delayed on the CSX RF&P subdivision due to the CSX I135-05 swapping out the EOT device with a local.

Train	Delay	Comment
67(04)	46"	

Train 41(04) South of Connellsville, PA - Freight Train Interference

05OCT26: Train 41(04) E/111, E/37 and 10 cars was delayed on the CSX Keystone BF MP 211.1 due meeting disabled CSX M225-04. They were further delayed following CSX 1836 then being held by dispatcher due to freight congestion down the mountain.

Train 41(04) was further delayed on the CSX Cumberland BA due to following CSX M405-05 and M415-05.

Train	Delay	Comment
41(04)	1'44"	
41(04)	31"	

North Tube - New York, NY -Broken Rail/ M of W Work

05OCT26: At 704A-ET, C&S reported a broken rail in the North Tube at MP 3.15. NJT 3217 was held in the North Tube and was reverse back into New York. New York expected delays between 30-40 minutes.

As of 1030A-ET, New York reported that they were still single tracking and expected delays to be 60 minutes. As of 1045A-ET, North Tube was returned to service with no restrictions.

Train	Delay	Comment
190(05)	25"	
641(05)	31"	
2107(05)	12"	
2150(05)	36"	
2109(05)	26"	
110(05)	44"	
170(05)	1'07"	
113(05)	12"	
141(05)	18"	
185(05)	43"	
643(05)	40"	
2113(05)	07"	
119(05)	25"	late turn off 130(05)
130(05)	57"	
2154(05)	19"	
172(05)	13"	
600(05)	54"	
2104(05)	33"	
642(05)	36"	
2152(05)	24"	
183(05)	25"	
131(05)	21"	
95(05)	30"	
645(05)	20"	late turn off 644(05)
175(05)	11"	late turn off 170(05)

27-FOI-00046 0000000008954 "UNCLASSIFIED" 10/19/2026

Train 181(05) South of Philadelphia, PA -Inverted Pantograph/ Engine Failure

05OCT26: Train 181(05) with E/602, E/602 and 9 cars, was stopped south of Philadelphia on the Philadelphia to Washington main line at MP 5.2 due to an inverted pantograph on rear engine E/602. The crew will remove E/602, and Train 181(05) will proceed south with 347 customers onboard. Once the inverted pantograph is secured, the Philadelphia protect diesel will return E/602 to Philadelphia.

Train 181(05) was back on the move after rear engine E/602 was removed from the consist. ET was enroute, and rescue equipment departed Philadelphia to recover E/602. Train 181(05) is currently operating 49 minutes late.

As of 840A-ET, ET arrived at E/602.

Train	Delay	Comment
181(05)	49"	

Train 113(05) New York, NY - Engine Failure

05OCT26: Train 113(05) with E/606, E/636 and 10 cars was delayed departing New York due to having mechanical issues with E/606 prior to departing the yard.

This also caused train 84905) to be delayed departing Washington due to the late arrival of 113(05).

Train	Delay	Comment
113(05)	34"	

Train 280(05) - Niagara Falls, NY - Initial Terminal Delay

05OCT26: Train 280(05) was delayed at its initial terminal at Niagara Falls, NY Station/MP 28.4 on the CSX Niagara Subdivision due to PTC failure. The crew consulted with the host's railroad PTC Desk and NFL Mechanical Personnel. The crew was able to get the train out of the yard and into the station, but had to attempt a hard reset to gain full functionality of the PTC system.

They were further delayed on the CSX Buffalo Terminal QC at MP QC396.1 due to losing GPS signal around MP QC402.0 the crew contacted the dispatcher and rebooted the system again.

The conductor reported upon arrival into Rome station they were having PTC issues again. The dispatcher instructed them to cut out PTC and continue operating at restricted speed into Albany.

Train	Delay	Comment
280(05)	38"	
280(05)	37"	MP QC396.1
280(05)	11"	ROM
280(05)	21"	ROM-ALB

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

27-FOU00046 00000098854 "UNCLASSIFIED" 10/19/2026

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
125(5)	WBG	XCSXT7084	E/371 hydrostatic oil leak	NPN	10/6/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				
40(3)	CLB	1	CAM	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train 518(05) South of Vancouver, BC - Drawbridge Opening

05OCT26: Train 518(05) with 64 customers was delayed on the CN New Westminster subdivision at the Fraser River Bridge/MP 143.4 due to holding for maritime traffic.

Train	Delay	Comment
518(05)	33"	

Train 48/448(05) - Late Inbound Equipment

05OCT26: Train 48/448(05), with 211 customers to board, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late turn of inbound equipment. Due to the late operation of train 40(03), the equipment for train 49(04) turned for train 41(05). Train 40(03) arrived in Chicago 8 hours and 46 minutes late. That equipment turned for train 48(05). Once the trainset was made up complete, train 48/448(05) shoved into the depot, boarded customers, and departed Chicago Union Station.

Train	Delay	Comment
48/448(05)	40"	

Train 509(05) North of Tacoma, WA - Trespasser Incident

05OCT26: Train 509(05) with C/90253, three cars, WS/1406, and 108 customers was delayed on the BNSF Seattle subdivision due to striking a trespasser on an overpass going over Highway 410 at MP 29.4 located in Sumner, Washington and in Pierce County. There were no reported injuries to the customers or crew and the train maintained head end power. Local authorities responded to the scene for an investigation. The trespasser was located beneath the overpass on Highway 410 and was fatally wounded. The Pierce County coroner and Amtrak trainmaster responded to the scene. The crew requested and was granted relief. The relief engineer and conductor arrived on scene and once the tracks were released train movement continued. Train 14(04) was delayed holding at Tacoma/MP 1.9. Train 506(05) was delayed holding at Manitou/MP 7.0. Train 511(05) was delayed holding at Ellingson/MP 23.8. Train 508(05) was delayed holding at Nisqually/MP 24.5.

Once the tracks were clear, BNSF advised that a vehicle was stuck on the tracks of the Seattle subdivision 10 miles north of Tacoma on main track one at MP 30.8. Trains 14(04), 506(05), and 508(05) were further delayed holding for the vehicle to be removed and the tracks inspected.

National Response Center Number: 1475429

Train	Delay	Comment
509(05)	2'52"	
14(04)	2'09"	
506(05)	1'48"	
508(05)	20"	
511(05)	1'06"	

Train 1(05) East of San Antonio, TX - Engine Failure

05OCT26: Train 1(05), with engines 349 and 114, 7 cars, and 89 customers onboard, stopped mile post 155.8 in Luling, TX, 55 miles east of San Antonio, TX/MP209.5, on the UP Glidden subdivision due to the lead engine 349 shutting down. HEP was down. The crew investigated with CNOC Mechanical Desk and Siemens Desk by phone and determined engine 349 had a redundant I/O 41 fault. The engine was restarted so that the system failed over to a backup I/O module. HEP was down approximately 28 minutes.

Train	Delay	Comment
1(05)	40"	

Train 25(05) North of New Orleans, LA - Freight Train Interference

05OCT26: Train 25(05), with 28 customers onboard, was delayed at Paris Rd/MP5.9, 5.9 miles north of New Orleans, LA/MP0.0, on the NS New Orleans subdivision meeting freight. Once the route was clear, train 25(05) continued south.

Train	Delay	Comment
25(05)	33"	

Train 581(05) East of Fullerton, CA - Signal

05OCT26: Train 581(05) with 136 customers was delayed on the SCRRA Orange subdivision just east of Fullerton due to switch issues at Fullerton Jct./MP 165.5.

Train	Delay	Comment
581(05)	31"	

Train 3(05) East of Fort Madison, IA - Freight Train Interference

05OCT26: Train 3(05), with 253 customers onboard, was delayed between mile post 225.1 and Niota/MP230.7, beginning 7.5 miles east of Fort Madison, IA/MP232.9, on the BNSF Chillicothe subdivision following freight. Once the route was clear, train 3(05) continued west.

Train	Delay	Comment
3(05)	33"	

Train 21/421(04) South of Cleburne, TX - M of W Work

05OCT26: Train 21/421(04) was delayed at Blum/MP304.7, 12 miles south of Cleburne, TX, on the BNSF Fort Worth Subdivision, due to MW working ahead.

Train	Delay	Comment
21/421(04)	35"	

Train 716(05) Oakland, CA - Third Party Contractor Car Failure

05OCT26: Train 716(05) with C/8308, seven cars, and C/2106 originated at Emeryville due to door sensor issues. TASI worked to rectify the issue and once the equipment was released and set in the station, all customers were welcomed aboard, and 716(05) departed Emeryville at 327PM-PT, 59 minutes late. Customers traveling between Oakland and Emeryville were accommodated on train 536(05).

Train	Delay	Comment
716(05)	59"	Orig EMY

27-FDI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train 1(05) East of Houston, TX - Freight Train Interference

05OCT26: Train 1(05), with 82 customers onboard, was delayed at Dayton siding/MP329.3, 33 miles east of Houston, TX/MP362.3, on the UP Houston subdivision meeting BNSF 5486. Once the route was clear, train 1(05) continued west.

Train	Delay	Comment
1(05)	48"	

Train 782(05) North of Ventura, CA - Passenger Train Interference

05OCT26: Train 782(05) with 101 customers was delayed on the UPRR Santa Barbara subdivision nine miles north of Ventura due to meeting train 14(05) at Seacliff/MP 386.3.

Train	Delay	Comment
782(05)	33"	

Train 22(05) North of Temple, TX - Temporary Speed Restrictions

05OCT26: Train 22(05), with 145 customers, was delayed north of Temple, TX/MP218, on the BNSF Fort Worth Subdivision, due to temporary speed restrictions in effect between MP220 and MP239.5. Train 22(05) was delayed operating through the affected area.

Train	Delay	Comment
22(05)	40"	

Train 712(05) Stockton, CA - Third Party Contractor Engine Failure

05OCT26: Train 712(05), with 155 customers, was delayed at Stockton, CA, on the BNSF Stockton Subdivision due to a momentary loss of HEP. The engineer reset the locomotive, and HEP was successfully restored. Train 712(05) was additionally delayed departing Stockton due to a disabled freight train ahead at Keddie Jct., MP 1120.3. Once the freight train cleared, Train 712(05) was authorized to resume operations.

Train	Delay	Comment
712(05)	31"	

Train 821(05) South of Ardmore, OK - Engine

05OCT26: Train 821(05), E/135-2 cars-E/203, with 87 customers, was delayed enroute south of Ardmore, OK/MP450.5, on the BNSF Red Rock Subdivision, due to E/135 PTC issues syncing and disengaging. Train 821(05) contacted PTC desk while stopped at the Gainesville, TX station stop/MP410.78, on the BNSF Fort Worth Subdivision, to troubleshoot issues. Train 821(05) was further delayed south of Gainesville due to E/135 PTC held at restricting to the next signal.

Train	Delay	Comment
821(05)	09"	S/ADM
821(05)	09"	GLE
821(05)	20"	S/GLE

Train 4(04) East of Albuquerque, NM - Commuter Train Interference

05OCT26: Train 4(04) with 170 customers was delayed 17 miles east of Albuquerque on the NMRX Albuquerque subdivision due to meeting NMRX at East Bernalillo/MP 885.25.

Train	Delay	Comment

27-FOI-00046 000000008954 "UNCLASSIFIED" 10/19/2026

Train 20(05) North of Meridian, MS - Freight Train Interference

05OCT26: Train 20(05) with 110 customers aboard was delayed between Meridian Station/MP295.0 and Toomsuba siding/MP282.2 on the NS AGS District subdivision following NS freight NS130. Once the route was clear, train 20(05) continued north.

Train 20(05) was further delayed at the crossing at Tuscaloosa/MP198.4 due to a vehicle on the tracks. Train 20(05) continued north once the route was clear.

Train 19(04) was delayed at Eutaw/MP232.5 meeting Amtrak train 20(05).

Train	Delay	Comment
20(05)	10"	Vehicle on the tracks
19(04)	37"	Meet 20(05)
20(05)	30"	Follow NS130

Train 1340(05) East of St. Paul-Minneapolis, MN - Freight Train Interference

05OCT26: Train 1340(05), with 192 customers, was delayed just east of St. Paul-Minneapolis, MN/MP409.6, on the CPKC Meriam Park Subdivision, due to westbound CPKC 445 (CP8174) blocking route ahead and then local police placed a hold on traffic due to a body found on/near the right of way. Once the police hold was released and the westbound freight cleared, Train 1340(05) was able to proceed east. Train 1340(05) was further delayed enroute following eastbound CPKC freight traffic, CPKC 448 and CPKC 248.

Due to the late operation of Train 1340(05), the following Hiawatha Service adjustment was in effect:
- Train 341(05) was cancelled, with on time alternate transportation. Two busses were secured and operated between Chicago, IL and Milwaukee, WI.

Late Train 1340(05) equipment was serviced in Chicago and then operated deadhead to Milwaukee to be in position for AM service 06OCT.

WBS#: B.TR.100150.7245

Train	Delay	Comment
1340(05)	1'03"	E/MSP
1340(05)	20"	E/MSP, follow CP448 & CP248
341(05)	Cancelled	

Train 5(03) West of Winnemucca, NV - Freight Train Interference

05OCT26: Train 5(03) was delayed 33 miles west of Winnemucca, NV, on the UPRR Nevada Subdivision due to freight train UP7399 going into emergency near Humboldt Siding at MP 382.6. Once UP7399 was repaired and cleared the area, Train 5(03) was able to proceed to its destination.

Train	Delay	Comment
5(03)	1'25"	

Train 11(04) East of Martinez, CA - Drawbridge Opening

05OCT26: Train 11(04) was delayed at Benicia, MP 35.3 on the UPRR Martinez Subdivision, 3 miles east of Martinez, CA, waiting for maritime traffic. Once the vessels had cleared, train 11(04) continued to Martinez at track speed.

Train	Delay	Comment
11(04)	39"	

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train 4(04) Flagstaff, AZ - Freight Train Interference

05OCT26: Train 4(04), with 155 customers, was delayed 41 miles east of Flagstaff, AZ, on the BNSF Seligman Subdivision due to BNSF freight interference between MP 340.8 and MP 288.4.

Train	Delay	Comment
4(04)	39"	

Train 40(03) West of Pittsburgh, PA - Freight Train Interference

05OCT26: Train 40(03), with 96 customers, was delayed beginning 40 miles west of Pittsburgh, PA, on the NS Conway West Subdivision, following NS 171 between MP40 and MP73.

Train	Delay	Comment
40(03)	35"	

Train 350(05) East of Dowagiac, MI - Switch Failure

05OCT26: Train 350(05), with 201 customers, was delayed at MP171.6, 8 miles east of Dowagiac, MI, on the Amtrak Michigan Line, due to switch failure ahead at the No 1 Switch at CP-171. Maintainer responded to scene and okayed switch for movement.

Train	Delay	Comment
350(05)	31"	

Train 3(04) West of Fort Madison, IA - Freight Train Interference

05OCT26: Train 3(04), with 252 customers, was delayed west of Fort Madison, IA/MP232.9, on the BNSF Marceline Subdivision, following BNSF 8164 between Fort Madison and Marceline/MP346.9.

Train	Delay	Comment
3(04)	1'50"	

Train 8/28(03) East of Fargo, ND - Signal Issues

05OCT26: Train 8/28(03) was delayed at Moorhead Jct/MP5.8, 3 miles east of Fargo, ND, on the BNSF KO Subdivision, due to signal issues. Train 8/28(03) was delayed holding signal maintainer to resolve issues and then delayed operating through the affected area.

Train	Delay	Comment
8/28(03)	45"	

Train 22(04)/422(02) North of Marshall, TX - Freight Train Interference

05OCT26: Train 22(04)/422(02), with 143 customers, was delayed north of Marshall, TX/MP66.5, on the UPRR Little Rock Subdivision, following non-fitter UP3064 between Marshall and Sulphur/MP6.8.

Train	Delay	Comment
22(04)/422(02)	1'25"	

Train 5(30) East Omaha, NE - Tornado Warnings Downed Trees Washout BNSF Hastings sub

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

01OCT26: Due to a weather-related washout on the BNSF Hastings Subdivision between MP 64 and MP 65, 6(29) and 5(30) experienced significant delays. BNSF established a detour through Cobb Yard between Hall and Lincoln, requiring pilot crews to guide both trains through the affected area. 6(29), carrying 139 customers, was initially delayed 2 hours and 45 minutes and later held near MP 68.1 while awaiting pilots, whose arrival was delayed by flooded roadways.

5(30), carrying 183 customers, was additionally delayed west of Omaha when a tree blocked the tracks near MP 39. After BNSF crews removed the tree and inspected the track, the train was recrewed and proceeded to Lincoln, where pilots boarded for the detour route. The same pilots and relief crew later transferred to 6(29) to assist it through the washout area. 6(29) subsequently arrived at Lincoln, was recrewed, resolved a PTC issue, and continued west.

Later, 5(30) encountered a second tree obstruction west of Lincoln near MP 69.7, resulting in another delay of approximately two hours while BNSF crews cleared and inspected the track. The train resumed operation under weather-related speed restrictions but was projected to exceed Hours of Service limits. A relief crew was dispatched from Denver, and 5(30) departed Hastings at 3:39 p.m. CT operating 13 hours and 17 minutes late before proceeding to Kenesaw Siding to await the recrew. Train 5(30) was back on the move at 736PM CT with the re-crew on duty. Train 5(30) was delayed at McCook NE completing daily inspections.

As a result of the washout, multiple weather-related track obstructions, speed restrictions, and crew shortages, both 6(29) and 5(30) incurred substantial delays throughout the territory. The service disruptions also resulted in the cancellation of 6(3) and 5(5), with no alternate transportation provided.

02OCT26: Tracks open at the scene of the washout at 1230AM CT.

Train	Delay	Comment
5(30)	33"	Flash Flood warnings
5(30)	4'06"	Downed Trees
5(30)	3'47"	Re-crew
5(30)	45"	Daily Inspections MCK
5(05)	Cancelled	
6(03)	Cancelled	
5(30)	28"	LNK Routing
6(29)	7'20"	Holding W/LNK

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	

Maintenance of Way Highlights

87-FOI-00046 00000908854 "UNCLASSIFIED" 10/19/2026

BNSF Fort Worth Subdivision Track Work - Texas Eagle Service TW 27-007

05OCT26: BNSF will perform tie replacement work on the Fort Worth Subdivision north of Temple, TX/MP218.2, between MP230 and MP245 beginning Monday October 5th through Friday October 9th. The work curfew will be from 630AM until 1230PM on the scheduled work days. To accommodate this infrastructure work, Amtrak's Texas Eagle Service will be adjusted as follows:

- Train 22(05-09) will depart San Antonio, TX, 59 minutes later, depart Fort Worth, TX, 30 minutes later and resume normal schedule upon departure from Dallas, TX.
- Train 422(04, 07) will depart San Antonio, 59 minutes later, depart Fort Worth 30 minutes later and resume normal schedule upon departure from Dallas.

WBS#: B.TR.100150.7225

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

27-FOI-00046 000000089554 "UNCLASSIFIED" 10/19/2026

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gang will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

27-FOI-00048 0000008954 "UNCLASSIFIED" 10/19/2026

16MAY26: Metra has track work scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
11(3)	KEL	BNSF3880	E/355 high voltage fault	LAX	10/5/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 59(04) Passenger Removal at McComb, Mississippi – Improper Conduct

05OCT26, Passenger on PNR 2B75CC, traveling from Chicago, IL to New Orleans, LA was reportedly removed by local police due to using offensive language and disturbing other passengers. Amtrak Police notified.
Delay: 59(04) 02"

Consist Deviations

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
572 (05)	LAX	no bike space or wifi	NONE	0	90215
757 (05)	LAX	no bike space or wifi	YES	2	90215
572 (05)	LAX	6 bv bike spaces and wifi	YES	1	6908
757 (05)	LAX	no bike space//no wifi	PASSENGERS NOTIFIED	0	90215
98 (05)	MIA	vi replaced with vii	YES	4	62508
98 (05)	MIA	vi replaced with vii	YES	2	62523
567 (05)	SAN	no bike space or wifi	NONE	0	90215
567 (05)	SAN	6 bv bike spaces and wifi	NONE	0	6908
765 (06)	SAN	no bike space or wifi	YES	3	90215
786 (05)	SLO	no bike space or wifi	YES	6	90215
786 (05)	SLO	no bike space//no wifi	NONE	0	90215
794 (06)	SLO	no bike space or wifi	YES	1	90215

Reverse Consists

Train Number	Station	Reason
173 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
95 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
93 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
190 (05)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
110 (05)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
138 (05)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
280 (05)	NFL	Consist reversed | Business class seat orientation may have changed | At Front
137 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front

27-FOI-00046 00000008954 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason
198 (05)	WAS	Consist reversed | Business class seat orientation may have changed | At Rear