

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, August 29, 2026

Rules: 3-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/28/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	35	89.2%	8,668	1,294	85.1%	99,612	13,846	86.1%
Central Division	86.0%	59	3	94.9%	1,593	186	88.3%	19,021	1,760	90.7%
East Division	82.0%	175	13	92.6%	4,673	659	85.9%	52,343	8,077	84.6%
West Division	86.0%	91	19	79.1%	2,402	449	81.3%	28,248	4,009	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00703 00000008730 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/28/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	109,250	26,215	76%	2,951,666	853,413	71%	33,284,664	8,494,763	74%
Northeast Corridor	81%	44,468	7,909	82%	1,282,959	305,358	76%	14,584,472	3,561,386	76%
Acela	83%	10,759	1,913	82%	274,239	52,517	81%	2,934,663	754,068	74%
Northeast Regional	79%	33,709	5,996	82%	1,008,720	252,841	75%	11,649,809	2,807,318	76%
Richmond / Newport News / Norfolk	77%	10,644	2,111	80%	311,325	103,353	67%	3,611,301	1,064,814	71%
Springfield Shuttles	89%	548	0	100%	17,417	3,035	83%	205,144	32,903	84%
Roanoke	79%	4,317	501	88%	100,822	27,409	73%	1,106,106	246,065	78%
On Spine Northeast Regional	80%	18,200	3,384	81%	579,156	119,044	79%	6,727,258	1,463,536	78%
State Supported	80%	53,298	10,948	79%	1,336,822	358,039	73%	14,646,441	3,163,964	78%
Borealis	80%	560	27	95%	16,593	4,157	75%	186,219	39,789	79%
Capitol Corridor	90%	4,166	1,268	70%	105,535	16,795	84%	1,221,254	162,544	87%
Carolinian	70%	1,572	507	68%	30,130	11,891	61%	375,012	146,890	61%
Cascades	75%	3,022	470	84%	59,823	23,820	60%	843,073	238,856	72%
Downeaster	82%	1,754	17	99%	54,635	5,809	89%	514,948	61,764	88%
Empire	78%	6,613	1,383	79%	179,265	61,287	66%	1,822,978	444,746	76%
Adirondack	72%	409	220	46%	12,808	5,756	55%	112,771	36,601	68%
Ethan Allen Express	70%	625	201	68%	16,394	10,498	36%	185,302	70,847	62%
Maple Leaf	70%	909	109	88%	25,686	11,895	54%	226,035	88,738	61%
New York - Albany	85%	2,346	56	98%	79,292	19,206	76%	841,640	145,133	83%
New York - Niagara Falls	75%	1,762	555	69%	40,973	11,392	72%	445,005	97,073	78%
Berkshire Flyer	60%	562	242	57%	4,112	2,540	38%	12,225	6,354	48%
Gold Runner	73%	2,294	1,911	17%	66,797	34,461	48%	822,363	304,914	63%
Heartland Flyer	70%	218	218	0%	6,186	4,269	31%	70,869	29,691	58%
Hiawatha	90%	2,268	0	100%	57,219	5,058	91%	578,138	62,755	89%
Illinois	78%	3,002	646	78%	73,514	26,793	64%	819,738	231,348	72%
Carl Sandburg / Illinois Zephyr	85%	467	112	76%	11,561	5,026	57%	136,361	39,184	71%
Illini / Saluki	85%	1,105	158	86%	23,264	8,514	63%	283,151	70,414	75%
Lincoln Service	70%	1,430	376	74%	38,689	13,253	66%	400,226	121,750	70%
Keystone	92%	9,435	136	99%	223,556	17,169	92%	2,505,675	256,715	90%
Lincoln / Missouri	70%	925	351	62%	22,989	15,946	31%	255,480	134,254	47%
Mardi Gras Service	80%	299	64	79%	8,453	1,996	76%	132,174	29,611	78%
Michigan	70%	3,263	1,361	58%	68,815	31,392	54%	666,240	223,813	66%
Blue Water	70%	972	338	65%	17,321	9,298	46%	156,979	65,126	59%
Pere Marquette	85%	408	0	100%	7,156	1,234	83%	85,590	16,358	81%
Wolverine	70%	1,883	1,023	46%	44,338	20,860	53%	423,671	142,329	66%
Missouri	80%	190	190	0%	6,882	4,216	39%	72,718	20,652	72%
Pacific Surfliner	85%	9,797	1,777	82%	267,911	69,494	74%	2,680,083	499,201	81%
Pennsylvanian	80%	987	198	80%	24,416	4,347	82%	290,218	55,424	81%
Piedmont	80%	1,539	424	72%	27,745	5,394	81%	368,019	94,046	74%
Vermont	75%	1,394	0	100%	36,358	13,745	62%	421,242	126,951	70%
Long Distance	70%	11,484	7,358	36%	331,885	190,016	43%	4,014,484	1,766,950	56%
Auto Train	70%	691	691	0%	23,544	6,782	71%	257,953	87,571	66%
California Zephyr	70%	875	282	68%	26,946	17,996	33%	318,540	124,653	61%
Cardinal	70%	260	154	41%	5,031	3,298	34%	76,512	38,841	49%
City Of New Orleans	75%	686	686	0%	16,267	13,226	19%	207,491	71,405	66%
Coast Starlight	70%	1,218	409	66%	28,956	12,527	57%	373,633	132,989	64%
Crescent	70%	843	350	58%	22,502	7,373	67%	302,155	93,356	69%
Empire Builder	70%	1,065	856	20%	29,481	17,364	41%	317,848	159,569	50%
Floridian	60%	673	436	35%	37,713	30,966	18%	515,479	358,008	31%
Lake Shore Ltd	73%	1,166	432	63%	32,168	11,649	64%	319,405	96,755	70%
Palmetto	70%	1,236	704	43%	24,534	11,531	53%	300,637	94,140	69%
Silver Meteor	70%	935	773	17%	26,671	16,657	38%	331,871	154,008	54%
Southwest Chief	60%	750	727	3%	24,550	19,535	20%	275,016	182,128	34%
Sunset Ltd	70%	269	266	1%	6,625	4,964	25%	94,991	37,732	60%
Texas Eagle	70%	817	592	28%	26,897	16,148	40%	322,953	135,795	58%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00700 00000000700 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 28, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	189,120	3,003,421	630	1,979,199	34,951,359	566

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	9,753	916,877	106	95,665	10,113,879	95
INFRASTRUCTURE PLANNED	135	17,928	916,877	196	113,983	10,113,879	113
FLEET RELIABILITY	90	30,504	3,003,421	102	316,644	34,951,359	91
TRAIN OPERATIONS	424	130,935	3,003,421	436	1,452,907	34,951,359	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/28/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	35	89.2%	8,668	1,294	85.1%	99,612	13,846	86.1%
Central Division	86.0%	59	3	94.9%	1,593	186	88.3%	19,021	1,760	90.7%
East Division	82.0%	175	13	92.6%	4,673	659	85.9%	52,343	8,077	84.6%
West Division	86.0%	91	19	79.1%	2,402	449	81.3%	28,248	4,009	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/28/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	35	89.2%	8,668	1,294	85.1%	99,612	13,846	86.1%
Central Division	86.0%	59	3	94.9%	1,593	186	88.3%	19,021	1,760	90.7%
CDL	95.0%	2	0	100.0%	54	6	88.9%	630	31	95.1%
CHI	86.0%	28	0	100.0%	740	122	83.5%	8,790	1,089	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	28	2	92.9%	355	38	89.3%
GBB	-	-	-	-	2	1	50.0%	15	12	20.0%
GRR	95.5%	1	0	100.0%	23	3	87.0%	311	11	96.5%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	55	9	83.6%	642	53	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	162	11	93.2%	1,942	125	93.6%
MOE	97.5%	2	0	100.0%	56	0	100.0%	661	9	98.6%
MSP	96.5%	1	0	100.0%	28	1	96.4%	325	7	97.8%
NOL	94.5%	4	0	100.0%	123	3	97.6%	1,396	63	95.5%
OKC	97.0%	1	0	100.0%	28	0	100.0%	326	6	98.2%
PNT	88.0%	3	1	66.7%	80	9	88.8%	867	73	91.6%
PTH	93.0%	1	0	100.0%	28	2	92.9%	320	13	95.9%
QCY	91.0%	2	0	100.0%	48	5	89.6%	625	48	92.3%
SAS	90.5%	1	1	0.0%	28	5	82.1%	329	38	88.4%
STL	89.0%	4	0	100.0%	109	6	94.5%	1,284	106	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	13	92.6%	4,673	659	85.9%	52,343	8,077	84.6%
ALB	88.5%	7	1	85.7%	211	11	94.8%	2,461	186	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	140	15	89.3%	1,606	173	89.2%
BOS	85.5%	18	1	94.4%	489	33	93.3%	5,652	637	88.7%
BRK	92.5%	5	0	100.0%	128	10	92.2%	1,580	112	92.9%
BTN	82.0%	-	-	-	26	1	96.2%	316	42	86.7%
CLT	91.5%	5	0	100.0%	140	15	89.3%	1,617	165	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	49	3	93.9%	642	60	90.7%
GRO	-	-	-	-	16	0	100.0%	49	10	79.6%
HAR	79.5%	13	0	100.0%	316	44	86.1%	3,680	592	83.9%
HFD	-	2	0	100.0%	39	4	89.7%	230	19	91.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	28	1	96.4%	328	39	88.1%
MIA	89.5%	2	0	100.0%	52	8	84.6%	652	76	88.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/28/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	35	89.2%	8,668	1,294	85.1%	99,612	13,846	86.1%
East Division	82.0%	175	13	92.6%	4,673	659	85.9%	52,343	8,077	84.6%
MTR	79.0%	1	0	100.0%	28	6	78.6%	315	58	81.6%
NFK	84.5%	2	2	0.0%	56	12	78.6%	739	135	81.7%
NFL	93.5%	2	0	100.0%	56	2	96.4%	668	31	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	0	100.0%	134	31	76.9%	1,688	284	83.2%
NPN	93.0%	2	0	100.0%	56	9	83.9%	628	50	92.0%
NYP	75.5%	51	3	94.1%	1,316	259	80.3%	13,800	3,037	78.0%
PGH	93.0%	1	0	100.0%	28	1	96.4%	329	23	93.0%
PHL	48.0%	5	1	80.0%	132	53	59.8%	1,682	793	52.9%
PIT	76.0%	1	0	100.0%	8	6	25.0%	23	18	21.7%
POR	-	-	-	-	12	7	41.7%	23	15	34.8%
RGH	95.0%	4	0	100.0%	96	5	94.8%	1,254	54	95.7%
RNK	83.5%	2	1	50.0%	56	5	91.1%	652	92	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	24	0	100.0%	311	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	1	1	0.0%	1	1	0.0%	3	3	0.0%
SAV	96.0%	1	0	100.0%	28	2	92.9%	325	12	96.3%
SFA	88.0%	1	1	0.0%	28	5	82.1%	328	46	86.0%
SPG	92.5%	4	0	100.0%	137	8	94.2%	1,944	113	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	28	3	89.3%	317	63	80.1%
WAS	84.0%	31	2	93.5%	815	99	87.9%	8,287	1,066	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	91	19	79.1%	2,402	449	81.3%	28,248	4,009	85.8%
ARN	92.0%	1	0	100.0%	28	2	92.9%	330	28	91.5%
BFD	79.0%	7	3	57.1%	195	50	74.4%	2,092	443	78.8%
EMY	72.0%	1	0	100.0%	28	5	82.1%	346	99	71.4%
EUG	86.5%	2	0	100.0%	56	3	94.6%	654	59	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	1	1	0.0%	3	1	66.7%	7	4	42.9%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	84	26	69.0%	993	169	83.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	2	81.8%	289	38	86.9%	3,288	364	88.9%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	12	5	58.3%	328	114	65.2%	3,589	942	73.8%
PDX	86.0%	4	1	75.0%	94	35	62.8%	1,582	216	86.3%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/28/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	35	89.2%	8,668	1,294	85.1%	99,612	13,846	86.1%
West Division	86.0%	91	19	79.1%	2,402	449	81.3%	28,248	4,009	85.8%
SAC	88.5%	16	3	81.3%	413	52	87.4%	4,679	514	89.0%
SAN	90.5%	13	1	92.3%	357	34	90.5%	3,998	378	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	152	40	73.7%	2,537	387	84.7%
SJC	89.0%	7	0	100.0%	195	18	90.8%	2,319	227	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	84	11	86.9%	756	76	89.9%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	13	4	69.2%	311	30	90.4%
VAC	97.0%	2	0	100.0%	56	0	100.0%	647	14	97.8%
VAN	-	-	-	-	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	54	12	2	83.3%	140	11	92.1%	11	9	18.2%	140	40	71.4%
2	No OS	12	5	58.3%	141	36	74.5%	12	5	58.3%	136	29	78.7%
3	38	28	7	75.0%	330	66	80.0%	27	20	25.9%	327	156	52.3%
4	64	28	6	78.6%	329	52	84.2%	28	20	28.6%	329	219	33.4%
5		28	6	78.6%	328	56	82.9%	28	21	25.0%	324	109	66.4%
6		28	5	82.1%	327	90	72.5%	28	20	28.6%	327	123	62.4%
7	49	28	8	71.4%	319	50	84.3%	27	11	59.3%	310	85	72.6%
8	130	28	16	42.9%	319	145	54.5%	28	21	25.0%	318	196	38.4%
11		28	15	46.4%	330	72	78.2%	28	7	75.0%	324	67	79.3%
14		28	5	82.1%	331	54	83.7%	27	12	55.6%	328	104	68.3%
19		28	6	78.6%	329	83	74.8%	28	9	67.9%	326	80	75.5%
20		28	0	100.0%	329	23	93.0%	28	7	75.0%	329	65	80.2%
21	No OS	28	10	64.3%	326	35	89.3%	28	15	46.4%	325	97	70.2%
22	51	28	5	82.1%	327	36	89.0%	28	16	42.9%	325	97	70.2%
23		28	0	100.0%	331	6	98.2%	28	5	82.1%	329	90	72.6%
24	18	28	0	100.0%	331	16	95.2%	28	9	67.9%	330	65	80.3%
25		28	0	100.0%	330	3	99.1%	27	11	59.3%	327	94	71.3%
26		28	0	100.0%	330	5	98.5%	27	4	85.2%	327	64	80.4%
28		9	3	66.7%	290	67	76.9%	10	4	60.0%	291	60	79.4%
40	134	24	6	75.0%	320	47	85.3%	23	17	26.1%	316	172	45.6%
42	22	28	1	96.4%	331	25	92.4%	28	6	78.6%	329	58	82.4%
43		28	3	89.3%	330	45	86.4%	28	5	82.1%	329	75	77.2%
48		28	5	82.1%	329	62	81.2%	28	8	71.4%	328	50	84.8%
49	37	28	9	67.9%	329	84	74.5%	28	7	75.0%	329	69	79.0%
50		10	3	70.0%	134	33	75.4%	9	7	22.2%	133	83	37.6%
52	87	28	5	82.1%	328	46	86.0%	28	3	89.3%	327	75	77.1%
53	161	28	1	96.4%	328	39	88.1%	28	10	64.3%	327	105	67.9%
55		20	2	90.0%	210	9	95.7%	20	8	60.0%	207	46	77.8%
56		20	2	90.0%	211	25	88.2%	20	6	70.0%	207	40	80.7%
58	69	27	1	96.3%	304	17	94.4%	26	23	11.5%	302	96	68.2%
59	33	28	17	39.3%	303	50	83.5%	27	23	14.8%	298	80	73.2%
63	47	28	10	64.3%	332	142	57.2%	28	28	0.0%	326	194	40.5%
64		28	3	89.3%	330	71	78.5%	28	22	21.4%	329	131	60.2%
66		28	2	92.9%	329	63	80.9%	28	6	78.6%	325	60	81.5%
67		20	1	95.0%	228	14	93.9%	20	4	80.0%	228	40	82.5%
68	21	28	6	78.6%	332	67	79.8%	28	15	46.4%	331	133	59.8%
69		28	11	60.7%	319	79	75.2%	28	12	57.1%	314	55	82.5%
71		28	0	100.0%	327	3	99.1%	27	4	85.2%	325	85	73.8%
72		28	4	85.7%	323	35	89.2%	27	7	74.1%	321	68	78.8%
73		28	4	85.7%	326	23	92.9%	28	5	82.1%	324	147	54.6%
74		28	2	92.9%	324	35	89.2%	28	9	67.9%	322	117	63.7%
75	13	28	0	100.0%	320	16	95.0%	28	12	57.1%	314	149	52.5%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	48	28	2	92.9%	320	31	90.3%	28	13	53.6%	311	130	58.2%
77	29	28	1	96.4%	322	21	93.5%	28	10	64.3%	320	133	58.4%
78		28	3	89.3%	326	28	91.4%	28	12	57.1%	325	75	76.9%
79		28	3	89.3%	329	59	82.1%	28	10	64.3%	328	111	66.2%
80		28	4	85.7%	329	37	88.8%	28	8	71.4%	326	71	78.2%
84		20	5	75.0%	201	19	90.5%	18	5	72.2%	197	48	75.6%
85		20	2	90.0%	212	18	91.5%	20	4	80.0%	212	74	65.1%
86		20	1	95.0%	212	16	92.5%	20	6	70.0%	211	121	42.7%
89	44	28	13	53.6%	327	78	76.1%	28	11	60.7%	325	96	70.5%
90		28	2	92.9%	327	12	96.3%	28	9	67.9%	326	60	81.6%
93		20	2	90.0%	211	21	90.0%	20	8	60.0%	210	55	73.8%
94		20	6	70.0%	242	61	74.8%	20	6	70.0%	240	89	62.9%
95	162	20	2	90.0%	211	6	97.2%	20	13	35.0%	211	82	61.1%
97	89	28	19	32.1%	329	217	34.0%	28	19	32.1%	327	119	63.6%
98	108	28	2	92.9%	329	28	91.5%	28	15	46.4%	327	123	62.4%
110		20	8	60.0%	208	110	47.1%	20	3	85.0%	205	22	89.3%
111		20	2	90.0%	202	37	81.7%	20	1	95.0%	200	22	89.0%
112		20	2	90.0%	202	20	90.1%	20	1	95.0%	201	20	90.0%
113		20	8	60.0%	133	33	75.2%	20	2	90.0%	132	16	87.9%
119		20	4	80.0%	199	49	75.4%	20	4	80.0%	197	26	86.8%
125	24	20	1	95.0%	212	12	94.3%	20	9	55.0%	212	83	60.8%
129		20	3	85.0%	211	50	76.3%	20	2	90.0%	211	30	85.8%
130		20	2	90.0%	202	20	90.1%	20	0	100.0%	200	16	92.0%
131	22	20	4	80.0%	204	57	72.1%	20	4	80.0%	204	39	80.9%
134		20	5	75.0%	212	32	84.9%	20	6	70.0%	211	42	80.1%
136		20	3	85.0%	212	27	87.3%	20	3	85.0%	210	28	86.7%
137		20	1	95.0%	209	36	82.8%	20	4	80.0%	209	62	70.3%
138		20	4	80.0%	212	43	79.7%	20	4	80.0%	211	38	82.0%
141	17	20	1	95.0%	211	4	98.1%	20	4	80.0%	210	37	82.4%
148		20	2	90.0%	211	22	89.6%	20	5	75.0%	209	41	80.4%
151	19	28	8	71.4%	328	103	68.6%	28	4	85.7%	327	99	69.7%
170		20	0	100.0%	207	12	94.2%	20	1	95.0%	206	30	85.4%
171	39	20	0	100.0%	212	11	94.8%	20	12	40.0%	212	87	59.0%
172		20	4	80.0%	211	19	91.0%	20	7	65.0%	209	69	67.0%
173	61	20	1	95.0%	204	25	87.7%	20	6	70.0%	203	84	58.6%
174		20	3	85.0%	212	23	89.2%	20	4	80.0%	212	52	75.5%
175		20	1	95.0%	212	23	89.2%	20	8	60.0%	212	70	67.0%
176	Cncld	20	2	90.0%	204	17	91.7%	19	2	89.5%	201	26	87.1%
177	55	20	1	95.0%	212	28	86.8%	20	2	90.0%	212	48	77.4%
178		20	2	90.0%	212	28	86.8%	20	4	80.0%	210	35	83.3%
179	24	20	2	90.0%	212	25	88.2%	20	6	70.0%	211	76	64.0%
181		20	5	75.0%	208	64	69.2%	19	2	89.5%	205	17	91.7%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182	23	20	1	95.0%	202	31	84.7%	20	2	90.0%	200	23	88.5%
183		20	6	70.0%	211	62	70.6%	20	5	75.0%	208	43	79.3%
184		20	3	85.0%	212	36	83.0%	20	1	95.0%	211	28	86.7%
185		20	4	80.0%	212	41	80.7%	20	4	80.0%	212	18	91.5%
186		20	8	60.0%	211	29	86.3%	20	8	60.0%	210	61	71.0%
190		20	6	70.0%	211	75	64.5%	20	1	95.0%	210	44	79.0%
192		20	0	100.0%	209	24	88.5%	20	2	90.0%	209	19	90.9%
193		19	5	73.7%	207	83	59.9%	19	2	89.5%	206	90	56.3%
196		20	3	85.0%	208	23	88.9%	19	2	89.5%	206	17	91.7%
197		20	1	95.0%	212	76	64.2%	20	4	80.0%	212	71	66.5%
198		20	0	100.0%	144	17	88.2%	20	1	95.0%	143	22	84.6%
230		28	0	100.0%	165	4	97.6%	28	1	96.4%	165	8	95.2%
232		28	1	96.4%	331	12	96.4%	28	2	92.9%	331	23	93.1%
234		28	0	100.0%	332	22	93.4%	28	3	89.3%	331	28	91.5%
235		28	7	75.0%	256	41	84.0%	28	6	78.6%	255	58	77.3%
236		28	0	100.0%	316	10	96.8%	28	4	85.7%	315	43	86.3%
237		28	3	89.3%	329	59	82.1%	28	7	75.0%	327	58	82.3%
238		28	3	89.3%	256	23	91.0%	28	3	89.3%	254	21	91.7%
239		28	3	89.3%	330	82	75.2%	28	3	89.3%	329	41	87.5%
240		28	2	92.9%	331	23	93.1%	28	7	75.0%	328	67	79.6%
241		28	8	71.4%	331	82	75.2%	28	8	71.4%	331	79	76.1%
243		28	5	82.1%	267	70	73.8%	28	5	82.1%	266	38	85.7%
245		28	6	78.6%	212	39	81.6%	28	7	75.0%	211	29	86.3%
280		28	2	92.9%	332	17	94.9%	28	14	50.0%	331	75	77.3%
281		28	3	89.3%	332	40	88.0%	28	2	92.9%	332	59	82.2%
283		28	10	64.3%	332	84	74.7%	28	4	85.7%	332	65	80.4%
284		28	0	100.0%	332	13	96.1%	28	4	85.7%	329	58	82.4%
290		28	2	92.9%	332	52	84.3%	28	20	28.6%	329	134	59.3%
291		28	16	42.9%	331	109	67.1%	26	12	53.8%	327	88	73.1%
300		27	2	92.6%	315	22	93.0%	26	5	80.8%	312	73	76.6%
301	36	28	0	100.0%	329	10	97.0%	28	8	71.4%	325	63	80.6%
302		27	1	96.3%	310	34	89.0%	27	12	55.6%	306	90	70.6%
305		27	3	88.9%	313	31	90.1%	26	7	73.1%	308	122	60.4%
306		28	1	96.4%	327	17	94.8%	27	7	74.1%	325	89	72.6%
307	146	28	6	78.6%	320	44	86.3%	27	16	40.7%	316	98	69.0%
311	135	27	2	92.6%	324	28	91.4%	27	18	33.3%	318	81	74.5%
316	31	27	5	81.5%	320	23	92.8%	26	20	23.1%	314	98	68.8%
318		28	4	85.7%	330	35	89.4%	28	20	28.6%	327	164	49.8%
319	46	28	0	100.0%	331	20	94.0%	28	26	7.1%	326	191	41.4%
329		20	3	85.0%	235	12	94.9%	20	4	80.0%	235	19	91.9%
330		24	0	100.0%	282	6	97.9%	24	0	100.0%	282	15	94.7%
331		28	0	100.0%	332	33	90.1%	27	0	100.0%	331	44	86.7%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		27	2	92.6%	331	19	94.3%	27	3	88.9%	331	46	86.1%
334		28	1	96.4%	332	11	96.7%	27	3	88.9%	330	43	87.0%
335		28	1	96.4%	332	35	89.5%	27	4	85.2%	329	55	83.3%
336		27	0	100.0%	331	10	97.0%	27	1	96.3%	329	29	91.2%
337		28	2	92.9%	332	20	94.0%	28	8	71.4%	328	44	86.6%
338		28	6	78.6%	332	53	84.0%	27	8	70.4%	329	102	69.0%
339		28	3	89.3%	332	53	84.0%	28	3	89.3%	332	56	83.1%
341		25	5	80.0%	317	49	84.5%	25	10	60.0%	311	51	83.6%
342		28	2	92.9%	332	26	92.2%	28	1	96.4%	330	61	81.5%
350	21	26	1	96.2%	307	19	93.8%	25	20	20.0%	299	171	42.8%
351	22	27	2	92.6%	314	29	90.8%	27	13	51.9%	312	91	70.8%
352		27	3	88.9%	298	24	91.9%	27	11	59.3%	292	92	68.5%
353	28	27	1	96.3%	269	14	94.8%	27	11	59.3%	263	49	81.4%
354	19	28	2	92.9%	313	37	88.2%	27	15	44.4%	305	116	62.0%
355		26	6	76.9%	320	37	88.4%	24	19	20.8%	311	118	62.1%
364		28	7	75.0%	321	72	77.6%	28	13	53.6%	315	120	61.9%
365		28	2	92.9%	320	13	95.9%	27	15	44.4%	317	124	60.9%
370		23	4	82.6%	318	39	87.7%	20	6	70.0%	305	75	75.4%
371		23	3	87.0%	311	11	96.5%	20	1	95.0%	307	30	90.2%
380		24	3	87.5%	313	30	90.4%	23	9	60.9%	312	72	76.9%
381		26	3	88.5%	328	15	95.4%	24	10	58.3%	325	70	78.5%
382		26	3	88.5%	327	30	90.8%	24	16	33.3%	325	116	64.3%
383	55	25	1	96.0%	318	27	91.5%	25	14	44.0%	315	137	56.5%
390		27	5	81.5%	313	24	92.3%	26	12	53.8%	311	85	72.7%
391	22	27	3	88.9%	314	14	95.5%	26	12	53.8%	309	88	71.5%
392		27	1	96.3%	327	11	96.6%	25	10	60.0%	322	100	68.9%
393		27	1	96.3%	331	19	94.3%	26	11	57.7%	327	102	68.8%
425		19	1	94.7%	223	7	96.9%	18	0	100.0%	222	7	96.8%
448		22	6	72.7%	256	49	80.9%	21	8	61.9%	252	88	65.1%
449		22	2	90.9%	253	34	86.6%	22	2	90.9%	253	44	82.6%
470		20	2	90.0%	235	39	83.4%	20	3	85.0%	229	27	88.2%
471		19	3	84.2%	224	14	93.8%	19	1	94.7%	224	6	97.3%
473		20	0	100.0%	231	15	93.5%	20	0	100.0%	228	10	95.6%
475		19	2	89.5%	228	8	96.5%	19	1	94.7%	228	16	93.0%
478		20	4	80.0%	223	36	83.9%	20	1	95.0%	221	28	87.3%
479		20	2	90.0%	230	36	84.3%	20	5	75.0%	228	36	84.2%
486		20	4	80.0%	234	35	85.0%	20	3	85.0%	228	61	73.2%
494		21	6	71.4%	237	47	80.2%	20	7	65.0%	229	64	72.1%
495		19	0	100.0%	218	4	98.2%	19	0	100.0%	216	3	98.6%
500		11	0	100.0%	306	16	94.8%	11	1	90.9%	303	36	88.1%
502		12	1	91.7%	314	19	93.9%	12	3	75.0%	310	61	80.3%
503		28	13	53.6%	328	40	87.8%	28	15	46.4%	321	102	68.2%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		28	1	96.4%	332	20	94.0%	28	8	71.4%	330	98	70.3%
505		22	1	95.5%	324	42	87.0%	22	6	72.7%	319	90	71.8%
506	24	28	14	50.0%	327	56	82.9%	26	5	80.8%	319	51	84.0%
507		28	13	53.6%	332	49	85.2%	28	15	46.4%	332	115	65.4%
508	17	28	2	92.9%	327	43	86.9%	28	12	57.1%	323	80	75.2%
509		12	1	91.7%	313	15	95.2%	12	4	66.7%	313	70	77.6%
511	24	12	1	91.7%	308	25	91.9%	12	3	75.0%	307	53	82.7%
516		28	6	78.6%	323	35	89.2%	28	12	57.1%	322	146	54.7%
517		28	0	100.0%	332	8	97.6%	28	22	21.4%	328	149	54.6%
518		28	8	71.4%	332	45	86.4%	28	23	17.9%	330	230	30.3%
519		28	0	100.0%	323	9	97.2%	28	6	78.6%	321	72	77.6%
520	37	20	4	80.0%	193	29	85.0%	18	2	88.9%	188	11	94.1%
521	41	20	0	100.0%	231	7	97.0%	19	4	78.9%	230	31	86.5%
522	43	20	4	80.0%	231	43	81.4%	20	4	80.0%	228	24	89.5%
523		20	2	90.0%	231	9	96.1%	20	4	80.0%	230	26	88.7%
524		19	1	94.7%	230	17	92.6%	19	4	78.9%	227	27	88.1%
525		19	0	100.0%	228	16	93.0%	19	1	94.7%	224	15	93.3%
526		20	7	65.0%	205	41	80.0%	20	3	85.0%	202	18	91.1%
527		20	0	100.0%	231	10	95.7%	20	3	85.0%	230	40	82.6%
528		20	2	90.0%	231	19	91.8%	20	2	90.0%	230	32	86.1%
529	20	20	1	95.0%	231	13	94.4%	20	7	65.0%	230	65	71.7%
530	42	20	2	90.0%	185	18	90.3%	20	6	70.0%	185	38	79.5%
531		20	1	95.0%	205	14	93.2%	20	0	100.0%	205	13	93.7%
532		20	6	70.0%	231	57	75.3%	19	4	78.9%	229	35	84.7%
534		20	3	85.0%	190	28	85.3%	19	1	94.7%	187	17	90.9%
535	14	19	1	94.7%	217	26	88.0%	19	5	73.7%	212	28	86.8%
536		20	9	55.0%	231	64	72.3%	20	3	85.0%	227	41	81.9%
537	17	19	2	89.5%	200	24	88.0%	19	5	73.7%	194	25	87.1%
538		20	2	90.0%	231	26	88.7%	20	3	85.0%	230	46	80.0%
539	37	20	4	80.0%	185	28	84.9%	20	10	50.0%	185	81	56.2%
540		20	6	70.0%	230	44	80.9%	18	3	83.3%	220	21	90.5%
541		20	3	85.0%	230	25	89.1%	19	5	73.7%	223	41	81.6%
542		20	1	95.0%	230	25	89.1%	20	3	85.0%	227	40	82.4%
543	44	20	4	80.0%	231	28	87.9%	20	10	50.0%	231	73	68.4%
544		20	1	95.0%	229	21	90.8%	19	2	89.5%	225	22	90.2%
545		20	3	85.0%	231	20	91.3%	20	4	80.0%	228	28	87.7%
547		20	6	70.0%	231	47	79.7%	20	7	65.0%	231	54	76.6%
549		20	1	95.0%	226	27	88.1%	18	3	83.3%	216	20	90.7%
550		20	2	90.0%	185	20	89.2%	20	8	60.0%	185	44	76.2%
551		20	1	95.0%	227	23	89.9%	20	3	85.0%	217	23	89.4%
562		28	4	85.7%	323	27	91.6%	28	1	96.4%	319	36	88.7%
564		28	0	100.0%	324	19	94.1%	28	3	89.3%	316	41	87.0%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566		28	4	85.7%	322	29	91.0%	28	7	75.0%	319	52	83.7%
567		28	1	96.4%	209	11	94.7%	28	4	85.7%	207	13	93.7%
572		28	3	89.3%	319	27	91.5%	27	10	63.0%	311	93	70.1%
573		28	3	89.3%	321	43	86.6%	28	5	82.1%	314	56	82.2%
579		28	2	92.9%	209	13	93.8%	26	6	76.9%	202	43	78.7%
580		28	2	92.9%	324	18	94.4%	28	6	78.6%	317	34	89.3%
581		28	6	78.6%	324	56	82.7%	27	9	66.7%	321	73	77.3%
584	33	28	5	82.1%	208	30	85.6%	27	23	14.8%	202	131	35.1%
587	24	27	3	88.9%	316	19	94.0%	27	10	63.0%	307	63	79.5%
588	Cncld	26	3	88.5%	207	21	89.9%	25	9	64.0%	205	42	79.5%
591		28	3	89.3%	321	24	92.5%	27	8	70.4%	314	47	85.0%
593	Cncld	24	4	83.3%	314	51	83.8%	23	3	87.0%	292	40	86.3%
595	No OS	26	6	76.9%	317	59	81.4%	26	11	57.7%	314	71	77.4%
600		20	0	100.0%	239	9	96.2%	20	3	85.0%	237	22	90.7%
601		20	7	65.0%	222	90	59.5%	20	2	90.0%	219	27	87.7%
605		20	8	60.0%	229	138	39.7%	20	1	95.0%	225	23	89.8%
607		20	0	100.0%	238	30	87.4%	20	0	100.0%	235	25	89.4%
609		20	0	100.0%	229	23	90.0%	20	4	80.0%	228	23	89.9%
626		20	4	80.0%	143	20	86.0%	20	0	100.0%	141	18	87.2%
639		20	2	90.0%	209	40	80.9%	19	1	94.7%	207	20	90.3%
640		20	0	100.0%	229	7	96.9%	20	4	80.0%	227	84	63.0%
641		20	5	75.0%	211	43	79.6%	20	1	95.0%	211	27	87.2%
642		20	2	90.0%	227	11	95.2%	20	1	95.0%	226	27	88.1%
643		20	0	100.0%	241	44	81.7%	20	3	85.0%	238	39	83.6%
644		20	0	100.0%	233	28	88.0%	20	3	85.0%	231	55	76.2%
645		20	1	95.0%	241	42	82.6%	20	9	55.0%	238	55	76.9%
646		20	5	75.0%	230	56	75.7%	20	11	45.0%	228	112	50.9%
647	12	20	3	85.0%	241	35	85.5%	19	2	89.5%	239	51	78.7%
648		20	3	85.0%	237	59	75.1%	20	1	95.0%	237	35	85.2%
649		20	2	90.0%	242	44	81.8%	19	0	100.0%	238	34	85.7%
650		20	4	80.0%	241	45	81.3%	20	3	85.0%	238	39	83.6%
651		20	1	95.0%	241	17	92.9%	19	1	94.7%	238	43	81.9%
652		20	2	90.0%	242	31	87.2%	20	4	80.0%	238	41	82.8%
653		20	3	85.0%	230	36	84.3%	19	2	89.5%	226	41	81.9%
654		20	4	80.0%	231	44	81.0%	20	2	90.0%	227	20	91.2%
655		20	2	90.0%	239	74	69.0%	19	3	84.2%	236	76	67.8%
656		20	7	65.0%	241	54	77.6%	19	3	84.2%	239	33	86.2%
657		20	2	90.0%	230	29	87.4%	19	1	94.7%	228	30	86.8%
658		20	2	90.0%	241	37	84.6%	20	2	90.0%	239	35	85.4%
680		20	0	100.0%	236	12	94.9%	19	0	100.0%	234	27	88.5%
681		20	1	95.0%	236	18	92.4%	19	7	63.2%	229	93	59.4%
682		20	3	85.0%	235	9	96.2%	20	3	85.0%	235	41	82.6%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
683		20	1	95.0%	218	18	91.7%	20	8	60.0%	217	75	65.4%
684		20	5	75.0%	217	37	82.9%	20	2	90.0%	217	47	78.3%
685		20	2	90.0%	232	33	85.8%	20	2	90.0%	229	55	76.0%
686		20	2	90.0%	237	39	83.5%	20	5	75.0%	236	52	78.0%
687	13	20	4	80.0%	236	38	83.9%	20	4	80.0%	235	40	83.0%
688		20	2	90.0%	235	15	93.6%	20	4	80.0%	234	40	82.9%
689		10	1	90.0%	155	21	86.5%	10	2	80.0%	154	23	85.1%
701		28	3	89.3%	264	28	89.4%	28	6	78.6%	261	31	88.1%
702	32	28	3	89.3%	331	35	89.4%	28	13	53.6%	328	83	74.7%
703	29	28	19	32.1%	332	112	66.3%	28	14	50.0%	330	99	70.0%
704	63	28	10	64.3%	263	47	82.1%	27	11	59.3%	255	57	77.6%
710	32	28	1	96.4%	332	78	76.5%	28	7	75.0%	328	88	73.2%
711	63	28	4	85.7%	323	38	88.2%	26	13	50.0%	300	65	78.3%
712	27	28	10	64.3%	329	90	72.6%	27	13	51.9%	319	111	65.2%
713	Cncld	27	3	88.9%	199	19	90.5%	20	12	40.0%	176	79	55.1%
714		28	16	42.9%	213	91	57.3%	26	17	34.6%	197	93	52.8%
715	Cncld	28	2	92.9%	331	63	81.0%	23	13	43.5%	303	154	49.2%
716	42	28	20	28.6%	332	140	57.8%	26	21	19.2%	324	139	57.1%
717	158	28	9	67.9%	317	77	75.7%	22	11	50.0%	292	97	66.8%
718	27	28	22	21.4%	332	175	47.3%	27	17	37.0%	329	126	61.7%
719	96	28	10	64.3%	332	113	66.0%	27	13	51.9%	315	97	69.2%
757	17	28	2	92.9%	117	7	94.0%	28	4	85.7%	116	12	89.7%
761		28	1	96.4%	328	13	96.0%	28	2	92.9%	325	43	86.8%
765		28	0	100.0%	328	25	92.4%	28	4	85.7%	328	46	86.0%
769		28	0	100.0%	328	27	91.8%	27	6	77.8%	321	63	80.4%
770		28	3	89.3%	328	25	92.4%	27	13	51.9%	325	102	68.6%
774		28	1	96.4%	328	17	94.8%	27	8	70.4%	326	77	76.4%
777	22	28	0	100.0%	213	12	94.4%	28	13	53.6%	212	55	74.1%
782		28	21	25.0%	213	103	51.6%	28	9	67.9%	208	34	83.7%
785		28	5	82.1%	328	27	91.8%	28	6	78.6%	328	59	82.0%
786	24	28	3	89.3%	117	22	81.2%	27	17	37.0%	113	64	43.4%
790		28	2	92.9%	328	30	90.9%	28	7	75.0%	325	53	83.7%
794		28	7	75.0%	328	40	87.8%	28	7	75.0%	324	73	77.5%
821	33	28	0	100.0%	326	6	98.2%	28	17	39.3%	326	138	57.7%
822	43	28	2	92.9%	328	18	94.5%	28	26	7.1%	326	168	48.5%
1233		8	1	87.5%	23	5	78.3%	6	4	33.3%	21	12	42.9%
1246	21	8	6	25.0%	23	18	21.7%	8	5	37.5%	23	12	47.8%
1333		28	8	71.4%	328	40	87.8%	28	11	60.7%	325	110	66.2%
1340		28	1	96.4%	327	7	97.9%	27	4	85.2%	326	55	83.1%
2102		20	3	85.0%	88	16	81.8%	20	1	95.0%	87	7	92.0%
2103		20	2	90.0%	152	14	90.8%	20	1	95.0%	151	10	93.4%
2104		20	0	100.0%	178	10	94.4%	20	1	95.0%	176	13	92.6%

Amtrak On Time Performance

Trains Arriving Through: 8/28/2026

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107		20	1	95.0%	209	35	83.3%	20	1	95.0%	206	21	89.8%
2108		20	2	90.0%	209	28	86.6%	20	7	65.0%	203	27	86.7%
2109	41	20	2	90.0%	102	13	87.3%	20	2	90.0%	100	6	94.0%
2112		20	2	90.0%	49	6	87.8%	20	0	100.0%	47	2	95.7%
2113		20	1	95.0%	88	9	89.8%	20	0	100.0%	88	10	88.6%
2115	21	20	2	90.0%	88	13	85.2%	20	2	90.0%	87	12	86.2%
2116		20	0	100.0%	49	1	98.0%	20	1	95.0%	49	8	83.7%
2118		20	2	90.0%	49	4	91.8%	20	3	85.0%	49	12	75.5%
2119		20	4	80.0%	49	8	83.7%	19	2	89.5%	48	12	75.0%
2120	21	20	10	50.0%	49	19	61.2%	19	10	47.4%	47	23	51.1%
2123		20	2	90.0%	87	10	88.5%	20	0	100.0%	86	15	82.6%
2124		19	4	78.9%	180	38	78.9%	19	2	89.5%	178	24	86.5%
2127		20	3	85.0%	49	10	79.6%	20	2	90.0%	48	9	81.3%
2128		20	1	95.0%	49	4	91.8%	20	1	95.0%	49	3	93.9%
2131		20	4	80.0%	49	10	79.6%	20	3	85.0%	49	6	87.8%
2150		20	0	100.0%	202	22	89.1%	20	1	95.0%	199	74	62.8%
2151		20	1	95.0%	151	7	95.4%	20	4	80.0%	149	41	72.5%
2152		20	1	95.0%	107	7	93.5%	20	1	95.0%	106	31	70.8%
2154		20	0	100.0%	110	23	79.1%	20	3	85.0%	106	45	57.5%
2155	52	20	1	95.0%	211	17	91.9%	20	5	75.0%	207	101	51.2%
2158	51	20	1	95.0%	48	5	89.6%	20	4	80.0%	48	16	66.7%
2159		20	2	90.0%	204	16	92.2%	20	10	50.0%	202	69	65.8%
2160		20	0	100.0%	49	2	95.9%	20	10	50.0%	48	28	41.7%
2162	144	20	5	75.0%	210	23	89.0%	20	6	70.0%	204	91	55.4%
2165		20	2	90.0%	46	4	91.3%	20	8	60.0%	46	21	54.3%
2167		20	0	100.0%	197	20	89.8%	20	1	95.0%	197	40	79.7%
2171		20	0	100.0%	138	10	92.8%	20	0	100.0%	134	23	82.8%
2190		20	2	90.0%	207	29	86.0%	20	1	95.0%	205	24	88.3%
2193		20	1	95.0%	202	26	87.1%	20	1	95.0%	200	50	75.0%

Amtrak Endpoint OTP Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/28/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2109	WAS	41	ENG	46	ENG	23	NYP-NYP	AM	Undesired emergency application, 2123 NG NP, DEPREPARED TRAIN A/C DUE TO MULTIPLE ENGINE FAULTS	
2115	WAS	21	OTH	21	OTH	10	BWI-XNY	AM	Lost time - N.A.R., PRT	
2120	NYP	21	CAR	27	CAR	27	BAL-BAL	AM	Heat / AC, 3708 NG NB, had 3 hot cars, de-prepared train and resolved issue	
2155	WAS	52	ENG	41	ENG	41	XCY-XHM	AM	Undesired emergency application, 2144 NG NP, PANS DROPPED JUST WEST OF ADAMS	
2158	BOS	51	ENG	70	ENG	42	NHV-XGX	AM	Other electrical failure, 2121 NG NP, ACSES FAULT. HAD TO RESET THE ENG	
2162	BOS	144	SYS	59	SYS	59	XGX-PVD	AM	Blocked by or assisting another, disabled Amtrak train, Service disruption. Reversed from Mystic River to NLC to pick up PAX off disabled 176.	
95	NFK	162	ENG	132	ENG	39	OSB-NHV	AM	Cab signal failure, 639 EX ES, Train did declare cab signal failure on E/639 capped at 59mph. MNRR able to take AM95 and will be capped in NHV	
125	NPN	24	OTH	34	DSR	12	BRP-STM	MN	Per bulletin Milepost, 41.7, 42.0, 15, 2	
131	WAS	22	OTH	15	SMW	10	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 2 track a/c 3 track o/s between Davis & Bacon	
141	WAS	17	OTH	18	OTH	10	WIL-XPV	AM	Lost time - N.A.R., PRT	
151	RNK	19	FTI	22	FTI	22	LYH-RNK	NS	Follow 19m, Milepost, 239.0, 222.0	
171	RNK	39	PTI	20	SVS	16	WAS-WAS	AM	Water, commissary, toilet/trash dumping, HANDLING MULTIPLE TRAINS SIMULTANEOUSLY 40, 125, & 178	
173	WAS	61	DSR	28	DSR	14	BRP-STM	MN	Per bulletin Working limits at MP 53.3, Milepost w/Letters, BRP, STM, 30, 2	
176	BOS	Trn Cancelled	ENG	76	ENG	76	OSB-OSB	AM	Other electrical failure, 652 EX ES, 176 has a battery charging fault on the lead unit, engine 652, and a traction motor fault on the second unit, engine 623. RFE M. Williams and RFE J. Romikitis notified. No. 176 stopped at Old Saybrook Station	
177	PHL	55	CTI	26	MTI	23	WLY-XGX	AM	Disabled train ahead, Other, 2158, TRAIN 2158 DISABLED AT XSS	
179	PHL	24	CTI	17	CTI	11	NLC-NHV	AM	Follow, CDOT, 1695, Milepost w/Letters, NLC, NHV, AM179 followed signals of CD1695	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
182	BOS	23	CTI	20	OTH	9	XPV-WIL	AM	Lost time - N.A.R., PRT
52	LOR	87	TRS	97	TRS	97	XJG-XSA	CS	Vehicle on track ahead Milepost, 537.0, 537.0
53	SFA	161	TRS	163	TRS	163	XSE-XFL	CS	Vehicle on track ahead Milepost w/Letters, A209.4, A209.4
647	HAR	12	DCS	10	DCS	10	PHL-PAO	AM	T.O.L, Control Point, BRYN MAWR TO PAOLI, T.O.L. BRYN MAWR TO PAOLI; STOP AND PRO ON AUTOMATIC 119, CABS CLEAR AFTER THAT
687	BRK	13	PTI	14	PTI	14	WEM-SAO	CS	Meet 688, Control Point, wells
63	TWO	47	RTE	12	PTI	5	NYP-NYP	AM	Meet, AM230, Other, NYP-NYP, HELD A/C AM230 XING AHEAD
68	NYP	21	DCS	50	DCS	50	SAR-XSY	DH	Power switch failure Control Point, 31
1246	NYP	21	PTI	35	PTI	29	X7X-XRD	CS	Meet 448, Control Point, 176
49	CHI	37	FTI	75	FTI	21	TOL-BYN	NS	Follow 25E, Milepost, 314, 340
42	NYP	22	MTI	20	MTI	20	NWK-NYP	AM	Disabled train ahead, Other, XBH-NYP, AM2116 DISABLED AHEAD IN THE SOUTH TUBE
75	CLT	13	PTI	14	PTI	14	CYN-DNC	NS	Meet #Amt72, Control Point, Nelson
76	RGH	48	DCS	43	DCS	43	CLT-KAN	NS	T.O.L Shamrock - Adams, Control Point, Shamrock
77	CLT	29	DCS	15	DCS	15	KAN-CLT	NS	Had to get talked by Stop Signal Talked by, and then restricted speed until Concord., Control Point, Adams
89	SAV	44	WTR	40	WTR	17	PTB-RMT	CS	Heat order Other, N. E. Sub
97	MIA	89	FTI	72	FTI	41	XDI-FLO	CS	Follow Milepost w/Letters, A284.7, A292, IO31
98	NYP	108	FTI	137	FTI	67	XDI-FAY	CS	CSX Train hit someone CSX, Other, stopped at 232mp
40	CHI	134	PTI	88	DCS	45	MRB-CUM	CS	Power switch failure Milepost, 105.0, 105.0
24	MOE	18	FTI	52	FTI	22	BIX-PAG	CS	Meet CSX 4035, Siding, Gautier
520	SAC	37	DBS	39	DBS	39	RIC-RIC	UP	Debris blocking track (no debris strike) Milepost, 12.4, 12.4
521	SJC	41	POL	44	POL	44	MTZ-RIC	UP	Fire department hold FIRE PERSONNEL REQUESTED TRAIN TO STOP BEFORE MP 12.14 FOR FOR ADJACENT TO TRACKS.

Amtrak Endpoint OTP Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
522	SAC	43	DCS	41	DCS	41	OKJ-OKJ	UP	PTC system failure (wayside) While logging in to PTC, log-in process kept timing out at the "wait for train ID confirmation from UP" screen. Contacted the UP PTC Desk who remotely reset multiple issues from the UP side so we could successfully log in., Other, OKJ Depot
529	SJC	20	FTI	16	FTI	16	RSV-SAC	UP	Cross Traffic Train stalled on tracks ahead, Control Point, RV101, UP8494east
530	SAC	42	MBO	28	MBO	28	MTZ-SUI	UP	For maritime traffic Control Point, RV033
535	OKJ	14	SYS	9	SYS	9	SAC-DAV	UP	PTC problem or failure (cause unknown) Red fence on the PTC screen caused train to go into penalty. Signal on the field was an Advance Approach., Control Point, RV988
537	OKJ	17	MBO	18	MBO	18	SUI-MTZ	UP	For maritime traffic Bridge, Suisun Bay Bridge
539	SJC	37	POL	30	POL	18	OAC-HAY	UP	Right of Way police hold MP 16.74
543	SJC	44	CTI	26	CTI	26	FMT-GAC	UP	Meet ace, ace8, Siding, Albrae
506	SEA	24	PTI	23	PTI	16	XNI-TAC	ST	Meet amtk 511, Control Point, manitou
508	SEA	17	PTI	26	PTI	11	EUG-ALY	UP	Meet 11, Control Point, swain
511	PDX	24	FTI	15	PTI	15	OLW-CTL	BN	Meet AMT508, Control Point, Plumb
58	CHI	69	DSR	88	DSR	17	MEM-NBN	CC	Per bulletin Milepost, 390.99, 390.6, 10, main, Milepost, 390.0, 389.6, 10, main, Milepost, 371.52, 370.9, 30, main, Milepost, 351.2, 351.2, 70, main, Milepost, 338.8, 338.4, 39, main, Milepost, 337.0, 336.6, 60, main, Milepost, 328.6, 327.9, 30, main, Milepost, 311.0, 310.6, 30, 1
59	NOL	33	DSR	70	CAR	41	CHI-CHI	AM	Switch car for no reason given 37013
7	SEA	49	ENG	97	ENG	87	SPK-SPK	BN	Set out defective locomotive Added freight locomotive then had to remove freight locomotive for failure, 368
8	CHI	130	FTI	217	CON	58	SPK-SPK	BN	Hold for connecting train 28
821	FTW	33	DSR	40	DSR	25	GLE-FTW	BN	Per bulletin Milepost, 409.5, 409.3, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 397.5, 397.1, 60, m, Milepost, 396.3, 396.2, 30, m, Milepost, 395.3, 395, 60, m, Milepost, 393.4, 392.8, 60, m, Milepost, 392.4, 39272, 60, m, Milepost, 391.9, 391.3, 60, m, Milepost,
822	OKC	43	FTI	48	FTI	42	FTW-GLE	BN	Meet BN Freight, Siding, Metro

Amtrak Endpoint OTP Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/28/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
350	PNT	21	PTI	22	CAR	18	XTF-HMI	NS	Air / Brake / Wheel ID4312, ID4010, Train in emergency 511.4, air hoses came apart between 4312 and 4010.
351	CHI	22	PTI	19	PTI	16	XMC-XPI	NS	Follow amtk 49 & 41, Other, 236
353	CHI	28	FTI	43	FTI	20	XMC-XPI	NS	Cross Traffic ns, Control Point, 482
354	PNT	19	DSR	21	DSR	15	TRM-PNT	CC	Per bulletin Milepost, 28.6, 13.9, 30, m1
584	SAN	33	PTI	30	PTI	26	SNC-SNP	SC	Meet 587, Control Point, serra
587	LAX	24	CTI	30	CTI	26	OSD-X98	SC	Meet Metrolink, Control Point, Songs
588	SAN	Trn Cancelled							
593	LAX	Trn Cancelled							
595	LAX	No OS Rpt	DCS	6	DCS	6	OSD-OSD	SN	Restrictive signal(s) from unknown cause Stop, Control Point, Shell
757	SLO	17	PTI	19	PTI	19	GTA-X3G	UP	Meet 774, Siding, ellwood
777	SLO	22	PTI	43	PTI	18	OXN-VEC	UP	Meet AMTK 790, Control Point, North Ventura
786	SAN	24	CTI	34	CTI	31	SIM-CWT	SC	Meet Metrolink, 127, Control Point, Davis
702	BFD	32	FTI	32	PTI	15	MOD-TRK	BN	Meet Shuffle, 711, Control Point, east denair
703	SAC	29	PTI	23	TEN	23	BFD-BFD	BN	Air / Brake Main reservoir wasn't loading upon doing air brake test. Mechanical and TASI approved us to run without the air dryer in the engine on., C2002
704	BFD	63	SYS	63	SYS	48	MCD-MDR	BN	PTC problem or failure (cause unknown) PTC desk said radio comm. had been down for 24hrs, wanted us to cycle breakers, told us to call CNOC , CNOC said call tasi, they said it was up to host railroad, RF.Cooper told us cycle while sitting at W.Sharon, CNOC said mech. defect and it came back up, Cont
710	BFD	32	PTI	32	PTI	24	SKN-MOD	BN	Meet AMTK 701, Control Point, East Riverbank
711	OKJ	63	FTI	37	FTI	22	MOD-SKN	BN	Follow Followed BNSF 8377 W from MOD to E. Riverbank. Grain train clearing out @ Riverbank yrdu, Control Point, E. Riverbank, BNSF 8377 W, Grain
712	BFD	27	PTI	39	PTI	15	RIC-MTZ	UP	Meet amt 535, Control Point, costa
713	OKJ	Trn Cancelled	FTI	44	FTI	20	FNO-MDR	BN	Meet bnsf 7810, Siding, e Gregg

Amtrak Endpoint OTP Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
715	OKJ	Trn Cancelled	DSR	19	FTI	18	HNF-FNO	BN	Meet North Bay, SF6602, Control Point, Shirley
716	BFD	42	PTI	31	TCR	22	MDR-MDR	BN	Electrical failure C9002, Fell asleep caused HEP ALARM LOST LOAD
717	OKJ	158	ENG	145	ENG	145	XPR-MTZ	UP	PTC - On Board Cab Signal or PTC Failure C2013
718	BFD	27	TSV	30	TSV	30	OKJ-OKJ	UP	Water, commissary, toilet/trash dumping
719	OKJ	96	PTI	58	PTI	30	FNO-MDR	BN	Meet 716, Control Point, Gregg
3	LAX	38	FTI	142	FTI	36	FLG-KNG	BN	Meet Bn 8128 East, Bn 7105 East, Control Point, E Crookton, Control Point, Yampai
4	CHI	64	WTR	89	ENG	50	LAX-LAX	SC	Lead Eng 170 bad ordered due to wheel slip 170 taken out replaced with 138, 138
1	LAX	54	FTI	156	SVS	42	SAS-SAS	UP	Planned Switch Issue with adding transfer cars to rear of train
2	NOL	No OS Rpt	TRS	313	TRS	207	XWJ-HOS	UP	Vehicle strike Milepost, 28.6, 28.6
21	SAS	No OS Rpt	FTI	262	FTI	82	MHL-LVW	UP	Train In emergency 7406, Milepost, 72, 74
22	CHI	51	FTI	89	DCS	33	PBF-ACD	UP	Restrictive signal(s) from known wayside signal failure Restricted , Milepost, 118.0, 109.0
301	STL	36	CAR	29	CAR	29	JOL-BNL	UP	Air / Brake / Wheel ID4016, ID4310, Air hose separation @ Chenoa. Had to replace air hose on car #4310 due to a crack in the glad hand.
307	STL	146	ITI	165	ITI	165	CHI-CHI	AM	Service, turn, or wye train 353
383	QCY	55	RTE	62	RTE	60	KEE-GBB	BN	Dispatcher hold Control Point, Wataga, Control Point, B Plant
391	CDL	22	INJ	27	INJ	27	CHM-MAT	CC	Injured or sick passenger Steve Miller had health issues and was removed from the train by ems
311	KCY	135	TRS	108	TRS	108	IDP-XRC	UP	Trespasser strike Other, 274.7
316	STL	31	ITI	35	ITI	35	KCY-KCY	KC	Service, turn, or wye train 311
319	KCY	46	DSR	38	PTI	18	JEF-SED	UP	Meet 316, Siding, dow

Amtrak Initial Terminal Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/28/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	08/27	5	5	Dispatcher hold Foul time as per Disp, Control Point, 142
BOS	65	08/28	7	7	Other electrical failure, 606 EX ES, trailing fault on e/606 BOS
NFK	94	08/28	10	10	NFK mechanical left blue flag and derail up. Had to wait for them to come back and remove. Arrived in the station at 8:54. Loaded 200 passengers.
NFK	138	08/28	1		
NYP	63	08/28	5	5	Meet, AM230, Other, NYP-NYP, HELD A/C AM230 XING AHEAD
NYP	111	08/28	3	3	Passenger and/or baggage
NYP	2109	08/28	23	23	Undesired emergency application, 2123 NG NP, DEPARED TRAIN A/C DUE TO MULTIPLE ENGINE FAULTS
PHL	605	08/28	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RNK	178	08/28	40	40	Set out defective car 82539
SAR	290	08/28	14		
SFA	52	08/28	43	18	Follow CFRC, 324, Control Point, sanford
SFA	52	08/28	43	25	Service, turn, or wye train 53, Short crew working the yard job.
WAS	112	08/28	2	2	Delay in Block, CREW IDENTIFIED AND RECTIFIED DOOR ISSUE.
WAS	2162	08/28	3	3	Cross over or go around, 171, Control Point, A INTERLOCKING
KCY	316	08/28	35	35	Service, turn, or wye train 311
PNT	353	08/28	2	2	Mobility Impaired 2 Ada showed up at the last minute to board
SAS	22	08/28	164	164	Added locomotive up 5068 and brake test
BFD	703	08/28	23	23	Air / Brake Main reservoir wasn't loading upon doing air brake test. Mechanical and TASI approved us to run without the air dryer in the engine on., C2002
BFD	713	08/28	2	2	Door C9814
BFD	717	08/28	3	3	Water, commissary, toilet/trash dumping
GAC	552	08/28	15	15	Passenger and/or baggage Hold per RFE Ward
GTA	782	08/28	7	3	Meet 14, Control Point, CO 358
GTA	782	08/28	7	4	Restrictive signal(s) from unknown cause Waiting on DS after 14 cleared, Stop, Control Point, CO 358
LAX	4	08/28	4	4	PTC- IETMS Software Download Red signal. Bulletins did not have engine numbers, BNSF did not have train sheet. PTC would not activate until information relayed by us could be fed into their system., Control Point, Terminal
LAX	588	08/28	(Trn Cxld)		Engine Issue

Amtrak Initial Terminal Details

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/28/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	522	08/28	41	41	PTC system failure (wayside) While logging in to PTC, log-in process kept timing out at the "wait for train ID confirmation from UP" screen. Contacted the UP PTC Desk who remotely reset multiple issues from the UP side so we could successfully log in., Other, OKJ Depot
OKJ	536	08/28	1		
OKJ	714	08/28	3	3	Wait for station track Delay occurred on the way to OKJ. 535 and 711 delayed causing delay for 714 to depart yard and board pax at OKJ, 535, Control Point, North Jack London
OKJ	716	08/28	3	3	Water, commissary, toilet/trash dumping
OKJ	718	08/28	88	88	Service, turn, or wye train 713, Loco swap and air hose change
PDX	506	08/28	5	5	Air / Brake / Wheel 7560, Brakes not setting up on business class 2 car
SAC	543	08/28	12	12	Service, turn, or wye train 530
SAC	545	08/28	10	10	Water, commissary, toilet/trash dumping Late removal of Blue Flag protection., Other, SAC Station
SAC	702	08/28	1	1	Door C9017, Train set having problems getting doorlights some doors close some doors stay open
SAN	593	08/28	(Trn Cxld)		Engine Issue
SEA	8	08/28	29	29	Pick up rescue locomotive due to mechanical failure 6688
SEA	507	08/28	7	7	PTC- IETMS recycle breaker to clear fault 90251, Had to cycle breaker due to message on screen preventing engineer from logging on. Red banner about non-sync. After cycling breaker brakes would not release without dumping train twice with an air test each time. Finally released and we were able to g

Eastern Region

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	84.5	84.4	90.2	58	9
SEPTA	95.0	97.2	95.4	91.5	213	6
NJT-NED	95.0	No Data	No Data	88.6	No Data	No Data
NJT-SED	95.0	100	98.8	97.2	20	0

Operating Highlights

Train 97(28) North of Richmond, VA - Car Failure

29AUG26: Train 97(28) operating with engines 342, 320, and 219 customers onboard was delayed on the CSX RFP subdivision multiple times for an air hose disconnecting between car 62016 and car 62019. Initial stop was at milepost 109.6 and then milepost 86.4. Upon arrival in Richmond Staples Mills Station, a safety penalty fault was active on engine 320 causing the train to stay in emergency. The crew worked with a tech to resolve the issue and clear the fault.

Train	Delay	Comment
97(28)	50"	Car Air Hose
97(28)	1'00"	

Train 176(28) Old Saybrook, CT - Engine Failure

28AUG26: Train 176(28) operating with engines 652, 623, and 395 customers onboard was terminated at New London, CT on the AMtrak NHB Line due to battery charger fault on engine 652 and a traction motor fault on rear engine 623. Train 176(28) was utilized at Old Saybrook to transfer customers and then 176(28) operating to New London, CT to finish transferring the remaining customers to Acela 2162 causing train 176(28) to terminate. The equipment then deadheaded to Boston, MA.

Train	Delay	Comment
176(28)		TERM NLC
178(28)	1'26"	
2162(28)	59"	

Train 19(28) Alexandria, VA - Engine Failure

28AUG26: At 8:50 p.m. train 19(28) operating with engines 33, 369, and 191 customers onboard was delayed departing Alexandria, VA on the CSX RFP subdivision after losing head end power due to a cabling issue. The temperature outside was 78 degrees and clear. The crew worked with CNOC mechanical and was able to short loop behind engine 33 on the left side to regain trainline. Train 19(28) departed Alexandria Station at 9:14 p.m.

Train	Delay	Comment
19(28)	51"	

Washington D.C. - Diesel Shortage

28AUG26: Due to diesel shortage in Washington D.C. account of shopped equipment, multiple trains departed late due to late arrivals of diesels from the pit due to waiting on inbound trains for equipment.

Train	Delay	Comment
97(28)	45"	
19(28)	1'21"	

Train 68(28) North of Schenectady, NY - Signal

28AUG26: Train 68(28) operating with engines 112, 704, and 138 customers onboard was delayed 5 miles north of Schenectady, NY on the CPKC Canadian subdivision holding at milepost 31.0 for power switch failure that needed to be fixed by a CPKC maintainer.

Train	Delay	Comment
68(28)	50"	

Train 2158(28) West of New London, CT - Engine Failure

28AUG26: Acela 2158(28) operating with power car 2121, 2123, and 317 customers onboard was delayed less than 1 mile west of New London, CT at milepost 123.0 on the Amtrak NHB Line due to faults on power car 2121. The faults caused the pantographs to drop and head end power to become disengaged at 6:50 p.m. The temperature outside was 79 degrees and clear and customers were reported as comfortable onboard. The crew was able to work with hi-speed rail mechanical and Amtrak management to de-prepare and re-prepare the train set to reset the power car. The train was back on the move at 7:24 p.m. with head end power reinstated. Train 177(28) and Acela 2193(28) were both delayed holding at Palmers Cove milepost 128.1 until 2158(28) was back on the move.

Train	Delay	Comment
2158(28)	42"	
177(28)	23"	
2193(28)	09"	

Train 97(28) North of Washington, D.C. - Car Failure

28AUG26: Train 97(28) operating with engine 605 and 298 customers onboard was delayed north of Washington D.C. stopped at milepost 117.3 due to an air hose needing to be resecured between car 62016 and car 62019 after becoming loose and putting the train into emergency.

Train	Delay	Comment
97(28)	31"	

Train 53(28) South of Lorton, VA - Freight Train Interference

28AUG26: Train 53(28) operating with engines 352, 317, and 344 customers onboard was delayed 9 miles south of Lorton, VA on the CSX RFP subdivision holding at CFP83.0 waiting for BD dispatcher to give permission by high/wide restriction on M407-28.

Train	Delay	Comment
53(28)	30"	

Train 2155(28) East of Princeton Junction, NJ - Engine Failure

28AUG26: Train 2155(28) at 00000008730 UNCLASSIFIED 9/2/2026 was delayed west of Adams on the Amtrak NYP Line on track three due to the pantographs dropping on the equipment. There was a high-speed technician onboard that was able to assist the crew to troubleshoot the issue. The pantograph was able to be raised and the train advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2155(28)	41"	

Train 474/417(28) - Cancelled Equipment Shortage

28AUG26: Due to equipment shortage of shuttle sets, train 474(28) and 417(28) were cancelled in their entirety with 2 DATCO buses sourced as alternate transportation for both trains.

WBS#: B.TR.100150.7106

Train 41(27) East of Cumberland, MD - Freight Train Interference

28AUG26: Train 41(27) operating with engines 182, 136, 10 cars, and 143 customers onboard was delayed at milepost 164.1, 14 miles east of Cumberland, MD on the CSX Cumberland subdivision due to meeting CSX freight train E792-27. Once the freight train cleared, Train 41(27) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(27)	33"	

Train 20(27) South of Culpeper, VA - Trespasser Incident

28AUG26: Train 20(27) operating with engines 342, 320, 384, 8 cars, and 198 customers onboard struck a vehicle at milepost 67.6, 0.2 miles south of Culpeper, VA on the NS Washington District. The vehicle strike was not fatal. The strike occurred at a crossing, DOTX714682K. The crossing was equipped with crossbucks, signs and signals. The train maintained head end power and was intact on the rails. The weather was 83 degrees and mostly sunny. There were no injuries reported to the crew or the customers. There was no damage to the equipment and minimal damage to the vehicle. The police responded to the scene and released the train. Once the train was released by the police and NS, Train 20(27) advanced to the next station.

National Response Center Number: 1472118

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(27)	1'13"	

Train 178(28) Roanoke, VA - Car Failure

28AUG26: Train 178(28) operating with engine 369, 10 cars, and 125 customers was delayed departing Roanoke, VA on the NS Roanoke Terminal District due to setting out shopped car 82539 for bad brakes. The car was set out, and the train departed the station with 9 cars.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
178(28)	40"	

Train 95(28) Route 128, MA - Engine Failure

28AUG26: Train 95(28) 26-FOI-00703 00000008730 UNCLASSIFIED 8/2/2026 was stopped at Route 128, MA on the Amtrak NHB Line due to mechanical issues with engine 639. the crew worked with the road foreman to troubleshoot. The engine was successfully recycled and the train advanced to the next station. The train had the same issue when it arrived into Kingston Station. The crew declared cab signal and cut them out. Train 95(28) advanced to New Haven operating at 59 MPH. Once the train arrived in New Haven, engine 629 was added to the consist.

Train 125(28) operated from New Haven to Washington with a diesel engine. The train was required to operate at diesel speeds.

There was an equipment shortage in New Haven due to there being no diesel. As a result, trains 474(28) and 417(28) were cancelled in their entirety. Alternate transportation was secured. Two buses were sourced for Train 474(28).

Train	Delay	Comment
95(28)	34"	RTE
95(28)	1'16"	KIN-NHV
95(28)	22"	KIN
494(28)	Cancelled	
417(28)	Cancelled	
95(28)	28"	NHV

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 43(28) Passenger Removal at Johnstown, Pennsylvania – Fare Evader***

28AUG26, Passenger on PNR Unknown, traveling from Paoli, PA to Johnstown, PA was removed from the train by conductor. The passenger was unable to provide a ticket after being asked by conductor. Amtrak Police notified.

Delay: 43 (28) None

Train 657(28) Passenger Removal at Harrisburg, Pennsylvania – Fare Evader

28AUG26, Passenger on PNR Unknown, traveling from Lancaster, PA to Harrisburg, PA was removed from the train by conductor. The passenger boarded the train without a ticket. The passenger became argumentative when asked to purchase a ticket. Amtrak Police notified.

Delay: 657 (28) None

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Western Region

Operating Highlights

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Train 2(26) Houston, TX - Routing

29AUG26: Train 2(26) was delayed departing Houston TX station/MP362.3 on the UPRR Lafayette routing around until MP280 due to freight trains departing Englewood blocking the normal route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2 (26)	54"	

Train 11(28) South of Klamath Falls, OR - Signal

29AUG26: Train 11(28), operating with engines, 349/378, 9 coaches and 182 customers, was stopped south of Klamath Falls, Oregon, at Milepost 393.4, on UP Black Butte subdivision, due to a switch ahead of the train that was out of correspondence. A Union Pacific switch maintainer responded to the scene to assess the issue. Upon inspection, Union Pacific personnel determined that the switch was broken and required repairs. Union Pacific initially estimated that the repair work would take approximately 30 minutes to complete. After the necessary repairs were made, the switch was restored to service, and Train 11(28) resumed movement and continued its trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(28)	1'35"	Witronix estimate

Train 383(28) East of Galesburg, IL - Routing

28AUG26: Train 383(28) was delayed holding at MP155.3, 8.84 miles east of Galesburg, IL station on the BNSF Mendota subdivision due to a yard crew blocking the route ahead. Train 383(28) was back on the move at 927PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(28)	1'00"	

Train 21(27) North of Austin, TX - Freight Train Interference

28AUG26: Train 21(27) was delayed holding at MP146.2, 33.58 miles north of Austin TX station on the UPRR Austin subdivision meeting UP freight train 6053. Train 21(25) was back on the move at 810PM CT after the freight train cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(27)	50"	

Train 822(28) South of Gainesville, TX - Freight Train Interference

28AUG26: Train 822(28) was delayed holding in the Metro siding/MP388.5, 22.30 miles south of Gainesville TX station on the BNSF Fort Worth subdivision meeting BN freight train ZWSPALT327U. Train 822(28) was back on the move at 656PM CT after the freight cleared to the south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822(28)	42"	

Train 717(28) East of Martinez, CA - PTC Red Fence

29AUG26: Train 717(28) was delayed with engine 2013, 8 coaches, and carrying 97 customers, was stopped east of Martinez, CA, due to a Positive Train Control (PTC) issue that resulted in a red fence condition. The crew worked with the Union Pacific PTC Desk to troubleshoot and resolve the problem. As part of the troubleshooting process, the crew attempted to reverse behind their last signal and proceed again on signal indication; however, this effort was unsuccessful. During the incident, an Amtrak Road Foreman was dispatched to Martinez, CA, to provide assistance. At the same time, Train 704(28) experienced similar PTC-related issues and was also engaged in troubleshooting efforts.

Train 704(28) successfully resolved its issue by resetting the PTC breaker and reinitializing the PTC system, allowing the train to resume movement after an approximate delay of one hour. Following the successful resolution on Train 704(28), Train 717(28) performed the same procedure but were unsuccessful. After continual efforts of UP PTC desk, they were able to restore PTC. As a result, Train 717(28) resumed normal operations, and the Oakland, CA, yard crew protected the train into Oakland, CA.

Train	Delay	Comment
717(28)	2'25"	
704(28)	1'03"	
718(28)	1'56"	Holding MTZ for Open Route
718(28)	08"	PTC Failure

Train 5(28) East of Ottumwa, IA - Freight Train Interference

28AUG26: Train 5(28) was delayed beginning at MP250.2, 30.01 miles east of Ottumwa, IA station on the BNSF Ottumwa subdivision following BNSF freight train 6029. Train 5(28) was able to get around the freight after departing Ottumwa IA station.

Train	Delay	Comment
5(28)	30"	

Train 588/593(28) - Cancelled - Engine Failure

29AUG26: Due to engine failure of engine CDTX 2114, train 588(28) was cancelled and customers were accommodated on train 790(28). Train 593(28) was cancelled and customers were accommodated on train 595(28).

Train 719(28) East of Madera, CA - Passenger Train Interference

29AUG26: Train 719(28), operating with engine 2006, 8 coaches, and 132 customers, was delayed 12 mile east of Madera, CA, on BNSF Stockton subdivision, due to meeting train 716(28).

Train	Delay	Comment
719(28)	30"	

Train 786(28) West of Chatsworth, CA - Commuter Train Interference

28AUG26: Train 786(28), operating with engine 2113, six coaches, and 205 customers, was delayed 5 miles west of Chatsworth, CA, on SCRRA Ventura subdivision, due to meeting metro train 127.

Train	Delay	Comment
786(28)	31"	

Train 22(28)/422(26) McGregor, TX - Injured or Sick Passenger or Employee

28AUG26: Train 22(28)/422(26) was delayed at McGregor, TX station on the BNSF Fort Worth subdivision on the BNSF Fort Worth subdivision due to a passenger medical emergency. Local emergency responders arrived to the scene to assist the passenger. Emergency responders transported the passenger to a local hospital for care. Train 22(28)/422(26) was back on the move at 512PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(28)/422(26)	1'24"	

Train 8/28(27) East of Malta, MT - Freight Train Interference

29AUG26: Train 8/28(27), operating with engines 37/179, 10 coaches and 202 customers, was delayed 27 miles east of Malta, MT, on BNSF Milk River subdivision, due to meeting BNSF8461, BNSF8139, BNSF3971 at Saco, Siding, and Tampico sidings.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(27)	54"	

Train 539(28) Oakland, CA - Police Related

28AUG26: UPRR reported that a hold had been placed on all traffic on the Niles Subdivision at MP 16.74 due to a propane tank being located on the tracks. Train 539(28) operating with engine 2123, five coaches and 110 customers, arrived at OAC at 2:04 PM, 10 minutes late, and was held awaiting the reopening of the track. A track inspector was dispatched to assess the situation with an estimated arrival time of 15 to 25 minutes. Once the obstruction was addressed, Train 539(28) resumed movement. As a result of the incident and track closure, operations experienced an approximate delay of 35 minutes.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
539(28)	30"	

Train 530(28) East of Martinez, CA - Drawbridge Opening

28AUG26: Train 530(28) was delayed at MP 32.7, 1 miles east of Martinez, CA, on the UPRR Martinez Subdivision due to the Suisun Bridge being raised for maritime traffic. Once all maritime traffic cleared, Train 530(28) proceeded east.

Train 543(28) was delayed departing Sacramento, CA due to the late turn of equipment from Train 530(28). Once the equipment arrived and all customers detrained, Train 543(28) boarded and was able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
530(28)	28"	
543(28)	12"	ITD SAC- Turn of equip

Train 311(28) West of Independence, MO - Trespasser Strike

28AUG26: Train 311(28) consisted of 10 cars, struck a trespasser at 2:00PM-CT approximately 1.4 miles west of Independence, MO (MP273.3), on the UPRR Sedalia Subdivision at MP274.7 in Jackson County. RMCC requested a hold on all traffic following the incident. Train 311(28) was operating at 39MPH at the time of the strike, which did not occur at a crossing and was determined to be fatal. There were no injuries reported to the crew or the 75 customers onboard. Weather conditions at the time were 84 degrees and sunny. Independence Police and Fire personnel, along with UP management, responded quickly to the scene. Amtrak's Kansas City Road Foreman was enroute to the strike location but the scene was released prior to arrival. Head end power remained active throughout the incident, and there was no reported damage to the equipment. Following release by local authorities, the crew stated they would take the train into Kansas City. At 3:46PM-CT, Train 311(28) was released by officials to continue to Kansas City.

Train 316(28) was delayed departing Kansas City, MO (MP 6.9), on the Kansas City Terminal KCT Subdivision, due to a late turn of Train 311(28)'s equipment that arrived at 4:05PM-CT, 2 hours and 15 minutes late.

National Response Center Number: 1472134

Train	Delay	Comment
311(28)	1'48"	
316(28)	35"	ITD KCY

Train 713(28) East of Madera, CA - Freight Train Interference

28AUG26: Train 713(28) was delayed at Gregg/MP 1010.4, 14 miles east of Madera, CA, on the BNSF Stockton Subdivision due to freight interference. The crew held at MP 1010.4 for BN7810 and another BNSF freight to clear route. Once route was clear, Train 713(28) proceeded west.

Train	Delay	Comment
713(28)	38"	

Train 8/28(27) West of Essex, MT - Freight Train Interference

28AUG26: Train 8/28(27) was delayed at Pinnacle/MP 1173.2, 5 miles west of Essex, MT, on the BNSF Hi Line Subdivision due to freight interference. The crew held at MP 1173.2 until BN7829 and BN7293 cleared route. Once route was clear, Train 8/28(27) proceeded east.

Train	Delay	Comment
8/28(27)	33"	

Train 715(28) Emeryville, CA - Third Party Contractor Cab Car Failure

28AUG26: Train 715(28), E/C2004-7 cars-CC/C6961, was terminated in Emeryville, CA due to electrical cable issues on CC/6961. The 23 impacted customers traveling between Emeryville and Oakland were reaccommodated on 547(28). The equipment was deadheaded to the Oakland Maintenance Facility for repairs and servicing.

Train	Delay	Comment
715(28)	Term	EMY

Train 713(28) Emeryville, CA - Third Party Contractor Engine Failure

28AUG26: Due to issues with E/C2005 reclassification a locomotive swap for the turn of equipment on Train 718(28), Train 713(28), E/C2005-7 cars-CC/C8312, was terminated in Emeryville, CA. The 28 impacted customers traveling Emeryville to Oakland were reaccommodated on Train 543(28). The equipment was then deadheaded from Emeryville to the Oakland Maintenance Facility to begin the locomotive swap.

Train	Delay	Comment
713(28)	Term EMY	
718(28)	1'28"	Eng swap/Air Hose Replacement

Train 2(26) West of Houston, TX - Freight Train Interference

28AUG26: At 11:30AM-CT, Union Pacific 5492 reported striking an 18-wheeler with a dump truck 27.2 miles west of Houston, TX (MP362.3), on the UPRR Glidden Subdivision at MP26.4. Both main tracks were shut down due to reported debris on the tracks and track damage on Main Track 1. At 12:09PM-CT, Train 2(26), with 89 customers onboard, stopped at MP28.1. Union Pacific stated that the delay was expected to be extensive. As a result, a detour was established via the BNSF Mykawa Subdivision from Rosenberg (MP38.4) into Houston Station. The detour was expected to take 90 minutes to complete with no missed stops. Train 2(26) shoved back 8 miles to Rosenberg to meet the BNSF pilots, who were on location at 2:15PM-CT. At 3:00PM-CT, the detour movement began arriving into Houston Station at 551PM CT. The current crew was scheduled to expire at 6:15PM-CT, and a relief crew with pilots, who went on duty at 4:00PM-CT, were arranged to meet the train at Houston TX station.

Train	Delay	Comment
2(26)	5'13"	
2(26)	1'05"	Re-crew

UPRR Martinez Subdivision - Trackside Fire

28AUG26: At 5:39A- PT, due to a trackside fire at MP 12.4 on the UPRR Martinez Subdivision, a quarter mile east of Richmond, CA, the UPRR placed a hold on all tracks while the local fire department worked to put fire out. Once the fire was extinguished, the tracks needed to be inspected. Train 521(28) held at MP 12.14 and Train 520(28) held at Richmond station/ MP 12.1 for the track inspector to arrive. The track inspector arrived at 6:30A-PT and once inspection was complete, train traffic resumed.

Train	Delay	Comment
520(28)	39"	
521(28)	44"	

Train 6(27) West of Helper, UT - Animal Strike

28AUG26: Train 6(27), E/163-E/196-9 cars, was delayed at MP 647, 20 miles west of Helper, UT, on the UPRR Provo Subdivision after striking an animal. After striking the animal, the crew performed a running brake test then proceeded east at track speed.

Train	Delay	Comment
6(27)	02"	

Train 522(28) Oakland, CA - PTC Issues

28AUG26: Train 522(08) 26-FOI-00703 00000008780- UNCLASSIFIED was delayed departing Oakland, CA due to PTC issues. While attempting to log in the crew experienced a timing out issues while the UPRR information was loading. The crew contacted the UPRR PTC desk to troubleshoot issues. Once issues were resolved, the crew was able to depart.

Train	Delay	Comment
522 (28)	41"	

Train 49(27) West of Toledo, OH - Freight Train Interference

28AUG26: Train 49(27) was delayed beginning 25.7 miles west of Toledo, OH (MP288.3) on the NSRR Chicago Line while following NS 25E from MP314 to MP423 due to freight interference. Train 40(26) was also delayed through the area while trailing Train 49(27). As a result, Train 351(28) was delayed at Porter (MP482.2) while following both trains into Chicago Union Station.

Train	Delay	Comment
49(27)	55"	
351(28)	16"	
40(26)	42"	

Train 7/27(26) East of Spokane, WA - Signal Issues

28AUG26: Train 7/27(26) was delayed starting at Otis Orchards/ MP 58.9, 11 miles east of Spokane, WA, on the BNSF Spokane Subdivision due to signal issues. The crew operated at restricted speed from MP 58.9 to Park Water/ MP 66.1 then hand lined switch at Irvin/MP 63.0. Once through the affected area, Train 7/27(26) proceeded west.

Train 8/28(27) was delayed at Irvin/MP 63.0 holding for Train 7/27(26) to operate through affected area.

Train	Delay	Comment
7/27(26)	31"	
8/28(25)	37"	

Train 21(27) South of Marshall, TX - Freight Train Interference

28AUG26: Train 21(27) was delayed 7.4 miles south of Marshall, TX (MP66.5), on the UPRR Little Rock Subdivision at Keokuk (MP73.9) due to MBZLI-27 (UP 7406) experiencing an undesired emergency ahead at MP72. The freight crew walked the train and identified a broken knuckle. A carman responded to assist with the repair. Once the knuckle was replaced and MBZLI-27 cleared the area, Train 21(27) was able to proceed south.

Train	Delay	Comment
21(27)	1'22"	

Train 301(28) North of Bloomington-Normal, IL - Debris

28AUG26: At 9:11AM-CT, Train 301(28), E/ID4624-5 Cars, went into emergency 21.7 miles north of Bloomington-Normal, IL (MP124.0), on the UPRR Joliet Subdivision, after traversing the Chenoa diamond at MP102.3. The Conductor reported having to replace the hose on car ID4310 due to a crack in the glad hand. There were no injuries to the crew or 199 customers onboard. There was no damage to the equipment. Once the hose was replaced and air restored, Train 301(28) was back on the move south at 9:38AM-CT.

Train	Delay	Comment
301(28)	29"	

Train 300(28) North of Joliet, IL - Near Miss

28AUG26: At 8:39AM-CT, Train 300(28) went into an emergency stop on the CNRR Joliet Subdivision at MP23.4, approximately 13.9 miles north of Joliet, IL (MP37.3), to avoid striking a semi-truck on the tracks. No collision occurred, and there were no injuries to the crew or 279 customers onboard. No damage was reported to the equipment. At 8:47AM-CT, the air was restored and Train 300(28) resumed movement toward Chicago Union Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
300 (28)	06"	

Train 2(26) San Antonio, TX - Engine Failure

28AUG26: Train 2 (26), E/344-E/313-7 Cars, was delayed departing San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision due to locomotive mechanical issues. The equipment arrived at 6:12AM-CT, after which mechanical forces repaired a diesel pump failure on engine 344. Once repairs were completed, additional time was required to troubleshoot and correct head end power issues affecting both locomotives. After the mechanical issues were resolved, Train 2(26) continued its trip to New Orleans.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2 (26)	44"	

Train 40(26) West of Toledo, OH - Freight Train Interference

28AUG26: Train 40(26) was delayed starting 1.7 miles west of Toledo, OH (MP288.3), on the NSRR Chicago Line, following NS 29G from MP290 to MP340.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40 (26)	40"	

Train 59(27) South of Newbern-Dyersburg, TN - Freight Train Interference

28AUG26: Train 59(27) was delayed starting 8.6 miles south of Newbern-Dyersburg, TN (MP305.6), on the CNRR Fulton Subdivision, following CN M334 from Dyersburg (MP314.2) to Rialto (MP349.8).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59 (27)	35"	

Train 3(26) West of Flagstaff, AZ - Freight Train Interference

28AUG26: Train 3(26) was delayed 74.2 miles west of Flagstaff, AZ (MP344.2), on the BNSF Seligman Subdivision, at East Crookton (MP418.4) in order to meet BNSF 8128). Additional delay was incurred at Yampai (MP453.8) meeting BNSF 7105.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3 (26)	36"	

Train 22(27) North of Poplar Bluff, MO - Signal

28AUG26: Train 22(27) was delayed beginning 47.4 miles north of Poplar Bluff, MO (MP165.6) on the UPRR Desoto Subdivision due to signal issues at Gads Hill (MP118.2). As a result, operating speeds were restricted until the train reached a clear signal at Annapolis (MP108.9).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 22(27) North of Arkadelphia, AR - Freight Train Interference

28AUG26: Train 22(27) was delayed starting at Arkadelphia, AR (MP410.9), on the UPRR Little Rock Subdivision, following UP 6247 to Saline Jct (MP370.3).

Train	Delay	Comment
22(27)	51"	

Train 4(27) Needles, CA - Freight Train Interference

28AUG26: Train 4(27) was delayed beginning 44.6 miles west of Needles, CA (MP578.0) on the BNSF Needles Subdivision while following BNSF 3824 from Fenner (MP622.6) into the station

Train	Delay	Comment
4(27)	45"	

Train 22(27) East of Dallas, TX - Heat Orders

28AUG26: Train 22(27) was delayed starting 4.4 miles east of Dallas, TX (MP214.4), on the UPRR Mineola Subdivision, due to heat orders in effect from MP210 to MP67.

Train	Delay	Comment
22(27)	52"	

Train 7/27(26) Spokane, WA - Engine Failure

28AUG26: Train 7/27(26), operating with engine 377/368, 10 coaches, 202 customers will terminate its 27(26) section at Spokane, WA, due to a fault code indicating a bad fuel pump on trailing loco 368. A BNSF freight was sourced (BNSF6572) to assist out of Spokane. The entire consist of 7/27(26) will travel to Seattle where loco 368 can be repaired. Buses were sourced for customers traveling Spokane to Portland and for customers traveling Portland to Spokane on train 28(28).

Train 7(26) was delayed departing Spokane, WA due to brake issues. The crew found a brake pipe issue on lead E/377, which mechanical was unable to resolve, therefore BN6572 was removed from consist. Once the freight was removed, the crew was able to perform brake test and depart. Due to the issues with trail E/368, mechanical monitored into Seattle.

Train 28(28) originated in Spokane, WA with two buses secured to accommodate customers traveling between Portland and Spokane.

WBS#: B.TR.100150.7102

Train	Delay	Comment
7/27(26)	1'27"	Brake Pipe issue SPK
27(26)	Term SPK	
28(28)	Orig SPK	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task scheduled on C&M Subdivision at Western Avenue -
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In
order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be
adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues
22 (18)	XNT	315		I/O 47 faults

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (28)	SEA	BNSF6688	E/368 Fuel inj faults		
22 (28)	SAS	UP5068	E/325 Battery faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 43(28) Passenger Removal at Johnstown, Pennsylvania – Medical

28AUG26, Passenger on PNR 48021F, traveling from Philadelphia, PA to Johnstown, PA was removed from the train by Johnstown EMS. The passenger was complaining of having chest pains. Amtrak Police notified.

Delay: **43 (28)** **02"**

Consist Deviations

26-FOI-00703

00000008730

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
95 (28)	BOS	BUSINESS CLASS CAR IN LIEU OF A COACH CAR. INVENTORY REDUCED. PLEASE NOTIFY EFFECTED PAX IF ANY.	0 impact	0	81514
301 (28)	CHI	TRAIN WILL OPERATE WITH ONE LESS COACE DUE TO B/O PA SYSTEM.	n/a	0	ID4104
59 (27)	CHI	OPERATING WITH DINER 38032 IN CONSIST IN LIEU OF DINER/LOUNGE A/C 37005 UTILIZED IN 3(27) BECAUSE DINER WASN'T REPAIRED IN TIME.	n/a	0	38032
21 (28)	CHI	OPERATING WITH DINER 38066 IN LIEU OF DINER/LOUNGE A/C 37013 BYD FOR HVAC ISSUES.	n/a	0	38066
5 (28)	CHI	OPERATING WITH STANDARD COACH IN LIEU OF BAGGAGE COACH DUE TO NO GOOD CAR ON THE CHI YARD.	n/a	0	34096
59 (28)	CHI	OPERATING WITH EXTRA COACH IN LIEU OF SLEEPER A/C 32071 UTILIZED IN 7(28) DUE TO HIGH SHOP COUNT NO REPLACEMENT CAR.	ALL PAX REACCOM EXCEPT 7 DOWNGRADES	7	34113
448 (29)	CHI	ALL TABLE CAR IN LIEU OF AMII LOUNGE. NO CUSTOMER IMPACT.	n/a	0	43349
41 (29)	CHI	VII IN LIEU OF VI FOR 4111(*29*) CAR. TWO LESS ROOMS. SCHEUDLE CHANGE PERFORMED. CHECK WAR REPORT.	SVWR41/29AUG NO WAR DATA THIS TRAIN/DATE	0	62514
6 (31)	EMY	OPERATING WITH STANDARD COACH IN LIEU OF BAGGAGE COACH DUE TO NO GOOD CAR ON THE CHI YARD.	n/a	0	34096
782 (28)	GTA	Due to equipment swap 90225 in consist will not be able to accomodate passenger with BV reservation. CNOC CSV will	NO BV	1	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00703 00000008730 "UNCLASSIFIED" 9/2/2026			
		need to reaccommodate any passengers impacted by this.			
316 (28)	KCY	ID4017 DHing inline due to byd hvac. inventory reduced. train is overcapacity (-13 @WAR).	fare protect pax	0	ID4017
98 (29)	MIA	98(*29*) will go out with a VII in lieu of a VI for the 9811 car. schedulechanges performed for 9810 and 9811. check war report	n/a	0	625XX
58 (30)	NOL	OPERATING WITH EXTRA COACH IN LIEU OF SLEEPER A/C 32071 UTILIZED IN 7(28) DUE TO HIGH SHOP COUNT NO REPLACEMENT CAR.	n/a	0	34113
761 (28)	SAN	Due to equipment swap 90225 in consist will not be able to accomodate passenger with BV reservation. CNOC CSV will need to reaccommodate any passengers impacted by this.	NO BV	2	90225
593 (28)	SAN	Due to equipment swap 90225 in consist will not be able to accomodate passenger with BV reservation. CNOC CSV will need to reaccommodate any passengers impacted by this.	NO BV	0	90225
306 (28)	STL	TRAIN WILL OPERATE WITH ONE LESS COACE DUE TO B/O PA SYSTEM. INVENTORY REDUCED, PLEASE NOTIFY EFFECTED PAX.	n/a	0	ID4104
311 (28)	STL	ID4017 D/Hing inline due to BYD HVAC. inventory reduced. not overcapacity.	no pax impact	0	ID4017

Reverse Consists

Train Number	Station	Reason
95 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00703	00000008730 "UNCLASSIFIED" 9/2/2026
173 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
113 (28)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
84 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
193 (28)	NYP	Consist reversed Business class seat orientation may have changed At Front	
136 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
197 (28)	NYP	Business class change only Business class seating orientation may have changed At Rear	
158 (29)	NFK	Consist reversed Business class seat orientation may have changed At Front	
128 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front	