

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, August 30, 2026

Rules: 3-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/29/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/29/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	286	50	82.5%	8,954	1,344	85.0%	99,898	13,896	86.1%
Central Division	86.0%	59	9	84.7%	1,652	195	88.2%	19,080	1,769	90.7%
East Division	82.0%	143	18	87.4%	4,816	677	85.9%	52,486	8,095	84.6%
West Division	86.0%	84	23	72.6%	2,486	472	81.0%	28,332	4,032	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00703 00000008729 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	97,969	30,179	69%	3,053,830	884,287	71%	33,386,828	8,525,637	74%
Northeast Corridor	81%	41,122	7,915	81%	1,325,906	313,574	76%	14,627,419	3,569,602	76%
Acela	83%	6,916	232	97%	281,425	52,786	81%	2,941,849	754,337	74%
Northeast Regional	79%	34,206	7,683	78%	1,044,481	260,788	75%	11,685,570	2,815,265	76%
Richmond / Newport News / Norfolk	77%	11,143	1,948	83%	322,919	105,406	67%	3,622,895	1,066,867	71%
Springfield Shuttles	89%	591	114	81%	18,054	3,148	83%	205,781	33,016	84%
Roanoke	79%	2,138	1,680	21%	103,185	29,124	72%	1,108,469	247,780	78%
On Spine Northeast Regional	80%	20,334	3,941	81%	600,323	123,110	79%	6,748,425	1,467,602	78%
State Supported	80%	44,803	15,568	65%	1,383,812	373,874	73%	14,693,431	3,179,799	78%
Borealis	80%	520	0	100%	17,136	4,160	76%	186,762	39,792	79%
Capitol Corridor	90%	3,401	986	71%	109,110	17,783	84%	1,224,829	163,532	87%
Carolinian	70%	891	402	55%	31,066	12,302	60%	375,948	147,301	61%
Cascades	75%	2,637	675	74%	62,684	24,616	61%	845,934	239,652	72%
Downeaster	82%	1,862	0	100%	56,584	5,809	90%	516,897	61,764	88%
Empire	78%	6,378	4,394	31%	185,807	65,718	65%	1,829,520	449,177	75%
Adirondack	72%	338	241	29%	13,153	6,003	54%	113,116	36,848	67%
Ethan Allen Express	70%	504	494	2%	16,918	10,997	35%	185,826	71,346	62%
Maple Leaf	70%	973	415	57%	26,692	12,314	54%	227,041	89,157	61%
New York - Albany	85%	2,815	1,641	42%	82,159	20,850	75%	844,507	146,777	83%
New York - Niagara Falls	75%	1,748	1,603	8%	42,755	13,011	70%	446,787	98,692	78%
Berkshire Flyer	60%	0	0	-	4,130	2,543	38%	12,243	6,357	48%
Gold Runner	73%	2,324	1,134	51%	69,274	35,730	48%	824,840	306,183	63%
Heartland Flyer	70%	256	180	30%	6,462	4,469	31%	71,145	29,891	58%
Hiawatha	90%	2,027	499	75%	59,306	5,557	91%	580,225	63,254	89%
Illinois	78%	3,402	360	89%	77,042	27,195	65%	823,266	231,750	72%
Carl Sandburg / Illinois Zephyr	85%	570	39	93%	12,158	5,080	58%	136,958	39,238	71%
Illini / Saluki	85%	993	273	73%	24,310	8,800	64%	284,197	70,700	75%
Lincoln Service	70%	1,839	48	97%	40,574	13,315	67%	402,111	121,812	70%
Keystone	92%	5,733	0	100%	229,653	16,983	93%	2,511,772	256,529	90%
Lincoln / Missouri	70%	667	379	43%	23,679	16,334	31%	256,170	134,642	47%
Mardi Gras Service	80%	337	68	80%	8,801	2,069	76%	132,522	29,684	78%
Michigan	70%	2,458	906	63%	71,346	32,312	55%	668,771	224,733	66%
Blue Water	70%	572	31	95%	17,923	9,336	48%	157,581	65,164	59%
Pere Marquette	85%	387	0	100%	7,552	1,234	84%	85,986	16,358	81%
Wolverine	70%	1,499	875	42%	45,871	21,742	53%	425,204	143,211	66%
Missouri	80%	210	158	25%	7,096	4,378	38%	72,932	20,814	71%
Pacific Surfliner	85%	8,244	4,953	40%	276,624	74,477	73%	2,688,796	504,184	81%
Pennsylvanian	80%	832	0	100%	25,271	4,349	83%	291,073	55,426	81%
Piedmont	80%	1,373	243	82%	29,179	5,657	81%	369,453	94,309	74%
Vermont	75%	1,251	231	82%	37,692	13,976	63%	422,576	127,182	70%
Long Distance	70%	12,044	6,696	44%	344,112	196,839	43%	4,026,711	1,773,773	56%
Auto Train	70%	709	366	48%	24,253	7,148	71%	258,662	87,937	66%
California Zephyr	70%	821	292	64%	27,778	18,289	34%	319,372	124,946	61%
Cardinal	70%	254	237	7%	5,291	3,541	33%	76,772	39,084	49%
City Of New Orleans	75%	662	319	52%	16,936	13,552	20%	208,160	71,731	66%
Coast Starlight	70%	1,145	507	56%	30,123	13,044	57%	374,800	133,506	64%
Crescent	70%	831	344	59%	23,399	7,777	67%	303,052	93,760	69%
Empire Builder	70%	1,142	819	28%	30,638	18,198	41%	319,005	160,403	50%
Floridian	60%	1,639	1,167	29%	39,352	32,133	18%	517,118	359,175	31%
Lake Shore Ltd	73%	1,104	251	77%	33,288	11,904	64%	320,525	97,010	70%
Palmetto	70%	856	19	98%	25,406	11,550	55%	301,509	94,159	69%
Silver Meteor	70%	853	513	40%	27,529	17,175	38%	332,729	154,526	54%
Southwest Chief	60%	702	702	0%	25,256	20,241	20%	275,722	182,834	34%
Sunset Ltd	70%	297	297	0%	6,922	5,261	24%	95,288	38,029	60%
Texas Eagle	70%	1,029	863	16%	27,941	17,026	39%	323,997	136,673	58%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00700 00000000720 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 29, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	196,333	3,109,089	631	1,986,412	35,057,027	567

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	10,128	944,798	107	96,040	10,141,800	95
INFRASTRUCTURE PLANNED	135	18,417	944,798	195	114,472	10,141,800	113
FLEET RELIABILITY	90	31,210	3,109,089	100	317,350	35,057,027	91
TRAIN OPERATIONS	424	136,578	3,109,089	439	1,458,550	35,057,027	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/29/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/29/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	286	50	82.5%	8,954	1,344	85.0%	99,898	13,896	86.1%
Central Division	86.0%	59	9	84.7%	1,652	195	88.2%	19,080	1,769	90.7%
East Division	82.0%	143	18	87.4%	4,816	677	85.9%	52,486	8,095	84.6%
West Division	86.0%	84	23	72.6%	2,486	472	81.0%	28,332	4,032	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/29/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/29/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	286	50	82.5%	8,954	1,344	85.0%	99,898	13,896	86.1%
Central Division	86.0%	59	9	84.7%	1,652	195	88.2%	19,080	1,769	90.7%
CDL	95.0%	2	0	100.0%	56	6	89.3%	632	31	95.1%
CHI	86.0%	27	5	81.5%	767	127	83.4%	8,817	1,094	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	29	2	93.1%	356	38	89.3%
GBB	-	-	-	-	2	1	50.0%	15	12	20.0%
GRR	95.5%	1	0	100.0%	24	3	87.5%	312	11	96.5%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	57	10	82.5%	644	54	91.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	168	12	92.9%	1,948	126	93.5%
MOE	97.5%	2	0	100.0%	58	0	100.0%	663	9	98.6%
MSP	96.5%	1	0	100.0%	29	1	96.6%	326	7	97.9%
NOL	94.5%	5	1	80.0%	128	4	96.9%	1,401	64	95.4%
OKC	97.0%	1	0	100.0%	29	0	100.0%	327	6	98.2%
PNT	88.0%	3	0	100.0%	83	9	89.2%	870	73	91.6%
PTH	93.0%	1	0	100.0%	29	2	93.1%	321	13	96.0%
QCY	91.0%	2	0	100.0%	50	5	90.0%	627	48	92.3%
SAS	90.5%	1	1	0.0%	29	6	79.3%	330	39	88.2%
STL	89.0%	4	0	100.0%	113	6	94.7%	1,288	106	91.8%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	143	18	87.4%	4,816	677	85.9%	52,486	8,095	84.6%
ALB	88.5%	8	1	87.5%	219	12	94.5%	2,469	187	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	2	60.0%	145	17	88.3%	1,611	175	89.1%
BOS	85.5%	17	1	94.1%	506	34	93.3%	5,669	638	88.7%
BRK	92.5%	5	0	100.0%	133	10	92.5%	1,585	112	92.9%
BTN	82.0%	1	0	100.0%	27	1	96.3%	317	42	86.8%
CLT	91.5%	5	0	100.0%	145	15	89.7%	1,622	165	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	51	3	94.1%	644	60	90.7%
GRO	-	-	-	-	16	0	100.0%	49	10	79.6%
HAR	79.5%	7	1	85.7%	323	45	86.1%	3,687	593	83.9%
HFD	-	-	-	-	39	4	89.7%	230	19	91.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	29	1	96.6%	329	39	88.1%
MIA	89.5%	2	0	100.0%	54	8	85.2%	654	76	88.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/29/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/29/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	286	50	82.5%	8,954	1,344	85.0%	99,898	13,896	86.1%
East Division	82.0%	143	18	87.4%	4,816	677	85.9%	52,486	8,095	84.6%
MTR	79.0%	1	0	100.0%	29	6	79.3%	316	58	81.6%
NFK	84.5%	2	1	50.0%	58	13	77.6%	741	136	81.6%
NFL	93.5%	2	0	100.0%	58	2	96.6%	670	31	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	2	50.0%	138	33	76.1%	1,692	286	83.1%
NPN	93.0%	2	1	50.0%	58	10	82.8%	630	51	91.9%
NYP	75.5%	36	4	88.9%	1,352	263	80.5%	13,836	3,041	78.0%
PGH	93.0%	1	0	100.0%	29	1	96.6%	330	23	93.0%
PHL	48.0%	4	1	75.0%	136	54	60.3%	1,686	794	52.9%
PIT	76.0%	-	-	-	8	6	25.0%	23	18	21.7%
POR	-	-	-	-	12	7	41.7%	23	15	34.8%
RGH	95.0%	4	0	100.0%	100	5	95.0%	1,258	54	95.7%
RNK	83.5%	2	1	50.0%	58	6	89.7%	654	93	85.8%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	25	0	100.0%	312	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	1	1	0.0%	3	3	0.0%
SAV	96.0%	1	0	100.0%	29	2	93.1%	326	12	96.3%
SFA	88.0%	1	1	0.0%	29	6	79.3%	329	47	85.7%
SPG	92.5%	6	1	83.3%	143	9	93.7%	1,950	114	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	29	3	89.7%	318	63	80.2%
WAS	84.0%	22	1	95.5%	837	100	88.1%	8,309	1,067	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	84	23	72.6%	2,486	472	81.0%	28,332	4,032	85.8%
ARN	92.0%	1	0	100.0%	29	2	93.1%	331	28	91.5%
BFD	79.0%	7	1	85.7%	202	51	74.8%	2,099	444	78.8%
EMY	72.0%	1	0	100.0%	29	5	82.8%	347	99	71.5%
EUG	86.5%	2	0	100.0%	58	3	94.8%	656	59	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	1	1	0.0%	4	2	50.0%	8	5	37.5%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	2	33.3%	87	28	67.8%	996	171	82.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	299	40	86.6%	3,298	366	88.9%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	8	7	12.5%	336	121	64.0%	3,597	949	73.6%
PDX	86.0%	5	0	100.0%	99	35	64.6%	1,587	216	86.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/29/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/29/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	286	50	82.5%	8,954	1,344	85.0%	99,898	13,896	86.1%
West Division	86.0%	84	23	72.6%	2,486	472	81.0%	28,332	4,032	85.8%
SAC	88.5%	12	3	75.0%	425	55	87.1%	4,691	517	89.0%
SAN	90.5%	13	5	61.5%	370	39	89.5%	4,011	383	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	0	100.0%	160	40	75.0%	2,545	387	84.8%
SJC	89.0%	7	1	85.7%	202	19	90.6%	2,326	228	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	87	12	86.2%	759	77	89.9%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	14	4	71.4%	312	30	90.4%
VAC	97.0%	2	0	100.0%	58	0	100.0%	649	14	97.8%
VAN	-	-	-	-	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	140	29	7	75.9%	331	66	80.1%	28	21	25.0%	328	157	52.1%
4	57	29	6	79.3%	330	52	84.2%	29	21	27.6%	330	220	33.3%
5		29	6	79.3%	329	56	83.0%	29	21	27.6%	325	109	66.5%
6	51	29	5	82.8%	328	90	72.6%	29	21	27.6%	328	124	62.2%
7	39	29	9	69.0%	320	51	84.1%	28	12	57.1%	311	86	72.3%
8	114	29	16	44.8%	320	145	54.7%	29	22	24.1%	319	197	38.2%
11		29	15	48.3%	331	72	78.2%	29	7	75.9%	325	67	79.4%
14	32	29	5	82.8%	332	54	83.7%	28	13	53.6%	329	105	68.1%
19	49	29	6	79.3%	330	83	74.8%	29	10	65.5%	327	81	75.2%
20		29	0	100.0%	330	23	93.0%	29	7	75.9%	330	65	80.3%
21	57	29	10	65.5%	327	35	89.3%	29	16	44.8%	326	98	69.9%
22	768	29	6	79.3%	328	37	88.7%	29	17	41.4%	326	98	69.9%
23		29	0	100.0%	332	6	98.2%	29	5	82.8%	330	90	72.7%
24		29	0	100.0%	332	16	95.2%	29	9	69.0%	331	65	80.4%
25		29	0	100.0%	331	3	99.1%	28	11	60.7%	328	94	71.3%
26	22	29	0	100.0%	331	5	98.5%	28	5	82.1%	328	65	80.2%
27		14	6	57.1%	299	22	92.6%	11	5	54.5%	292	98	66.4%
40		25	6	76.0%	321	47	85.4%	24	17	29.2%	317	172	45.7%
41	128	26	10	61.5%	321	124	61.4%	25	22	12.0%	318	246	22.6%
42		29	1	96.6%	332	25	92.5%	29	6	79.3%	330	58	82.4%
43		29	3	89.7%	331	45	86.4%	29	5	82.8%	330	75	77.3%
48	54	29	5	82.8%	330	62	81.2%	29	9	69.0%	329	51	84.5%
49		29	9	69.0%	330	84	74.5%	29	7	75.9%	330	69	79.1%
51	279	9	3	66.7%	135	58	57.0%	10	7	30.0%	131	51	61.1%
52	34	29	6	79.3%	329	47	85.7%	29	4	86.2%	328	76	76.8%
53		29	1	96.6%	329	39	88.1%	29	10	65.5%	328	105	68.0%
54		9	0	100.0%	118	8	93.2%	9	0	100.0%	118	16	86.4%
57		9	0	100.0%	117	5	95.7%	9	1	88.9%	117	10	91.5%
58		28	1	96.4%	305	17	94.4%	27	23	14.8%	303	96	68.3%
59		29	17	41.4%	304	50	83.6%	28	23	17.9%	299	80	73.2%
63	25	29	10	65.5%	333	142	57.4%	29	29	0.0%	327	195	40.4%
64	52	29	3	89.7%	331	71	78.5%	29	23	20.7%	330	132	60.0%
65		9	1	88.9%	102	13	87.3%	9	1	88.9%	100	14	86.0%
66	Cncld	29	3	89.7%	330	64	80.6%	28	6	78.6%	325	60	81.5%
68	90	29	6	79.3%	333	67	79.9%	29	16	44.8%	332	134	59.6%
69		29	11	62.1%	320	79	75.3%	29	12	58.6%	315	55	82.5%
71		29	0	100.0%	328	3	99.1%	28	4	85.7%	326	85	73.9%
72		29	4	86.2%	324	35	89.2%	28	7	75.0%	322	68	78.9%
73	19	29	4	86.2%	327	23	93.0%	29	6	79.3%	325	148	54.5%
74		29	2	93.1%	325	35	89.2%	29	9	69.0%	323	117	63.8%
75	11	29	0	100.0%	321	16	95.0%	29	13	55.2%	315	150	52.4%
76		29	2	93.1%	321	31	90.3%	29	13	55.2%	312	130	58.3%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		29	1	96.6%	323	21	93.5%	29	10	65.5%	321	133	58.6%
78		29	3	89.7%	327	28	91.4%	29	12	58.6%	326	75	77.0%
79	66	29	3	89.7%	330	59	82.1%	29	11	62.1%	329	112	66.0%
80		29	4	86.2%	330	37	88.8%	29	8	72.4%	327	71	78.3%
82		5	1	80.0%	77	10	87.0%	5	0	100.0%	77	24	68.8%
87		9	2	77.8%	121	26	78.5%	9	6	33.3%	121	45	62.8%
88		9	1	88.9%	117	16	86.3%	9	2	77.8%	117	25	78.6%
89		29	13	55.2%	328	78	76.2%	29	11	62.1%	326	96	70.6%
90		29	2	93.1%	328	12	96.3%	29	9	69.0%	327	60	81.7%
97	223	29	19	34.5%	330	217	34.2%	29	20	31.0%	328	120	63.4%
98		29	2	93.1%	330	28	91.5%	29	15	48.3%	328	123	62.5%
99		9	0	100.0%	120	12	90.0%	9	6	33.3%	117	67	42.7%
101		5	2	60.0%	76	8	89.5%	5	1	80.0%	76	12	84.2%
103		9	3	66.7%	119	24	79.8%	9	2	77.8%	119	11	90.8%
106		5	2	60.0%	92	11	88.0%	5	2	60.0%	91	14	84.6%
107		5	2	60.0%	92	30	67.4%	5	2	60.0%	91	15	83.5%
109		5	1	80.0%	59	9	84.7%	5	0	100.0%	59	6	89.8%
118		9	0	100.0%	119	8	93.3%	9	0	100.0%	119	8	93.3%
124	71	9	1	88.9%	118	9	92.4%	9	4	55.6%	117	34	70.9%
126		5	1	80.0%	55	9	83.6%	5	1	80.0%	55	13	76.4%
127		5	3	40.0%	55	17	69.1%	5	0	100.0%	55	6	89.1%
135		9	1	88.9%	120	18	85.0%	9	1	88.9%	120	57	52.5%
136		20	3	85.0%	212	27	87.3%	21	3	85.7%	211	28	86.7%
140		9	2	77.8%	119	14	88.2%	9	4	55.6%	118	28	76.3%
142		5	1	80.0%	75	8	89.3%	5	0	100.0%	74	9	87.8%
143		9	2	77.8%	118	13	89.0%	9	3	66.7%	118	28	76.3%
144		5	4	20.0%	77	52	32.5%	5	2	60.0%	76	11	85.5%
146		9	1	88.9%	118	18	84.7%	9	3	66.7%	118	42	64.4%
147	179	5	2	60.0%	78	10	87.2%	5	3	40.0%	78	27	65.4%
150	18	9	4	55.6%	117	61	47.9%	9	3	66.7%	115	54	53.0%
151		29	8	72.4%	329	103	68.7%	29	4	86.2%	328	99	69.8%
152		5	0	100.0%	77	6	92.2%	5	0	100.0%	77	27	64.9%
153		9	1	88.9%	119	11	90.8%	9	3	66.7%	119	19	84.0%
155	71	9	2	77.8%	121	20	83.5%	9	3	66.7%	121	43	64.5%
156	41	9	1	88.9%	121	12	90.1%	9	4	55.6%	121	42	65.3%
158		9	2	77.8%	120	22	81.7%	9	1	88.9%	120	27	77.5%
159		5	0	100.0%	75	8	89.3%	5	0	100.0%	75	11	85.3%
160		9	2	77.8%	118	8	93.2%	9	1	88.9%	115	27	76.5%
161	33	9	1	88.9%	119	10	91.6%	9	8	11.1%	118	80	32.2%
162		9	3	66.7%	119	10	91.6%	9	3	66.7%	119	58	51.3%
163	63	5	0	100.0%	75	15	80.0%	5	5	0.0%	75	62	17.3%
164		9	0	100.0%	121	9	92.6%	9	3	66.7%	121	50	58.7%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
165		9	0	100.0%	119	27	77.3%	9	2	77.8%	119	47	60.5%
167		5	0	100.0%	78	16	79.5%	5	0	100.0%	77	22	71.4%
168	29	5	2	60.0%	76	14	81.6%	5	2	60.0%	76	28	63.2%
178	114	20	2	90.0%	212	28	86.8%	21	5	76.2%	211	36	82.9%
179		20	2	90.0%	212	25	88.2%	21	6	71.4%	212	76	64.2%
194		5	1	80.0%	77	18	76.6%	5	1	80.0%	76	23	69.7%
195		9	1	88.9%	119	5	95.8%	9	6	33.3%	119	65	45.4%
198		20	0	100.0%	144	17	88.2%	21	1	95.2%	144	22	84.7%
230		29	0	100.0%	166	4	97.6%	29	1	96.6%	166	8	95.2%
232		29	1	96.6%	332	12	96.4%	29	2	93.1%	332	23	93.1%
233	59	21	5	76.2%	294	66	77.6%	21	12	42.9%	293	100	65.9%
234		29	0	100.0%	333	22	93.4%	29	3	89.7%	332	28	91.6%
235	55	29	8	72.4%	257	42	83.7%	29	7	75.9%	256	59	77.0%
236		29	0	100.0%	317	10	96.8%	29	4	86.2%	316	43	86.4%
237	58	29	3	89.7%	330	59	82.1%	29	8	72.4%	328	59	82.0%
238	23	29	3	89.7%	257	23	91.1%	29	4	86.2%	255	22	91.4%
239	196	29	3	89.7%	331	82	75.2%	29	4	86.2%	330	42	87.3%
240	33	29	2	93.1%	332	23	93.1%	29	8	72.4%	329	68	79.3%
241	22	29	8	72.4%	332	82	75.3%	29	9	69.0%	332	80	75.9%
243		29	5	82.8%	268	70	73.9%	29	5	82.8%	267	38	85.8%
244	46	21	0	100.0%	293	12	95.9%	21	15	28.6%	293	64	78.2%
245		29	7	75.9%	213	40	81.2%	29	7	75.9%	212	29	86.3%
280	60	29	2	93.1%	333	17	94.9%	29	15	48.3%	332	76	77.1%
281	39	29	3	89.7%	333	40	88.0%	29	3	89.7%	333	60	82.0%
283	53	29	10	65.5%	333	84	74.8%	29	5	82.8%	333	66	80.2%
284	35	29	0	100.0%	333	13	96.1%	29	5	82.8%	330	59	82.1%
290	54	29	2	93.1%	333	52	84.4%	29	21	27.6%	330	135	59.1%
291	45	29	17	41.4%	332	110	66.9%	27	13	51.9%	328	89	72.9%
300		28	2	92.9%	316	22	93.0%	27	5	81.5%	313	73	76.7%
301		29	0	100.0%	330	10	97.0%	29	8	72.4%	326	63	80.7%
302		28	1	96.4%	311	34	89.1%	28	12	57.1%	307	90	70.7%
305		28	3	89.3%	314	31	90.1%	27	7	74.1%	309	122	60.5%
306		29	1	96.6%	328	17	94.8%	28	7	75.0%	326	89	72.7%
307		29	6	79.3%	321	44	86.3%	28	16	42.9%	317	98	69.1%
311	141	28	2	92.9%	325	28	91.4%	28	19	32.1%	319	82	74.3%
316	66	28	6	78.6%	321	24	92.5%	27	21	22.2%	315	99	68.6%
318	100	29	4	86.2%	331	35	89.4%	29	21	27.6%	328	165	49.7%
319		29	0	100.0%	332	20	94.0%	29	26	10.3%	327	191	41.6%
330		25	0	100.0%	283	6	97.9%	25	0	100.0%	283	15	94.7%
331		29	0	100.0%	333	33	90.1%	28	0	100.0%	332	44	86.7%
332		28	2	92.9%	332	19	94.3%	28	3	89.3%	332	46	86.1%
334		29	1	96.6%	333	11	96.7%	28	3	89.3%	331	43	87.0%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		29	1	96.6%	333	35	89.5%	28	4	85.7%	330	55	83.3%
336		28	0	100.0%	332	10	97.0%	28	1	96.4%	330	29	91.2%
337	33	29	3	89.7%	333	21	93.7%	29	9	69.0%	329	45	86.3%
338	42	29	7	75.9%	333	54	83.8%	28	9	67.9%	330	103	68.8%
339	17	29	4	86.2%	333	54	83.8%	29	4	86.2%	333	57	82.9%
341	14	26	5	80.8%	318	49	84.6%	26	11	57.7%	312	52	83.3%
342		29	2	93.1%	333	26	92.2%	29	1	96.6%	331	61	81.6%
343		4	0	100.0%	47	3	93.6%	5	0	100.0%	47	10	78.7%
350	20	27	1	96.3%	308	19	93.8%	26	21	19.2%	300	172	42.7%
351	94	28	2	92.9%	315	29	90.8%	28	14	50.0%	313	92	70.6%
352	49	28	3	89.3%	299	24	92.0%	28	12	57.1%	293	93	68.3%
353		28	1	96.4%	270	14	94.8%	28	11	60.7%	264	49	81.4%
354		29	2	93.1%	314	37	88.2%	28	15	46.4%	306	116	62.1%
355		27	6	77.8%	321	37	88.5%	25	19	24.0%	312	118	62.2%
364		29	8	72.4%	322	73	77.3%	29	13	55.2%	316	120	62.0%
365		29	2	93.1%	321	13	96.0%	28	15	46.4%	318	124	61.0%
370		24	4	83.3%	319	39	87.8%	21	6	71.4%	306	75	75.5%
371		24	3	87.5%	312	11	96.5%	21	1	95.2%	308	30	90.3%
380		25	3	88.0%	314	30	90.4%	24	9	62.5%	313	72	77.0%
381		27	3	88.9%	329	15	95.4%	25	10	60.0%	326	70	78.5%
382		27	3	88.9%	328	30	90.9%	25	16	36.0%	326	116	64.4%
383		26	1	96.2%	319	27	91.5%	26	14	46.2%	316	137	56.6%
390		28	5	82.1%	314	24	92.4%	27	12	55.6%	312	85	72.8%
391		28	3	89.3%	315	14	95.6%	27	12	55.6%	310	88	71.6%
392	23	28	1	96.4%	328	11	96.6%	26	11	57.7%	323	101	68.7%
393	23	28	1	96.4%	332	19	94.3%	27	12	55.6%	328	103	68.6%
400		7	0	100.0%	98	6	93.9%	7	0	100.0%	96	2	97.9%
405		7	0	100.0%	91	0	100.0%	7	0	100.0%	91	4	95.6%
448	40	23	7	69.6%	257	50	80.5%	22	9	59.1%	253	89	64.8%
449		23	2	91.3%	254	34	86.6%	23	2	91.3%	254	44	82.7%
450		7	2	71.4%	94	29	69.1%	7	1	85.7%	92	29	68.5%
460	106	7	2	71.4%	94	30	68.1%	7	1	85.7%	91	31	65.9%
461		7	0	100.0%	99	5	94.9%	7	1	85.7%	98	3	96.9%
463		4	0	100.0%	50	4	92.0%	4	0	100.0%	50	0	100.0%
464		8	5	37.5%	95	21	77.9%	7	3	57.1%	92	28	69.6%
467		4	0	100.0%	50	1	98.0%	4	0	100.0%	49	3	93.9%
488		7	1	85.7%	104	29	72.1%	7	1	85.7%	94	14	85.1%
499		7	1	85.7%	95	14	85.3%	7	0	100.0%	92	6	93.5%
500		12	0	100.0%	307	16	94.8%	12	1	91.7%	304	36	88.2%
502		13	1	92.3%	315	19	94.0%	13	3	76.9%	311	61	80.4%
503		29	13	55.2%	329	40	87.8%	29	15	48.3%	322	102	68.3%
504		29	1	96.6%	333	20	94.0%	29	8	72.4%	331	98	70.4%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		23	1	95.7%	325	42	87.1%	23	6	73.9%	320	90	71.9%
506		29	14	51.7%	328	56	82.9%	27	5	81.5%	320	51	84.1%
507		29	13	55.2%	333	49	85.3%	29	15	48.3%	333	115	65.5%
508	46	29	2	93.1%	328	43	86.9%	29	13	55.2%	324	81	75.0%
509	25	13	1	92.3%	314	15	95.2%	13	5	61.5%	314	71	77.4%
511		13	1	92.3%	309	25	91.9%	13	3	76.9%	308	53	82.8%
516		29	6	79.3%	324	35	89.2%	29	12	58.6%	323	146	54.8%
517	18	29	0	100.0%	333	8	97.6%	29	23	20.7%	329	150	54.4%
518	47	29	8	72.4%	333	45	86.5%	29	24	17.2%	331	231	30.2%
519		29	0	100.0%	324	9	97.2%	29	6	79.3%	322	72	77.6%
552	15	3	1	66.7%	4	2	50.0%	3	1	66.7%	4	2	50.0%
562		29	4	86.2%	324	27	91.7%	29	1	96.6%	320	36	88.8%
564		29	0	100.0%	325	19	94.2%	29	3	89.7%	317	41	87.1%
566	75	29	4	86.2%	323	29	91.0%	29	8	72.4%	320	53	83.4%
567		29	1	96.6%	210	11	94.8%	29	4	86.2%	208	13	93.8%
572	59	29	3	89.7%	320	27	91.6%	28	11	60.7%	312	94	69.9%
573	37	29	3	89.7%	322	43	86.6%	29	6	79.3%	315	57	81.9%
579	252	29	3	89.7%	210	14	93.3%	27	7	74.1%	203	44	78.3%
580	80	29	2	93.1%	325	18	94.5%	29	7	75.9%	318	35	89.0%
581	154	29	7	75.9%	325	57	82.5%	28	10	64.3%	322	74	77.0%
584	Cncld	29	6	79.3%	209	31	85.2%	27	23	14.8%	202	131	35.1%
587	49	28	3	89.3%	317	19	94.0%	28	11	60.7%	308	64	79.2%
588	135	27	4	85.2%	208	22	89.4%	26	10	61.5%	206	43	79.1%
591	108	29	4	86.2%	322	25	92.2%	28	9	67.9%	315	48	84.8%
593	Cncld	25	5	80.0%	315	52	83.5%	23	3	87.0%	292	40	86.3%
595	No OS	27	6	77.8%	318	59	81.4%	27	12	55.6%	315	72	77.1%
611		5	5	0.0%	48	35	27.1%	5	1	80.0%	48	5	89.6%
624		4	0	100.0%	123	38	69.1%	5	2	60.0%	124	33	73.4%
660		9	1	88.9%	90	13	85.6%	9	1	88.9%	89	26	70.8%
661		9	0	100.0%	118	12	89.8%	9	3	66.7%	117	44	62.4%
662		5	0	100.0%	50	0	100.0%	5	0	100.0%	50	1	98.0%
663		9	1	88.9%	91	15	83.5%	9	1	88.9%	90	9	90.0%
664		9	0	100.0%	90	8	91.1%	9	4	55.6%	90	15	83.3%
665		9	0	100.0%	91	10	89.0%	9	1	88.9%	91	25	72.5%
666		9	0	100.0%	89	22	75.3%	9	0	100.0%	89	7	92.1%
667		9	0	100.0%	89	7	92.1%	9	0	100.0%	87	16	81.6%
669		9	0	100.0%	89	7	92.1%	9	0	100.0%	87	22	74.7%
670		9	0	100.0%	91	13	85.7%	9	2	77.8%	89	17	80.9%
671		9	0	100.0%	89	8	91.0%	9	2	77.8%	87	11	87.4%
672		9	2	77.8%	91	10	89.0%	9	3	66.7%	91	18	80.2%
674		9	3	66.7%	89	29	67.4%	9	0	100.0%	89	7	92.1%
690		9	0	100.0%	95	2	97.9%	9	1	88.9%	94	5	94.7%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
691		9	1	88.9%	95	8	91.6%	9	5	44.4%	93	28	69.9%
692		9	1	88.9%	95	4	95.8%	9	1	88.9%	94	15	84.0%
693		9	2	77.8%	95	14	85.3%	9	6	33.3%	93	30	67.7%
694		9	1	88.9%	94	10	89.4%	9	1	88.9%	94	15	84.0%
695		9	0	100.0%	93	10	89.2%	9	2	77.8%	93	16	82.8%
696		9	2	77.8%	95	11	88.4%	9	2	77.8%	95	27	71.6%
697		9	4	55.6%	95	23	75.8%	9	2	77.8%	95	19	80.0%
698		9	1	88.9%	93	3	96.8%	9	1	88.9%	93	8	91.4%
701		29	4	86.2%	265	29	89.1%	29	6	79.3%	262	31	88.2%
702		29	3	89.7%	332	35	89.5%	29	13	55.2%	329	83	74.8%
703		29	19	34.5%	333	112	66.4%	29	14	51.7%	331	99	70.1%
704	37	29	11	62.1%	264	48	81.8%	28	12	57.1%	256	58	77.3%
710		29	2	93.1%	333	79	76.3%	29	7	75.9%	329	88	73.3%
711		29	4	86.2%	324	38	88.3%	27	13	51.9%	301	65	78.4%
712	17	29	11	62.1%	330	91	72.4%	28	14	50.0%	320	112	65.0%
713	101	28	3	89.3%	200	19	90.5%	21	13	38.1%	177	80	54.8%
714	107	29	17	41.4%	214	92	57.0%	27	18	33.3%	198	94	52.5%
715		29	2	93.1%	332	63	81.0%	24	13	45.8%	304	154	49.3%
716	Cncld	29	21	27.6%	333	141	57.7%	26	21	19.2%	324	139	57.1%
717	31	29	9	69.0%	318	77	75.8%	23	12	47.8%	293	98	66.6%
718	240	29	23	20.7%	333	176	47.1%	28	18	35.7%	330	127	61.5%
719	106	29	10	65.5%	333	113	66.1%	28	14	50.0%	316	98	69.0%
720		9	0	100.0%	102	9	91.2%	9	0	100.0%	102	6	94.1%
723		9	0	100.0%	102	5	95.1%	9	2	77.8%	102	11	89.2%
724	22	9	2	77.8%	102	5	95.1%	7	3	57.1%	100	22	78.0%
727		9	1	88.9%	102	8	92.2%	9	1	88.9%	102	15	85.3%
728		9	1	88.9%	102	7	93.1%	9	1	88.9%	102	18	82.4%
729		9	1	88.9%	101	16	84.2%	9	4	55.6%	100	25	75.0%
732	62	9	4	55.6%	100	19	81.0%	9	4	55.6%	98	21	78.6%
733		9	0	100.0%	102	14	86.3%	9	3	66.7%	97	32	67.0%
734	56	9	2	77.8%	102	16	84.3%	9	3	66.7%	101	24	76.2%
736		9	1	88.9%	78	8	89.7%	9	3	66.7%	76	12	84.2%
737		9	0	100.0%	78	7	91.0%	9	2	77.8%	77	14	81.8%
738		9	0	100.0%	102	15	85.3%	8	0	100.0%	96	13	86.5%
741	52	9	2	77.8%	102	15	85.3%	9	2	77.8%	102	20	80.4%
743	36	9	4	55.6%	102	21	79.4%	6	2	66.7%	98	12	87.8%
744		9	1	88.9%	102	16	84.3%	9	2	77.8%	102	34	66.7%
745		9	3	66.7%	102	13	87.3%	9	1	88.9%	101	15	85.1%
746		9	1	88.9%	102	9	91.2%	9	2	77.8%	101	15	85.1%
747		9	1	88.9%	102	16	84.3%	9	3	66.7%	102	24	76.5%
748		9	1	88.9%	101	14	86.1%	9	1	88.9%	101	14	86.1%
749		9	1	88.9%	99	15	84.8%	9	2	77.8%	90	12	86.7%

Amtrak On Time Performance

Trains Arriving Through: 8/29/2026

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
751		9	1	88.9%	101	17	83.2%	8	0	100.0%	97	11	88.7%
757		29	2	93.1%	118	7	94.1%	29	4	86.2%	117	12	89.7%
761		29	1	96.6%	329	13	96.0%	29	2	93.1%	326	43	86.8%
765		29	0	100.0%	329	25	92.4%	29	4	86.2%	329	46	86.0%
769	155	29	0	100.0%	329	27	91.8%	28	7	75.0%	322	64	80.1%
770	74	29	3	89.7%	329	25	92.4%	28	14	50.0%	326	103	68.4%
774	73	29	1	96.6%	329	17	94.8%	28	9	67.9%	327	78	76.1%
777	56	29	0	100.0%	214	12	94.4%	29	14	51.7%	213	56	73.7%
782	32	29	22	24.1%	214	104	51.4%	29	10	65.5%	209	35	83.3%
785	126	29	6	79.3%	329	28	91.5%	29	7	75.9%	329	60	81.8%
786	218	29	4	86.2%	118	23	80.5%	28	18	35.7%	114	65	43.0%
790	104	29	3	89.7%	329	31	90.6%	29	8	72.4%	326	54	83.4%
794	75	29	7	75.9%	329	40	87.8%	29	8	72.4%	325	74	77.2%
821	29	29	0	100.0%	327	6	98.2%	29	18	37.9%	327	139	57.5%
822		29	2	93.1%	329	18	94.5%	29	26	10.3%	327	168	48.6%
1333		29	8	72.4%	329	40	87.8%	29	11	62.1%	326	110	66.3%
1340		29	1	96.6%	328	7	97.9%	28	4	85.7%	327	55	83.2%
1689		15	1	93.3%	110	6	94.5%	16	3	81.3%	110	14	87.3%
2207		5	0	100.0%	28	5	82.1%	5	1	80.0%	28	6	78.6%
2208		9	1	88.9%	20	4	80.0%	9	1	88.9%	20	4	80.0%
2211		5	0	100.0%	11	1	90.9%	5	1	80.0%	11	2	81.8%
2219		9	1	88.9%	20	4	80.0%	9	2	77.8%	20	6	70.0%
2224		9	1	88.9%	35	6	82.9%	8	0	100.0%	34	4	88.2%
2250		5	1	80.0%	109	12	89.0%	5	0	100.0%	108	35	67.6%
2252		9	1	88.9%	115	10	91.3%	9	0	100.0%	113	32	71.7%
2254		9	0	100.0%	50	3	94.0%	9	1	88.9%	50	13	74.0%
2255		9	0	100.0%	117	11	90.6%	9	4	55.6%	116	54	53.4%
2258		9	0	100.0%	53	9	83.0%	9	5	44.4%	52	24	53.8%
2259		9	1	88.9%	73	25	65.8%	9	4	55.6%	72	34	52.8%
2260		9	0	100.0%	19	2	89.5%	9	4	55.6%	19	12	36.8%
2262		5	1	80.0%	26	5	80.8%	5	2	60.0%	26	9	65.4%
2265		9	2	77.8%	54	6	88.9%	9	2	77.8%	53	29	45.3%
2267		9	0	100.0%	17	3	82.4%	9	4	55.6%	16	9	43.8%
2271		9	0	100.0%	100	11	89.0%	9	1	88.9%	99	47	52.5%
2293		9	2	77.8%	18	3	83.3%	9	0	100.0%	18	3	83.3%

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
66	BOS	Trn Cancelled	ENG	35	ENG	35	WIL-PHL	AM	Air / Brake, 657 EX ES, STOPPED AT MP 13.2 DUE TO EMERGENCY APPLICATION OF BRAKES. INSPECTIONS RESULTED IN LOOSE HOSES ON CARS 3 AND 4.
124	PHL	71	DCS	77	DCS	72	NPN-NPN	CS	PTC- Unplanned PTC system /server outage Other, NPN Station
147	RNK	179	OTH	146	OTH	144	BER-BER	AM	Lost time - N.A.R.
150	BOS	18	OTH	8	SMW	8	NHV-NHV	AM	Scheduled in track usage program, Milepost, nhv, nhv, O/S track a/c track outage between NHV-XM4
155	NFK	71	PTI	101	PTI	91	XVG-ALX	CS	Follow 89 Switch Failure, 89, Control Point, CP.Virginia
156	NYP	41	DCS	46	DCS	35	ALX-XVG	CS	Power switch failure Milepost, 110.0, 110.0
161	WAS	33	CTI	18	HLD	8	NHV-NHV	MN	High passenger count Train #147 3 hours late was advised to take there passengers at NHV over 150 passengers boarding
163	WAS	63	CTI	15	DCS	12	MET-TRE	AM	Power switch failure, Other, NO.23SW AT COUNTY FAILING CONGESTION
168	BOS	29	SMW	21	SMW	18	BBY-BOS	AM	Scheduled in track usage program, Milepost, XT1, BOS, Held at Tower 1 for clear track account Terminal congestion due scheduled track outage.
178	BOS	114	MTI	86	MTI	86	NHV-NLC	AM	Disabled train ahead, Milepost w/Letters, NHV, NLC, AM178 stopped on adjacent track at OSB to transfer 145 psngs from train AM176 and followed AM176
460	SPG	106	SMW	100	SMW	96	NHV-NHV	AM	Scheduled in track usage program, Milepost, NHV, NHV, Late release from the yard due to track outage between NHV_XM4
52	LOR	34	FTI	55	ITI	25	SFA-SFA	FR	Service, turn, or wye train 53, Short crew working the yard job.
79	CLT	66	DCS	89	DCS	73	XVG-ALX	CS	Restrictive signal(s) from known wayside signal failure Stop, Other, lefant
19	NOL	49	ENG	132	ENG	81	WAS-WAS	AM	HEP, 342-320, WAITING FOR DSLS FROM THE PIT
63	TWO	25	SYS	21	CTI	14	CRT-POU	MN	Follow mnrr, local, Control Point, 58
64	NYP	52	DCS	79	DCS	34	SYR-SYR	CS	PTC- Unplanned PTC system /server outage Unable to login ok to Depart SYR by NF dispatch ACR 1552 and the NOM Capped at 59, Other, SYR

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
68	NYP	90	FTI	54	DMW	45	POU-CRT	MN	Held for or routed around MW work or equipment Single track conditions, hold for 2 northbound, Control Point, 72, Control Point, 58	
233	ALB	59	CTI	57	CTI	54	CRT-POU	MN	Meet District D let us hold back on the platform at cold spring to open a door for passenger comfort. Thank you district D, mnrr, 8836, Control Point, 53	
235	ALB	55	RTE	49	RTE	49	CRT-POU	MN	Dispatcher hold Control Point, 58	
237	ALB	58	PTI	36	PTI	36	CRT-POU	MN	Meet Single tracking, 48, 244, Control Point, 58	
238	NYP	23	DCS	9	DCS	9	RHI-XCP	AM	Wayside detector failure including false actuation Other, Staatsburg	
239	ALB	196	ENG	152	ENG	55	CRT-POU	MN	PTC - On Board Cab Signal or PTC Failure 9701	
240	NYP	33	RTE	32	RTE	29	POU-POU	MN	Dispatcher hold Held at Poughkeepsie due to single tracking ahead at 61.6-61.3, Other, POU	
241	ALB	22	CTI	26	CTI	26	CRT-POU	MN	Cross Traffic Stopped at CP 58 on TRK 1. Waiting for on time departure MNRR 2860 on TRK 2 and on time departure of MNRR 8864 on TRK 2., MNRR, 2860, MNRR, 8864, Control Point, 58	
244	NYP	46	DMW	34	DMW	22	RHI-XCP	MN	Held for or routed around MW work or equipment Held at cp75 due to single tracking POU to Beacon, Control Point, cp75	
280	NYP	60	ENG	53	ENG	39	AMS-XHF	CS	Pick up rescue locomotive due to mechanical failure Engine 114 had no cabs and no acces so had to be rescued before going on Amtrak Hudson line at cp 169, 114	
281	NFL	39	FTI	84	FTI	46	XSV-ROC	CS	Follow csx, Milepost, 296, 370	
283	NFL	53	CTI	64	CTI	64	CRT-POU	MN	Meet MNRR, Milepost w/Letters, 53, cold spring	
284	NYP	35	RTE	33	RTE	27	POU-POU	MN	Dispatcher hold Single tracking between CP 72 and CP 53. Dispatcher hold waiting for MNRR 8827., Other, POU	
290	NYP	54	RTE	37	RTE	33	RHI-XCP	MN	Dispatcher hold Control Point, 75	
291	BTN	45	PTI	48	PTI	36	CRT-POU	MN	Meet 290, Control Point, 58	
48	NYP	54	FTI	58	FTI	32	UCA-XHF	CS	Follow M364, Milepost, 223, 169	
448	BOS		ENG	53	ENG	51	ALB-XRD	AM	PTC would not initiate 93	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
73	CLT	19	TEN	12	TEN	8	RGH-CYN	NS	Loading problem RNCX 1984 shut down., NC1984
75	CLT	11	DSR	8	PTI	6	CYN-DNC	NS	Meet 72, Control Point, D&S Junction
97	MIA	223	ENG	182	ENG	60	RVR-RVR	CS	Undesired emergency application 320
41	MIA	128	FTI	104	FTI	33	CUM-MRB	CS	Meet E79227, Milepost w/Letters, Brickyard, Brickyard
26	MOE	22	FTI	38	FTI	31	PAG-MOE	CS	Follow csx 80129, Milepost, 687.4, 687.4
6	CHI	51	FTI	189	FTI	62	COX-XSO	UP	Meet up 9821, Control Point, switch 9
552	SAC	15	HLD	15	HLD	15	GAC-GAC	UP	Passenger and/or baggage Hold per RFE Ward
724	SAC	22	MBO	21	MBO	21	MTZ-SUI	UP	For maritime traffic Bridge, Suisun Bridge
732	SAC	62	SYS	73	SYS	73	OKJ-OKJ	UP	Amtrak PTC Outage Nationwide
734	SAC	56	SYS	64	SYS	64	SJC-SJC	UP	PTC problem or failure (cause unknown) NATIONWIDE PTC OUTAGE, Other, SJC DEPOT
741	SJC	52	SYS	49	SYS	49	SAC-SAC	UP	PTC problem or failure (cause unknown)
743	SJC	36	PTI	2	PTI	2	RIC-BKY	UP	Meet 734, Control Point, Rv009
51	CHI	279	FTI	222	FTI	154	CIN-CIN	CS	Meet m361, Siding, mcgonigle
508	SEA	46	FTI	46	FTI	46	SLM-ORC	UP	Meet UP7391, Siding, hito
509	PDX	25	FTI	22	DCS	11	TAC-XNI	ST	Issue with automatic road crossing protection Protected road crossings, Milepost, 9.56, 9.56, Milepost, 10.4, 10.4
517	PDX	18	RTE	11	DMW	8	TAC-XNI	BN	Two box 1s Milepost, 10.39, 10.39, Milepost, 10.4, 10.4
518	VAC	47	PTI	31	PTI	15	PDX-VAN	BN	Meet AMT 11, Control Point, Willbridge
14	SEA	32	PTI	51	POL	39	VAN-VAN	BN	Removal of passenger by police Mitchell, Michael - PNR 6A67CC Removed by Vancouver Police. Please see report.
7	SEA	39	FTI	87	FTI	68	LWA-XEN	BN	Engine was on fire Engine was on fire, Control Point, E.SCNIC, BNSF 7361, Oil Cars
8	CHI	114	FTI	161	FTI	54	MAL-GGW	BN	Meet BNSF 8461, BNSF 8139, BNSF 3971, Siding, Saco, Siding, Tampico
821	FTW	29	FTI	27	FTI	23	GLE-FTW	BN	Meet Bn 3865, Siding, Valleyview

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
337	MKE	33	SYS	30	SYS	30	CHI-CHI	AM	PTC problem or failure (cause unknown)
338	CHI	42	SYS	41	SYS	33	MKE-MKE	CP	PTC problem or failure (cause unknown) PTC Cut out, 59MPH, Other, MKE
339	MKE	17	ITI	24	ITI	24	CHI-CHI	AM	Service, turn, or wye train 338
341	MKE	14	ENG	13	ENG	5	GLN-XRO	ME	Reduced speed due to cab volatility 519
350	PNT	20	PTI	30	PTI	19	KAL-XGO	CC	Meet amtk365, amtk351, Control Point, gord
351	CHI	94	DMW	90	DMW	90	TRM-TRM	CC	Hold for defect repair Cable dragging Pontiac mechanical came to Troy and spiced a new 480 cable, Other, troy station
352	PNT	49	SVS	77	SVS	71	CHI-XTF	AM	PTC - Initializing PTC (no failure) Nationwide PTC outage on NS., Control Point, Roosevelt
566	SAN	75	ENG	25	ENG	25	FUL-FUL	BN	Air / Brake Blended brake issue. Walk through it with Lester Griffin, 58
572	SAN	59	CTI	54	CTI	22	IRV-SNC	SC	Meet metrolink, 1663, Control Point, trabuco
573	LAX	37	CTI	47	CTI	47	OSD-X98	SC	Meet metro link, 1859, Control Point, songs
579	LAX	252	SYS	211	SYS	118	FUL-XRJ	BN	Re-crew / job briefing
580	SAN	80	PTI	69	PTI	64	SNC-SNP	SC	Meet 581, Control Point, sera
581	LAX	154	CTI	62	CTI	62	OSD-X98	SC	Meet Metrolink, 1664, Control Point, SONGS
584	SAN	Trn Cancelled							
587	LAX	49	CTI	40	CTI	20	OSD-X98	SC	Meet Metrolink, 1667, Control Point, Songs
588	SAN	135	PTI	42	PTI	40	SNC-SNP	SC	Meet 591, Control Point, Serra
591	LAX	108	ITI	52	ITI	52	SAN-SAN	SN	Service, turn, or wye train 580
593	LAX	Trn Cancelled							
595	LAX	No OS Rpt	PTI	105	PTI	105	OSD-X98	SN	Meet NCTD dispatcher informed us that Metrolink was sending 3 Eastbound Amtraks before we could pass Songs westbound. Waited at Pulgas so we could go around BNSF freight between Don and Songs after the 3 Amtraks passed us at Pulgas., 588, 786, 790, Control Point, Pulgas
769	GTA	155	SYS	98	SYS	98	LAX-LAX	SC	PTC problem or failure (cause unknown) PTC system wide outage, Other, Los Angeles Union Station
770	SAN	74	CTI	39	CTI	39	SNC-SNP	SC	Meet 1663 had to flag due to signal issues, Metrolink, 1663, Control Point, Serra

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
774	SAN	73	PTI	54	PTI	41	SNC-SNP	SC	Meet Train was flagging from CP Songs to CP Pier., 777, Control Point, serra	
777	SLO	56	DCS	76	DCS	23	MPK-XMR	UP	PTC- I-ETMS Red Fence/Signal Status Unknown Red fence remained after receiving authority., Control Point, Las Posas	
782	SAN	32	PTI	38	PTI	18	SIM-CWT	SC	Meet 769, Control Point, Davis	
785	GTA	126	PTI	69	PTI	57	OSD-X98	SC	Meet 580, 782, Control Point, 782	
786	SAN	218	SYS	104	SYS	104	SLO-SLO	UP	PTC problem or failure (cause unknown)	
790	SAN	104	PTI	102	ITI	50	GTA-GTA	UP	Service, turn, or wye train 769, Late inbound 769 due to PTC systemwide outage and a late Metrolink 1857 at Control Point Songs.	
794	SAN	75	PTI	32	PTI	32	SNC-X98	SC	Meet 595, Control Point, Serra	
704	BFD	37	SYS	51	SYS	51	WAC-BFD	BN	Blocked by or assisting another, disabled Amtrak train Amtrak 704 had too couple into Amtrak 716 and dragged them into Bakersfield since 716 Ran out of fuel and lost HEP., Siding, Wasco	
712	BFD	17	ADA	12	FTI	7	MDR-FNO	BN	Meet bnsf 3765 west, Siding, madera	
713	OKJ	101	SYS	97	SYS	96	MCD-MCD	BN	PTC problem or failure (cause unknown) Nationwide Amtrak PTC issue	
714	BFD	107	SYS	92	SYS	92	OKJ-OKJ	UP	PTC problem or failure (cause unknown) Milepost, 7.0, 7.0	
716	BFD	Trn Cancelled	OTH	14	OTH	14	OKJ-OKJ	UP	PTC nationwide outage Toned for the light out of OMF at 1405 Got the light 1416 Causing delay for departure out of OKJ Informed Danielle at operations of the said delay	
717	OKJ	31	PTI	26	DCS	23	WAC-COC	BN	Track indication. Flagging block Clear signal at mp 935, Control Point, east allensworth, Control Point, west allensworth	
718	BFD	240	PTI	116	PTI	116	MTZ-MTZ	UP	Meet 717 had ptc issues at TR041 and not given authorization to run cut out, 717, Control Point, ferry	
719	OKJ	106	TEN	102	TEN	102	BFD-WAC	BN	Unrecoverable penalty (PCS) C2004	
3	LAX	140	FTI	188	FTI	41	XSJ-XAR	BN	Meet BNSF, Control Point, 3.5	
4	CHI	57	FTI	198	FTI	53	XRJ-FUL	BN	Cross Traffic Held at Basta, for 3 freight trains, related to earlier service disruption, BNSF, Control Point, basta	
21	SAS	57	SYS	97	SYS	75	FTW-FTW	UP	PTC problem or failure (cause unknown)	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/29/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
22	CHI	768	SVS	251	SVS	164	SAS-SAS	UP	Added locomotive up 5068 and brake test	
392	CHI	23	FTI	33	FTI	23	RTL-GLM	CC	Meet Z 194, Siding, Paxton	
393	CDL	23	FTI	18	FTI	14	CHM-MAT	CC	Meet CN3093, Siding, TUSCOLA	
311	KCY	141	FTI	153	FTI	103	LEE-IDP	UP	Follow Broken knuckle on freight, UP 8312, Other, LEE, Control Point, Ind jct	
316	STL	66	ITI	35	ITI	35	KCY-KCY	KC	Service, turn, or wye train 311, Due to late arrival and wye of train 311, departed KCY 35 minutes late	
318	CHI	100	PTI	67	FTI	35	WAR-SED	UP	Meet 8312, Siding, dresden	

Amtrak Initial Terminal Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/29/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	1	08/29	234	234	Service, turn, or wye train 2, Late departure due to late arriving Amtrak train 2
ALB	448	08/28	5	5	PTC problem or failure (cause unknown)
BON	693	08/29	1	1	Passenger and/or baggage Mother and infant
BON	697	08/29	1		
BOS	169	08/29	8	8	Water, commissary, toilet/trash dumping, cleaners still on board train, late boarding BOS, sat on the bridge for 10" due to no track space
HAR	672	08/29	8	8	Door, 82595 AX AS, DOORS THAT WONT CLOSE; MECHANICAL FIXED THE ISSUE
NFK	128	08/29	54	54	PTC problem or failure (cause unknown) PTC outage nationwide
NHV	450	08/29	11	11	Scheduled in track usage program, Milepost, NHV, NHV, O/S track due to track outage between NHV-XM4
NHV	460	08/29	96	96	Scheduled in track usage program, Milepost, NHV, NHV, Late release from the yard due to track outage between NHV_XM4
NPN	124	08/29	72	72	PTC- Unplanned PTC system /server outage Other, NPN Station
NYP	127	08/29	10	10	Electrical failure, 9644, LOSS OF POWER
NYP	235	08/29	8	8	Service, turn, or wye train, 238
NYP	245	08/29	60	60	Service, turn, or wye train, 68
NYP	291	08/29	17	17	Service, turn, or wye train, 240
PHL	611	08/29	2	2	PTC - Stop Bypass Permission Required, Control Point, .
RNK	66	08/29	32	32	PTC problem or failure (cause unknown) Could not initialize PTC due to system wide outage, Milepost w/Letters, N 257.7, N 247.7
SFA	52	08/29	41	41	PTC problem or failure (cause unknown)
SPG	147	08/29	4	4	Wheelchair, multiple ADA psgrs
WAS	126	08/29	2	2	Removal of passenger by police, MARC PAX'S ATTEMPT TO TRANSFER TO 126. APD CALLED FOR CROWD CONTROL.
CHI	7	08/29	47	47	PTC problem or failure (cause unknown) PTC OUTAGE was advised to not leave initial terminal before issue was resolved
CHI	50	08/29	131	131	Service, turn, or wye train 5128
CHI	337	08/29	30	30	PTC problem or failure (cause unknown)
CHI	339	08/29	24	24	Service, turn, or wye train 338
CHI	364	08/29	2	2	PTC- IETMS Software Download
KCY	316	08/29	35	35	Service, turn, or wye train 311, Due to late arrival and wye of train 311, departed KCY 35 minutes late
MKE	338	08/29	33	33	PTC problem or failure (cause unknown) PTC Cut out, 59MPH, Other, MKE

Amtrak Initial Terminal Details

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/29/2026

Terminal	Train	Date	Late	Delay	Cause
SAS	22	08/29	18	18	Dispatcher hold Dispatcher hold due to making decision on where to wye train. Normal route for wye unavailable due to severe weather., Control Point, San Antonio
BFD	701	08/29	4	4	Door C9813, Train not getting door lights have to put override on , same problem as before with this train set been an issue for a while now, car 9813 A engineer side.
GAC	750	08/29	(No OS)		
GTA	782	08/29	2	2	Meet 14, Control Point, CO 358
GTA	790	08/29	50	50	Service, turn, or wye train 769, Late inbound 769 due to PTC systemwide outage and a late Metrolink 1857 at Control Point Songs.
LAX	584	08/29	(Trn Cxld)		Engine Issue
LAX	588	08/29	43	10	Door 6402, Door 4 in car 6402. Had to call depot mechanical.
LAX	588	08/29	43	33	Late equipment 581 581
OKJ	710	08/29	2	2	Loading problem C2004
OKJ	712	08/29	1	1	Copy authority / restriction DS Reports BOL trespasser near BKJ potentially on ROW wielding a knife.
OKJ	714	08/29	92	92	PTC problem or failure (cause unknown) Milepost, 7.0, 7.0
OKJ	716	08/29	14	14	PTC nationwide outage Toned for the light out of OMF at 1405 Got the light 1416 Causing delay for departure out of OKJ Informed Danielle at operations of the said delay
OKJ	718	08/29	62	62	Water, commissary, toilet/trash dumping
OKJ	732	08/29	73	73	Amtrak PTC Outage Nationwide
OKJ	736	08/29	1	1	Restrictive signal(s) from unknown cause Red, Control Point, north jack london
SAC	704	08/29	3	3	Door C8312, All doors are fully shut in the 8312, but still needed to insert key and press the "close button". This happens when the A or the end breaker is down and someone tries to unlock the door from the outside.
SAC	741	08/29	49	49	PTC problem or failure (cause unknown)
SAC	743	08/29	1		
SAN	579	08/29	46	46	PTC problem or failure (cause unknown) NATIONWIDE OUTAGE, Other, SAN STATION
SAN	581	08/29	36	36	Service, turn, or wye train 770
SAN	591	08/29	52	52	Service, turn, or wye train 580
SAN	593	08/29	(Trn Cxld)		Engine Issue
SAN	785	08/29	4	4	Meet coaster, Control Point, ash

Amtrak Initial Terminal Details

26-FOI-00703 00000008729 "UNCLASSIFIED" 9/2/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 8/29/2026

Terminal	Train	Date	Late	Delay	Cause
SJC	734	08/29	64	64	PTC problem or failure (cause unknown) NATIONWIDE PTC OUTAGE, Other, SJC DEPOT
SLO	786	08/29	104	104	PTC problem or failure (cause unknown)

Eastern Region

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	66.7	84.1	90.2	18	6
SEPTA	95.0	89.9	95.3	91.5	109	11
NJT-NED	95.0	90.7	91.8	88.6	194	18
NJT-SED	95.0	100	98.9	97.2	24	0

Operating Highlights

Train 52(29) South of Charleston, SC - Freight Train Interference

30AUG26: Train 52(29) operating with engines 317, 352, and 437 customers onboard was delayed 1 miles south of Charleston, SC on the CSX Charleston subdivision holding at SY milepost 388.4 due to CSX M410-29 fatally striking a trespasser at Charleston station. Once the scene was open, train 52(29) proceeded on track 2. Train 53(29) held at milepost 383.2 and was able to proceed on track 2 at restricted speed once released and followed CSX I031-29.

Train	Delay	Comment
53(29)	1'25"	
52(29)	3'38"	

Train 97(28) South of Okeechobee, FL - Animal Strike

29AUG26: Train 97(28) operating with engines 342, 320, and 108 customers onboard struck a wild boar 4 miles south of Okeechobee, FL on the CSX Auburndale subdivision at milepost 913.4. The crew inspected their equipment upon arrival in West Palm Beach and took no exceptions.

Train	Delay	Comment
97(28)	02"	

Train 97(28) South of Winter Haven, FL - Freight Train Interference

29AUG26: Train 97(28) operating with engines 342, 320, and 108 customers onboard was delayed 20 miles south of Winter Haven, FL on the CSX Auburndale subdivision holding at milepost 847.3 for CSX M453-29 which struck a tree at milepost 849.4. The freight crew was able to clear the tree and proceed. Train 97(28) followed the freight to milepost 453.

Train	Delay	Comment
97(28)	51"	

Train 54(29) North of Claremont, NH - Debris

29AUG26: Train 54(29) operating with engine 106 and 58 customers onboard struck a tree 4 miles north of Claremont, NH on the NECR Roxbury subdivision at milepost 167.5. The crew inspected their equipment and took no exceptions.

Train	Delay	Comment
54 (29)	08"	

Train 124(29) South of Ashland, VA - Debris

29AUG26: Train 124(29) operating with engine 15 and 142 customers onboard struck part of a tree 2 miles south of Ashland, VA on the CSX RFP subdivision at milepost 17. The crew inspected their equipment and took no exceptions.

Train	Delay	Comment
124 (29)	02"	

Train 239(29) South of Croton, NY - Engine Failure

29AUG26: Train 239(29) operating with cab car 9701, engine 714, and 154 customers onboard was delayed operating to Albany, NY after declaring cab signal failure on cab car 9701 causing the train to operate reduced speed max 59mph.

Train	Delay	Comment
239 (29)	2'32"	

Train 281(29) Lakeland, NY - Freight Train Interference

29AUG26: Train 281(29) operating with engine 92 and 193 customers onboard was delayed on the CSX Rochester subdivision following CSX freight from NY State Fair Station in Lakeland, NY milepost 296.0 to Rochester, NY milepost 370.

Train	Delay	Comment
281 (29)	46"	

Train 281(29) West of Rome, NY - Freight Train Interference

29AUG26: Train 281(29) operating with engine 92, 5 cars, and 169 customers onboard was delayed beginning at milepost 268.0, 17 miles west of Rome, NY on the CSX Syracuse Terminal subdivision due to following a CSX freight train from milepost 268.0 to milepost 286. Once the freight train cleared, Train 281(29) advanced to the next station.

Train	Delay	Comment
281 (29)	38"	

Train 48(28) East of Utica, NY - Freight Train Interference

29AUG26: Train 48(28) operating with engines 709, 706, 7 cars, and 173 customers onboard was delayed beginning at milepost 223.0, 14 miles east of Utica, NY on the CSX Mohawk subdivision due to following CSX freight train M364 from milepost 223.0 to milepost 169.0. Once the freight train cleared, Train 48(28) advanced to the next station.

CSX Power Switch Failure South of Washington, DC - Switch Failure

29AUG26: Multiple trains were delayed on the CSX RF&D subdivision due to power switch failure at milepost 111.6. The switch failed due to a power loss. A CSX maintainer responded to the scene and was able to hand throw the switch to allow train traffic to resume.

Train	Delay	Comment
20 (28)	36"	
89 (29)	1'15"	
155 (29)	1'31"	
79 (29)	1'13"	
41 (28)	46"	
80 (29)	30"	
156 (29)	35"	
128 (29)	41"	
66 (29)	35"	

Train 147(29) South of Berlin, CT - Engine Failure

29AUG26: Train 147(29) operating with engine 120, 8 cars, and 206 customers onboard was stopped at milepost 25.2, 1 mile south of Berlin, CT on the Amtrak MRS Line due to a total loss of power including head end power. The crew attempted to troubleshoot with the road foreman and mechanical. The power and head end power were able to be restored. The train reversed back to Berlin to wait for a rescue set the was dispatched from New Haven. The rescue set arrived to Berlin and coupled to the equipment. The train advanced to the next station. The power was changed in New Haven and the train was able to continue.

The rescue set being sent to Train 147(29) required that Train 461(29) short turn for train 460(29). Train 460(29) was delayed departing the initial terminal due to waiting on the equipment to arrive.

Train	Delay	Comment
460 (29)	1'36"	Short turn of equipment
147 (29)	2'24"	

Train 280(29) South of Amsterdam, NY - Engine Failure

29AUG26: Train 280(29) operating with engine 114, 5 cars, and 186 customers was delayed at milepost 169.0, 8 miles south of Amsterdam, NY on the CSX Mohawk subdivision due to rescue engines 709 and 706 being added to the consist for ACSES failure. Train 280(29) departed Niagara Falls with ACSES cut out. The train was met by the rescue diesels at milepost 169.0 as the train entered ACSES territory. The train advanced to Albany where the three engines were removed and replaced with engine 117. Once the replacement engine was added to the consist, Train 280(29) advanced to the next station.

Train	Delay	Comment
280 (29)	39"	CP 169
280 (29)	20"	ALB

Train 66(28) Kingston, RI - Engine Failure

29AUG26: Train 66(28) operating with engine 657, 6 cars, and 204 customers onboard was terminated in Kingston, RI on the Amtrak NHB Line due to extensive damage to both pantographs on engine 657. The customers were all transferred to Train 150(29). Rescue engine 623 was dispatched from Boston to tow the equipment back to Boston.

Train	Delay	Comment
66 (28)	Term KIN	

Train 97(28) North of Richmond, VA - Car Failure

29AUG26: Train 97(28) 26-FD-00703 in 00000008729 engine UNCLASSIFIED, 320 and 219 customers onboard was delayed on the CSX RFP subdivision multiple times for an air hose disconnecting between car 62016 and car 62019. Initial stop was at milepost 109.6 and then milepost 86.4. Upon arrival in Richmond Staples Mills Station, a safety penalty fault was active on engine 320 causing the train to stay in emergency. The crew worked with a tech to resolve the issue and clear the fault. Upon arrival into Fayetteville, NC on the South End subdivision, the air hose on car 62016 and car 62019 became disconnected and had to be secured again.

Train	Delay	Comment
97(28)	1'00"	
97(28)	1'15"	Total Car Air Hose

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

Train	Delay	Comment
240(29)	29"	
280(29)	18"	
233(29)	54"	
283(29)	64"	
284(29)	39"	
291(29)	36"	
290(29)	47"	
49(29)	49"	
235(29)	49"	
48(28)	31"	
237(29)	36"	
239(29)	1'10"	

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train 6(28) West of Holdrege, NE - Weather

30AUG26: Train 6(28) operating with engines 148, 83, 388, and 175 customers onboard was delayed 1 miles west of Holdrege, NE on the BNSF Hastings subdivision operating through high winds warnings from milepost 211 to milepost 165.

Train	Delay	Comment
6(28)	32"	

Train 719(29) - Third Party Contractor Engine Failure

30AUG26: Train 719(29) departed Bakersfield on schedule after mechanical personnel met the train to address an air system issue. Shortly after departure, the train was stopped west of Bakersfield due to continual penalty brake applications that the crew was unable to fully recover from. TASI mechanical personnel assisted the crew with troubleshooting efforts, and Road Foreman of Engines (RFE) was dispatched to the location, arriving approximately 10 minutes later. While the train remained stopped, the crew continued working with TASI mechanical personnel and the RFE to diagnose and resolve the issue.

Following troubleshooting and corrective actions, Train 719(29) successfully recovered and resumed movement. The train subsequently arrived and departed Wasco (WAC) at 6:12 p.m. PT, operating approximately 1 hour and 40 minutes behind schedule as a result of the mechanical delay.

Train	Delay	Comment
719(29)	1'42"	

Train 26(29) Mobile, AL - Freight Train Interference

29AUG26: Train 26(29) was delayed holding at 687.4, 11.89 miles south of Mobile AL station on the CSX NO and M subdivision meeting CSX freight train 80129. Train 26(29) was back on the move at 915PM CT after the freight cleared to the south.

Train	Delay	Comment
26(29)	31"	

Train 716(29) South of Wasco, CA - Engine Failure

30AUG26: Train 716(29) 26-FOI-00703 100000008729 UNCLASSIFIED 2014, 9/2/2026 located at 00000008729 location 00000008729 car 6964, seven coaches, and carrying 38 customers, came to a stop approximately two miles south of Wasco, California, on the BNSF Bakersfield Subdivision due to a low-fuel condition. Shortly after departing Wasco, the engineer reported that the train lost load and came to a stop. Upon inspecting the locomotive, the engineer found that both the fuel gauges and the sight glass indicated no fuel was remaining. As a result, Head End Power (HEP) was unavailable. At the time of the incident, the temperature was approximately 79 degrees. The conductor advised that the train was stopped in an area that was difficult for customers to traverse because ballast had been deposited in preparation for upcoming track work. The initial recovery plan called for Train 704(29) to couple to Train 716(29) and tow it into Bakersfield. Train 716(29) was subsequently terminated at Wasco.

Train 704(29) later arrived at the location of Train 716(29), and crews began the coupling process. Road Foreman of Engines responded to the scene to assist. APD was notified and facilitated getting local police to respond to the scene. After the two trains were coupled, the combined 716/704(29) consist departed and proceeded toward Bakersfield. The incident resulted in an approximate delay of three hours to Train 716(29), while Train 704(29) incurred an approximate delay of 35 minutes.

Train	Delay	Comment
716(29)	Term WAC	
716(29)	3'00"	Approximate Delay to Pax
704(29)	51"	

Train 50(29) Chicago, IL - Initial Terminal Delay

29AUG26: Train 50(29) was delayed departing initial terminal of Chicago IL station due to a late turn off 51(28) and the replacement of two bad ordered engines. Train 51(28) arrived to Chicago IL station at 304pm CT operating 4 hours and 39 minutes late. Engine 314 was bad ordered due to a missing speedometer and engine 139 was bad ordered for a traction motor. Engine 196 was identified as the replacement and released from the yard at 627PM CT and tied onto the train at 656PM CT. Train 50(29) was released by mechanical and set in the station at 733PM CT. Train 50(29) departed Chicago IL station at 806PM CT 2 hours and 11 minutes late with 133 passengers on board.

Train	Delay	Comment
50(29)	2'11"	

Train 6(27) West of Chicago, IL - Commuter Train Interference

29AUG26: Train 6(27) was delayed beginning at MP27.6, 27.8 miles west of Chicago IL station on the BNSF Chicago subdivision following a Metra commuter train.

Train	Delay	Comment
6(27)	33"	

Train 22(28) St. Louis, MO - Servicing

29AUG26: Train 22(28) was delayed at St. Louis MO station/MP1.5 on the TRRA Merchants subdivision performing calendar inspections on their engine due to late operation.

Train	Delay	Comment
22(28)	59"	

Train 58(29) South of Marks, MS - Freight Train Interference

29AUG26: Train 58(29) delayed beginning at MP106, 29.6 miles south of Marks MS station on the CN Yazoo city subdivision following CN freight train 8843. Train 58(29) followed the freight into Marks station and was able to resume operating track speed upon departure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(29)	41"	

Train 20(29) North of Tuscaloosa, AL - Freight Train Interference

29AUG26: Train 20(29) was delayed beginning at MP257, north of Tuscaloosa AL station on the AGS South subdivision following Norfolk Southern freight train 340. Train 20(29) followed the freight until MP224 and resumed operating track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(29)	37"	

Train 508(29) South of Oregon City, OR - Freight Train Interference

29AUG26: Train 508(29), operating with engine 1404, 4 coaches and 73 customers, was stopped south of Orocopia (ORC), on UP Brooklyn subdivision, while waiting for a freight train to clear the route. As a result of the congestion, Train 507(29) was also delayed while following the freight train.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
508(29)	46"	
507(29)	23"	

Train 579(29) Fullerton, CA - Engine Failure

29AUG26: Train 579(29) initially experienced a Positive Train Control (PTC) failure south of San Onofre (SNP). The crew stopped the train and rebooted the PTC system, after which the train resumed movement. The incident resulted in an approximate delay of 17 minutes.

Later, Train 579(29), operating with locomotive 58, six coaches, and 23 customers, was stopped west of Fullerton (FUL) due to additional PTC and alerter system issues. The crew worked with CNOC mechanical personnel to troubleshoot the problem while Head End Power (HEP) remained active, allowing onboard services and climate control to continue operating.

As issues with the locomotive continued, Train 579(29) was again stopped east of Los Angeles (LAX) to await a replacement crew. The crew from Train 584(29) was dispatched to rescue the train; however, Train 579(29) remained holding pending the recrew. Due to the locomotive failure on Train 579(29), several service adjustments were implemented to minimize the impact on customers and maintain corridor operations. Train 584(29) was canceled, and its customers were accommodated on Trains 786(29) and 588(29). Train 593(29) was also canceled, with customers accommodated on Train 595(29). Additionally, the equipment from Train 782(29) was scheduled to turn at San Diego and operate as Train 595(29) to support service recovery efforts. Customers from Train 579(29) were transferred to Train 581(29) at Norwalk so they could continue their journey with minimal additional delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
579(29)	2'24"	

Train 11(29) South of Kelso-Longview, WA - Engine Failure

29AUG26: At 12:50P-PT, 26-FOI00703 100000008729 E/350 E/350-9 9/2/2026 was delayed at MP 108.9, 10 miles south of Kelso-Longview, WA, on the BNSF Seattle Subdivision due to head end power(HEP) faults on the trail locomotive E/350. The crew was able to restore HEP briefly before it failed again. There were 215 customers on board and the ambient outside temperature was 67 degrees and partly sunny. The crew contacted an Amtrak road foreman and mechanical to troubleshoot. After multiple troubleshooting efforts, the crew was unable to resolve issues at location. Train 11(29) continued south for approximately 40 minutes with intermittent HEP where mechanical met the train to at Portland station to continue troubleshooting efforts.

Upon arriving at Portland, OR, train 11(29) was inspected by mechanical. They Isolated the trailing engine 350 which resolved the HEP issues.

Train	Delay	Comment
11(29)	54"	
11(29)	9"	Mech Meet PDX

Amtrak PTC Outage - Nationwide

29AUG26: Starting at 3:00PM-ET, Amtrak experienced a nationwide PTC outage that affected many trains across the entire network affecting the east, central, and west. During this time, many Amtrak trains were affected initial terminal and at crew change locations. DT worked to try and resolve the issue. At 4:36PM-ET, services were restored with all trains initializing successfully after Wabtec support restarted their application gateway.

Train	Delay	Comment
64(29)	34"	SYR
66(29)	32"	RNK
124(29)	1'12"	NPN
89(29)	11"	RVR
21(28)	1'15"	FTW
338(28)	33"	MKE
352(28)	1'11"	CHI
21(29)	1'29"	CHI
337(29)	30"	
51(28)	43"	
319(29)	22"	
364(29)	02"	CHI
7/27(29)	47"	
769(29)	1'38"	
579(29)	1'07"	
741(29)	49"	
732(29)	1'13"	
786(29)	1'44"	
713(29)	1'36"	
734(29)	1'04"	
714(29)	1'32"	
790(29)	50"	
89(29)	11"	
53(29)	58"	
128(29)	54"	
52(29)	41"	
98(29)	18"	
2260(29)	08"	
667(29)	02"	
611(29)	05"	
785(29)	48"	
718(29)	1'02"	

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

26:FOI-00703 100000008729 UNCLASSIFIED 9/2/2026
29AUG26: Multiple Pacific Surfliner trains experienced delays due to high tide ocean conditions affecting the Metrolink Orange Subdivision east of San Clemente Pier, between approximately MP 206 and MP 207. The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. These restrictions resulted in cascading delays throughout the corridor, including additional train meets, congestion, and late-turn equipment impacts.

6 customers missed their connection to train 4(29) and needed to be housed for travel the following day.

WBS#: B.TR.100150.7111

Train	Delay	Comment
769(29)	50"	Extended meet at Songs for ML1857
770(29)	59"	
573(29)	47"	
769(29)	50"	
581(29)	1'32"	
580(29)	1'04"	
579(29)	30"	
785(29)	57"	
591(29)	52"	
588(29)	33"	late turn of equipment
588(29)	1'01"	
790(29)	52"	
794(29)	45"	
595(29)	1'45"	

Train 311(29) Lees Summit, MO - Freight Train Interference

29AUG26: Train 311(29) was delayed starting 16.1 miles east of Lee's Summit, MO (MP259.9), on the UPRR Sedalia Subdivision, following UP 8312 starting at Strasburg (MP243.8). At Lee's Summit, Train 311(29) was held after UP 8312 went into emergency on the single main track ahead. The freight conductor inspected the train and discovered a broken knuckle approximately 30 cars behind the head end. A Union Pacific manager responded to assist with replacing the knuckle. Once repairs were completed, Train 311(29) continued following UP 8312 until it was able to pass the freight train at Independence Jct (MP271.2).

Train 316(29) was delayed departing Kansas City, MO, on the Kansas City Terminal KCT Subdivision, due to a late turn of Train 311(29)'s equipment.

Train	Delay	Comment
311(29)	34"	Follow UP 8312
311(29)	1'43"	LEE - Broken Knuckle
316(29)	35"	LATE TURN

Train 769(29) East of San Clemente Pier, CA - Commuter Train Interference

29AUG26: Train 769(29) was delayed at Songs/MP209.3, 4 miles east of San Clemente Pier, CA, on the NCTD San Diego Subdivision holding for commuter rail traffic to clear. Once Metrolink 1857 cleared, Train 769(29) proceeded west.

Train	Delay	Comment
769(29)	50"	

Train 6(27) East of Burlington, IA - Freight Train Interference

29AUG26: Train 6(27) was delayed starting 0.5 miles east of Burlington, IA (MP205.6), on the BNSF Ottumwa Subdivision, following BNSF 7657 from South Street (MP205.1) into Galesburg, IL (MP162.6).

Train 318(29) West of Sedalia, MO - Freight Train Interference

29AUG26: Train 318(29) was held 6.8 miles west of Sedalia, MO (MP188.9), on the UPRR Sedalia Subdivision at Dresden to meet UP 8312. The freight experienced air issues but quickly recovered and cleared. Once a route was established, Train 318(29) advanced 12.8 miles east into the Smithton siding (MP182.9) behind UP 7950 to allow Train 311(29) to pass through the territory. Train 311(29) was delayed en route after having to sawby UP 7679 at Dow (MP165.2). After Train 311(29) cleared the area, Train 318(29) reversed out of the siding and continued east, operating around UP 7679 at Dow.

Train	Delay	Comment
318(29)	35"	Dresden
311(29)	16"	Dow
318(29)	09"	Dow
318(29)	33"	Smithton

Train 7(27) West of Leavenworth, WA - Police Related

29AUG26: Train 7(27) was delayed at MP 1721.2, 36 miles west of Leavenworth, WA, on the BNSF Scenic Subdivision due to BNSF freight FEPPEM4-28A ahead with a fire on BN7265 on main track one. The crew held while the local fire dept responded to the scene and was able to contain the fire. Once the fire was contained, the crew operated past the area at restricted speed on main track two. After Train 7(37) was through the affected area, the crew proceeded at track speed.

Train	Delay	Comment
7(27)	1'08"	

Train 19(28) South of Atlanta, GA - Signal

29AUG26: Train 19(28) was delayed south of Atlanta, GA (MP633.3), on the NSRR East End Subdivision due to a signal failure at Austell (MP124.7). A lightning strike overnight damaged the signal, requiring Maintenance of Way forces to perform repairs and restore the system. Upon completion of the repairs and restoration of signal functionality, Train 19(28) was released to continue south.

Train	Delay	Comment
19(28)	1'09"	

Train 718(28) East of Wasco, CA - Temporary Speed Restrictions

29AUG26: Train 718(28) was delayed starting at Shafter/MP 905.2, 8 miles east of Wasco, CA, on the BNSF Bakersfield Subdivision due to temporary speed restrictions put in place by the BNSF. The crew operate at a restricted speed not exceeding 15MPH from MP 905.2 to MP 902.8. The crew was further delayed operating at restricted speed not exceeding 25MPH from MP 901.0 until MP 898.0. Once the crew was through affected area, they proceeded at track speed.

Train	Delay	Comment
718(28)	30"	

Train 2/422(28) East of Palm Springs, CA - Freight Train Interference

29AUG26: Train 2/422(28) delayed starting at Thermal/MP 589.0, 1 miles east of Palm Spring, CA, on the UPRR Yuma Subdivision due to freight interference. The crew held at MP 589.0 for meet with UP2671 and UP2533. Once the east bound freights were clear, Train 2/422(28) was further delayed starting at Thermal/MP 620.2 following UP8892 until Bertram/MP 646.1. AT Clyde/ MP 707.9, the crew held, again, for meet with UP7824.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422 (28)	22"	UP2671/UP2533
2/422 (28)	17"	UP8892
2/422 (28)	11"	UP7409

Train 365(29) West of Flint, MI - Freight Train Interference

29AUG26: Train 365(29) held 1.7 miles west of Flint, MI (MP271.7), on the CNRR Flint Subdivision, in the Flint siding (MP270.0) waiting on eastbound CN 3240 to clear. The freight train was stopped ahead waiting on their recrew to arrive. Once a route was established, Train 365(29) was back on the move west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
365 (29)	32"	

Train 3(28) East of La Junta, CO - Vehicle on Tracks

29AUG26: Train 3(28) was held 18.3 miles east of La Junta, CO (MP554.9), on the BNSF Boise City Subdivision at Las Animas (MP536.6) due to a vehicle stuck on the tracks at MP541.2. After the vehicle was removed and the track was inspected, Train 3(28) was released to proceed west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3 (28)	35"	

Train 351(29) Troy, MI - Engine Failure

29AUG26: At 6:03AM-ET, Train 351(29), E/ID4633 and five cars, was delayed at the Troy, MI station (MP17.4) on the CNRR Holly Subdivision due to a damaged HEP cable, resulting in a loss of head end power to the trainset with 27 customers onboard. Weather conditions were 60 degrees. Pontiac Mechanical responded quickly and replaced the damaged cable. At 7:34AM-ET, HEP was restored to the trainset, and Train 351(29) was back on the move.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
351 (29)	1'30"	

Train 51(28) Cincinnati, OH - Freight Train Interference

29AUG26: At 3:00 AM ET, Train 51(28) was delayed at Cincinnati, OH (MP 2.1) on the CSX Louisville Subdivision due to disabled CSX freight train M361-28 ahead at McGonigle (MP 32.7). M361-28 experienced locomotive issues, and its crew subsequently expired under Hours of Service regulations. A relief crew boarded M361-28 at 4:45 AM and worked to recover the train from the locomotive failure. At 5:44 AM, Train 51(28) was released from Cincinnati and proceeded westward. During the delay period, M361-28 successfully recovered and cleared into the McGonigle siding prior to Train 51(28)'s arrival, resulting in no additional delay beyond the initial hold.

Train 22(28)/422(26) Dallas, TX - Recrew / Freight Interference

29AUG26: Train 22(28)/422(26) (00000008729) held at Dallas, TX (MP214.4) on the UPRR Dallas Subdivision awaiting the arrival of UP pilots to protect the crew east. After the pilots boarded, the train proceeded 50.3 miles east before stopping at Willis Point (MP166.7) on the UPRR Mineola Subdivision due to UP 5782 stopped ahead with air issues. The freight crew identified a broken air hose but did not have a replacement available. The crew of Train 22(28)/422(26) provided a spare air hose, which was installed by the freight crew; however, air issues persisted. The freight crew subsequently discovered and corrected a problem with the end-of-train device. After air was restored and a route was established, Train 22(28)/422(26) continued east.

Additional delay was incurred 13.3 miles east of Mineola, TX (MP136.1), at Fada (MP122.8), awaiting the Marshall recrew and a new set of Union Pacific pilots, as the original pilots were not qualified to operate through to Marshall. Once the replacement crew and pilots boarded, the train proceeded approximately 5 miles before stopping at MP117.8 to inspect axle 12 on engine 325 after a wayside detector alert. The crew conducted an inspection and found no defects. Train 22(28)/422(26) was subsequently released to continue to Marshall.

Train	Delay	Comment
22(28)/422(26)	1'59"	UP 5782
22(28)/422(26)	42"	DAL - Pilots
22(28)/422(26)	35"	Fada - Witronix
22(28)/422(26)	35"	MP117.8 - Witronix

Train 21(27) North of San Antonio, TX - Weather

29AUG26: Train 21(27), with 66 customers onboard, encountered multiple operating conditions south of San Marcos, TX (MP209.8), on the UPRR Austin Subdivision, resulting in significant delay. The train operated through restrictive signals between CP248 and CP259. Weather-related conditions further impacted operations, including flash flood warnings between MP212 and MP260, trees down near CP233 Corbin, and storm debris, downed trees, and power lines fouling the track at North Loop near MP258.90. Due to the track ahead being impassable, the train was required to back up from CP252 to CP238 and operate via Main 2 into the San Antonio, TX station from Tower 205. The train also encountered freight interference while meeting UP 6238 at CP Q937 and required a re-crew at North Loop. These combined signal, weather, routing, and freight interference conditions contributed to the delay.

Train 22(22) departed San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision, 18 minutes late due to a late turn of equipment. After departure, the train had to wye the equipment on the outbound as a result of Train 21(27) coming in backwards the night prior via main track 2. Once the wye move was complete, Train 22(22) was able to proceed north.

Train	Delay	Comment
21(27)	1'00"	Signals
21(27)	2'20"	Trees Down
21(27)	05"	Flash Flood
21(27)	15"	Recrew - North Loop
21(27)	1'04"	Reverse to go MT1 to MT2
21(27)	35"	UP 6238
22(29)	18"	ITD SAS
22(29)	1'21"	Wye / Routing to SMC

Maintenance of Way Highlights

Metra BRC / Kenton Line - Scheduled M/W Work TWA 26-093

28AUG26: Metra has trackwork scheduled at the 80th Street Interlocking for the Rock Island Bridge Project starting Friday, August 28th through Sunday, August 30th. To accommodate the outlined infrastructure work, Amtrak's Cardinal Service has been adjusted as follows:

- Train 51(28Aug) will shift between Belt Junction and 80th Street Interlocking using Metra Main 1 and NS Stack Connection tracks before resuming normal operation onto the Metra Southwest Sub District. Delays of approximately 1-hour can be expected.
- Train 50(29Aug) will shift between Belt Junction and 80th Street Interlocking using Metra Main 1 and NS Stack Connection tracks before resuming normal operation onto the UPRR Villa Grove Subdivision. Delays of approximately 1-hour can be expected.

WBS#: B.TR.100150.7057

Train	Delay	Comment
51(28)	33"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
- Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
- Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
- Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.

*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task controlled work scheduled on C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues
22 (18)	XNT	315		I/O 47 faults

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (28)	SEA	BNSF6688	E/368 Fuel faults		
22 (28)	SAS	UP5068	E/325 Battery faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
449 (29)	BOS	all table lounge in lieu of amll lounge due to equipment availability. no customer impact.	no impact	0	43391
381 (29)	CHI	TRAIN WILL OPERATE WITH A EXTRA BUSINESS CLASS /CAFE IN LIEU OF A COACH. DUE TO B/O OF COACH CAR. INVENTORY REDUCED.	0 IMPACT	0	48181
448 (28)	CHI	Train 448(28) coach car 25090 having a HVAC issue on it's A end. We have reduced inventory to half the coach car. It has not caused any standees as a result.	0 IMPACT	0	25090
21 (29)	CHI	OPERATING WITH SLPR IN LIEU OF T-DORM A/C 39010 SHOPPED NO REPLACEMENT. SCHEDULE CHANGE HAS BEEN PERFORMED. CNOC CSV WILL NEED TO BLOCK ALL DS/HS/FS ROOMS.	n/a	0	32098
7 (29)	CHI	OPERATING WITH SLPR IN LIEU OF T-DORM A/C 39021 SHOPPED NO REPLACEMENT CAR. SCHEDULE CHANGE HAS BEEN PERFORMED. CNOC CSV WILL NEED TO BLOCK ALL DS AND FS ROOM.	n/a	0	32074
59 (30)	CHI	OPERATING WITH DINER IN LIEU OF DINER/ LOUNGE UNABLE TO CORRECT CONSIST.	n/a	0	38032
770 (30)	GTA	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.	-2 pax	2	90225
572 (29)	LAX	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.	n/a	0	90225
588 (30)	LAX	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO	0 impact	0	90225

Train Number	Station	Reason 26-FOI-00703 00000008729 "UNCLASSIFIED" 9/2/20	Customer Impact	Affected Psgr	Unit Number(s)
		ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.			
158 (29)	NFK	Business Class Coach 81514 operating in lieu of regular Coach - 10 less seats vs planned inventory, no passenger impact	0 impact	0	81514
382 (29)	QCY	TRAIN WILL OPERATE WITH A EXTRA BUSINESS CLASS /CAFE IN LIEU OF A COACH. DUE TO B/O OF COACH CAR. INVENTORY REDUCED.	0 IMPACT	0	48181
567 (29)	SAN	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.	n/o	0	90225
587 (29)	SAN	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.	n/a	0	90225
581 (30)	SAN	DUE TO EQUIPMENT SWAP WILL BE OPERATING WITH 90225 IN CONSIST. UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC SVC WILL NEED TO ACCOMMODATE PASSENGERS IMPACTED BY THIS.	-3 pax	3	90225
22 (31)	SAS	OPERATING WITH SLPR IN LIEU OF T-DORM A/C 39010 SHOPPED NO REPLACEMENT. SCHEDULE CHANGE HAS BEEN PERFORMED. CNOC CSV WILL NEED TO BLOCK ALL DS/HS/FS ROOMS.	n/a	0	32047
8 (31)	SEA	OPERATING WITH SLPR IN LIEU OF T-DORM A/C 39021 SHOPPED NO REPLACEMENT CAR. SCHEDULE CHANGE HAS BEEN PERFORMED. CNOC CSV WILL NEED TO BLOCK ALL DS AND FS ROOM.	n/a	0	32074

Reverse Consists

26-FOI-00703

00000008729

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason
195 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front
161 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front
150 (29)	PHL	Consist reversed Business class seat orientation may have changed At Front
127 (29)	NYP	Consist reversed Business class seat orientation may have changed At Rear
87 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front
88 (29)	WAS	Consist reversed Business class seat orientation may have changed At Front
194 (29)	WAS	Consist reversed Business class seat orientation may have changed At Front
168 (29)	WAS	Consist reversed Business class seat orientation may have changed At Front
156 (30)	RNK	Consist reversed Business class seat orientation may have changed At Front
123 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
135 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front
128 (30)	NFK	Consist reversed Business class seat orientation may have changed At Front