

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, August 10, 2026

Rules: 0-45



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/09/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	274	56	79.6%	2,688	481	82.1%	93,560	13,025	86.1%
Central Division	86.0%	52	5	90.4%	488	58	88.1%	17,844	1,624	90.9%
East Division	82.0%	143	33	76.9%	1,453	255	82.5%	49,123	7,673	84.4%
West Division	86.0%	79	18	77.2%	747	168	77.5%	26,593	3,728	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00671 00000008700 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/9/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	104,544	36,908	65%	982,423	316,191	68%	31,315,421	7,957,541	75%
Northeast Corridor	81%	44,838	17,193	62%	422,765	122,121	71%	13,724,278	3,378,149	75%
Acela	83%	8,727	3,434	61%	86,735	21,334	75%	2,747,159	722,885	74%
Northeast Regional	79%	36,111	13,759	62%	336,030	100,787	70%	10,977,119	2,655,264	76%
Richmond / Newport News / Norfolk	77%	12,628	5,788	54%	106,180	42,543	60%	3,406,156	1,004,004	71%
Springfield Shuttles	89%	0	0	-	4,908	831	83%	192,635	30,699	84%
Roanoke	79%	2,695	1,169	57%	33,177	9,243	72%	1,038,461	227,899	78%
On Spine Northeast Regional	80%	20,788	6,802	67%	191,765	48,170	75%	6,339,867	1,392,662	78%
State Supported	80%	45,873	11,284	75%	443,013	123,436	72%	13,752,632	2,929,361	79%
Borealis	80%	667	0	100%	5,536	671	88%	175,162	36,303	79%
Capitol Corridor	90%	2,339	278	88%	31,675	6,037	81%	1,147,394	151,786	87%
Carolinian	70%	511	469	8%	9,509	5,168	46%	354,391	140,167	60%
Cascades	75%	1,802	571	68%	16,762	8,636	48%	800,012	223,672	72%
Downeaster	82%	2,308	327	86%	19,324	2,522	87%	479,637	58,477	88%
Empire	78%	5,815	1,899	67%	57,865	19,680	66%	1,701,578	403,139	76%
Adirondack	72%	193	128	34%	3,992	2,015	50%	103,955	32,860	68%
Ethan Allen Express	70%	651	613	6%	5,607	3,698	34%	174,515	64,047	63%
Maple Leaf	70%	914	70	92%	8,247	3,123	62%	208,596	79,966	62%
New York - Albany	85%	2,421	767	68%	25,590	6,444	75%	787,938	132,371	83%
New York - Niagara Falls	75%	1,353	321	76%	12,965	3,234	75%	416,997	88,915	79%
Berkshire Flyer	60%	283	0	100%	1,464	1,166	20%	9,577	4,980	48%
Gold Runner	73%	2,641	992	62%	23,250	12,743	45%	778,816	283,196	64%
Heartland Flyer	70%	318	186	42%	2,649	2,048	23%	67,332	27,470	59%
Hiawatha	90%	1,560	78	95%	18,751	1,232	93%	539,670	58,929	89%
Illinois	78%	2,987	855	71%	24,362	7,563	69%	770,586	212,118	72%
Carl Sandburg / Illinois Zephyr	85%	683	162	76%	4,033	1,667	59%	128,833	35,825	72%
Illini / Saluki	85%	896	204	77%	7,851	2,588	67%	267,738	64,488	76%
Lincoln Service	70%	1,408	489	65%	12,478	3,308	73%	374,015	111,805	70%
Keystone	92%	5,062	205	96%	68,558	3,636	95%	2,350,677	243,182	90%
Lincoln / Missouri	70%	1,429	913	36%	8,314	4,993	40%	240,805	123,301	49%
Mardi Gras Service	80%	346	0	100%	3,168	831	74%	126,889	28,446	78%
Michigan	70%	2,577	1,754	32%	22,785	10,279	55%	620,210	202,700	67%
Blue Water	70%	687	653	5%	5,510	2,960	46%	145,168	58,788	60%
Pere Marquette	85%	171	0	100%	2,430	176	93%	80,864	15,300	81%
Wolverine	70%	1,719	1,101	36%	14,845	7,143	52%	394,178	128,612	67%
Missouri	80%	446	344	23%	2,749	1,242	55%	68,585	17,678	74%
Pacific Surfliner	85%	11,749	2,141	82%	99,077	28,365	71%	2,511,249	458,072	82%
Pennsylvanian	80%	915	51	94%	7,958	2,078	74%	273,760	53,155	81%
Piedmont	80%	1,263	221	83%	9,127	1,338	85%	349,401	89,990	74%
Vermont	75%	1,138	0	100%	11,594	4,374	62%	396,478	117,580	70%
Long Distance	70%	13,833	8,431	39%	116,645	70,634	39%	3,799,244	1,647,568	57%
Auto Train	70%	911	0	100%	7,859	1,383	82%	242,268	82,172	66%
California Zephyr	70%	1,070	889	17%	9,339	7,206	23%	300,933	113,863	62%
Cardinal	70%	0	0	-	1,483	890	40%	72,964	36,433	50%
City Of New Orleans	75%	557	253	55%	5,770	4,346	25%	196,994	62,525	68%
Coast Starlight	70%	972	415	57%	9,687	5,514	43%	354,364	125,976	64%
Crescent	70%	955	318	67%	8,033	1,616	80%	287,686	87,599	70%
Empire Builder	70%	1,018	310	70%	8,928	6,643	26%	297,295	148,848	50%
Floridian	60%	1,846	1,488	19%	15,824	12,390	22%	493,590	339,432	31%
Lake Shore Ltd	73%	1,190	473	60%	10,805	4,766	56%	298,042	89,872	70%
Palmetto	70%	1,392	1,328	5%	8,705	5,254	40%	284,808	87,863	69%
Silver Meteor	70%	972	940	3%	9,106	6,566	28%	314,306	143,917	54%
Southwest Chief	60%	989	763	23%	9,311	6,917	26%	259,777	169,510	35%
Sunset Ltd	70%	295	295	0%	2,049	1,656	19%	90,415	34,424	62%
Texas Eagle	70%	1,666	959	42%	9,746	5,487	44%	305,802	125,134	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 00000000700 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 09, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	62,447	954,160	654	1,852,526	32,902,097	563

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,586	284,753	126	89,498	9,481,755	94
INFRASTRUCTURE PLANNED	135	5,261	284,753	185	101,316	9,481,755	107
FLEET RELIABILITY	90	9,997	954,160	105	296,137	32,902,097	90
TRAIN OPERATIONS	424	43,603	954,160	457	1,365,575	32,902,097	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/09/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	274	56	79.6%	2,688	481	82.1%	93,560	13,025	86.1%
Central Division	86.0%	52	5	90.4%	488	58	88.1%	17,844	1,624	90.9%
East Division	82.0%	143	33	76.9%	1,453	255	82.5%	49,123	7,673	84.4%
West Division	86.0%	79	18	77.2%	747	168	77.5%	26,593	3,728	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/09/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	274	56	79.6%	2,688	481	82.1%	93,560	13,025	86.1%
Central Division	86.0%	52	5	90.4%	488	58	88.1%	17,844	1,624	90.9%
CDL	95.0%	2	1	50.0%	18	3	83.3%	594	28	95.3%
CHI	86.0%	24	2	91.7%	225	34	84.9%	8,239	998	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	9	0	100.0%	336	36	89.3%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	7	0	100.0%	295	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	9	2	77.8%	566	44	92.2%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	0	100.0%	51	3	94.1%	1,831	117	93.6%
MOE	97.5%	2	0	100.0%	18	0	100.0%	623	9	98.6%
MSP	96.5%	1	0	100.0%	9	1	88.9%	306	7	97.7%
NOL	94.5%	4	0	100.0%	40	2	95.0%	1,313	62	95.3%
OKC	97.0%	1	0	100.0%	9	0	100.0%	307	6	98.0%
PNT	88.0%	3	0	100.0%	26	2	92.3%	813	66	91.9%
PTH	93.0%	1	1	0.0%	9	2	77.8%	301	13	95.7%
QCY	91.0%	2	0	100.0%	15	2	86.7%	592	45	92.4%
SAS	90.5%	1	1	0.0%	9	3	66.7%	310	36	88.4%
STL	89.0%	3	0	100.0%	33	3	90.9%	1,202	100	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	143	33	76.9%	1,453	255	82.5%	49,123	7,673	84.4%
ALB	88.5%	6	1	83.3%	68	5	92.6%	2,318	180	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	45	8	82.2%	1,511	166	89.0%
BOS	85.5%	17	1	94.1%	158	11	93.0%	5,321	615	88.4%
BRK	92.5%	5	1	80.0%	45	4	91.1%	1,497	106	92.9%
BTN	82.0%	1	0	100.0%	9	0	100.0%	299	41	86.3%
CLT	91.5%	5	0	100.0%	45	4	91.1%	1,522	154	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	-	-	-	11	0	100.0%	604	57	90.6%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	7	1	85.7%	93	15	83.9%	3,457	563	83.7%
HFD	-	-	-	-	10	3	70.0%	201	18	91.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	9	0	100.0%	309	38	87.7%
MIA	89.5%	2	0	100.0%	18	2	88.9%	618	70	88.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/09/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	274	56	79.6%	2,688	481	82.1%	93,560	13,025	86.1%
East Division	82.0%	143	33	76.9%	1,453	255	82.5%	49,123	7,673	84.4%
MTR	79.0%	1	1	0.0%	9	4	55.6%	296	56	81.1%
NFK	84.5%	2	0	100.0%	18	3	83.3%	701	126	82.0%
NFL	93.5%	2	0	100.0%	18	1	94.4%	630	30	95.2%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	3	2	33.3%	41	10	75.6%	1,595	263	83.5%
NPN	93.0%	2	0	100.0%	18	3	83.3%	590	44	92.5%
NYP	75.5%	42	13	69.0%	406	105	74.1%	12,890	2,883	77.6%
PGH	93.0%	1	0	100.0%	9	1	88.9%	310	23	92.6%
PHL	48.0%	4	3	25.0%	41	23	43.9%	1,591	763	52.0%
PIT	76.0%	1	1	0.0%	3	3	0.0%	18	15	16.7%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	1	75.0%	28	1	96.4%	1,186	50	95.8%
RNK	83.5%	2	2	0.0%	18	2	88.9%	614	89	85.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	-	-	-	6	0	100.0%	293	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	9	0	100.0%	306	10	96.7%
SFA	88.0%	1	0	100.0%	9	0	100.0%	309	41	86.7%
SPG	92.5%	-	-	-	40	2	95.0%	1,847	107	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	9	1	88.9%	298	61	79.5%
WAS	84.0%	27	5	81.5%	252	44	82.5%	7,724	1,011	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	79	18	77.2%	747	168	77.5%	26,593	3,728	86.0%
ARN	92.0%	1	1	0.0%	9	2	77.8%	311	28	91.0%
BFD	79.0%	7	2	71.4%	62	16	74.2%	1,959	409	79.1%
EMY	72.0%	1	0	100.0%	9	2	77.8%	327	96	70.6%
EUG	86.5%	2	0	100.0%	18	1	94.4%	616	57	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	27	9	66.7%	936	152	83.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	0	100.0%	93	8	91.4%	3,092	334	89.2%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	4	55.6%	99	44	55.6%	3,360	872	74.0%
PDX	86.0%	3	3	0.0%	20	13	35.0%	1,508	194	87.1%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/09/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	274	56	79.6%	2,688	481	82.1%	93,560	13,025	86.1%
West Division	86.0%	79	18	77.2%	747	168	77.5%	26,593	3,728	86.0%
SAC	88.5%	12	2	83.3%	126	15	88.1%	4,392	477	89.1%
SAN	90.5%	13	0	100.0%	116	11	90.5%	3,757	355	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	0	100.0%	46	24	47.8%	2,431	371	84.7%
SJC	89.0%	7	2	71.4%	62	8	87.1%	2,186	217	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	27	5	81.5%	699	70	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	18	0	100.0%	609	14	97.7%
VAN	-	2	2	0.0%	9	7	22.2%	9	7	22.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	108	4	3	25.0%	133	34	74.4%	4	2	50.0%	128	26	79.7%
3		9	2	77.8%	311	61	80.4%	9	6	33.3%	309	142	54.0%
4	152	9	0	100.0%	310	46	85.2%	9	6	33.3%	310	205	33.9%
5	139	9	1	88.9%	309	51	83.5%	9	9	0.0%	305	97	68.2%
6	145	9	2	77.8%	308	87	71.8%	9	8	11.1%	308	111	64.0%
7		9	3	66.7%	300	45	85.0%	8	5	37.5%	291	79	72.9%
8		9	7	22.2%	300	136	54.7%	9	7	22.2%	299	182	39.1%
11		9	7	22.2%	311	64	79.4%	9	2	77.8%	305	62	79.7%
14	53	9	2	77.8%	312	51	83.7%	8	7	12.5%	309	99	68.0%
19		9	1	88.9%	310	78	74.8%	9	1	88.9%	307	72	76.5%
20		9	0	100.0%	310	23	92.6%	9	1	88.9%	310	59	81.0%
21		9	4	55.6%	307	29	90.6%	9	4	55.6%	306	86	71.9%
22		9	3	66.7%	308	34	89.0%	9	3	66.7%	306	84	72.5%
23		9	0	100.0%	312	6	98.1%	9	2	77.8%	310	87	71.9%
24		9	0	100.0%	312	16	94.9%	9	3	66.7%	311	59	81.0%
25		9	0	100.0%	311	3	99.0%	8	4	50.0%	308	87	71.8%
26		9	0	100.0%	311	5	98.4%	8	1	87.5%	308	61	80.2%
40	62	9	2	77.8%	305	43	85.9%	9	5	44.4%	302	160	47.0%
41	75	9	3	66.7%	304	117	61.5%	9	7	22.2%	302	231	23.5%
42		9	1	88.9%	312	25	92.0%	9	3	66.7%	310	55	82.3%
43		9	1	88.9%	311	43	86.2%	9	1	88.9%	310	71	77.1%
48		9	3	66.7%	310	60	80.6%	9	1	88.9%	309	43	86.1%
49		9	3	66.7%	310	78	74.8%	9	3	66.7%	310	65	79.0%
50	102	3	0	100.0%	127	30	76.4%	3	2	33.3%	127	78	38.6%
52		9	0	100.0%	309	41	86.7%	9	0	100.0%	308	72	76.6%
53		9	0	100.0%	309	38	87.7%	9	3	66.7%	308	98	68.2%
54		4	0	100.0%	113	8	92.9%	4	0	100.0%	113	16	85.8%
57		4	0	100.0%	112	5	95.5%	4	0	100.0%	112	9	92.0%
58	62	9	1	88.9%	286	17	94.1%	8	7	12.5%	284	80	71.8%
59		9	7	22.2%	284	40	85.9%	9	6	33.3%	280	63	77.5%
63	36	9	4	55.6%	313	136	56.5%	9	9	0.0%	307	175	43.0%
64		9	1	88.9%	311	69	77.8%	9	6	33.3%	310	115	62.9%
65		3	0	100.0%	96	12	87.5%	4	1	75.0%	95	14	85.3%
66		9	1	88.9%	310	62	80.0%	9	2	77.8%	306	56	81.7%
68	116	9	4	55.6%	313	65	79.2%	9	5	44.4%	312	123	60.6%
69	44	9	7	22.2%	300	75	75.0%	9	6	33.3%	295	49	83.4%
71	20	9	0	100.0%	308	3	99.0%	8	1	87.5%	306	82	73.2%
72		9	2	77.8%	304	33	89.1%	8	2	75.0%	302	63	79.1%
73	13	9	1	88.9%	307	20	93.5%	9	2	77.8%	305	144	52.8%
74		9	0	100.0%	305	33	89.2%	9	2	77.8%	303	110	63.7%
75		9	0	100.0%	301	16	94.7%	9	1	88.9%	295	138	53.2%
76		9	0	100.0%	301	29	90.4%	9	3	66.7%	292	120	58.9%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		9	0	100.0%	303	20	93.4%	9	2	77.8%	301	125	58.5%
78	37	9	0	100.0%	307	25	91.9%	9	4	55.6%	306	67	78.1%
79	84	9	1	88.9%	310	57	81.6%	9	3	66.7%	309	104	66.3%
80	38	9	2	77.8%	310	35	88.7%	9	5	44.4%	307	68	77.9%
87	77	4	1	75.0%	116	25	78.4%	4	3	25.0%	116	42	63.8%
88		4	0	100.0%	112	15	86.6%	4	1	75.0%	112	24	78.6%
89	41	9	5	44.4%	308	70	77.3%	9	6	33.3%	306	91	70.3%
90		9	0	100.0%	308	10	96.8%	9	4	55.6%	307	55	82.1%
96		2	0	100.0%	40	8	80.0%	2	0	100.0%	40	10	75.0%
97	35	9	8	11.1%	310	206	33.5%	9	6	33.3%	308	106	65.6%
98	217	9	0	100.0%	310	26	91.6%	9	7	22.2%	308	115	62.7%
99	35	4	0	100.0%	115	12	89.6%	4	3	25.0%	112	64	42.9%
100		2	0	100.0%	25	5	80.0%	2	0	100.0%	24	4	83.3%
103		4	2	50.0%	114	23	79.8%	4	2	50.0%	114	11	90.4%
104		2	0	100.0%	37	4	89.2%	2	0	100.0%	37	3	91.9%
105		2	2	0.0%	39	19	51.3%	2	1	50.0%	39	7	82.1%
117		2	2	0.0%	24	15	37.5%	2	0	100.0%	24	4	83.3%
118		4	0	100.0%	114	8	93.0%	4	0	100.0%	114	8	93.0%
120	17	2	0	100.0%	40	5	87.5%	2	1	50.0%	40	5	87.5%
121	93	2	1	50.0%	40	12	70.0%	2	1	50.0%	40	17	57.5%
122	88	2	1	50.0%	39	16	59.0%	2	2	0.0%	39	10	74.4%
123		2	1	50.0%	42	7	83.3%	2	0	100.0%	42	1	97.6%
124	34	4	0	100.0%	113	8	92.9%	4	2	50.0%	112	32	71.4%
128		4	0	100.0%	116	19	83.6%	3	1	66.7%	115	23	80.0%
132	37	2	0	100.0%	40	3	92.5%	2	1	50.0%	40	5	87.5%
135		4	0	100.0%	115	17	85.2%	4	0	100.0%	115	56	51.3%
140		4	1	75.0%	114	13	88.6%	4	2	50.0%	113	26	77.0%
143		4	2	50.0%	113	13	88.5%	4	0	100.0%	113	25	77.9%
145	21	2	1	50.0%	40	7	82.5%	2	1	50.0%	40	15	62.5%
146	29	4	0	100.0%	113	17	85.0%	4	1	75.0%	113	40	64.6%
149		2	0	100.0%	40	3	92.5%	2	0	100.0%	40	14	65.0%
150		4	1	75.0%	112	58	48.2%	4	0	100.0%	110	51	53.6%
151		9	5	44.4%	309	100	67.6%	9	0	100.0%	308	95	69.2%
153	35	4	1	75.0%	114	11	90.4%	4	3	25.0%	114	19	83.3%
154		2	0	100.0%	40	5	87.5%	2	0	100.0%	40	20	50.0%
155	30	4	1	75.0%	116	19	83.6%	4	1	75.0%	116	41	64.7%
156	29	4	1	75.0%	116	12	89.7%	4	2	50.0%	116	40	65.5%
157		2	1	50.0%	40	4	90.0%	2	0	100.0%	40	12	70.0%
158		4	2	50.0%	115	22	80.9%	4	1	75.0%	115	27	76.5%
160		4	1	75.0%	113	7	93.8%	4	0	100.0%	110	26	76.4%
161	36	4	0	100.0%	114	9	92.1%	4	3	25.0%	113	75	33.6%
162		4	3	25.0%	114	10	91.2%	4	1	75.0%	114	56	50.9%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
164	27	4	0	100.0%	116	9	92.2%	4	1	75.0%	116	48	58.6%
165		4	0	100.0%	114	27	76.3%	4	1	75.0%	114	46	59.6%
169		4	0	100.0%	114	12	89.5%	3	0	100.0%	113	24	78.8%
189	48	2	1	50.0%	39	12	69.2%	2	2	0.0%	39	17	56.4%
195	45	4	1	75.0%	114	5	95.6%	4	3	25.0%	114	62	45.6%
230		9	0	100.0%	146	4	97.3%	9	0	100.0%	146	7	95.2%
232		9	0	100.0%	312	11	96.5%	9	1	88.9%	312	22	92.9%
234		9	0	100.0%	313	22	93.0%	9	0	100.0%	312	25	92.0%
235		9	4	55.6%	237	38	84.0%	9	2	77.8%	236	54	77.1%
236	20	9	0	100.0%	297	10	96.6%	9	3	66.7%	296	42	85.8%
237		9	0	100.0%	310	56	81.9%	9	1	88.9%	308	52	83.1%
238		9	3	66.7%	237	23	90.3%	9	1	88.9%	235	19	91.9%
239		9	1	88.9%	311	80	74.3%	9	0	100.0%	310	38	87.7%
240	17	9	1	88.9%	312	22	92.9%	9	3	66.7%	309	63	79.6%
241	16	9	2	77.8%	312	76	75.6%	9	4	55.6%	312	75	76.0%
243		9	2	77.8%	248	67	73.0%	9	2	77.8%	247	35	85.8%
245		9	2	77.8%	193	35	81.9%	9	2	77.8%	192	24	87.5%
280		9	1	88.9%	313	16	94.9%	9	2	77.8%	312	63	79.8%
281		9	0	100.0%	313	37	88.2%	9	1	88.9%	313	58	81.5%
283	43	9	5	44.4%	313	79	74.8%	9	3	66.7%	313	64	79.6%
284		9	0	100.0%	313	13	95.8%	9	1	88.9%	310	55	82.3%
290	27	9	0	100.0%	313	50	84.0%	9	6	33.3%	310	120	61.3%
291	23	9	6	33.3%	312	99	68.3%	9	5	44.4%	310	81	73.9%
301		9	0	100.0%	310	10	96.8%	9	2	77.8%	306	57	81.4%
302	26	8	0	100.0%	291	33	88.7%	8	2	75.0%	287	80	72.1%
305		7	0	100.0%	293	28	90.4%	7	0	100.0%	289	115	60.2%
306	Cncld	9	1	88.9%	308	17	94.5%	8	2	75.0%	306	84	72.5%
307		9	1	88.9%	301	39	87.0%	8	3	62.5%	297	85	71.4%
311	44	9	1	88.9%	306	27	91.2%	9	4	55.6%	300	67	77.7%
316	24	9	2	77.8%	302	20	93.4%	9	6	33.3%	297	84	71.7%
318	61	9	0	100.0%	311	31	90.0%	9	5	44.4%	308	149	51.6%
319	33	9	0	100.0%	312	20	93.6%	9	8	11.1%	307	173	43.6%
331		9	0	100.0%	313	33	89.5%	9	0	100.0%	313	44	85.9%
332		8	0	100.0%	312	17	94.6%	8	0	100.0%	312	43	86.2%
334		9	0	100.0%	313	10	96.8%	9	0	100.0%	312	40	87.2%
335		9	0	100.0%	313	34	89.1%	9	2	77.8%	311	53	83.0%
336		9	0	100.0%	313	10	96.8%	9	0	100.0%	311	28	91.0%
337	11	9	0	100.0%	313	18	94.2%	9	2	77.8%	309	38	87.7%
338	11	9	2	77.8%	313	49	84.3%	9	5	44.4%	311	99	68.2%
339		9	2	77.8%	313	52	83.4%	9	1	88.9%	313	54	82.7%
341	14	8	2	75.0%	300	46	84.7%	8	3	62.5%	294	44	85.0%
342		9	1	88.9%	313	25	92.0%	9	0	100.0%	311	60	80.7%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
350	32	9	0	100.0%	290	18	93.8%	9	7	22.2%	283	158	44.2%
351		8	1	87.5%	295	28	90.5%	8	4	50.0%	293	82	72.0%
352	101	8	1	87.5%	279	22	92.1%	8	4	50.0%	273	85	68.9%
353	32	9	0	100.0%	251	13	94.8%	9	2	77.8%	245	40	83.7%
354	49	9	0	100.0%	294	35	88.1%	9	7	22.2%	287	108	62.4%
355	35	9	1	88.9%	303	32	89.4%	9	8	11.1%	296	107	63.9%
364		9	3	66.7%	302	68	77.5%	9	4	55.6%	296	111	62.5%
365	53	9	2	77.8%	301	13	95.7%	8	4	50.0%	298	113	62.1%
371		7	0	100.0%	295	8	97.3%	7	0	100.0%	294	29	90.1%
380		6	1	83.3%	295	28	90.5%	5	0	100.0%	294	63	78.6%
381	30	9	0	100.0%	311	12	96.1%	9	4	55.6%	310	64	79.4%
382		9	1	88.9%	310	28	91.0%	9	6	33.3%	310	106	65.8%
383		7	0	100.0%	300	26	91.3%	7	6	14.3%	297	129	56.6%
390	24	9	3	66.7%	295	22	92.5%	9	5	44.4%	294	78	73.5%
391		9	1	88.9%	296	12	95.9%	9	5	44.4%	292	81	72.3%
392		9	0	100.0%	309	10	96.8%	9	2	77.8%	306	92	69.9%
393		9	0	100.0%	313	18	94.2%	9	4	55.6%	310	95	69.4%
449		9	0	100.0%	240	32	86.7%	9	2	77.8%	240	44	81.7%
503	44	9	7	22.2%	309	34	89.0%	9	7	22.2%	302	94	68.9%
504		9	0	100.0%	313	19	93.9%	9	2	77.8%	311	92	70.4%
505		4	0	100.0%	306	41	86.6%	4	2	50.0%	301	86	71.4%
506		9	6	33.3%	308	48	84.4%	7	2	71.4%	300	48	84.0%
507		9	7	22.2%	313	43	86.3%	9	6	33.3%	313	106	66.1%
508	19	9	1	88.9%	308	42	86.4%	9	7	22.2%	304	75	75.3%
516		9	4	55.6%	304	33	89.1%	9	5	44.4%	303	139	54.1%
517		9	0	100.0%	313	8	97.4%	9	6	33.3%	309	133	57.0%
518	51	9	6	33.3%	313	43	86.3%	9	9	0.0%	311	216	30.5%
519		9	0	100.0%	304	9	97.0%	9	3	66.7%	302	69	77.2%
562		9	0	100.0%	304	23	92.4%	9	0	100.0%	300	35	88.3%
564		9	0	100.0%	305	19	93.8%	9	2	77.8%	297	40	86.5%
566		9	2	77.8%	303	27	91.1%	9	5	44.4%	300	50	83.3%
567		9	0	100.0%	190	10	94.7%	9	2	77.8%	188	11	94.1%
572	23	9	0	100.0%	300	24	92.0%	9	3	66.7%	293	86	70.6%
573		9	0	100.0%	302	40	86.8%	9	2	77.8%	295	53	82.0%
579		9	1	88.9%	190	12	93.7%	8	2	75.0%	184	39	78.8%
580		9	0	100.0%	305	16	94.8%	9	4	55.6%	298	32	89.3%
581		9	2	77.8%	305	52	83.0%	9	5	44.4%	303	69	77.2%
584	27	9	1	88.9%	189	26	86.2%	9	9	0.0%	184	117	36.4%
587		9	1	88.9%	298	17	94.3%	9	2	77.8%	289	55	81.0%
588		9	1	88.9%	190	19	90.0%	9	3	66.7%	189	36	81.0%
591		9	1	88.9%	302	22	92.7%	9	3	66.7%	296	42	85.8%
593		8	2	75.0%	298	49	83.6%	8	0	100.0%	277	37	86.6%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
595	16	9	2	77.8%	300	55	81.7%	9	3	66.7%	297	63	78.8%
612		2	1	50.0%	39	6	84.6%	2	0	100.0%	39	1	97.4%
615		2	1	50.0%	40	22	45.0%	2	0	100.0%	39	7	82.1%
637		4	0	100.0%	67	7	89.6%	3	0	100.0%	66	5	92.4%
660		4	0	100.0%	85	12	85.9%	4	0	100.0%	84	25	70.2%
661		4	0	100.0%	113	12	89.4%	4	1	75.0%	112	42	62.5%
663		4	0	100.0%	86	14	83.7%	4	0	100.0%	85	8	90.6%
664	12	4	0	100.0%	85	8	90.6%	4	2	50.0%	85	13	84.7%
665	26	4	0	100.0%	86	10	88.4%	4	1	75.0%	86	25	70.9%
666		4	0	100.0%	84	22	73.8%	4	0	100.0%	84	7	91.7%
667		4	0	100.0%	84	7	91.7%	4	0	100.0%	82	16	80.5%
669		4	0	100.0%	84	7	91.7%	4	0	100.0%	82	22	73.2%
670	14	4	0	100.0%	86	13	84.9%	4	1	75.0%	84	16	81.0%
671		4	0	100.0%	84	8	90.5%	4	0	100.0%	82	9	89.0%
672		4	1	75.0%	86	9	89.5%	4	0	100.0%	86	15	82.6%
674		4	2	50.0%	84	28	66.7%	4	0	100.0%	84	7	91.7%
690		4	0	100.0%	90	2	97.8%	4	1	75.0%	89	5	94.4%
691		4	1	75.0%	90	8	91.1%	4	1	75.0%	88	24	72.7%
692		4	1	75.0%	90	4	95.6%	4	1	75.0%	89	15	83.1%
693	18	4	1	75.0%	90	13	85.6%	4	3	25.0%	88	27	69.3%
694		4	1	75.0%	89	10	88.8%	4	1	75.0%	89	15	83.1%
695		4	0	100.0%	88	10	88.6%	4	1	75.0%	88	15	83.0%
696	17	4	1	75.0%	90	10	88.9%	4	2	50.0%	90	27	70.0%
697		4	3	25.0%	90	22	75.6%	4	1	75.0%	90	18	80.0%
698		4	1	75.0%	88	3	96.6%	4	1	75.0%	88	8	90.9%
701		9	0	100.0%	245	25	89.8%	9	0	100.0%	242	25	89.7%
702		9	0	100.0%	312	32	89.7%	9	3	66.7%	309	73	76.4%
703	57	9	7	22.2%	313	100	68.1%	9	5	44.4%	311	90	71.1%
704		9	2	77.8%	244	39	84.0%	9	2	77.8%	237	48	79.7%
710		9	1	88.9%	313	78	75.1%	9	3	66.7%	309	84	72.8%
711		9	0	100.0%	304	34	88.8%	9	5	44.4%	283	57	79.9%
712		9	5	44.4%	310	85	72.6%	9	6	33.3%	301	104	65.4%
713	Cncld	8	0	100.0%	180	16	91.1%	5	4	20.0%	161	71	55.9%
714		9	7	22.2%	194	82	57.7%	8	7	12.5%	179	83	53.6%
715	Cncld	9	1	88.9%	312	62	80.1%	6	4	33.3%	286	145	49.3%
716	145	9	7	22.2%	313	127	59.4%	8	6	25.0%	306	124	59.5%
717		9	2	77.8%	298	70	76.5%	6	3	50.0%	276	89	67.8%
718	16	9	7	22.2%	313	160	48.9%	9	7	22.2%	311	116	62.7%
719	31	9	6	33.3%	313	109	65.2%	8	5	37.5%	296	89	69.9%
720		4	0	100.0%	97	9	90.7%	4	0	100.0%	97	6	93.8%
723		4	0	100.0%	97	5	94.8%	4	2	50.0%	97	11	88.7%
724	Cncld	4	2	50.0%	97	5	94.8%	2	1	50.0%	95	20	78.9%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
727		4	0	100.0%	97	7	92.8%	4	1	75.0%	97	15	84.5%
728		4	1	75.0%	97	7	92.8%	4	1	75.0%	97	18	81.4%
729	12	4	2	50.0%	96	17	82.3%	4	3	25.0%	95	24	74.7%
732	67	4	3	25.0%	95	18	81.1%	4	3	25.0%	93	20	78.5%
733		4	0	100.0%	97	14	85.6%	4	2	50.0%	92	31	66.3%
734		4	1	75.0%	97	15	84.5%	4	1	75.0%	96	22	77.1%
736		4	0	100.0%	73	7	90.4%	4	2	50.0%	71	11	84.5%
737		4	0	100.0%	73	7	90.4%	4	1	75.0%	72	13	81.9%
738		4	0	100.0%	97	15	84.5%	3	0	100.0%	91	13	85.7%
741		4	0	100.0%	97	13	86.6%	4	0	100.0%	97	18	81.4%
742	Cncld	3	2	33.3%	95	13	86.3%	2	0	100.0%	92	7	92.4%
743	Cncld	4	3	25.0%	97	20	79.4%	2	1	50.0%	94	11	88.3%
744	No OS	4	1	75.0%	97	16	83.5%	4	1	75.0%	97	33	66.0%
745		4	0	100.0%	97	10	89.7%	4	0	100.0%	96	14	85.4%
746		4	1	75.0%	97	9	90.7%	4	1	75.0%	96	14	85.4%
747	34	4	0	100.0%	97	15	84.5%	4	2	50.0%	97	23	76.3%
748	43	4	0	100.0%	96	13	86.5%	4	1	75.0%	96	14	85.4%
749		4	0	100.0%	94	14	85.1%	4	1	75.0%	85	11	87.1%
751		4	1	75.0%	96	17	82.3%	3	0	100.0%	92	11	88.0%
757		9	0	100.0%	98	5	94.9%	9	1	88.9%	97	9	90.7%
761		9	1	88.9%	309	13	95.8%	9	1	88.9%	306	42	86.3%
765		9	0	100.0%	309	25	91.9%	9	1	88.9%	309	43	86.1%
769		9	0	100.0%	309	27	91.3%	9	1	88.9%	303	58	80.9%
770	34	9	1	88.9%	309	23	92.6%	9	6	33.3%	307	95	69.1%
774		9	0	100.0%	309	16	94.8%	9	3	66.7%	308	72	76.6%
777		9	0	100.0%	194	12	93.8%	9	4	55.6%	193	46	76.2%
782		9	8	11.1%	194	90	53.6%	9	4	55.6%	189	29	84.7%
785		9	1	88.9%	309	23	92.6%	9	2	77.8%	309	55	82.2%
786		9	2	77.8%	98	21	78.6%	8	4	50.0%	94	51	45.7%
790		9	0	100.0%	309	28	90.9%	9	1	88.9%	306	47	84.6%
794	20	9	3	66.7%	309	36	88.3%	9	3	66.7%	305	69	77.4%
821		9	0	100.0%	307	6	98.0%	9	7	22.2%	307	128	58.3%
822	18	9	0	100.0%	309	16	94.8%	9	9	0.0%	307	151	50.8%
1233	Cncld	3	1	66.7%	18	5	72.2%	2	2	0.0%	17	10	41.2%
1246		3	3	0.0%	18	15	16.7%	3	2	33.3%	18	9	50.0%
1333		9	1	88.9%	309	33	89.3%	9	1	88.9%	306	100	67.3%
1340		9	1	88.9%	308	7	97.7%	9	1	88.9%	308	52	83.1%
1689		7	1	85.7%	102	6	94.1%	8	1	87.5%	102	12	88.2%
2208	21	4	1	75.0%	15	4	73.3%	4	1	75.0%	15	4	73.3%
2209		2	0	100.0%	6	0	100.0%	2	1	50.0%	6	2	66.7%
2212	Cncld	2	1	50.0%	7	1	85.7%	1	0	100.0%	6	1	83.3%
2213		2	1	50.0%	6	1	83.3%	2	0	100.0%	6	2	66.7%

Amtrak On Time Performance

Trains Arriving Through: 8/9/2026

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2215		2	0	100.0%	26	9	65.4%	2	0	100.0%	26	13	50.0%
2216	23	2	0	100.0%	74	3	95.9%	2	1	50.0%	74	4	94.6%
2218		2	0	100.0%	71	14	80.3%	2	1	50.0%	71	14	80.3%
2219		4	0	100.0%	15	3	80.0%	4	0	100.0%	15	4	73.3%
2222	31	2	0	100.0%	56	4	92.9%	2	1	50.0%	55	8	85.5%
2223	Cncld	2	1	50.0%	26	6	76.9%	1	0	100.0%	24	4	83.3%
2224	Cncld	4	1	75.0%	30	6	80.0%	3	0	100.0%	29	4	86.2%
2226	18	2	1	50.0%	38	8	78.9%	2	1	50.0%	36	10	72.2%
2227		2	1	50.0%	6	2	66.7%	2	0	100.0%	6	0	100.0%
2252		4	0	100.0%	110	9	91.8%	4	0	100.0%	108	32	70.4%
2254		4	0	100.0%	45	3	93.3%	4	1	75.0%	45	13	71.1%
2255	23	4	0	100.0%	112	11	90.2%	4	2	50.0%	111	52	53.2%
2258	44	4	0	100.0%	48	9	81.3%	4	3	25.0%	47	22	53.2%
2259		4	0	100.0%	68	24	64.7%	4	0	100.0%	67	30	55.2%
2260	34	4	0	100.0%	14	2	85.7%	4	3	25.0%	14	11	21.4%
2265	24	4	2	50.0%	49	6	87.8%	4	1	75.0%	48	28	41.7%
2267		4	0	100.0%	12	3	75.0%	4	2	50.0%	11	7	36.4%
2271		4	0	100.0%	95	11	88.4%	4	0	100.0%	94	46	51.1%
2290		2	0	100.0%	38	9	76.3%	2	0	100.0%	37	7	81.1%
2293		4	2	50.0%	13	3	76.9%	4	0	100.0%	13	3	76.9%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2208	NYP	21	SMW	31	SMW	20	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XNYP, CONGESTION A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK	
2212	NYP	Trn Cancelled	ENG	10	ENG	10	WAS-WAS	AM	Other electrical failure, 2139 NG NP, TRAINLINE ISSUES	
2216	NYP	23	MTI	17	MTI	10	BAL-BAL	AM	Disabled train ahead, Control Point, ., Passenger transfer from Acela 2212, a/c disabled with Door issues.	
2222	NYP	31	SMW	25	SMW	11	XHM-XCY	AM	Scheduled in track usage program, Other, XMO-XMW, OPERATED NO.1 TRK A/C NO.2 TRK OOS	
2223	WAS	Trn Cancelled								
2224	NYP	Trn Cancelled								
2226	NYP	18	ITI	12	ITI	12	WAS-WAS	AM	Service, turn, or wye train, 2265, TURNED OFF LATE INBOUND 2265	
2255	WAS	23	OTH	20	CTI	13	NHV-STM	MN	Follow mn, Milepost, 72, 33	
2258	BOS	44	POL	42	POL	42	XHM-XCY	AM	On-train police or DEA activity, STOPPED IN TRENTON FOR EMS FOR SICK PSGR	
2260	BOS	34	ENG	18	ENG	18	XGX-PVD	AM	Other electrical failure, 2104 NG NP, integrity failure, stopped to inspect train	
2265	WAS	24	ENG	17	ENG	17	XSH-NYP	AM	Undesired emergency application, 2116 NG NP, MULTIPLE FAULTS MP16.4 ON PC2116	
87	NFK	77	CAR	57	CAR	57	NYP-NYP	AM	Set out defective car, 81515 AX AN, HIGH LOW CAR	
99	NPN	35	OTH	26	ENG	25	WAS-WAS	AM	Other electrical failure, 39 DX BD, LATE DSL FROM PIT	
120	NYP	17	SMW	20	SMW	20	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK	
121	WAS	93	SVS	43	SVS	43	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE FROM OBS CLEANING	
122	NYP	88	ITI	75	ITI	75	WAS-WAS	AM	Service, turn, or wye train, 121, LATE RELEASE FROM YARD IN NYP	
124	PHL	34	WTR	23	PTI	17	ALX-XVG	CS	Follow P050, Milepost, 105.2, 109.9	
132	BOS	37	MBO	50	MBO	50	STM-BRP	MN	Open bridge Control Point, cp241	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
145	RNK	21	HLD	18	OTH	7	PHL-WIL	AM	Lost time - N.A.R., PRT
146	NHV	29	DMW	39	DMW	39	STM-NHV	MN	Held for or routed around MW work or equipment Bridge, cp241
153	WAS	35	CAR	16	CAR	16	WIL-WIL	AM	Air / Brake / Wheel, 82699 AX AS, inspected overinflated bellows between 5th and 6th car
155	NFK	30	WTR	36	WTR	12	FBG-ASD	CS	Heat order Other, RFP
156	NYP	29	SMW	22	SMW	12	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
161	WAS	36	SMW	18	CON	17	NHV-NHV	MN	Hold for bus with passengers from train, Held for 461 bus connx.
164	BOS	27	ADA	17	DCS	8	NRO-STM	MN	Stop signal Stop signal track 2, Milepost, 29, 29
189	WAS	48	ADA	16	SMW	10	MET-TRE	AM	Scheduled in track usage program, Other, XCY-TRE, OPERATED NO.4 TRK A/C NO.3 TRK OOS MIDWAY TO HAM
195	WAS	45	SMW	24	SMW	13	NYP-NWK	AM	Scheduled in track usage program, Other, XPT-XPT, HELD A/C SINGLE TRACKING NO.3 TRK LACK TO HUDSON
79	CLT	84	WTR	59	PTI	28	FBG-RVR	CS	Follow Amtk 89, Control Point, Crossroads
80	NYP	38	WTR	48	FTI	23	CYN-RGH	NS	Follow NS 350, Control Point, Boylan
664	NYP	12	SMW	16	SMW	16	NWK-NYP	AM	Scheduled in track usage program, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
665	HAR	26	CTP	23	CTP	23	ARD-PAO	AM	Delay due to mechanical problems on a Commuter train, SEPTA 8539 AHEAD AT RADNOR WITH FAULTS AND A BURNING SMELL; INSTRUCTED BY MECHANICAL TO DISCHARGE PSGRS AND DEADHEAD TO FRAZER YARD
670	NYP	14	SMW	16	SMW	16	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
693	BRK	18	PTI	6	PTI	6	EXR-DHM	CS	Meet 694, Control Point, rockingham
696	BON	17	PTI	13	PTI	13	ORB-SAO	CS	Meet amt 693, Siding, surf
63	TWO	36	FTI	7	OTH	4	NYP-XSD	AM	Lost time - N.A.R.
68	NYP	116	PTI	53	WTR	53	SLQ-RSP	CN	Heat order Other, RSP
69	MTR	44	WTR	47	WTR	47	XLQ-SLQ	CN	Heat order Milepost, 2, 42

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
236	NYP	20	ENG	15	ENG	15	HUD-RHI	AM	Air / Brake Compressor failure, 123
240	NYP	17	DSR	14	DSR	7	ALB-HUD	AM	Per bulletin Milepost, 120, 118, 30, 2
241	ALB	16	PTI	9	PTI	9	CRT-POU	MN	Meet 64, Control Point, 58
283	NFL	43	ITI	48	ITI	48	NYP-NYP	AM	Service, turn, or wye train, 236, LATE F/SSYD A/C LATE TURN OFF AM236
290	NYP	27	CTI	25	CTI	25	POU-CRT	MN	Follow metro, 8844, Milepost, 62, 38
291	BTN	23	CTI	13	CTI	10	CRT-POU	MN	Meet mnrr, Milepost, 52.0, 65.0
1233	PIT	Trn Cancelled	TRS	13	TRS	13	NYP-XSD	AM	Near-miss, Other, XIW-XIW, HELD A/C POLICE HOLD AT YONKERS
71	CLT	20	FTI	14	FTI	8	CYN-DNC	NS	Meet Fti leaving yard heading east, Milepost w/Letters, nc 59, nc 59, p 50, p50
73	CLT	13	FTI	20	FTI	20	RGH-RGH	NS	Meet #NS350, Control Point, Boylan
78	RGH	37	FTI	46	FTI	26	GRO-BNC	NS	Follow Followed #NS 50E from GRO into siding at Mcleansville were both NS 50E and AMTK 78 waited in siding for AMTK 79 to clear Mcleansville main track at which point AMTK 78 shoved west from siding back to the main and proceeded East to BNC station, #NS 50E, Milepost w/Letters, NC 0.3, NC 7.7
89	SAV	41	FTI	60	FTI	34	SSM-FAY	CS	Meet CSX???, Control Point, N. Milan
97	MIA	35	PTI	63	CAR	59	NYP-NYP	AM	Set out defective car, 20815, LATE F/SSYD A/C CAR 20815 FULL REFRIGERATION FAILURE IN ENTIRE CAR
98	NYP	217	ENG	98	ENG	98	XPV-WIL	AM	Air / Brake, 629 EX ES, stopped on No. 2 track just south of Brandy Int due to penalty brake application.
40	CHI	62	FTI	56	SVS	48	XSE-RMT	CS	Fuel Locomotives wasn't fueled out of JAX or SAV for an undisclosed reason had to fill them @ Rocky Mount yard
41	MIA	75	FTI	121	FTI	32	XDJ-RVR	CS	Follow CSX111, Other, CFP57.1
5	EMY	139	DSR	123	PTI	37	TRU-XSO	UP	Cross over or go around 6, Control Point, west norden
6	CHI	145	WTR	187	WTR	53	XMS-WNN	UP	Heat order Milepost, 291, 417
724	SAC	Trn Cancelled	TEN	59	TEN	47	OAC-OAC	UP	Loading problem C2009
729	SJC	12	DSR	9	CTI	7	SCC-SJC	UP	Follow Caltrain, Control Point, Stockton

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
732	SAC	67	TCC	77	TCC	77	OKJ-OKJ	UP	LOADING ISSUES MSG: 732(09) WITH C2013 WILL NOT LOAD WITHOUT BEING SHORTLOOPE. CC6961 CUT FROM CONSIST, EQUIPMENT WYED C6961
742	SAC	Trn Cancelled							
743	OKJ	Trn Cancelled							
744	ARN	No OS Rpt	TRS	160	TRS	160	BKY-RIC	UP	Vandalism Trespasser threw very large rock into cab car windshield at mp 7.5 MTZ sub, Caused shatter and glass into cab car. Unable to use prior equipment. Train 744 returned to OMF to swap equipment., Milepost, 7.5, 7.5
747	SJC	34	PTI	41	PTI	19	FMT-GAC	UP	Meet Amtk748, Control Point, albrae
748	SAC	43	SVS	45	SVS	45	DAV-SAC	UP	Pick up equipment Shove back to DAV to hook up to 744 to drag them to SAC., Control Point, rv077
50	NYP	102	DSR	59	CAR	21	WAS-WAS	AM	Air / Brake / Wheel, XXXXX, EXTENDED BLUE FLAG PROCEDURES UP 822P DOWN 850PM
503	EUG	44	DCS	33	DCS	18	SLM-ALY	UP	Issue with automatic road crossing protection Milepost, 692.34, 691.35
508	PDX	19	DSR	13	FTI	10	EUG-ALY	UP	Meet manifest, Siding, eugene, up ptrv
518	VAC	51	DSR	28	CON	27	VAN-VAN	BN	Hold for bus with passengers from train Waited on buses from PDX
58	CHI	62	FTI	98	FTI	43	MEM-NBN	CC	Meet Grain, CN 2896, Siding, Rialto
14	PDX	53	DCS	79	DCS	38	ALY-SLM	UP	Issue with automatic road crossing protection Six crossings to protect, Milepost, 691.65, 692.34
822	OKC	18	DSR	40	DSR	26	FTW-GLE	BN	Per bulletin Milepost, 355.5, 355.9, 50, m1, Milepost, 357.3, 357.6, 29, m2, Milepost, 361.5, 362.9, 60, m2, Milepost, 371.4, 371.5, 50, main, Milepost, 374.0, 374.1, 60, main, Milepost, 379.5, 380.7, 60, main, Milepost, 383.3, 383.8, 30, main, Milepost, 385.3, 385.5, 30, main, Milepost, 389.0, 389.
337	MKE	11	WTR	9	WTR	6	XRO-SVT	CP	Flash flood warning Critical areas 25 mph, Milepost, 40.11, 40.11, Milepost, 40.37, 40.37, Milepost, 46.78, 46.78, Milepost, 47.27, 47.27

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
338	CHI	11	WTR	7	WTR	5	SVT-XRO	CP	Flash flood warning Flash flood warning, went 25 through critical areas, Milepost, 47.27, 47.27, Milepost, 46.78, 46.78, Milepost, 40.37, 40.37, Milepost, 40.11, 40.11
341	MKE	14	FTI	14	FTI	9	XWA-GLN	ME	Follow 2-247, Other, xwa-gln
350	PNT	32	DSR	36	DSR	21	ROY-TRM	CC	Per bulletin Milepost, 13.9, 17.1, 10, 1
352	PNT	101	WTR	56	WTR	50	XH6-XPI	NS	High winds STOPPED AT MP 490.0, Milepost, 479.0, 502.0
353	CHI	32	DSR	30	DCS	25	HMI-XTF	AM	Power switch failure Control Point, 21st st
354	PNT	49	DSR	52	DSR	22	TRM-PNT	CC	Per bulletin Milepost, 16.58, 18.19, 25, MAIN ONE, Milepost, 18.19, 19.2, 25, MAIN ONE, Milepost, 19.2, 22.0, 30, MAIN ONE
355	CHI	35	DSR	53	DSR	19	TRM-ROY	CC	Per bulletin Milepost, 16.3, 13.9, 10, MAIN ONE, Milepost, 15.25, 15.15, 30, MAIN ONE, Milepost, 12.9, 12.7, 25, MAIN ONE, Milepost, 11.5, 11, 25, MAIN 1&2
365	CHI	53	CAR	28	CAR	19	PTH-LPE	CC	Air / Brake / Wheel ID4012, Stop at mp331 inspect Bend of car smoke was coming from brake. Control cabinet said brake applied in travel. Released brake walking inspection of wheels. Called CNOC mechanical instructed by Brian to travel five miles at 50mph and reinspect wheels.
572	SAN	23	DSR	9	TRS	9	FUL-FUL	BN	Unticketed or fare evading passenger Aggressive fare evader refuses to detrain. Wait for authorities. When he finally did detrain, we departed., Other, Fullerton Sta. M-1
584	SAN	27	PTI	18	PTI	12	SNC-SNP	SC	Meet 587, Control Point, serra
595	LAX	16	FTI	18	FTI	10	OSD-X98	SN	Meet bnsf, Control Point, songs
770	SAN	34	CTI	31	CTI	23	SNC-SNP	SC	Meet metrolink, 1663, Control Point, serra
794	SAN	20	PTI	25	PTI	23	X3G-GTA	UP	Meet AMTK 777, Control Point, CPCO336
703	SAC	57	ITI	67	ITI	67	BFD-BFD	BN	Service, turn, or wye train 714
713	OKJ	Trn Cancelled	FTI	16	FTI	16	SKN-ACA	BN	Meet bnsf, Control Point, WEST SANDO
715	OKJ	Trn Cancelled	PTI	26	PTI	10	WAC-COC	BN	Meet 702, Control Point, Allensworth
716	BFD	145	TSV	154	TSV	154	EMY-EMY	UP	Planned set out / pick out of locomotives, cars or section of train
718	BFD	16	FTI	33	FTI	23	SKN-MOD	BN	Meet bnsf, Control Point, Duffy

Amtrak Endpoint OTP Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/9/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
719	OKJ	31	PTI	22	TEN	14	COC-COC	BN	HEP HEP motor overheat shutdown, C2014
4	CHI	152	DMW	138	DMW	128	RAT-RAT	BN	Hold for defect repair Milepost, 619.8, 619.2
2	NOL	108	FTI	138	FTI	31	XTS-XVL	UP	Follow SDG OPEN XTS ,MALLIE. Resulting on severe unnecessary delay., up5899, Control Point, xts, Control Point, hot wells
302	CHI	26	FTI	47	FTI	18	ALN-CRV	UP	Meet up 6999, Control Point, shipman
306	CHI	Trn Cancelled	ENG	30	ENG	30	SMT-SMT	CC	Due to fault code on engine. Passenger detained at summit for buses ID4604
381	QCY		FTI	17	FTI	17	MAC-QCY	BN	Meet bnsf 8400, Control Point, west colchester
390	CHI		ENG	23	ENG	20	HMW-HMW	CC	COMPRESSOR WARNING,CUT OUT MAIN RES ID4631
311	KCY	44	PTI	20	PTI	20	JEF-SED	UP	Meet Amtrak 318, Siding, Shell
316	STL	24	DSR	19	WTR	10	JEF-HEM	UP	Heat order Milepost, 125.0, 81.0
318	CHI	61	WTR	33	FTI	15	WAR-SED	UP	Meet Took the siding for the freight, Siding, Dresden, UP 7745 West, Intermodal
319	KCY	33	WTR	23	DCS	10	HEM-JEF	UP	Issue with automatic road crossing protection XG, Milepost, 92.88, 92.88

Amtrak Initial Terminal Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/9/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	240	08/09	5	5	Eng705 from amt 63 705
BON	693	08/09	2	2	Cross over or go around keolis, Other, trk 8
BOS	2265	08/09	12	12	Water, commissary, toilet/trash dumping, late out of yard and late commissary loading
BRK	692	08/09	4	4	Unplanned Wye Other, Brunswick
HAR	672	08/09	1	1	Passenger and/or baggage
MTR	68	08/09	11	11	Routine inspections Via mechanical at MMC needed to send over the map 1173 for the private cars
NHV	143	08/09	1	1	Had to hold 1 min extra for buss passengers
NHV	157	08/09	6	6	Had to wait on bus
NYP	69	08/09	7	7	Passenger and/or baggage, STILL LOADING AT DEPARTURE TIME
NYP	89	08/09	2	2	Passenger and/or baggage, LOADING
NYP	97	08/09	46	46	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY OBS AND CATERING
NYP	105	08/09	11	11	Service, turn, or wye train, 120, LATE TURN OFF AM120
NYP	121	08/09	43	43	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE FROM OBS CLEANING
NYP	123	08/09	7	7	Other late crew, LATE F/SSYD A/C HELD TO BRING CREWS TO THE STATION
NYP	239	08/09	2	2	Passenger and/or baggage, BOARDING
NYP	241	08/09	4	4	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	245	08/09	80	80	Service, turn, or wye train, 68
NYP	283	08/09	48	48	Service, turn, or wye train, 236, LATE F/SSYD A/C LATE TURN OFF AM236
NYP	291	08/09	8	8	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	2223	08/09	(Trn Cxld)		Equipment Issues
NYP	2227	08/09	2	2	Cross Traffic, NJT, NJ7265, Other, NYP-NYP, HELD A/C NJ7265 XING AHEAD
PHL	117	08/09	2	2	Passenger and/or baggage
PHL	151	08/09	1	1	Passenger and/or baggage
PHL	615	08/09	3	3	PTC - Stop Bypass Permission Required, Control Point, ., CC/9649
PIT	1246	08/09	(Trn Cxld)		Downed Trees
RGH	73	08/09	20	20	Meet #NS350, Control Point, Boylan
RNK	66	08/09	1		
RNK	156	08/09	1		

Amtrak Initial Terminal Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/9/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	122	08/09	75	75	Service, turn, or wye train, 121, LATE RELEASE FROM YARD IN NYP
WAS	140	08/09	15	15	High passenger count, NORTH END ESCALATOR FACING WRONG DIRECTION PREVENTED PAX FROM BOARDING ON TIME. PAX BOARDED FROM BOTH NORTH AND SOUTH END ESCALATORS (361 PAX)
WAS	2212	08/09	10	10	Other electrical failure, 2139 NG NP, TRAINLINE ISSUES
WAS	2224	08/09	(Trn Cxld)		Engine Issue
WAS	2226	08/09	12	12	Service, turn, or wye train, 2265, TURNED OFF LATE INBOUND 2265
CDL	390	08/09	3	3	AUXILIARY ID4631
CHI	21	08/09	73	73	Service, turn, or wye train 22
CHI	59	08/09	39	39	Restrictive signal(s) from unknown cause Stop, Other, chicago yard
PTH	365	08/09	3	3	Failure of diesel engine Engine would not start, not able to do load test., ID4605
SAS	22	08/09	192	192	Service, turn, or wye train 21, Train 21 and 2 both arrived late. Rear Sleeper and coach removed from train 2 attached to Amtrak 22. Mechanical inspection. Cnoc sent out a notification saying train won't depart till 10am. Waited until 10 to depart
ARN	729	08/09	1		
BFD	703	08/09	67	67	Service, turn, or wye train 714
BFD	719	08/09	12	12	Hold for thruway bus #5619
GTA	782	08/09	5	5	Meet 14, Control Point, CO 358
OKJ	716	08/09	(Trn Cxld)		Third Party Engine Failure
OKJ	718	08/09	(Trn Cxld)		Third Party Engine Failure
OKJ	732	08/09	77	77	LOADING ISSUES MSG: 732(09) WITH C2013 WILL NOT LOAD WITHOUT BEING SHORTLOOPEd. CC6961 CUT FROM CONSIST, EQUIPMENT WYED C6961
OKJ	742	08/09	(Trn Cxld)		Third Party Engine Failure
PDX	11	08/09	28	13	Hold for Z train entering ALBINA yard UP Z, Control Point, PdX, Z
PDX	11	08/09	28	10	Water coaches Control Point, PDX
PDX	503	08/09	28	0	Hold for bus with passengers from train Third shuttle bus from Vancouver late arrival
PDX	507	08/09	4		
SAC	743	08/09	(Trn Cxld)		Third Party Engine Failure
SAC	751	08/09	1		
SJC	724	08/09	1		
SJC	744	08/09	1		

Amtrak Initial Terminal Details

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/9/2026

Terminal	Train	Date	Late	Delay	Cause
SLO	794	08/09	2	2	Door C6465, No door lights, doors recycled. Car 6465 has the door open light on the conductor panel and doors are closed. Went into door override
VAN	506	08/09	5	5	Door 7205, Steps did not retract and train went into emergency.
VAN	518	08/09	27	27	Hold for bus with passengers from train Waited on buses from PDX

Eastern Region

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.1	94.8	166	0
CDOT	95.0	81.3	89.6	92.4	16	3
MARC	95.0	83.3	81.7	90.2	12	2
SEPTA	95.0	83.8	93.1	91.5	99	16
NJT-NED	95.0	70.8	90.2	88.6	192	56
NJT-SED	95.0	100.0	98.9	97.2	12	0

Operating Highlights

Train 66(09) - Washington, DC - Engine Failure

10AUG26: Train 66(09) was delayed at Washington Union Terminal due to its motors being delivered late from the Pit.

Train	Delay	Comment
66(09)	1'03"	

Train 2233(09) - South of Baltimore, MD - Miscellaneous Amtrak Responsible

09AUG26: Acela Train 2233(09) was terminated at BWI Airport Station/MP 106.3 on the Amtrak PW Line due to its Map 100 paperwork expiring at 12:00am. Road Foreman Tyrone Jordan out of Washington Union Terminal procured a Conductor and took the set of equipment that represented train 2227(09) from WAS to BWI to rescue the 121 passengers. The original 2233(09) equipment was later inspected and deadheaded to Washington.

Train	Delay	Comment
2233(09)	Term BWI	50" wait for rescue set.

Train 2224(09) - Washington, DC - Engine Failure

09AUG26: Due to multiple unresolvable mechanical issues, Train 2224(09) was cancelled in its entirety. All 117 passengers were moved to Train 2226(09) for travel north to NYP.

Train	Delay	Comment
2224(09)	Cancelled	
2226(09)	12"	Pax transfer from 2224(09) Equip

Train 51(09) Charlottesville, VA - Temporary Speed Restrictions

09AUG26: Train 51(09) with E/337 and 7 cars was delayed on the Buckingham Branch North Mountain subdivision due to speed restrictions from MP 187.5 to MP 216.4.

Train	Delay	Comment
51(09)	40"	

Train 97(09) New York, NY - Servicing

09AUG26: Train 97(09) with E/615 and 10 cars was delayed departing New York due to late release from the yard caused by OBS and Catering.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(09)	46"	

Train 68(09) Rouses Point, NY -Heat Orders/Weather

09AUG26: Train 68(09) was delayed on the CN Rouses Point due to heat orders at Rouses Point. They were further delayed due to customs. Then they were delayed on the CPKC Canadian subdivision at MP 188.7 meeting 69(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(09)	32"	CUSTOMS
68(09)	54"	HEAT ORDERS
68(09)	51"	MEETING 69(09)
69(09)	47"	HEAT ORDERS
245(09)	1'20"	TURN OFF 68(09)

Train 2258(09) Trenton, NJ - Injured or Sick Passenger or Employee

09AUG26: Next Gen 2258(09) was delayed on the New York to Philadelphia main line due to stopping at Trenton for a sick passenger. The passenger was removed and the train was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2258(09)	42"	

Train 1233(09) South of Albany-Rensselaer, NY -Down Tree/ Debris

09AUG26: Train 1233(09) with E/714 and 6 cars was delayed on the Amtrak Post Road at MP 197.0 due to a down tree ahead at MP 196.9.

Due to this train 1233(09) reversed back into Albany and the 10 customers were re-accommodated on the bus for 448(08). Train 1246(09) originated at Albany and customers were re-accommodated to train 449(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1233(09)	TERM ALB	
1246(09)	ORIG ALB	

Train 283(09) New York, NY - Servicing

09AUG26: Train 283(09) with E/123, E/717 and 4 cars was delayed departing New York due to the late arrival of 236(09) and catering in the yard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
283(09)	48"	

Train 2212(09) Baltimore, MD - Car Failure

09AUG26: Next Gen Train 2212(09) with PC/0110 and 2139/2139 delayed on the Philadelphia to Washington main line at MP 95.7/Baltimore due to having door issues. Crew was trouble shooting. They were able to clear the door issue and then had a brake issue. The crew was working on clearing the brake fault. The crew was instructed to de-prepare the train to clear the brake penalty.

The customers were being transferred to train 96(09), 2216(09) and 20(08). Once they were finished with the transfer the equipment was deadhead to Philadelphia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2223(09)	CANCELLED	
2212(09)	TERM BAL	
96(09)	04"	
2216(09)	17"	
20(08)	05"	

Train 98(09) North of Winter Haven, FL - Passenger Train Interference

09AUG26: Train 98(09) with E/324, E/369 and 11 cars was delayed on the CSX Carters subdivision due to meeting 41(07) at MP 824.7/Davenport.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(09)	35"	

Train 121(09) New York, NY - Servicing

09AUG26: Train 121(09) with CC/9640, E/662 and 10 cars was delayed departing New York due to the late servicing of commissary in the yard.

This also delayed 122(09) due to the late turn of equipment in Washington then further delayed due to having trainline issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
121(09)	43"	
122(09)	1'15"	

CSX Heat Orders - Weather

09AUG26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Baltimore Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, New River, North End, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(09)	16"	
53(09)	27"	
98(09)	41"	
79(09)	30"	
155(09)	33"	
128(09)	12"	
99(09)	11"	
89(09)	35"	
124(09)	23"	
40(09)	50"	
158(09)	30"	
80(09)	48"	
90(09)	47"	
40(08)	48"	
41(08)	30"	

Train 284(09) North of Buffalo, NY - Freight Train Interference

09AUG26: Train 284(09) delayed on the CSX Buffalo Terminal due to meeting unknown CSX at CP 402

Train	Delay	Comment
284 (09)	35"	

Train 98(8) North of Wilmington, DE - Engine Failure

09AUG26: Train 98(08) with E/629 and 12 cars with 216 customers onboard was stopped on the Philadelphia to Washington main line at MP 27.5 track 2 due to being unable to release the brakes. The train was able to maintain HEP. Amtrak Road Foreman was notified and was enroute. Engine 650 was being readied at Philadelphia for possible rescue. The crew was inspecting the consist for air leaks. Train 164(09) was held for possible transfer. Crew was able to recycle the engine but had to cut out cabs and ACSES and will continue at restricted speed 59MPH to Philadelphia where they were capped with an engine 650.

Train	Delay	Comment
98 (8)	1'38"	
164 (09)	05"	
120 (09)	04"	
98 (08)	53"	PHL

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00671a 00000008700 UNCLASSIFIED 19/2/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train 58(09) South of Carbondale, IL - Freight Train Interference

09AUG26: Train 58(09), with 188 customers onboard, was delayed at Wetaug siding/MP340.9, 33 miles south of Carbondale, IL/MP308.3, on the CN Centralia subdivision meeting CN freight. Once CN/2720 was clear of the route, train 58(09) continued north at track speed.

Train	Delay	Comment
58(09)	51"	

Train 306(09) North of Joliet, IL - Engine Failure

09AUG26: Train 306(09), with engine IDTX4604, 5 cars, and 215 customers onboard, was delayed at Springfield, IL/185.1 on the UP Springfield subdivision due to an engine fault I/O 43. The crew was able to restart the engine and continue north. The engine IDTX 4604 shut down again at Bloomington-Normal, IL/MP124.0 but the crew was able to start the engine again.

In an effort to protect the customers onboard, four buses were sourced to meet the equipment at Summit, IL/MP11.8. The customers boarded the buses and traveled to Chicago Union Station, IL. Train 306(09) terminated at Summit, IL. and the crew operated the equipment deadhead to Chicago, IL.

WBS#: B.TR.100150.7016

Train	Delay	Comment
306(09)	30"	Holding for Buses at SMT
306(09)	Terminated	SMT

Train 22(09)/422(07) East of Dallas, TX - Freight Train Interference

09AUG26: Train 22(09)/422(07), with 205 customers onboard, was delayed between Dallas, TX/MP214.4 and Mineola, TX/MP136.1, beginning on the UP Dallas subdivision following UP freights 5810 and 6656. UP freight 5810 was disabled while freight crews replaced a broken drawbar. Once the route was clear, train 22(09)/422(07) continued east.

Train	Delay	Comment
22(09)/422(07)	1'07"	

Train 703(09) Bakersfield, CA - Third Party Contractor Engine Failure

09AUG26: Train 703(09) was delayed due to an equipment issue involving locomotive C2102, which was identified with a bad-ordered HVAC system in the cab prior to departure. To maintain service, a decision was made to utilize the inbound Train 714(09) equipment for Train 703(09). Following the equipment reassignment, Train 703(09) departed Bakersfield, CA, with 63 customers onboard and continued its scheduled operation.

Train	Delay	Comment
703(09)	1'07"	

Train 744(09) East of Berkeley, CA - Train Stoned

09AUG26: Train 744(09) 26-FOI-00671 10000008700 UNCLASSIFIED Four 9/2/2026, and locomotive JPBX921, was delayed after a rock struck the engineer's windshield east of Berkeley, CA near MP 7.56 on the Union Pacific Martinez Subdivision. The damage obstructed the engineer's field of vision, requiring the train to stop and preventing continued operation with the affected equipment. The train subsequently made a reverse movement to Emeryville, CA, where customers were provided the option to transfer to Train 746(09). The damaged equipment was removed from service and replaced with a substitute consist operating with CC/C8311, four cars, and locomotive C2009. Once the replacement equipment was prepared and released, Train 744(09) returned to Emeryville and resumed service to Auburn, CA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
744(09)	2'40"	

Train 1(08)/421(07) East of Deming, NM - Heat Orders

09AUG26: Train 1(08)/421(07), with 145 customers onboard, was delayed for 66 miles between mile post 1274.0 and Deming, NM/MP1208.2 on the UP Lordsburg subdivision following level 2 heat orders. Train 1(08)/421(07) was required to operate at 50MPH. Once clear of the heat orders, train 1(08)/421(07) continued west at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(08)/421(07)	30"	

Train 6(09) East of Reno, NV - Heat Orders

09AUG26: Train 6(09), carrying 145 customers onboard, was delayed east of Reno, NV, on the Union Pacific Nevada Subdivision due to heat-order restrictions. The train operated at reduced speeds between Vista (MP 249.4) and Winnemucca (MP 417.2) in accordance with temporary operating restrictions implemented due to high rail temperatures as it continued its eastbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(09)	1'02"	
6(09)	29"	WNN-XW6

Train 4(08) East of Lamy, NM - Temporary Speed Restrictions

09AUG26: Train 4(08), carrying 157 customers onboard, was delayed east of Lamy, NM, on the BNSF Glorieta Subdivision due to multiple speed restrictions in effect between MP 830.8 and MP 812.0. The train was required to operate at reduced speeds ranging from 15 MPH to 50 MPH through the affected territory in accordance with bulletin orders. After departing the Lamy area, Train 4(08) encountered additional speed restrictions east of Las Vegas, NM, between MP 770.0 and MP 670.7 on the BNSF Raton Subdivision. The train continued through the affected territory at the prescribed speeds outlined in the bulletin orders, resulting in reduced operating speeds as it continued its eastbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(08)	23"	LMY-LSV
4(08)	09"	LSV-RAT

Train 3(09) East of Fort Madison, IA - Drawbridge Opening

09AUG26: Train 3(09), 28-FOI-0067168 00000008700 "UNCLASSIFIED" 9/2/2026, was delayed at the Mississippi River Bridge/MP231.8, 1 mile east of Fort Madison, IA/MP232.9, on the BNSF Chillicothe subdivision waiting for the bridge to close. Once the route was clear, train 3(09) continued into Fort Madison Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(09)	58"	

Train 22(09)/421(07) Cleburne, TX - Police Related

09AUG26: Train 22(09)/422(07) was delayed on the BNSF Fort Worth subdivision seven miles north of Cleburne due to a right of way fire at MP 324.8 with a hold on all traffic. Train 22(09)/422(07) held behind UCLBDV107B at Midway/MP 321.4 to meet VALTEAP508A and then shoved out and continued to Fort Worth once rail traffic resumed.

Train 22(09)/422(07) was further delayed at Tower 55 operating through freight congestion before entering Fort Worth.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(09)/421(07)	1'30"	Freight Congestion into FTW
22(09)/421(07)	1'16"	Trackside Fire

Train 14(08) North of Albany, OR - Automatic Crossing Issues

09AUG26: Train 14(08), carrying 179 customers onboard, was delayed operating between Albany, OR, and Salem, OR, on the Union Pacific Brooklyn Subdivision due to an issue with an automatic grade crossing warning system. As a result, the crew was required to provide protection at six crossings between MP 691.25 and MP 692.34 before proceeding through the affected territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(08)	38"	

Train 732(09) Oakland, CA - Third Party Contractor Engine Failure

09AUG26: Train 732 (09) was delayed departing Oakland, CA, on the UPRR Niles Subdivision after locomotive C2013 would not load unless operated in short-loop mode. To address the issue, cab car 6961 was cut from the consist and the equipment was scheduled to be wye'd. The train was wye'd in Sacramento for the operation of Train 749 (09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
732(09)	1'17"	

Train 21/421(09) South of Chicago, IL - Freight Train Interference

09AUG26: Train 21/421(09), 312 customers onboard, was delayed at Brighton/MP5.1, 5.1 miles south of Chicago Union Station, IL/MP0.0, on the CN Joliet subdivision meeting freight cross traffic. Once the route was clear, train 21/421(09) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(09)	1'01"	

Train 8/28(08) East of Shelby, MT - Freight Train Interference

09AUG26: Train 8/28(08) with 26:01,00671 customers onboard was delayed between Shelby, MT/MP1065.7 and Williston, ND/MP121.1 beginning on the BNSF Hi Line subdivision following multiple BNSF freights. Train 8/28(08) met 3862 at Lothair/MP1034.7, 8329 at Burnham/MP971.0, 5660 and 5019 at Lohman/MP416.6, 5737 at Dodson/MP359.3, 8382 at Saco/MP316.3, 3695 at Glasgow East/MP275.9, 1445 at CP136.0, and, finally, freights 5798 and 6788 at Poplar/MP205.3. Train 8/28(08) continued to Minot, ND at 3:40AM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(08)	1'27"	

Train 5(07) West of Truckee, CA - Passenger Train Interference

09AUG26: Train 5(07) was delayed approximately 15 miles west of Truckee, CA, at West Norden (MP 191.4) on the Union Pacific Roseville Subdivision while holding to meet Train 6(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(07)	37"	

Train 352(09) East of Chicago, IL - High Wind Warnings

09AUG26: Train 352(09), with 281 customers onboard, was delayed at mile post 490.0, 33 miles east of Chicago Union Station, IL/MP0.0, on the NS Chicago Terminal subdivision due to high wind warnings. Once the warning expired, train 352(09) cleared the area and continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(09)	50"	

Train 4(08) Albuquerque, NM - Engine Failure

09AUG26: Train 4 (08) with locomotives E138 and E147 was delayed departing Albuquerque, NM, on the NMRX Glorieta Subdivision after the HVAC system on the lead locomotive, E138, was bad ordered en route due to a sparking circuit breaker. Upon arrival in Albuquerque, the locomotives were flat switched, resulting in a departure delay while the consist was rearranged and the defective locomotive addressed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(08)	1'24"	

Train 724(09) Oakland, CA - Third Party Contractor Engine Failure

09AUG26: Train 724(09) with C2009 was delayed departing Oakland Coliseum Station, Oakland, CA, on the UPRR Niles Subdivision due to recurring loading issues on C2009, preventing the locomotive from making track speed. While stopped at Oakland Coliseum Station, the crew reported the same alarm experienced the previously, including a MUX input failure and PCS open condition from the locomotive. The crew attempted recovery by changing ends, restoring PCS, and checking locomotive loading. TASI responded to assist. The MUX fault temporarily cleared, and the locomotive regained load, but an alerter penalty then occurred and could not initially be cleared. The crew eventually cleared the alerter penalty and planned to operate from the cab car, placing the AC in the locomotive in case the issue continued. En route to Oakland Jack London station, Wi-Tronix indicated a loss of speed consistent with another loss of load, and the MUX fault reappeared, though the crew regained control. After detrainning passengers at Oakland, the train returned to the yard for troubleshooting. . Due to the recurring locomotive issues, Train 724(09) terminated at Oakland, CA, and passengers were accommodated on the next available service.

As a result of locomotive availability, the turn of 743(09) was canceled in its entirety. Later, train 742(09) was also canceled due to locomotive C2009 unable to be repaired and experiencing more issues such as batteries being dead and unable to start. There were no other locomotives available for service at the time. Customers here were accommodated on train 744(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
724(09)	47"	At OAC
724(09)	Terminated	OKJ
743(09)	Canceled	
742(09)	Canceled	

Train 7(07) Wenatchee, WA - Debris

09AUG26: Train 7(07) with E196 and E150 was delayed approximately 3 miles west of Wenatchee, WA, on the BNSF Scenic Subdivision after striking debris on the track. A rock/small boulder caused the air hoses between cars to become detached, requiring inspection and reattachment before the train could continue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(07)	33"	

Train 21/421(09) Chicago, IL - Initial Terminal Delay

09AUG26: Train 21/421(09) with E/58-311, nine cars, and 312 customers was delayed departing Chicago due to a late release of equipment. Once the equipment was released and set in the station, the customers were welcomed aboard, and 21/421(09) departed Chicago at 323PM-CT, 1 hour, and 13 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(09)	1'13"	

Amtrak Chicago District South of Chicago, IL - Signal

09AUG26: Trains were delayed on the Amtrak Chicago district two miles south of Chicago due to code line failure at 21st Street/MP 1.64. Maintainers were on scene to assist in hand lining switches until the issue was rectified.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421 (09)	25"	
59 (09)	39"	
393 (09)	22"	
364 (09)	11"	
353 (09)	25"	

Train 311(09) West of Jefferson City, MO - Car Failure

09AUG26: Train 311(09) with E/ID4609, seven cars, and 134 customers was delayed 28 miles west of Jefferson City on the UPRR Sedalia subdivision at Shell/MP 153.5 due to back door sensor issues. The crew worked with CNOC mechanical, rectified the issue, and continued to Sedalia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
311 (09)	37"	

Train 22(09)/422(07) San Antonio, TX - System

09AUG26: Train 22(09)/422(07) was delayed departing San Antonio on the UPRR Del Rio subdivision due to the late arrival of connecting train 422(07), which arrived in San Antonio at 723AM-CT, 2 hours, and 23 minutes late. The crews for train 2(07) and 22(09)/422(07) at San Antonio were set back until 900AM-CT. Once the crews were on duty and briefed, train 22(09)/422(07) departed San Antonio at 1000AM-CT, 3 hours, and 12 minutes late. Train 2(07) departed San Antonio at 1001AM-CT, 3 hours, and 36 minutes late.

WBS#: B.TR.100150.7017

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22 (09) /422 (07)	3'12"	
2 (07)	1'13"	

Train 59(08) South of Newbern-Dyersburg, TN - Freight Train Interference

09AUG26: Train 59(08) with 121 customers was delayed on the CN Flint subdivision starting 42 miles south of Newburn between Rialto/MP 347.6 and Woodstock/ MP 380.4 due to following CN freight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59 (08)	35"	

Train 744(09) Davis, CA - Third Party Contractor Engine Failure

10AUG26: Train 744(09) originally departed at 10:00 AM, operating with CC/C6964, four cars, and locomotive JPBX921. After the cab car was damaged east of Berkeley by a rock thrown at the train, the equipment was returned to the Oakland Maintenance Facility, where it was exchanged for a consist operating with CC/C8311, four cars, and locomotive C2009. After returning to service, Train 744(09) experienced a second mechanical issue when locomotive C2009 lost traction effort while approaching Davis, CA. The crew worked with mechanical personnel to troubleshoot the locomotive; however, a reset attempt was unsuccessful, and the locomotive could not be restarted. This was the same issue that presented itself earlier in the day's services and caused the cancelation of trains 743(09) and 742(09). To recover service, Train 748(09) was routed to couple onto the disabled Train 744(09) equipment at Davis and operate as a combined consist to Sacramento. Upon arrival in Sacramento, the Train 748(09) section was separated and utilized to operate Train 744(09) onward to Auburn, CA, while the disabled equipment was removed from service for further mechanical attention in Sacramento.

Train	Delay	Comment
744(09)	1'23"	
748(09)	54"	
14(09)	34"	

Train 8/28(08) Spokane, WA - Engine Failure

09AUG26: Train 8/28(08), operating with locomotives E/312 and E/171 and 10 cars, was delayed in Spokane, WA, after mechanical personnel identified a bad-ordered traction motor on locomotive E/312. Initial inspection indicated possible strike damage, resulting in the loss of gear oil from the traction motor assembly. A decision was made to set out the locomotive and secure a replacement unit from BNSF. BNSF locomotive 8269 was subsequently identified for lease and dispatched to the train to allow operations to continue.

Train	Delay	Comment
8/28(08)	56"	set out E/312
8/28(08)	09"	Operating w/Freight SPK-SBY
8/28(08)	51"	Operating w/Freight SBY-MOT

Gold Runner Service - Equipment Servicing/ Repair Issues

07AUG26: Train 712(07), CC/C8306-5 cars- E/C2102, was delayed departing Oakland, CA due to a late release from mechanical. Equipment arrived into the maintenance facility at 7:28P-PT on August 6th from Train 715(06). With the equipment still not fully serviced, at 10:00A-PT, mechanical estimated another twenty minutes were needed for servicing the equipment. Once equipment was serviced, it departed the maintenance facility at 11:14A-PT en route to Oakland Station for boarding. Once all customers were boarded, Train 712(07) was able to depart at 11:29A-PT.

Train 714(07), E/C2013-8 cars-E/C2014, was delayed departing Oakland, CA due to the late turn of equipment arriving on Train 711(07). The equipment, E/C2012-6 cars-CC/C6962, arrived to the maintenance facility from Train 719(06) at 11:05P-PT on August 6th and was not ready for departure. To avoid a lengthy delay, the inbound Train 711(07) equipment was turned for Train 714(07). Once Train 711(07) arrived into the maintenance facility at 11:30A-PT the equipment was serviced and fueled and it departed at 12:47P-PT for Oakland station for boarding. Once all customers were on board, Train 714(07) departed at 12:59P-PT.

Train 532(07) was delayed departing Oakland, CA due to the congestion in the yard from the Gold Runner service being serviced. Once Train 714(07) cleared yard and worked the Oakland station, the crew on Train 532(07) was able to head to station for boarding.

Train 716(07), CC/C8309-8 cars-E/C2012, was delayed departing Oakland, CA due to a late release from mechanical. At 2:00P-PT, mechanical estimated another thirty minutes were needed for servicing the equipment. Equipment arrived into the maintenance facility at 2:30P-PT and was able to depart at 3:00P-PT.

The Union Pacific dispatcher did not receive the information in time and allowed 716(07) to depart Oakland as soon as they were able to initialize PTC. Train 716(07) was then terminated at Emeryville, where all passengers detrained and were accommodated on train 718(07).

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train 718(07) was then delayed departing Oakland, CA due to trains 542, 715, 716 and 545(07) all arriving causing congestion.

08AUG26: Train 712(08), CC/C8314-7 cars-E/C2004, was delayed departing Oakland, CA due to a late release from mechanical. The original equipment, CC/C8312-7 cars-E/C2005, arrived into the maintenance facility from Train 719(07) at 10:27P-PT on August 7th. At 9:55A-PT, mechanical was still working on restroom issues on CC/C8212, as well as addressing door issues. Due to the length of delay anticipated for repairs, the equipment for Train 714(08), CC/C8314-7 cars-E/C2004, was decided to be moved up at 10:48A-PT with an anticipated additional thirty minute delay to finish the daily inspections. At 11:27A-PT, mechanical released the equipment to the crew where they performed their necessary inspections and departed the yard at 11:44A-PT to take equipment to station for boarding. Once all customers where boarded, Train 712(08) departed at 11:567A-PT.

Train 714(08), CC/C8312-7 cars-E/C2005, was delayed departing Oakland, CA due to mechanical resolving restroom issues on CC/C8312. The equipment was moved to Train 714(08) from Train 712(08) to give more time for repairs to be made. Once mechanical released the equipment at 12:17P-PT, the crew performed their necessary tests and departed the yard for the station. Once all customers were boarded, Train 714(08) departed at 12:50P-PT.

09AUG26: Train 716(09) was delayed due to an equipment reassignment at Oakland Jack London Square, CA. The train was originally scheduled to operate using the inbound Train 711(09) consist with locomotive E/C2012 and eight cars; however, locomotive E/C2012 required repairs to a shock absorber. To expedite service, a decision was made to utilize the inbound Train 713(09) equipment for Train 716(09). As part of the operating plan, Train 713(09) was terminated at Emeryville, CA, and Train 716(09) originated from Emeryville using the reassigned equipment. Customers traveling between Oakland Jack London Square and Emeryville were accommodated using existing Capitol Corridor service. Because Train 713(09) was scheduled to turn for Train 718(09), the equipment reassignment also affected the operation of Train 718(09). To maintain service, equipment from inbound Train 715(09) was utilized for Train 718(09). As part of this adjustment, Train 715(09) was terminated at Emeryville and Train 718(09) originated there. Customers traveling between Oakland Jack London Square and Emeryville were accommodated using Capitol Corridor service and Bus 6613.

WBS#: B.TR.100150.7012

Train	Delay	Comment
712(07)	1'11"	
714(07)	41"	
532(07)	18"	yard congestion
716(07)	3'07"	Terminated EMY
716(07)	37"	OKJ- PTC
718(07)	40"	
714(08)	32"	ITD OKJ
712(08)	1'39"	ITD OKJ
703(08)	1'02"	late turn 712(08)
716(09)	2'34"	ORIG EMY
715(09)	TERM EMY	
713(09)	TERM EMY	
718(09)	49"	ORIG EMY

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13) cancelled entirely - sourcing alternate.
- Train 371(14) cancelled entirely - sourcing alternate.
- Train 370(16) cancelled entirely - sourcing alternate.
- Train 371(17) cancelled entirely - sourcing alternate.
- Train 370(20) cancelled entirely - sourcing alternate.
- Train 371(21) cancelled entirely - sourcing alternate.

26-FOI-00671 00000008700 "UNCLASSIFIED" 9/2/2026

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely - with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(15) cancelled entirely - sourcing alternate.
- Train 355(15) cancelled entirely - sourcing alternate.
- Train 350(18) cancelled entirely - sourcing alternate.
- Train 355(18) cancelled entirely - sourcing alternate.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 382(10) cancelled entirely, with 2 alternate buses secured between Quincy, IL and Chicago IL.
- Train 381(14) cancelled entirely, - sourcing alternate.
- Train 382(14) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.

Saluki/Illini Service

- Train 391(12) cancelled entirely - with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(12) cancelled entirely, with 2 alternate buses secured between Carbondale,

WBS#: B.TR.100150.6992

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04-10) Cancelled entirely, No alternate Transportation.
- Train 502 (04-10) Cancelled entirely. With alternate transportation.
- Train 504 (04-10) Will terminate in Portland, OR. With alternate transportation.
- Train 518 (04-07) Originates at Seattle, WA. 518 (08-10) Originates Vancouver, WA All with alternate transportation.
- Train 517 (04-10) Will terminate in Vancouver, WA. No alternate Transportation.
- Train 506 (04-10) Originates in Vancouver, WA. No alternate Transportation.
- Train 508 (04-10) Will terminate Portland, OR. With alternate transportation.
- Train 503 (04-10) Originates Portland, OR. With alternate transportation.
- Train 505 (04-07) Cancelled entirely. With alternate transportation. 505 (08-10) Will Terminate in Vancouver, WA, no alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing
 -Train 27 (02-08) Will Terminate at Spokane, WA. Alternate Transportation provided.
 -Train 28 (04-10) Will Originate at Spokane, WA. Alternate Transportation provided.

26-FOI-00671 00000008700 "UNCLASSIFIED" 9/2/2026

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

-Train 14 (04-09) Will Terminate at Portland, OR, no alternate transportation provided.
 -Train 11 (05-10) Will Originate at Portland, OR, no alternate transportation provided.

WBS#: B.TR.100150.6981

Train	Delay	Comment
507(02)	1'41"	bus VAN-PDX
506(02)	Canceled	
508(02)	45"	bus PDX-VAN
509(02)	77"	couple 509-511(02)
509(02)	75"	Detour through UP yard
511(02)	76"	Detour through UP yard
500(03)	Canceled	
502(03)	Canceled	
511(03)	Canceled	
505(03)	Canceled	
518(03)	Canceled	between SEA-PDX
507(03)	Canceled	between SEA-PDX
508(03)	Term PDX	
504(03)	Term PDX	
509(03)	Canceled	
517(03)	Term VAN	
506(03)	Orig VAN	
503(03)	24"	canceled SEA-PDX
507(03)	1'10"	waiting for bus at PDX
14(02)	58"	detour
11(03)	51"	detour
14(04)	term PDX	
506(04)	1'03"	wait for inbound bus
518(04)	1'27"	wait for inbound bus
507(05)	1'09"	PDX- wait for inbound bus
507(06)	1'06"	PDX- inbound bus
503(07)	33"	PDX- inbound bus
507(07)	1'21"	PDX- inbound bus
503(08)	22"	PDX- inbound buses

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple trackwork projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		Mu issues
8 (8)	SPK	312		Blown traction motor

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008700

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
236 (09)	ALB	b/o 82752 no replacement -72Y seats	Passengers notified	71	82752
2165 (10)	BOS	Consist operating with Next Gen Equipment. Schedule change has been made. Check War Reports and re-accommodate any displaced passengers.	PASSENGERS NOTIFIED	458	
566 (09)	LAX	no bike space	NONE	0	90225
584 (09)	LAX	no bike space	NONE	0	90225
566 (10)	LAX	no bike space or wifi	NONE	0	90225
584 (10)	LAX	no bike space or wifi	NONE	0	90225
280 (09)	NFL	Consist departing NFL short a coach, Coach 82808 being added in ALB.	NONE	0	
157 (09)	NHV	Business class car operating in lieu of a coach. Passengers not adversely affected.	NONE	0	81527
283 (09)	NYP	b/o 82752 no replacement -72Y seats	Passengers notified	70	82752
2190 (10)	NYP	Consist operating with Next Gen Equipment. Schedule change has been made. Check War Reports and re-accommodate any displaced passengers.	PASSENGERS NOTIFIED	172	
579 (09)	SAN	no bike space	NONE	0	90225
595 (09)	SAN	no bike space	NONE	0	90225
579 (10)	SAN	no bike space or wifi	NONE	0	90225
595 (10)	SAN	no bike space or wifi	NONE	0	90225
2128 (10)	WAS	Consist operating with Next Gen Equipment. Schedule change has been made. Check War Reports and re-accommodate any displaced passengers.	PASSENGERS NOTIFIED	109	
100 (09)	WAS	Business class car operating in lieu of a coach. Passengers not adversely affected.	NONE	0	81527

Reverse Consists

Train Number	Station	Reason
195 (09)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
87 (09)	BOS	Consist reversed Business class seat orientation may have changed At Front
156 (09)	RNK	Consist reversed Business class seat orientation may have changed At Front
145 (09)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (09)	NYP	Consist reversed Business class seat orientation may have changed At Front
96 (09)	WAS	Consist reversed Business class seat orientation may have changed At Front
154 (09)	WAS	Consist reversed Business class seat orientation may have changed At Front