

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, August 11, 2026

Rules: 0-45



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/10/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	313	46	85.3%	3,001	523	82.6%	93,873	13,067	86.1%
Central Division	86.0%	54	3	94.4%	542	61	88.7%	17,898	1,627	90.9%
East Division	82.0%	174	22	87.4%	1,627	277	83.0%	49,297	7,695	84.4%
West Division	86.0%	85	21	75.3%	832	185	77.8%	26,678	3,745	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00671 00000008599 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	106,618	38,079	64%	1,095,349	356,208	67%	31,428,347	7,997,558	75%
Northeast Corridor	81%	46,815	16,351	65%	472,261	139,651	70%	13,773,774	3,395,679	75%
Acela	83%	10,269	2,971	71%	97,501	24,666	75%	2,757,925	726,217	74%
Northeast Regional	79%	36,546	13,380	63%	374,760	114,985	69%	11,015,849	2,669,462	76%
Richmond / Newport News / Norfolk	77%	11,199	5,428	52%	118,229	48,260	59%	3,418,205	1,009,721	70%
Springfield Shuttles	89%	700	0	100%	5,580	824	85%	193,307	30,692	84%
Roanoke	79%	1,807	624	65%	35,138	9,964	72%	1,040,422	228,620	78%
On Spine Northeast Regional	80%	22,840	7,328	68%	215,813	55,937	74%	6,363,915	1,400,429	78%
State Supported	80%	47,132	13,826	71%	493,557	137,799	72%	13,803,176	2,943,724	79%
Borealis	80%	578	0	100%	6,137	671	89%	175,763	36,303	79%
Capitol Corridor	90%	4,242	529	88%	36,195	6,656	82%	1,151,914	152,405	87%
Carolinian	70%	1,743	1,265	27%	11,262	6,443	43%	356,144	141,442	60%
Cascades	75%	1,241	831	33%	18,218	9,522	48%	801,468	224,558	72%
Downeaster	82%	1,956	111	94%	21,408	2,661	88%	481,721	58,616	88%
Empire	78%	6,750	2,957	56%	64,828	22,703	65%	1,708,541	406,162	76%
Adirondack	72%	790	748	5%	4,790	2,765	42%	104,753	33,610	68%
Ethan Allen Express	70%	630	532	16%	6,261	4,251	32%	175,169	64,600	63%
Maple Leaf	70%	871	724	17%	9,152	3,857	58%	209,501	80,700	61%
New York - Albany	85%	3,065	581	81%	28,735	7,048	75%	791,083	132,975	83%
New York - Niagara Falls	75%	1,394	372	73%	14,416	3,616	75%	418,448	89,297	79%
Berkshire Flyer	60%	0	0	-	1,474	1,166	21%	9,587	4,980	48%
Gold Runner	73%	2,426	909	63%	25,880	13,739	47%	781,446	284,192	64%
Heartland Flyer	70%	212	126	41%	2,897	2,195	24%	67,580	27,617	59%
Hiawatha	90%	1,816	191	89%	21,334	1,425	93%	542,253	59,122	89%
Illinois	78%	2,674	477	82%	27,202	8,102	70%	773,426	212,657	73%
Carl Sandburg / Illinois Zephyr	85%	303	0	100%	4,374	1,684	61%	129,174	35,842	72%
Illini / Saluki	85%	807	100	88%	8,733	2,711	69%	268,620	64,611	76%
Lincoln Service	70%	1,564	377	76%	14,095	3,707	74%	375,632	112,204	70%
Keystone	92%	8,744	281	97%	77,779	3,922	95%	2,359,898	243,468	90%
Lincoln / Missouri	70%	786	570	27%	9,130	5,590	39%	241,621	123,898	49%
Mardi Gras Service	80%	195	41	79%	3,378	872	74%	127,099	28,487	78%
Michigan	70%	2,473	1,231	50%	25,332	11,573	54%	622,757	203,994	67%
Blue Water	70%	616	106	83%	6,145	3,084	50%	145,803	58,912	60%
Pere Marquette	85%	142	38	73%	2,577	214	92%	81,011	15,338	81%
Wolverine	70%	1,715	1,087	37%	16,610	8,275	50%	395,943	129,744	67%
Missouri	80%	204	8	96%	2,962	1,258	58%	68,798	17,694	74%
Pacific Surfliner	85%	8,311	3,363	60%	107,949	31,728	71%	2,520,121	461,435	82%
Pennsylvanian	80%	836	17	98%	8,817	2,096	76%	274,619	53,173	81%
Piedmont	80%	745	251	66%	9,930	1,601	84%	350,204	90,253	74%
Vermont	75%	1,200	668	44%	12,919	5,042	61%	397,803	118,248	70%
Long Distance	70%	12,671	7,902	38%	129,531	78,758	39%	3,812,130	1,655,692	57%
Auto Train	70%	850	466	45%	8,709	1,849	79%	243,118	82,638	66%
California Zephyr	70%	1,124	979	13%	10,486	8,208	22%	302,080	114,865	62%
Cardinal	70%	651	417	36%	2,134	1,307	39%	73,615	36,850	50%
City Of New Orleans	75%	722	484	33%	6,491	4,829	26%	197,715	63,008	68%
Coast Starlight	70%	895	310	65%	10,595	5,830	45%	355,272	126,292	64%
Crescent	70%	1,024	443	57%	9,088	2,060	77%	288,741	88,043	70%
Empire Builder	70%	973	482	50%	9,908	7,126	28%	298,275	149,331	50%
Floridian	60%	1,835	1,564	15%	17,677	13,972	21%	495,443	341,014	31%
Lake Shore Ltd	73%	1,140	43	96%	11,975	4,915	59%	299,212	90,021	70%
Palmetto	70%	580	407	30%	9,319	5,695	39%	285,422	88,304	69%
Silver Meteor	70%	1,126	802	29%	10,235	7,371	28%	315,435	144,722	54%
Southwest Chief	60%	972	726	25%	10,308	7,668	26%	260,774	170,261	35%
Sunset Ltd	70%	302	302	0%	2,357	1,964	17%	90,723	34,732	62%
Texas Eagle	70%	477	477	0%	10,249	5,964	42%	306,305	125,611	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 000000000000 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 10, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	69,308	1,060,926	653	1,859,387	33,008,863	563

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,159	319,060	130	90,071	9,516,063	95
INFRASTRUCTURE PLANNED	135	5,955	319,060	187	102,010	9,516,063	107
FLEET RELIABILITY	90	10,636	1,060,926	100	296,776	33,008,863	90
TRAIN OPERATIONS	424	48,558	1,060,926	458	1,370,530	33,008,863	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/10/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	313	46	85.3%	3,001	523	82.6%	93,873	13,067	86.1%
Central Division	86.0%	54	3	94.4%	542	61	88.7%	17,898	1,627	90.9%
East Division	82.0%	174	22	87.4%	1,627	277	83.0%	49,297	7,695	84.4%
West Division	86.0%	85	21	75.3%	832	185	77.8%	26,678	3,745	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/10/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	313	46	85.3%	3,001	523	82.6%	93,873	13,067	86.1%
Central Division	86.0%	54	3	94.4%	542	61	88.7%	17,898	1,627	90.9%
CDL	95.0%	2	0	100.0%	20	3	85.0%	596	28	95.3%
CHI	86.0%	25	1	96.0%	250	35	86.0%	8,264	999	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	10	0	100.0%	337	36	89.3%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	-	-	-	7	0	100.0%	295	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	10	2	80.0%	567	44	92.2%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	57	4	93.0%	1,837	118	93.6%
MOE	97.5%	2	0	100.0%	20	0	100.0%	625	9	98.6%
MSP	96.5%	1	0	100.0%	10	1	90.0%	307	7	97.7%
NOL	94.5%	5	0	100.0%	45	2	95.6%	1,318	62	95.3%
OKC	97.0%	1	0	100.0%	10	0	100.0%	308	6	98.1%
PNT	88.0%	3	1	66.7%	29	3	89.7%	816	67	91.8%
PTH	93.0%	1	0	100.0%	10	2	80.0%	302	13	95.7%
QCY	91.0%	1	0	100.0%	16	2	87.5%	593	45	92.4%
SAS	90.5%	1	0	100.0%	10	3	70.0%	311	36	88.4%
STL	89.0%	4	0	100.0%	37	3	91.9%	1,206	100	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	174	22	87.4%	1,627	277	83.0%	49,297	7,695	84.4%
ALB	88.5%	7	0	100.0%	75	5	93.3%	2,325	180	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	50	8	84.0%	1,516	166	89.1%
BOS	85.5%	17	1	94.1%	175	12	93.1%	5,338	616	88.5%
BRK	92.5%	5	1	80.0%	50	5	90.0%	1,502	107	92.9%
BTN	82.0%	1	0	100.0%	10	0	100.0%	300	41	86.3%
CLT	91.5%	5	0	100.0%	50	4	92.0%	1,527	154	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	13	1	92.3%	606	58	90.4%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	0	100.0%	106	15	85.8%	3,470	563	83.8%
HFD	-	2	0	100.0%	12	3	75.0%	203	18	91.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	10	0	100.0%	310	38	87.7%
MIA	89.5%	2	0	100.0%	20	2	90.0%	620	70	88.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/10/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	313	46	85.3%	3,001	523	82.6%	93,873	13,067	86.1%
East Division	82.0%	174	22	87.4%	1,627	277	83.0%	49,297	7,695	84.4%
MTR	79.0%	1	0	100.0%	10	4	60.0%	297	56	81.1%
NFK	84.5%	2	0	100.0%	20	3	85.0%	703	126	82.1%
NFL	93.5%	2	0	100.0%	20	1	95.0%	632	30	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	7	3	57.1%	48	13	72.9%	1,602	266	83.4%
NPN	93.0%	2	0	100.0%	20	3	85.0%	592	44	92.6%
NYP	75.5%	50	12	76.0%	456	117	74.3%	12,940	2,895	77.6%
PGH	93.0%	1	0	100.0%	10	1	90.0%	311	23	92.6%
PHL	48.0%	5	1	80.0%	46	24	47.8%	1,596	764	52.1%
PIT	76.0%	-	-	-	3	3	0.0%	18	15	16.7%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	1	75.0%	32	2	93.8%	1,190	51	95.7%
RNK	83.5%	2	0	100.0%	20	2	90.0%	616	89	85.6%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	7	0	100.0%	294	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	10	0	100.0%	307	10	96.7%
SFA	88.0%	1	0	100.0%	10	0	100.0%	310	41	86.8%
SPG	92.5%	3	0	100.0%	43	2	95.3%	1,850	107	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	10	1	90.0%	299	61	79.6%
WAS	84.0%	31	2	93.5%	283	46	83.7%	7,755	1,013	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	85	21	75.3%	832	185	77.8%	26,678	3,745	86.0%
ARN	92.0%	1	0	100.0%	10	1	90.0%	312	27	91.3%
BFD	79.0%	7	3	57.1%	69	19	72.5%	1,966	412	79.0%
EMY	72.0%	1	0	100.0%	10	2	80.0%	328	96	70.7%
EUG	86.5%	2	0	100.0%	20	1	95.0%	618	57	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	30	10	66.7%	939	153	83.7%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	103	10	90.3%	3,102	336	89.2%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	4	69.2%	112	48	57.1%	3,373	876	74.0%
PDX	86.0%	3	2	33.3%	23	15	34.8%	1,511	196	87.0%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/10/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	313	46	85.3%	3,001	523	82.6%	93,873	13,067	86.1%
West Division	86.0%	85	21	75.3%	832	185	77.8%	26,678	3,745	86.0%
SAC	88.5%	15	3	80.0%	141	16	88.7%	4,407	478	89.2%
SAN	90.5%	13	3	76.9%	129	14	89.1%	3,770	358	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	0	100.0%	49	24	51.0%	2,434	371	84.8%
SJC	89.0%	7	0	100.0%	69	7	89.9%	2,193	216	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	30	6	80.0%	702	71	89.9%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	20	0	100.0%	611	14	97.7%
VAN	-	2	2	0.0%	11	9	18.2%	11	9	18.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	288	5	1	80.0%	133	10	92.5%	3	3	0.0%	132	34	74.2%
3		10	2	80.0%	312	61	80.4%	10	6	40.0%	310	142	54.2%
4	176	10	1	90.0%	311	47	84.9%	10	7	30.0%	311	206	33.8%
5	179	10	2	80.0%	310	52	83.2%	10	10	0.0%	306	98	68.0%
6	115	10	2	80.0%	309	87	71.8%	10	9	10.0%	309	112	63.8%
7		10	3	70.0%	301	45	85.0%	9	5	44.4%	292	79	72.9%
8	266	10	7	30.0%	301	136	54.8%	10	8	20.0%	300	183	39.0%
11		10	7	30.0%	312	64	79.5%	10	2	80.0%	306	62	79.7%
14		10	2	80.0%	313	51	83.7%	9	7	22.2%	310	99	68.1%
19		10	1	90.0%	311	78	74.9%	10	1	90.0%	308	72	76.6%
20	44	10	0	100.0%	311	23	92.6%	10	2	80.0%	311	60	80.7%
21	180	10	4	60.0%	308	29	90.6%	10	5	50.0%	307	87	71.7%
22	358	10	3	70.0%	309	34	89.0%	10	4	60.0%	307	85	72.3%
23		10	0	100.0%	313	6	98.1%	10	2	80.0%	311	87	72.0%
24	46	10	0	100.0%	313	16	94.9%	10	4	60.0%	312	60	80.8%
25		10	0	100.0%	312	3	99.0%	9	4	55.6%	309	87	71.8%
26		10	0	100.0%	312	5	98.4%	9	1	88.9%	309	61	80.3%
40	88	10	2	80.0%	306	43	85.9%	10	6	40.0%	303	161	46.9%
41	165	10	3	70.0%	305	117	61.6%	10	8	20.0%	303	232	23.4%
42		10	1	90.0%	313	25	92.0%	10	3	70.0%	311	55	82.3%
43		10	2	80.0%	312	44	85.9%	10	1	90.0%	311	71	77.2%
48		10	3	70.0%	311	60	80.7%	10	1	90.0%	310	43	86.1%
49		10	4	60.0%	311	79	74.6%	10	3	70.0%	311	65	79.1%
51	123	3	1	66.7%	129	56	56.6%	4	3	25.0%	125	47	62.4%
52		10	0	100.0%	310	41	86.8%	10	0	100.0%	309	72	76.7%
53		10	0	100.0%	310	38	87.7%	10	3	70.0%	309	98	68.3%
55	40	6	1	83.3%	196	8	95.9%	6	3	50.0%	193	41	78.8%
56		6	2	66.7%	197	25	87.3%	6	3	50.0%	193	37	80.8%
58	64	10	1	90.0%	287	17	94.1%	9	8	11.1%	285	81	71.6%
59	49	10	7	30.0%	285	40	86.0%	10	7	30.0%	281	64	77.2%
63	62	10	5	50.0%	314	137	56.4%	10	10	0.0%	308	176	42.9%
64	27	10	1	90.0%	312	69	77.9%	10	7	30.0%	311	116	62.7%
66		10	1	90.0%	311	62	80.1%	10	2	80.0%	307	56	81.8%
67		7	1	85.7%	215	14	93.5%	6	2	66.7%	214	38	82.2%
68	28	10	4	60.0%	314	65	79.3%	10	6	40.0%	313	124	60.4%
69	19	10	8	20.0%	301	76	74.8%	10	7	30.0%	296	50	83.1%
71		10	0	100.0%	309	3	99.0%	9	1	88.9%	307	82	73.3%
72	12	10	2	80.0%	305	33	89.2%	9	3	66.7%	303	64	78.9%
73	20	10	2	80.0%	308	21	93.2%	10	3	70.0%	306	145	52.6%
74	11	10	0	100.0%	306	33	89.2%	10	3	70.0%	304	111	63.5%
75	23	10	0	100.0%	302	16	94.7%	10	2	80.0%	296	139	53.0%
76	85	10	0	100.0%	302	29	90.4%	10	4	60.0%	293	121	58.7%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		10	0	100.0%	304	20	93.4%	10	2	80.0%	302	125	58.6%
78		10	0	100.0%	308	25	91.9%	10	4	60.0%	307	67	78.2%
79	51	10	1	90.0%	311	57	81.7%	10	4	60.0%	310	105	66.1%
80	84	10	2	80.0%	311	35	88.7%	10	6	40.0%	308	69	77.6%
84	23	6	3	50.0%	187	17	90.9%	5	3	40.0%	184	46	75.0%
85	38	6	0	100.0%	198	16	91.9%	6	1	83.3%	198	71	64.1%
86		6	0	100.0%	198	15	92.4%	6	4	33.3%	197	119	39.6%
89	40	10	6	40.0%	309	71	77.0%	10	7	30.0%	307	92	70.0%
90	73	10	0	100.0%	309	10	96.8%	10	5	50.0%	308	56	81.8%
93	79	6	0	100.0%	197	19	90.4%	6	4	33.3%	196	51	74.0%
94		6	1	83.3%	228	56	75.4%	6	2	66.7%	226	85	62.4%
95	115	6	1	83.3%	197	5	97.5%	6	5	16.7%	197	74	62.4%
97	50	10	8	20.0%	311	206	33.8%	10	7	30.0%	309	107	65.4%
98		10	0	100.0%	311	26	91.6%	10	7	30.0%	309	115	62.8%
110		6	0	100.0%	194	102	47.4%	6	0	100.0%	191	19	90.1%
111	22	6	1	83.3%	188	36	80.9%	6	1	83.3%	186	22	88.2%
112		6	1	83.3%	188	19	89.9%	6	0	100.0%	187	19	89.8%
113	23	6	4	33.3%	119	29	75.6%	6	1	83.3%	118	15	87.3%
119		6	1	83.3%	185	46	75.1%	6	1	83.3%	183	23	87.4%
125	80	6	1	83.3%	198	12	93.9%	6	3	50.0%	198	77	61.1%
128		4	0	100.0%	116	19	83.6%	4	1	75.0%	116	23	80.2%
129		6	2	66.7%	197	49	75.1%	6	1	83.3%	197	29	85.3%
130		6	0	100.0%	188	18	90.4%	6	0	100.0%	186	16	91.4%
131		6	1	83.3%	190	54	71.6%	6	0	100.0%	190	35	81.6%
134	30	6	2	66.7%	198	29	85.4%	6	3	50.0%	197	39	80.2%
137		6	1	83.3%	195	36	81.5%	6	2	66.7%	195	60	69.2%
138	22	6	0	100.0%	198	39	80.3%	6	3	50.0%	197	37	81.2%
139	45	2	0	100.0%	40	5	87.5%	2	1	50.0%	40	14	65.0%
141		6	1	83.3%	197	4	98.0%	6	2	66.7%	196	35	82.1%
148		6	1	83.3%	197	21	89.3%	6	1	83.3%	195	37	81.0%
151		10	5	50.0%	310	100	67.7%	10	0	100.0%	309	95	69.3%
166		2	0	100.0%	40	5	87.5%	2	0	100.0%	39	13	66.7%
169		4	0	100.0%	114	12	89.5%	4	0	100.0%	114	24	78.9%
170		6	0	100.0%	193	12	93.8%	6	0	100.0%	192	29	84.9%
171	124	6	0	100.0%	198	11	94.4%	6	5	16.7%	198	80	59.6%
172	46	6	2	66.7%	197	17	91.4%	6	4	33.3%	195	66	66.2%
173	27	6	1	83.3%	190	25	86.8%	6	5	16.7%	189	83	56.1%
174		6	1	83.3%	198	21	89.4%	6	3	50.0%	198	51	74.2%
175		6	0	100.0%	198	22	88.9%	6	2	66.7%	198	64	67.7%
176		6	1	83.3%	190	16	91.6%	6	2	66.7%	188	26	86.2%
177		6	0	100.0%	198	27	86.4%	6	0	100.0%	198	46	76.8%
181		6	3	50.0%	194	62	68.0%	5	1	80.0%	191	16	91.6%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		6	0	100.0%	188	30	84.0%	6	0	100.0%	186	21	88.7%
183	19	6	4	33.3%	197	60	69.5%	6	3	50.0%	194	41	78.9%
184		6	2	66.7%	198	35	82.3%	6	1	83.3%	197	28	85.8%
185		6	0	100.0%	198	37	81.3%	6	0	100.0%	198	14	92.9%
186	65	6	3	50.0%	197	24	87.8%	6	4	33.3%	196	57	70.9%
190		6	2	66.7%	197	71	64.0%	6	1	83.3%	196	44	77.6%
192		6	0	100.0%	195	24	87.7%	6	1	83.3%	195	18	90.8%
193		5	2	60.0%	193	80	58.5%	5	1	80.0%	192	89	53.6%
196		6	0	100.0%	194	20	89.7%	5	1	80.0%	192	16	91.7%
197		6	1	83.3%	198	76	61.6%	6	2	66.7%	198	69	65.2%
230		10	0	100.0%	147	4	97.3%	10	0	100.0%	147	7	95.2%
232		10	0	100.0%	313	11	96.5%	10	1	90.0%	313	22	93.0%
233		7	1	85.7%	280	62	77.9%	7	4	42.9%	279	92	67.0%
234		10	0	100.0%	314	22	93.0%	10	0	100.0%	313	25	92.0%
235		10	4	60.0%	238	38	84.0%	10	2	80.0%	237	54	77.2%
236		10	0	100.0%	298	10	96.6%	10	3	70.0%	297	42	85.9%
237		10	0	100.0%	311	56	82.0%	10	1	90.0%	309	52	83.2%
238		10	3	70.0%	238	23	90.3%	10	1	90.0%	236	19	91.9%
239	40	10	1	90.0%	312	80	74.4%	10	1	90.0%	311	39	87.5%
240		10	1	90.0%	313	22	93.0%	10	3	70.0%	310	63	79.7%
241		10	2	80.0%	313	76	75.7%	10	4	60.0%	313	75	76.0%
243		10	3	70.0%	249	68	72.7%	10	2	80.0%	248	35	85.9%
244	32	7	0	100.0%	279	12	95.7%	7	5	28.6%	279	54	80.6%
245	71	10	2	80.0%	194	35	82.0%	10	3	70.0%	193	25	87.0%
280	56	10	1	90.0%	314	16	94.9%	10	3	70.0%	313	64	79.6%
281		10	0	100.0%	314	37	88.2%	10	1	90.0%	314	58	81.5%
283		10	5	50.0%	314	79	74.8%	10	3	70.0%	314	64	79.6%
284		10	0	100.0%	314	13	95.9%	10	1	90.0%	311	55	82.3%
290	29	10	0	100.0%	314	50	84.1%	10	7	30.0%	311	121	61.1%
291		10	7	30.0%	313	100	68.1%	10	5	50.0%	311	81	74.0%
300	25	8	1	87.5%	296	21	92.9%	8	2	75.0%	294	70	76.2%
301		10	0	100.0%	311	10	96.8%	10	2	80.0%	307	57	81.4%
302		9	0	100.0%	292	33	88.7%	9	2	77.8%	288	80	72.2%
305		8	0	100.0%	294	28	90.5%	8	0	100.0%	290	115	60.3%
306		10	1	90.0%	309	17	94.5%	9	2	77.8%	307	84	72.6%
307		10	1	90.0%	302	39	87.1%	9	3	66.7%	298	85	71.5%
311		10	1	90.0%	307	27	91.2%	10	4	60.0%	301	67	77.7%
316		10	2	80.0%	303	20	93.4%	10	6	40.0%	298	84	71.8%
318	33	10	0	100.0%	312	31	90.1%	10	6	40.0%	309	150	51.5%
319	57	10	0	100.0%	313	20	93.6%	10	9	10.0%	308	174	43.5%
329	19	6	0	100.0%	221	9	95.9%	6	1	83.3%	221	16	92.8%
330		8	0	100.0%	266	6	97.7%	8	0	100.0%	266	15	94.4%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		10	0	100.0%	314	33	89.5%	10	0	100.0%	314	44	86.0%
332		9	1	88.9%	313	18	94.2%	9	0	100.0%	313	43	86.3%
334		10	0	100.0%	314	10	96.8%	10	0	100.0%	313	40	87.2%
335		10	0	100.0%	314	34	89.2%	10	2	80.0%	312	53	83.0%
336		10	0	100.0%	314	10	96.8%	10	0	100.0%	312	28	91.0%
337		10	0	100.0%	314	18	94.3%	10	2	80.0%	310	38	87.7%
338		10	2	80.0%	314	49	84.4%	10	5	50.0%	312	99	68.3%
339		10	2	80.0%	314	52	83.4%	10	1	90.0%	314	54	82.8%
341	18	9	2	77.8%	301	46	84.7%	9	4	55.6%	295	45	84.7%
342		10	1	90.0%	314	25	92.0%	10	0	100.0%	312	60	80.8%
350	41	10	0	100.0%	291	18	93.8%	10	8	20.0%	284	159	44.0%
351	20	9	1	88.9%	296	28	90.5%	9	5	44.4%	294	83	71.8%
352		9	1	88.9%	280	22	92.1%	9	4	55.6%	274	85	69.0%
353		10	0	100.0%	252	13	94.8%	10	2	80.0%	246	40	83.7%
354	46	10	0	100.0%	295	35	88.1%	10	8	20.0%	288	109	62.2%
355	82	10	2	80.0%	304	33	89.1%	10	9	10.0%	297	108	63.6%
364		10	3	70.0%	303	68	77.6%	10	4	60.0%	297	111	62.6%
365		10	2	80.0%	302	13	95.7%	9	4	55.6%	299	113	62.2%
370		7	0	100.0%	302	35	88.4%	7	1	85.7%	292	70	76.0%
380		7	1	85.7%	296	28	90.5%	6	0	100.0%	295	63	78.6%
383		8	0	100.0%	301	26	91.4%	8	6	25.0%	298	129	56.7%
390		10	3	70.0%	296	22	92.6%	10	5	50.0%	295	78	73.6%
391		10	1	90.0%	297	12	96.0%	10	5	50.0%	293	81	72.4%
392		10	0	100.0%	310	10	96.8%	10	2	80.0%	307	92	70.0%
393	16	10	0	100.0%	314	18	94.3%	10	5	50.0%	311	96	69.1%
417		6	1	83.3%	208	45	78.4%	6	1	83.3%	199	23	88.4%
425	Cncld	5	1	80.0%	209	7	96.7%	4	0	100.0%	208	7	96.6%
470		6	0	100.0%	221	37	83.3%	6	0	100.0%	215	24	88.8%
471		6	2	66.7%	211	13	93.8%	6	0	100.0%	211	5	97.6%
473		6	0	100.0%	217	15	93.1%	6	0	100.0%	214	10	95.3%
474		6	1	83.3%	215	64	70.2%	6	3	50.0%	200	66	67.0%
475		6	0	100.0%	215	6	97.2%	6	0	100.0%	215	15	93.0%
478	50	6	1	83.3%	209	33	84.2%	6	1	83.3%	207	28	86.5%
479		6	1	83.3%	216	35	83.8%	6	1	83.3%	214	32	85.0%
486		6	2	66.7%	220	33	85.0%	6	2	66.7%	214	60	72.0%
494		6	1	83.3%	222	42	81.1%	6	1	83.3%	215	58	73.0%
495		6	0	100.0%	205	4	98.0%	6	0	100.0%	203	3	98.5%
503	78	10	8	20.0%	310	35	88.7%	10	8	20.0%	303	95	68.6%
504		10	0	100.0%	314	19	93.9%	10	2	80.0%	312	92	70.5%
505		5	0	100.0%	307	41	86.6%	5	2	60.0%	302	86	71.5%
506		10	7	30.0%	309	49	84.1%	8	2	75.0%	301	48	84.1%
507	48	10	8	20.0%	314	44	86.0%	10	7	30.0%	314	107	65.9%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508	42	10	1	90.0%	309	42	86.4%	10	8	20.0%	305	76	75.1%
516		10	4	60.0%	305	33	89.2%	10	5	50.0%	304	139	54.3%
517	62	10	0	100.0%	314	8	97.5%	10	7	30.0%	310	134	56.8%
518	No OS	10	7	30.0%	314	44	86.0%	10	10	0.0%	312	217	30.4%
519	29	10	0	100.0%	305	9	97.0%	10	4	60.0%	303	70	76.9%
520	Cncld	6	3	50.0%	179	28	84.4%	4	0	100.0%	174	9	94.8%
521		6	0	100.0%	217	7	96.8%	6	2	66.7%	217	29	86.6%
522		6	2	66.7%	217	41	81.1%	6	0	100.0%	214	20	90.7%
523		6	1	83.3%	217	8	96.3%	6	1	83.3%	216	23	89.4%
524		5	0	100.0%	216	16	92.6%	5	2	60.0%	213	25	88.3%
525		5	0	100.0%	214	16	92.5%	5	0	100.0%	210	14	93.3%
526	34	6	2	66.7%	191	36	81.2%	6	2	66.7%	188	17	91.0%
527		6	0	100.0%	217	10	95.4%	6	1	83.3%	216	38	82.4%
528		6	0	100.0%	217	17	92.2%	6	1	83.3%	216	31	85.6%
529		6	0	100.0%	217	12	94.5%	6	4	33.3%	216	62	71.3%
530		6	0	100.0%	171	16	90.6%	6	2	66.7%	171	34	80.1%
531		6	0	100.0%	191	13	93.2%	6	0	100.0%	191	13	93.2%
532		6	1	83.3%	217	52	76.0%	6	1	83.3%	216	32	85.2%
534		6	1	83.3%	176	26	85.2%	6	0	100.0%	174	16	90.8%
536		6	3	50.0%	217	58	73.3%	6	1	83.3%	213	39	81.7%
537		5	0	100.0%	186	22	88.2%	5	0	100.0%	180	20	88.9%
538		6	1	83.3%	217	25	88.5%	6	1	83.3%	216	44	79.6%
539	37	6	1	83.3%	171	25	85.4%	6	4	33.3%	171	75	56.1%
540		6	1	83.3%	216	39	81.9%	5	0	100.0%	207	18	91.3%
541		6	1	83.3%	216	23	89.4%	6	1	83.3%	210	37	82.4%
542		6	0	100.0%	216	24	88.9%	6	2	66.7%	213	39	81.7%
543		6	1	83.3%	217	25	88.5%	6	2	66.7%	217	65	70.0%
544	19	6	1	83.3%	215	21	90.2%	5	1	80.0%	211	21	90.0%
545		6	0	100.0%	217	17	92.2%	6	1	83.3%	214	25	88.3%
547		6	3	50.0%	217	44	79.7%	6	3	50.0%	217	50	77.0%
548		5	0	100.0%	211	21	90.0%	5	1	80.0%	209	16	92.3%
549		6	1	83.3%	212	27	87.3%	5	2	60.0%	203	19	90.6%
550		6	0	100.0%	171	18	89.5%	6	3	50.0%	171	39	77.2%
551		6	1	83.3%	213	23	89.2%	6	1	83.3%	203	21	89.7%
562		10	0	100.0%	305	23	92.5%	10	0	100.0%	301	35	88.4%
564		10	0	100.0%	306	19	93.8%	10	2	80.0%	298	40	86.6%
566		10	2	80.0%	304	27	91.1%	10	5	50.0%	301	50	83.4%
567		10	0	100.0%	191	10	94.8%	10	2	80.0%	189	11	94.2%
572	19	10	0	100.0%	301	24	92.0%	10	4	60.0%	294	87	70.4%
573		10	0	100.0%	303	40	86.8%	10	2	80.0%	296	53	82.1%
579		10	1	90.0%	191	12	93.7%	9	2	77.8%	185	39	78.9%
580		10	1	90.0%	306	17	94.4%	10	4	60.0%	299	32	89.3%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
581		10	2	80.0%	306	52	83.0%	10	5	50.0%	304	69	77.3%
584	34	10	1	90.0%	190	26	86.3%	10	10	0.0%	185	118	36.2%
587	47	10	2	80.0%	299	18	94.0%	10	3	70.0%	290	56	80.7%
588	21	10	1	90.0%	191	19	90.1%	10	4	60.0%	190	37	80.5%
591	23	10	1	90.0%	303	22	92.7%	10	4	60.0%	297	43	85.5%
593	24	9	2	77.8%	299	49	83.6%	9	1	88.9%	278	38	86.3%
595	18	10	3	70.0%	301	56	81.4%	10	4	60.0%	298	64	78.5%
600		6	0	100.0%	225	9	96.0%	6	1	83.3%	223	20	91.0%
601		6	5	16.7%	208	88	57.7%	6	2	66.7%	205	27	86.8%
605		6	4	33.3%	215	134	37.7%	6	0	100.0%	211	22	89.6%
607		6	0	100.0%	224	30	86.6%	6	0	100.0%	221	25	88.7%
609		6	0	100.0%	215	23	89.3%	6	1	83.3%	214	20	90.7%
622		5	1	80.0%	125	33	73.6%	5	0	100.0%	123	5	95.9%
626		6	2	66.7%	129	18	86.0%	6	0	100.0%	127	18	85.8%
637		4	0	100.0%	67	7	89.6%	4	0	100.0%	67	5	92.5%
639		6	1	83.3%	195	39	80.0%	6	0	100.0%	194	19	90.2%
640		6	0	100.0%	215	7	96.7%	6	4	33.3%	213	84	60.6%
641		6	1	83.3%	197	39	80.2%	6	1	83.3%	197	27	86.3%
642		6	1	83.3%	213	10	95.3%	6	0	100.0%	212	26	87.7%
643		6	0	100.0%	227	44	80.6%	6	2	66.7%	224	38	83.0%
644	13	6	0	100.0%	219	28	87.2%	6	2	66.7%	217	54	75.1%
645	19	6	0	100.0%	227	41	81.9%	6	3	50.0%	224	49	78.1%
646	14	6	0	100.0%	216	51	76.4%	6	3	50.0%	214	104	51.4%
647		6	0	100.0%	227	32	85.9%	6	0	100.0%	226	49	78.3%
648		6	0	100.0%	223	56	74.9%	6	1	83.3%	223	35	84.3%
649		6	1	83.3%	228	43	81.1%	6	0	100.0%	225	34	84.9%
650		6	1	83.3%	227	42	81.5%	6	0	100.0%	224	36	83.9%
651		6	1	83.3%	227	17	92.5%	6	1	83.3%	225	43	80.9%
652		6	2	66.7%	228	31	86.4%	6	1	83.3%	224	38	83.0%
653		6	2	66.7%	216	35	83.8%	6	0	100.0%	213	39	81.7%
654		6	1	83.3%	217	41	81.1%	6	1	83.3%	213	19	91.1%
655		6	1	83.3%	225	73	67.6%	6	1	83.3%	223	74	66.8%
656		6	3	50.0%	227	50	78.0%	6	0	100.0%	226	30	86.7%
657		6	1	83.3%	216	28	87.0%	6	0	100.0%	215	29	86.5%
658		6	0	100.0%	227	35	84.6%	6	0	100.0%	225	33	85.3%
680		6	0	100.0%	222	12	94.6%	6	0	100.0%	221	27	87.8%
681	11	6	0	100.0%	222	17	92.3%	6	3	50.0%	216	89	58.8%
682		6	0	100.0%	221	6	97.3%	6	1	83.3%	221	39	82.4%
683		6	1	83.3%	204	18	91.2%	6	2	66.7%	203	69	66.0%
684		6	1	83.3%	203	33	83.7%	6	0	100.0%	203	45	77.8%
685	29	6	0	100.0%	218	31	85.8%	6	1	83.3%	215	54	74.9%
686		6	0	100.0%	223	37	83.4%	6	1	83.3%	222	48	78.4%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
687		6	1	83.3%	222	35	84.2%	6	1	83.3%	221	37	83.3%
688		6	0	100.0%	221	13	94.1%	6	2	66.7%	220	38	82.7%
699		1	0	100.0%	63	8	87.3%	1	0	100.0%	63	3	95.2%
701		10	1	90.0%	246	26	89.4%	10	0	100.0%	243	25	89.7%
702		10	0	100.0%	313	32	89.8%	10	3	70.0%	310	73	76.5%
703	No OS	10	8	20.0%	314	101	67.8%	10	6	40.0%	312	91	70.8%
704	27	10	3	70.0%	245	40	83.7%	10	3	70.0%	238	49	79.4%
710		10	1	90.0%	314	78	75.2%	10	3	70.0%	310	84	72.9%
711		10	0	100.0%	305	34	88.9%	10	5	50.0%	284	57	79.9%
712		10	6	40.0%	311	86	72.3%	10	6	40.0%	302	104	65.6%
713		9	0	100.0%	181	16	91.2%	6	4	33.3%	162	71	56.2%
714	18	10	8	20.0%	195	83	57.4%	9	8	11.1%	180	84	53.3%
715	25	10	1	90.0%	313	62	80.2%	7	5	28.6%	287	146	49.1%
716	No OS	10	7	30.0%	314	127	59.6%	9	7	22.2%	307	125	59.3%
717		10	2	80.0%	299	70	76.6%	7	3	57.1%	277	89	67.9%
718	41	10	8	20.0%	314	161	48.7%	10	8	20.0%	312	117	62.5%
719	27	10	7	30.0%	314	110	65.0%	9	6	33.3%	297	90	69.7%
757		10	0	100.0%	99	5	94.9%	10	1	90.0%	98	9	90.8%
761	74	10	1	90.0%	310	13	95.8%	10	2	80.0%	307	43	86.0%
765	138	10	0	100.0%	310	25	91.9%	10	2	80.0%	310	44	85.8%
769	31	10	0	100.0%	310	27	91.3%	10	2	80.0%	304	59	80.6%
770		10	2	80.0%	310	24	92.3%	10	6	40.0%	308	95	69.2%
774	121	10	0	100.0%	310	16	94.8%	10	4	60.0%	309	73	76.4%
777		10	0	100.0%	195	12	93.8%	10	4	60.0%	194	46	76.3%
782		10	8	20.0%	195	90	53.8%	10	4	60.0%	190	29	84.7%
785	57	10	2	80.0%	310	24	92.3%	10	3	70.0%	310	56	81.9%
786	19	10	2	80.0%	99	21	78.8%	9	5	44.4%	95	52	45.3%
790	33	10	0	100.0%	310	28	91.0%	10	2	80.0%	307	48	84.4%
794		10	4	60.0%	310	37	88.1%	10	3	70.0%	306	69	77.5%
821	24	10	0	100.0%	308	6	98.1%	10	8	20.0%	308	129	58.1%
822		10	0	100.0%	310	16	94.8%	10	9	10.0%	308	151	51.0%
1333		10	1	90.0%	310	33	89.4%	10	1	90.0%	307	100	67.4%
1340		10	1	90.0%	309	7	97.7%	10	1	90.0%	309	52	83.2%
2102		6	1	83.3%	74	14	81.1%	6	0	100.0%	73	6	91.8%
2103		6	0	100.0%	138	12	91.3%	6	1	83.3%	137	10	92.7%
2104		6	0	100.0%	164	10	93.9%	6	0	100.0%	162	12	92.6%
2107		6	0	100.0%	195	34	82.6%	6	1	83.3%	192	21	89.1%
2108	25	6	1	83.3%	195	27	86.2%	6	4	33.3%	189	24	87.3%
2109		6	1	83.3%	88	12	86.4%	6	1	83.3%	86	5	94.2%
2112		6	1	83.3%	35	5	85.7%	6	0	100.0%	33	2	93.9%
2113		6	1	83.3%	74	9	87.8%	6	0	100.0%	74	10	86.5%
2115		6	1	83.3%	74	12	83.8%	6	0	100.0%	73	10	86.3%

Amtrak On Time Performance

Trains Arriving Through: 8/10/2026

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2116	21	6	0	100.0%	35	1	97.1%	6	1	83.3%	35	8	77.1%
2118		6	1	83.3%	35	3	91.4%	6	1	83.3%	35	10	71.4%
2119	18	6	2	66.7%	35	6	82.9%	5	2	60.0%	34	12	64.7%
2120	43	6	4	33.3%	35	13	62.9%	5	5	0.0%	33	18	45.5%
2123		6	1	83.3%	73	9	87.7%	6	0	100.0%	72	15	79.2%
2124		5	1	80.0%	166	35	78.9%	5	1	80.0%	164	23	86.0%
2127		6	1	83.3%	35	8	77.1%	6	1	83.3%	34	8	76.5%
2128		6	0	100.0%	35	3	91.4%	6	1	83.3%	35	3	91.4%
2131		6	2	66.7%	35	8	77.1%	6	1	83.3%	35	4	88.6%
2150		6	0	100.0%	188	22	88.3%	6	1	83.3%	185	74	60.0%
2151	34	6	0	100.0%	137	6	95.6%	6	1	83.3%	135	38	71.9%
2152		6	1	83.3%	93	7	92.5%	6	1	83.3%	92	31	66.3%
2154		6	0	100.0%	96	23	76.0%	6	2	66.7%	92	44	52.2%
2155		6	0	100.0%	197	16	91.9%	6	2	66.7%	193	98	49.2%
2158		6	1	83.3%	34	5	85.3%	6	2	66.7%	34	14	58.8%
2159	23	6	1	83.3%	190	15	92.1%	6	4	33.3%	188	63	66.5%
2160	124	6	0	100.0%	35	2	94.3%	6	4	33.3%	34	22	35.3%
2162	95	6	2	66.7%	196	20	89.8%	6	3	50.0%	190	88	53.7%
2165	55	6	0	100.0%	32	2	93.8%	6	5	16.7%	32	18	43.8%
2167		6	0	100.0%	183	20	89.1%	6	0	100.0%	183	39	78.7%
2171		6	0	100.0%	124	10	91.9%	6	0	100.0%	120	23	80.8%
2190		6	1	83.3%	193	28	85.5%	6	1	83.3%	191	24	87.4%
2193		6	0	100.0%	188	25	86.7%	6	0	100.0%	186	49	73.7%
2233	Cncld	2	0	100.0%	24	4	83.3%	1	0	100.0%	23	4	82.6%
2264	33	2	0	100.0%	6	0	100.0%	2	1	50.0%	6	5	16.7%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	25	SMW	14	DMW	8	WIL-PHL	AM	Held for or routed around MW work or equipment, Control Point, LANDLITH, S/R 10/2 A/C TRACK DEFECT
2116	NYP	21	OTH	10	DMW	7	WIL-PHL	AM	Held for or routed around MW work or equipment, Control Point, LANDLITH, S/R 10/2 A/C TRACK DEFECT
2119	WAS	18	PTI	8	SMW	6	PHL-WIL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRK O/S
2120	NYP	43	ENG	18	ENG	18	PHL-XHM	AM	Other electrical failure, 2137 NG NP, issue with pantograph and traction fault, reconfigured and on the move
2151	WAS	34	DCS	21	DCS	21	XSH-NYP	AM	T.O.L, Other, XPB-LEGGETT, TOL ON 2 TRK BETWEEN PELHAM BAY & LEGGETT
2159	WAS	23	WTR	11	WTR	9	XCY-XHM	AM	Heat order, Other, XCY-XHM
2160	BOS	124	ENG	180	ENG	104	NYP-XSH	AM	Other electrical failure, 2136 NG NP, STOPPED IN LINE 1 A/C MECHANICAL ISSUES
2162	BOS	95	ENG	39	ENG	39	NYP-NYP	AM	Other electrical failure, 2148 NG NP, HELD TO DE-PREPARE TRAIN A/C MECHAINCAL ISSUES
2165	WAS	55	OTH	21	DMW	19	NHV-STM	MN	Waiting for MW clearance Milepost, 50.9, 49.2
2233	WAS	Trn Cancelled	SVS	70	SVS	63	BWI-BWI	AM	Routine inspections, MAP 100 EXPIRED AT MIDNIGHT ON PC/2133
2264	BOS	33	SMW	20	SMW	9	XHM-XCY	AM	Scheduled in track usage program, Other, XMO-XMW, OPERATED NO.1 TRK A/C NO.2 TRK OOS
84	NYP	23	SMW	9	SMW	6	WIL-PHL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRACK O/S
85	WAS	38	CTI	16	DSR	12	BRP-STM	MN	Per bulletin Milepost, 50.9, 49.2, 30, 3, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2, Milepost, 33.6, 32.2, 30, 2
93	NFK	79	CTI	75	CTI	28	BRP-STM	MN	Follow metro north, Control Point, 252
95	NFK	115	WTR	109	WTR	47	FBG-RVR	CS	High winds Milepost, 59.3, 4.6
111	WAS	22	SVS	19	SVS	19	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING FROM SSYD
113	WAS	23	CTI	16	SMW	13	PHL-WIL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRACK O/S

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
125	NPN	80	WTR	84	WTR	38	ALX-WDB	CS	High winds Not exceeding 20 mph, Milepost, 105.1, 88.9	
134	NYP	30	PTI	11	SMW	10	WIL-PHL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRK O/S	
138	NYP	22	WTR	52	WTR	38	FBG-QAN	CS	High winds High winds greater than 60 mph., Milepost, 59.3, 78.0	
139	WAS	45	ENG	44	ENG	20	PHL-WIL	AM	Traction motor, 620 EX ES, OPR AT REDUCED SPEED TO AVOID FURTHER OVERHEATING OF TRACTION MOTOR	
171	RNK	124	WTR	48	WTR	33	CLP-CVS	NS	Trees down Control Point, Orange	
172	BOS	46	DCS	33	DCS	27	KIN-PVD	AM	Power switch failure, Milepost w/Letters, KIN, PVD, due to 21sw failure, AM172 backed-up at KIN to route around the switch failure and continue east	
173	WAS	27	HLD	15	OTH	8	XPV-BAL	AM	Lost time - N.A.R., PRT	
183	WAS	19	SVS	17	SVS	17	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY OBS	
186	PHL	65	PTI	62	PTI	39	RVR-ASD	CS	Follow 90, Other, rvr-asd	
425	SPG	Trn Cancelled								
478	SPG	50	CON	40	CON	40	NHV-NHV	AM	Hold for connecting train	
79	CLT	51	WTR	65	WTR	24	PTB-RMT	CS	Heat order Other, rmt	
80	NYP	84	WTR	77	WTR	35	QAN-ALX	CS	High winds We had to travel at 20 mph, Milepost, 78.0, 98.0	
644	NYP	13	PTI	13	PTI	7	NWK-NYP	AM	Follow, AM172, Other, NWK-NYP	
645	HAR	19	WTR	10	CTC	8	PHL-PAO	AM	PTC - Stop Bypass Permission Required, Control Point, N PENN	
646	NYP	14	OTH	10	OTH	5	PAO-PHL	AM	Lost time - N.A.R., PRT	
20	NYP	44	DMW	112	DMW	98	CLP-MSS	NS	Hold for defect repair Control Point, Calverton	
681	BRK	11	PTI	11	PTI	6	POR-FRE	CS	Meet 684, Control Point, Mountain	
685	BRK	29	INJ	13	INJ	13	ORB-ORB	CS	Injured or sick passenger Passenger kiiyan Jackson res# c0333B was taken off train by EMTs due to seizure symptoms	
63	TWO	62	ENG	23	ENG	23	NYP-NYP	AM	HEP, 92, LATE F/SSYD UNSPECIFIED PROBLEM WITH ENG.92	
64	NYP	27	CTI	37	FTI	26	BUF-ROC	CS	Meet Held at 393 due to single tracking, CSX, CSX, Control Point, CP393	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
68	NYP	28	PTI	41	WTR	41	SLQ-RSP	CN	Heat order Milepost, 42, 2
69	MTR	19	PTI	20	PTI	16	SAR-SAR	DH	Meet 290, Control Point, 37
239	ALB	40	CTI	58	CTI	25	YNY-CRT	MN	Blocked from station track Told station was full held for 2 north bounds and 2 south bounds, all metro north trains, mnr, Control Point, 33
244	NYP	32	CTI	25	CTI	25	POU-CRT	MN	Follow Followed MNRR 882 the entire way from POU to CRT, MNRR, 882, Milepost w/Letters, cp72, cp35
245	ALB	71	ITI	80	ITI	80	NYP-NYP	AM	Service, turn, or wye train, 68
280	NYP	56	FTI	49	FTI	40	BUF-ROC	CS	Meet Control Point, 393, 151
290	NYP	29	DSR	24	PTI	11	XSD-NYP	AM	Meet, AM237, Other, XEE
72	RGH	12	ADA	11	FTI	4	HPT-GRO	NS	Cross over or go around NS freight, Control Point, Pomona
73	CLT	20	PTI	10	FTI	8	HPT-SAL	NS	Held at Spencer for sperry car to clear the main. sperry, Control Point, Spencer
74	RGH	11	DMW	10	DMW	10	CYN-RGH	NS	Stop board after limits were expired; permission to pass by the dispatcher at restricted speed Milepost w/Letters, S164.9, S164.5
75	CLT	23	FTI	17	FTI	17	DNC-BNC	NS	Meet #NS91Z, Control Point, Mebane
76	RGH	85	DCS	60	DCS	60	GRO-DNC	NS	Restrictive signal(s) from known wayside signal failure Cleared up at Merrill, Restricting, Control Point, Superior
89	SAV	40	FTI	67	FTI	28	XDJ-RVR	CS	Follow CSXT I1108, Milepost w/Letters, CFP 61.1, CFP 5.0, Intermodal
90	NYP	73	WTR	56	WTR	29	RVR-XDJ	CS	High winds Milepost, 4.8, 14.8
97	MIA	50	SVS	48	SVS	46	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY OBS AND CATERING
55	WAS	40	DSR	19	SMW	11	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAMBAY 2 TRK DUE TO SCHEDULED MAINTENANCE
40	CHI	88	WTR	109	FTI	33	XPI-XH6	NS	Cross Traffic Train stuck on diamond, unknown, Milepost, 502, 502
41	MIA	165	FTI	76	DCS	27	DNK-SAV	CS	Restrictive signal(s) from known wayside signal failure Restricted Proceed, Control Point, NE Garnett

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
24	MOE	46	FTI	58	FTI	58	PAG-MOE	CS	Follow CSX 606, Milepost, 696.9, 666.6
5	EMY	179	FTI	165	FTI	39	XNV-XSN	UP	Follow Milepost, 799, 771, up 7625
6	CHI	115	WTR	151	WTR	46	XMS-WNN	UP	Heat order Level 2 heat restriction cprv 249 to cprv417, Control Point, cprv249
520	SAC	Trn Cancelled							
526	SAC	34	POL	32	POL	18	EMY-EMY	UP	Right of Way police hold Suspicious object at MP 13.77.
539	SJC	37	TEN	18	TEN	16	SAC-DAV	UP	Loading problem Alertor penalty. Reset the Alertor and cut it out. A/C riding the head end., C2009
544	SAC	19	TEN	28	TEN	9	FFV-DAV	UP	Loading problem Engine did not like climbing the hill out of FFV. Load kept dropping., C2009
51	CHI	123	TRS	89	TRS	86	REN-DYE	CS	Vehicle on track ahead Milepost w/Letters, Q 36.4, Q 36.4
503	EUG	78	DCS	22	DCS	22	SLM-ALY	UP	Issue with automatic road crossing protection Multiple XG, Milepost, 692.34, 691.94
507	EUG	48	CON	20	CON	20	PDX-PDX	UP	Hold for thruway bus
508	PDX	42	PTI	21	PTI	21	EUG-ALY	UP	Meet 11, Control Point, Shedd
517	VAN	62	DSR	9	DCS	8	TAC-XNI	ST	Restrictive signal(s) from unknown cause Held to restricted speed when signal aspect was clear, Restricting, Milepost, 19.7, 21.4
518	VAC	No OS Rpt	PTI	37	CON	34	VAN-VAN	BN	Hold for buses that departed out of PDX
519	SEA	29	PTI	22	PTI	22	STW-EVR	BN	Meet Dispatcher had 519 pull behind freight train at English . 518 pass by then 519 shove move out back to main track., 518, Milepost, 46.2, 46.2
58	CHI	64	FTI	88	FTI	51	FTN-CDL	CC	Hold behind CN2720 for AMTK 59 to head south then shove back to continue north CN2720, Siding, wetuag
59	NOL	49	DSR	79	DCS	39	CHI-CHI	AM	Replacement engine wye move delayed due to signal outage at 21st street leading to late release and late departure, Other,
8	CHI	266	FTI	198	ENG	56	SPK-SPK	BN	Pick up rescue locomotive due to mechanical failure 312

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	24	DSR	36	DSR	28	GLE-FTW	BN	Per bulletin Milepost, 401.0, 400.2, 25, main, Milepost, 396.3, 396.2, 30, main, Milepost, 394.1, 393.5, 30, main, Milepost, 389.7, 389.0, 25, main, Milepost, 385.5, 385.3, 30, main, Milepost, 383.8, 385.3, 30, main, Milepost, 371.5, 371.4, 50, main, Milepost, 357.6, 357.3, 29, main2, Milepost, 355.
329	MKE	19	CTI	13	CTI	13	XWA-GLN	ME	Meet Stopped at Morton Grove on #1, freight was over on #2. Waited for 2104 to crossover 1-2 in front of us , then proceeded, Metra, 2104, Control Point, Morton Grove
341	MKE	18	CTI	15	CTI	13	XWA-GLN	ME	Follow metra, Control Point, Mayfair
350	PNT	41	PTI	32	CAR	20	HMI-XPI	NS	Air / Brake / Wheel 800043, Hose came apart and caused emergency application
351	CHI	20	DSR	35	DSR	22	TRM-ROY	CC	Per bulletin Milepost, 17.4, 17.1, 25, 1, Milepost, 17.1, 13.9, 10, 1
354	PNT	46	DSR	63	DSR	20	ROY-TRM	CC	Per bulletin Milepost, 13.9, 16.3, 10, MAIN ONE, Milepost, 14.63, 17.1, 10, MAIN ONE
355	CHI	82	ITI	43	ITI	43	PNT-PNT	CC	Service, turn, or wye train 350, Inbound AMT 350 needed wyeed. Crew expired for hours of service on main. Crew of 355 had to get cabled and bring train back to PNT.
572	SAN	19	DCS	16	DCS	11	X98-OSD	SN	Restrictive signal(s) from unknown cause Approach, Control Point, Inter 211
584	SAN	34	DCS	26	DCS	26	X98-OSD	SN	CTC system failure Line 2 dual control switches by hand/Restricted Speed., Control Point, Mesa
587	LAX	47	ITI	25	ITI	25	SAN-SAN	SN	Service, turn, or wye train 774, Equipment change with late bound 774.
588	SAN	21	PTI	24	PTI	24	SNC-SNP	SC	Meet 591, Control Point, snc
591	LAX	23	DCS	24	DCS	24	OSD-X98	SN	Power switch failure Hand throw CP Mesa and double check electric lock-timer switch near CP Stuart, Control Point, Mesa
593	LAX	24	FTI	30	FTI	20	OSD-X98	SN	Meet manifest, bnsf8259, Control Point, songs
595	LAX	18	FTI	27	FTI	22	OSD-X98	SN	Meet Control Point, shell, bn 8259
761	GTA	74	CAR	71	CAR	49	OLT-SOL	SN	Air / Brake / Wheel 6406, MR dropping took hoses apart changed gladhand rings and dumped air. Able to hold MR air
765	SLO	138	CTI	115	CTI	115	VNC-VNC	SC	Blocked from station track Metrolink, 108, Other, Van Nuys Station

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
769	GTA	31	CTI	27	PTI	14	OXN-VEC	UP	Meet 782, Control Point, North Ventura
774	SAN	121	CTI	65	CTI	35	SIM-SIM	SC	Blocked from station track Metrolink broke down cwt holding at sim valley, metrolink, Other, simi station
785	GTA	57	CTI	28	SYS	22	SAN-SAN	SN	PTC- IETMS incorrect consist Control Point, ash
786	SAN	19	DCS	21	RTE	18	X98-OSD	SN	Line manual or spring switch Control Point, mesa
790	SAN	33	PTI	22	PTI	22	CPN-VEC	UP	Meet 777, Control Point, South Seacliff
703	SAC	No OS Rpt	POL	125	POL	125	COC-COC	BN	RR blocked by trespasser or vehicle strike by another train AMT 716, trespasser strike at HNF
704	BFD	27	POL	28	POL	28	HNF-HNF	BN	RR blocked by trespasser or vehicle strike by another train
714	BFD	18	FTI	19	SYS	8	MCD-MCD	BN	PTC problem or failure (cause unknown) Engineer's PTC login needed to be corrected. PTC login was resolved., Other, Merced Station
715	OKJ	25	PTI	33	PTI	11	EMY-OKJ	UP	Wait for station track AMTK 542, Control Point, King st
716	BFD	No OS Rpt	SYS	239	SYS	237	HNF-COC	BN	Re-crew / job briefing Re-crew after trespasser strike, Other, Hanford station
718	BFD	41	ITI	49	ITI	49	EMY-EMY	UP	Service, turn, or wye train 715
719	OKJ	27	CON	31	CON	31	BFD-BFD	BN	Hold for bus with passengers from train Held for multiple thruway buses.
4	CHI	176	FTI	153	ENG	84	ABQ-ABQ	NM	B/O AC on AMTK 138. Flat switched at ABQ to put AMTK 147 in lead. 138
1	LAX	288	ENG	185	ITI	142	NOL-NOL	AM	Late release from mechanical 1
21	SAS	180	FTI	196	ITI	73	CHI-CHI	AM	Service, turn, or wye train 22
22	CHI	358	FTI	218	ITI	192	SAS-SAS	UP	Service, turn, or wye train 21, Train 21 and 2 both arrived late. Rear Sleeper and coach removed from train 2 attached to Amtrak 22. Mechanical inspection. Cnoc sent out a notification saying train won't depart till 10am. Waited until 10 to depart

Amtrak Endpoint OTP Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
300	CHI	25	FTI	19	DTR	16	STL-XWR	TR	Traveled via Highline Went into Emergency at North Market street due to PTC because of loss of power at interlocked ClassII and running air brake test performed Notified CNOC Control Point, North Market St, STL, XWR
393	CDL	16	DSR	26	CTI	7	XCS-HMW	CC	Per Schedule South Shore, Control Point, Kensington
318	CHI	33	WTR	31	WTR	13	JEF-HEM	UP	Heat order Milepost w/Letters, JEF, hem
319	KCY	57	SVS	36	SVS	36	STL-STL	TR	Fuel

Amtrak Initial Terminal Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/10/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	95	08/10	12	12	Traction motor, 616 EX ES
BRK	684	08/10	1		
GFD	425	08/10	(Trn Cxld)		Downed Trees
NHV	125	08/10	3	3	Hold for thruway bus
NHV	141	08/10	11	11	Hold for bus with passengers from train
NHV	474	08/10	8	4	High passenger count, heavy boarding - per district G -
NHV	474	08/10	8	4	Hold for connecting train
NYP	43	08/10	4	4	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	49	08/10	7	7	Dispatcher hold, Other, LOOPS, HELD ON LOOPS A/C "A" TRK OCCUPIED WITH A TRANSIT TRAIN AND "A" TRK IS THE ONLY TRACK TO HOLD 12 CARS
NYP	63	08/10	23	23	HEP, 92, LATE F/SSYD UNSPECIFIED PROBLEM WITH ENG.92
NYP	69	08/10	4	4	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	89	08/10	2	2	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD A/C CATERING
NYP	111	08/10	19	19	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING FROM SSYD
NYP	113	08/10	10	10	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	181	08/10	9	9	Routine inspections, LATE SERVICING IN SSYD
NYP	183	08/10	17	17	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY OBS
NYP	243	08/10	3	3	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	291	08/10	22	22	Hold for connecting train, HELD FOR PSNGRS OFF AM93
NYP	2123	08/10	2	2	Passenger and/or baggage, BOARDING
PHL	601	08/10	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RGH	73	08/10	5	5	Meet #Amt40, Control Point, Boylan
WAS	84	08/10	2	2	Service, turn, or wye train, 113, ARRIVED LATE
WAS	172	08/10	2	2	Set out defective car, N/A, NE'Y TO UPDATE THE 1173 FROM 10 CARS TO 9 CARS
CHI	5	08/10	77	77	Late arrival of locomotives 45, 193
MKE	332	08/10	4	4	Service, turn, or wye train 329

Amtrak Initial Terminal Details

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/10/2026

Terminal	Train	Date	Late	Delay	Cause
PNT	355	08/10	43	43	Service, turn, or wye train 350, Inbound AMT 350 needed wyed. Crew expired for hours of service on main. Crew of 355 had to get cabbed and bring train back to PNT.
BFD	701	08/10	8	8	Leaving off lead 1 instead of normal lead 2 track waiting for signal
BFD	703	08/10	21	21	Hold for thruway bus
BFD	719	08/10	31	31	Hold for bus with passengers from train Held for multiple thruway buses.
GTA	770	08/10	12	11	Air / Brake / Wheel 6905, Issue with trapped air through consist, not able to get full application of set air. Had GTA Mech assist
LAX	4	08/10	(Trn Cxld)		Freight Derailment
LAX	580	08/10	7	7	Planned set out / pick out of locomotives, cars or section of train + CDTX 2118 to consist., Control Point, terminal
OKJ	520	08/10	(Trn Cxld)		Third Party Engine Failure
OKJ	712	08/10	4	4	PTC - Initializing PTC (no failure) Other, Oakland Station
OKJ	714	08/10	4	4	Door C8303, Doors were opened on both sides of A-end doors.
OKJ	718	08/10	12	6	Meet 715, Control Point, magnolia
OKJ	718	08/10	12	6	Meet 545, Milepost, 7.0, 7.0
PDX	503	08/10	45		
PDX	507	08/10	20	20	Hold for thruway bus
SAC	539	08/10	8	8	Service, turn, or wye train 526, Water the loco 2009
SAC	551	08/10	2	2	Wheelchair 2 pax with motorized wheelchair
SAC	704	08/10	1	1	Door C9307, Door unable to trainline/ need to turn on car door override
SAN	587	08/10	25	25	Service, turn, or wye train 774, Equipment change with late bound 774.
SAN	595	08/10	1	1	Restrictive signal(s) from unknown cause Wheels rolled, Red, Control Point, beech
SAN	785	08/10	22	22	PTC- IETMS incorrect consist Control Point, ash
SLO	794	08/10	46	46	Service, turn, or wye train 765, 765 arrived at 16:55
VAN	506	08/10	15	15	High passenger count
VAN	518	08/10	34	34	Hold for buses that departed out of PDX

Eastern Region

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.3	98.9	94.8	342	6
CDOT	95.0	90.0	89.7	92.4	20	2
MARC	95.0	79.3	81.4	90.2	52	12
SEPTA	95.0	95.8	93.5	91.5	214	9
NJT-NED	95.0	97.1	91.0	88.6	350	10
NJT-SED	95.0	100.0	99.0	97.2	12	0

Operating Highlights

Train 478(10) - New Haven, CT - Hold for Connection

10AUG26: Train 478(10) was delayed at its initial terminal at New Haven Station due to being held for connections on late arriving train 178(10).

Train	Delay	Comment
478(10)	40"	

Train 53(10) - South of Richmond, VA - Weather

10AUG26: Train 53(10) was delayed on the CSX North End Subdivision between MP 25.9 and MP 72 due to high winds warnings.

Train	Delay	Comment
53(10)	30"	

Train 171(10) - Washington, DC - Engine Failure

10AUG26: Train 171(10) was delayed at Washington Union Terminal due to PTC-IETMS and Hot Journal faults. The motor was recycled to clear the faults.

Train	Delay	Comment
171(10)	30"	

Train 2160(10) - New York Penn Station, NY - Engine Failure

10AUG26: Train 2160(10) was delayed at New York Penn Station due to multiple unrecoverable faults. The train departed and then was shoved back into the station where the crew deprepared and reconfigured the pantograph. These actions cleared the faults and Train 2160(10) was permitted to continue east.

Train	Delay	Comment
2160(10)	1'16"	

Train 76(10) - West of Burlington, NC - Signal

10AUG26: Train 76(10) was delayed on the Norfolk Southern Danville/ Goldsboro-Greensboro Subdivision between MP 0.5 and MP 23.3 due to bad signals attributed to an unknown cause.

Train	Delay	Comment
76(10)	60"	

Train 179(10) - South of Boston, MA - Engine Failure

10AUG26: Train 179(10) was delayed on the Amtrak New Haven to Boston Line at MP 225.5 due to an unknown issue with E/619 (at the time of this writing). The crew requested protection on the adjacent track so the engine could be inspected. The crew also consulted with RFE Mingione. The issue was seemingly resolved and the train continued west.

Train	Delay	Comment
179(10)	39"	

Train 40(09) - Washington, DC - Miscellaneous Amtrak Responsible

10AUG26: Due to multiple delays en route to Washington, DC, multiple passengers missed connections and required overnight lodging. This WBS was generated as a result.

WBS#: B.TR.100151.0838

Train 178(10) - South of Baltimore, MD - Debris Strike

10AUG26: Train 178(10) with E/616, plus 9 cars, carrying 424 passengers struck debris at MP 100.0 on the Amtrak PW Line. Main reservoir was lost on E/616. The Engineer was able to recycle and recover.

Train	Delay	Comment
178(10)	25"	
2162(10)	30"	

Train 68(10) South of St-Lambert, QC - Heat Orders/Weather

10AUG26: Train 68(10) with E/112 and 5 cars was delayed on the CN Rouses Point subdivision due to heat orders from MP 42.0 to MP 0.2.

Train	Delay	Comment
68(10)	41"	

Train 80(10) South of Raleigh, NC - Switch Issues/Signal

10AUG26: Train 80(10) with E/121 and 7 cars was delayed on the NS Goldsboro-Greensboro subdivision due to switch issues at MP 85.4. Train 40(09) with E/78, E/82 and 10 cars was also delayed due to the same issues. Which made it necessary for both trains to hand throw switches and get permission pass the stop signals.

Train	Delay	Comment
40(09)	30"	
80(10)	20"	

CSX Heat Orders - Weather

10AUG26: Multiple trains are affected by weather CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Baltimore Terminal, Capital, Cumberland, Keystone, Metropolitan, New River, North End, Old Main Line, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(10)	55"	
98(10)	48"	
186(10)	23"	
125(10)	24"	
53(10)	18"	
79(10)	1'05"	
138(10)	14"	
80(10)	31"	
95(10)	10"	
52(10)	09"	
89(10)	58"	
41(09)	45"	
40(09)	40"	
97(09)	27"	

Train 280(10) North of Buffalo, NY - Freight Train Interference

10AUG26: Train 280(100 with E/97 and 5 cars was delayed on the CSX Buffalo Terminal at MP 394.0 due to meeting CSX 151.

Train	Delay	Comment
280(10)	40"	

Train 425(10) Springfield, MA - Down Tree/Weather

10AUG26: Train 425(10) was cancelled due to DH Train 5552(10) being unable to get into position. The route for Train 5552(10) was blocked by downed trees across the CSX diamond. Bussing was secured for the 4 passengers.

WBS#: B.TR.100151.0837

Train	Delay	Comment
425(10)	Cancelled	Bussing Secured

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

25-F91-00670 00000008688 "UNCLASSIFIED" 1/1/2019

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00671a 00000008699 UNCLASSIFIED 19/2/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Western Region

Operating Highlights

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train 518(10) North of Bellingham, WA - Engine Failure

11AUG26: Train 518(10), operating with locomotive WS1405 and 13 cars, was delayed north of Bellingham, WA, at MP 116.6 on the BNSF Bellingham Subdivision due to a smoke detector fault in the locomotive cab. The crew worked with the CNOC Mechanical Desk to assess the condition and isolate the affected system. Once the system was cut out in accordance with operating procedures, the train resumed its trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518(10)	34"	

Train 7/27(09) East of East Glacier Park, MT - M of W Work

10AUG26: Train 7/27(09), with 188 customers onboard, was delayed at Blackfoot/MP1116.4, 22 miles east of East Glacier Park, MT/MP1138.1, on the BNSF Hi Line subdivision holding for a Maintenance of Way crew to release the tracks ahead. Once the route was clear, train 7/27(09) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(09)	1'09"	

Train 11(10) Albany, OR - Freight Train Interference

10AUG26: Train 11(10), carrying 207 customers onboard, was delayed north of Albany, OR, at Hallawell (MP 687.5) on the Union Pacific Brooklyn Subdivision while meeting UP 9061. Once the meet was completed, the train continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(10)	30"	

Train 719(10) Bakersfield, CA - Hold for Connection

10AUG26: Train 719(10) was delayed departing Bakersfield, CA, while awaiting the arrival of multiple late inbound bus connections. The buses were delayed due to a local highway traffic accident, impacting customer transfers to the train. Once all connecting customers arrived and boarded, Train 719(10) departed with 180 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(10)	31"	

Train 716(10) East of Hanford, CA - Trespasser Incident

10AUG26: At approximately 10:07 PM, Train 716(10), carrying 71 customers onboard and operating with CC/C8306, five cars, and locomotive C2102, fatally struck a trespasser east of Hanford, CA, at MP 967.2 on the BNSF Bakersfield Subdivision in Hanford, Kings County, California. The incident occurred at the West 4th Street Crossing (DOT #028421T), a public grade crossing equipped with advance warning signs, pavement markings, and functioning crossing gates. Emergency responders, including local fire and medical personnel, Amtrak Police, BNSF Police, and an Amtrak Road Foreman, responded to the scene. Weather conditions at the time were reported as approximately 86°F and clear, and head-end power remained operational throughout the incident. Following the arrival of the Coroner and completion of all required investigative activities, the train was released. Train 716(10) then shoved back to the Hanford Station platform, where customers transferred to Train 704(10) for continued travel to Bakersfield. The equipment remained at Hanford until a relief engineer arrived, after which the train continued toward Bakersfield.

Train 703(10), carrying 56 customers onboard, was delayed at Corcoran, CA, while awaiting the release of the affected territory. Once the investigation was completed and the tracks were reopened, the train resumed its trip.

National Response Center Number: 1470367

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(10)	2'24"	
716(10)	3'57"	
704(10)	32"	
718(10)	38"	follow 716(10)

Train 6(10) East of Reno, NV - Heat Orders

10AUG26: Train 6(10), with 160 customers onboard, was delayed at Massie siding/MP292.0, 51 miles east of Reno, NV/MP240.7, on the UP Nevada subdivision operating under heat orders. Once the orders expired, train 6(10) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(10)	46"	

Train 4(09) East of Las Vegas, NM - High Wind Warnings

10AUG26: Train 4(09), with 109 customers onboard, was delayed between mile post 721.0 and mile post 699.0, beginning 49 miles east of Las Vegas, NM/MP770.1, on the BNSF Raton subdivision following high wind warnings. Once clear of the affected area, train 4(09) continued east at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(09)	57"	

Train 19(09) Meridian, MS - Debris Fire

10AUG26: Train 19(09), with engines 328 and 164, 8 cars, and 74 customers onboard, was delayed at Meridian, MS/MP295.0, on the NS AGS South subdivision due to smoke conditions on car 62032. The local fire department was called to spray the equipment and put out the fire. Train 19(09) departed Meridian and upon arrival at Hattiesburg, the crew found smoldering debris in the wheel wells on the other side of car 62032. The local fire department responded and put out the fire. After completing station work at Hattiesburg, train 19(09) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(09)	51"	

Train 355(10) Pontiac, MI - Initial Terminal Delay

10AUG26: Train 355(10) with E/104600, five cars, and 18 customers was delayed departing Pontiac due to setting out private C/800043 from train 350(10). Train 350(10) arrived Pontiac at 302PM-ET, 41 minutes late and the crew was up on hours of service at 443PM-ET while cutting off the private car and turning the equipment. The CN required the private car to be set out on track 26, which prolonged the set out. The outbound crew was vanned to track 26 to bring the equipment over to the station. Once the equipment was set in the station, the customers were welcomed aboard, and 355(10) departed Pontiac at 5:46PM ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(10)	43"	

Train 5(10) Chicago, IL - Initial Terminal Delay

10AUG26: Train 5(10) with E/45-193, nine cars, and 210 customers was delayed departing Chicago due to the late release of locomotive power. Once the power and the equipment were released and set in the station, the customers were welcomed aboard, and 5(10) departed Chicago at 317PM-CT, 1 hour, and 17 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(10)	1'17"	

Train 765(10) Van Nuys, CA - Disabled Train Ahead

10AUG26: Train 765(10) was delayed west of Van Nuys, California, on the SCRRA/Metrolink Ventura Subdivision after Metrolink Train ML108 became disabled at MP 253 on the single main track, blocking all rail traffic. While awaiting rescue equipment for the disabled train, Train 765(10) was required to shove back into Van Nuys Station. Upon arrival of the rescue equipment, crews discovered a broken brake pipe on ML108, which extended the delay while repairs were completed. Following successful repairs to the disabled Metrolink train, Train 765(10) was able to proceed and resume normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(10)	1'22"	Single main blocked
774(10)	35"	Single main blocked
765(10)	1'55"	Single main blocked
14(10)	32"	follow 765
794(10)	46"	late turn of 765(10)

Train 319(10) St. Louis, MO - Fueling

10AUG26: Train 319(10), with 152 customers onboard, was delayed at St Louis, MO/MP1.5 on the TRRA Merchants subdivision fueling the engine IDTX4624. Once completed, train 319(10) departed St Louis, MO.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(10)	36"	

Train 24(10) East of Pascagoula, MS - Freight Train Interference

10AUG26: Train 24(10) with 41 customers was delayed on the CSX NO&M subdivision starting 10 miles east of Pascagoula between MP 696.9 and MP 666.6 due to following CSX 606.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(10)	58"	

Train 7/27(09) Minot, ND - System

10AUG26: Train 7/27(09) with 195 customers was delayed on the BNSF KO subdivision at Minot/MP 203.3 due to the crew signing up at 957AM-CT. Once the crew signed up and briefed, 7/27(09) departed Minot at 1029AM-CT, 38 minutes late.

Train	Delay	Comment
7/27(09)	38"	

Train 2/422(09) East of Maricopa, AZ - Freight Train Interference

10AUG26: Train 2/422(09) with 196 customers was delayed on the UPRR Gila subdivision starting 42 miles east of Maricopa between MP 940.0 and MP 948.0 due to following ZLBHO-09. Additional delay was accumulated following AMLEG-09 between Rillito/MP 965.7 and Tucson/MP 983.9.

Train	Delay	Comment
2/422(09)	25"	ZLBHO-09
2/422(09)	20"	AMLEG-09

Train 51(09) Dyer, IN - Trespasser Incident

10AUG26: Train 51(09) with 139 customers was delayed on the CSX Monon subdivision eight miles south of Dyer due to a tractor trailer stuck on the tracks at MP 36.4. Once the tractor trailer was removed and the tracks were inspected, 51(09) continued to Dyer.

Train	Delay	Comment
51(09)	1'26"	

Train 520(10) Oakland, CA - Third Party Contractor Engine Failure

10AUG26: Train 520(10) was canceled in its entirety from Oakland, California, due to a HEP (Head End Power) motor failure on locomotive C2103. As a result of the equipment shortage created by the cancellation, Train 535(10) was subsequently canceled from Sacramento, California, to balance equipment and maintain operational requirements across the service.

Train	Delay	Comment
520(10)	Canceled	
535(10)	Canceled	

Train 40(08) East of Chicago, IL - Freight Train Interference

10AUG26: Train 40(08) with 197 customers was delayed on the NS Chicago district 23 miles east of Chicago at CP 502 due to meeting unknown freight. Train 49/449(09) was delayed following.

Train	Delay	Comment
40(08)	33"	
49/449(09)	33"	

Train 5(08) Salt Lake City, UT - Freight Train Interference

10AUG26: Train 5(08), 26-FOI-00671 00000008699 UNCLASSIFIED 9/2/2026, was delayed approximately 16 miles west of Salt Lake City, Utah, on the UPRR Shafter Subdivision. The train initially lost time while operating behind Train 6(09) and later followed freight train UP7626 between MP 799 and MP 771. Additional delay was incurred when Train 5(08) encountered opposing freight traffic, UP7312, at Shafter Siding near MP 767, resulting in further operating delays.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(08)	16"	6(09)
5(08)	39"	UP7625
5(08)	39"	UP7312

Train 761(10) West of San Diego, CA - Engine Failure

10AUG26: Train 761(10), led by C2122, was delayed at San Diego Old Town Station at MP253.2 on the SCRRA/Metrolink San Diego Subdivision after experiencing air system issues in coach 6406. According to NCTD, the crew believed the problem had been corrected while stopped at Old Town Station; however, after departing, the air issues persisted. The train subsequently stopped on the grade near Miramar Yard, blocking the main track while the crew coordinated with San Diego Mechanical. Mechanical personnel responded to the scene and successfully troubleshot the issue, allowing Train 761(10) to resume normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
761(10)	12"	at San Diego Old Town
761(10)	49"	OLT-SOL

Train 21/421(09) North of Little Rock, AR - Passenger Train Interference

10AUG26: Train 21/421(09) with 119 customers was delayed on the UPRR Little Rock subdivision one mile north of Little Rock at Locust Street/MP 344.3 due to meeting train 22(09)/422(07).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(09)	46"	

Train 6(10) Service Recovery

10AUG26: rain 6(04), E/40-E/179 & 9 cars, reported the 6th car, diner C/38041 has broken refrigerators prior to departure from Emeryville, CA. This car was bad ordered inline for entirety of trip to Chicago, IL. As enroute service recovery- Sleepers customers received modified meals for breakfast, lunch, and dinner.

B.TR.100150.7018

WBS#: B.TR.100150.7018

Train 21/421(09) North of Walnut Ridge, AR - Freight Train Interference

10AUG26: Train 21/421(09) with 105 customers was delayed on the UPRR Hoxie subdivision 25 miles north of Walnut Ridge due to meeting UP 6922 at Knobel/MP 200.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(09)	36"	

Train 22(09)/422(07) South of Texarkana, AR - Freight Train Interference

10AUG26: Train 22(09)/422(07) 00000008699 191 "UNCLASSIFIED" was delayed on the UPRR Little Rock subdivision starting 16 miles south of Texarkana between Springdale/MP 15.5 and Texarkana/MP 0.0 due to following UP 6906.

Train	Delay	Comment
22(09)/422(07)	30"	

Train 794(10) South of Lompoc-Surf, CA UP Santa Barbara Subdivision - Loss of Shunt

10AUG26: Union Pacific Railroad advised that train 794(10) operating with CC/6904, C/6410, C/6400, C/6300, C/6800, C/34039, and E/C2113 experienced a loss of shunt on August 10th, 2026, at 5:22:52PM PST. This occurred south of Lompoc-Surf station at MP 299.94 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 32 seconds. UPRR signal department was notified, and shunt testing will be performed.

Train 5(09) East of Helper, UT - Broken Parking Brake Line

10AUG26: Train 5(09), operating with locomotives E/25 and E/48, nine cars, and 161 customers onboard, was delayed approximately 23 miles east of Helper, UT, at Mounds (MP 603.7) on the Union Pacific Green River Subdivision due to a sticking parking brake on lead locomotive E/25. The crew worked with the CNOC Mechanical Desk to troubleshoot the issue and initially implemented a temporary repair to a brake line; however, the corrective action was unsuccessful. With assistance from Union Pacific personnel and the crew of a passing coal train, a pipe wrench was obtained and used to release the stuck parking brake, allowing the train to resume movement. After continuing eastward, the train stopped again at Wash (MP 611.3) on the Union Pacific Green River Subdivision when the parking brake issue reoccurred. Additional troubleshooting efforts, including assistance from a Union Pacific Track Inspector, were unsuccessful in restoring the locomotive to service. As a result, a decision was made to move the train to Wellington Siding (MP 612.4) and set out locomotive E/25. A replacement freight locomotive UP 4292 was subsequently sourced downline to be added at Sparks.

Train	Delay	Comment
5(09)	EST 7'00"	

East of Barstow, CA - BNSF Freight Train Derailment

10AUG26: At approximately 6:45 PM, BNSF freight train S-LPCLBT1-07N, led by BNSF 6000W, derailed near East Siberia (MP 675.7) on the BNSF Needles Subdivision, approximately 69 miles east of Barstow, CA. Reports indicated that 35 railcars had overturned, blocking both Main Track 1 and Main Track 2. BNSF established an initial estimated track reopening time of approximately 24 hours while recovery and repair operations were undertaken.

As a result of the derailment and extended track outage, the following service adjustments were implemented:

- Train 4(10) was canceled between Los Angeles, CA, and Albuquerque, NM. No alternate transportation was provided.
- Train 3(09), which had already departed Albuquerque, NM, was turned at Baca (MP 114) on the BNSF Seligman Subdivision and returned to Albuquerque, where the train was terminated.
- Two buses were secured to transport Train 3(09) customers from Albuquerque, NM, to Needles, CA.
- Upon arrival in Needles, CA, passengers transferred to an additional two buses for onward transportation to Los Angeles, CA.

WBS#: B.TR.100150.7022

Train	Delay	Comment
4(10)	Cancel	LAX-ABQ
3(09)	Term	ABQ

Train 744(09) Davis, CA - Third Party Contractor Engine Failure

10AUG26: Train 744(09) originally departed San Jose, CA, operating with CC/C6964, four cars, and locomotive JPBX921. After the cab car was damaged east of Berkeley by a rock thrown at the train, the equipment was returned to the Oakland Maintenance Facility, where it was exchanged for a consist operating with CC/C8311, four cars, and locomotive C2009. After returning to service, Train 744(09) experienced a second mechanical issue when locomotive C2009 lost traction effort while approaching Davis, CA. The crew worked with mechanical personnel to troubleshoot the locomotive; however, a reset attempt was unsuccessful, and the locomotive could not be restarted. This was the same issue that presented itself earlier in the day's services and caused the cancelation of trains 743(09) and 742(09). To recover service, Train 748(09) was routed to couple onto the disabled Train 744(09) equipment at Davis and operate as a combined consist to Sacramento. Upon arrival in Sacramento, the Train 748(09) section was separated and utilized to operate Train 744(09) onward to Auburn, CA, while the disabled equipment was removed from service for further mechanical attention in Sacramento.

Train	Delay	Comment
744(09)	1'23"	
748(09)	54"	
14(09)	34"	

Train 8/28(08) Spokane, WA - Engine Failure

09AUG26: Train 8/28(08) FDI-00670 00000008699 with "UNCLASSIFIED" 5/2/2026 and E/171 and 10 cars, was delayed in Spokane, WA, after mechanical personnel identified a bad-ordered traction motor on locomotive E/312. Initial inspection indicated possible strike damage, resulting in the loss of gear oil from the traction motor assembly. A decision was made to set out the locomotive and secure a replacement unit from BNSF. BNSF locomotive 8269 was subsequently identified for lease and dispatched to the train to allow operations to continue.

WBS#: B.TR.100150.7020

Train	Delay	Comment
8/28(08)	56"	set out E/312
8/28(08)	09"	Operating w/Freight SPK-SBY
8/28(08)	51"	Operating w/Freight SBY-MOT
8/28(08)	12"	Operating w/Freight SBY-HAV
8/28(08)	4"	Operating w/Freight GGW-WPT
8/28(08)	5"	Operating w/Freight HAV-MAL
8/28(08)	12"	Operating w/Freight WPT-WTN
8/28(08)	5"	Operating w/Freight WTN-STN
8/28(08)	7"	Operating w/Freight MAL-GGW
8/28(08)	6"	Operating w/Freight STN-MOT
8/28(08)	28"	Operating with freight MOT-WIN

Gold Runner Service - Equipment Servicing/ Repair Issues

07AUG26: Train 712(07), CC/C8306-5 cars- E/C2102, was delayed departing Oakland, CA due to a late release from mechanical. Equipment arrived into the maintenance facility at 7:28P-PT on August 6th from Train 715(06). With the equipment still not fully serviced, at 10:00A-PT, mechanical estimated another twenty minutes were needed for servicing the equipment. Once equipment was serviced, it departed the maintenance facility at 11:14A-PT en route to Oakland Station for boarding. Once all customers were boarded, Train 712(07) was able to depart at 11:29A-PT.

Train 714(07), E/C2013-8 cars-E/C2014, was delayed departing Oakland, CA due to the late turn of equipment arriving on Train 711(07). The equipment, E/C2012-6 cars-CC/C6962, arrived to the maintenance facility from Train 719(06) at 11:05P-PT on August 6th and was not ready for departure. To avoid a lengthy delay, the inbound Train 711(07) equipment was turned for Train 714(07). Once Train 711(07) arrived into the maintenance facility at 11:30A-PT the equipment was serviced and fueled and it departed at 12:47P-PT for Oakland station for boarding. Once all customers were on board, Train 714(07) departed at 12:59P-PT.

Train 532(07) was delayed departing Oakland, CA due to the congestion in the yard from the Gold Runner service being serviced. Once Train 714(07) cleared yard and worked the Oakland station, the crew on Train 532(07) was able to head to station for boarding.

Train 716(07), CC/C8309-8 cars-E/C2012, was delayed departing Oakland, CA due to a late release from mechanical. At 2:00P-PT, mechanical estimated another thirty minutes were needed for servicing the equipment. The train was released and departed the yard at 500P-PT. After arriving at the station, crew was unable to log into PTC causing further delay. Due to the extended delay, and closing in on the departure time for Train 718, the decision was made to cancel Train 716(07) and deadhead the equipment to Bakersfield. The Union Pacific dispatcher did not receive the information in time and allowed 716(07) to depart Oakland as soon as they were able to initialize PTC. Train 716(07) was then terminated at Emeryville, where all passengers detrained and were accommodated on train 718(07).

Train 718(07) was then delayed departing Oakland, CA due to trains 542, 715, 716 and 545(07) all arriving causing congestion.

08AUG26: Train 712(08), CC/C8314-7 cars-E/C2004, was delayed departing Oakland, CA due to a late release from mechanical. The original equipment, CC/C8312-7 cars-E/C2005, arrived into the maintenance facility from Train 719(07) at 10:27P-PT on August 7th. At 9:55A-PT, mechanical was still working on restroom issues on CC/C8212, as well as

inspections. At 11:27A-PT, mechanical released the equipment to the crew where they performed their necessary inspections and departed the yard at 11:44A-PT to take equipment to station for boarding. Once all customers where boarded, Train 712(08) departed at 11:567A-PT 26-FOI-00671 00000008699 "UNCLASSIFIED" 9/2/2026

Train 714(08), CC/C8312-7 cars-E/C2005, was delayed departing Oakland, CA due to mechanical resolving restroom issues on CC/C8312. The equipment was moved to Train 714(08) from Train 712(08) to give more time for repairs to be made. Once mechanical released the equipment at 12:17P-PT, the crew performed their necessary tests and departed the yard for the station. Once all customers were boarded, Train 714(08) departed at 12:50P-PT.

09AUG26: Train 716(09) was delayed due to an equipment reassignment at Oakland Jack London Square, CA. The train was originally scheduled to operate using the inbound Train 711(09) consist with locomotive E/C2012 and eight cars; however, locomotive E/C2012 required repairs to a shock absorber. To expedite service, a decision was made to utilize the inbound Train 713(09) equipment for Train 716(09). As part of the operating plan, Train 713(09) was terminated at Emeryville, CA, and Train 716(09) originated from Emeryville using the reassigned equipment. Customers traveling between Oakland Jack London Square and Emeryville were accommodated using existing Capitol Corridor service. Because Train 713(09) was scheduled to turn for Train 718(09), the equipment reassignment also affected the operation of Train 718(09). To maintain service, equipment from inbound Train 715(09) was utilized for Train 718(09). As part of this adjustment, Train 715(09) was terminated at Emeryville and Train 718(09) originated there. Customers traveling between Oakland Jack London Square and Emeryville were accommodated using Capitol Corridor service and Bus 6613.

WBS#: B.TR.100150.7012

Train	Delay	Comment
712(07)	1'11"	
714(07)	41"	
532(07)	18"	yard congestion
716(07)	3'07"	Terminated EMY
716(07)	37"	OKJ- PTC
718(07)	40"	
714(08)	32"	ITD OKJ
712(08)	1'39"	ITD OKJ
703(08)	1'02"	late turn 712(08)
716(09)	2'34"	ORIG EMY
715(09)	TERM EMY	
713(09)	TERM EMY	
718(09)	49"	ORIG EMY

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG:

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids

Chicago.

- Train 370(16) cancelled entirely - sourcing alternate.
- Train 371(17) cancelled entirely - 3 alternate buses secured between Grand Rapids and

Chicago.

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

- Train 370(20) cancelled entirely - sourcing alternate.
- Train 371(21) cancelled entirely - 3 alternate buses secured between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely - with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(15) cancelled entirely - sourcing alternate.
- Train 355(15) cancelled entirely - sourcing alternate.
- Train 350(18) cancelled entirely - sourcing alternate.
- Train 355(18) cancelled entirely - sourcing alternate.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 382(10) cancelled entirely, with 2 alternate buses secured between Quincy, IL and Chicago IL.
- Train 381(14) cancelled entirely, - sourcing alternate.
- Train 382(14) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.

Saluki/Illini Service

- Train 391(12) cancelled entirely - with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(12) cancelled entirely, with 2 alternate buses secured between Carbondale, IL and Chicago, IL.
- Train 391(19) cancelled entirely - sourcing alternate.
- Train 392(19) cancelled entirely, with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

Train 507(02) East of Portland, OR - Warehouse Fire

regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04-10) Cancelled entirely, No alternate Transportation.
- Train 502 (04-10) Cancelled entirely. With alternate transportation.
- Train 504 (04-10) Will terminate in Portland, OR. With alternate transportation.
- Train 518 (04-07) Originates at Seattle, WA. 518 (08-10) Originates Vancouver, WA All with alternate transportation.
- Train 517 (04-10) Will terminate in Vancouver, WA. No alternate Transportation.
- Train 506 (04-10) Originates in Vancouver, WA. No alternate Transportation.
- Train 508 (04-10) Will terminate Portland, OR. With alternate transportation.
- Train 503 (04-10) Originates Portland, OR. With alternate transportation.
- Train 505 (04-07) Cancelled entirely. With alternate transportation. 505 (08-10) Will Terminate in Vancouver, WA, no alternate transportation.
- Train 507 (04-10) Originates Portland, OR. With alternate transportation.
- Train 509 (04-10) Cancelled entirely, with alternate transportation.
- Train 511 (04-10) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-08) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-10) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

505(08-10) Will terminate Vancouver, WA no alternate transportation provided.

518(08-10) Will originate Vancouver, WA no alternate transportation provided

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 14, 2026.

Amtrak Cascades

-Train 500 (04 - 14 AUG) cancelled in entirety Portland, OR to Seattle, WA with NO alternative transportation

-Train 502 (04 - 14 AUG) cancelled in entirety; alternate transportation provided Portland, OR to Seattle, WA

Replaced by bus 3502

-Train 504 (04 - 14AUG) terminates Portland, OR; alternate transportation provided Portland to Seattle, WA

Portland to Seattle section replaced by bus 3504

-Train 518 (08 - 14AUG) originates Vancouver, WA; alternate transportation provided from Portland, OR to Vancouver, WA

Portland to Vancouver, WA replaced with by bus 3518

-Train 506 (04 - 10 AUG) originates Vancouver, WA; NO alternate transportation Portland, OR to Vancouver, WA

-Train 506 (11 - 14 AUG) originates Vancouver, WA; alternate transportation provided Portland, OR to Vancouver, WA

-Train 508 (04 - 14AUG) terminates Portland, OR; alternate transportation provided Portland to Seattle, WA

Portland to Seattle section replaced by bus 3508

-Train 503 (04 - 14AUG) originates Portland, OR; alternate transportation provided Seattle, WA to Portland, OR

Seattle to Portland section replaced by bus 3503

-Train 505 (08 - 10AUG) terminates Vancouver, WA, NO alternate transportation Vancouver, WA to Portland, OR

-Train 505 (11 - 14AUG) terminates Vancouver, WA, alternate transportation provided Vancouver, WA to Portland, OR

-Train 517 (04 - 10 AUG) terminate Vancouver, WA; NO alternate transportation Vancouver, WA to Portland, OR

-Train 517 (11 - 14 AUG) terminate Vancouver, WA; alternate transportation provided Vancouver, WA to Portland, OR

-Train 507 (04 - 14 AUG) originates Portland, OR; alternate transportation provided Seattle, WA to Portland, OR

Seattle to Portland section replaced by bus 3507

Effective Tuesday 8th AUG 3507 bus to operate 1 hour earlier at 1:20pm

-Train 509 (04 - 14 AUG) cancelled in entirety; alternate transportation provided Seattle, WA to Portland, OR

Seattle to Portland section replaced by bus 3509

-Train 511 (04 - 14 AUG) cancelled in entirety Seattle, WA to Portland, OR with NO alternate transportation

Coast Starlight

-Train 14 (03 - 14 AUG) terminates Portland, OR; cancelled Portland to Seattle, WA with NO alternate transportation

-Train 11 (05 - 15 AUG) originates Portland, OR; cancelled Seattle, WA to Portland with NO alternate transportation

Empire Builder

-Train 27 (02 - 14th AUG) terminates Spokane, WA; alternate transportation provided Spokane to Portland, OR

-Train 27 (02 - 14th AUG) equipment will operate into Seattle with Train 7 for servicing/inspection

-Train 28 (04 - 16th AUG) originates Spokane, WA; alternate transportation provided Portland, OR to Spokane

-Train 28 (04 - 16th AUG) equipment will operate from Seattle to Spokane with Train 8 equipment after servicing/inspection

Train 505 Bus VAN-PDX depart VAN at 12pm
 Train 518 bus PDX-VAN depart PDX at 1:30pm
 Train 517 bus VAN-PDX depart VAN at 330pm
 Train 506 bus PDX-VAN depart PDX at 5:20pm
 28-FOR-00671 00000008699 UNCLASSIFIED 9/2/2026

WBS#: B.TR.100150.6981

Train	Delay	Comment
507(02)	1'41"	bus VAN-PDX
506(02)	Canceled	
508(02)	45"	bus PDX-VAN
509(02)	77"	couple 509-511(02)
509(02)	75"	Detour through UP yard
511(02)	76"	Detour through UP yard
500(03)	Canceled	
502(03)	Canceled	
511(03)	Canceled	
505(03)	Canceled	
518(03)	Canceled	between SEA-PDX
507(03)	Canceled	between SEA-PDX
508(03)	Term PDX	
504(03)	Term PDX	
509(03)	Canceled	
517(03)	Term VAN	
506(03)	Orig VAN	
503(03)	24"	canceled SEA-PDX
507(03)	1'10"	waiting for bus at PDX
14(02)	58"	detour
11(03)	51"	detour
14(04)	term PDX	
506(04)	1'03"	wait for inbound bus
518(04)	1'27"	wait for inbound bus
507(05)	1'09"	PDX- wait for inbound bus
507(06)	1'06"	PDX- inbound bus
503(07)	33"	PDX- inbound bus
507(07)	1'21"	PDX- inbound bus
503(08)	22"	PDX- inbound buses
503(09)	28"	bus connections
518(09)	27"	bus connections
518(10)	34"	bus connections
503(10)	45"	bus connections

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple trackwork projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		Mu issues
8 (8)	SPK	312		Blown traction motor

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (8)	SPK	BN8269	Due to E/312 being S/O in SPK	CHI	8/10/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train790(10) Passenger Removed at Camarillo, California –Passenger Removal

10AUG26, Passenger on PNR C0ACF7, traveling from Ventura, CA to Los Angeles, CA reportedly Passenger was observed attempting to sell drug paraphernalia and soliciting phone numbers from male passengers in exchange for drugs and/or other illicit activity. The passenger was removed at Moorpark Station. Amtrak Police were notified.

Delay: 790 (10)**NONE**

Consist Deviations

26-FOI-00671

00000008699

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
171 (10)	BOS	48140 split club used in place of a cafe, best available	No impact	0	48140
171 (10)	BOS	Consist operating with Club-dinette in lieu of cafe.	NONE	1279	
2165 (10)	BOS	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-accommodate all displaced passengers.	PASSENGERS NOTIFIED	505	
2165 (11)	BOS	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-accommodate all displaced passengers.	PASSENGERS NOTIFIED	422	
41 (10)	CHI	Train 41(10) has set out car 25106(BYD wheels and is due DPF). Inventory has been reduced to 3 coaches and we are -5 over capacity. When car is roadworthy we will d/h to NYP for DPF.	OVERCAPACITY	5	25106
6 (10)	EMY	train will not have diner due to (BYD) refrigeration in car 38041 which is d/h in line	PASSENGERS PROVIDED SERVICE RECOVERY	412	38041
566 (11)	LAX	NO BIKE SPACE OR WIFI	none	0	90225
584 (11)	LAX	NO BIKE SPACE OR WIFI	NONE	0	90225
284 (10)	NFL	Consist short one coach. Re-accommodate overbooked passengers.	PASSENGERS NOTIFIED	16	
97 (10)	NYP	VW II used instead of VW I sleeper on the 9711 line	PASSENGERS RELOCATED	7	62507
237 (10)	NYP	CONSIST SHORT ONE COACH. RE-ACCOMMODATE OVERBOOKED PASSENGERS.	NONE	0	
2190 (10)	NYP	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-	PASSENGERS NOTIFIED	179	

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00671 00000008699 "UNCLASSIFIED" 9/2/2026			
		accommodate all displaced passengers.			
2190 (11)	NYP	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-accommodate all displaced passengers.	PASSENGERS NOTIFIED	138	
579 (11)	SAN	NO BIKE SPACE OR WIFI	NONEQ	0	90225
595 (11)	SAN	NO BIKE SPACE OR WIFI	NONE	0	90225
2128 (10)	WAS	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-accommodate all displaced passengers.	PASSENGERS NOTIFIED	157	
2128 (11)	WAS	A schedule change has been made to reflect being Next Gen in place of legacy equipment. Please check the war reports and re-accommodate all displaced passengers.	PASSENGERS NOTIFIED	118	

Reverse Consists

Train Number	Station	Reason
95 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
093 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
113 (10)	NYP	Consist reversed Business class seat orientation may have changed At Rear
181 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front
95 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
138 (10)	NFK	Consist reversed Business class seat orientation may have changed At Front
178 (10)	RNK	Consist reversed Business class seat orientation may have changed At Front
84 (10)	WAS	Consist reversed Business class seat orientation may have changed At

Train Number	Station	Reason
		Front
136 (10)	WAS	Consist reversed Business class seat orientation may have changed At Front
198 (10)	WAS	Consist reversed Business class seat orientation may have changed At Rear
184 (10)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (11)	SPG	Consist reversed Business class seat orientation may have changed At Front
94 (11)	NFK	Consist reversed Business class seat orientation may have changed At Front
138 (11)	NFK	Consist reversed Business class seat orientation may have changed At Front
148 (10)	WAS	Consist reversed Business class seat orientation may have changed At Front
141 (11)	SPG	Consist reversed Business class seat orientation may have changed At Front