

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, September 12, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/11/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	36	88.8%	3,455	492	85.8%	103,977	14,460	86.1%
Central Division	86.0%	56	4	92.9%	631	75	88.1%	19,826	1,850	90.7%
East Division	82.0%	181	19	89.5%	1,879	216	88.5%	54,699	8,350	84.7%
West Division	86.0%	84	13	84.5%	945	201	78.7%	29,452	4,260	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00757 00000008815 UNCL ASSIFIED Endpoint Arrival Dates through 9/11/26 9/29/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	104,517	26,554	75%	1,143,896	302,356	74%	34,734,942	8,888,336	74%
Northeast Corridor	81%	47,462	9,159	81%	516,842	94,689	82%	15,231,741	3,681,971	76%
Acela	83%	11,000	1,944	82%	117,198	14,883	87%	3,079,824	774,023	75%
Northeast Regional	79%	36,462	7,215	80%	399,644	79,806	80%	12,151,917	2,907,948	76%
Richmond / Newport News / Norfolk	77%	10,617	3,287	69%	118,257	34,015	71%	3,641,056	1,081,314	70%
Springfield Shuttles	89%	870	81	91%	8,131	1,286	84%	214,533	34,424	84%
Roanoke	79%	4,033	1,086	73%	40,011	6,837	83%	1,153,814	256,531	78%
On Spine Northeast Regional	80%	20,942	2,761	87%	233,245	37,668	84%	7,142,514	1,535,679	78%
State Supported	80%	44,618	10,437	77%	496,105	140,120	72%	15,284,699	3,351,394	78%
Borealis	80%	558	0	100%	6,541	705	89%	194,530	41,176	79%
Capitol Corridor	90%	3,948	843	79%	43,184	6,337	85%	1,272,688	170,383	87%
Carolinian	70%	1,201	227	81%	12,549	4,452	65%	389,877	152,602	61%
Cascades	75%	2,783	922	67%	29,844	8,739	71%	880,480	249,393	72%
Downeaster	82%	1,673	0	100%	19,545	262	99%	539,525	62,107	88%
Empire	78%	5,879	826	86%	66,740	15,360	77%	1,908,544	470,322	75%
Adirondack	72%	345	11	97%	4,142	1,003	76%	118,237	37,956	68%
Ethan Allen Express	70%	616	164	73%	6,100	2,037	67%	193,002	74,313	61%
Maple Leaf	70%	835	24	97%	9,556	2,958	69%	237,868	92,837	61%
New York - Albany	85%	2,123	293	86%	28,742	4,635	84%	878,009	153,124	83%
New York - Niagara Falls	75%	1,452	81	94%	16,535	4,458	73%	466,927	104,967	78%
Berkshire Flyer	60%	508	253	50%	1,665	269	84%	14,501	7,125	51%
Gold Runner	73%	3,085	2,606	16%	28,148	16,635	41%	857,870	325,394	62%
Heartland Flyer	70%	218	211	3%	2,131	966	55%	73,688	31,151	58%
Hiawatha	90%	1,873	222	88%	20,123	2,421	88%	603,900	66,268	89%
Illinois	78%	2,832	415	85%	26,809	11,919	56%	855,166	244,553	71%
Carl Sandburg / Illinois Zephyr	85%	358	4	99%	4,411	1,097	75%	142,157	40,431	72%
Illini / Saluki	85%	1,104	400	64%	9,725	5,109	47%	295,737	76,586	74%
Lincoln Service	70%	1,370	11	99%	12,673	5,713	55%	417,272	127,536	69%
Keystone	92%	9,565	499	95%	94,671	12,691	87%	2,608,562	268,943	90%
Lincoln / Missouri	70%	882	643	27%	7,921	6,209	22%	265,532	141,666	47%
Mardi Gras Service	80%	372	0	100%	3,439	518	85%	137,391	30,503	78%
Michigan	70%	2,352	677	71%	23,927	9,756	59%	697,205	235,306	66%
Blue Water	70%	529	239	55%	5,610	2,277	59%	164,235	67,421	59%
Pere Marquette	85%	180	0	100%	3,060	604	80%	89,541	16,957	81%
Wolverine	70%	1,643	438	73%	15,257	6,875	55%	443,429	150,928	66%
Missouri	80%	242	63	74%	2,587	2,027	22%	75,947	23,292	69%
Pacific Surfliner	85%	3,740	2,098	44%	72,452	32,954	55%	2,799,298	551,527	80%
Pennsylvanian	80%	979	0	100%	9,581	2,150	78%	302,134	57,981	81%
Piedmont	80%	1,208	185	85%	10,498	2,264	78%	381,426	96,865	75%
Vermont	75%	1,228	0	100%	15,415	3,755	76%	440,936	131,962	70%
Long Distance	70%	12,437	6,958	44%	130,949	67,547	48%	4,179,235	1,852,508	56%
Auto Train	70%	614	356	42%	6,985	3,278	53%	267,056	92,019	66%
California Zephyr	70%	907	524	42%	10,322	4,388	57%	331,657	130,567	61%
Cardinal	70%	0	0	-	2,114	1,403	34%	79,130	40,654	49%
City Of New Orleans	75%	706	595	16%	7,221	6,468	10%	216,873	78,933	64%
Coast Starlight	70%	1,152	705	39%	13,123	3,707	72%	390,377	138,349	65%
Crescent	70%	908	460	49%	9,680	2,396	75%	315,077	96,866	69%
Empire Builder	70%	1,163	774	33%	12,121	5,554	54%	331,677	166,304	50%
Floridian	60%	1,396	1,139	18%	16,150	12,387	23%	536,056	372,393	31%
Lake Shore Ltd	73%	1,082	309	71%	11,207	4,593	59%	332,888	102,436	69%
Palmetto	70%	758	241	68%	8,628	3,582	58%	311,809	98,380	68%
Silver Meteor	70%	891	585	34%	9,717	5,416	44%	344,127	160,820	53%
Southwest Chief	60%	912	506	45%	9,641	5,864	39%	286,896	189,459	34%
Sunset Ltd	70%	651	58	91%	2,888	1,063	63%	98,592	39,562	60%
Texas Eagle	70%	1,297	706	46%	11,152	7,448	33%	337,020	145,766	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00757 00000000015 "UNCLASSIFIED" 0/20/2020

Train Index Dates Through September 11, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	72,686	1,211,258	600	2,072,504	36,485,424	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,349	374,142	90	99,788	10,581,577	94
INFRASTRUCTURE PLANNED	135	6,417	374,142	172	121,963	10,581,577	115
FLEET RELIABILITY	90	11,174	1,211,258	92	330,719	36,485,424	91
TRAIN OPERATIONS	424	51,746	1,211,258	427	1,520,034	36,485,424	417

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/11/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	36	88.8%	3,455	492	85.8%	103,977	14,460	86.1%
Central Division	86.0%	56	4	92.9%	631	75	88.1%	19,826	1,850	90.7%
East Division	82.0%	181	19	89.5%	1,879	216	88.5%	54,699	8,350	84.7%
West Division	86.0%	84	13	84.5%	945	201	78.7%	29,452	4,260	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/11/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	36	88.8%	3,455	492	85.8%	103,977	14,460	86.1%
Central Division	86.0%	56	4	92.9%	631	75	88.1%	19,826	1,850	90.7%
CDL	95.0%	2	0	100.0%	22	4	81.8%	658	35	94.7%
CHI	86.0%	26	3	88.5%	295	48	83.7%	9,165	1,148	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	11	1	90.9%	369	39	89.4%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	10	0	100.0%	324	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	22	1	95.5%	670	55	91.8%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	65	2	96.9%	2,024	128	93.7%
MOE	97.5%	2	0	100.0%	22	1	95.5%	689	10	98.5%
MSP	96.5%	1	0	100.0%	11	0	100.0%	339	7	97.9%
NOL	94.5%	4	0	100.0%	47	1	97.9%	1,457	65	95.5%
OKC	97.0%	1	0	100.0%	10	0	100.0%	339	6	98.2%
PNT	88.0%	3	0	100.0%	28	2	92.9%	904	75	91.7%
PTH	93.0%	1	0	100.0%	11	0	100.0%	334	13	96.1%
QCY	91.0%	1	0	100.0%	20	1	95.0%	651	49	92.5%
SAS	90.5%	1	1	0.0%	11	2	81.8%	343	41	88.0%
STL	89.0%	4	0	100.0%	41	7	82.9%	1,337	113	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	181	19	89.5%	1,879	216	88.5%	54,699	8,350	84.7%
ALB	88.5%	7	0	100.0%	84	9	89.3%	2,568	197	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	55	1	98.2%	1,676	176	89.5%
BOS	85.5%	19	2	89.5%	205	17	91.7%	5,910	657	88.9%
BRK	92.5%	5	1	80.0%	55	2	96.4%	1,650	114	93.1%
BTN	82.0%	1	0	100.0%	11	1	90.9%	330	43	87.0%
CLT	91.5%	5	0	100.0%	49	5	89.8%	1,680	172	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	21	2	90.5%	669	62	90.7%
GRO	-	-	-	-	6	2	66.7%	56	13	76.8%
HAR	79.5%	13	1	92.3%	125	17	86.4%	3,832	611	84.1%
HFD	-	2	0	100.0%	16	1	93.8%	248	20	91.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	11	1	90.9%	342	41	88.0%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/11/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/11/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	36	88.8%	3,455	492	85.8%	103,977	14,460	86.1%
East Division	82.0%	181	19	89.5%	1,879	216	88.5%	54,699	8,350	84.7%
MIA	89.5%	2	0	100.0%	22	5	77.3%	680	81	88.1%
MTR	79.0%	1	0	100.0%	11	2	81.8%	329	60	81.8%
NFK	84.5%	2	0	100.0%	22	2	90.9%	767	138	82.0%
NFL	93.5%	2	0	100.0%	22	1	95.5%	696	32	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	53	9	83.0%	1,755	296	83.1%
NPN	93.0%	2	0	100.0%	22	1	95.5%	656	52	92.1%
NYP	75.5%	52	7	86.5%	527	83	84.3%	14,456	3,140	78.3%
PGH	93.0%	1	0	100.0%	11	1	90.9%	343	24	93.0%
PHL	48.0%	5	2	60.0%	52	21	59.6%	1,747	820	53.1%
PIT	76.0%	1	0	100.0%	3	2	33.3%	27	21	22.2%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	4	1	75.0%	32	4	87.5%	1,296	58	95.5%
RNK	83.5%	2	0	100.0%	22	1	95.5%	680	94	86.2%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	11	0	100.0%	325	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	11	0	100.0%	339	12	96.5%
SFA	88.0%	1	0	100.0%	11	2	81.8%	342	49	85.7%
SPG	92.5%	5	0	100.0%	58	1	98.3%	2,020	116	94.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	11	1	90.9%	331	64	80.7%
WAS	84.0%	33	3	90.9%	340	22	93.5%	8,709	1,096	87.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	84	13	84.5%	945	201	78.7%	29,452	4,260	85.5%
ARN	92.0%	1	0	100.0%	11	1	90.9%	344	29	91.6%
BFD	79.0%	7	4	42.9%	75	24	68.0%	2,188	472	78.4%
EMY	72.0%	1	0	100.0%	11	4	63.6%	360	104	71.1%
EUG	86.5%	2	0	100.0%	21	3	85.7%	681	62	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	32	10	68.8%	1,033	182	82.4%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	8	0	100.0%	100	15	85.0%	3,420	384	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	4	69.2%	130	55	57.7%	3,749	1,008	73.1%
PDX	86.0%	5	1	80.0%	55	8	85.5%	1,660	233	86.0%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/11/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/11/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	36	88.8%	3,455	492	85.8%	103,977	14,460	86.1%
West Division	86.0%	84	13	84.5%	945	201	78.7%	29,452	4,260	85.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	2	87.5%	164	25	84.8%	4,883	545	88.8%
SAN	90.5%	5	0	100.0%	104	18	82.7%	4,141	410	90.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	88	17	80.7%	2,641	397	85.0%
SJC	89.0%	7	0	100.0%	77	13	83.1%	2,417	242	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	33	2	93.9%	798	79	90.1%
SNA	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
SNC	-	1	0	100.0%	7	1	85.7%	38	14	63.2%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	11	1	90.9%	323	30	90.7%
VAC	97.0%	2	0	100.0%	22	2	90.9%	675	16	97.6%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		4	1	75.0%	146	13	91.1%	5	1	80.0%	146	42	71.2%
2		5	1	80.0%	147	37	74.8%	4	0	100.0%	141	29	79.4%
3		11	3	72.7%	344	69	79.9%	11	3	72.7%	341	160	53.1%
4		11	3	72.7%	343	56	83.7%	11	4	63.6%	343	225	34.4%
5		11	1	90.9%	342	58	83.0%	11	3	72.7%	338	114	66.3%
6	423	11	4	63.6%	341	95	72.1%	11	6	45.5%	341	131	61.6%
7	94	11	0	100.0%	333	51	84.7%	11	2	81.8%	324	88	72.8%
8		11	3	72.7%	333	148	55.6%	11	6	45.5%	332	204	38.6%
11		11	3	72.7%	344	75	78.2%	11	1	90.9%	338	68	79.9%
14	40	11	6	45.5%	345	60	82.6%	11	1	90.9%	342	106	69.0%
19	36	11	1	90.9%	343	84	75.5%	11	1	90.9%	340	83	75.6%
20		11	0	100.0%	343	23	93.3%	11	1	90.9%	343	66	80.8%
21		11	1	90.9%	340	37	89.1%	11	5	54.5%	339	104	69.3%
22	63	11	2	81.8%	341	39	88.6%	11	10	9.1%	339	109	67.8%
23		11	1	90.9%	345	7	98.0%	11	4	63.6%	343	94	72.6%
24		11	0	100.0%	345	16	95.4%	11	2	81.8%	344	67	80.5%
25		11	0	100.0%	344	3	99.1%	11	0	100.0%	341	94	72.4%
26		11	1	90.9%	344	6	98.3%	11	1	90.9%	341	67	80.4%
27	102	11	3	72.7%	310	22	92.9%	11	3	72.7%	304	100	67.1%
28		11	1	90.9%	304	68	77.6%	11	1	90.9%	304	61	79.9%
40		11	3	72.7%	334	50	85.0%	11	6	45.5%	330	178	46.1%
41	173	11	9	18.2%	334	133	60.2%	11	10	9.1%	331	257	22.4%
42		11	1	90.9%	345	26	92.5%	11	1	90.9%	343	59	82.8%
43		11	0	100.0%	344	45	86.9%	11	5	54.5%	343	81	76.4%
48		11	0	100.0%	343	62	81.9%	11	4	63.6%	342	55	83.9%
49		11	2	81.8%	343	86	74.9%	11	4	63.6%	343	74	78.4%
50	No OS	5	2	60.0%	140	36	74.3%	5	5	0.0%	138	88	36.2%
52		11	2	81.8%	342	49	85.7%	11	4	63.6%	341	81	76.2%
53	39	11	1	90.9%	342	41	88.0%	11	6	45.5%	341	112	67.2%
55		8	0	100.0%	219	9	95.9%	8	0	100.0%	216	46	78.7%
56		8	0	100.0%	220	25	88.6%	8	4	50.0%	216	44	79.6%
58	126	11	0	100.0%	318	17	94.7%	11	11	0.0%	316	108	65.8%
59	78	11	3	72.7%	317	54	83.0%	11	10	9.1%	312	91	70.8%
63	32	11	3	72.7%	346	147	57.5%	11	11	0.0%	340	208	38.8%
64		11	1	90.9%	344	72	79.1%	11	5	54.5%	343	138	59.8%
66		11	1	90.9%	343	65	81.0%	11	2	81.8%	338	62	81.7%
67	36	7	0	100.0%	237	14	94.1%	8	2	75.0%	237	42	82.3%
68		11	2	81.8%	346	69	80.1%	11	3	72.7%	345	137	60.3%
69		11	4	63.6%	333	83	75.1%	11	3	72.7%	328	59	82.0%
71		11	1	90.9%	341	4	98.8%	11	1	90.9%	339	87	74.3%
72		11	1	90.9%	337	37	89.0%	11	1	90.9%	335	70	79.1%
73		5	1	80.0%	333	24	92.8%	5	0	100.0%	331	148	55.3%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74		5	0	100.0%	331	35	89.4%	5	2	60.0%	329	120	63.5%
75	20	11	3	72.7%	334	20	94.0%	11	4	63.6%	328	155	52.7%
76	167	11	0	100.0%	334	31	90.7%	11	4	63.6%	324	134	58.6%
77		11	1	90.9%	336	22	93.5%	11	3	72.7%	333	136	59.2%
78	45	11	3	72.7%	340	32	90.6%	12	3	75.0%	338	78	76.9%
78		11	3	72.7%	340	32	90.6%	12	3	75.0%	338	78	76.9%
79		11	0	100.0%	343	59	82.8%	11	4	63.6%	341	116	66.0%
80		11	1	90.9%	343	38	88.9%	11	2	81.8%	340	73	78.5%
84		8	0	100.0%	210	19	91.0%	8	1	87.5%	206	49	76.2%
85		8	0	100.0%	221	18	91.9%	8	3	62.5%	221	77	65.2%
86	25	8	0	100.0%	221	16	92.8%	8	4	50.0%	220	125	43.2%
89	33	11	2	81.8%	341	80	76.5%	11	5	54.5%	339	102	69.9%
90		11	0	100.0%	341	12	96.5%	11	3	72.7%	340	63	81.5%
93	19	8	0	100.0%	220	21	90.5%	8	5	37.5%	219	60	72.6%
94	30	8	1	87.5%	251	62	75.3%	8	4	50.0%	249	93	62.7%
95		8	1	87.5%	220	7	96.8%	8	4	50.0%	220	86	60.9%
97	57	11	7	36.4%	343	224	34.7%	11	6	45.5%	341	126	63.0%
98		11	2	81.8%	343	30	91.3%	11	4	63.6%	341	127	62.8%
110		7	1	85.7%	216	111	48.6%	6	0	100.0%	212	22	89.6%
111	26	8	0	100.0%	211	37	82.5%	8	1	87.5%	209	23	89.0%
112		8	1	87.5%	211	21	90.0%	8	0	100.0%	210	20	90.5%
113		8	0	100.0%	142	33	76.8%	8	0	100.0%	141	16	88.7%
119		8	1	87.5%	208	50	76.0%	8	1	87.5%	206	27	86.9%
125	22	8	0	100.0%	221	12	94.6%	8	5	37.5%	221	89	59.7%
129		8	1	87.5%	220	51	76.8%	8	1	87.5%	220	31	85.9%
130		8	0	100.0%	211	20	90.5%	8	0	100.0%	209	16	92.3%
131		8	1	87.5%	213	58	72.8%	8	0	100.0%	213	39	81.7%
134		8	1	87.5%	221	33	85.1%	8	0	100.0%	220	42	80.9%
136		8	1	87.5%	221	28	87.3%	8	3	62.5%	219	31	85.8%
137		8	2	75.0%	218	38	82.6%	7	3	57.1%	217	65	70.0%
138		8	1	87.5%	221	44	80.1%	8	1	87.5%	220	39	82.3%
141		8	1	87.5%	220	5	97.7%	8	1	87.5%	219	38	82.6%
148	44	8	2	75.0%	220	24	89.1%	8	2	75.0%	218	42	80.7%
151		11	3	72.7%	342	108	68.4%	11	3	72.7%	341	102	70.1%
170		8	0	100.0%	216	12	94.4%	8	1	87.5%	215	31	85.6%
171	35	8	0	100.0%	221	11	95.0%	8	3	62.5%	221	91	58.8%
172		8	1	87.5%	220	20	90.9%	8	4	50.0%	218	73	66.5%
173		8	1	87.5%	213	26	87.8%	8	1	87.5%	212	85	59.9%
174		8	0	100.0%	221	23	89.6%	8	2	75.0%	221	54	75.6%
175		8	1	87.5%	221	24	89.1%	8	3	62.5%	221	73	67.0%
176	21	8	0	100.0%	213	17	92.0%	8	2	75.0%	210	28	86.7%
177		8	1	87.5%	221	29	86.9%	8	2	75.0%	221	50	77.4%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		8	0	100.0%	221	28	87.3%	8	1	87.5%	219	37	83.1%
179	56	8	1	87.5%	221	26	88.2%	8	5	37.5%	220	81	63.2%
181		8	2	75.0%	217	66	69.6%	8	2	75.0%	214	19	91.1%
182		8	1	87.5%	211	32	84.8%	8	3	62.5%	209	26	87.6%
183		8	1	87.5%	220	63	71.4%	8	1	87.5%	217	45	79.3%
184		8	0	100.0%	221	36	83.7%	8	1	87.5%	220	29	86.8%
185		8	3	62.5%	221	44	80.1%	8	0	100.0%	221	18	91.9%
186		8	1	87.5%	220	30	86.4%	8	3	62.5%	219	64	70.8%
190		8	4	50.0%	220	79	64.1%	8	1	87.5%	219	45	79.5%
192		8	0	100.0%	218	24	89.0%	8	0	100.0%	218	19	91.3%
193		8	2	75.0%	216	85	60.6%	8	3	62.5%	215	93	56.7%
196		8	2	75.0%	217	25	88.5%	8	0	100.0%	215	17	92.1%
197	17	8	1	87.5%	221	78	64.7%	8	5	37.5%	221	76	65.6%
198		8	2	75.0%	153	19	87.6%	8	3	62.5%	152	25	83.6%
230		11	0	100.0%	179	4	97.8%	11	1	90.9%	179	10	94.4%
232		11	1	90.9%	345	13	96.2%	11	1	90.9%	345	24	93.0%
234		11	0	100.0%	346	23	93.4%	11	0	100.0%	345	29	91.6%
235		11	1	90.9%	270	43	84.1%	11	1	90.9%	269	61	77.3%
236		11	1	90.9%	330	11	96.7%	11	1	90.9%	329	44	86.6%
237	43	11	2	81.8%	343	63	81.6%	11	4	63.6%	341	63	81.5%
238		10	1	90.0%	269	24	91.1%	10	1	90.0%	267	23	91.4%
239		11	3	72.7%	344	86	75.0%	11	1	90.9%	343	43	87.5%
240		11	2	81.8%	345	25	92.8%	11	1	90.9%	342	70	79.5%
241		11	4	63.6%	345	86	75.1%	10	3	70.0%	344	84	75.6%
243		11	1	90.9%	281	72	74.4%	11	0	100.0%	280	39	86.1%
245		11	2	81.8%	226	43	81.0%	11	0	100.0%	225	30	86.7%
280		11	0	100.0%	346	17	95.1%	11	2	81.8%	345	80	76.8%
281		11	0	100.0%	346	40	88.4%	11	2	81.8%	346	62	82.1%
283		11	3	72.7%	346	88	74.6%	11	5	54.5%	346	71	79.5%
284		11	1	90.9%	346	14	96.0%	11	3	72.7%	343	64	81.3%
290		11	1	90.9%	346	53	84.7%	11	4	63.6%	343	141	58.9%
291		11	2	81.8%	345	114	67.0%	11	2	81.8%	341	92	73.0%
300		10	3	70.0%	328	25	92.4%	9	1	88.9%	324	74	77.2%
301		10	1	90.0%	342	11	96.8%	10	5	50.0%	338	68	79.9%
302		10	2	80.0%	323	36	88.9%	10	5	50.0%	319	95	70.2%
305		11	3	72.7%	327	34	89.6%	10	5	50.0%	321	127	60.4%
306		10	1	90.0%	340	18	94.7%	10	6	40.0%	338	95	71.9%
307		10	2	80.0%	333	46	86.2%	10	5	50.0%	329	103	68.7%
311		11	1	90.9%	338	29	91.4%	11	9	18.2%	332	93	72.0%
316		11	1	90.9%	334	25	92.5%	11	10	9.1%	328	111	66.2%
318	16	11	0	100.0%	344	35	89.8%	11	9	18.2%	341	175	48.7%
319	53	11	1	90.9%	345	21	93.9%	11	11	0.0%	340	204	40.0%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
329		9	1	88.9%	245	13	94.7%	9	1	88.9%	245	20	91.8%
330		10	1	90.0%	294	7	97.6%	10	1	90.0%	294	16	94.6%
331		11	2	81.8%	346	35	89.9%	11	2	81.8%	345	46	86.7%
332		11	1	90.9%	345	20	94.2%	11	3	72.7%	345	49	85.8%
334		11	0	100.0%	346	11	96.8%	11	1	90.9%	344	44	87.2%
335		11	0	100.0%	346	35	89.9%	11	0	100.0%	343	55	84.0%
336		11	0	100.0%	345	10	97.1%	11	3	72.7%	343	32	90.7%
337		11	1	90.9%	346	22	93.6%	11	3	72.7%	342	50	85.4%
338	28	11	0	100.0%	346	54	84.4%	11	3	72.7%	343	107	68.8%
339		11	2	81.8%	346	56	83.8%	11	1	90.9%	346	59	82.9%
341		11	2	81.8%	331	53	84.0%	11	2	81.8%	325	55	83.1%
342		11	0	100.0%	346	26	92.5%	11	2	81.8%	344	63	81.7%
350	24	10	1	90.0%	320	21	93.4%	10	7	30.0%	312	181	42.0%
351	18	11	1	90.9%	328	30	90.9%	11	5	54.5%	326	97	70.2%
352		11	0	100.0%	312	24	92.3%	11	9	18.2%	306	102	66.7%
353		11	1	90.9%	283	15	94.7%	11	3	72.7%	277	52	81.2%
354		11	1	90.9%	327	38	88.4%	11	5	54.5%	319	121	62.1%
355		10	4	60.0%	333	41	87.7%	10	4	60.0%	324	123	62.0%
364		11	1	90.9%	335	74	77.9%	11	5	54.5%	329	125	62.0%
365		11	0	100.0%	334	13	96.1%	11	4	63.6%	331	128	61.3%
371		10	0	100.0%	324	11	96.6%	10	2	80.0%	320	32	90.0%
380		11	0	100.0%	327	30	90.8%	11	1	90.9%	326	73	77.6%
383		11	3	72.7%	332	30	91.0%	10	3	70.0%	328	141	57.0%
390	32	11	2	81.8%	327	26	92.0%	10	6	40.0%	324	92	71.6%
391	23	11	0	100.0%	328	14	95.7%	11	8	27.3%	323	96	70.3%
392		11	2	81.8%	341	13	96.2%	10	7	30.0%	335	110	67.2%
393		11	3	72.7%	345	22	93.6%	10	6	40.0%	340	110	67.6%
417		8	0	100.0%	229	47	79.5%	8	1	87.5%	220	26	88.2%
425		7	0	100.0%	231	7	97.0%	7	0	100.0%	230	7	97.0%
448		11	4	63.6%	270	53	80.4%	11	3	72.7%	266	92	65.4%
449		11	0	100.0%	267	34	87.3%	11	1	90.9%	267	46	82.8%
470		8	2	75.0%	244	42	82.8%	8	3	62.5%	238	30	87.4%
471		8	0	100.0%	233	14	94.0%	8	0	100.0%	233	6	97.4%
473		8	1	87.5%	240	16	93.3%	8	0	100.0%	237	10	95.8%
474		9	3	66.7%	237	69	70.9%	8	1	87.5%	221	72	67.4%
475		7	0	100.0%	236	8	96.6%	7	0	100.0%	236	16	93.2%
478		8	1	87.5%	232	37	84.1%	8	1	87.5%	230	29	87.4%
479		8	0	100.0%	239	36	84.9%	8	1	87.5%	237	37	84.4%
486		8	1	87.5%	243	36	85.2%	8	0	100.0%	237	61	74.3%
494		8	1	87.5%	246	48	80.5%	8	4	50.0%	238	68	71.4%
495		8	0	100.0%	227	4	98.2%	8	0	100.0%	225	3	98.7%
500		11	2	81.8%	320	18	94.4%	11	1	90.9%	317	37	88.3%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502		11	1	90.9%	328	20	93.9%	11	4	63.6%	324	65	79.9%
503	29	11	2	81.8%	342	42	87.7%	10	4	60.0%	334	106	68.3%
504	20	11	2	81.8%	346	22	93.6%	11	4	63.6%	344	103	70.1%
505	22	11	3	72.7%	338	46	86.4%	11	7	36.4%	333	98	70.6%
506		11	1	90.9%	341	57	83.3%	10	2	80.0%	332	53	84.0%
507		11	0	100.0%	346	49	85.8%	11	3	72.7%	346	118	65.9%
508		10	1	90.0%	340	44	87.1%	10	1	90.0%	336	82	75.6%
509		11	3	72.7%	327	18	94.5%	11	3	72.7%	327	74	77.4%
511		11	1	90.9%	322	26	91.9%	11	1	90.9%	321	54	83.2%
516	56	11	2	81.8%	337	37	89.0%	11	6	45.5%	336	152	54.8%
517	68	11	0	100.0%	346	8	97.7%	11	5	54.5%	342	155	54.7%
518		11	3	72.7%	346	49	85.8%	11	7	36.4%	344	239	30.5%
519		11	2	81.8%	337	11	96.7%	10	4	60.0%	334	76	77.2%
520		8	1	87.5%	202	30	85.1%	8	1	87.5%	197	12	93.9%
521		8	1	87.5%	240	8	96.7%	8	1	87.5%	239	32	86.6%
522		8	2	75.0%	240	45	81.3%	8	1	87.5%	237	25	89.5%
523		8	0	100.0%	240	9	96.3%	8	2	75.0%	239	28	88.3%
524		8	1	87.5%	239	18	92.5%	8	2	75.0%	236	29	87.7%
525		8	1	87.5%	237	17	92.8%	7	1	85.7%	232	16	93.1%
526		8	3	62.5%	214	44	79.4%	7	1	85.7%	210	19	91.0%
527		8	0	100.0%	240	10	95.8%	8	1	87.5%	238	41	82.8%
528		8	0	100.0%	240	19	92.1%	8	2	75.0%	239	34	85.8%
529	14	8	0	100.0%	240	13	94.6%	8	2	75.0%	239	67	72.0%
530		8	3	62.5%	194	21	89.2%	7	1	85.7%	193	39	79.8%
531		8	2	75.0%	214	16	92.5%	8	2	75.0%	214	15	93.0%
532		8	3	62.5%	240	60	75.0%	8	2	75.0%	238	37	84.5%
534		8	4	50.0%	199	32	83.9%	8	1	87.5%	196	18	90.8%
535		8	1	87.5%	226	27	88.1%	8	0	100.0%	221	28	87.3%
536	82	8	4	50.0%	240	68	71.7%	8	2	75.0%	236	43	81.8%
537		8	2	75.0%	209	26	87.6%	8	0	100.0%	203	25	87.7%
538	43	8	3	62.5%	240	29	87.9%	8	1	87.5%	239	47	80.3%
539		8	1	87.5%	194	29	85.1%	8	3	62.5%	194	85	56.2%
540	28	8	2	75.0%	239	46	80.8%	8	2	75.0%	229	23	90.0%
541		8	1	87.5%	239	26	89.1%	8	1	87.5%	232	42	81.9%
542		8	1	87.5%	239	26	89.1%	8	2	75.0%	236	43	81.8%
543		8	3	62.5%	240	31	87.1%	8	6	25.0%	240	79	67.1%
544		8	0	100.0%	238	22	90.8%	8	0	100.0%	234	22	90.6%
545		8	2	75.0%	240	22	90.8%	8	1	87.5%	237	30	87.3%
547	73	8	3	62.5%	240	50	79.2%	8	3	62.5%	240	57	76.3%
548		7	0	100.0%	231	22	90.5%	7	1	85.7%	228	18	92.1%
549		8	0	100.0%	235	27	88.5%	8	0	100.0%	225	20	91.1%
550		8	2	75.0%	194	22	88.7%	8	2	75.0%	194	46	76.3%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
551		8	0	100.0%	236	23	90.3%	8	0	100.0%	226	23	89.8%
562	37	11	0	100.0%	337	27	92.0%	11	6	45.5%	332	43	87.0%
564		11	0	100.0%	338	19	94.4%	10	2	80.0%	329	45	86.3%
579		11	0	100.0%	223	14	93.7%	11	3	72.7%	216	48	77.8%
580		11	2	81.8%	338	20	94.1%	11	4	63.6%	331	41	87.6%
591		11	3	72.7%	335	29	91.3%	10	4	60.0%	327	53	83.8%
593		7	3	57.1%	324	56	82.7%	5	2	60.0%	299	43	85.6%
600		8	0	100.0%	248	9	96.4%	8	3	62.5%	246	25	89.8%
601		8	2	75.0%	231	92	60.2%	8	1	87.5%	228	28	87.7%
605		8	6	25.0%	238	145	39.1%	7	1	85.7%	233	24	89.7%
607		8	1	87.5%	247	31	87.4%	8	1	87.5%	244	26	89.3%
609	23	8	1	87.5%	238	24	89.9%	8	1	87.5%	237	24	89.9%
626		8	1	87.5%	152	21	86.2%	8	1	87.5%	150	19	87.3%
639		8	1	87.5%	218	41	81.2%	8	1	87.5%	216	21	90.3%
640		8	1	87.5%	238	8	96.6%	8	2	75.0%	236	86	63.6%
641		8	1	87.5%	220	44	80.0%	8	5	37.5%	220	32	85.5%
642		8	1	87.5%	236	12	94.9%	8	1	87.5%	235	28	88.1%
643		8	1	87.5%	250	45	82.0%	8	2	75.0%	247	41	83.4%
644	12	8	2	75.0%	242	30	87.6%	8	5	37.5%	240	61	74.6%
645		8	0	100.0%	250	42	83.2%	8	0	100.0%	247	55	77.7%
646		8	4	50.0%	239	60	74.9%	8	4	50.0%	237	117	50.6%
647		8	3	62.5%	250	38	84.8%	8	2	75.0%	248	53	78.6%
648		8	2	75.0%	246	61	75.2%	8	1	87.5%	246	36	85.4%
649		8	3	62.5%	251	47	81.3%	8	2	75.0%	247	36	85.4%
650	15	8	1	87.5%	250	46	81.6%	8	4	50.0%	247	43	82.6%
651		8	1	87.5%	250	18	92.8%	8	1	87.5%	247	44	82.2%
652		8	0	100.0%	251	31	87.6%	8	2	75.0%	247	43	82.6%
653		8	2	75.0%	239	38	84.1%	8	3	62.5%	235	44	81.3%
654		8	0	100.0%	240	44	81.7%	8	1	87.5%	236	21	91.1%
655		8	3	62.5%	248	77	69.0%	8	2	75.0%	245	78	68.2%
656	39	8	2	75.0%	250	56	77.6%	8	2	75.0%	248	35	85.9%
657		8	0	100.0%	239	29	87.9%	8	1	87.5%	237	31	86.9%
658	Cncld	8	1	87.5%	250	38	84.8%	7	0	100.0%	247	35	85.8%
680		9	1	88.9%	246	13	94.7%	9	0	100.0%	244	27	88.9%
681		9	0	100.0%	246	18	92.7%	9	2	77.8%	239	95	60.3%
682		9	1	88.9%	245	10	95.9%	9	0	100.0%	245	42	82.9%
683		9	1	88.9%	228	19	91.7%	9	2	77.8%	227	77	66.1%
684		9	0	100.0%	227	37	83.7%	9	1	88.9%	227	48	78.9%
685		9	0	100.0%	242	33	86.4%	9	1	88.9%	239	56	76.6%
686	11	9	0	100.0%	247	39	84.2%	9	2	77.8%	246	54	78.0%
687		9	0	100.0%	246	38	84.6%	9	0	100.0%	245	40	83.7%
688		9	0	100.0%	245	15	93.9%	9	0	100.0%	244	41	83.2%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
689		5	0	100.0%	160	21	86.9%	5	0	100.0%	159	23	85.5%
701		11	2	81.8%	278	32	88.5%	11	3	72.7%	275	35	87.3%
702	46	11	2	81.8%	345	38	89.0%	10	5	50.0%	341	88	74.2%
703		11	5	54.5%	346	117	66.2%	11	5	54.5%	344	105	69.5%
704	58	11	4	63.6%	277	53	80.9%	11	6	45.5%	269	65	75.8%
710	34	11	3	72.7%	346	82	76.3%	9	6	33.3%	340	94	72.4%
711	17	11	2	81.8%	337	40	88.1%	11	4	63.6%	314	69	78.0%
712	21	11	4	63.6%	343	95	72.3%	11	7	36.4%	333	121	63.7%
713	21	10	4	60.0%	212	24	88.7%	7	6	14.3%	184	86	53.3%
714	43	11	7	36.4%	227	99	56.4%	10	8	20.0%	210	103	51.0%
715	21	11	2	81.8%	345	65	81.2%	9	7	22.2%	314	162	48.4%
716	170	11	8	27.3%	346	151	56.4%	10	8	20.0%	336	149	55.7%
717	70	10	4	60.0%	330	83	74.8%	10	7	30.0%	305	105	65.6%
718	103	11	10	9.1%	346	188	45.7%	11	9	18.2%	343	138	59.8%
719		11	5	54.5%	346	118	65.9%	10	5	50.0%	328	103	68.6%
757		11	0	100.0%	131	7	94.7%	11	1	90.9%	130	15	88.5%
761		11	1	90.9%	342	14	95.9%	11	1	90.9%	339	45	86.7%
765	44	11	2	81.8%	342	27	92.1%	11	6	45.5%	342	52	84.8%
769	33	11	1	90.9%	342	28	91.8%	11	7	36.4%	335	72	78.5%
770	23	11	2	81.8%	342	27	92.1%	11	6	45.5%	339	110	67.6%
774	56	11	0	100.0%	342	17	95.0%	11	7	36.4%	340	87	74.4%
777	52	11	2	81.8%	227	15	93.4%	11	10	9.1%	226	68	69.9%
782	18	11	8	27.3%	227	113	50.2%	11	4	63.6%	222	40	82.0%
785	27	11	1	90.9%	342	30	91.2%	11	8	27.3%	342	69	79.8%
786		11	1	90.9%	131	24	81.7%	9	6	33.3%	125	72	42.4%
790	72	11	0	100.0%	342	31	90.9%	10	5	50.0%	338	59	82.5%
794		11	1	90.9%	342	41	88.0%	11	3	72.7%	338	79	76.6%
821	25	10	0	100.0%	339	6	98.2%	10	4	60.0%	339	144	57.5%
822	50	11	1	90.9%	342	19	94.4%	10	8	20.0%	339	178	47.5%
1233		3	0	100.0%	27	5	81.5%	3	1	66.7%	25	14	44.0%
1246	58	3	2	33.3%	27	21	22.2%	3	1	66.7%	27	14	48.1%
1333		11	2	81.8%	342	42	87.7%	11	3	72.7%	339	115	66.1%
1340		11	0	100.0%	341	7	97.9%	11	0	100.0%	340	56	83.5%
2102		8	0	100.0%	97	16	83.5%	8	0	100.0%	96	7	92.7%
2103	29	8	0	100.0%	161	14	91.3%	8	2	75.0%	160	12	92.5%
2104		8	0	100.0%	187	10	94.7%	7	0	100.0%	184	13	92.9%
2105		8	0	100.0%	9	1	88.9%	8	0	100.0%	9	0	100.0%
2107		7	1	85.7%	217	36	83.4%	7	0	100.0%	214	21	90.2%
2108		8	2	75.0%	218	30	86.2%	7	0	100.0%	211	27	87.2%
2109		8	2	75.0%	111	15	86.5%	8	0	100.0%	109	6	94.5%
2112		8	0	100.0%	58	6	89.7%	8	0	100.0%	56	2	96.4%
2113		8	1	87.5%	97	10	89.7%	8	1	87.5%	97	11	88.7%

Amtrak On Time Performance

Trains Arriving Through: 9/11/2026

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2115		8	2	75.0%	97	15	84.5%	7	0	100.0%	95	12	87.4%
2116		8	0	100.0%	58	1	98.3%	8	0	100.0%	58	8	86.2%
2118		8	0	100.0%	58	4	93.1%	8	0	100.0%	58	12	79.3%
2119		7	1	85.7%	57	9	84.2%	7	1	85.7%	56	13	76.8%
2120		8	1	87.5%	58	20	65.5%	8	0	100.0%	56	23	58.9%
2123		8	2	75.0%	96	12	87.5%	8	0	100.0%	95	15	84.2%
2124		8	0	100.0%	189	38	79.9%	8	0	100.0%	187	24	87.2%
2126		8	1	87.5%	106	27	74.5%	8	0	100.0%	105	22	79.0%
2127		8	0	100.0%	58	10	82.8%	8	0	100.0%	57	9	84.2%
2128		8	1	87.5%	58	5	91.4%	8	0	100.0%	58	3	94.8%
2131		8	0	100.0%	58	10	82.8%	8	0	100.0%	58	6	89.7%
2150		8	0	100.0%	211	22	89.6%	8	0	100.0%	208	75	63.9%
2151	54	8	1	87.5%	160	8	95.0%	8	4	50.0%	158	45	71.5%
2152		8	0	100.0%	116	7	94.0%	8	0	100.0%	115	31	73.0%
2154		8	1	87.5%	119	24	79.8%	7	1	85.7%	114	46	59.6%
2155		8	0	100.0%	220	17	92.3%	8	1	87.5%	216	103	52.3%
2156		8	0	100.0%	9	0	100.0%	8	2	75.0%	9	2	77.8%
2158		8	0	100.0%	57	6	89.5%	8	1	87.5%	57	17	70.2%
2159	21	8	1	87.5%	213	17	92.0%	8	3	62.5%	211	72	65.9%
2160	59	8	1	87.5%	58	3	94.8%	8	2	75.0%	57	30	47.4%
2162		8	0	100.0%	219	23	89.5%	8	0	100.0%	213	91	57.3%
2163		8	0	100.0%	171	17	90.1%	8	5	37.5%	165	74	55.2%
2165		8	0	100.0%	55	4	92.7%	8	1	87.5%	55	22	60.0%
2167		8	1	87.5%	206	21	89.8%	8	2	75.0%	206	43	79.1%
2171	22	8	1	87.5%	147	11	92.5%	8	3	62.5%	143	26	81.8%
2190		8	1	87.5%	216	30	86.1%	8	0	100.0%	214	24	88.8%
2193		7	1	85.7%	210	27	87.1%	7	1	85.7%	208	51	75.5%

Amtrak Endpoint OTP Details

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/11/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2103	WAS	29	CAR	14	CAR	14	PHL-PHL	AM	Toilet, ENTIRE CONSIST, MET BY MECHANICAL A/C WATER ISSUE ON TRAIN
2151	WAS	54	CAR	24	CAR	24	BOS-BOS	AM	Electrical failure, 3361 NG ND, Had to de-prepare and re-prepare set due to mechanical issues with cafe car.
2159	WAS	21	DMW	22	DMW	22	NHV-STM	MN	Waiting for MW clearance WORKING LIMITS STOP SIGN MP 54.6 TO 53.1 CP 255 MOBILE UNIT 803, Milepost, 54.6, 53.1
2160	BOS	59	DCS	47	DCS	35	NYP-XSH	AM	T.O.L, Other, LEGGETT, 100HZ POWER OFF AT LEGGETT INT
2171	WAS	22	DCS	45	DCS	45	XSH-NYP	AM	T.O.L, Other, LEGGETT, 100HZ POWER OFF AT LEGGETT INT
67	NPN	36	ENG	25	DMW	21	ALX-QAN	CS	Unable to contact dispatcher / MW foreman Control Point, cfp99.3
86	NYP	25	ENG	29	ENG	29	WDB-ALX	CS	Radio failure Radio transmission to the EIC not communicating clearly., 328
93	NFK	19	PTI	36	SMW	9	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 2 track a/c 3 track o/s between Davis & Ragan
94	BOS	30	DCS	24	DCS	21	NYP-XSH	AM	T.O.L, Other, LEGGETT, 100HZ POWER OFF AT LEGGETT INT
111	WAS	26	CTI	29	CTI	12	BWI-NCR	AM	Follow, MARC, 419, Control Point, .
125	NPN	22	ENG	41	ENG	41	WAS-WAS	AM	HEP, 369 DX AG, NO HEP, REPLACED WITH DSL 336
148	SPG	44	DCS	53	DCS	53	NYP-XPB	AM	T.O.L, Other, LEGGETT, 100HZ POWER OFF TOL AT LEGGETT INT
171	RNK	35	CTI	30	OTH	9	WIL-XPV	AM	Lost time - N.A.R., PRT
176	BOS	21	SMW	20	DCS	18	NYP-XSH	AM	T.O.L, Other, LEGGETT, 100HZ POWER OFF TOL AT LEGGETT INT
179	PHL	56	DCS	42	DCS	42	XSH-NYP	AM	Power switch failure, Other, XHR-XHR, NECESSARY TO REVERSE TO OPR IN LINE 2 A/C 707 SWITCH FAILURE AT HAROLD
197	WAS	17	SMW	15	SMW	15	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Davis & Ragan, followed 193
53	SFA	39	FTI	70	CTI	37	XDD-XSF	FR	Per Schedule Bridge, Lake Monroe, Control Point, VSMF, Sunrail, P308, Sunrail, P310

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/11/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
609	HAR	23	SVS	30	SVS	30	PHL-PAO	AM	Unplanned Wye, WYE ON OUTBOUND A/C BAD C/C 9645	
644	NYP	12	DCS	11	DCS	11	PHL-XHM	AM	Restrictive signal(s) from unknown cause, OPERATE 4 TRACK A/C TOL 2 AND 3 TRACKS, Control Point, MANTUA	
650	NYP	15	POL	10	POL	10	TRE-TRE	AM	On-train police or DEA activity, PSNGR REMOVAL	
656	NYP	39	SVS	45	SVS	45	PHL-XHM	AM	Unplanned Wye, WYE OUT OF PENN A/C CAB SIGNAL FAILURE ON THE 9645	
658	NYP	Trn Cancelled	CCR	10	CCR	10	HAR-MID	AM	Cab signal failure, 9647, CABS HELD AT RESTRICTING FROM HARRISBURG ALL THE WAY TO ABOUT MP 101	
19	NOL	36	ENG	78	ENG	78	NYP-NWK	AM	Other electrical failure, 657 EX ES, DISABLED IN NORTH TUBE	
686	BON	11	RTE	5	RTE	5	DHM-DHM	CS	Dispatcher hold Held to copy EC-1 for Main st Plaistow., Other, Durham Station	
63	TWO	32	OTH	9	OTH	7	NYP-XSD	AM	Lost time - N.A.R.	
237	ALB	43	CTI	24	CTI	24	CRT-POU	MN	Meet Sat and waited for a northbound metro north train... we are also going north. Then followed train to co 72, metro north, Control Point, 61	
1246	NYP	58	CTI	46	CTI	23	RHI-XCP	MN	Blocked from station track Held at 75 due to commuter train traffic in POU station, MNRR, Control Point, cp75	
75	CLT	20	TEN	24	TEN	15	KAN-CLT	NS	Failure of diesel engine NC1984	
76	RGH	167	TRS	165	TRS	165	CYN-RGH	NS	Trespasser strike Milepost, 161.2, 161.2	
78	RGH	45	TRS	28	TRS	28	DNC-DNC	NS	Trespasser strike Held for strike ahead of us on train 76, Milepost, 54.7, 54.7	
89	SAV	33	FTI	53	FTI	18	CHS-YEM	CS	Meet Xover main to 2 Trk running on approach to all stop waiting, Control Point, Berry Hill, CSXT 410, Mixed	
97	MIA	57	SVS	49	POL	45	XVG-ALX	CS	Right of Way police hold POLICE HOLD) 97 (10) HOLDING L'ENFANT STATION FOR POLICE HOLD REGARDING SUSPECT BEING CHASED IN THE AREA.	
41	MIA	173	FTI	120	FTI	31	SAV-XJG	CS	Follow MIXTURE OF APPR, ADV APPR, AND CLR SIGNALS, Milepost, 503.2, 543.6, I 031/10	
6	CHI	423	FTI	258	DMW	90	GSC-GSC	UP	Waiting for MW clearance MOW Track Overstay., Other, GSC	

Amtrak Endpoint OTP Details

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
529	SJC	14	PTI	14	PTI	13	GAC-SCC	UP	Routed into siding Amtk530north, Control Point, expressway
536	SAC	82	MBO	85	MBO	85	DAV-SAC	UP	For maritime traffic Bridge stuck open . Waited for bridge maintenance ., Other, I street bridge
538	ARN	43	TRS	27	TRS	27	FFV-DAV	UP	Trespasser on tracks at DAV. Control Point, rv075
540	SAC	28	POL	25	POL	25	FFV-DAV	UP	Police closed tracks at station for removal of trespasser
547	SJC	73	DCS	74	DCS	72	SAC-SAC	UP	Drawbridge stuck open I street bridge stuck open, waiting at Sacramento station until bridge closed., Control Point, RV989
50	NYP	No OS Rpt	ENG	180	ENG	168	CHI-CHI	AM	Set out defective locomotive Burnt radiator fan connection, 196
503	EUG	29	RTE	40	RTE	33	KEL-VAN	BN	Line manual or spring switch Control Point, woodland
504	SEA	20	PTI	23	PTI	14	PDX-VAN	BN	Meet Amtk 503, Control Point, Willamette River Br
505	PDX	22	PTI	12	PTI	10	XA4-XTW	BN	Meet amtrak 500, Control Point, sumner
516	VAC	56	FTI	47	FTI	39	X8B-XF2	BN	Follow Followed from the border to Colebrook and then after copying a 567.2 from BCR caught up to the same train at Townsend, Control Point, Colebrook, Control Point, Mud Bay west, Control Point, Townsend, BNSF 4039, Local
517	PDX	68	CAR	43	CAR	43	SEA-SEA	BN	Broken suspension on car 7561 7561
58	CHI	126	DSR	126	FTI	37	BRH-HAZ	CC	Meet cn2316, Control Point, wesson jct
59	NOL	78	DSR	107	DSR	34	MCB-HMD	CC	Per bulletin Milepost, 807.1, 807.3, 10, main 1, Milepost, 808.4, 808.8, 60, main, Milepost, 814.3, 814.7, 25, main, Milepost, 823, 849, 40, main, Milepost, 842.26, 842.46, 30, main, Milepost, 854.3, 854.5, 30, main, Milepost, 854.5, 856.2, 25, main
14	SEA	40	DSR	53	ENG	37	LAX-LAX	SC	Locomotive Position Swap Swapped trail and lead locomotive positions, 205, 329
7	SEA	94	ENG	173	ENG	133	WGL-WFH	BN	Air / Brake 337
27	PDX	-42	SVS	15	SVS	11	VAN-PDX	BN	Wye train at Vancouver

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	25	DSR	48	DSR	34	GLE-FTW	BN	Per bulletin Milepost, 406.5, 409, 60, m, Milepost, 405.5, 406.7, 60, m, Milepost, 405.9, 405, 60, m, Milepost, 404.1, 403.9, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.4, 400.2, 60, m, Milepost, 399.8, 399.2, 60, m, Milepost, 397.8, 397.1, 60, m, Milepost, 39
822	OKC	50	FTI	44	FTI	29	FTW-GLE	BN	Cross Traffic BN 5924, Milepost, 355.6, 355.6
338	CHI	28	CTI	29	CTI	27	GLN-XWA	ME	Follow Metra, 2140, Milepost, 17.4, 2.9
350	PNT	24	DSR	23	PTI	15	XB0-XA5	MI	Meet 353, Siding, albion
351	CHI	18	DSR	26	MBO	18	XPI-XH6	NS	For maritime traffic Bridge, 503
562	SAN	37	CTI	22	CTI	12	OSD-SOL	SN	Follow nctd, Milepost, 226, 241
765	SLO	44	PTI	37	PTI	37	X3G-LPS	UP	Meet Meet Amtrak 786, 786, Siding, Sudden
769	GTA	33	CON	23	CON	23	IRV-IRV	SC	Hold for thruway bus
770	SAN	23	CON	35	CON	35	OSD-OSD	SN	Hold for bus with passengers from train
774	SAN	56	DCS	16	CTI	11	SOL-SOL	SN	Meet NCTD, 637, Other, Solana beach station
777	SLO	52	CON	38	CON	38	IRV-IRV	SC	Hold for bus with passengers from train
782	LAX	18	PTI	37	PTI	37	GTA-GTA	UP	Meet 14, Control Point, CO 358
785	GTA	27	CON	29	CON	29	IRV-IRV	SC	Hold for bus with passengers from train OSD-IRV
790	SAN	72	CON	82	CON	80	OSD-OSD	SN	Hold for bus with passengers from train Hold for busses from SNA.
702	BFD	46	FTI	23	DSR	13	COC-WAC	BN	Per bulletin Milepost, 942.4, 942.3, 45, main, Milepost, 925.8, 921.5, 30, main
704	BFD	58	PTI	41	CAR	26	SAC-SAC	UP	Door C9015, Couldn't get a door light, doors were closed and working, message said switch 2 door lock failure, control switch defective, or wiring is faulty, take door out of service. Mechanical came out and fixed it
710	BFD	34	PTI	32	PTI	14	RIC-MTZ	UP	Meet AMTK 529, Control Point, Costa
711	OKJ	17	DSR	20	FTI	6	BFD-WAC	BN	Meet Control Point, E Kit Fox, BNSF 6847 E
712	BFD	21	FTI	20	RTE	19	MOD-TRK	BN	Held us for amt 713 which had just left MCD 10 min earlier. Shuffle, Siding, denair
713	OKJ	21	DSR	13	FTI	10	BFD-WAC	BN	Meet 5210 bnsf freight, Siding, e. wasco, BNSF freight
714	BFD	43	DSR	30	FTI	10	COC-WAC	BN	Meet bnsf 3876, Siding, angiola

Amtrak Endpoint OTP Details

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
715	OKJ	21	DSR	24	DSR	9	WAC-COC	BN	Per bulletin Milepost, 921.5, 925.8, 30, MT
716	BFD	170	TRS	122	TRS	122	SKN-MOD	BN	Trespasser strike Milepost, 1096.6, 1096.6
717	OKJ	70	TRS	70	TRS	44	MOD-MOD	BN	Trespasser strike Control Point, riverbank
718	BFD	103	ADA	16	ADA	16	TRK-TRK	BN	Vision / hearing-impaired Visually impaired passenger was not assisted by TA at Modesto. Passenger missed station stop. Family picked her up at Denair. We waited for her family to arrive per Road Foreman Lauren Crawford. Causing delay.
22	CHI	63	WTR	98	FTI	22	MHL-TXA	UP	Meet KCS interlocker waiting on freight train to pass, Control Point, R03, UP, UP
390	CHI	32	FTI	40	FTI	36	KKI-HMW	CC	Follow Stopped at HMW on m3 behind e281, e281, Control Point, hmw
391	CDL	23	FTI	22	FTI	22	HMW-KKI	CC	Meet Three way meet, Control Point, peotone, cn2766, cn2935
318	CHI	16	DSR	24	PTI	18	LCN-BNL	UP	Meet Amtk21, Siding, Athol
319	KCY	53	DSR	40	PTI	12	BNL-LCN	UP	Meet AMT 22, Siding, McLean

Amtrak Initial Terminal Details

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/11/2026

Terminal	Train	Date	Late	Delay	Cause
BON	683	09/11	1		
BOS	65	09/11	9	9	Planned set out / pick out of locomotives, cars or section of train, 65 may have a short delay departing South Station due to the DTMF switch in the yard malfunctioning. The crew is hand lining the route out of the yard
BOS	2151	09/11	24	24	Electrical failure, 3361 NG ND, Had to de-prepare and re-prepare set due to mechanical issues with cafe car.
BRK	680	09/11	3	3	HEP Resolving HEP issue when departing the BLF, 96
HAR	648	09/11	2	2	Engineer restroom break
NHV	470	09/11	6	6	Waiting for MW clearance, Milepost, nhv, nhv, Late into NHV sta.
NYP	69	09/11	6	6	Passenger and/or baggage, HEAVY LOADING
NYP	97	09/11	13	13	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR 4 COACH CARS OFF AM98 TO COMPLETE CONSIST
NYP	131	09/11	8	8	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING WITH ONLY 1 ENGINE
NYP	291	09/11	4	4	Passenger and/or baggage, LOADING
NYP	647	09/11	2	2	Passenger and/or baggage, LOADING
NYP	2107	09/11	2	2	Meet, AM230, Other, NYP, CONGESTION A/C LATE AM230
NYP	2190	09/11	6	6	OCS/ET defect, HELD IN NYP A/C WAITING FOR POWER TO BE RESTORED ON NO.2 TRK BETWEEN LEGGETT AND CP 216
PHL	601	09/11	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF YARD
PHL	605	09/11	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RGH	71	09/11	4	4	HEP Hep failure both engines. Had to swap equipment., NC1810, NC1984
WAS	134	09/11	3	3	Passenger and/or baggage, PAX BOARDING AT DEP TIME.
WAS	182	09/11	4	4	Other late crew, Delay in block, no applicable reason given by crew
WAS	2108	09/11	11	11	Disabled train ahead, Other, PHL, 2103 ARRIVED LATE DUE TO ISSUES IN CAFÉ CAR IN PHL
CHI	21	09/11	24	24	PER GLASSHOUSE DELAY ON ENGINE 55
CHI	41	09/11	76	76	Late engine Off inbound 4, 58
CHI	339	09/11	4	4	Service, turn, or wye train 338
SAS	22	09/11	330	5	PTC - Initializing PTC (no failure)
SAS	22	09/11	330	325	Service, turn, or wye train 21, Train 21 arrived late. 422 cars attached. Mechanical inspection

Amtrak Initial Terminal Details

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/11/2026

Terminal	Train	Date	Late	Delay	Cause
BFD	701	09/11	1		
BFD	703	09/11	3	3	Passenger and/or baggage Late arriving city bus, 7 pax on. One non-pax off.
BFD	711	09/11	1	1	Door C9303
BFD	713	09/11	4	4	While perform class 2 brake test. We couldn't get a set due to BFD mechanical cutting out the air to the loco. Had to walk the train and trouble shoot C2123
GTA	782	09/11	37	37	Meet 14, Control Point, CO 358
OKJ	536	09/11	2	2	Follow Had to follow 716 out of yard. And then waited for 541 to come into jacklondon., amt541, amt 716, Control Point, n jack
OKJ	540	09/11	7	7	Meet 538, Control Point, ni007
OKJ	716	09/11	23	23	Routine inspections
OKJ	718	09/11	7	7	Meet 545, Control Point, north jack london
PDX	500	09/11	3	3	Mobility Impaired 2 Lifts and 4 people needing redcap assistance
SAC	547	09/11	72	72	Drawbridge stuck open I street bridge stuck open, waiting at Sacramento station until bridge closed., Control Point, RV989
SAC	704	09/11	26	26	Door C9015, Couldn't get a door light, doors were closed and working, message said switch 2 door lock failure, control switch defective, or wiring is faulty, take door out of service. Mechanical came out and fixed it
SEA	8	09/11	78	78	Service, turn, or wye train 7

Eastern Region

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	87.9	91.0	90.2	58	7
SEPTA	95.0	85.9	90.9	91.5	213	30
NJT-NED	95.0	No Data	No Data	88.6	No Data	No Data
NJT-SED	95.0	100	98.9	97.2	24	0

Operating Highlights

Train 76(11) East of Cary, NC - Trespasser Incident

11SEP26: At 8:46 p.m. train 76(11) operating with engines NC1984, NC1810, and 94 customers onboard fatally struck a trespasser 4 miles east of Cary, NC on the CSX Aberdeen subdivision at milepost 161.0. The incident occurred in Wake County in the city of Raleigh, NC. Headend power remained operational and no injuries were reported by the crew on customers onboard. The incident occurred on the main tracks and not at a grade crossing. Amtrak management was on scene approximately 9:20 p.m. to assist along with Raleigh police department. The scene was clear at 11:20 p.m. and all train traffic was released restricted max 10mph in the area.

National Response Center Number: 1473384

Train	Delay	Comment
76(11)	2'45"	
78(11)	28"	
41(10)	30"	

Train 658(11) Lancaster, PA - Engine Failure

11SEP26: Train 658(11) operating with engine 635, cab car 9647, and 94 customers onboard terminated Lancaster, PA due to main res and traction motor faults on engine 635. All customers were transferred to train 626(11) at Lancaster and any customers from Philadelphia to New York were able to board next available services.

Train	Delay	Comment
658(11)		TERM LNC

Leggett Interlocking East of New York, NY - Signal

11SEP26: Due to 100HZ power loss in Leggett Interlocking milepost 9.5 at 6:20 p.m., all east and westbound traffic was affected operating through the area until it was resolved. All trains received Rule 241 to operate through. The issue was resolved around 7:38 p.m.

Train	Delay	Comment
2160(11)	35"	
2171(11)	45"	
148(11)	53"	

Train 291(11) East of Albany, NY - Routing

11SEP26: Train 291(11) operating with locomotive 600, 4 cars, and 197 customers onboard was delayed 20 miles east of Albany, NY on the Amtrak Hudson Line operating a different track route due to the 12 switch being on center at CP124.

Train	Delay	Comment
291(11)	47"	

Train 609(11) Philadelphia, PA - Cab Car Failure

11SEP26: Train 609(11) operating with locomotive 620, 4 cars, cab car 9645 and 165 customers was delayed at Philadelphia due to needing to wye the train resulting from the train being dispatched from New York with non-compliant cab signals due to a failed test in the yard. After the train completed the move around the wye train 609(11) was able to continue without further delay.

Train	Delay	Comment
609(11)	30"	
656(11)	46"	

Train 90(11) North of Fayetteville, NC - Freight Train Interference

11SEP26: Train 90(11) operating with locomotive 353, 7 cars, and 99 customers was delayed 1 mile north of Fayetteville, NC at MP 210 on the CSX South End subdivision due to freight train interference meeting CSX491 at control point AR. Once the CSX freight passed an open route was established and train 90(11) was able to proceed.

Train	Delay	Comment
90(11)	33"	

CSX Heat Orders - Weather

11SEP26: CSX has imposed heat orders in effect between 1pm and 7pm for the following subdivisions: Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
41(09)	52"	
97(10)	23"	
40(11)	45"	
52(11)	07"	
98(11)	26"	

Train 41(09) South of Savannah, GA - Freight Train Interference

11SEP26: Train 41(09) operating with locomotives 125-199, 10 cars and 185 customers was delayed 12 miles south of Savannah, GA due to freight train interference. Train 41(09) followed CSX IO31-10 from Burroughs interlocking to Burch interlocking and were then able to cross over to the No.2 track. Once clear on No.2 track train 41(09) was able to proceed without further delay.

Train	Delay	Comment
41(09)	55''	

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	26-FOI-00757 00000008815 "UNCLASSIFIED" 9/29/2026
78(03)	50"	Turn of Late 77(03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 43(11) Passenger Removal at Tyrone, Pennsylvania – Medical***

11SEP26, Passenger on PNR D7810E, traveling from Harrisburg, PA to Tyrone, PA, was removed from the train by Amed. The passenger fell down the steps onboard. The passenger couldn't get up after taking a fall. Amtrak Police notified.

Delay: 43 (11) 11"

Western Region

Operating Highlights

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Train 2/422(11) Ontario, CA - Police Related

12SEP26: Train 2/422(11) was delayed at Ontario, CA /MP520.2 on the UPRR Alhambra Subdivision, due to a police hold on all tracks to search for an active shooter near the tracks at MP526.47. Once hold was released, Train 2/422(11) was able to proceed east. During this delay, UPRR advised that a freight was disabled blocking W. Garnet/MP587.9 Yuma Subdivision, resulting in the inability to make the Palm Springs (PSN) stop. Three passengers were notified by crew onboard and detrained at Ontario during the extended delay. All scheduled to board were notified and given the option to rebook another day.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(11)	1'40"	

Train 28(11) Bingen-White Salmon, WA - Freight Train Interference

12SEP26: Train 28(11) was delayed at East Bingen siding/ MP78.2 on the BNSF Fallbridge Subdivision, 2.1 miles east of Bingen-White Salmon, WA station, due to meeting freight unit BN4725.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(11)	46"	

Train 538(11) West of Davis, CA - Police Related

12SEP26: Train 538(11) was delayed at RV075 West Davis /MP75.4 on the UPRR Martinez Subdivision 0.1 miles west Davis, CA station, due to a police hold on all tracks at Davis to remove a trespasser reportedly on the tracks. Train 540(11) was also delayed due to this, held at MP74.8. Once the tracks were released, both trains were able to proceed.

Service Recovery- 20% Cafe discounts were provided onboard both trains.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
538(11)	27"	
540(11)	25"	

Train 547(11) Sacramento, CA - I Street Bridge Malfunction

12SEP26: Train 547(11) was delayed departing Sacramento, CA due to the I Street Bridge at MP 88.6 on the UPRR Martinez Subdivision, malfunctioned by being stuck in the open position, and unable to lock. Amtrak Management, UPRR SR Signal Maintainer and Management personnel were all dispatched to the scene to troubleshoot and resolve the issue. As a result, train 547(11) was held at at Sacramento, CA (SAC) and Train 536(11) was held at MP87.8. Once the bridge was lined and locked closed, both trains were able to proceed.

Service Recovery- 20% Cafe discounts were provided onboard both trains.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
547(11)	1'12"	
536(11)	1'25"	

Train 6(09) West of Granby, CO - Engine Failure

10SEP26: Train 6(09) was delayed at MP141.3 west of Granby CO station on the UPRR Glenwood Springs subdivision due to engine 15 shutting down. Crew was able to reset the engine and get it started. Train 6(09) was back on the move at 440PM MT. Train 6(09) was delayed again at MP103.6 west of Granby, CO. due to engine 15 shutting down for a second time. Crew called in to troubleshoot with CNOC mechanical. The crew was able to get the engine restarted for a second time and was back on the move at 626PM MT. A BNSF Freight engine was requested to be added at Denver CO station and engine 7757 was set out for train 6(09). Train 6(09) arrived to Denver CO station and added BNSF freight engine 7757. Train 6(09) departed Denver CO station at 1107PM CT 4 hours and 8 minutes late after completing their daily inspections.

11SEP26: Train 5(11) was delayed departing Ottumwa, IA/MP279.8 on the BNSF Ottumwa subdivision due to the late sign up of the crew.

Train	Delay	Comment
6(09)	1'07"	
6(09)	35"	Daily Inspections
6(09)	19"	Add Freight
5(11)	1'05"	
6(09)	35"	Operating with freight OTM-CHI

Train 8(11) Seattle, WA - Initial Terminal Delay

11SEP26: Train 8(11) was delayed departing Seattle, WA due to the normal turn and servicing of equipment from late inbound Train 7(09), that arrived Seattle 1 hour and 34 minutes late.

Train	Delay	Comment
8(11)	1'18"	

Train 6(10) East of Fort Morgan, CO - Temporary Speed Restrictions

11SEP26: Train 6(10), with 156 customers onboard, was delayed between Fort Morgan, CO/MP646.2 and McCook, NE/MP287.8 beginning on the BNSF Brush subdivision operating through temporary speed restrictions. Once clear of the affected area, train 6(10) continued east.

Train	Delay	Comment
6(10)	31"	

Train 7/27(11) West of Winona, MN - Freight Train Interference

11SEP26: Train 7/27(11), with 281 customers onboard, was delayed between Midland West/MP340.0 and Frontenac East/MP361.0, beginning 32 miles west of Winona, MN/MP308.2 on the CPKC River subdivision following CP freight CP/7459. The freight had been involved in a trespasser strike. Once clear of the affected area, train 7/27(11) continued west.

Train	Delay	Comment
7/27(11)	32"	

Train 21/421(11) South of St. Louis, MO - Signal Issues

11SEP26: Train 21/421(11), with 114 customers onboard, was delayed between Wickes/MP19.7 and Riverside/MP26.3, beginning 18.2 miles south of St Louis, MO/MP1.5, on the UP Desoto subdivision due to signal issues. Once clear of the affected area, train 21/421(11) continued south.

Train 19(10) South of Slidell, LA - Drawbridge Open

11SEP26: Train 19(10) 26-FOI-00757 119 00000008815 00000008815 UNCLASSIFIED, was delayed holding for the North Drawbridge/MP173.4, 6 miles south of Slidell, LA/MP167.3, on the NS N.O.&N.E. subdivision to close. Maintainers arrived on the scene and inspected the bridge. Once the track was opened, train 19(10) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(10)	1'10"	

Train 716(11) West of Modesto, CA - Trespasser Strike

11SEP26: At approximately 5:00 PM PT, Train 716(11), CC/C6963, 6 cars, E/C2004, struck a trespasser 5.1 miles west of Modesto station at milepost 1096.6 in Riverbank, CA in Stanislaus county on the BNSF Stockton Subdivision, on single main track. The individual sustained undisclosed injuries and was treated at the scene. No injuries were reported among the 135 passengers or crew, and the train incurred no damage. Weather was sunny and 93°F. Crew requested and granted relief. A promotable trackmen took the train into Bakersfield. The engineer was relieved at the scene. Stockton Police, Fire Department, and Amtrak personnel conducted the investigation. Amtrak Police department also responded to the scene. After clearance, the train continued to Modesto. The scene was not released upon departure account of the ambulance that became stuck in the ballast behind 716(11). Once a tow truck arrived and cleared the ambulance, the tracks were released. Trains 717(11) and 704(11) were also delayed due to this.

National Response Center Number: 1473381

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(11)	2'02"	
704(11)	30"	
717(11)	1'10"	

Train 41(11) Chicago, IL - Late Engines

11SEP26: Train 41(11), with 238 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late release of the equipment by Chicago Mechanical. The engines off of inbound 40(09) were added to Amtrak train 5(11). Train 41(11) was given the engines off inbound 4(09), which needed to be serviced before going out again. Once train 41(11) was made up complete, the equipment shoved into the depot, boarded customers, and departed Chicago Union Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(11)	1'16"	

Train 765(11) South of Lompoc-Surf, CA - Passenger Train Interference

11SEP26: Train 765(11), carrying 119 customers onboard, was delayed at Sudden Siding/MP313.2 on the UPRR Santa Barbara Subdivision, 13.9 miles south of Lompoc-Surf, CA station, due to meeting Amtrak Train 786(11).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(11)	37"	

Train 6(09) West of Ottumwa, IA - Freight Train Interference

11SEP26: Train 6(09)26-FOI-00757 at 00000008815 with "UNCLASSIFIED" BNSF757 148/15, 9 coaches and 172 customers, was delayed 37 miles west of Ottumwa, IA, on BNSF Ottumwa subdivision, due to single tracking around milepost 316 due to a disabled freight on main track 1. 6(09) was delayed meeting a BNSF coal train. Once the freight cleared and route was made available, train 6(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(09)	1'20"	

Train 782(11) Goleta, CA - Initial Terminal Delay - Passenger Train Interference

11SEP26: Train 782(11) operating with cab car 6908, 5 cars, CDTX 2111, and 41 customers was delayed departing Goleta, CA on the UPRR Santa Barbara subdivision due to meeting Train 14(11). Once Train 14(11) cleared, Train 782(11) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
782(11)	37"	

Train 3(10) East of Lamy, NM - Passenger Train Interference

11SEP26: Train 3(10) operating with engines 22, 181, 322, 9 cars, and 150 customers onboard was delayed at milepost 830.5, 5 miles east of Lamy, NM on the BNSF Glorieta subdivision due to meeting Train 4(10). Once Train 4(10) cleared, Train 3(10) advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(10)	30"	

Train 821(11) North of Gainesville, TX - Temporary Speed Restrictions

11SEP26: Train 821(11), operating with engine 135 in the lead, engine 50 in the trail, 3 coaches, and 128 customers, was delayed operating between Gainesville, TX, and Fort Worth, TX, on BNSF Ft. Worth subdivision, due to temporary speed restrictions caused by track defects. BNSF has not given a time of repair.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
821(11)	34"	

Train 517(11) Seattle, WA - Car Failure

11SEP26: Train 517(11) operating with 178 customers onboard was delayed departing Seattle, WA on the BNSF Seattle subdivision due to broken suspension on car 7561. The equipment was swapped with the equipment from Train 500(11). The change in equipment resulted in overcapacity conditions for the train departing Seattle. One bus was secured to transport the customers.

WBS#: B.TR.100150.7167

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
517(11)	43"	

Train 516(11) North of Bellingham, WA - Freight Train Interference

11SEP26: Train 516(11) operating with engines 1408, 929, cab car 90253, and 160 customers onboard was delayed beginning at milepost 119.6, 26 miles north of Bellingham, WA on the BNSF New Westminster subdivision due to following BNSF freight train 4039 from milepost 119.6 to milepost 136.9. Once the freight train cleared, Train 516(11) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
516(11)	39"	

Train 503(11) South of Kelso-Longview, WA - Routing

11SEP26: Train 503(11) operating with cab car 90340, 3 cars, engine 186, and 152 customers onboard was delayed at milepost 118.3, 21 miles south of Kelso-Longview, WA on the BNSF Seattle subdivision due to the route through the area was not properly lined. The crew had to manually line the switch. Once the correct route was available, Train 503(11) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(11)	33"	

Train 1(09)/421(08) West of Palm Springs, CA - Trespasser Incident

11SEP26: Train 1(09)/421(08) operating with engines 147, 23, 9 cars, and 201 customers onboard was delayed at milepost 574.2, 14 miles west of Palm Springs, CA on the UPRR Yuma subdivision due to a vehicle on the tracks ahead. Once the vehicle was removed and the hold on the tracks lifted, Train 1(09)/421(08) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(09)/421(08)	40"	

Train 58(11) North of New Orleans, LA - Temporary Speed Restrictions

11SEP26: Train 58(11), with 50 customers onboard, was delayed between Southport Junction/MP908.6 and Greenwood, MS/MP122.5, beginning 4 miles north of New Orleans, LA/MP0.0 on the CN McComb subdivision following temporary speed restrictions. Once clear of the affected area, train 58(11) continued north.

Train 59(10) was also delayed by temporary speed restrictions while operating on the Yazoo and McComb subdivisions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(11)	47"	NOL-GWD
59(10)	1'04"	GWD-NOL

Train 390(11) South of Homewood, IL - Freight Train Interference

11SEP26: Train 390(11), operating with engine 4605, 7 coaches, and 268 customers, was delayed 1 mile south of Homewood, IL, on CN Chicago subdivision, due to meeting unknown freight, at Control Point Homewood. Once the freight cleared and a route was made available, train 390(11) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
390(11)	36"	

Train 58(11) North of Hammond, LA - Freight Train Interference

11SEP26: Train 58(11) was operating with engine 15, 7 coaches and 79 customers, was delayed 0.2 miles north of Hammond, LA, on CN McComb subdivision, due to meeting and following CN3906. Once the freight cleared and a route was made available, train 58(11) was able to proceed at normal speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(11)	30"	

Train 50(10) North of Indianapolis, IN - Freight Train Interference

11SEP26: Train 50(10) was delayed holding in the Jamestown siding/MP26.6, 26.8 miles north of Indianapolis IN station on the CSX Crawfordsville subdivision meeting CSX freight train.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(10)	35"	

Train 59(10) Memphis, TN - Freight Train Interference

11SEP26: Train 59(10), Operating with engine 339, 7 coaches, and 144 customers, was delayed departing Memphis, TN, on CN Memphis subdivision, due to freight crossing over the CN Junction ahead of them. The crew reported 3 unknown BN freights that cleared ahead. Once the freights cleared and a route was made available, train 59(10) was able to proceed.

59(10) was further delayed just north of Memphis due to meeting an additional freight at Control Point Darling.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(10)	22"	N/MEM
59(10)	30"	MEM

Train 790(10) East of Solana Beach, CA - Fatal Trespasser Strike

11SEP26: At approximately 1151P-PT Train 790(10) E/C2114, 6 cars, fatally struck a trespasser at MP245.61 on the San Diego Subdivision, San Diego Railway, 3.8 miles east of Solana Beach in San Diego County. The incident occurred on the right of way as trespasser was in the gauge when struck. Local authorities responded to the scene for an investigation. There were no injuries to the (75) passengers or crew. Track speed is 79pmh. Weather was 75°F and clear. The train crew requested and was granted relief at the scene. There was no reported damage to equipment. An Amtrak Trainmaster arrived to the scene after transporting the relief crew from San Diego. After re-crew and release from the local police and Coroner, Train 790(10) proceeded east.

National Response Center Number: 1473296

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
790(10)	3'27"	

Train 21(09) McGregor, TX - Freight Train Interference

11SEP26: Train 21(09), operating with engine 311/63, 7 coaches, and 61 customers, was delayed operating between McGregor, TX, and Temple TX, on BNSF Ft. Worth subdivision, due to following unknown BNSF freight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	43"	

Train 765(11) South of Lompoc-Surf, CA - Loss of Shunt

11SEP26: Union Pacific Railroad advised that Train 765(11) operating with E/C2110, C/34981, C/6805, C/C6352, C/6413, C/C6464, and CC/6903 experienced a loss of shunt on September 9th, 2026 at 12:37:24 PM-PST. This occurred south of Lompoc-Surf, CA station at MP 303.49 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 36 seconds. UPRR signal department was notified, and shunt testing will be performed.

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

05SEP26: High tides along the Southern California coast caused track indication issues between San Clemente Pier (MP 204.8) and CP SONGS (MP 209.5) on the Metrolink Orange Subdivision, requiring trains to operate at restricted speed and flag through the affected territory. Metrolink personnel conducted track inspections following each train movement through the area, resulting in significant congestion and delays to Pacific Surfliner service.

The incident resulted in the following service impacts and recovery actions:

- Train 581(05), carrying 244 customers onboard, was delayed at CP SONGS (MP 209.5) while awaiting authorization to proceed through the affected territory under restricted-speed conditions.
- Train 580(05), carrying 373 customers onboard, was delayed at San Clemente Pier Station (MP 204.9) before proceeding through the area under flag protection.
- Train 785(05), carrying 374 customers onboard, was delayed at CP SONGS while awaiting the passage of Train 580(05) before proceeding toward San Clemente Pier.
- Train 587(05), carrying 410 customers onboard, was delayed at CP SONGS while awaiting track inspections and clearance through the affected territory.
- Train 782(05), carrying 411 customers onboard, was delayed at CP Serra (MP 199.7) pending clearance through the affected territory.
- Train 584(05), carrying 167 customers onboard, was delayed at CP Serra after initially holding near Trabuco (MP 195.5).
- Train 588(05), carrying 106 customers onboard, experienced delays approaching the affected territory.
- Train 591(05) experienced delays approaching and departing Oceanside, CA, due to congestion created by the restricted operations.
- Train 786(05) encountered downstream delays while operating south toward the affected territory.

To mitigate customer impacts, the following service adjustments were implemented:

- Train 584(05) was terminated at San Juan Capistrano, CA, with customers accommodated on Train 588(05).
- Train 786(05) was terminated at Irvine, CA, after customers detrained at Laguna Niguel/Mission Viejo Station and were accommodated on Train 790(05).
- Train 593(05) was canceled, with customers accommodated on Train 595(05).
- Train 595(05) operated late after turning from the delayed Train 782(05).
- Equipment from Trains 584(05) and 786(05) was returned to Los Angeles, CA.

Additional service adjustments for Pacific Surfliner for 9/6

Trains 566(06), 567(06), 572(06), 573(06), 581(06), 584(06), 588(06), 587(06), 593(06) are canceled entirely with customers to next available services.

Train 782(06) is canceled LAX-SAN, customers to next services.

Train 761(06) is canceled SAN-LAX, customers to next services.

Train 794(06) is canceled LAX-SAN with alternate bus 3594 transportation.

Train 564(06) will term IRV.

Train 595(06) will orig IRV.

Train 580(06) will term IRV.

Train 579(06) will orig IRV.

the following trains will operate a bus bridge between Oceanside (OSD) and Irvine (IRV): 765(06), 562(06), 777(06), 774(06), 591(06), 790(06), 769(06), 770(06), 785(06),

and Monday 9/7.

07SEP26: Pacific Surfliner service resumed normal operations on September 7, 2026. All trains returned to the standard operating plan, with the exception of Train 567(07), due to only three trainsets being available in San Diego, CA.

26-FOI-00757 00000008815 "UNCLASSIFIED" 9/29/2026

The following service adjustments were implemented:

- Train 567(07) was canceled, with customers accommodated on Train 769(07).
- Equipment from Los Angeles 8th Street Yard was utilized to operate Train 572(07).

07SEP26: Tracks east of San Clemente Pier, CA, were reopened for service on September 8, 2026; however, high tides later caused washout conditions and recurring signal issues between San Clemente Pier and CP SONGS on the Metrolink Orange Subdivision. Metrolink personnel responded to replace ballast and conduct ongoing inspections of the affected track structure. As a result, Pacific Surfliner trains were required to operate at restricted speeds through the area, causing delays and congestion throughout the corridor.

The incident resulted in the following service impacts and recovery actions:

- Train 579(07), carrying 382 customers onboard, was delayed at Oceanside, CA, while maintenance personnel repaired the affected track. After departing Oceanside, the train incurred additional delays while holding at CP SONGS pending authorization to proceed through the affected territory.
- Train 581(07), carrying 364 customers onboard, was delayed at Oceanside, CA, while awaiting the reopening of the route.
- Train 782(07), carrying 405 customers onboard, was the last train authorized through the affected territory before Metrolink suspended train movements due to worsening tide conditions.
- Train 584(07), carrying 128 customers onboard, was held at Irvine, CA.
- Train 786(07), carrying 258 customers onboard, was held at Santa Ana, CA.
- Train 587(07), carrying 434 customers onboard, was held at Oceanside, CA.
- Train 588(07) was held at Los Angeles, CA.
- Train 591(07) was held at San Diego, CA.

To mitigate customer impacts, the following service adjustments were implemented:

- Trains 591(07), 593(07), and 595(07) were canceled.
- Trains 588(07) and 790(07) were canceled between Los Angeles and San Diego.
- Train 794(07) operated between Los Angeles and Irvine, where it terminated.
- Seven buses were secured to transport customers from Train 587(07) from Oceanside to Irvine.
- The same buses were then utilized to transport customers from Trains 584(07) and 786(07) from Irvine to San Diego, making all intermediate station stops.
- The buses were also used to accommodate customers from the canceled Trains 591(07), 593(07), and 595(07).
- Three additional buses were secured for customers requiring transportation south of Irvine from Trains 790(07) and 794(07).

08SEP2026: Pacific Surfliner Service Adjustments for Tuesday, September 8th and September 9th:

Trains 566, 567, 572, 573, 581, 584, 588, 587(08, 09, 10, 11), 593(08, 09, 10) and 595(11) are cancelled entirely. Customers will need to book next available services. Train 782 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, Customers to next available services.

Train 761 (08, 09, 10, 11) cancelled San Diego-Los Angeles, CA, Customers to next available services.

Train 794 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, with alternate BUS 3594 Transportation and an additional bus.

Train 564 (08, 09, 10, 11), will terminate in San Juan Capistrano, CA.

Train 595 (08, 09, 10), will originate in San Juan Capistrano, CA.

Train 580 (08, 09, 10, 11), will terminate in San Juan Capistrano, CA.

Train 579 (08, 09, 10, 11), will originate in San Juan Capistrano, CA.

Trains 765, 562, 777, 774, 591, 769, 770, 785, 786(08, 09, 10, 11) and 790(08, 09, 10) will operate a Bus Bridge between Oceanside, CA and Irvine, CA. (***)Please note: Trains will operate TO AND SERVICE San Juan Capistrano (SNC) Station- WILL THEN TURN AND MEET BUS BRIDGE AT T-11117 SECTION (**). "UNCLASSIFIED" 9/29/2026

Initially, there were 3 buses providing alternate transportation between Irvine, CA and San Juan Capistrano. Two additional buses were secured account of the high ridership.

11SEP26: Train 790(11) incurred a delay at Oceanside, CA waiting for the bus bridge to arrive from Santa Ana. The busses had initially staged at Irvine, CA and were later rerouted back to Santa Ana to pick up passengers.

WBS#: B.TR.100150.7150

Train	Delay	Comment
-------	-------	---------

584 (05)	Term SNC				
786 (05)	Term IRV				
593 (05)	Canceled				
785 (05)	50"				
587 (05)	2'19"	26-FOI-00757	00000008815	"UNCLASSIFIED"	9/29/2026
584 (05)	52"				
591 (05)	24"			late turn of 580	
591 (05)	2'17"				
782 (05)	3'35"				
588 (05)	2'52"				
790 (05)	2'11"				
595 (05)	2'36"			late turn of 782	
567 (06)	Canceled				
572 (06)	Canceled				
566 (06)	Canceled				
573 (06)	Canceled				
581 (06)	Canceled				
584 (06)	Canceled				
588 (06)	Canceled				
587 (06)	Canceled				
593 (06)	Canceled				
782 (06)	Canceled LAX-SAN				
761 (06)	Canceled SAN--LAX				
794 (06)	Canceled LAX-SAN				
564 (06)	Term IRV				
595 (06)	Orig IRV				
580 (06)	Term IRV				
579 (06)	Orig IRV				
765 (06)	Bus Bridge OSD-IRV				
562 (06)	Bus Bridge OSD-IRV				
777 (06)	Bus Bridge OSD-IRV				
774 (06)	Bus Bridge OSD-IRV				
591 (06)	Bus Bridge OSD-IRV				
790 (06)	Bus Bridge OSD-IRV				
769 (06)	Bus Bridge OSD-IRV				
770 (06)	Bus Bridge OSD-IRV				
785 (06)	Bus Bridge OSD-IRV				
786 (06)	Bus Bridge OSD-IRV				
567 (07)	Canceled				
581 (07)	1'01"				
579 (07)	1'50"				
782 (07)	2'24"				
584 (07)	41"			late turn 579	
584 (07)	Term IRV				
786 (07)	Term IRV				
587 (07)	3'47"			Bus Bridge OSD-IRV	
588 (07)	Canceled				
591 (07)	Canceled				
593 (07)	Canceled				
790 (07)	Term LAX				
595 (07)	Canceled				
794 (07)	Term IRV				
785 (07)	58"				
769 (08)	32"			IRV Bus Connect	
770 (08)	36"			OSD Bus Connect	
765 (08)	19"			IRV Bus Connect	
765 (09)	30"			IRV for bus connections	
769 (09)	25"			IRV Bus connects	
770 (09)	17"			OSD bus connects	
777 (09)	40"			OSD- Bus connection	
765 (10)	27"			IRV Bus Connections	
765 (11)	27"			IRV Bus Connections	
769 (11)	23"			IRV Bus Connections	
770 (11)	35"			OSD Bus Connections	
777 (11)	38"			IRV Bus Connection	
790 (11)	1'21"			OSD- Bus Connections	

Train 8/28(08) East of Havre, MT - Occupied Vehicle Strike

09SEP26: At 2:02 PM-MT, Train 8/28(08) operated with engines 325, 316, 10 cars, and 176 customers fatally struck an occupied vehicle at milepost 388.5, 42 miles east of Havre, MT on the BNSF Milk River subdivision. The strike occurred at DOTX 059431J. The crossing was equipped with crossbucks and signs or signals. The train maintained head end power and was intact on the rails. There were no reported injuries to the crew or customers. The weather was 77 degrees. The vehicle was stuck on the front of the equipment. Emergency services and road foreman responded to the scene. The crew requested relief, then agreed to take the train into Minot, ND. Once the vehicle was removed and investigation complete, the train was released to proceed. Train 7/27(08) was also delayed due to this, held at Dodson/MP359.3.

Upon departure, the crew reported a speedometer issue on engine E/325 from sustained damage from the strike, and were unable to operate with PTC. The crew was able to proceed with permission to operate from the BNSF host railroad, with PTC cut out causing additional delays operating at reduced speed. After discussion with the mechanical team, the decision was made to set out engine E/325 at Minot, ND and source a BNSF freight to add. BNSF 6662 was identified to be added to the train. Once the move was complete, Train 8/28(08) was able to proceed operating at freight speeds.

11SEP26: Train 8/28(10) was delayed departing Minot, ND due to adding the engine 325.

WBS#: B.TR.100150.7162

National Response Center Number: 1473174

Train	Delay	Comment
8/28(08)	2'28"	
7/27(08)	1'48"	
8/28(08)	34"	Add Freight MOT
8/28(08)	49"	W/MOT- Operating reduced speeds
8/28(10)	1'10"	Adding E/325 at MOT

Midwest Service Adjustments Chicago, IL - Engine Failure

08SEP26: Due to locomotive availability and foreseen maintenance. As a result, the following trains were cancelled in their entirety with customer service working to source alternate transportation:

Lincoln Service: 307(08), 302(09), 301(10), and 306(10). Three buses were confirmed for 307(08), 305(12), 300(13). Four buses were confirmed for 302(09). 4 busses were confirmed for 306(10). One bus confirmed for 301(10). Two buses confirmed for 300(11)

Pere Marquette: 370(09), 371(10), 370(11), and 371(12). Two buses were confirmed for 370(09). Two buses were confirmed for 370(11). Two buses were confirmed for 371(10). Three buses were secured for 371(12)

Carl Sandburg: 381(09), 382(09), 381(11), and 382(11), 381(13), 382(13). One bus was confirmed for 381(09). bus was confirmed for 381(11). One bus confirmed for 382(09). One bus confirmed for 381(13). One bus secured for 382(11)

Wolverine: 350(10) and 355(10). Two buses were confirmed for 350(10).

WBS#: B.TR.100150.7158

Maintenance of Way Highlights

Pacific Surfliner/Coast Starlight Scheduled M/W Work TWA 26-089

27JUL26:

To accommodate infrastructure work on the SCRRA Ventura and Orange subdivisions, NCTD San Diego subdivision and the UPRR Santa Barbara subdivision, Amtrak's Pacific Surfliner and Coast Starlight Services will be adjusted as follows:

COAST STARLIGHT

- Train 11(11Sep, 12Sep), which normally operates between SEA and LAX, will terminate at EMY.
- Train 14(12Sep, 13Sep), which normally operates between LAX and SEA, will originate at EMY.
- Alternate transportation will be provided between SAC and LAX via Gold Runner service for Train 11(11Sep, 12Sep)
- Alternate transportation will be provided between LAX and MTZ via Gold Runner service for Train 14(12Sep, 13Sep)

PACIFIC SURFLINER

- ALL Pacific Surfliner Trains on Saturday September 12th and Sunday September 13th are cancelled in their entirety with no alternate transportation.

AFFECTED TRAIN (ORIGIN DATE)

Train 11 (11Sep, 12Sep)
Train 567 (12Sep-13Sep)
Train 573 (12Sep-13Sep)
Train 579 (12Sep-13Sep)
Train 581 (12Sep-13Sep)
Train 587 (12Sep-13Sep)
Train 591 (12Sep-13Sep)
Train 593 (12Sep-13Sep)
Train 595 (12Sep-13Sep)
Train 757 (12Sep-13Sep)
Train 761 (12Sep-13Sep)
Train 765 (12Sep-13Sep)
Train 769 (12Sep-13Sep)
Train 777 (12Sep-13Sep)
Train 785 (12Sep-13Sep)
Train 14 (12Sep-13Sep)
Train 562 (12Sep-13Sep)
Train 564 (12Sep-13Sep)
Train 566 (12Sep-13Sep)
Train 572 (12Sep-13Sep)
Train 580 (12Sep-13Sep)
Train 584 (12Sep-13Sep)
Train 588 (12Sep-13Sep)
Train 770 (12Sep-13Sep)
Train 774 (12Sep-13Sep)
Train 782 (12Sep-13Sep)
Train 786 (12Sep-13Sep)
Train 790 (12Sep-13Sep)
Train 794 (12Sep-13Sep)

Coast Starlight - Scheduled M/W Work 26-090

03AUG26: To accommodate the construction in the structure, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep, 12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00757 00000008835 UNCLASSIFIED 9/29/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
8 (8)	MOT	325		Strike DMG//brake pipe//PTC/ P/UP by 8 (10)

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (9)	DEN	BNSF7557	E/15 running, loading, air brk comp	CHI	9/11/26
7 (9)	SPK	BNSF7773	E/337 stuck brakes	SEA	9/11/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00757

00000008815

"UNCLASSIFIED"

9/29/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
341 (11)	CHI	34113 D/Hing due to BYD toilets. inventory reduced with no overages.	No impact	0	34113
364 (11)	CHI	broken PA system. inventory reduced with no overage.	No impact	0	ID4019
5 (11)	CHI	Operating with snack car in lieu of bag coach.			35007
21 (11)	CHI	Operating with snack coach in lieu of standard coach. No passenger impacted by this.			35001
3 (12)	CHI	Operating w/standard coach in lieu of bag coach. Inventory for lower level seating has been increase to reflect this.			34088
6 (14)	EMY	Operating with snack coach in lieu of baggage coach.			35007
332 (12)	MKE	332(*12*) 34113 B/O toilets. Inventory reduced with 40 seats over.			34113
1340 (11)	MSP	34113 has a b/o vacuum pump/no toilets. Inventory has been reduced with 70 seats overcapacity.			34113
365 (12)	PTH	broken PA system. inventory reduced with no overage. chi will correct for 364(12).	No impact	0	ID4019
48 (10)	ROC	Conductor reported no HVAC in 25077 (enroute failure). sales capped with minimal overages. conductor reported no bus required.	No impact	0	25077
22 (11)	STL	Operating with snack coach in lieu of standard coach. No passenger impacted by this.			35001

Reverse Consists

Train Number	Station	Reason
190 (11)	PHL	Consist reversed Business class seat orientation may have changed At Front
95 (11)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (11)	BOS	Consist reversed Business class seat orientation may have changed At Front
137 (11)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
143 (12)	SOG	Consist reversed Business class seat orientation may have changed At Front
129 (11)	NYP	Consist reversed Business class seat orientation may have changed At Front
193 (11)	NYP	Consist reversed Business class seat orientation may have changed At Rear
174 (11)	WAS	Consist reversed Business class seat orientation may have changed At Front
148 (11)	WAS	Consist reversed Business class seat orientation may have changed At Front
184 (11)	WAS	Consist reversed Business class seat orientation may have changed At Rear
94 (11)	NFK	Consist reversed Business class seat orientation may have changed At Front