

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, July 05, 2026

Rules: 0-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/04/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	267	43	83.9%	1,169	183	84.3%	82,527	11,308	86.3%
Central Division	86.0%	73	6	91.8%	291	27	90.7%	20,330	1,845	90.9%
East Division	82.0%	127	26	79.5%	586	110	81.2%	43,147	6,719	84.4%
West Division	86.0%	67	11	83.6%	292	46	84.2%	19,050	2,744	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00580 00000008155 "UNCLASSIFIED" 7/7/2026

Endpoint Arrival Dates through 7/4/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	75,933	32,559	57%	386,648	176,490	54%	26,656,789	6,418,203	76%
Northeast Corridor	81%	33,274	16,579	50%	157,589	80,555	49%	12,005,375	2,864,606	76%
Acela	83%	5,745	2,953	49%	33,890	18,902	44%	2,370,912	621,274	74%
Northeast Regional	79%	27,529	13,626	51%	123,699	61,653	50%	9,634,463	2,243,332	77%
Richmond / Newport News / Norfolk	77%	9,733	7,397	24%	37,500	24,446	35%	2,989,354	838,749	72%
Springfield Shuttles	89%	509	134	74%	2,784	1,225	56%	171,821	25,672	85%
Roanoke	79%	2,312	1,608	30%	12,373	7,525	39%	906,228	182,898	80%
On Spine Northeast Regional	80%	14,975	4,487	70%	71,042	28,457	60%	5,567,060	1,196,013	79%
State Supported	80%	30,943	8,089	74%	177,526	59,993	66%	11,282,738	2,189,116	81%
Borealis	80%	466	0	100%	2,281	1,057	54%	153,043	31,423	79%
Capitol Corridor	90%	2,199	273	88%	15,048	2,210	85%	1,018,462	131,737	87%
Carolinian	70%	503	94	81%	4,885	3,667	25%	314,960	119,607	62%
Cascades	75%	1,951	839	57%	12,795	4,979	61%	700,647	193,600	72%
Downeaster	82%	1,058	381	64%	6,313	2,849	55%	402,651	48,157	88%
Empire	78%	3,857	1,246	68%	22,357	10,510	53%	1,476,606	325,159	78%
Adirondack	72%	323	274	15%	1,750	1,292	26%	88,212	26,785	70%
Ethan Allen Express	70%	395	227	43%	2,058	1,528	26%	153,063	49,160	68%
Maple Leaf	70%	771	318	59%	3,409	1,526	55%	178,742	68,546	62%
New York - Albany	85%	1,551	361	77%	9,744	3,415	65%	686,808	107,286	84%
New York - Niagara Falls	75%	817	66	92%	4,951	2,488	50%	366,170	72,261	80%
Berkshire Flyer	60%	0	0	-	445	261	41%	3,611	1,121	69%
Heartland Flyer	70%	160	2	99%	1,056	546	48%	56,658	21,048	63%
Hiawatha	90%	1,287	0	100%	7,643	856	89%	465,450	51,407	89%
Illinois	78%	1,900	902	53%	11,344	6,085	46%	673,534	182,154	73%
Carl Sandburg / Illinois Zephyr	85%	308	57	81%	2,160	1,083	50%	111,723	28,885	74%
Illini / Saluki	85%	655	381	42%	3,782	1,962	48%	237,475	56,011	76%
Lincoln Service	70%	937	464	50%	5,402	3,040	44%	324,336	97,258	70%
Keystone	92%	3,251	295	91%	25,528	7,731	70%	2,084,803	217,732	90%
Lincoln / Missouri	70%	357	175	51%	3,523	1,694	52%	212,196	105,589	50%
Mardi Gras Service	80%	339	122	64%	1,758	446	75%	111,912	22,590	80%
Michigan	70%	3,106	1,958	37%	10,109	5,780	43%	530,147	170,842	68%
Blue Water	70%	654	488	25%	2,397	2,213	8%	122,725	47,595	61%
Pere Marquette	85%	404	238	41%	956	420	56%	68,522	13,757	80%
Wolverine	70%	2,048	1,232	40%	6,756	3,147	53%	338,900	109,490	68%
Missouri	80%	104	0	100%	924	83	91%	60,156	13,340	78%
Pacific Surfliner	85%	8,860	1,306	85%	42,604	6,425	85%	2,114,698	332,037	84%
Pennsylvanian	80%	801	322	60%	3,714	1,989	46%	242,484	44,175	82%
Piedmont	80%	193	174	10%	1,106	694	37%	314,293	79,189	75%
Vermont	75%	551	0	100%	4,538	2,392	47%	350,038	99,330	72%
Long Distance	70%	11,716	7,891	33%	51,533	35,942	30%	3,329,409	1,362,018	59%
Auto Train	70%	793	398	50%	3,492	810	77%	212,406	71,692	66%
California Zephyr	70%	1,038	715	31%	4,164	2,415	42%	263,572	87,292	67%
Cardinal	70%	542	458	15%	1,089	981	10%	64,752	31,179	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,085	49,375	72%
Coast Starlight	70%	1,242	147	88%	5,065	1,096	78%	309,458	105,570	66%
Crescent	70%	440	440	0%	3,567	3,001	16%	253,217	74,503	71%
Empire Builder	70%	1,193	844	29%	5,195	3,460	33%	259,487	123,302	52%
Floridian	60%	1,005	1,005	0%	6,118	6,071	1%	436,148	289,528	34%
Lake Shore Ltd	73%	955	872	9%	4,674	3,485	25%	257,472	75,492	71%
Palmetto	70%	269	66	75%	3,639	3,055	16%	251,286	69,104	72%
Silver Meteor	70%	1,217	1,198	2%	4,481	4,187	7%	276,865	114,306	59%
Southwest Chief	60%	1,109	442	60%	4,216	3,194	24%	222,677	141,467	36%
Sunset Ltd	70%	0	0	-	1,216	768	37%	79,488	27,414	66%
Texas Eagle	70%	1,913	1,306	32%	4,617	3,419	26%	265,496	101,794	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000155 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through July 04, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	27,911	408,720	683	1,595,211	29,046,367	549

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,958	112,763	174	75,339	8,333,763	90
INFRASTRUCTURE PLANNED	135	1,436	112,763	127	80,394	8,333,763	96
FLEET RELIABILITY	90	4,601	408,720	113	257,598	29,046,367	89
TRAIN OPERATIONS	424	19,916	408,720	487	1,181,880	29,046,367	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/04/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	267	43	83.9%	1,169	183	84.3%	82,527	11,308	86.3%
Central Division	86.0%	73	6	91.8%	291	27	90.7%	20,330	1,845	90.9%
East Division	82.0%	127	26	79.5%	586	110	81.2%	43,147	6,719	84.4%
West Division	86.0%	67	11	83.6%	292	46	84.2%	19,050	2,744	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/04/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	267	43	83.9%	1,169	183	84.3%	82,527	11,308	86.3%
Central Division	86.0%	73	6	91.8%	291	27	90.7%	20,330	1,845	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	8	0	100.0%	525	18	96.6%
CHI	86.0%	26	1	96.2%	106	14	86.8%	7,345	878	88.0%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	8	0	100.0%	544	52	90.4%
FTW	92.5%	1	0	100.0%	4	1	75.0%	300	35	88.3%
GBB	-	-	-	-	-	-	-	1	1	0.0%
GRR	95.5%	1	0	100.0%	3	0	100.0%	262	8	96.9%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	8	1	87.5%	546	41	92.5%
LAX	89.5%	1	0	100.0%	4	0	100.0%	266	40	85.0%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	24	3	87.5%	1,622	100	93.8%
MOE	97.5%	2	0	100.0%	8	1	87.5%	553	9	98.4%
MSP	96.5%	1	0	100.0%	4	0	100.0%	270	5	98.1%
NOL	94.5%	4	1	75.0%	14	2	85.7%	1,164	55	95.3%
OKC	97.0%	1	0	100.0%	4	0	100.0%	271	6	97.8%
PDX	86.0%	4	2	50.0%	16	3	81.3%	1,098	110	90.0%
PNT	88.0%	3	0	100.0%	12	0	100.0%	715	58	91.9%
PTH	93.0%	1	0	100.0%	4	0	100.0%	265	10	96.2%
QCY	91.0%	2	0	100.0%	8	0	100.0%	538	39	92.8%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	4	0	100.0%	273	27	90.1%
SEA	85.0%	7	2	71.4%	28	2	92.9%	1,918	209	89.1%
STL	89.0%	4	0	100.0%	16	0	100.0%	1,073	90	91.6%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	8	0	100.0%	538	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	127	26	79.5%	586	110	81.2%	43,147	6,719	84.4%
ALB	88.5%	8	2	75.0%	31	2	93.5%	2,045	163	92.0%
BON	87.5%	4	1	75.0%	19	6	68.4%	1,331	146	89.0%
BOS	85.5%	16	1	93.8%	64	5	92.2%	4,704	567	87.9%
BRK	92.5%	4	0	100.0%	19	6	68.4%	1,320	90	93.2%
BTN	82.0%	1	0	100.0%	4	0	100.0%	263	39	85.2%
CLT	91.5%	2	0	100.0%	9	1	88.9%	1,350	133	90.1%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	8	2	75.0%	539	52	90.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/04/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	267	43	83.9%	1,169	183	84.3%	82,527	11,308	86.3%
East Division	82.0%	127	26	79.5%	586	110	81.2%	43,147	6,719	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	6	1	83.3%	38	3	92.1%	3,061	509	83.4%
HFD	-	-	-	-	4	0	100.0%	151	8	94.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	4	0	100.0%	273	34	87.5%
MIA	89.5%	2	1	50.0%	8	2	75.0%	547	62	88.7%
MTR	79.0%	1	1	0.0%	4	1	75.0%	260	47	81.9%
NFK	84.5%	2	1	50.0%	8	5	37.5%	629	114	81.9%
NFL	93.5%	2	1	50.0%	8	1	87.5%	558	23	95.9%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	4	0	100.0%	18	1	94.4%	1,424	224	84.3%
NPN	93.0%	1	1	0.0%	7	1	85.7%	520	36	93.1%
NYP	75.5%	33	6	81.8%	164	40	75.6%	11,218	2,502	77.7%
PGH	93.0%	1	0	100.0%	4	1	75.0%	275	20	92.7%
PHL	48.0%	4	2	50.0%	18	7	61.1%	1,418	684	51.8%
PIT	76.0%	-	-	-	1	1	0.0%	7	6	14.3%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	1	0	100.0%	4	0	100.0%	1,061	41	96.1%
RNK	83.5%	2	1	50.0%	8	1	87.5%	542	78	85.6%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAB	98.0%	1	0	100.0%	4	0	100.0%	263	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	-	-	-	3	0	100.0%	271	10	96.3%
SFA	88.0%	1	0	100.0%	4	0	100.0%	273	37	86.4%
SPG	92.5%	6	0	100.0%	22	1	95.5%	1,674	93	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	4	0	100.0%	263	56	78.7%
WAS	84.0%	21	7	66.7%	97	23	76.3%	6,693	864	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	67	11	83.6%	292	46	84.2%	19,050	2,744	85.6%
ARN	92.0%	1	0	100.0%	4	0	100.0%	275	19	93.1%
BFD	79.0%	6	2	66.7%	25	11	56.0%	1,711	352	79.4%
EMY	72.0%	1	1	0.0%	4	3	25.0%	280	87	68.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	12	2	83.3%	828	116	86.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/04/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	267	43	83.9%	1,169	183	84.3%	82,527	11,308	86.3%
West Division	86.0%	67	11	83.6%	292	46	84.2%	19,050	2,744	85.6%
LAX	89.5%	9	1	88.9%	38	5	86.8%	2,452	241	90.2%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	9	4	55.6%	45	13	71.1%	2,944	749	74.6%
PDX	86.0%	1	0	100.0%	4	0	100.0%	259	59	77.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	3	75.0%	60	7	88.3%	3,864	417	89.2%
SAN	90.5%	13	0	100.0%	52	2	96.2%	3,296	296	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	0	100.0%	4	2	50.0%	256	105	59.0%
SJC	89.0%	7	0	100.0%	28	0	100.0%	1,935	182	90.6%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	12	1	91.7%	591	61	89.7%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	4	0	100.0%	270	20	92.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		4	0	100.0%	275	54	80.4%	4	1	75.0%	273	118	56.8%
4		4	0	100.0%	274	42	84.7%	4	3	25.0%	274	182	33.6%
5	75	4	1	75.0%	273	44	83.9%	3	2	33.3%	269	65	75.8%
6	67	4	3	25.0%	272	80	70.6%	4	3	25.0%	272	85	68.8%
7		4	1	75.0%	264	36	86.4%	4	1	75.0%	257	62	75.9%
8		4	2	50.0%	264	113	57.2%	4	3	25.0%	263	152	42.2%
11		4	0	100.0%	275	50	81.8%	4	0	100.0%	269	54	79.9%
14		4	0	100.0%	276	41	85.1%	4	0	100.0%	274	83	69.7%
19	109	4	2	50.0%	274	67	75.5%	4	4	0.0%	272	63	76.8%
20	No OS	4	2	50.0%	274	20	92.7%	4	4	0.0%	274	51	81.4%
21	56	4	0	100.0%	271	22	91.9%	4	4	0.0%	270	66	75.6%
22		4	0	100.0%	272	25	90.8%	4	3	25.0%	270	65	75.9%
23		4	1	75.0%	277	6	97.8%	4	1	75.0%	275	70	74.5%
24		4	0	100.0%	277	14	94.9%	4	1	75.0%	276	44	84.1%
25	20	4	0	100.0%	276	3	98.9%	4	2	50.0%	274	71	74.1%
26		4	0	100.0%	276	5	98.2%	4	0	100.0%	274	52	81.0%
27		4	2	50.0%	262	17	93.5%	4	1	75.0%	258	82	68.2%
28	87	4	0	100.0%	258	59	77.1%	4	1	75.0%	258	52	79.8%
40	128	4	1	75.0%	270	39	85.6%	4	4	0.0%	269	136	49.4%
41	382	4	3	25.0%	270	105	61.1%	4	4	0.0%	268	200	25.4%
42		4	1	75.0%	276	21	92.4%	4	2	50.0%	274	44	83.9%
43	118	4	0	100.0%	275	41	85.1%	4	4	0.0%	275	60	78.2%
48		4	1	75.0%	274	54	80.3%	4	2	50.0%	274	40	85.4%
49		4	3	25.0%	274	70	74.5%	4	2	50.0%	274	54	80.3%
51	176	2	2	0.0%	114	51	55.3%	2	2	0.0%	110	39	64.5%
52		4	0	100.0%	273	37	86.4%	4	0	100.0%	272	61	77.6%
53	45	4	0	100.0%	273	34	87.5%	4	2	50.0%	272	87	68.0%
54		2	0	100.0%	102	6	94.1%	2	1	50.0%	102	14	86.3%
57	112	2	0	100.0%	101	4	96.0%	2	1	50.0%	101	7	93.1%
63		4	2	50.0%	277	119	57.0%	4	3	25.0%	273	143	47.6%
64	91	4	0	100.0%	275	63	77.1%	4	3	25.0%	275	94	65.8%
65	Cncld	3	0	100.0%	86	12	86.0%	1	0	100.0%	84	11	86.9%
66		4	1	75.0%	274	55	79.9%	4	0	100.0%	272	49	82.0%
68	43	4	1	75.0%	277	56	79.8%	4	4	0.0%	277	107	61.4%
69	34	4	0	100.0%	264	59	77.7%	4	2	50.0%	260	34	86.9%
71	19	4	0	100.0%	272	3	98.9%	4	4	0.0%	271	70	74.2%
78	62	4	0	100.0%	272	20	92.6%	4	3	25.0%	271	53	80.4%
79	78	4	0	100.0%	274	55	79.9%	4	4	0.0%	273	88	67.8%
80		4	1	75.0%	274	29	89.4%	4	3	25.0%	272	52	80.9%
82	50	2	1	50.0%	69	8	88.4%	2	2	0.0%	69	22	68.1%
87	46	2	0	100.0%	105	24	77.1%	2	2	0.0%	105	35	66.7%
89		4	1	75.0%	272	59	78.3%	5	3	40.0%	271	73	73.1%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
90		4	0	100.0%	272	10	96.3%	4	3	25.0%	271	40	85.2%
97	106	4	4	0.0%	274	177	35.4%	4	4	0.0%	272	80	70.6%
98	78	4	1	75.0%	274	22	92.0%	4	4	0.0%	272	84	69.1%
99	Cncld	2	0	100.0%	104	12	88.5%	0	0	0.0%	101	57	43.6%
101		2	0	100.0%	68	6	91.2%	2	0	100.0%	68	11	83.8%
103		2	0	100.0%	103	21	79.6%	2	0	100.0%	103	8	92.2%
109		2	0	100.0%	51	8	84.3%	2	0	100.0%	51	5	90.2%
118		2	2	0.0%	103	8	92.2%	2	0	100.0%	103	5	95.1%
124	127	2	1	50.0%	102	8	92.2%	2	2	0.0%	101	25	75.2%
126	24	2	1	50.0%	47	8	83.0%	2	2	0.0%	47	10	78.7%
127		2	1	50.0%	47	13	72.3%	2	0	100.0%	47	5	89.4%
128	133	2	0	100.0%	105	19	81.9%	1	1	0.0%	104	17	83.7%
135	175	2	0	100.0%	104	17	83.7%	2	2	0.0%	104	53	49.0%
140		2	0	100.0%	103	12	88.3%	2	1	50.0%	102	21	79.4%
143		2	0	100.0%	102	9	91.2%	2	1	50.0%	102	23	77.5%
144		2	1	50.0%	69	46	33.3%	2	0	100.0%	68	9	86.8%
146	48	2	1	50.0%	102	17	83.3%	2	2	0.0%	102	36	64.7%
147	No OS	2	0	100.0%	70	7	90.0%	2	2	0.0%	70	22	68.6%
150		2	0	100.0%	101	54	46.5%	2	1	50.0%	99	49	50.5%
151	464	4	1	75.0%	273	87	68.1%	4	4	0.0%	272	88	67.6%
152		2	0	100.0%	69	5	92.8%	2	1	50.0%	69	26	62.3%
153	56	2	2	0.0%	103	10	90.3%	2	1	50.0%	103	15	85.4%
155	147	2	1	50.0%	105	16	84.8%	2	2	0.0%	105	35	66.7%
156	157	2	0	100.0%	105	10	90.5%	2	2	0.0%	105	33	68.6%
158	283	2	2	0.0%	104	17	83.7%	2	2	0.0%	104	22	78.8%
160		2	0	100.0%	102	5	95.1%	2	0	100.0%	100	23	77.0%
161	57	2	0	100.0%	103	9	91.3%	2	2	0.0%	102	65	36.3%
162		2	0	100.0%	103	5	95.1%	2	1	50.0%	103	50	51.5%
164		2	0	100.0%	105	8	92.4%	2	1	50.0%	105	45	57.1%
165	65	2	0	100.0%	104	27	74.0%	2	2	0.0%	104	42	59.6%
167		2	0	100.0%	70	15	78.6%	2	1	50.0%	69	21	69.6%
168	59	2	1	50.0%	68	11	83.8%	2	2	0.0%	68	24	64.7%
169		2	0	100.0%	103	12	88.3%	1	0	100.0%	102	21	79.4%
194	22	2	2	0.0%	69	17	75.4%	2	2	0.0%	68	20	70.6%
195	17	2	0	100.0%	103	4	96.1%	2	2	0.0%	103	54	47.6%
230		4	0	100.0%	111	4	96.4%	4	0	100.0%	111	6	94.6%
232		4	0	100.0%	277	11	96.0%	4	0	100.0%	277	17	93.9%
233		3	0	100.0%	254	56	78.0%	3	1	66.7%	254	74	70.9%
234		4	1	75.0%	277	20	92.8%	4	0	100.0%	277	24	91.3%
235		4	0	100.0%	201	27	86.6%	4	3	25.0%	201	44	78.1%
236		4	0	100.0%	261	7	97.3%	4	0	100.0%	261	36	86.2%
237	115	4	0	100.0%	275	52	81.1%	4	2	50.0%	273	45	83.5%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
238	44	4	0	100.0%	201	19	90.5%	4	0	100.0%	200	14	93.0%
239		4	1	75.0%	276	73	73.6%	4	2	50.0%	275	32	88.4%
240		4	0	100.0%	276	20	92.8%	4	1	75.0%	274	45	83.6%
241		4	1	75.0%	277	69	75.1%	4	1	75.0%	277	67	75.8%
243		4	3	25.0%	213	58	72.8%	4	3	25.0%	212	29	86.3%
244		3	0	100.0%	254	10	96.1%	3	2	33.3%	254	40	84.3%
245		4	2	50.0%	158	29	81.6%	4	1	75.0%	157	18	88.5%
280		4	1	75.0%	277	12	95.7%	4	0	100.0%	277	50	81.9%
281		4	0	100.0%	277	29	89.5%	4	3	25.0%	277	50	81.9%
283		4	2	50.0%	277	66	76.2%	4	3	25.0%	277	55	80.1%
284		4	0	100.0%	277	10	96.4%	4	2	50.0%	275	44	84.0%
290	18	4	0	100.0%	277	48	82.7%	4	3	25.0%	275	94	65.8%
291		4	1	75.0%	276	76	72.5%	4	3	25.0%	274	61	77.7%
300	32	4	0	100.0%	261	19	92.7%	4	2	50.0%	259	58	77.6%
301		4	0	100.0%	275	9	96.7%	4	1	75.0%	272	51	81.3%
302		4	0	100.0%	262	31	88.2%	4	2	50.0%	258	74	71.3%
305	74	4	0	100.0%	265	28	89.4%	4	4	0.0%	261	106	59.4%
306		4	0	100.0%	273	15	94.5%	4	3	25.0%	272	74	72.8%
307	57	4	0	100.0%	265	35	86.8%	4	2	50.0%	262	72	72.5%
311		4	0	100.0%	275	23	91.6%	4	0	100.0%	270	50	81.5%
316	No OS	4	0	100.0%	272	16	94.1%	4	2	50.0%	269	66	75.5%
318	52	4	1	75.0%	276	27	90.2%	4	2	50.0%	273	126	53.8%
319	No OS	4	0	100.0%	277	17	93.9%	4	3	25.0%	275	148	46.2%
330		4	0	100.0%	235	4	98.3%	4	0	100.0%	235	13	94.5%
331		4	0	100.0%	277	29	89.5%	4	0	100.0%	277	40	85.6%
332		4	0	100.0%	277	14	94.9%	4	1	75.0%	277	40	85.6%
334		4	0	100.0%	277	9	96.8%	4	0	100.0%	276	36	87.0%
335		4	0	100.0%	277	30	89.2%	4	2	50.0%	275	45	83.6%
336		4	1	75.0%	277	9	96.8%	4	0	100.0%	275	25	90.9%
337		4	0	100.0%	277	17	93.9%	4	1	75.0%	273	34	87.5%
338		4	2	50.0%	277	43	84.5%	4	1	75.0%	275	82	70.2%
339		4	1	75.0%	277	47	83.0%	4	1	75.0%	277	49	82.3%
341		4	1	75.0%	266	36	86.5%	4	1	75.0%	261	36	86.2%
342		4	0	100.0%	277	21	92.4%	4	0	100.0%	275	53	80.7%
343		1	0	100.0%	39	3	92.3%	1	0	100.0%	39	9	76.9%
350	74	4	0	100.0%	258	17	93.4%	4	3	25.0%	253	139	45.1%
351		4	0	100.0%	260	25	90.4%	4	1	75.0%	258	69	73.3%
352		4	0	100.0%	244	20	91.8%	4	2	50.0%	238	73	69.3%
353		4	0	100.0%	219	12	94.5%	4	0	100.0%	213	35	83.6%
354	130	4	1	75.0%	258	29	88.8%	4	3	25.0%	254	92	63.8%
355	51	4	0	100.0%	271	27	90.0%	4	4	0.0%	264	89	66.3%
364		4	1	75.0%	266	61	77.1%	4	3	25.0%	260	93	64.2%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
365	28	4	0	100.0%	265	10	96.2%	4	4	0.0%	263	96	63.5%
370		4	1	75.0%	268	34	87.3%	3	1	66.7%	260	66	74.6%
371		3	0	100.0%	262	8	96.9%	3	1	66.7%	261	28	89.3%
380		4	0	100.0%	263	24	90.9%	4	3	25.0%	263	52	80.2%
381		4	0	100.0%	277	11	96.0%	4	2	50.0%	276	50	81.9%
382	75	4	0	100.0%	276	16	94.2%	4	3	25.0%	276	87	68.5%
383	105	4	0	100.0%	266	25	90.6%	4	2	50.0%	264	107	59.5%
390	21	4	0	100.0%	259	17	93.4%	4	2	50.0%	258	65	74.8%
391		4	0	100.0%	262	8	96.9%	4	3	25.0%	259	68	73.7%
392	25	4	0	100.0%	276	5	98.2%	4	4	0.0%	274	82	70.1%
393	42	4	0	100.0%	277	16	94.2%	4	4	0.0%	274	81	70.4%
400		2	0	100.0%	84	6	92.9%	2	0	100.0%	82	2	97.6%
405		2	0	100.0%	79	0	100.0%	2	0	100.0%	79	4	94.9%
448	39	4	2	50.0%	207	40	80.7%	4	3	25.0%	205	71	65.4%
449	33	4	1	75.0%	205	31	84.9%	4	4	0.0%	205	40	80.5%
450	33	2	0	100.0%	83	26	68.7%	2	2	0.0%	81	26	67.9%
460	29	2	0	100.0%	82	27	67.1%	2	2	0.0%	79	27	65.8%
461		2	0	100.0%	85	5	94.1%	2	0	100.0%	84	2	97.6%
463		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	0	100.0%
464		2	0	100.0%	82	16	80.5%	2	1	50.0%	80	25	68.8%
467		2	0	100.0%	44	1	97.7%	2	1	50.0%	43	3	93.0%
488		2	0	100.0%	88	21	76.1%	2	0	100.0%	80	11	86.3%
499		2	0	100.0%	81	11	86.4%	2	0	100.0%	78	6	92.3%
500	Cncld	4	1	75.0%	268	16	94.0%	3	0	100.0%	265	32	87.9%
502	Cncld	4	1	75.0%	275	16	94.2%	3	0	100.0%	271	56	79.3%
503	18	4	1	75.0%	273	26	90.5%	4	3	25.0%	267	77	71.2%
504	26	4	0	100.0%	277	17	93.9%	4	2	50.0%	275	84	69.5%
505	Cncld	4	1	75.0%	275	37	86.5%	3	2	33.3%	270	75	72.2%
506		4	1	75.0%	272	39	85.7%	4	1	75.0%	267	42	84.3%
507		4	0	100.0%	277	34	87.7%	4	2	50.0%	277	90	67.5%
508		4	0	100.0%	272	39	85.7%	4	0	100.0%	269	62	77.0%
509		4	0	100.0%	274	12	95.6%	4	0	100.0%	274	63	77.0%
511		4	0	100.0%	269	21	92.2%	4	0	100.0%	268	45	83.2%
516		4	0	100.0%	269	27	90.0%	4	2	50.0%	268	125	53.4%
517	65	4	0	100.0%	277	8	97.1%	4	4	0.0%	273	112	59.0%
518	23	4	0	100.0%	277	35	87.4%	4	3	25.0%	275	186	32.4%
519	20	4	0	100.0%	269	9	96.7%	4	1	75.0%	267	64	76.0%
562		4	0	100.0%	269	21	92.2%	4	0	100.0%	266	29	89.1%
564		4	0	100.0%	269	17	93.7%	4	1	75.0%	261	31	88.1%
566	28	4	0	100.0%	267	17	93.6%	4	1	75.0%	264	33	87.5%
567		4	0	100.0%	154	8	94.8%	4	0	100.0%	152	6	96.1%
572	16	4	1	75.0%	264	23	91.3%	4	2	50.0%	259	67	74.1%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		4	0	100.0%	267	40	85.0%	4	0	100.0%	260	44	83.1%
579		4	0	100.0%	154	8	94.8%	4	1	75.0%	149	27	81.9%
580		4	0	100.0%	269	14	94.8%	4	0	100.0%	264	21	92.0%
581		4	0	100.0%	269	43	84.0%	4	1	75.0%	267	55	79.4%
584	31	4	2	50.0%	153	19	87.6%	4	4	0.0%	149	86	42.3%
587		4	0	100.0%	264	15	94.3%	4	1	75.0%	255	39	84.7%
588		4	1	75.0%	154	13	91.6%	4	0	100.0%	153	22	85.6%
591		4	0	100.0%	268	18	93.3%	4	0	100.0%	262	29	88.9%
593		4	0	100.0%	263	37	85.9%	4	1	75.0%	245	28	88.6%
595		4	1	75.0%	264	42	84.1%	4	1	75.0%	261	47	82.0%
611		2	2	0.0%	40	28	30.0%	2	0	100.0%	40	4	90.0%
637		2	0	100.0%	56	6	89.3%	1	0	100.0%	55	4	92.7%
660		2	0	100.0%	75	11	85.3%	2	0	100.0%	75	25	66.7%
661		2	0	100.0%	103	11	89.3%	2	1	50.0%	102	38	62.7%
662		2	0	100.0%	42	0	100.0%	2	0	100.0%	42	1	97.6%
663	53	2	1	50.0%	75	11	85.3%	2	1	50.0%	75	7	90.7%
664		2	0	100.0%	74	6	91.9%	2	1	50.0%	74	7	90.5%
665		2	0	100.0%	75	8	89.3%	2	1	50.0%	75	20	73.3%
669	Cncld	2	0	100.0%	74	7	90.5%	1	1	0.0%	73	21	71.2%
670		2	0	100.0%	75	10	86.7%	2	1	50.0%	75	14	81.3%
671	Cncld	2	0	100.0%	74	6	91.9%	1	1	0.0%	73	8	89.0%
672		2	0	100.0%	75	7	90.7%	2	1	50.0%	75	13	82.7%
674	84	2	1	50.0%	74	23	68.9%	2	1	50.0%	74	5	93.2%
689		3	1	66.7%	142	19	86.6%	3	1	66.7%	141	21	85.1%
690		1	0	100.0%	79	2	97.5%	1	0	100.0%	78	4	94.9%
691		1	0	100.0%	79	7	91.1%	1	0	100.0%	77	21	72.7%
692	15	1	0	100.0%	79	3	96.2%	1	1	0.0%	78	14	82.1%
693	29	1	0	100.0%	79	12	84.8%	1	1	0.0%	78	22	71.8%
696	41	1	0	100.0%	79	8	89.9%	1	1	0.0%	79	21	73.4%
697	84	1	1	0.0%	79	17	78.5%	1	1	0.0%	79	16	79.7%
698		1	0	100.0%	77	2	97.4%	1	0	100.0%	77	7	90.9%
701		4	2	50.0%	209	23	89.0%	4	0	100.0%	206	20	90.3%
702		4	0	100.0%	276	31	88.8%	4	1	75.0%	274	61	77.7%
703		4	2	50.0%	277	79	71.5%	4	2	50.0%	276	72	73.9%
704		4	0	100.0%	208	32	84.6%	3	0	100.0%	202	38	81.2%
710		4	2	50.0%	277	71	74.4%	4	1	75.0%	273	74	72.9%
711	Cncld	4	2	50.0%	268	30	88.8%	3	1	66.7%	250	46	81.6%
712		4	1	75.0%	274	72	73.7%	4	1	75.0%	266	88	66.9%
714		3	2	33.3%	158	60	62.0%	3	2	33.3%	146	60	58.9%
715	Cncld	4	1	75.0%	276	59	78.6%	2	1	50.0%	255	126	50.6%
716	54	4	1	75.0%	277	108	61.0%	4	2	50.0%	272	104	61.8%
717		4	1	75.0%	263	63	76.0%	4	2	50.0%	245	72	70.6%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
718	26	4	3	25.0%	277	139	49.8%	4	3	25.0%	275	94	65.8%
719		4	3	25.0%	277	91	67.1%	4	3	25.0%	263	75	71.5%
720		1	0	100.0%	86	9	89.5%	1	0	100.0%	86	4	95.3%
723		1	0	100.0%	86	5	94.2%	1	0	100.0%	86	9	89.5%
724		1	0	100.0%	86	3	96.5%	1	0	100.0%	86	15	82.6%
727		1	0	100.0%	86	6	93.0%	1	0	100.0%	86	14	83.7%
728		1	0	100.0%	86	6	93.0%	1	0	100.0%	86	15	82.6%
729		1	0	100.0%	85	9	89.4%	1	0	100.0%	85	20	76.5%
732		1	0	100.0%	84	14	83.3%	1	0	100.0%	82	14	82.9%
733	30	1	0	100.0%	86	13	84.9%	1	1	0.0%	82	28	65.9%
734		1	0	100.0%	86	14	83.7%	1	0	100.0%	85	17	80.0%
736		1	1	0.0%	62	5	91.9%	1	0	100.0%	62	7	88.7%
737		1	0	100.0%	62	6	90.3%	1	0	100.0%	62	11	82.3%
738		1	0	100.0%	86	12	86.0%	1	0	100.0%	82	10	87.8%
741		1	0	100.0%	86	12	86.0%	1	0	100.0%	86	15	82.6%
742		1	0	100.0%	86	10	88.4%	1	0	100.0%	84	7	91.7%
743		1	1	0.0%	86	16	81.4%	1	0	100.0%	85	8	90.6%
744		1	0	100.0%	86	11	87.2%	1	0	100.0%	86	28	67.4%
745		1	1	0.0%	86	8	90.7%	1	0	100.0%	86	14	83.7%
746		1	0	100.0%	86	6	93.0%	1	0	100.0%	86	12	86.0%
747		1	0	100.0%	86	14	83.7%	1	0	100.0%	86	18	79.1%
748		1	0	100.0%	85	12	85.9%	1	0	100.0%	85	13	84.7%
749		1	0	100.0%	83	12	85.5%	1	0	100.0%	76	9	88.2%
751		1	1	0.0%	85	15	82.4%	1	0	100.0%	83	9	89.2%
757		4	0	100.0%	62	3	95.2%	4	0	100.0%	61	4	93.4%
761		4	1	75.0%	273	12	95.6%	4	0	100.0%	270	34	87.4%
765		4	0	100.0%	273	24	91.2%	4	0	100.0%	273	36	86.8%
769		4	0	100.0%	273	25	90.8%	4	0	100.0%	267	49	81.6%
770	30	4	0	100.0%	273	21	92.3%	4	2	50.0%	271	76	72.0%
774		4	0	100.0%	273	16	94.1%	4	0	100.0%	272	56	79.4%
777		4	0	100.0%	158	9	94.3%	4	0	100.0%	157	34	78.3%
782		4	2	50.0%	158	58	63.3%	4	0	100.0%	153	15	90.2%
785		4	0	100.0%	273	17	93.8%	4	0	100.0%	273	46	83.2%
786		4	0	100.0%	62	16	74.2%	4	1	75.0%	61	28	54.1%
790	45	4	0	100.0%	273	26	90.5%	4	1	75.0%	270	33	87.8%
794		4	1	75.0%	273	32	88.3%	4	1	75.0%	270	56	79.3%
821		4	0	100.0%	271	6	97.8%	4	2	50.0%	271	105	61.3%
822		4	1	75.0%	273	15	94.5%	4	2	50.0%	271	120	55.7%
1333		4	2	50.0%	273	30	89.0%	4	2	50.0%	270	90	66.7%
1340		4	0	100.0%	272	5	98.2%	4	2	50.0%	272	44	83.8%
2207		2	1	50.0%	20	5	75.0%	2	0	100.0%	20	5	75.0%
2208		2	1	50.0%	4	1	75.0%	2	0	100.0%	4	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 7/4/2026

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2211		2	0	100.0%	3	1	66.7%	2	0	100.0%	3	1	66.7%
2219	41	2	1	50.0%	4	2	50.0%	2	2	0.0%	4	2	50.0%
2224		2	0	100.0%	19	4	78.9%	2	0	100.0%	19	2	89.5%
2250	39	2	2	0.0%	101	10	90.1%	2	1	50.0%	101	35	65.3%
2252		2	0	100.0%	100	8	92.0%	2	0	100.0%	98	28	71.4%
2254		2	0	100.0%	35	0	100.0%	2	1	50.0%	35	9	74.3%
2255	24	2	0	100.0%	101	11	89.1%	2	2	0.0%	100	48	52.0%
2258	47	2	0	100.0%	37	9	75.7%	2	2	0.0%	36	14	61.1%
2259	37	2	0	100.0%	57	23	59.6%	2	2	0.0%	56	27	51.8%
2260	53	2	0	100.0%	4	0	100.0%	2	2	0.0%	4	3	25.0%
2262	84	2	1	50.0%	18	3	83.3%	2	2	0.0%	18	5	72.2%
2265	39	2	0	100.0%	38	3	92.1%	2	2	0.0%	37	22	40.5%
2267	24	2	1	50.0%	4	2	50.0%	1	1	0.0%	3	3	0.0%
2271	55	2	0	100.0%	85	9	89.4%	2	2	0.0%	84	44	47.6%
2293	26	2	0	100.0%	4	0	100.0%	2	1	50.0%	4	2	50.0%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2219	WAS	41	WTR	70	WTR	39	PHL-WAS	AM	Heat order, Milepost, 3.0, CP AVENUE, 100 MPH HEAT RESTRICTION ON ALL TRACKS BETWEEN 1200P AND 600P
2250	BOS	39	SYS	53	SYS	53	WAS-WAS	AM	Other late crew, NO CNDR AVAILABLE AT THE TIME OF DP
2255	WAS	24	WTR	27	DSR	16	NHV-STM	MN	Per bulletin Milepost, 48.6, 33.6, 30, 1
2258	BOS	47	WTR	46	WTR	12	XHM-XCY	AM	Heat order, Other, XHM XCY HEAT ORDERS IN EFFECT
2259	WAS	37	WTR	39	WTR	12	XCY-XHM	AM	Heat order, Other, XCY-XHM, HEAT ORDERS
2260	BOS	53	WTR	38	WTR	12	XHM-XCY	AM	Heat order, Other, XHM XCY
2262	BOS	84	WTR	36	ENG	21	NHV-XGX	AM	Other electrical failure, 2104 NG NP, 2262 reports an integrity failure at the East Haven HBD/DED detector eastbound on track No. 2. 1024pm Update No. 2262 stopped to inspect and on the move after speaking with their Road Foreman
2265	WAS	39	WTR	28	PTI	12	XCY-XHM	AM	Follow, AM87, Other, XCY XHM
2267	WAS	24	WTR	20	ITI	9	BOS-BOS	AM	Service, turn, or wye train, 2250, Late turn
2271	WAS	55	WTR	66	WTR	55	XPV-BAL	AM	Trees down, Milepost, 71.3, ., SINGLE TRACKING ON NO. 2 TRACK A/C TREES ACROSS NOS. 3 AND 4 TRACK AT MP 71.3
2293	NYP	26	ENG	18	ENG	18	BOS-X74	AM	Other electrical failure, 2149 NG NP, AM2293 stopped to insp a/c integrity failure trk 1 at Midway HBD/DED MP 127.6
65	NPN	Trn Cancelled	SYS	24	SYS	19	WAS-WAS	AM	Other late crew, NO CNDR AVAILABLE AT THE TIME OF DP
82	BOS	50	BSP	21	BSP	21	NYP-XSH	AM	Addition to TSRB a/c bridge strike, Other, MP17.87
87	NFK	46	PTI	34	ENG	15	NHV-NHV	MN	Undesired emergency application 665
99	NPN	Trn Cancelled	WTR	84	WTR	22	ALX-QAN	CS	High winds 60 mph +. Max speed 20 mph., Milepost, 105.2, 96.0
124	PHL	127	WTR	18	WTR	18	ASD-FBG	CS	Heat order Other, asd to fbg
126	NYP	24	WTR	27	WTR	15	XNY-BAL	AM	Heat order, Milepost, 3.0, CP AVENUE, 100 MPH HEAT RESTRICTION ON ALL TRACKS BETWEEN 1200P AND 600P
128	NYP	133	WTR	113	WTR	113	NFK-X3V	NS	Heat order Milepost, .3.5, 77.7

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
135	WAS	175	WTR	162	WTR	91	NRK-XPV	AM	Trees down, Control Point, ABERDEEN, SIGNALS DOWN DUE TO TREE ACROSS NOS. 3 AND 4 TRACK AT MP 71.3
146	SPG	48	WTR	32	CTI	10	WFD-MDN	AM	Follow, CT Rail, 6411, Milepost, WFD, MDN
147	RNK	No OS Rpt	WTR	72	DCS	30	MSS-CLP	NS	Power switch failure Control Point, Calverton
151	RNK	464	WTR	305	ITI	160	PHL-PHL	AM	Service, turn, or wye train, 124
153	WAS	56	CAR	44	CAR	44	NYP-NYP	AM	Door, 0000, LATE F/SSYD A/C UNSPECIFIED DOOR ISSUES
155	NFK	147	CAR	67	CAR	67	NYP-NYP	AM	Set out defective car, 82689 82676, LATE F/SSYD A/C CARS 82689 AND 82676 SHOPPED OUT
156	NYP	157	WTR	162	WTR	63	CLP-MSS	NS	Heat order Milepost, 67.0, 42.0
158	NYP	283	WTR	166	WTR	123	NFK-X3V	NS	Heat order Milepost, 1.5, 77.6, Milepost, 0.0, 3.1
161	WAS	57	WTR	32	ADA	20	NRO-NRO	MN	Wheelchair WCHR getting off at NRO station. passenger was located in the front of the train past the barricade. We received permission from district E to shove east to clear the barricade and let the wchr off.
165	WAS	65	DSR	9	DSR	9	BRP-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 4, Milepost, 41.7, 38.2, 30, 4, Milepost, 33.6, 32.3, 30, 4
168	BOS	59	WTR	27	ENG	15	NHV-OSB	AM	Other electrical failure, 626 EX ES, AM168 stopped to insp at MP 82.1 a/c integrity failure at East Haven HBD/DED MP 79.0
194	BOS	22	WTR	40	WTR	10	BAL-XPV	AM	Heat order, Milepost, 3.0, CP AVENUE, 100 MPH HEAT RESTRICTION ON ALL TRACKS BETWEEN 1200P AND 600P
195	WAS	17	WTR	18	WTR	8	MET-XHM	AM	Heat order, Other, XMW-XHM, HEAT ORDERS
450	SPG	33	SMW	22	SMW	22	WFD-MDN	AM	Diversions around M/W work, Control Point, Holt-Willow, Held at Holt for AM147 to clear a/c O/S track trk 1
460	SPG	29	SMW	18	SMW	18	WFD-MDN	AM	Scheduled in track usage program, Control Point, Holt-Willow, Held for AM461 a/c O/S track 1 for the installation of continuous welded rail.
53	SFA	45	FTI	69	FTI	61	XOU-XSA	CS	Meet csx410, Control Point, sand island
79	CLT	78	WTR	60	WTR	30	PTB-RMT	CS	Heat order Other, rmt

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
663	HAR	53	ENG	73	ENG	73	NYP-NYP	AM	Undesired emergency application, 660 EX ES, ENG.660 SHOPPED OUT FOR CARBON STRIPS	
669	HAR	Trn Cancelled	WTR	15	WTR	9	NWK-TRE	AM	Heat order, Other, NWK TRE	
671	HAR	Trn Cancelled	SMW	2	SMW	2	NWK-TRE	AM	Scheduled in track usage program, Other, NO TIME LOST	
674	NYP	84	WTR	207	WTR	155	ELT-MJY	AM	Trees down, Milepost, 95.0, STATE, TREES DOWN AROUND MP 95.0 BETWEEN ROY AND STATE. TRAIN ANNULLED HAR-PHL. TRAIN 671 TO OPR AS TRAIN 674 PHL-NYP	
19	NOL	109	CAR	136	CAR	127	NYP-NYP	AM	Set out defective car, 0000, HELD FOR AM98 TO ADD SLEEPER TO CONSIST	
20	NYP	No OS Rpt	DCS	200	ITI	197	NOL-NOL	AM	Service, turn, or wye train 19	
692	BON	15	DCS	19	DCS	8	HHL-WOB	MT	Restrictive signal(s) from unknown cause Stop, Control Point, WWJ	
693	BRK	29	PTI	13	PTI	8	POR-FRE	CS	Meet P670-04, Control Point, Congress	
696	BON	41	WTR	17	MBO	9	WOB-BON	MT	For maritime traffic Control Point, tower a	
697	BRK	84	DCS	69	DCS	63	BON-BON	MT	Restrictive signal(s) from known wayside signal failure Track circuit issue. Waited for electrician to fix it., Stop signal, Control Point, tower a	
64	NYP	91	POL	81	POL	81	HUD-HUD	AM	Fire department hold Held at HUD station for brush fire hold at mp 97.4	
68	NYP	43	WTR	45	WTR	45	SLQ-RSP	CN	Heat order Milepost, 42, 2	
69	MTR	34	WTR	56	WTR	56	XLQ-SLQ	CN	Heat order Other, rsp sub	
237	ALB	115	POL	108	POL	108	RHI-HUD	AM	Brush fire police hold on all tracks @97.4	
239	ALB	44	POL	47	POL	47	RHI-RHI	AM	Fire department hold	
290	NYP	18	CTI	18	CTI	15	POU-CRT	MN	Follow metro, 8848, Milepost, 72, 39	
448	BOS	-20	ITI	44	ITI	44	ALB-ALB	AM	Train was late arriving into Albany, lost time out of Chicago holding for dispatcher storm warning and flash flood warnings 48	
449	ALB	33	FTI	25	FTI	20	SPG-PIT	CS	Meet Z62404, Control Point, 109	
43	PGH	118	DSR	116	DSR	30	LEW-HGD	NS	Per bulletin Milepost, 176.0, 191.3, 25, 2	
71	CLT	19	SYS	12	DSR	9	DNC-GRO	NS	Per bulletin Milepost, 46.7, 46.2, 25, 1	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
78	RGH	62	WTR	49	WTR	45	CLT-KAN	NS	Heat order NS Heat Order 25 mph until 9:00pm, Milepost, 376, 349	
97	MIA	106	CAR	134	CAR	113	NYP-NYP	AM	Set out defective car, 0000, HELD FOR AM98 TO ADD COACH AND SLEEPER TO CONSIST	
98	NYP	78	FTI	103	FTI	39	JAX-JSP	CS	Meet 137, Siding, Broadhurst	
57	WAS	112	WTR	63	WTR	60	WIL-XPV	AM	Trees down, Control Point, PERRY INT, LOSS OF SIGNAL POWER A/C TREES OVER NOS. 3 AND 4 TRACKS AT MP 71.3	
40	CHI	128	WTR	105	WTR	16	XDJ-ALX	CS	Heat order Other, ALX	
41	MIA	382	ITI	223	ITI	208	CHI-CHI	AM	Service, turn, or wye train 40, Delay per chi glasshouse	
25	NOL	20	PTI	19	PTI	19	BAS-XNO	CS	Meet 26, Siding, Nicholson	
5	EMY	75	DSR	89	RTE	51	XAZ-ELK	UP	Crossover(s) due to N.A.R. 1/2, Control Point, elburz	
6	CHI	67	FTI	108	PTI	46	XNV-XSZ	UP	Meet AMT 5, Siding, Clive	
733	SJC	30	MBO	25	MBO	25	SUI-MTZ	UP	For maritime traffic Control Point, RV035	
51	CHI	176	WTR	106	PTI	70	MSS-CLP	NS	Cross over or go around 156, 20, Milepost, 36.4, 46.0	
500	SEA	Trn Cancelled								
502	SEA	Trn Cancelled								
503	EUG	18	DSR	27	DSR	7	ALY-EUG	UP	Per bulletin XH MP 664.98 4th of July festival, Milepost, 664.98, 664.98, 15, main	
504	SEA	26	DTR	17	DTR	17	XNI-TAC	ST	Rerouted due to traffic accident on Lakewood Sub. XNI, TAC	
505	PDX	Trn Cancelled								
517	PDX	65	RTE	65	RTE	39	TAC-TAC	ST	Waiting for 504 for BNSF pilots to take detour over Seattle subdivision due to closure of Lakewood Subdivision Control Point, Tacoma	
518	VAC	23	RTE	25	RTE	18	XNI-TAC	ST	Lakewood subdivision closed due to pedestrian accident. With BNSF pilots, we continued on the Seattle Sub, then at TR Junction shoved back onto unaffected Lakewood Sub to do station stop Milepost w/Letters, 25.4, 38.2x	
519	SEA	20	PTI	15	PTI	15	MVW-STW	BN	Meet 518, Siding, Logen	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
28	SPK	87	POL	85	POL	85	BNG-WIH	BN	Fire department hold Fire on/near tracks @ approx MP 99 to MP 100; held at North Dalles for tracks to be released then traverse area at restricted speed while following BNSF 7646
350	PNT	74	ENG	56	ENG	56	JXN-ARB	MI	Received codes 0939 , 0940 loss of diesel engine major fault. Shut engine 4617 down completely worked with CNOC mechanical to get it restarted ID4617
354	PNT	130	DCS	82	DCS	56	JXN-ARB	MI	T.O.L Stop at CP 52. Wait for AMT 352 to clear CP 37 before we could get authority past stop signal at CP 52. Restricted speed to signal 49 which was clear. APP at Signal 40 stop at CP 37. Authority past then restricted speed to ARB., Control Point, 52, Other, Signal 49, Control Point, 37
355	CHI	51	FTI	50	FTI	45	XPI-HMI	NS	Follow 267, Milepost, 485, 492
365	CHI	28	DSR	29	DSR	25	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, 2, Milepost, 221.42, 221.42, 30, main, Milepost, 219.15, 219.15, 25, main, Milepost, 219, 218.5, 30, main, Milepost, 216.1, 215.79, 60, main, Milepost, 214.96, 214.96, 25, main & mill crossover, Milepost, 214.93, 214.93, 25, 1, Milepost, 210.40, 210.40, 30,
566	SAN	28	CTI	14	CTI	14	OSD-SOL	SN	Meet Coaster, Control Point, Ponto
572	SAN	16	CTI	11	CTI	11	OSD-SOL	SN	Meet NCTD, 677, Control Point, longboard
584	SAN	31	CTI	23	PTI	21	SNC-SNP	SC	Meet 587, Control Point, Serra
770	SAN	30	CTI	25	CTI	25	SNC-SNP	SC	Meet metrolink, 1663, Control Point, Serra
790	SAN	45	POL	44	POL	42	SOL-SOL	SN	Right of Way police hold
711	OKJ	Trn Cancelled	PTI	19	PTI	16	TRK-MOD	BN	Meet AMTK 702, Control Point, West Modesto Empire
715	OKJ	Trn Cancelled	PTI	51	DCS	14	MOD-SKN	BN	Signal suspension Control Point, Keddie Junction
716	BFD	54	PTI	20	CON	18	EMY-EMY	UP	Hold for connecting train Left the yard at 250 mechanical problems. New train consist per Tazzy and Train master Chris Howe due to original train consist not operable causing delay. Emeryville being first station stop informed Operations (Danielle), 736
718	BFD	26	PTI	20	FTI	12	MDR-FNO	BN	Follow bnsf ?, Control Point, east figarden, Control Point, fresno

Amtrak Endpoint OTP Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/4/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
21	SAS	56	FTI	195	DCS	30	ACD-PBF	UP	CTC system failure Restricted to piedmont, Control Point, gads hill
300	CHI	32	FTI	44	FTI	25	BNL-PON	UP	Cross over or go around up2760, Siding, normal
305	STL	74	RTE	87	RTE	81	XWR-XQT	TR	Dispatcher hold 4th of July fireworks show, Control Point, Q Tower
307	STL	57	FTI	71	FTI	30	SMT-XUD	CC	Cross Traffic NA, Other, CANAL
382	CHI	75	TEN	42	TEN	30	QCY-MAC	BN	PTC - On Board Cab Signal or PTC Failure Went half a mile from last PTC failure and PTC failed again. Recycled breaker and PTC came back. Proceeded at restricted speed, ID4608
383	QCY	105	WTR	79	WTR	44	NPV-PLO	BN	Flood / washout Critical area: 35.4-35.7; Water over the rail MP 35.1, per maintainer 10mph through it, Milepost w/Letters, 26.0, PLO
390	CHI	21	FTI	28	FTI	17	CEN-EFG	CC	Meet CN 3025, Control Point, Effingham
392	CHI	25	WTR	43	WTR	7	CEN-EFG	CC	Heat order Milepost w/Letters, Centralia, Effungham
393	CDL	42	WTR	49	WTR	14	CHM-MAT	CC	Heat order Other, CHM SUB
316	STL	No OS Rpt	WTR	369	WTR	369	JEF-JEF	UP	Trees down Due to severe weather, we were unable to proceed past JEF, unloaded all pax (23) on to bus to deliver pax to final destinations of KWD and STL. Currently still sitting just east of JEF depot during the completion of this entry at 0205., Other, JEF to HEM
318	CHI	52	FTI	49	WTR	20	STL-XQT	TR	High winds Control Point, gratiot
319	KCY	No OS Rpt	WTR	117	WTR	107	WAH-HEM	UP	Trees down Milepost, 76.67, 76.67

Amtrak Initial Terminal Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/4/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	20	07/04	4	4	Inability to contact dispatcher Tried calling Clara Street dispatch by radio and phone, no response.. lost 10-15 minutes waiting..., Other, NOL Terminal
ALB	234	07/04	6	6	Service, turn, or wye train 234
ALB	448	07/03	44	44	Train was late arriving into Albany, lost time out of Chicago holding for dispatcher storm warning and flash flood warnings 48
BON	697	07/04	63	63	Restrictive signal(s) from known wayside signal failure Track circuit issue. Waited for electrician to fix it., Stop signal, Control Point, tower a
BOS	2267	07/04	9	9	Service, turn, or wye train, 2250, Late turn
HAR	674	07/04	3	3	Trees down, Control Point, SECTION B, 241 OUT OF HARRISBURG A/C LOSS OF SIGNAL POWER AND RTU CONTROL DUE TO TREES IN CATENARY THROUGHOUT SECTION B.
MIA	98	07/04	60	60	Flat Switch Engines Flat switch Engines at Miami Station Platform, 307 now in lead with 314 trail, 314, 307
MTR	68	07/04	1		
NFK	158	07/04	1	1	For maritime traffic Milepost, 1.5, 1.5
NFL	280	07/04	1	1	Re-crew / job briefing Job briefing with ng and engineer to clarify high wind warning
NPN	124	07/04	(No OS)		
NYP	97	07/04	24	24	Water, commissary, toilet/trash dumping
NYP	127	07/04	5	5	Undesired emergency application, 9638, LATE F/SSYD A/C BOTTLED AIR
NYP	153	07/04	44	44	Door, 0000, LATE F/SSYD A/C UNSPECIFIED DOOR ISSUES
NYP	155	07/04	67	67	Set out defective car, 82689 82676, LATE F/SSYD A/C CARS 82689 AND 82676 SHOPPED OUT
NYP	245	07/04	4	4	Service, turn, or wye train, 68
NYP	663	07/04	73	73	Undesired emergency application, 660 EX ES, ENG.660 SHOPPED OUT FOR CARBON STRIPS
PHL	151	07/04	160	160	Service, turn, or wye train, 124
PHL	611	07/04	1		
RNK	66	07/04	520	520	Wait for scheduled departure time Waited for train 151 to arrive to conduct calendar day inspection and prep train for departure.
WAS	82	07/04	21	12	HEP, 82662, MISSING 1173
WAS	82	07/04	21	9	Other electrical failure, 650, LATE RELEASE OF MTR 650
WAS	118	07/04	12	12	Other electrical failure, 614, LACK OF MOTOR AVAILABILITY.
WAS	168	07/04	3	3	Heat order, Control Point, K INT, MULTIPLE HOT CARS
WAS	194	07/04	3	3	Air / Brake / Wheel, ., BLUE LIGHT STILL UP ON SOUTH END.

Amtrak Initial Terminal Details

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/4/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2208	07/04	3	3	Water, commissary, toilet/trash dumping, LATE COMMISSARY
WAS	2250	07/04	52	53	Other late crew, NO CNDR AVAILABLE AT THE TIME OF DP
WAS	2262	07/04	10	10	HEP, 2104 NG NP, LOST HEP
CHI	41	07/04	25	25	Service, turn, or wye train 40
BFD	711	07/04	2		
BFD	719	07/04	1	1	Dispatcher hold I have no clue why., Control Point, Bakersfield
EMY	6	07/04	4	4	Meet 710, Control Point, east emeryville
LAX	572	07/04	2		
OKJ	714	07/04	21	4	Meet 732, Other, OKJ STA
OKJ	714	07/04	21	17	PTC - Initializing PTC (no failure) CONSIST NOT LISTED IN EMD. OPS CALLED, PTC CALLED, UP AND BNSF CALLED AND NOTIFIED BY CONDUCTOR., Other, OMF
OKJ	716	07/04	(Trn Cxld)		Third Party Engine Failure
OKJ	718	07/04	(Trn Cxld)	52	Third Party Engine Failure
OKJ	736	07/04	1		
PDX	500	07/04	(Trn Cxld)		Utility Line Issues
PDX	502	07/04	(Trn Cxld)		Utility Line Issues
SAC	743	07/04	8	8	Air / Brake / Wheel C8010, Issue with ADA lift causing the air to dump . Now isolated.
SAC	745	07/04	1		
SAC	751	07/04	1		
SEA	503	07/04	(Trn Cxld)		Utility Line Issues
SEA	505	07/04	(Trn Cxld)		Utility Line Issues

Eastern Region

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	100.0	69.9	90.2	18	0
SEPTA	95.0	88.0	91.5	91.5	108	13
NJT-NED	95.0	86.5	83.9	88.6	179	24
NJT-SED	95.0	91.7	93.9	97.2	12	1

Operating Highlights

Severe Storm/ High Winds - South of Alexandria, VA

05JUL26: Due to a severe weather storm moving through the area on both CSX and NS territories, several trains were delayed south of Alexandria, VA operating reduced speeds due to High Winds and Tornado warnings.

Train	Delay	Comment
19(04)	46"	High Winds - ALX-MSS
99(04)	43"	High Winds - ALX-FBG
147(04)	48"	High Winds - ALX-CLP
147(04)	13"	Followed 99(04)
97(04)	05"	High Winds - N/RVR

Train 158(04) North of BWI Marshall Airport, MD - Engine Failure

05JUL26: Train 158(04) E/604, 9 cars, with 268 customers onboard, was delayed on the Amtrak Philadelphia to Washington Line, 5 miles north of Baltimore Marshall Airport station, just north of Halethorpe at MP101.8, due to the MCB opening on E/604. The crew worked with an Amtrak Road Foreman to troubleshoot and recycle the engine. Once issue was resolved, the train continued north. The train was further delayed with continued MCB issues north of Baltimore, after being met by mechanical at Baltimore station.

Train	Delay	Comment
158(04)	40"	MP101.8
158(04)	1'36"	BAL- Mechanical meet

PW Line Trees Down and Signal Loss

05JUL26: At 9:14 PM-ET, it was reported that there was a signal power loss between Perry and Oak interlockings on the Amtrak PW line. It was reported that there was a tree down on track 3 and 4. Trains that operated through that area had significant delays. Single track conditions were created by the power loss. At 3:17 AM-ET, it was reported that the signal power was restore and tracks returned to scheduled speed and service.

Train	Delay	Comment
135(04)	1'31"	
57(04)	1'00"	
2271(04)	55"	
135(04)	2'26"	

Train 52(04) North of Jesup, GA - Freight Train Interference

05JUL26: Train 52(04) delayed at milepost 77.2 A543.6 on the CSX Nahunta Subdivision, 5 miles north of Jesup, GA, meeting freight unit M491. Once a route was clear, Train 52(04) was able to proceed at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(04)	34"	

Train 41(03) North of Connellsville, PA - Trees down

05JUL26: Train 41(03) with engines 316, 330, 10 cars, and 107 customers onboard went into emergency at milepost 279.1, north of Connellsville, PA on the CSX Pittsburgh subdivision to avoid striking a large tree on the tracks. The train remained intact and on the rails. The train maintained headend power. There were no reported injuries to crew or the customers. CSX responded to the area and removed the trees. once the tree was removed, train 41(03) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(03)	2'42"	

Train 41(02) South of Tampa, FL - Signal

05JUL26: Train 41(02) with engines 198, 339, 10 cars, and 149 customers onboard was delayed at milepost 864.9, 17 miles south of Tampa, FL on the CSX Lakeland subdivision due to wayside detector failure including a false activation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(02)	33"	

Hudson Line Brush Fire Police Hold North of Rhinecliff, NY

05JUL26: A police hold was placed at milepost 97.4, 8 miles north of Rhinecliff, NY on the Amtrak Hudson Line due to a brush fire close to the tracks. Multiple trains in the area were stopped waiting on a clear route. Once the police hold was lifted at 8:24 PM-ET, the trains were able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(04)	32"	
239(04)	47"	
64(04)	1'21"	
237(04)	1'48"	

Train 20(03) Charlottesville, VA - Signal

05JUL26: Train 20(03) with engines 37, 151, 8 cars, and 161 customers onboard was delayed beginning at milepost 132.0, 20 miles south of Charlottesville, VA on the NS Washington District due to restrictive signals from milepost 132.0 to milepost 114.8. The train was required to operate at restricted speed. The train was able to advance once it was through the affected area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(03)	1'20"	

Train 697(04) Boston, MA - Signal

05JUL26: Train 697(04) took an initial delay at Boston for crew staffing. The crew for train 98(03) was moved up to work 2250(04) and they were able to depart WAS. 26-FOI-00580 00000008155 7/7/2026 UNCLASSIFIED

04JUL26: Train 697(04) operating with engines, 37/151, 8 coaches and 162 customers onboard was delayed departing Boston, MA on the MBTA New Hampshire Route Main Line due to restrictive signals from a known wayside signal failure. The train had to wait for the electrician to fix the signal. Once the signal was working, train 697(04) departed the station.

Train	Delay	Comment
697(04)	1'03"	

Train 20(03) Charlottesville, VA - Wayside Signal Failure

04JUL26: Train 20(03), operating with engines, 37/151, 8 coaches and 161 customers, was delayed 20 miles west of Charlottesville, VA, on NS Alexandria-Montview_62 subdivision, due to wayside signal failure. This required train 20(03) to operate at restricted speed from milepost 132 to milepost 114.

Train	Delay	Comment
20(03)	1'20"	

Train 20(03) East of Culpeper, VA - Signal

04JUL26: Train 20(03), operating with engines, 37/151, 8 coaches, and 162 customers, was delayed 21 miles east of Culpeper, VA, on NS Alexandria-Montview_62 subdivision, due to power switch failure at Control Point Calverton. This required multiple trains to hand line switches for their routes. NS ran all westbound traffic first and then train 20(03) followed once a route was made available. Multiple trains were delayed operating through the affected area. Train 19(04) and 20(03) were further delayed for re-crew due to this.

Train	Delay	Comment
20(03)	1'48"	
19(04)	1'15"	
147(04)	45"	
19(04)	2'21"	CLP - Re-crew
20(03)	1'19"	BCV - Re-crew

Train 69(04) North of Fort Edward-Glens Falls, NY - Freight Train Interference

04JUL26: Train 69(04) operating with locomotive 112, 5 cars, and 105 customers was delayed 22 miles north of Fort Edward at MP 77 on the CPKC Canadian subdivision meeting a Cn freight at CP 288. After the freight passed train 69(04) was able to proceed without further delay.

Train	Delay	Comment
69(04)	35"	

Train 2250(04) Washington, DC - Initial terminal Delay - Crew

04JUL26: Train 2250(04) took an initial terminal delay at Washington for crew staffing. The crew for train 98(03) was moved up to work 2250(04) and they were able to depart WAS.

Train	Delay	Comment
2250(04)	53"	

Train 155(03) New York, NY - Initial terminal Delay - Car Failure

04JUL26: Train 155(04) operating with locomotive 626, 9 cars and 429 customers was delayed at the initial terminal of New York due to cars 52689-82676 shopping out off 158(03) during servicing and inspection. After the replacement cars were added to the equipment train 155(04) was released from the yard and positioned in the station. Once the customers were boarded train 155(03) was able to depart New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
155(03)	1'07"	

Train 153(04) New York, NY - Initial terminal Delay - Car Failure

04JUL26: Train 153(04) operating with locomotive 625, 9 cars, and 352 customers was delayed at the initial terminal of New York due to cars 82689 and 82676 shopping out for HVAC failure during the servicing and inspections. To mitigate the delay to train 153(04) the equipment slated to operate as train 155(04) was utilized for service on train 153(04) after servicing was completed. Once the equipment was released from the yard it was placed in the station, customers boarded and train 153(04) was able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
153(04)	44"	

Train 663(04) New York, NY - Initial Terminal Delay - Engine Failure

04JUL26: Train 663(04) operating with locomotive 660, 5 cars and 212 customers was delayed at the initial terminal of New York due to locomotive 660 shopping out during the servicing and inspections for a worn carbon strip requiring it to be replaced with locomotive 642. After the equipment was released, it was moved into the station, boarded by the customers and departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
663(04)	1'13"	

Train 151(04) Philadelphia, PA - Initial Terminal Delay - Servicing

04JUL26: Train 151(04) operating with locomotive 606, 8 cars, 96 customers was delayed at the initial terminal of Philadelphia due to the late arrival of train 124(03) into Philadelphia at 4:46am 6'23" late due to the CSX derailment on the Peninsula subdivision and subsequent servicing required. After the train was released from servicing and moved into the station train 151(04) was able to depart Philadelphia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
151(04)	2'40"	

Train 20(03) North of Atlanta, GA - Freight Train Interference

04JUL26: Train 20(03) was delayed starting 2.4 miles north of Atlanta, GA (MP633.3), on the NSRR Greenville District, following NS 154 from Foremost (MP630.9) to Walters (MP599.8).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(03)	1'00"	

Train 98(04) Miami, FL - Initial Terminal Delay - Engine Failure

04JUL26: Train 98(04) 26-FOI-00580 00000008155 UNCLASSIFIED 314-307 7/7/2026 10 cars and 58 customers was delayed at the initial terminal of Miami due to engine issues with locomotive 314. Prior to departure locomotive 314 presented a master controller fault. Upon investigation, CNOC Mechanical and Siemens determined it would be necessary to flat switch the locomotive from lead to the trail position to prevent the locomotive from impacting over the road operational failure. After the locomotives were flat switched train 98(04) was able to depart MIA.

Train	Delay	Comment
98(04)	1'00"	

NS Heat Orders - Weather

04JUL26: NS has imposed heat orders for near the entirety of their network due to expected ambient temperatures exceeding 100 degrees in locations with expected rail temps exceeding 140 degrees. Trains operating over these routes will operate at speeds of 25 mph with delays expected to be significant.

Train	Delay	Comment
19(04)	46"	
78(04)	49"	
151(04)	5'05"	
156(04)	2'18"	
158(04)	2'03"	
20(03)	2'44"	
40(03)	43"	
43(04)	1'56"	
128(04)	2'11"	
155(04)	45"	

Amtrak Northeast Corridor Heat Orders - Weather

04JUL26: With high temperatures expected across the Northeast Corridor, Amtrak imposed heat orders on the PW Line, NYP Line, PH Line, NHB Line and MRS Lines resulting in delays to trains and causing initial terminal delays to equipment turns off delayed trains.

The high temperatures caused mechanical HVAC failure on multiple trains. The trains took delays trying to troubleshoot the issues.

Train	Delay	Comment
118 (04)	04"	
126 (04)	27"	
124 (04)	10"	
127 (04)	07"	
135 (04)	16"	
140 (04)	30"	
143 (04)	02"	
146 (04)	22"	
153 (04)	03"	
147 (04)	24"	
155 (04)	09"	
156 (04)	21"	
161 (04)	32"	
164 (04)	05"	
19 (04)	15"	
168 (04)	27"	
194 (04)	30"	
195 (04)	18"	
2255 (04)	27"	
2258 (04)	44"	
2262 (04)	32"	
2259 (04)	39"	
239 (04)	04"	
244 (04)	02"	
2265 (04)	28"	
284 (04)	03"	
291 (04)	06"	
42 (04)	11"	
43 (04)	04"	
57 (04)	03"	
664 (04)	10"	
665 (04)	19"	
669 (04)	15"	
670 (04)	14"	
82 (04)	13"	
80 (04)	15"	
87 (04)	27"	
99 (04)	26"	
97 (04)	11"	

CN Heat Orders - Weather

04JUL26: CN imposed heat orders between Rouses Point, NY and St. Lambert, QC of 25 mph created delays for trains 68 and 69.

Train	Delay	Comment
68 (04)	45"	
69 (04)	56"	

CSX Heat Orders - Weather

04JUL26: CSX has imposed a heat order between Philadelphia and New York City impacting trains operating over the affected territories.

Train	Delay	Comment
155 (04)	27"	
156 (04)	03"	
124 (04)	18"	
158 (04)	18"	
19 (04)	05"	
40 (03)	54"	
40 (04)	1'00"	
449 (04)	22"	
448 (03)	22"	
52 (04)	12"	
53 (04)	23"	
693 (04)	13"	
696 (04)	17"	
698 (04)	05"	
79 (04)	1'00"	
80 (04)	17"	
97 (03)	09"	
98 (04)	37"	
98 (04)	37"	

Downeaster Service Adjustments - Weather

04JUL26: The following Downeaster trains have been cancelled due to the heat and equipment constraints: train 694(04) and 695(04). Customers will be reaccommodated on train 696(04) and train 697(04).

Train	Delay	Comment
694 (04)	Cancelled	
695 (04)	Cancelled	

Keystone Line Trees Down and Signal Power Loss

05JUL26: Severe weather on the Amtrak Keystone line created signal power loss between State and Holland Interlockings. The power was then lost between Downs and Park. Multiple trees were reported down across the area. Train 674(04) with 28 passengers was stopped at Rheems interlocking with no headend power. The train was able to eventually recover power and was able to operate under its own power to Lancaster station. The train was met by one bus to transport the customers to their destinations. The train was tied down in Lancaster due to no clear route to Harrisburg or Philadelphia.

Train 669(04) with 185 customers onboard was stopped at Parkersburg station without headend power. Two rescue diesels were dispatched from Philadelphia. The rescue diesels arrived to the train set and towed the train to a live section of track. The train was then able to operate under its own power back to Philadelphia.

Train 671(04) was cancelled from Philadelphia to Harrisburg with no alternate transportation. The equipment from train 671(04) was turned in Philadelphia and operated as train 674(04) from Philadelphia to New York.

Trains 660(05), 661(05), 664(05), and 663(04) were cancelled in their entirety.

Train	Delay	Comment
669 (04)	Term PAR	
660 (05)	Cancelled	
671 (04)	Term PHL	
661 (05)	Cancelled	
664 (05)	Cancelled	
663 (05)	Cancelled	
674 (04)	2'35"	

CSX Freight Train Derailment on the Peninsula Subdivision

03JUL26: CSX reported a freight train derailed on the Peninsula Subdivision at milepost 83, 8 miles east of Richmond, VA. Three cars had derailed and fallen off of the viaduct into the water. Three cars and one locomotive were leaning. CSX personnel responded to the scene. Train 124(03) with 166 customers onboard was stopped at milepost 80 at 5:00 PM-ET. The train then reversed east to crossing at Charles City Road to transfer customers to buses. The road foreman responded to the train to assist in customer transfer. Buses were secured by station services. Once bus operated from where train 124(03) stood to Richmond Main Street Station and then returned to the train. A total of three buses then transferred the rest of the passengers to Richmond. The buses were then staged at Richmond to take the customers from train 99(03) to their destinations. Train 99(03) was terminated in Richmond and turned for train 124(03). Train 158(03) made train 124(03) stops.

Train 164(04) was originated in Washington, DC. Train 65(03) was terminated in Richmond.

04JUL26: 9:00 am-et CSX reports derailment site will not be cleared for rail traffic to resume until am hours of 7/5. As a result, the following additional adjustments have been made with no alternate transportation due to no bus availability: 124(04) will be cancelled between Newport News and Richmond and will operate Richmond to Philadelphia with train 65(03) equipment. Train 99(04) will terminate Richmond. Train 164(05) is cancelled Newport News and Richmond and will operate Richmond to Boston with the equipment off 99(04). Train 65(04) will terminate Washington.

WBS#: B.TR.100151.0828

Train	Delay	Comment
99(03)	Term RVR	
124(03)	6'30"	
164(04)	Orig WAS	
65(03)	Term RVR	
124(04)	ORIG RVR	
99(04)	TERM RVR	
164(05)	ORIG RVR	
65(04)	TERM WAS	

NEC Service Adjustments for 07/03/26 - 07/05/26- Weather

03JUL26: Due to the impending hot weather with ambient temperatures elevated over 90 degrees the following service adjustments were made: Northeast Regional trains 163, 88, 159, 142, 106, and 107(03-04) were cancelled in their entirety. Keystone trains 666 and 667(03-04) were also cancelled in their entirety.

04JUL26: The continued hot weather required further service adjustment to be made. The following trains were cancelled in their entirety with no alternate transportation: 2290, 2293, 2252, 2254, 2267, 2271, 88, 149, 189, 105, 122, and 104(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
163(03)	Cancelled	
159(03)	Cancelled	
88(03)	Cancelled	
142(03)	Cancelled	
106(03)	Cancelled	
107(03)	Cancelled	
666(03)	Cancelled	
667(03)	Cancelled	
163(04)	Cancelled	
159(04)	Cancelled	
88(04)	Cancelled	
142(04)	Cancelled	
106(04)	Cancelled	
107(04)	Cancelled	
666(04)	Cancelled	
667(04)	Cancelled	
2293(05)	Cancelled	
2290(05)	Cancelled	
2252(05)	Cancelled	
2254(05)	Cancelled	
2267(05)	Cancelled	
2271(05)	Cancelled	
88(05)	Cancelled	
149(05)	Cancelled	
189(05)	Cancelled	
105(05)	Cancelled	
122(05)	Cancelled	
104(05)	Cancelled	

Piedmont Service Cancellations - Norfolk Southern Heat Orders - Weather

03JUL26: Heat orders issued by the "UNCLASSIFIED" Districts would cause significant delays to the service scheduled through the area. As a result, trains were cancelled with alternate transportation secured. Two buses were secured for train 72(03). One bus operated express stopping and picking up in Charlotte, Greensboro and Raleigh. One bus making all stops. Two buses were secured for train 74(03) and both made all stops. Two buses were secured for train 76(03). One bus made stops in Charlotte, Durham, Cary, and Raleigh. The second bus made stops in Charlotte, Kannapolis, Greensboro, Durham, Cary, and Raleigh. Two buses were secured for train 73(03). One bus made stops in Raleigh, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 75(03). One bus made stops in Raleigh, Cary, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 77(03). One bus made stops in Raleigh, Durham, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Greensboro, Highpoint, Salisbury, and Charlotte. Trains 71(03) and 78(03) were scheduled to make all stops.

04JUL26: The heat orders were continued into 07/04/26. The following trains were cancelled with alternate transportation secured: 72(04), 73(04), 75(04), 76(04), and 77(04).

05JUN26: The heat orders were continued into 07/05/26. The following trains were cancelled with alternate transportation secured: 72(05), 73(05), 75(05), 76(05), and 77(05).

Train	Delay	Comment
77(03)	Cancelled	
76(03)	Cancelled	
74(03)	Cancelled	
75(03)	Cancelled	
73(03)	Cancelled	
72(03)	Cancelled	
72(04)	Cancelled	
73(04)	Cancelled	
74(04)	Cancelled	
75(04)	Cancelled	
76(04)	Cancelled	
77(04)	Cancelled	
72(05)	Cancelled	
73(05)	Cancelled	
75(05)	Cancelled	
74(05)	Cancelled	
76(05)	Cancelled	
77(05)	Cancelled	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00580a 00000008155 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
43	LEW	1	HGD	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train 8/28(03) West of Wolf Point, MT - Freight Train Interference

05JUL26: Train 8/28(03) was delayed at Oswego/MP237.8 on the BNSF Glasgow Subdivision, 10 miles west of Wolf Point, MT meeting two freight trains, BNSF 3281 and BNSF 6508.

Train	Delay	Comment
8/28(03)	36"	

Train 4(03) West of La Junta, CO - Temporary Speed Restrictions

04JUL26: Train 4(03) was delayed starting at MP 605, 51 miles west of La Junta, CO, on the BNSF Raton Subdivision due to operating at reduced speed account of BNSF placed multiple temporary speed restrictions between MP 605 to MP 581.9. Once through the affected area, the crew was able to proceed at track speed.

Train	Delay	Comment
4(03)	34"	

Train 777(04) North of Goleta, CA - Passenger Train Interference

04JUL26: Train 777(04) was delayed at North Gaviota/ MP335.4 on the UPRR Santa Barbara Subdivision, 21 miles north of Goleta, CA, due to meeting train 794(04).

Train	Delay	Comment
777(04)	30"	

Train 6(04) East of Winnemucca, NV - Heat Orders

05JUL26: Train 6(04) was delayed east of Winnemucca, NV on the UPRR Elko Subdivision, between MP426 and MP502 operating reduced speeds account of heat orders.

Train	Delay	Comment
6(04)	31"	

Train 790(04) Solana Beach, CA - Police Related

05JUL26: Train 790(04) was delayed at Solana Beach, CA/MP241.8 on the SCRRA NCTD San Diego Subdivision, due to a police hold on all tracks account trespassers on the tracks. Once the hold was released, Train 790(04) was able to proceed.

Train	Delay	Comment
790(04)	42"	

Train 718(04) Merced, CA - Police Related

05JUL26: Train 718(04) was delayed at Merced/MP1055.9 on the BNSF Stockton Subdivision, due to a hold on all tracks account of a track-side fire at MP1055.1 Once the hold was released, Train 718(04) was able to proceed.

Train	Delay	Comment
718(04)	39"	

Train 22(04) Little Rock, AR - Freight Train Interference

05JUL26: train 22(04) 26-FOI-005801 UNCLASSIFIED 00000008155 26/48 7/7/2026 at Little Rock, AR, with engine 2200, 2 coaches, was delayed 7 miles south of Little Rock, AR, on UP Little Rock subdivision, due to meeting UP3066 at Control Point A352. Once the freight cleared and a route was made available, train 22(04) was able to proceed.

Train	Delay	Comment
22(04)	32"	

Train 7/27(03) Havre, MT - Engine Failure

04JUL26: Train 7/27(03) E/170, E/327, 9 cars, was delayed at Havre, MT/MP430.3 on the BNSF Milk River Subdivision to inspect E/170 due to reported high temperatures. The crew inspected and cut out traction motor 3 in order to proceed west. The train was delayed again at Shelby, MT with traction motors overheating again. The crew worked with CNOC mechanical to resolve the issue by removing the traction motor filters in order to continue west. Due to this, a BNSF freight unit BN6714 was secured to be added ahead of 7(03) at Spokane, WA in order to protect the train into Seattle. Once the freight locomotive was added, and brake test complete, Train 7(27) departed west towards Seattle.

Train	Delay	Comment
7(03)		SPK
7/27(03)	15"	HAV
7/27(03)	12"	Adtl lost time SBY-WGL
7/27(03)	19"	SBY

Train 794(04) South of Lompoc-Surf, CA - Engine Failure

04JUL26: Train 794(04) CC/6908, 5 cars, E/C2112, was delayed 33 miles south of Lompoc-Surf, CA at MP332.2 on the UPRR Santa Barbara subdivision with loading problems. The crew worked to troubleshoot and were able to resolve the issue allowing Train 794(04) to proceed south.

Train	Delay	Comment
794(04)	31"	

Train 11(4) Portland, OR - HAZMAT/ Passenger Related

04JUL26: Train 11(04) was delayed departing Portland, OR due to HAZMAT cleaners were requested to clean the accessible restroom in coach car C/34512 after a detrainning passenger got sick. Once required cleaning was completed, Train 11(04) departed.

Train	Delay	Comment
11(4)	59"	

Train 305(04) North of St. Louis, MO - Police Related

05JUL26: Train 305(04), operating with engine 319, 5 coaches, and 25 customers, was delayed 2 miles north of Saint Louis, MO, on TRRA EADS subdivision, due to being held out the station by the fire department for a fireworks show near the station. Once the show was over, train 305(04) was able to proceed into the station.

Train	Delay	Comment
305(04)	1'21"	

Train 316/319(04) UPRR JEFFERSON CITY SUB - Severe Weather

04JUL26: Due to extreme weather on the UPRR Jefferson City subdivision, between Jefferson City, MO and Hermann, MO. UPRR dispatched Maintenance of Way personnel to remove downed trees from several locations. UPRR personnel reported downed wires in several locations as well. While enroute to the original reported locations of the downed trees, MOW kept finding other trees on the tracks that needed to be removed. Train 316(04) held at Jefferson City, MO for an open route and train 319(04) was initially held East of Hermann, MO and then West of Hermann, MO. Due to the extended delay buses were secured to accommodate customers. Buses arrived at a crossing 1 mile east of Jefferson City for train 316(04) at approximately 2:50am-ct and all customers were safely transferred to buses. Amtrak Road Foreman arrived on location of 319(04) at approximately 3:50am-ct as well as the buses. At 3:45am-ct, UPRR reported that there was an 11 mile stretch with 40 trees across the tracks that required heavy equipment to remove. As a result the following service adjustments have been made.

311(05) was cancelled in its entirety, 318(05) originated in Saint Louis.

316(04) & 319(04) was terminated at Jefferson City, MO.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(04)	Term JEF	
316(04)	Term JEF	
311(05)	Cancelled	
318(05)	Orig STL	

Train 382(04) Quincy, IL - PTC Failure

04JUL26: Train 382(04), operating with engine 4608, 4 coaches, was delayed north of Quincy, IL, on BNSF Brookfield, subdivision, due to PTC failure. The crew initially stopped to troubleshoot the issue and it seemed to be resolved, but, once back on the move, PTC failed again. Train 382(04) then continued at a reduced speed due to the PTC failure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(04)	1'03"	

Train 21(03) South of Cleburne, TX - Freight Train Interference

04JUL26: Train 21(03), operating with engines 69/68, 9 coaches and 56 customers, was delayed operating between Cleburne, TX and Temple, TX, due to multiple freight meets. This was caused by limited meet/pass locations through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(03)	56"	

Train 716(04) Oakland, CA - Third Party Contractor Engine Failure

04JUL26: Train 716(04) CC/8310-7 cars-E/C2014 was delayed departing Oakland, CA due to bell issues on E/C2014. Due to the length of delay, equipment was swapped to CC/C8312-7 cars-E/C2102 at 2:15P-PT. Mechanical still needed to work and estimated the equipment would be ready to depart at 2:35P-PT. Due to the extended delay, after mechanical released equipment, the crew deadheaded the equipment to Emeryville Station where it was originated. Eight affected passengers boarding at Oakland were accommodated on Train 736(04) OKJ-EMY.

The CC/8310 set was to be utilized for Train 718(04), however mechanical issues persisted with the bell and then the event recorder was not communicating with PTC. This prompted the termination of Train 715(04) at Emeryville, so the equipment could be fueled in the yard and then turned out to represent Train 718(04) originating at Emeryville. Passengers between Emeryville and Oakland were accommodated on trains 744(04) and 745(04).

Train	Delay	Comment
716(04)	54"	Originated EMY
718(04)	55"	Originated EMY
715(04)	00"	Terminated EMY
745(04)	06"	EMY

Train 4(02) and 6(02) East of Princeton, IL - Weather

04JUL26: Train 4(02) and 6(02) were delayed east of Princeton, IL (MP104.3), on the BNSF Mendota Subdivision, due to high wind warnings from MP101 to MP58.

Train	Delay	Comment
4(02)	12"	
6(02)	30"	

Train 4(03) East of Lamy, NM - Passenger Train Interference

04JUL26: Train 4(03) was delayed at MP 820.2, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision due to meet with Train 3(03). Once Train 3(03) cleared, Train 4(03) proceeded east.

Train	Delay	Comment
4(03)	44"	

Train 6(03) East of Glenwood Springs, CO - Medical Emergency

04JUL26: Train 6(03) stopped on the UPRR Glenwood Springs Subdivision approximately 18.6 miles east of Glenwood Springs, CO (MP360.1), to meet EMS for a customer requiring medical attention. EMS responded to the train, evaluated the customer, and removed them from the train for further care. Once the customer was transferred to EMS, Train 6(03) was able to continue its trip.

Train	Delay	Comment
6(03)	33"	

Train 51(03) North of Dyer, IN - Freight Train Interference

04JUL26: Train 51(03) held 12.6 miles north of Dyer, IN (MP27.9), on the UPRR Villa Grove Subdivision, at Dolton Jct (MP16.7) in order to meet CSX I141106.

Train	Delay	Comment
51(03)	44"	

Train 1(04) Schriever, LA - Police Related

04JUL26: Train 1(04) held 26 miles east of Schriever, LA (MP55.0), on the BNSF Lafayette Subdivision, while awaiting law enforcement to respond and remove an unruly customer from the train. Once police arrived and addressed the situation, Train 1(04) was able to continue its trip.

Train	Delay	Comment
1(04)	46"	

Train 4(02) East of Fort Madison, IA - Freight Train Interference

04JUL26: Train 4(02) held 41 miles east of Fort Madison, IA (MP232.9), on the BNSF Chillicothe Subdivision, at Ormonde (MP191.9) meeting BNSF 6215.

Train	Delay	Comment
4(02)	32"	

Train 19(03) South of Atlanta, GA - Freight Train Interference

04JUL26: Train 19(03) was held at Howell (MP 635.0) on the NSRR Norcross Subdivision, approximately 1.7 miles south of Atlanta, GA (MP 633.3), while awaiting NS 4444 to complete its work and clear into Inman Yard (MP 148.0). Once NS 4444 cleared the route, Train 19(03) was able to proceed.

Train	Delay	Comment
19(03)	51"	

Train 350(04) East of Jackson, MI - Engine Failure

04JUL26: At 12:37PM-ET, Train 350(04), E/ID4627-5 Cars-E/ID4617, stopped at MP56.3 on the Michigan DOT Michigan Line, approximately 19.2 miles east of Jackson, MI (MP75.5), after both locomotives shut down with fault codes 0939 and 0940. The loss of locomotive power also resulted in the loss of HEP, affecting 147 customers onboard. At the time of the incident, the temperature was 72 degrees with partly sunny conditions. The onboard crew worked collaboratively to troubleshoot the issue with CNOC Mechanical, Siemens, and LAX Mechanical. At 1:15PM-ET, both locomotives were restarted and HEP was restored to the trainset. At 1:26PM-ET, Train 350(04) resumed its eastward movement.

Train	Delay	Comment
350(04)	56"	

Train 5(02) Elko, NV - Freight Train Interference

04JUL26: Train 5(02) was delayed entering Elko, NV (MP 557.0), on the BNSF Lakeside Subdivision after being routed through the yard due to multiple freight trains staged in the area following an earlier derailment. Further delay was incurred at Elburz (MP 573.3) when switches were hand thrown to facilitate a crossover move from Main Track 1 to Main Track 2.

Train	Delay	Comment
5(02)	51"	

Sound Transit Lakewood Subdivision - Vehicle Accident

04JUL26: At 2:51A-PT, 26-FOI-00880 00000008155 UNCLASSIFIED 7/7/2026 BNSF reported all trains were closed at MP 7.3, 6 miles south of Tacoma, WA, on the Sound Transit Lakewood Subdivision due to a fatal vehicle accident with utility pole and power lines across tracks occurring at 1:24A-PT. As of 6:00A-PT the police investigation was ongoing with no ETA for the coroner. The BNSF reported delays were anticipated into the afternoon due to the holiday and the ability to secure resources to repair the damaged utility equipment. Train 500(04), Train 502(04) and Train 505(04) were all cancelled in their entirety between Seattle, WA and Portland, OR. Train 503(04) originated in Portland to operate Portland to Eugene, OR. Customer service was unable to secure alternate bus transportation, therefore no alternate transportation was provided between Seattle and Portland. At 7:00A-PT, the BNSF reported an estimate of 8:00P-PT for track opening. Alternate routing options were sourced with the BNSF for trains later in the morning. The BNSF provided one pilot boarding in Auburn, WA on Train 11(04) to operate over the BNSF Seattle Subdivision to route around the closed Sound Transit Lakewood Subdivision, making all station stops after reversing from Tacoma, WA Station. Once Train 11(04) was through the detour, from Tacoma to Olympia-Lacey, WA, the pilot boarded 504(04) to operate through the area. Train 517(04) held at Tacoma, WA for the pilot off Train 504(04). An additional pilot was sourced to pilot Train 507(04) and Train 518(04) over the detour.

Tacoma Power was able to replace the power pole sooner than their original estimate and Tacoma PD released the tracks and crossing for normal service at approximately 4:20 PM-PT.

Train	Delay	Comment
500(04)	Cancelled	
505(04)	Cancelled	
502(04)	Cancelled	
503(04)	Orig PDX	
11(04)	25"	Detour
504(04)	31"	
517(04)	1'03"	
507(04)	24"	
518(04)	18"	

Train 1(04) West of New Orleans, LA - Freight Train Interference

04JUL26: Train 1(04) held west of New Orleans, LA, on the CNRR McComb Subdivision, at East Bridge Jct (MP906.4) waiting on NS 8038 and UP 5961 to clear across the Huey P Long Bridge (MP5.7).

Train	Delay	Comment
1(04)	1'06"	

Train 7/27(03) Minot, ND - Car Failure

04JUL26: Train 7/27(03), E/170-E/327-10 Cars, was delayed at Minot, ND (MP203.3), on the BNSF KO Subdivision, after having to setout diner car 38031 due to a broken spring. Once the setout was complete, Train 7/27(03) was back on the move west.

Service recovery was implemented as a result. Sleeper customers were affected. Snack packs, coffee, tea, juice, and water were offered to all customers as necessary. Lunch was provided for sleeper customers with hot dog, burger, salad, or soup options available from the café/lounge car. Dinner was provided in Havre with a pizza meal box from Pizza Hut. Breakfast on July 5 will be provided in Spokane with continental breakfast items. Lunch on July 5 will be provided in Everett with a to-go meal box from Panera Bread. Please note that, with no refrigeration and no lounge car available after Spokane, food service options will be limited.

WBS#: B.TR.100150.6853

Train	Delay	Comment
-------	-------	---------

Train 11(03) South of Chico, CA - Engine Failure

04JUL26: Train 11(03) was delayed 30.0 miles south of Chico, CA (MP184.1) due to a hot bearing alarm at MP161. The train was held at MP161 for 30 minutes. The train was then released at MP154.7 on the UPRR Sacramento Subdivision, approximately 67.3 miles south of Chico, CA (MP184.1), to inspect engine 23 after a wayside detector at MP161 reported a hot bearing alarm. A mechanical inspection was conducted, and no defects were found. The train then proceeded at 30MPH to the next wayside detector, which reported no defects. Upon receiving a clear reading, permission was granted for Train 11(03) to resume track speed.

Train	Delay	Comment
11(03)	30"	

Train 27(02) Pasco, WA - Engineer Rest

04JUL26: Train 27(02) was held at Pasco, WA (MP 145.4) on the BNSF Lakeside Subdivision while awaiting a fully rested Engineer to report for duty. The Engineer signed up at 6:56AM-PT. After coming on duty, the train experienced additional delay due to PTC initialization issues. Once the PTC problems were resolved and the system was successfully initialized, Train 27(02) proceeded westward.

Train	Delay	Comment
27(02)	48"	

Train 2/422(03) West of Maricopa, AZ - Broken Rail

04JUL26: Train 2/422(03) was delayed 50.7 miles west of Maricopa, AZ (MP897.7), on the UPRR Gila Subdivision, at Theba (MP847.0) due to a reported broken rail at MP852.2. Maintenance of Way responded and placed a 10MPH restriction over the defect. Once released, Train 2/422(03) had to follow UP 8061 to Gila Bend (MP857.4) and then UP 2722 from Shawmut (MP870.8) to Maricopa.

Train	Delay	Comment
2/422(03)	1'24"	

Train 22(03) North of Walnut Ridge, AR - Passenger Train Interference

04JUL26: Train 22(03) held 1.3 miles north of Walnut Ridge, AR (MP224.9), on the UPRR Hoxie Subdivision at Murta Jct (MP223.6) while meeting Train 21(03).

Train	Delay	Comment
22(03)	34"	

Train 21(03) South of Arcadia, MO - Signal

04JUL26: Train 21(03) was delayed starting 29.4 miles south of Arcadia, MO (MP88.8), on the UPRR Desoto Subdivision due to a CTC system failure at Gads Hill (MP118.2). Operating speeds were restricted until the train reached a clear signal at Piedmont (MP126.5). Additional delay was incurred at Williamsville (MP145.2) while meeting UP 7786. Train 22(03) also saw a delay operating north through the CTC system failure.

Train	Delay	Comment
21(03)	30"	CTC Failure
21(03)	19"	UP 7786
22(03)	25"	CTC Failure

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated JAN	
59(27JUN-06JUL, 09JUL)	Cancelled	
58(27JUN-06JUL, 08JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on MP 588.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL)	00"	BYPASS PSN
1 (01, 04JUL) / 421 (03JUL)	00"	BYPASS PSN

Maintenance of Way Highlights

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
59 (26)	JAN	62		Gouged Wheels

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
7 (3)	SPK	BN6714	E/170 TM #3 C/O	Enroute	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 6(03) Passenger Removal at Glenwood Springs, Colorado – Medical

04JUL26, Passenger on PNR 765F30, traveling from Emeryville, CA to Chicago, IL was removed from the train by Eagle County EMS after reporting to the Attendant he felt as if he was having a heart attack. Amtrak Police notified.

Delay: 6 (03) 33"

Consist Deviations

26-FOI-00580

00000008155

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
691 (04)	BON	Operating with 48183 club dinette in lieu of coach. Inventory has been adjusted to reflect consist.	No impact	0	48183
697 (04)	BON	Operating with 48183 club dinette in lieu of coach. Inventory has been adjusted to reflect consist.	No impact	0	48163
87 (04)	BOS	Operating with 81530 in lieu of coach, Inventory has been adjusted to reflect consist.	No impact	0	81530
690 (04)	BRK	Operating with 48183 club dinette in lieu of coach. Inventory has been adjusted to reflect consist.	No impact	0	48183
696 (04)	BRK	Operating with 48183 club dinette in lieu of coach. Inventory has been adjusted to reflect consist.	No impact	0	48183
562 (04)	LAX	Unable to accommodate passengers with bike reservations a/c operating with 90215 in consist. Please reaccommodate any passengers impacted by this.			90215
580 (04)	LAX	Unable to accommodate passengers with bike reservations a/c operating with 90215 in consist. Please reaccommodate any passengers impacted by this.			90215
7 (03)	MOT	Diner set out in MOT for broken spring.			38031
20 (04)	NOL	20(04) cut out 25091 due to it causing HEP issues. Mardi Gras protect 81545 added. capacity increase of 4 seats. **81545 must be returned to NOL**	0	0	81545
151 (04)	PHL	Due to CSX derailment operating w/ 99(3) original equipment. Will be operating with 6 coaches and cafe and full business class car.	No impact	0	82533 82518 82768 82592 43366 82741 82570 81546
66 (04)	RNK	Due to CSX derailment operating w/ 99(3) original equipment. Will be operating with 6 coaches and cafe and full business class car.	No impact	0	82533 82518 82768 82592 43366 82741 82570 81546

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
573 (04)	SAN	Unable to accommodate passengers with bike reservations a/c operating with 90215 in consist. Please reaccommodate any passengers impacted by this.			573
591 (04)	SAN	Unable to accommodate passengers with bike reservations a/c operating with 90215 in consist. Please reaccommodate any passengers impacted by this.			90215
8 (05)	SEA	No diner on set due to 38031 being set out in MOT off of 7(03). Service recovery will be required.			38031

Reverse Consists

Train Number	Station	Reason
127 (04)	NYP	Consist reversed Business class seat orientation may have changed At Rear
101 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front
150 (04)	PHL	Consist reversed Business class seat orientation may have changed At Front
2255 (04)	BOS	Consist reversed Business class seat orientation may have changed At Rear
158 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front
135 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
82 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front
140 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front