

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, July 06, 2026

Rules: 0-36



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/05/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	47	82.3%	1,435	230	84.0%	82,793	11,355	86.3%
Central Division	86.0%	66	4	93.9%	357	31	91.3%	20,396	1,849	90.9%
East Division	82.0%	131	24	81.7%	717	134	81.3%	43,278	6,743	84.4%
West Division	86.0%	69	19	72.5%	361	65	82.0%	19,119	2,763	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00580 00000008156 "UNCLASSIFIED" 7/7/2026

Endpoint Arrival Dates through 7/5/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	94,864	31,231	67%	496,215	213,460	57%	27,440,381	6,687,375	76%
Northeast Corridor	81%	41,398	15,130	63%	200,367	96,382	52%	12,048,152	2,880,433	76%
Acela	83%	7,804	2,027	74%	41,933	21,064	50%	2,378,955	623,436	74%
Northeast Regional	79%	33,594	13,103	61%	158,434	75,318	52%	9,669,197	2,256,997	77%
Richmond / Newport News / Norfolk	77%	10,032	4,387	56%	47,958	29,129	39%	2,999,812	843,432	72%
Springfield Shuttles	89%	884	210	76%	3,702	1,441	61%	172,738	25,888	85%
Roanoke	79%	2,485	1,501	40%	14,935	9,094	39%	908,790	184,467	80%
On Spine Northeast Regional	80%	20,193	7,005	65%	91,839	35,654	61%	5,587,857	1,203,210	78%
State Supported	80%	43,660	11,097	75%	234,117	75,793	68%	12,013,355	2,437,118	80%
Borealis	80%	578	0	100%	2,868	1,057	63%	153,630	31,423	80%
Capitol Corridor	90%	2,897	1,608	44%	18,061	3,819	79%	1,021,475	133,346	87%
Carolinian	70%	1,097	524	52%	6,003	4,193	30%	316,078	120,133	62%
Cascades	75%	3,665	2	100%	16,594	5,019	70%	704,446	193,640	73%
Downeaster	82%	1,731	38	98%	8,117	2,923	64%	404,455	48,231	88%
Empire	78%	6,578	1,253	81%	29,070	11,810	59%	1,483,319	326,459	78%
Adirondack	72%	489	85	83%	2,250	1,388	38%	88,712	26,881	70%
Ethan Allen Express	70%	652	298	54%	2,723	1,832	33%	153,728	49,464	68%
Maple Leaf	70%	920	342	63%	4,361	1,883	57%	179,694	68,903	62%
New York - Albany	85%	2,486	0	100%	12,284	3,426	72%	689,348	107,297	84%
New York - Niagara Falls	75%	1,525	22	99%	6,501	2,514	61%	367,720	72,287	80%
Berkshire Flyer	60%	506	506	0%	951	767	19%	4,117	1,627	60%
Gold Runner	73%	3,517	1,185	66%	14,064	5,232	63%	688,090	237,434	65%
Heartland Flyer	70%	367	204	44%	1,437	750	48%	57,039	21,252	63%
Hiawatha	90%	2,161	0	100%	9,863	856	91%	467,670	51,407	89%
Illinois	78%	3,399	593	83%	14,835	6,714	55%	677,025	182,783	73%
Carl Sandburg / Illinois Zephyr	85%	772	63	92%	2,950	1,151	61%	112,513	28,953	74%
Illini / Saluki	85%	1,110	36	97%	4,942	2,023	59%	238,635	56,072	77%
Lincoln Service	70%	1,517	494	67%	6,943	3,540	49%	325,877	97,758	70%
Keystone	92%	1,328	409	69%	27,229	8,388	69%	2,086,504	218,389	90%
Lincoln / Missouri	70%	278	278	0%	3,812	1,977	48%	212,485	105,872	50%
Mardi Gras Service	80%	386	153	60%	2,158	602	72%	112,312	22,746	80%
Michigan	70%	2,056	857	58%	12,231	6,672	45%	532,269	171,734	68%
Blue Water	70%	283	20	93%	2,692	2,240	17%	123,020	47,622	61%
Pere Marquette	85%	403	68	83%	1,368	490	64%	68,934	13,827	80%
Wolverine	70%	1,370	769	44%	8,171	3,942	52%	340,315	110,285	68%
Missouri	80%	0	0	-	926	83	91%	60,158	13,340	78%
Pacific Surfliner	85%	10,752	2,854	73%	54,556	9,463	83%	2,126,650	335,075	84%
Pennsylvanian	80%	871	766	12%	4,616	2,766	40%	243,386	44,952	82%
Piedmont	80%	15	0	100%	1,131	704	38%	314,318	79,199	75%
Vermont	75%	1,984	373	81%	6,546	2,765	58%	352,046	99,703	72%
Long Distance	70%	9,806	5,004	49%	61,731	41,285	33%	3,339,607	1,367,361	59%
Auto Train	70%	697	0	100%	4,189	810	81%	213,103	71,692	66%
California Zephyr	70%	1,058	561	47%	5,230	2,984	43%	264,638	87,861	67%
Cardinal	70%	0	0	-	1,091	983	10%	64,754	31,181	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,085	49,375	72%
Coast Starlight	70%	1,259	294	77%	6,339	1,390	78%	310,732	105,864	66%
Crescent	70%	355	355	0%	3,924	3,358	14%	253,574	74,860	70%
Empire Builder	70%	1,129	619	45%	6,329	4,083	35%	260,621	123,925	52%
Floridian	60%	858	858	0%	6,980	6,933	1%	437,010	290,390	34%
Lake Shore Ltd	73%	1,089	32	97%	5,771	3,522	39%	258,569	75,529	71%
Palmetto	70%	0	0	-	3,947	3,348	15%	251,594	69,397	72%
Silver Meteor	70%	1,109	656	41%	5,594	4,847	13%	277,978	114,966	59%
Southwest Chief	60%	925	662	28%	5,149	3,856	25%	223,610	142,129	36%
Sunset Ltd	70%	329	256	22%	1,545	1,024	34%	79,817	27,670	65%
Texas Eagle	70%	998	711	29%	5,643	4,147	27%	266,522	102,522	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000150 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through July 05, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	36,989	498,586	742	1,604,289	29,136,234	551

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,310	133,654	173	75,691	8,354,654	91
INFRASTRUCTURE PLANNED	135	1,717	133,654	128	80,675	8,354,654	97
FLEET RELIABILITY	90	7,676	498,586	154	260,673	29,136,234	89
TRAIN OPERATIONS	424	25,286	498,586	507	1,187,250	29,136,234	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/05/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	47	82.3%	1,435	230	84.0%	82,793	11,355	86.3%
Central Division	86.0%	66	4	93.9%	357	31	91.3%	20,396	1,849	90.9%
East Division	82.0%	131	24	81.7%	717	134	81.3%	43,278	6,743	84.4%
West Division	86.0%	69	19	72.5%	361	65	82.0%	19,119	2,763	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/05/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	47	82.3%	1,435	230	84.0%	82,793	11,355	86.3%
Central Division	86.0%	66	4	93.9%	357	31	91.3%	20,396	1,849	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	10	0	100.0%	527	18	96.6%
CHI	86.0%	24	0	100.0%	130	14	89.2%	7,369	878	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	10	0	100.0%	546	52	90.5%
FTW	92.5%	1	0	100.0%	5	1	80.0%	301	35	88.4%
GBB	-	-	-	-	-	-	-	1	1	0.0%
GRR	95.5%	1	0	100.0%	4	0	100.0%	263	8	97.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	-	-	-	8	1	87.5%	546	41	92.5%
LAX	89.5%	1	0	100.0%	5	0	100.0%	267	40	85.0%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	0	100.0%	29	3	89.7%	1,627	100	93.9%
MOE	97.5%	2	0	100.0%	10	1	90.0%	555	9	98.4%
MSP	96.5%	1	0	100.0%	5	0	100.0%	271	5	98.2%
NOL	94.5%	3	1	66.7%	17	3	82.4%	1,167	56	95.2%
OKC	97.0%	1	0	100.0%	5	0	100.0%	272	6	97.8%
PDX	86.0%	4	0	100.0%	20	3	85.0%	1,102	110	90.0%
PNT	88.0%	2	0	100.0%	14	0	100.0%	717	58	91.9%
PTH	93.0%	1	0	100.0%	5	0	100.0%	266	10	96.2%
QCY	91.0%	2	0	100.0%	10	0	100.0%	540	39	92.8%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	5	0	100.0%	274	27	90.1%
SEA	85.0%	7	2	71.4%	35	4	88.6%	1,925	211	89.0%
STL	89.0%	4	1	75.0%	20	1	95.0%	1,077	91	91.6%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	10	0	100.0%	540	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	131	24	81.7%	717	134	81.3%	43,278	6,743	84.4%
ALB	88.5%	7	0	100.0%	38	2	94.7%	2,052	163	92.1%
BON	87.5%	5	1	80.0%	24	7	70.8%	1,336	147	89.0%
BOS	85.5%	12	0	100.0%	76	5	93.4%	4,716	567	88.0%
BRK	92.5%	5	0	100.0%	24	6	75.0%	1,325	90	93.2%
BTN	82.0%	1	0	100.0%	5	0	100.0%	264	39	85.2%
CLT	91.5%	2	2	0.0%	11	3	72.7%	1,352	135	90.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	10	2	80.0%	541	52	90.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/05/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	47	82.3%	1,435	230	84.0%	82,793	11,355	86.3%
East Division	82.0%	131	24	81.7%	717	134	81.3%	43,278	6,743	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	3	3	0.0%	41	6	85.4%	3,064	512	83.3%
HFD	-	-	-	-	4	0	100.0%	151	8	94.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	5	0	100.0%	274	34	87.6%
MIA	89.5%	2	0	100.0%	10	2	80.0%	549	62	88.7%
MTR	79.0%	1	0	100.0%	5	1	80.0%	261	47	82.0%
NFK	84.5%	2	0	100.0%	10	5	50.0%	631	114	81.9%
NFL	93.5%	2	0	100.0%	10	1	90.0%	560	23	95.9%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	23	1	95.7%	1,429	224	84.3%
NPN	93.0%	1	0	100.0%	8	1	87.5%	521	36	93.1%
NYP	75.5%	36	8	77.8%	200	48	76.0%	11,254	2,510	77.7%
PGH	93.0%	1	0	100.0%	5	1	80.0%	276	20	92.8%
PHL	48.0%	5	3	40.0%	23	10	56.5%	1,423	687	51.7%
PIT	76.0%	1	1	0.0%	2	2	0.0%	8	7	12.5%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	1	0	100.0%	5	0	100.0%	1,062	41	96.1%
RNK	83.5%	2	2	0.0%	10	3	70.0%	544	80	85.3%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	1	1	0.0%	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	5	0	100.0%	264	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	-	-	-	3	0	100.0%	271	10	96.3%
SFA	88.0%	1	0	100.0%	5	0	100.0%	274	37	86.5%
SPG	92.5%	7	0	100.0%	29	1	96.6%	1,681	93	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	5	0	100.0%	264	56	78.8%
WAS	84.0%	23	3	87.0%	120	26	78.3%	6,716	867	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	69	19	72.5%	361	65	82.0%	19,119	2,763	85.5%
ARN	92.0%	1	1	0.0%	5	1	80.0%	276	20	92.8%
BFD	79.0%	7	3	57.1%	32	14	56.3%	1,718	355	79.3%
EMY	72.0%	1	1	0.0%	5	4	20.0%	281	88	68.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	15	3	80.0%	831	117	85.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/05/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	47	82.3%	1,435	230	84.0%	82,793	11,355	86.3%
West Division	86.0%	69	19	72.5%	361	65	82.0%	19,119	2,763	85.5%
LAX	89.5%	10	0	100.0%	48	5	89.6%	2,462	241	90.2%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	9	5	44.4%	54	18	66.7%	2,953	754	74.5%
PDX	86.0%	1	0	100.0%	5	0	100.0%	260	59	77.3%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	3	75.0%	72	10	86.1%	3,876	420	89.2%
SAN	90.5%	13	2	84.6%	65	4	93.8%	3,309	298	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	0	100.0%	5	2	60.0%	257	105	59.1%
SJC	89.0%	7	3	57.1%	35	3	91.4%	1,942	185	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	15	1	93.3%	594	61	89.7%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	5	0	100.0%	271	20	92.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		3	1	66.7%	118	26	78.0%	2	0	100.0%	114	20	82.5%
3		5	0	100.0%	276	54	80.4%	5	1	80.0%	274	118	56.9%
4	35	5	0	100.0%	275	42	84.7%	5	4	20.0%	275	183	33.5%
5		5	1	80.0%	274	44	83.9%	4	2	50.0%	270	65	75.9%
6	33	5	4	20.0%	273	81	70.3%	5	4	20.0%	273	86	68.5%
7		5	1	80.0%	265	36	86.4%	5	1	80.0%	258	62	76.0%
8		5	2	60.0%	265	113	57.4%	5	3	40.0%	264	152	42.4%
11		5	1	80.0%	276	51	81.5%	5	0	100.0%	270	54	80.0%
14		5	0	100.0%	277	41	85.2%	5	0	100.0%	275	83	69.8%
19	No OS	5	3	40.0%	275	68	75.3%	5	5	0.0%	273	64	76.6%
20	482	5	2	60.0%	275	20	92.7%	5	5	0.0%	275	52	81.1%
21		5	0	100.0%	272	22	91.9%	5	4	20.0%	271	66	75.6%
22		5	0	100.0%	273	25	90.8%	5	3	40.0%	271	65	76.0%
23	22	5	1	80.0%	278	6	97.8%	5	2	60.0%	276	71	74.3%
24		5	1	80.0%	278	15	94.6%	5	1	80.0%	277	44	84.1%
25		5	0	100.0%	277	3	98.9%	5	2	60.0%	275	71	74.2%
26	55	5	0	100.0%	277	5	98.2%	5	1	80.0%	275	53	80.7%
27		5	2	60.0%	263	17	93.5%	5	1	80.0%	259	82	68.3%
28		5	0	100.0%	259	59	77.2%	5	1	80.0%	259	52	79.9%
40	No OS	5	1	80.0%	271	39	85.6%	5	5	0.0%	270	137	49.3%
41	No OS	4	3	25.0%	270	105	61.1%	5	5	0.0%	269	201	25.3%
42	158	5	1	80.0%	277	21	92.4%	5	3	40.0%	275	45	83.6%
43	107	5	0	100.0%	276	41	85.1%	5	5	0.0%	276	61	77.9%
48		5	1	80.0%	275	54	80.4%	5	2	60.0%	275	40	85.5%
49		5	3	40.0%	275	70	74.5%	5	2	60.0%	275	54	80.4%
50	210	2	1	50.0%	113	27	76.1%	3	3	0.0%	113	66	41.6%
52		5	0	100.0%	274	37	86.5%	5	0	100.0%	273	61	77.7%
53		5	0	100.0%	274	34	87.6%	5	2	60.0%	273	87	68.1%
54		3	0	100.0%	103	6	94.2%	3	1	66.7%	103	14	86.4%
57		3	0	100.0%	102	4	96.1%	3	1	66.7%	102	7	93.1%
63	46	5	2	60.0%	278	119	57.2%	5	4	20.0%	274	144	47.4%
64		5	0	100.0%	276	63	77.2%	5	3	40.0%	276	94	65.9%
65		3	0	100.0%	86	12	86.0%	2	0	100.0%	85	11	87.1%
66	Cncld	5	2	60.0%	275	56	79.6%	4	0	100.0%	272	49	82.0%
68		5	1	80.0%	278	56	79.9%	5	4	20.0%	278	107	61.5%
69	28	5	0	100.0%	265	59	77.7%	5	3	40.0%	261	35	86.6%
71		5	0	100.0%	273	3	98.9%	5	4	20.0%	272	70	74.3%
78	165	5	1	80.0%	273	21	92.3%	5	4	20.0%	272	54	80.1%
79	32	5	0	100.0%	275	55	80.0%	5	5	0.0%	274	89	67.5%
80	Cncld	5	2	60.0%	275	30	89.1%	4	3	25.0%	272	52	80.9%
87	83	3	0	100.0%	106	24	77.4%	3	3	0.0%	106	36	66.0%
90	97	5	0	100.0%	273	10	96.3%	5	4	20.0%	272	41	84.9%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
96		1	0	100.0%	35	7	80.0%	1	0	100.0%	35	9	74.3%
97		5	5	0.0%	275	178	35.3%	5	4	20.0%	273	80	70.7%
98	66	5	1	80.0%	275	22	92.0%	5	5	0.0%	273	85	68.9%
99	314	3	0	100.0%	105	12	88.6%	1	1	0.0%	102	58	43.1%
100	172	1	1	0.0%	20	5	75.0%	1	1	0.0%	19	3	84.2%
103		3	0	100.0%	104	21	79.8%	3	0	100.0%	104	8	92.3%
117		1	0	100.0%	19	11	42.1%	1	0	100.0%	19	3	84.2%
118		3	2	33.3%	104	8	92.3%	3	0	100.0%	104	5	95.2%
120		1	0	100.0%	35	5	85.7%	1	0	100.0%	35	3	91.4%
121		1	0	100.0%	35	9	74.3%	1	0	100.0%	35	14	60.0%
123		1	0	100.0%	37	6	83.8%	1	0	100.0%	37	1	97.3%
124	87	3	1	66.7%	103	8	92.2%	3	3	0.0%	102	26	74.5%
128	119	3	0	100.0%	106	19	82.1%	2	2	0.0%	105	18	82.9%
132		1	0	100.0%	35	3	91.4%	1	0	100.0%	35	4	88.6%
135		3	0	100.0%	105	17	83.8%	3	2	33.3%	105	53	49.5%
140	28	3	0	100.0%	104	12	88.5%	3	2	33.3%	103	22	78.6%
143		3	0	100.0%	103	9	91.3%	3	1	66.7%	103	23	77.7%
145	84	1	0	100.0%	35	5	85.7%	1	1	0.0%	35	11	68.6%
146	18	3	1	66.7%	103	17	83.5%	3	3	0.0%	103	37	64.1%
150		3	1	66.7%	102	55	46.1%	3	1	66.7%	100	49	51.0%
151	65	5	2	60.0%	274	88	67.9%	5	5	0.0%	273	89	67.4%
153		3	2	33.3%	104	10	90.4%	3	1	66.7%	104	15	85.6%
154		1	1	0.0%	35	5	85.7%	1	0	100.0%	35	19	45.7%
155	119	3	2	33.3%	106	17	84.0%	3	3	0.0%	106	36	66.0%
156	422	3	1	66.7%	106	11	89.6%	3	3	0.0%	106	34	67.9%
157		1	0	100.0%	35	2	94.3%	1	0	100.0%	35	11	68.6%
158	181	3	2	33.3%	105	17	83.8%	3	3	0.0%	105	23	78.1%
160	19	3	0	100.0%	103	5	95.1%	3	1	66.7%	101	24	76.2%
161	41	3	0	100.0%	104	9	91.3%	3	3	0.0%	103	66	35.9%
162	44	3	0	100.0%	104	5	95.2%	3	2	33.3%	104	51	51.0%
164		3	1	66.7%	106	9	91.5%	3	1	66.7%	106	45	57.5%
165	121	3	0	100.0%	105	27	74.3%	3	3	0.0%	105	43	59.0%
169		3	0	100.0%	104	12	88.5%	2	0	100.0%	103	21	79.6%
195		3	0	100.0%	104	4	96.2%	3	2	33.3%	104	54	48.1%
230		5	0	100.0%	112	4	96.4%	5	0	100.0%	112	6	94.6%
232		5	0	100.0%	278	11	96.0%	5	0	100.0%	278	17	93.9%
234		5	1	80.0%	278	20	92.8%	5	0	100.0%	278	24	91.4%
235		5	0	100.0%	202	27	86.6%	5	3	40.0%	202	44	78.2%
236		5	0	100.0%	262	7	97.3%	5	0	100.0%	262	36	86.3%
237		5	0	100.0%	276	52	81.2%	5	2	60.0%	274	45	83.6%
238		5	0	100.0%	202	19	90.6%	5	0	100.0%	201	14	93.0%
239		5	1	80.0%	277	73	73.6%	5	2	60.0%	276	32	88.4%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
240		5	0	100.0%	277	20	92.8%	5	1	80.0%	275	45	83.6%
241		5	2	60.0%	278	70	74.8%	5	1	80.0%	278	67	75.9%
243		5	3	40.0%	214	58	72.9%	5	3	40.0%	213	29	86.4%
245		5	2	60.0%	159	29	81.8%	5	1	80.0%	158	18	88.6%
280		5	1	80.0%	278	12	95.7%	5	0	100.0%	278	50	82.0%
281		5	0	100.0%	278	29	89.6%	5	3	40.0%	278	50	82.0%
283		5	2	60.0%	278	66	76.3%	5	3	40.0%	278	55	80.2%
284		5	0	100.0%	278	10	96.4%	5	2	60.0%	276	44	84.1%
290	26	5	0	100.0%	278	48	82.7%	5	4	20.0%	276	95	65.6%
291		5	1	80.0%	277	76	72.6%	5	3	40.0%	275	61	77.8%
300	80	5	0	100.0%	262	19	92.7%	5	3	40.0%	260	59	77.3%
301	22	5	0	100.0%	276	9	96.7%	5	2	60.0%	273	52	81.0%
302		5	0	100.0%	263	31	88.2%	5	2	60.0%	259	74	71.4%
305		5	0	100.0%	266	28	89.5%	5	4	20.0%	262	106	59.5%
306		5	0	100.0%	274	15	94.5%	5	3	40.0%	273	74	72.9%
307		5	0	100.0%	266	35	86.8%	5	2	60.0%	263	72	72.6%
318	30	5	2	60.0%	277	28	89.9%	5	3	40.0%	274	127	53.6%
319	Cncld	5	0	100.0%	278	17	93.9%	3	2	33.3%	274	147	46.4%
331		5	0	100.0%	278	29	89.6%	5	0	100.0%	278	40	85.6%
332		5	0	100.0%	278	14	95.0%	5	1	80.0%	278	40	85.6%
334		5	0	100.0%	278	9	96.8%	5	0	100.0%	277	36	87.0%
335		5	0	100.0%	278	30	89.2%	5	2	60.0%	276	45	83.7%
336		5	1	80.0%	278	9	96.8%	5	0	100.0%	276	25	90.9%
337		5	0	100.0%	278	17	93.9%	5	1	80.0%	274	34	87.6%
338		5	2	60.0%	278	43	84.5%	5	1	80.0%	276	82	70.3%
339		5	1	80.0%	278	47	83.1%	5	1	80.0%	278	49	82.4%
341		5	1	80.0%	267	36	86.5%	5	1	80.0%	262	36	86.3%
342		5	0	100.0%	278	21	92.4%	5	0	100.0%	276	53	80.8%
350	16	5	0	100.0%	259	17	93.4%	5	4	20.0%	254	140	44.9%
351		5	0	100.0%	261	25	90.4%	5	1	80.0%	259	69	73.4%
352	28	5	0	100.0%	245	20	91.8%	5	3	40.0%	239	74	69.0%
354	56	5	1	80.0%	259	29	88.8%	5	4	20.0%	255	93	63.5%
355	81	5	0	100.0%	272	27	90.1%	5	5	0.0%	265	90	66.0%
364	44	5	1	80.0%	267	61	77.2%	5	4	20.0%	261	94	64.0%
365		5	0	100.0%	266	10	96.2%	5	4	20.0%	264	96	63.6%
370		5	1	80.0%	269	34	87.4%	4	1	75.0%	261	66	74.7%
371		4	0	100.0%	263	8	97.0%	4	1	75.0%	262	28	89.3%
380		5	0	100.0%	264	24	90.9%	5	3	40.0%	264	52	80.3%
381		5	0	100.0%	278	11	96.0%	5	2	60.0%	277	50	81.9%
382		5	0	100.0%	277	16	94.2%	5	3	40.0%	277	87	68.6%
383		5	0	100.0%	267	25	90.6%	5	2	60.0%	265	107	59.6%
390		5	0	100.0%	260	17	93.5%	5	2	60.0%	259	65	74.9%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
391		5	0	100.0%	263	8	97.0%	5	3	40.0%	260	68	73.8%
392		5	0	100.0%	277	5	98.2%	5	4	20.0%	275	82	70.2%
393		5	0	100.0%	278	16	94.2%	5	4	20.0%	275	81	70.5%
400		3	0	100.0%	85	6	92.9%	3	0	100.0%	83	2	97.6%
405		3	0	100.0%	80	0	100.0%	3	0	100.0%	80	4	95.0%
409	19	1	0	100.0%	38	1	97.4%	1	1	0.0%	38	4	89.5%
416		1	0	100.0%	34	4	88.2%	1	0	100.0%	34	3	91.2%
448		5	2	60.0%	208	40	80.8%	5	3	40.0%	206	71	65.5%
449		5	1	80.0%	206	31	85.0%	5	4	20.0%	206	40	80.6%
450		3	0	100.0%	84	26	69.0%	3	2	33.3%	82	26	68.3%
460	34	3	0	100.0%	83	27	67.5%	3	3	0.0%	80	28	65.0%
461		3	0	100.0%	86	5	94.2%	3	0	100.0%	85	2	97.6%
464		3	0	100.0%	83	16	80.7%	3	1	66.7%	81	25	69.1%
465		1	0	100.0%	38	1	97.4%	1	0	100.0%	38	1	97.4%
488		3	0	100.0%	89	21	76.4%	3	0	100.0%	81	11	86.4%
497		1	0	100.0%	35	1	97.1%	1	0	100.0%	35	7	80.0%
499		3	0	100.0%	82	11	86.6%	3	0	100.0%	79	6	92.4%
500		5	1	80.0%	269	16	94.1%	4	0	100.0%	266	32	88.0%
502		5	1	80.0%	276	16	94.2%	4	0	100.0%	272	56	79.4%
503		5	1	80.0%	274	26	90.5%	5	3	40.0%	268	77	71.3%
504		5	0	100.0%	278	17	93.9%	5	2	60.0%	276	84	69.6%
505		5	1	80.0%	276	37	86.6%	4	2	50.0%	271	75	72.3%
506		5	1	80.0%	273	39	85.7%	5	1	80.0%	268	42	84.3%
507		5	0	100.0%	278	34	87.8%	5	2	60.0%	278	90	67.6%
508		5	0	100.0%	273	39	85.7%	5	0	100.0%	270	62	77.0%
509		5	0	100.0%	275	12	95.6%	5	0	100.0%	275	63	77.1%
511		5	0	100.0%	270	21	92.2%	5	0	100.0%	269	45	83.3%
516		5	1	80.0%	270	28	89.6%	5	2	60.0%	269	125	53.5%
517		5	0	100.0%	278	8	97.1%	5	4	20.0%	274	112	59.1%
518		5	0	100.0%	278	35	87.4%	5	3	40.0%	276	186	32.6%
519		5	0	100.0%	270	9	96.7%	5	1	80.0%	268	64	76.1%
562		5	0	100.0%	270	21	92.2%	5	0	100.0%	267	29	89.1%
564		5	0	100.0%	270	17	93.7%	5	1	80.0%	262	31	88.2%
566		5	0	100.0%	268	17	93.7%	5	1	80.0%	265	33	87.5%
567		5	0	100.0%	155	8	94.8%	5	0	100.0%	153	6	96.1%
572		5	1	80.0%	265	23	91.3%	5	2	60.0%	260	67	74.2%
573		5	0	100.0%	268	40	85.1%	5	0	100.0%	261	44	83.1%
579	25	5	0	100.0%	155	8	94.8%	5	2	60.0%	150	28	81.3%
580		5	0	100.0%	270	14	94.8%	5	0	100.0%	265	21	92.1%
581		5	1	80.0%	270	44	83.7%	5	1	80.0%	268	55	79.5%
584	39	5	2	60.0%	154	19	87.7%	5	5	0.0%	150	87	42.0%
587		5	0	100.0%	265	15	94.3%	5	1	80.0%	256	39	84.8%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
588		5	1	80.0%	155	13	91.6%	5	0	100.0%	154	22	85.7%
591		5	0	100.0%	269	18	93.3%	5	0	100.0%	263	29	89.0%
593		5	0	100.0%	264	37	86.0%	5	1	80.0%	246	28	88.6%
595		5	1	80.0%	265	42	84.2%	5	1	80.0%	262	47	82.1%
615	Cncld	1	1	0.0%	35	19	45.7%	0	0	0.0%	34	5	85.3%
637		3	0	100.0%	57	6	89.5%	2	0	100.0%	56	4	92.9%
663	Cncld	3	2	33.3%	76	12	84.2%	2	1	50.0%	75	7	90.7%
664	55	3	1	66.7%	75	7	90.7%	3	2	33.3%	75	8	89.3%
665	83	3	0	100.0%	76	8	89.5%	3	2	33.3%	76	21	72.4%
666		1	1	0.0%	74	21	71.6%	1	0	100.0%	74	7	90.5%
667	Cncld	1	0	100.0%	74	6	91.9%	0	0	0.0%	73	14	80.8%
670	Cncld	3	1	66.7%	76	11	85.5%	2	1	50.0%	75	14	81.3%
672		3	0	100.0%	76	7	90.8%	3	1	66.7%	76	13	82.9%
690		2	0	100.0%	80	2	97.5%	2	0	100.0%	79	4	94.9%
691	16	2	0	100.0%	80	7	91.3%	2	1	50.0%	78	22	71.8%
692		2	0	100.0%	80	3	96.3%	2	1	50.0%	79	14	82.3%
693		2	0	100.0%	80	12	85.0%	2	1	50.0%	79	22	72.2%
694		1	0	100.0%	79	6	92.4%	1	0	100.0%	79	14	82.3%
695		1	1	0.0%	78	10	87.2%	1	0	100.0%	78	14	82.1%
696	15	2	0	100.0%	80	8	90.0%	2	2	0.0%	80	22	72.5%
697		2	1	50.0%	80	17	78.8%	2	1	50.0%	80	16	80.0%
698		2	0	100.0%	78	2	97.4%	2	0	100.0%	78	7	91.0%
699		2	0	100.0%	60	8	86.7%	1	0	100.0%	59	2	96.6%
701		5	2	60.0%	210	23	89.0%	5	0	100.0%	207	20	90.3%
702		5	0	100.0%	277	31	88.8%	5	1	80.0%	275	61	77.8%
703	19	5	3	40.0%	278	80	71.2%	5	3	40.0%	277	73	73.6%
704		5	0	100.0%	209	32	84.7%	4	0	100.0%	203	38	81.3%
710	57	5	2	60.0%	278	71	74.5%	5	2	60.0%	274	75	72.6%
711		5	2	60.0%	269	30	88.8%	4	1	75.0%	251	46	81.7%
712		5	2	60.0%	275	73	73.5%	5	1	80.0%	267	88	67.0%
713	45	2	1	50.0%	148	15	89.9%	2	2	0.0%	135	58	57.0%
714		4	3	25.0%	159	61	61.6%	4	2	50.0%	147	60	59.2%
715		5	1	80.0%	277	59	78.7%	3	1	66.7%	256	126	50.8%
716		5	1	80.0%	278	108	61.2%	5	2	60.0%	273	104	61.9%
717		5	1	80.0%	264	63	76.1%	5	2	60.0%	246	72	70.7%
718	97	5	4	20.0%	278	140	49.6%	5	4	20.0%	276	95	65.6%
719		5	4	20.0%	278	92	66.9%	5	3	40.0%	264	75	71.6%
720	285	2	0	100.0%	87	9	89.7%	2	1	50.0%	87	5	94.3%
723		2	0	100.0%	87	5	94.3%	2	0	100.0%	87	9	89.7%
724	153	2	0	100.0%	87	3	96.6%	2	1	50.0%	87	16	81.6%
727		2	0	100.0%	87	6	93.1%	2	0	100.0%	87	14	83.9%
728	86	2	0	100.0%	87	6	93.1%	2	1	50.0%	87	16	81.6%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
729		2	1	50.0%	86	10	88.4%	2	0	100.0%	86	20	76.7%
732	35	2	0	100.0%	85	14	83.5%	2	1	50.0%	83	15	81.9%
733	265	2	0	100.0%	87	13	85.1%	2	2	0.0%	83	29	65.1%
734	18	2	0	100.0%	87	14	83.9%	2	1	50.0%	86	18	79.1%
736	Cncld	2	2	0.0%	63	6	90.5%	1	0	100.0%	62	7	88.7%
737	Cncld	2	1	50.0%	63	7	88.9%	1	0	100.0%	62	11	82.3%
738	128	2	1	50.0%	87	13	85.1%	2	1	50.0%	83	11	86.7%
741	126	2	1	50.0%	87	13	85.1%	2	1	50.0%	87	16	81.6%
742		2	1	50.0%	87	11	87.4%	2	0	100.0%	85	7	91.8%
743	67	2	2	0.0%	87	17	80.5%	2	1	50.0%	86	9	89.5%
744	65	2	1	50.0%	87	12	86.2%	2	1	50.0%	87	29	66.7%
745		2	1	50.0%	87	8	90.8%	2	0	100.0%	87	14	83.9%
746	50	2	1	50.0%	87	7	92.0%	2	1	50.0%	87	13	85.1%
747	16	2	0	100.0%	87	14	83.9%	2	1	50.0%	87	19	78.2%
748		2	0	100.0%	86	12	86.0%	2	0	100.0%	86	13	84.9%
749		2	0	100.0%	84	12	85.7%	2	0	100.0%	77	9	88.3%
751		2	1	50.0%	86	15	82.6%	2	0	100.0%	84	9	89.3%
757		5	0	100.0%	63	3	95.2%	5	0	100.0%	62	4	93.5%
761	34	5	1	80.0%	274	12	95.6%	5	1	80.0%	271	35	87.1%
765		5	0	100.0%	274	24	91.2%	5	0	100.0%	274	36	86.9%
769		5	0	100.0%	274	25	90.9%	5	0	100.0%	268	49	81.7%
770	39	5	0	100.0%	274	21	92.3%	5	3	40.0%	272	77	71.7%
774	43	5	0	100.0%	274	16	94.2%	5	1	80.0%	273	57	79.1%
777		5	0	100.0%	159	9	94.3%	5	0	100.0%	158	34	78.5%
782		5	3	40.0%	159	59	62.9%	5	0	100.0%	154	15	90.3%
785		5	1	80.0%	274	18	93.4%	5	0	100.0%	274	46	83.2%
786		5	0	100.0%	63	16	74.6%	5	1	80.0%	62	28	54.8%
790		5	0	100.0%	274	26	90.5%	5	1	80.0%	271	33	87.8%
794		5	1	80.0%	274	32	88.3%	5	1	80.0%	271	56	79.3%
821	22	5	0	100.0%	272	6	97.8%	5	3	40.0%	272	106	61.0%
822	12	5	1	80.0%	274	15	94.5%	5	3	40.0%	272	121	55.5%
1233	67	2	1	50.0%	8	3	62.5%	2	2	0.0%	8	5	37.5%
1246	50	2	2	0.0%	8	7	12.5%	2	2	0.0%	8	3	62.5%
1333		5	2	60.0%	274	30	89.1%	5	2	60.0%	271	90	66.8%
1340		5	0	100.0%	273	5	98.2%	5	2	60.0%	273	44	83.9%
2208		3	1	66.7%	5	1	80.0%	3	0	100.0%	5	0	100.0%
2209		1	0	100.0%	2	0	100.0%	1	0	100.0%	2	0	100.0%
2212		1	0	100.0%	2	0	100.0%	1	0	100.0%	2	0	100.0%
2213		1	0	100.0%	2	0	100.0%	1	0	100.0%	2	0	100.0%
2215		1	0	100.0%	21	8	61.9%	1	0	100.0%	21	12	42.9%
2216		1	0	100.0%	69	3	95.7%	1	0	100.0%	69	2	97.1%
2218		1	0	100.0%	66	11	83.3%	1	0	100.0%	66	10	84.8%

Amtrak On Time Performance

Trains Arriving Through: 7/5/2026

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2219		3	1	66.7%	5	2	60.0%	3	2	33.3%	5	2	60.0%
2222		1	0	100.0%	51	3	94.1%	1	0	100.0%	50	4	92.0%
2223		1	0	100.0%	21	5	76.2%	1	0	100.0%	20	3	85.0%
2224		3	0	100.0%	20	4	80.0%	3	0	100.0%	20	2	90.0%
2226	Cncld	1	0	100.0%	34	7	79.4%	0	0	0.0%	32	8	75.0%
2227		1	1	0.0%	2	2	0.0%	1	0	100.0%	2	0	100.0%
2233	21	1	0	100.0%	19	3	84.2%	1	1	0.0%	19	3	84.2%
2255	19	3	0	100.0%	102	11	89.2%	3	3	0.0%	101	49	51.5%
2258	44	3	0	100.0%	38	9	76.3%	3	3	0.0%	37	15	59.5%
2259		3	0	100.0%	58	23	60.3%	3	2	33.3%	57	27	52.6%
2260	18	3	0	100.0%	5	0	100.0%	3	3	0.0%	5	4	20.0%
2265	27	3	0	100.0%	39	3	92.3%	3	3	0.0%	38	23	39.5%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2226	NYP	Trn Cancelled	SMW	5	SMW	5	BAL-XPV	AM	Diversions around M/W work, Control Point, .. OPERATED 1 TRK POINT TO GUNPOW A/C 2TRK RIVER TO GUNPOW O/S
2233	WAS	21	FTI	9	FTI	9	WIL-XPV	AM	Meet, NS37A, Control Point, RAGAN, NS37A IN EMERGENCY ON NO. 1 TRACK AT RAGAN. 2233 INSPECTED
2255	WAS	19	ENG	29	ENG	29	NHV-NHV	AM	Other electrical failure, 2139 NG NP, HAD TO RECYCLE EQUIPMENT TO CLEAR MULTIPLE FAULTS
2258	BOS	44	POL	32	POL	32	XGX-PVD	AM	Right of Way police hold, AM2258 held at Palver's Cove a/c police hold Mystic River - High St
2260	BOS	18	OTH	13	CAR	8	BBY-BBY	AM	Door, 3738 NG NB, door issues on c/4 and c/7
2265	WAS	27	DSR	27	DSR	25	NHV-STM	MN	Per bulletin Control Point, 273/234, 30, 1/2
66	BOS	Trn Cancelled	ENG	252	ENG	238	RNK-LYH	NS	Air / Brake 305
87	NFK	83	WTR	105	WTR	105	WAS-WAS	AM	Heat order, Control Point, K INT, NO DSL'S AVAILABLE, NEC'Y TO USE DSL OFF LATE INBOUND 158
99	NPN	314	WTR	184	WTR	147	WAS-WAS	AM	Heat order, Control Point, K INT, NO DSL'S AVAILABLE, NEC'Y TO USE DSL OFF LATE INBOUND 156
100	NYP	172	MTI	87	MTI	87	XHM-NWK	AM	Disabled train ahead, Other, XGY-XGY, HELD ON NO.3 TRACK AT GRUNDY TO TRANSFER PASSENGERS FROM DISABLED AM2226 ON NO.2 TRK
124	PHL	87	SVS	47	SVS	47	WAS-WAS	AM	Water, commissary, toilet/trash dumping, LATE COMMISSARY TO TRAIN, DUE TO TRAIN BEING ON 28TRK, COMMISSARY UNABLE TO CROSS OVER DUE TO A97 BLOCKING THE CROSSING
128	NYP	119	DSR	131	DSR	131	NFK-X3V	NS	Per bulletin Milepost w/Letters, N3.5, P3.0, 25, all tracks
140	SPG	28	DSR	21	MBO	16	NRO-STM	MN	For maritime traffic Bridge, cos cob
145	RNK	84	PTI	79	PTI	37	XA1-BCV	NS	Wait for station track 156, Control Point, burke
146	SPG	18	PSR	8	PSR	8	WNL-SPG	AM	Post MW Work, Milepost, WNL, SPG
151	RNK	65	PTI	50	PTI	25	CLP-CVS	NS	Meet po66, Milepost, 80.4, 80.4
155	NFK	119	WTR	128	WTR	90	X3V-NFK	NS	Heat order Milepost, 77.0, 8.5

Amtrak Endpoint OTP Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
156	NYP	422	WTR	195	ITI	107	RNK-RNK	NS	Service, turn, or wye train 147
158	NYP	181	DSR	122	DSR	115	NFK-X3V	NS	Per bulletin Milepost, 3.5, 8.57, 25, Main 1 & 2, Milepost, 8.85, 22.2, 25, Main 1 & 2, Milepost, 22.2, 77.7, 25, Main 1 & 2, Milepost, 0.01, 8.7, 25, Main 1 & 2
160	BOS	19	DSR	25	MBO	12	NRO-STM	MN	For maritime traffic Control Point, cos cob
161	WAS	41	PTI	23	PTI	7	MET-TRE	AM	Follow, AM2219, Other, NO.3 TRACK
162	BOS	44	DSR	25	DSR	11	STM-BRP	MN	Per dispatcher (radio/phone) Waited for AMTK 99 and 2259 to cross, Control Point, 255, 0, 4
165	WAS	121	ENG	41	ENG	41	XSH-NYP	AM	Set out defective locomotive, 637 EX ES, MAP 100 EXPIRING PAPERWORK
409	NHV	19	CTI	7	CTI	7	WNL-WND	AM	Meet, CTRAIL, 6454, Milepost w/Letters, WNL, WND, AM409 held for CT6454 to clear
460	SPG	34	CON	32	CON	32	NHV-NHV	AM	Hold for connecting train
79	RGH	32	WTR	36	WTR	12	FBG-RVR	CS	Heat order Other, RF&P
80	NYP	Trn Cancelled							
615	HAR	Trn Cancelled							
663	HAR	Trn Cancelled	DBS	78	DBS	78	NYP-NYP	AM	Debris blocking track (no debris strike), Other, NYP-NYP, HELD IN SSYD A/C TREES DOWN ON PH LINE
664	NYP	55	WTR	55	WTR	55	PHL-PHL	AM	Trees down, Control Point, ., Originated out of PHL a/c trees down PH line.
665	HAR	83	WTR	80	WTR	63	DOW-PAR	AM	Trees down, Control Point, SECTION B, HELD AT THORN UNTIL 42 GOT THROUGH. HEAVY DELAYS AND PSGR CONFUSION A/C MULTIPLE TREES DOWN THROUGHOUT SECTION B
667	HAR	Trn Cancelled	PTI	17	PTI	9	NYP-NWK	AM	Follow, AM97, Other, NYP NWK
670	NYP	Trn Cancelled							
19	NOL	No OS Rpt	SYS	172	SYS	141	CLP-CLP	NS	Re-crew / job briefing
20	NYP	482	WTR	171	WTR	91	DAN-LYH	NS	Heat order Milepost, 241.0, 172.5
691	BRK	16	PTI	12	PTI	10	POR-FRE	CS	Meet 694, Control Point, Congress

Amtrak Endpoint OTP Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
696	BON	15	HLD	10	HLD	3	WEM-WEM	CS	High passenger count High pax count but also loading paxs with care due to strange consist	
63	TWO	46	ENG	58	ENG	15	NYP-XSD	AM	PTC- IETMS hard cutout, 108 DX BD, OPERATED WITH ACSES CUT OUT	
69	MTR	28	WTR	50	WTR	50	XLQ-SLQ	CN	Heat order Milepost, 2, 42	
290	NYP	26	CTI	29	CTI	20	POU-CRT	MN	Follow metro north, 8844, Milepost, 73, 39	
1233	PIT	67	SVS	62	SVS	62	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, ADDED CAR TO AM232	
1246	NYP	50	OTH	61	OTH	61	PIT-PIT	CS	Late Arrival from 1233... then normal load and brake test	
42	NYP	158	WTR	144	WTR	87	LNC-EXT	AM	Trees down, Control Point, SECTION B, HEAVY DELAYS AND PSGR CONFUSION A/C MULTIPLE TREES DOWN THROUGHOUT SECTION B. RESTRICTED SPEED	
43	PGH	107	WTR	58	CON	34	HAR-HAR	NS	Waiting for passengers making independent transport from LNC due to station closure	
78	RGH	165	TEN	94	DBS	40	GRO-BNC	NS	Debris strike Struck big tree at 11.7NC and stopped at 12.1NC. Damaged ditch lights and disconnected main res. , Milepost w/Letters, 11.7NC, 12.1NC	
90	NYP		MTI	63	MTI	63	XHM-TRE	AM	Disabled train ahead, Other, XHM-TRE, HELD ON NO.3 TRACK TO PICK-UP PSGRS FROM DISABLED AM2226 ON NO.2 TRACK AT GRUNDY.	
98	NYP	66	ENG	60	ENG	60	MIA-MIA	FL	Flat Switch Engines Flat switch Engines at Miami Station Platform, 307 now in lead with 314 trail, 314, 307	
40	CHI	No OS Rpt	SYS	805	SYS	752	WAS-WAS	AM	Crew rest PGH engineer and DC conductor requiring test to complete trip. No other manpower available, Other, was	
41	MIA	No OS Rpt	ITI	695	ITI	695	CHI-CHI	AM	Service, turn, or wye train 40	
23	NOL	22	FTI	39	FTI	33	BAS-XNO	CS	Meet b101, Control Point, 795	
26	MOE	55	FTI	52	FTI	52	PAG-MOE	CS	Follow m6205, Control Point, st elmo	
6	CHI	33	FTI	60	POL	33	XDC-XBB	UP	Medical emergency, passenger removed toGrand Valley EMT. MP. 342.0	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
720	SAC	285	TRS	294	TRS	294	DAV-SAC	UP	Trespasser strike Fatality pedestrian trespasser strike. Strike location MP 83.2, head-end came to a stop at MP 83.9. Amtrak SAC RFE Barton and OAK RFE Crawford attended the scene along with Amtrak Police, Yolo County Sheriffs, Yolo County Coroner, and Davis Fire Dept., Milepost, 83.2, 83.9
724	SAC	153	POL	160	POL	96	DAV-DAV	UP	Trespasser Strike
728	SAC	86	POL	74	POL	74	DAV-SAC	UP	RR blocked by trespasser or vehicle strike by another train
732	SAC	35	POL	45	POL	45	DAV-SAC	UP	RR blocked by trespasser or vehicle strike by another train
733	SJC	265	TRS	203	TRS	203	SAC-DAV	UP	Trespasser strike Returned to Sac after initial departure due to 720 trespasser strike., Milepost, 83.1, 83.0
734	SAC	18	PTI	29	PTI	18	DAV-SAC	UP	Meet 745, Control Point, RV 081
736	SAC	Trn Cancelled							
737	OKJ	Trn Cancelled							
738	SAC	128	POL	129	POL	129	SJC-SJC	UP	RR blocked by trespasser or vehicle strike by another train
741	SJC	126	POL	120	POL	120	SAC-SAC	UP	RR blocked by trespasser or vehicle strike by another train
743	OKJ	67	ITI	66	ITI	66	SAC-SAC	UP	Service, turn, or wye train 724, trespasser strike at Mp83.11 train 720
744	ARN	65	ITI	47	ITI	47	SJC-SJC	UP	Service, turn, or wye train 733
746	SAC	50	ITI	45	ITI	45	SJC-SJC	UP	Service, turn, or wye train 741
747	SJC	16	DCS	7	DCS	5	GAC-SCC	UP	Restrictive signal(s) from unknown cause Red, Other, Coast
50	NYP	210	DBS	170	DBS	160	PRC-HIN	CS	Debris strike Tree strikes- caught under cow catcher on engine, Tree, Milepost w/Letters, ca 357.5, ca 357.4
821	FTW	22	FTI	21	DSR	15	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5, 385.3, 30, m, Milepost, 383.6, 383.4, 60, m, Milepost, 380, 379.5, 60, m, Milepost, 378.

Amtrak Endpoint OTP Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	12	DSR	32	DSR	22	FTW-GLE	BN	Per bulletin Milepost, 350.3, 350.4, 30, crossover, Milepost, 354, 354.5, 70, m1, Milepost, 355.5, 355.7, 70, m1, Milepost, 360.6, 361.1, 30, m1, Milepost, 364.7, 365.1, 60, m1, Milepost, 370.6, 370.7, 30, m, Milepost, 374, 374.1, 60, m, Milepost, 377.5, 378.3, 75, m, Milepost, 379.5, 380, 60, m, Mi
350	PNT	16	DCS	14	DCS	14	ALI-JXN	MI	Issue with automatic road crossing protection Protect 89.10 north concord Protect 78.80 wildwood road, Milepost, 89.10, 78.80
352	PNT	28	PTI	42	PTI	42	ALI-JXN	MI	Meet 355, Control Point, 75
354	PNT	56	WTR	72	WTR	30	XTF-XH6	NS	High winds Stopped., Control Point, 518
355	CHI	81	OTH	62	OTH	38	JXN-ALI	MI	No mode light PTC blacked out mile post 78
364	PTH	44	FTI	52	FTI	38	BTL-LNS	CC	Follow cn 3283, Milepost, 180, 216
579	LAX	25	PTI	17	CTI	11	SOL-OSD	SN	Meet Coaster, 680, Control Point, Swami
584	SAN	39	PTI	42	PTI	25	SNC-SNP	SC	Meet A587, Control Point, serra
761	GTA	34	PTI	49	PTI	49	MPK-XMR	UP	Meet 770, Control Point, Los Posas
770	SAN	39	DCS	57	DCS	55	CML-XMR	UP	Signal dropped at 414, which put train into emergency. Walked train, recovered air, completed class 2 brake test. Dispatcher told us Restricted speed from CO415 - CO423 Control Point, S Camarillo, Control Point, Los Posas
774	SAN	43	SVS	48	SVS	48	LAX-LAX	SC	Added protect locomotive 2111 at LAUS. Control Point, Terminal
703	SAC	19	CON	16	CON	16	BFD-BFD	BN	Hold for thruway bus
710	BFD	57	PTI	38	TEN	23	SKN-SKN	BN	Loading problem Couldn't get load, 2014
713	OKJ	45	TEN	23	TEN	23	RIC-EMY	UP	Other electrical failure LOSS OF RES. HEP SHUT DOWN. ABLE TO RECOVER., C2102
718	BFD	97	SVS	52	SVS	52	OKJ-OKJ	UP	Swap equipment with 715
4	CHI	35	DSR	92	PTI	44	LMY-LSV	BN	Meet AMTK 3, Siding, Fox
300	CHI	80	TRS	77	TRS	77	ALN-ALN	UP	Vehicle on track ahead Milepost, 244, 240
301	STL	22	PTI	20	DTR	13	XWR-STL	TR	MW Project XWR, STL
318	CHI		PTI	18	PTI	11	PON-DWT	UP	Meet Amtk305, Siding, O'Dell
319	KCY	Trn Cancelled	OTH	10	FTI	5	XTF-SMT	CC	Cross Traffic unknown, Control Point, Lemoyne

Amtrak Initial Terminal Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/5/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	24	07/05	22	22	Bolts holding the dog bone part of the wheel loose enough to turn with hand had to have mechanical and diesel shop come down to repair. Bolt was loose they tightened it and checked for other issues related to defect, 369
BON	695	07/05	3	3	Restrictive signal(s) from unknown cause Stop, Bridge, Draw One
CLT	78	07/05	14	14	PTC - Initializing PTC (no failure) PTC route showing KAN to RGH instead of CLT to RGH. CNOC troubleshooting., Other, Charlotte NC station
CLT	80	07/05	(Trn Cxld)		Freight Derailment
HAR	664	07/05	(Trn Cxld)		Signal Outage
HAR	666	07/05	(Trn Cxld)		Signal Outage
HAR	670	07/05	(Trn Cxld)		Signal Outage
NYP	19	07/05	24	26	Service, turn, or wye train, 20, late due to late servicing, by catering. Account, AM20 getting to the yard over five hours late. Also, sleeper 62047 was shopped out of line and replaced with the 62044.
NYP	89	07/05	2	2	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	97	07/05	44	44	Service, turn, or wye train, 98
NYP	155	07/05	11	11	Service, turn, or wye train, 158, LATE F/SSYD A/C LATE TURN OFF AM158
NYP	241	07/05	2	2	Other electrical failure, 708 DX DM, LATE RELEASE FROM SSYD A/C HOT ENGINE
NYP	663	07/05	78	78	Debris blocking track (no debris strike), Other, NYP-NYP, HELD IN SSYD A/C TREES DOWN ON PH LINE
NYP	1233	07/05	62	62	Planned set out / pick out of locomotives, cars or section of train, ADDED CAR TO AM232
NYP	2227	07/05	(No OS)		
PHL	150	07/05	4	4	Planned set out / pick out of locomotives, cars or section of train, RELEASED LATE OUT OF THE YARD
PHL	151	07/05	19	19	Planned set out / pick out of locomotives, cars or section of train, late out the yd a/c equipment
PHL	615	07/05	(Trn Cxld)		Signal Outage
PIT	1246	07/05	61	61	Late Arrival from 1233... then normal load and brake test
RNK	66	07/05	47	47	Crew rest Signed up off rest at 4:50 p.m.
RNK	156	07/05	107	107	Service, turn, or wye train 147
RVR	164	07/05	6		
WAS	100	07/05	59	59	Delay in Block, ENGR NOT QUALIFIED ON CAB CAR 9638, NEC'Y TO CAP OFF WITH MTR 600
WAS	154	07/05	3	3	Delay in Block, CNDR STILL CLOSING DOORS AT DEPARTURE TIME

Amtrak Initial Terminal Details

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/5/2026

Terminal	Train	Date	Late	Delay	Cause
STL	318	07/05	32		
ARN	729	07/05	2	2	Unable to contact dispatcher / MW foreman Waiting for dispatcher to get signal at Auburn depot, Control Point, rv124
BFD	703	07/05	16	16	Hold for thruway bus
BFD	713	07/05	16	16	Vandalism ENGINE SHUT DOWN FROM THE OUTSIDE. 715 ALSO SHUT DOWN. UNKNOWN WHO OR HOW, Other, BFD STA
BFD	719	07/05	21	7	Door C9001, C9002, C9018, C9027, C9803, C9808, Could not get TLC door light
BFD	719	07/05	21	14	Hold for thruway bus
EMY	6	07/05	7		
GTA	782	07/05	13	13	Meet 14, Control Point, CO 358
OKJ	712	07/05	2	2	Inability to contact dispatcher Could not contact dispatcher 2 mins before departure.sat waiting for the signal to leave, Control Point, n jacklondon
OKJ	712	07/05	2	0	Waiting on signal from dispatcher. Called dispatcher on radio and on phone. Received the signal late departing Oakland
OKJ	714	07/05	22	22	Loading problem Loading issue resolved by shutting down and "hard reboot" Departed yard at 12:19, C2103
OKJ	718	07/05	(Trn Cxld)		Third Party Cab Car Failure
OKJ	736	07/05	(Trn Cxld)		Right of Way Encroachment
OKJ	742	07/05	10	10	Service, turn, or wye train 542
SAC	737	07/05	(Trn Cxld)		Right of Way Encroachment
SAC	741	07/05	120	120	RR blocked by trespasser or vehicle strike by another train
SAC	743	07/05	66	66	Service, turn, or wye train 724, trespasser strike at Mp83.11 train 720
SAN	581	07/05	2	2	Service, turn, or wye train 770, Late arrival of AMTK 770 causing late turn for AMTK 581
SAN	785	07/05	11	11	PTC was unable to initialized at SAN due wrong consist given. Wrong consist given was 32 axle for AMTK 774. Ordered to take AMTK 572 with an axle count of 28. CNOC was unable to rectify the situation until 1611. Left immediately at 1612 6900
SEA	11	07/05	3	3	Mobility Impaired Ada passengers
SEA	516	07/05	2	2	HEP 7310, Refrigerator trip the breaker, cafe had no power wait for mechanical to repaired. Arrived station 0816
SJC	738	07/05	129	129	RR blocked by trespasser or vehicle strike by another train
SJC	744	07/05	47	47	Service, turn, or wye train 733
SJC	746	07/05	45	45	Service, turn, or wye train 741

Eastern Region

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	98.2	94.8	166	0
CDOT	95.0	93.8	95.5	92.4	16	1
MARC	95.0	75.0	70.3	90.2	12	3
SEPTA	95.0	97.9	92.5	91.5	97	2
NJT-NED	95.0	95.4	86.1	88.6	153	7
NJT-SED	95.0	87.5	92.5	97.2	24	3

Operating Highlights

Train 78(05) - East of Greensboro, NC - Weather

06JUL26: Train 78(05) was delayed on the Norfolk Southern Danville Subdivision at MP 12.0 after striking a large tree. Train 78(05) lost both ditch lights and HEP as a result of the impact. The train also lost Main Res. The crew was able to rectify the main res issues and conduct a successful brake test. The ditch lights were beyond repair - which restricted the train to 20MPH over all grade crossings for the remainder of the trip.

Train	Delay	Comment
78(05)	45"	

Train 166(05) - New York Penn Station, NY - System

05JUL26: Train 166(05) was delayed at New York Penn Station due to holding for a recrew. The delay was extended to to a disabled NJ MMC equipment move on Line 1 towards the Hellgate.

Train	Delay	Comment
166(05)	2'31"	

Train 2226(05) - Levittown, PA - Catenary or Wayside Failure

05JUL26: Acela train 2226(05) struck an object in the catenary near MP 64 on the NYP Line. The impact damaged the the rear pantograph. The train lost HEP. The decision was immediately made to terminate Train 2226(05) where it stood and transfer all passengers to Train 156(05) and Train 90(05).

Amtrak dispatched ET personnel and field management to the scene.

Service recover was initiated on Trains 156(05), 90(05) and 100(05).

The 2226(05) equipment was later deadheaded to NYP.

Train	Delay	Comment
2226(05)	Term MP 65	
158(05)	33"	
156(05)	1'22"	
100(05)	1'42"	
90(05)	1'28"	

Train 165(05) - New York Penn Station, NY - Servicing

05JUL26: Train 165(05) was delayed departing New York Penn Station due to an unscheduled engine swap. E/637 was swapped out for E/661 due to the former's paperwork being set to expire at midnight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
165(05)	41"	

Train 2258(05) - East of New Haven, CT - Police Related

05JUL26: Train 2258(05) was delayed on the Amtrak New Haven to Boston Line at MP 138.4 due to Stonington Police requesting a hold on all tracks due to a trespasser having a medical emergency.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2258(05)	32"	

Delayed Southbound Departures - Washington, DC

05JUL26: Multiple southbound departures out of Washington Union Terminal were substantially delayed due to a high shop count within the diesel motor inventory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
99(05)	2'27"	
87(05)	1'43"	
19(05)	5'05"	
97(05)	9'23"	

Train 97(05) New York, NY - Servicing

05JUL26: Train 97(05) was delayed departing New York due to turning off inbound 98(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(05)	44"	

Train 66(05) Roanoke, VA - Crew Rest /Servicing

05JUL26: Train 66(05) was delayed departing Roanoke due to crew signing up on rest at 450P-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66(05)	47"	

Train 41(04) Washington, DC - Car Failure

05JUL26: Train 41(04) was delayed departing Washington due to removing C/38047 that was dead heading on the rear of the train.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(04)	32"	

NS Heat Orders/Weather

05JUL26: Train 20(04) 2610-00580 0000008156, E48341, Train 8 cancelled with 175 customers onboard was delayed due to heat orders from MP 241.0 to MP 172.5 at 25MPH.

Train 156(05) was delayed due to heat orders on the NS Piedmont MP 162.2 to MP 112.2

Train	Delay	Comment
156 (05)	3'15"	
20 (04)	2'49"	
155 (05)	1'30"	
128 (05)	1'34"	
66 (05)	25"	
51 (05)	1'56"	

Train 68(05) Rouses Point, NY - Heat Orders/ Weather

05JUL26: Train 68(05) was delayed on the CN Rouses Points subdivision at MP 0.0/Rouse Point due to heat orders.

Train	Delay	Comment
68 (05)	43"	

Train 460(05) New Haven, CT - Hold for Connection

05JUL26: Train 460(05) was delayed departing New Haven due to holding for connections off the late 160(05).

Cause: Pending

Train	Delay	Comment
460 (05)	32"	

CSX Heat Orders - Weather

05JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Baltimore Terminal, Capital, Cumberland, Kanawha, Metropolitan, North End, Old Main Line, Peninsula, RF&P, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40 (05)	47"	
89 (05)	42"	
98 (05)	41"	
155 (05)	38"	
158 (05)	23"	
79 (05)	36"	
53 (05)	20"	
145 (05)	02"	
124 (05)	29"	
40 (04)	44"	
52 (05)	03"	
41 (04)	32"	
97 (04)	31"	
50 (04)	24"	

Train 1233(05) New York, NY - Adding a Coach/Servicing

05JUL26: Train 1233(05) was delayed departing New York due to adding C/82808 to the consist of 232(05). They were further delayed due to police hold on the empire division.

Train 50(04) East of Prince, WV - Struck a Tree/Debris

05JUL26: Train 50(04) with E/130, E/88 and 5 cars with 718 customers onboard was delayed on the CSX New River at MP CA374.8 due to striking a large tree. They did lose HEP for a couple minutes while crew reconfigured the engines. Amtrak Road Foreman was enroute to assist. CSX maintainers arrived around 1158A-ET and estimated 30" to reach the train and start removing the tree. The train was located in a spot with no cell service and communication was limited with the crew. The crew reported minimal damage to the frontend engineers side damage nothing impeding operation all lights were functional.

UPDATE: E/130 Firemans side ladder is bent but not condemnable and E/88 has an air leak but is holding. C/25117 has no freon/HVAC looking for CSX Mechanical to look at car at Clifton Forge.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(04)	2'50"	

Train 40(03) Washington, DC - Miscellaneous Amtrak Responsible

05JUL26: Train 40(03) with E/372, E/356 was delayed in Washington due to holding for engineer to sign up at 730A-ET and conductor to sign up at 835A-ET. They were further delayed due to having paperwork issues with CSX. Service recovery was enacted with Coach customers receiving snack packs, bottled water, beef stew over rice for lunch, and pizza delivered to Pittsburgh. First Class customers were served their normal lunch and dinner service from the dining car.

As a result of the late operation, Train 41(05) was cancelled entirely with no alternate provided.

WBS#: B.TR.100150.6858

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(03)	12'32"	
41(05)	Cancelled Entirely	

Train 156(05) Roanoke, VA - Car Failure

05JUL26: Train 156(05) with E/381 and 8 cars with 112 customers onboard was delayed departing Roanoke due to having mechanical issues with a C/81522 and then further delayed holding for crew to sign up on rest.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
156(05)	1'47"	

Train 20(04) North of Spartanburg, SC - Freight Trespasser Strike/Police Related

05JUL26: Train 20(04) with E/182, E/310, E/324 with 8 cars with 115 customers was delayed on the NS Charlotte District at MP 413.8 due to an NS Freight that struck a trespasser.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(04)	2'27"	
19(04)	21"	

Charlotte, NC - NS Freight Train Derailment

05JUL26: NS reported that NS freight train 1203 derailed at the Charlotte, NC station on the NS Charolette District. NS reported five cars derailed and were blocking both main tracks. NS personnel were on scene. There was an open route thru the yard and trains 20(04) and 19(04) were able to operate with NS Pilots. Both trains also had to shove

Train 80(05) is cancelled in its entirety due to no clear route. Train 79(05) was terminated in Raleigh.

Train 71(05) was terminated at Kannapolis and was attempting to source buses from Kannapolis to Charlotte. Train 71(05) equipment deadhead from Kannapolis to Charlotte and was routed thru the yard with NS Pilots for train 78(05).

Service recovery was enacted for Train 19(04) consisting of snack packs, bottled water, coffee, and tea for all coach customers. Lunch was extended for first class customers. Dominos Pizza was ordered in Atlanta to be distributed.

UPDATE: Train 80(06) will operate normal and train 79(06) will originate Raliegh to Charlotte. As of 450P-ET main 2 was open and NS estimates main 1 to be open around 630P-ET.

WBS#: B.TR.100150.6856

Train	Delay	Comment
20(04)	1'19"	
80(05)	CANCELLED	
79(05)	TERM RGH	
71(05)	TERM KAN	BUS KAN -CLT
19(04)	47"	
80(06)		OPERATING NORMAL
79(06)		ORIG RGH-CLT

Keystone Line Trees Down and Signal Power Loss

05JUL26: Severe weather on the 7/26/2026 Keystone Line caused signal power loss between State and Holland Interlockings. The power was then lost between Downs and Park. Multiple trees were reported down across the area. Train 674(04) with 28 passengers was stopped at Rheems interlocking with no headend power. The train was able to eventually recover power and was able to operate under its own power to Lancaster station. The train was met by one bus to transport the customers to their destinations. The train was tied down in Lancaster due to no clear route to Harrisburg or Philadelphia.

Train 669(04) with 185 customers onboard was stopped at Parksburg station without headend power. Two rescue diesels were dispatched from Philadelphia. The rescue diesels arrived to the train set and towed the train to a live section of track. The train was then able to operate under its own power back to Philadelphia.

Train 671(04) was cancelled from Philadelphia to Harrisburg with no alternate transportation. The equipment from train 671(04) was turned in Philadelphia and operated as train 674(04) from Philadelphia to New York.

Service Adjustments for 7/5/26:

Trains 660(05), 661(05) were cancelled in their entirety. Train 663(05) terminate in Philadelphia, Train 664(05) originate in Philadelphia and 666(05) originate in Philadelphia, 672(05) originate in Philadelphia and Train 667(05) terminated in Philadelphia. Trains 669(05), 671(05), 674(05), 670(05), 615(05) and 612(05) are cancelled in their entirety.

Train 43(05) did not make the Lancaster stop and there were passengers that missed and transported themselves to Harrisburg station to catch the train.

2 Buses were secured and operated Harrisburg to Philadelphia they departed at 440P-ET and 450P-ET. They will turn back at Philadelphia and operate back to Harrisburg for any passengers that may need to board.

Train	Delay	Comment
669(04)	Term PAR	
660(05)	Cancelled	
671(04)	Term PHL	
661(05)	Cancelled	
674(04)	2'35"	
664(05)	55"	ORIG PHL
663(05)	1'18"	TERM PHL
669(05)	CANCELLED	
671(05)	CANCELLED	
674(05)	CANCELLED	
670(05)	CANCELLED	
612(05)	CANCELLED	
615(05)	CANCELLED	
612(05)	CANCELLED	
666(05)		ORIG PHL
667(05)		TERM PHL
43(05)	35"	HAR
672(05)		ORIG PHL
665(05)	1'03"	
42(05)	1'27"	

CSX Freight Train Derailment on the Peninsula Subdivision

03JUL26: CSX reported freight train 124(03) derailed on the Peninsula Subdivision at milepost 83, 8 miles east of Richmond, VA. Three cars had derailed and fallen off of the viaduct into the water. Three cars and one locomotive were leaning. CSX personnel responded to the scene. Train 124(03) with 166 customers onboard was stopped at milepost 80 at 5:00 PM-ET. The train then reversed east to crossing at Charles City Road to transfer customers to buses. The road foreman responded to the train to assist in customer transfer. Buses were secured by station services. Once bus operated from where train 124(03) stood to Richmond Main Street Station and then returned to the train. A total of three buses then transferred the rest of the passengers to Richmond. The buses were then staged at Richmond to take the customers from train 99(03) to their destinations. Train 99(03) was terminated in Richmond and turned for train 124(03). Train 158(03) made train 124(03) stops.

Train 164(04) was originated in Washington, DC. Train 65(03) was terminated in Richmond.

04JUL26: 9:00 am-et CSX reports derailment site will not be cleared for rail traffic to resume until am hours of 7/5. As a result, the following additional adjustments have been made with no alternate transportation due to no bus availability: 124(04) will be cancelled between Newport News and Richmond and will operate Richmond to Philadelphia with train 65(03) equipment. Train 99(04) will terminate Richmond. Train 164(05) is cancelled Newport News and Richmond and will operate Richmond to Boston with the equipment off 99(04). Train 65(04) will terminate Washington.

CSX Reported that the scene was clear as of 10A-ET and they will operate test trains thru the area.

WBS#: B.TR.100151.0828

Train	Delay	Comment
99(03)	Term RVR	
124(03)	6'30"	
164(04)	Orig WAS	
65(03)	Term RVR	
124(04)	ORIG RVR	
99(04)	TERM RVR	
164(05)	ORIG RVR	
65(04)	TERM WAS	

NEC Service Adjustments for 07/03/26 - 07/05/26- Weather

03JUL26: Due to the impending hot weather with ambient temperatures elevated over 90 degrees the following service adjustments were made: Northeast Regional trains 163, 88, 159, 142, 106, and 107(03-04) were cancelled in their entirety. Keystone trains 666 and 667(03-04) were also cancelled in their entirety.

04JUL26: The continued hot weather required further service adjustment to be made. The following trains were cancelled in their entirety with no alternate transportation: 2290, 2293, 2252, 2254, 2267, 2271, 88, 149, 189, 105, 122, and 104(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
163(03)	Cancelled	
159(03)	Cancelled	
88(03)	Cancelled	
142(03)	Cancelled	
106(03)	Cancelled	
107(03)	Cancelled	
666(03)	Cancelled	
667(03)	Cancelled	
163(04)	Cancelled	
159(04)	Cancelled	
88(04)	Cancelled	
142(04)	Cancelled	
106(04)	Cancelled	
107(04)	Cancelled	
666(04)	Cancelled	
667(04)	Cancelled	
2293(05)	Cancelled	
2290(05)	Cancelled	
2252(05)	Cancelled	
2254(05)	Cancelled	
2267(05)	Cancelled	
2271(05)	Cancelled	
88(05)	Cancelled	
149(05)	Cancelled	
189(05)	Cancelled	
105(05)	Cancelled	
122(05)	Cancelled	
104(05)	Cancelled	

Piedmont Service Cancellations - Norfolk Southern Heat Orders - Weather

03JUL26: Heat orders issued by the Norfolk Southern Districts would cause significant delays to the service scheduled through the area. As a result, trains were cancelled with alternate transportation secured. Two buses were secured for train 72(03). One bus operated express stopping and picking up in Charlotte, Greensboro and Raleigh. One bus making all stops. Two buses were secured for train 74(03) and both made all stops. Two buses were secured for train 76(03). One bus made stops in Charlotte, Durham, Cary, and Raleigh. The second bus made stops in Charlotte, Kannapolis, Greensboro, Durham, Cary, and Raleigh. Two buses were secured for train 73(03). One bus made stops in Raleigh, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 75(03). One bus made stops in Raleigh, Cary, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 77(03). One bus made stops in Raleigh, Durham, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Greensboro, Highpoint, Salisbury, and Charlotte. Trains 71(03) and 78(03) were scheduled to make all stops.

04JUL26: The heat orders were continued into 07/04/26. The following trains were cancelled with alternate transportation secured: 72(04), 73(04), 74(04), 75(04), 76(04), and 77(04).

05JUN26: The heat orders were continued into 07/05/26. The following trains were cancelled with alternate transportation secured: 72(05), 73(05), 74(05), 75(05), 76(05), and 77(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(03)	Cancelled	
76(03)	Cancelled	
74(03)	Cancelled	
75(03)	Cancelled	
73(03)	Cancelled	
72(03)	Cancelled	
72(04)	Cancelled	
73(04)	Cancelled	
74(04)	Cancelled	
75(04)	Cancelled	
76(04)	Cancelled	
77(04)	Cancelled	
72(05)	Cancelled	
73(05)	Cancelled	
75(05)	Cancelled	
74(05)	Cancelled	
76(05)	Cancelled	
77(05)	Cancelled	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00580a 00000008158 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Train 7/27(04) East of Libby, MT - Freight Train Interference

06JUL26: Train 7/27(04) with 239 customers was delayed east of Libby, MT, at approximately MP 1286.5 on the BNSF Kootenai River Subdivision, due to a disabled freight train ahead. BNSF freight train H-NTWPAS1-01A experienced a mechanical issue between West Tamarack and East Fisher River, where an open joint was discovered between lines 90 and 91. The disabled train, measuring nearly 10,000 feet in length, blocked the territory while repairs were made. Complicating operations, BNSF grain train G-FRMVAW9-02, nearly 14,000 feet in length, was holding behind the disabled train. Once the freight crew resolved the issue and moved into Riverview Siding, both the grain train and Train 7/27(04) were able to proceed through the area. Train 7/27(04) then followed the grain train westward to Troy (MP 1337.2), where it was able to operate around the freight movement and continue its westbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(04)	1'12"	

Train 354(05) South of Royal Oak, MI - Freight Train Interference

06JUL26: Train 354(05) was delayed on the CN Holly subdivision two miles south of Royal Oak at Motem/MP 11.1 due to meeting CN 2536.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(05)	45"	

Train 21/421(05) South of Arcadia, MO - Signal

06JUL26: Train 21/421(05) was delayed on the UPRR Desoto subdivision due to signal issues between Tip Top/MP 91.4 and Annapolis/MP 108.9.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(05)	35"	

Train 19(04) North of Laurel, MS - Freight Train Interference

05JUL26: Train 19(04) with 99 customers was delayed on the NS NO&NE district 26 miles north of Laurel at Barnett/MP 30.5 due to NS 131-05 in emergency with engine issues and requiring the crew from NS 345-04 to assist them by adding an engine and clearing into Hawkes siding/MP 50.8. NS 345-04 was stopped on the single main between Barnett/MP 30.5 and Hawkes/MP 50.8, blocking the route for 19(04). Once the NS 345-04 crew was vanned back to their train, train traffic continued.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(04)	1'40"	

Train 26(05) West of Mobile, AL - Freight Train Interference

05JUL26: Train 26(05) with 59 customers was delayed on the CSX NO&M subdivision 19 miles west of Mobile due to meeting M620-05 at Saint Elmo/MP 685.6.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(05)	52"	

Train 21/421(05) North of Arcadia, MO - Signal

05JUL26: Train 21/421(05) was delayed on the Union Pacific Des Moines subdivision 37 miles north of Arcadia at Blackwell/MP 51.7 due to the crew utilizing the power box account of switch issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(05)	31"	

Train 794(05) North of Goleta, CA - Passenger Train Interference

05JUL26: Train 794(05), carrying 90 customers onboard, was delayed north of Goleta Station, while holding at Gaviota Siding (MP 336.1) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 777(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
794(05)	32"	

Train 718(05) Emeryville, CA - Late Release from Yard

05JUL26: Train 718(05), operating with CC/C8312, seven cars, and locomotive E/C2102, was delayed departing the Oakland Maintenance Facility while technicians completed servicing and addressed reported door light and air system issues. Due to the late release of the equipment, the train was originated at Emeryville, CA rather than Oakland Jack London Square. Customers traveling from Oakland Jack London Square to Emeryville were accommodated on Train 738(05). Once the equipment arrived at Emeryville Station, 100 customers boarded, and Train 718(05) departed without further incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(05)	39"	

Train 28(05) West of Bingen, WA - Signal

05JUL26: Train 28(05), carrying 124 customers onboard, was delayed west of Bingen, WA Station, while holding at Stevenson (MP 55.8) on the BNSF Fallbridge Subdivision due to signal indication issues ahead. The train remained in the siding while BNSF freight train XU-FYNPTL0-05T was authorized to flag through the affected territory. Once the freight train cleared, Train 28(05) was released from the siding and proceeded through the area. Due to the ongoing signal issues, the train was required to operate at restricted speed between Stevenson (MP 55.8) and Cook (MP 64.5).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(05)	1'05"	

Train 4(04) East of Trinidad, CO - Temporary Speed Restrictions

05JUL26: Train 4(04) with 179 customers was delayed on the BNSF Raton subdivision starting 31 miles east of Trinidad between MP 605.0 and MP 581.9 due to temporary speed restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(04)	30"	

Train 354(05) West of Battle Creek, MI - Passenger Train Interference

05JUL26: Train 354(05) was delayed on the Amtrak Michigan Line just west of Battle Creek at Gord/MP 121.4 due to meeting train 355(05).

Train 40(03) West of Pittsburgh, PA - Freight Train Interference

05JUL26: Train 40(03) with 60 customers was delayed on the NS Fort Wayne district starting 34 miles west of Pittsburgh between MP 34.0 and MP 73.0 due to following behind 11N-04, 65K-04, and 25G-05.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(03)	57"	

Train 364(05) East of Battle Creek, MI - Freight Train Interference

05JUL26: Train 364(05) with 230 customers was delayed on the CN Flint subdivision starting five miles east of Battle Creek between MP 180.0 and MP 216.0 due to following CN 3283.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(05)	38"	

Train 7/27(05) West of Wisconsin Dells, WI - Freight Train Interference

05JUL26: Train 7/27(05) was delayed on the CPKC Tomah subdivision at Wisconsin Dells/MP 195.1 due to holding for CPKC 149 with a hot bearing and restricted to 10mph to clear ahead into Mile Creek/MP 210.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(05)	1'04"	WDL
7/27(05)	13"	Follow 149

Train 355(05) West of Jackson, MI - System

05JUL26: Train 355(05) with E/58, five cars, E/4627, six cars, and 233 customers was delayed on the Amtrak Michigan Line two miles west of Jackson due to E/58 with no mode light.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(05)	38"	

Train 352(05) West of Jackson, MI - Passenger Train Interference

05JUL26: Train 352(05) with 273 customers was delayed on the Amtrak Michigan Line just west of Jackson at CP 75/MP 75.7 due to meeting train 355(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(05)	42"	

Train 20(05) East of Birmingham, AL - Freight Train Interference

05JUL26: Train 20(05) with 107 customers was delayed nine miles east of Birmingham on the NS East End district at Norris Jct./MP 790.7 due to meeting 379-05.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(05)	32"	

Train 40(03) West of Pittsburgh, PA - Signal

05JUL26: Train 40(03) was held at the CP Bell district due to power switch failure five miles west of Pittsburgh at CP Bell/MP 4.8. The crew held at Pittsburgh station for a maintainer and were then talked by the signal at CP Bell.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(03)	57"	

Train 786(05) North of Lompoc-Surf, CA - Passenger Train Interference

05JUL26: Train 786(05), carrying 132 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(05) and 14(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(05)	43"	

Train 21(04) Fort Worth, TX - Servicing

05JUL26: Train 21(04) was delayed at Fort Worth, Texas (MP 346.2), on the BNSF Fort Worth Subdivision, while awaiting completion of locomotive fueling.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(04)	37"	

Train 3(05) West of Naperville, IL - Freight Train Interference

05JUL26: Train 3(05) was delayed holding 12.5 miles west of Naperville, IL (MP28.5), on the BNSF Mendota Subdivision, at MP41 waiting on eastbound CSXT 7580 and Train 4(03) to clear. At the time, all train movements were operating via single-track operations on Main Track 1 between Bristol (MP 45.8) and Earlville (MP 72.5) because three trains were tied down on Main Track 2. Once the meeting was complete, Train 3(05) had to follow westbound BNSF 8115 until they were able to get around at Earlville. Train 5(05), which was operating behind Train 3(05), also experienced delay while following Train 3(05) through the affected territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(03)	35"	Follow CSX 5780
5(05)	43"	Trail 3(05)
3(05)	Est. 1'15"	

Train 774(05) Los Angeles, CA - Servicing

05JUL26: Train 774(05), with 424 customers, was delayed departing the Los Angeles, CA Union Station, account of a program move to add Locomotive C2114.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
774(05)	47"	

Train 5(04) Fraser-Winter Park, CO - Police Related

05JUL26: Train 5(04) was delayed at Fraser-Winter Park, CO (MP62.3) on the UPRR Moffat Tunnel Subdivision due to customer issues. One customer experienced a medical emergency, was evaluated by EMS, and was released to continue. A second customer was removed by police for disorderly conduct. After both situations were resolved, the train was cleared to proceed.

Train 23(05) South of Bay Saint Louis, MS - Freight Train Interference

05JUL26: Train 23(05) 28-FB-00580 .50000008156 south of "UNCLASSIFIED" Saint Louis, MO (MP754.5), on the CSX NO&M Subdivision, at MP795 in order to meet CSX B101.

Train	Delay	Comment
23(05)	33"	

Train 720(05) West of Sacramento, CA - Trespasser Incident

05JUL26: 9:42A-PDT, Train 720(05), with 83 customers, operating with Cab Car C8314, 4 cars and Locomotive C2003, stopped at MP 83.84 on the Union Pacific Martinez Subdivision, 5 miles west of the Sacramento, CA Valley Station, in Yolo county, after striking a trespasser laying on the tracks. The incident did not occur at a crossing. The weather was reported as 70°F and sunny. There were no injuries to the crew and 83 customers onboard. There was no damage reported to the equipment. Local authorities responded to perform their investigation. The location was not easily accessible causing extended delay.

Train 733(05) initially departed Sacramento, CA but made a reverse move back to the station.

Train 6(05) held at the Davis, CA station.

Multiple downline delays incurred from late turns.

As a result of the ongoing track closure the following trains were canceled in their entirety:

736(05) with 57 customers

737(05) with 130 customers.

Customers were advised to rebook to the next available train.

1:18P-PDT, The adjacent main track was release for rail traffic but the I-Bridge located just west of the Sacramento station was stuck open after opening for marine traffic.

National Response Center Number: 1467033

Train	Delay	Comment
737(05)		Canceled
736(05)		Canceled
720(05)	4'54"	
6(05)	4'46"	DAV
724(05)	2'40"	DAV
728(05)	1'14"	DAV
733(05)	3'23"	SAC
733(05)	50"	RV989
732(05)	45"	SAC
743(05)	1'06"	SAC - Turn Off Late Inbound 724(05)
5(03)	46"	Wait for SAC track
744(05)	47"	SJC - Turn Off Late Inbound 733(05)
741(05)	2'00"	SAC
738(05)	2'09"	Wait for crew at SJC
746(05)	45"	SJC - Turn Off Late Inbound 741(05)

Train 770(05) East of Camarillo, CA - Signal

05JUL26: Train 770(05) stopped in emergency account of the signal dropped in front of the train at Camarillo / MP 414.7 on the Union Pacific Santa Barbara Subdivision, 1 mile east of the Camarillo, CA station. After inspecting the equipment, the crew operated at restricted speed to the next signal of Las Posas / MP 523.1.

Train	Delay	Comment
770(05)	55"	
761(05)	49"	Las Posas - Met 770(05)

Train 11(04) East of Davis, CA - Police Related

05JUL26: Train 11(04) with 176 customers was delayed at MP 76.0 on the Union Pacific Martinez Subdivision, 0.5 miles east of the Davis, CA station, account of a reported fire near the tracks at MP 75.41.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(04)	30"	

Train 300(05) Alton, IL - Vehicle on Tracks

05JUL26: Train 300(05), carrying 82 customers, was held at the Alton, IL station (MP255.1) on the UPRR Springfield Subdivision due to a reported vehicle stuck on the tracks ahead at MP244.78. Local authorities responded and removed the vehicle from the tracks. Following the removal, the route was inspected and determined to be safe for train operations. Train 300(05) was subsequently released and continued northbound.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
300(05)	1'11"	

Train 21(04) South of Arcadia, MO - Signal

05JUL26: Train 21(04) was delayed starting 3.5 miles south of Arcadia, MO (MP88.8), on the UPRR Desoto Subdivision, due to signal issues at Tip Top (MP92.3). Operating speeds were restricted until a clear signal was reached at Annapolis (MP108.9).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(04)	1'00"	

Train 353(05) Pontiac, MI -Cancelled

05JUL26: Train 353(05), E/ID4601-5 Cars, was cancelled in its entirety at Pontiac, MI (MP25.9) on the CNRR Holly Subdivision due to an inoperable radio in engine ID4601. A total of 278 customers were affected by the service disruption. Six buses were secured to accommodate passengers and continue transportation to Chicago:

- Bus #1: Operated express from Detroit to Chicago.
- Bus #2: Served Ann Arbor, Battle Creek, and Chicago.
- Bus #3: Served Troy, Jackson, Niles, and Chicago.
- Bus #4: Made all scheduled station stops.
- Bus #5: Operated express from Kalamazoo to Chicago.
- Bus #6: Operated express from New Buffalo to Chicago.

All affected customers were accommodated via the bus bridge established following the train cancellation.

WBS#: B.TR.100150.6854

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
353(05)	Cancelled	

Train 6(04) East of Elko, NV - Freight Train Interference

05JUL26: Train 6(04), with 114 customers, was delayed between Elko, NV / MP 557.0 and Alazon / MP 603.7 on the Union Pacific Lakeside Subdivision, operating around GSPXBU-02 (UPRR 6923).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	42"	

Train 3(03) West of Flagstaff, AZ - Freight Train Interference

05JUL26: Train 3(03), 26-FBI-00580 3700000008158, UNCLASSIFIED 7/7/2026, delayed between East Bellemont / MP 354.5 and West Seligman / MP 429.7 on the Burlington Northern Santa Fe Seligman Subdivision, starting 10 miles west of the Flagstaff, AZ station, following an unknown freight train.

Train	Delay	Comment
3(03)	55"	

UPRR Jefferson City Subdivision - Severe Weather

04JUL26: Due to extreme weather event on the UPRR Jefferson City subdivision, between Jefferson City, MO and Hermann, MO. UPRR dispatched Maintenance of Way personnel to remove downed trees from several locations. UPRR personnel reported downed wires in several locations as well. While enroute to the original reported locations of the downed trees, MOW kept finding other trees on the tracks that needed to be removed. Train 316(04) held at Jefferson City, MO for an open route and train 319(04) was initially held East of Hermann, MO and then West of Hermann, MO. Due to the extended delay buses were secured to accommodate customers. Buses arrived at a crossing 1 mile east of Jefferson City for train 316(04) at approximately 2:50am-ct and all customers were safely transferred to buses. Amtrak Road Foreman arrived on location of 319(04) at approximately 3:50am-ct as well as the buses. At 3:45am-ct, UPRR reported that there was an 11 mile stretch with 40 trees across the tracks that required heavy equipment to remove. As a result the following service adjustments have been made:

- Train 316(04) was terminated at Jefferson City, MO with alternate buses provided.
- Train 319(04) was terminated at Hermann, MO with alternate buses provided.

05JUL26: At 10:00AM-CT, Main Track 1 was returned to service for 316(04) and 319(04)'s equipment to deadhead to their destination. At 12:30PM-CT, Main Track 2 was returned to service. Due to heavy freight interference from tied down equipment and lack of staffing, additional service adjustments were set in place:

- Train 311(05) was cancelled entirely with no alternate buses provided.
- Train 316(05) was cancelled entirely with three alternate buses provided.
- Train 318(05) originated at St. Louis, MO with no alternate buses provided. Inbound Train 319(05)'s equipment was turned at St. Louis to represent Train 318(05) which resulted in a departure delay.
- Train 319(05) terminated at St. Louis, MO with 8 buses secured between St. Louis and Kansas City.

06JUL26: UPRR advised that signal power issues and freight train interference continued on the Jefferson City subdivision between Jefferson City and Washington with one train tied down and flagging between MP 73.0 and MP 124.0. As a result, the following service adjustments were implemented:

- Train 311(06) was cancelled entirely with three alternate buses.
- Train 316(06) was cancelled entirely. Customer service was working to source alternate transportation.
- Train 319(06) terminated at St. Louis. Customer service was working to source alternate transportation.
- Train 318(06) originated at St. Louis off train 319(06) equipment. Customer service was working to source alternate transportation.

It was necessary for Chicago to add an additional locomotive to send to St. Louis to fill out service for the Missouri River Runner service on July 7 due to E/ID4609 shopped for multiple faults and deadhead in trail back to Chicago on train 302(06).

WBS#: B.TR.100150.6855

Train	Delay	Comment
319(04)	Term JEF	
316(04)	Term JEF	
311(05)	Cancelled	
316(05)	CANCELLED	
319(05)	TERM STI	

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated JAN	
59(27JUN-06JUL, 09JUL)	Cancelled	
58(27JUN-06JUL, 08JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on MP 588.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL)	00"	BYPASS PSN
1 (01, 04JUL) / 421 (03JUL)	00"	BYPASS PSN

Maintenance of Way Highlights

BNSF Track Work West of Macomb, IL - Carl Sandburg Service

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th. To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL) and Train 382(13JUL-17JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL) and Train 381(13JUL-17JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has announced a replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
59 (26)	JAN	62		Gouged Wheels

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
7 (3)	SPK	BN6714	E/170 TM #3 C/O	SEA	7/5/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00580

00000008156

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
566 (05)	LAX	90215- no bike space and no seating in this car. Notify passengers.	NONE	0	90215
584 (05)	LAX	90215- no bike space and no seating in this car. Notify passengers.	NONE	0	90215
564 (06)	LAX	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	0	9700
566 (06)	LAX	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	0	90215
584 (06)	LAX	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	1	90215
128 (05)	NFK	128(05) operating with a Business Class car in lieu of a coach.	NONE	0	81530
164 (05)	RVR	164(05) operating with 7 coaches vs 8 per plan. Train is overcapacity PHL-PVD.	YES	4	
579 (05)	SAN	90215- no bike space and no seating in this car. Oversold in coach. Re-accommodate passengers to avoid oversold conditions.	NONE	0	90215
595 (05)	SAN	90215- no bike space and no seating in this car. Notify passengers.	NONE	0	90215
777 (06)	SAN	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	3	9700
579 (06)	SAN	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	0	90215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
595 (06)	SAN	NO BIKE SPACE OR WIFI	email for passenger notifications sent no bike space no wi-fi	0	90215
11 (05)	SEA	Per Conductor HVAC is not functioning in 31019. Re-accommodate passengers as train is now oversold.	YES	45	31019
8 (05)	SEA	No diner this frequency due to 38031 off 7(03) set out at MOT for broken spring.			
154 (05)	WAS	154(05) operating with Business Class car 81511 in lieu of a coach.	none	0	81511

Reverse Consists

Train Number	Station	Reason
103 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
124 (05)	NPN	Consist reversed Business class seat orientation may have changed At Front
150 (05)	PHL	Consist reversed Business class seat orientation may have changed At Front
135 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
161 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
63 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
151 (06)	PHL	Consist reversed Business class seat orientation may have changed At Front
66 (06)	RNK	Consist reversed Business class seat orientation may have changed At Front
145 (05)	NYP	Business class change only Business class seating orientation may have changed At Rear
178 (06)	RNK	Business class change only Business class seating orientation may have changed At Rear
140 (05)	WAS	Business class change only Business class seating orientation may have changed At Rear
141 (06)	SPG	Business class change only Business class seating orientation may have changed At Rear

Train Number	Station	Reason
148 (06)	WAS	Business class change only Business class seating orientation may have changed At Rear