

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, July 07, 2026

Rules: 0-36



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/06/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	76	76.5%	1,758	301	82.9%	83,116	11,425	86.3%
Central Division	86.0%	71	14	80.3%	428	45	89.5%	20,467	1,863	90.9%
East Division	82.0%	176	47	73.3%	893	180	79.8%	43,454	6,788	84.4%
West Division	86.0%	76	15	80.3%	437	76	82.6%	19,195	2,774	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00580 00000008157 "UNCLASSIFIED" 7/7/2026

Endpoint Arrival Dates through 7/6/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	112,041	46,078	59%	613,775	260,835	58%	27,561,099	6,735,121	76%
Northeast Corridor	81%	51,418	25,969	49%	253,589	122,859	52%	12,097,370	2,906,052	76%
Acela	83%	11,272	5,086	55%	53,473	26,192	51%	2,390,238	628,869	74%
Northeast Regional	79%	40,146	20,883	48%	200,116	96,667	52%	9,707,132	2,277,183	77%
Richmond / Newport News / Norfolk	77%	12,656	7,267	43%	61,103	36,550	40%	3,011,831	850,171	72%
Springfield Shuttles	89%	691	122	82%	4,407	1,557	65%	172,441	25,771	85%
Roanoke	79%	2,488	1,367	45%	17,510	10,523	40%	910,570	185,808	80%
On Spine Northeast Regional	80%	24,311	12,127	50%	117,096	48,037	59%	5,612,290	1,215,433	78%
State Supported	80%	46,638	13,576	71%	284,556	90,265	68%	12,070,604	2,452,629	80%
Borealis	80%	551	75	86%	3,447	1,132	67%	154,417	31,578	80%
Capitol Corridor	90%	3,497	587	83%	21,899	4,493	79%	1,023,118	133,689	87%
Carolinian	70%	621	549	12%	6,661	4,769	28%	316,635	120,675	62%
Cascades	75%	3,099	1,083	65%	19,962	6,103	69%	707,606	194,663	72%
Downeaster	82%	1,894	904	52%	10,180	3,831	62%	407,678	49,301	88%
Empire	78%	6,271	2,251	64%	35,572	14,076	60%	1,489,577	328,493	78%
Adirondack	72%	492	135	73%	2,759	1,525	45%	89,192	27,009	70%
Ethan Allen Express	70%	579	29	95%	3,331	1,874	44%	154,296	49,481	68%
Maple Leaf	70%	909	455	50%	5,305	2,347	56%	180,124	69,134	62%
New York - Albany	85%	2,850	1,427	50%	15,194	4,820	68%	692,359	108,720	84%
New York - Niagara Falls	75%	1,441	205	86%	8,008	2,719	66%	369,467	72,498	80%
Berkshire Flyer	60%	0	0	-	975	791	19%	4,139	1,651	60%
Gold Runner	73%	2,929	1,160	60%	17,244	6,493	62%	690,864	238,591	65%
Heartland Flyer	70%	324	161	50%	1,771	915	48%	57,476	21,408	63%
Hiawatha	90%	1,696	0	100%	11,653	856	93%	469,347	51,404	89%
Illinois	78%	2,555	1,259	51%	17,581	7,996	55%	679,736	184,040	73%
Carl Sandburg / Illinois Zephyr	85%	363	6	98%	3,334	1,157	65%	112,888	28,963	74%
Illini / Saluki	85%	1,025	521	49%	6,052	2,545	58%	239,714	56,572	76%
Lincoln Service	70%	1,167	732	37%	8,195	4,294	48%	327,134	98,505	70%
Keystone	92%	8,373	365	96%	35,687	8,782	75%	2,092,764	218,717	90%
Lincoln / Missouri	70%	529	267	50%	4,355	2,258	48%	212,874	106,074	50%
Mardi Gras Service	80%	325	211	35%	2,495	820	67%	113,443	23,281	79%
Michigan	70%	2,415	1,896	21%	14,718	8,601	42%	534,465	173,556	68%
Blue Water	70%	859	733	15%	3,573	2,974	17%	123,799	48,308	61%
Pere Marquette	85%	364	0	100%	1,744	491	72%	69,316	13,821	80%
Wolverine	70%	1,192	1,163	2%	9,401	5,136	45%	341,350	111,427	67%
Missouri	80%	0	0	-	926	83	91%	60,162	13,323	78%
Pacific Surfliner	85%	8,462	1,207	86%	64,782	11,136	83%	2,147,306	338,298	84%
Pennsylvanian	80%	870	0	100%	5,580	2,851	49%	244,290	45,010	82%
Piedmont	80%	1,029	566	45%	2,160	1,270	41%	315,545	79,824	75%
Vermont	75%	1,198	1,035	14%	7,883	3,800	52%	353,301	100,704	71%
Long Distance	70%	13,985	6,533	53%	75,630	47,711	37%	3,353,858	1,373,977	59%
Auto Train	70%	825	0	100%	5,009	810	84%	213,853	71,638	67%
California Zephyr	70%	1,058	593	44%	6,276	3,582	43%	266,339	88,879	67%
Cardinal	70%	631	461	27%	1,721	1,443	16%	65,395	31,685	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,364	49,617	72%
Coast Starlight	70%	1,270	282	78%	7,645	1,678	78%	312,409	106,130	66%
Crescent	70%	1,414	838	41%	5,333	4,192	21%	255,826	76,284	70%
Empire Builder	70%	1,166	172	85%	7,377	4,149	44%	260,438	122,901	53%
Floridian	60%	1,990	1,990	0%	8,954	8,907	1%	439,119	292,550	33%
Lake Shore Ltd	73%	1,361	260	81%	7,092	3,779	47%	258,729	75,389	71%
Palmetto	70%	959	786	18%	4,903	4,131	16%	252,676	70,229	72%
Silver Meteor	70%	600	327	46%	6,209	5,174	17%	278,590	115,326	59%
Southwest Chief	60%	960	365	62%	6,105	4,217	31%	224,755	142,629	37%
Sunset Ltd	70%	373	70	81%	1,941	1,093	44%	80,326	27,774	65%
Texas Eagle	70%	1,378	389	72%	7,065	4,556	36%	268,039	102,946	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000157 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through July 06, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	46,195	603,685	765	1,613,466	29,241,332	552

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,537	167,243	152	75,916	8,388,243	91
INFRASTRUCTURE PLANNED	135	2,322	167,243	139	81,280	8,388,243	97
FLEET RELIABILITY	90	9,388	603,685	156	262,423	29,241,332	90
TRAIN OPERATIONS	424	31,948	603,685	529	1,193,847	29,241,332	408

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/06/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	76	76.5%	1,758	301	82.9%	83,116	11,425	86.3%
Central Division	86.0%	71	14	80.3%	428	45	89.5%	20,467	1,863	90.9%
East Division	82.0%	176	47	73.3%	893	180	79.8%	43,454	6,788	84.4%
West Division	86.0%	76	15	80.3%	437	76	82.6%	19,195	2,774	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/06/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	76	76.5%	1,758	301	82.9%	83,116	11,425	86.3%
Central Division	86.0%	71	14	80.3%	428	45	89.5%	20,467	1,863	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	12	0	100.0%	529	18	96.6%
CHI	86.0%	26	4	84.6%	156	19	87.8%	7,395	883	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	12	0	100.0%	548	52	90.5%
FTW	92.5%	1	0	100.0%	6	1	83.3%	302	35	88.4%
GBB	-	1	1	0.0%	1	1	0.0%	2	2	0.0%
GRR	95.5%	1	0	100.0%	5	0	100.0%	264	8	97.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	-	-	-	8	0	100.0%	546	40	92.7%
LAX	89.5%	1	1	0.0%	6	1	83.3%	268	41	84.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	35	3	91.4%	1,633	100	93.9%
MOE	97.5%	2	0	100.0%	12	1	91.7%	557	9	98.4%
MSP	96.5%	1	0	100.0%	6	0	100.0%	272	5	98.2%
NOL	94.5%	4	1	75.0%	21	4	81.0%	1,171	57	95.1%
OKC	97.0%	1	0	100.0%	6	0	100.0%	273	6	97.8%
PDX	86.0%	4	0	100.0%	24	3	87.5%	1,106	110	90.1%
PNT	88.0%	3	2	33.3%	17	2	88.2%	720	60	91.7%
PTH	93.0%	1	1	0.0%	6	1	83.3%	267	11	95.9%
QCY	91.0%	1	0	100.0%	11	0	100.0%	541	39	92.8%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	6	0	100.0%	275	27	90.2%
SEA	85.0%	7	2	71.4%	42	6	85.7%	1,932	213	89.0%
STL	89.0%	4	2	50.0%	24	3	87.5%	1,081	93	91.4%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	12	0	100.0%	542	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	47	73.3%	893	180	79.8%	43,454	6,788	84.4%
ALB	88.5%	8	0	100.0%	46	2	95.7%	2,060	163	92.1%
BON	87.5%	5	0	100.0%	29	7	75.9%	1,341	147	89.0%
BOS	85.5%	18	2	88.9%	94	7	92.6%	4,734	569	88.0%
BRK	92.5%	5	0	100.0%	29	6	79.3%	1,330	90	93.2%
BTN	82.0%	1	0	100.0%	6	0	100.0%	265	39	85.3%
CLT	91.5%	5	1	80.0%	16	4	75.0%	1,357	136	90.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	12	2	83.3%	543	52	90.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/06/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	76	76.5%	1,758	301	82.9%	83,116	11,425	86.3%
East Division	82.0%	176	47	73.3%	893	180	79.8%	43,454	6,788	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	13	1	92.3%	54	7	87.0%	3,077	513	83.3%
HFD	-	2	1	50.0%	6	1	83.3%	153	9	94.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	6	0	100.0%	275	34	87.6%
MIA	89.5%	1	0	100.0%	11	2	81.8%	550	62	88.7%
MTR	79.0%	1	1	0.0%	6	2	66.7%	262	48	81.7%
NFK	84.5%	2	1	50.0%	12	6	50.0%	633	115	81.8%
NFL	93.5%	2	0	100.0%	12	1	91.7%	562	23	95.9%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	2	60.0%	28	3	89.3%	1,434	226	84.2%
NPN	93.0%	2	1	50.0%	10	2	80.0%	523	37	92.9%
NYP	75.5%	49	21	57.1%	249	69	72.3%	11,303	2,530	77.6%
PGH	93.0%	1	1	0.0%	6	2	66.7%	277	21	92.4%
PHL	48.0%	5	3	40.0%	28	13	53.6%	1,428	690	51.7%
PIT	76.0%	-	-	-	2	2	0.0%	8	7	12.5%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	5	1	80.0%	10	1	90.0%	1,067	42	96.1%
RNK	83.5%	2	1	50.0%	12	4	66.7%	546	81	85.2%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	6	0	100.0%	265	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	4	0	100.0%	272	10	96.3%
SFA	88.0%	1	0	100.0%	6	0	100.0%	275	37	86.5%
SPG	92.5%	5	0	100.0%	34	1	97.1%	1,686	93	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	6	0	100.0%	265	56	78.9%
WAS	84.0%	32	10	68.8%	152	35	77.0%	6,748	876	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	76	15	80.3%	437	76	82.6%	19,195	2,774	85.5%
ARN	92.0%	1	0	100.0%	6	2	66.7%	277	21	92.4%
BFD	79.0%	7	2	71.4%	39	14	64.1%	1,725	355	79.4%
EMY	72.0%	1	0	100.0%	6	3	50.0%	282	87	69.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	18	4	77.8%	834	118	85.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/06/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	76	76.5%	1,758	301	82.9%	83,116	11,425	86.3%
West Division	86.0%	76	15	80.3%	437	76	82.6%	19,195	2,774	85.5%
LAX	89.5%	9	2	77.8%	57	6	89.5%	2,471	242	90.2%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	5	61.5%	67	23	65.7%	2,966	759	74.4%
PDX	86.0%	1	0	100.0%	6	0	100.0%	261	59	77.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	1	93.8%	88	10	88.6%	3,892	420	89.2%
SAN	90.5%	13	3	76.9%	78	7	91.0%	3,322	301	90.9%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	0	100.0%	6	2	66.7%	258	105	59.3%
SJC	89.0%	7	1	85.7%	42	4	90.5%	1,949	186	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	18	1	94.4%	597	61	89.8%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	6	0	100.0%	272	20	92.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		3	0	100.0%	118	8	93.2%	3	1	66.7%	118	24	79.7%
3		6	0	100.0%	277	54	80.5%	6	1	83.3%	275	118	57.1%
4		6	0	100.0%	276	42	84.8%	6	4	33.3%	276	183	33.7%
5	56	6	1	83.3%	275	44	84.0%	5	3	40.0%	271	66	75.6%
6		6	3	50.0%	274	80	70.8%	6	4	33.3%	274	86	68.6%
7		6	1	83.3%	266	36	86.5%	6	1	83.3%	259	62	76.1%
8		6	2	66.7%	266	113	57.5%	6	3	50.0%	265	152	42.6%
11		6	1	83.3%	277	51	81.6%	6	0	100.0%	271	54	80.1%
14		6	1	83.3%	278	42	84.9%	6	0	100.0%	276	83	69.9%
19	No OS	6	4	33.3%	276	69	75.0%	6	6	0.0%	274	65	76.3%
20		6	3	50.0%	276	21	92.4%	6	5	16.7%	276	52	81.2%
21		6	0	100.0%	273	22	91.9%	6	4	33.3%	272	66	75.7%
22		6	0	100.0%	274	25	90.9%	6	3	50.0%	272	65	76.1%
23	69	6	1	83.3%	279	6	97.8%	6	3	50.0%	277	72	74.0%
24	64	6	1	83.3%	279	15	94.6%	6	2	66.7%	278	45	83.8%
25		6	0	100.0%	278	3	98.9%	6	2	66.7%	276	71	74.3%
26	48	6	0	100.0%	278	5	98.2%	6	2	66.7%	276	54	80.4%
27		6	2	66.7%	264	16	93.9%	6	1	83.3%	260	82	68.5%
28		6	0	100.0%	260	59	77.3%	6	1	83.3%	260	52	80.0%
40	31	5	1	80.0%	271	39	85.6%	6	6	0.0%	271	138	49.1%
41	No OS	5	4	20.0%	271	106	60.9%	6	6	0.0%	270	202	25.2%
42		6	2	66.7%	278	22	92.1%	6	3	50.0%	276	45	83.7%
43		6	0	100.0%	277	41	85.2%	6	5	16.7%	277	61	78.0%
48		6	1	83.3%	276	54	80.4%	6	2	66.7%	276	40	85.5%
49		6	3	50.0%	276	70	74.6%	6	2	66.7%	276	54	80.4%
51	174	3	2	33.3%	115	51	55.7%	3	3	0.0%	111	40	64.0%
52		6	0	100.0%	275	37	86.5%	6	0	100.0%	274	61	77.7%
53		6	0	100.0%	275	34	87.6%	6	2	66.7%	274	87	68.2%
55	85	3	0	100.0%	171	6	96.5%	3	2	33.3%	168	36	78.6%
56	33	3	0	100.0%	172	22	87.2%	3	3	0.0%	169	29	82.8%
63	63	6	3	50.0%	279	120	57.0%	6	5	16.7%	275	145	47.3%
64		6	0	100.0%	277	63	77.3%	6	3	50.0%	277	94	66.1%
66	160	6	3	50.0%	276	57	79.3%	5	1	80.0%	273	50	81.7%
67		3	1	66.7%	190	12	93.7%	3	0	100.0%	190	31	83.7%
68		6	2	66.7%	279	57	79.6%	6	4	33.3%	279	107	61.6%
69	20	6	1	83.3%	266	60	77.4%	6	4	33.3%	262	36	86.3%
71	25	6	0	100.0%	274	3	98.9%	6	5	16.7%	273	71	74.0%
72		2	0	100.0%	270	29	89.3%	2	0	100.0%	269	55	79.6%
73		1	0	100.0%	273	16	94.1%	1	0	100.0%	271	126	53.5%
74	15	1	0	100.0%	271	30	88.9%	1	1	0.0%	269	95	64.7%
75		1	0	100.0%	271	14	94.8%	1	0	100.0%	266	125	53.0%
76	79	1	0	100.0%	271	26	90.4%	1	1	0.0%	263	105	60.1%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	67	1	1	0.0%	270	18	93.3%	1	1	0.0%	268	109	59.3%
78	14	6	2	66.7%	274	22	92.0%	6	5	16.7%	273	55	79.9%
79		6	0	100.0%	276	55	80.1%	6	5	16.7%	275	89	67.6%
80	63	6	2	66.7%	276	30	89.1%	5	4	20.0%	273	53	80.6%
84		2	0	100.0%	164	11	93.3%	2	1	50.0%	162	36	77.8%
85		3	0	100.0%	173	16	90.8%	3	2	33.3%	173	63	63.6%
86	94	3	1	66.7%	173	15	91.3%	3	3	0.0%	172	103	40.1%
89		6	2	66.7%	274	60	78.1%	6	3	50.0%	272	73	73.2%
90	72	6	0	100.0%	274	10	96.4%	6	5	16.7%	273	42	84.6%
93	70	3	0	100.0%	172	18	89.5%	3	3	0.0%	171	40	76.6%
94	127	3	3	0.0%	203	53	73.9%	3	3	0.0%	201	72	64.2%
95	169	3	0	100.0%	172	3	98.3%	3	3	0.0%	172	62	64.0%
97	No OS	6	6	0.0%	276	179	35.1%	6	5	16.7%	274	81	70.4%
98	48	6	1	83.3%	276	22	92.0%	6	6	0.0%	274	86	68.6%
110	24	3	2	33.3%	169	98	42.0%	3	1	66.7%	166	17	89.8%
111		3	0	100.0%	163	32	80.4%	3	0	100.0%	161	20	87.6%
112		3	0	100.0%	163	16	90.2%	3	0	100.0%	162	17	89.5%
113		3	1	66.7%	94	23	75.5%	3	0	100.0%	93	11	88.2%
119	17	2	1	50.0%	162	44	72.8%	2	2	0.0%	160	22	86.3%
125	21	3	0	100.0%	173	8	95.4%	3	3	0.0%	173	69	60.1%
128	148	3	0	100.0%	106	19	82.1%	3	3	0.0%	106	19	82.1%
129		3	0	100.0%	172	44	74.4%	3	2	33.3%	172	25	85.5%
130	59	3	1	66.7%	163	17	89.6%	3	1	66.7%	161	16	90.1%
131	42	3	1	66.7%	165	48	70.9%	3	3	0.0%	165	32	80.6%
134		3	1	66.7%	173	22	87.3%	3	2	33.3%	172	28	83.7%
137		3	0	100.0%	170	30	82.4%	3	1	66.7%	170	53	68.8%
138	49	3	1	66.7%	173	36	79.2%	3	3	0.0%	172	30	82.6%
139	31	1	0	100.0%	35	5	85.7%	1	1	0.0%	35	12	65.7%
141		3	0	100.0%	172	3	98.3%	3	1	66.7%	171	29	83.0%
148		3	0	100.0%	172	17	90.1%	3	1	66.7%	170	31	81.8%
151	19	6	2	66.7%	275	88	68.0%	6	6	0.0%	274	90	67.2%
166	172	1	0	100.0%	35	4	88.6%	1	1	0.0%	34	12	64.7%
169	40	3	0	100.0%	104	12	88.5%	3	1	66.7%	104	22	78.8%
170		3	0	100.0%	168	12	92.9%	3	0	100.0%	167	29	82.6%
171	126	3	0	100.0%	173	10	94.2%	3	3	0.0%	173	64	63.0%
172	60	3	0	100.0%	172	14	91.9%	3	2	33.3%	170	57	66.5%
173	38	2	0	100.0%	167	23	86.2%	2	2	0.0%	166	75	54.8%
174		3	0	100.0%	173	20	88.4%	3	2	33.3%	173	40	76.9%
175	17	3	0	100.0%	173	21	87.9%	3	1	66.7%	173	56	67.6%
176	79	2	1	50.0%	167	15	91.0%	2	2	0.0%	165	17	89.7%
177		3	1	66.7%	173	25	85.5%	3	0	100.0%	173	44	74.6%
181	37	3	0	100.0%	169	54	68.0%	3	1	66.7%	167	13	92.2%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		3	0	100.0%	163	28	82.8%	3	1	66.7%	161	17	89.4%
183	35	3	1	66.7%	172	49	71.5%	3	1	66.7%	170	34	80.0%
184	69	3	1	66.7%	173	30	82.7%	3	3	0.0%	172	26	84.9%
185		3	0	100.0%	173	36	79.2%	3	0	100.0%	173	11	93.6%
186	88	3	0	100.0%	172	17	90.1%	3	2	33.3%	171	42	75.4%
190	32	3	0	100.0%	172	62	64.0%	3	1	66.7%	171	38	77.8%
192		3	2	33.3%	170	21	87.6%	3	1	66.7%	170	15	91.2%
193	56	2	1	50.0%	171	72	57.9%	2	2	0.0%	170	82	51.8%
196		2	0	100.0%	171	18	89.5%	2	0	100.0%	170	15	91.2%
197	30	3	1	66.7%	173	69	60.1%	3	3	0.0%	173	56	67.6%
230		6	0	100.0%	113	4	96.5%	6	0	100.0%	113	6	94.7%
232		6	0	100.0%	279	11	96.1%	6	0	100.0%	279	17	93.9%
233	67	4	1	75.0%	255	57	77.6%	4	2	50.0%	255	75	70.6%
234		6	1	83.3%	279	20	92.8%	6	0	100.0%	279	24	91.4%
235		6	0	100.0%	203	27	86.7%	6	3	50.0%	203	44	78.3%
236	29	6	0	100.0%	263	7	97.3%	6	1	83.3%	263	37	85.9%
237	133	6	0	100.0%	277	52	81.2%	6	3	50.0%	275	46	83.3%
238		6	0	100.0%	203	19	90.6%	6	0	100.0%	202	14	93.1%
239	67	6	2	66.7%	278	74	73.4%	6	3	50.0%	277	33	88.1%
240	21	6	0	100.0%	278	20	92.8%	6	2	66.7%	276	46	83.3%
241	24	6	2	66.7%	279	70	74.9%	6	2	66.7%	279	68	75.6%
243		6	4	33.3%	215	59	72.6%	6	3	50.0%	214	29	86.4%
244	60	4	0	100.0%	255	10	96.1%	4	3	25.0%	255	41	83.9%
245		6	2	66.7%	160	29	81.9%	6	1	83.3%	159	18	88.7%
280		6	1	83.3%	279	12	95.7%	6	0	100.0%	279	50	82.1%
281		6	0	100.0%	279	29	89.6%	6	3	50.0%	279	50	82.1%
283		6	2	66.7%	279	66	76.3%	6	3	50.0%	279	55	80.3%
284		6	0	100.0%	279	10	96.4%	6	2	66.7%	277	44	84.1%
290		6	0	100.0%	279	48	82.8%	6	4	33.3%	277	95	65.7%
291		6	2	66.7%	278	77	72.3%	6	3	50.0%	276	61	77.9%
300	20	6	0	100.0%	263	19	92.8%	6	4	33.3%	261	60	77.0%
301	16	6	0	100.0%	277	9	96.8%	6	3	50.0%	274	53	80.7%
302		6	1	83.3%	264	32	87.9%	6	2	66.7%	260	74	71.5%
305	34	6	0	100.0%	267	28	89.5%	6	5	16.7%	263	107	59.3%
306		6	0	100.0%	275	15	94.5%	6	3	50.0%	274	74	73.0%
307		6	0	100.0%	267	35	86.9%	6	2	66.7%	264	72	72.7%
318	19	6	2	66.7%	278	28	89.9%	6	4	33.3%	275	128	53.5%
319		6	0	100.0%	279	17	93.9%	4	2	50.0%	275	147	46.5%
329		4	0	100.0%	196	8	95.9%	4	0	100.0%	196	13	93.4%
330		5	0	100.0%	236	4	98.3%	5	0	100.0%	236	13	94.5%
331		6	0	100.0%	279	29	89.6%	6	0	100.0%	279	40	85.7%
332	14	6	0	100.0%	279	14	95.0%	6	2	66.7%	279	41	85.3%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		6	0	100.0%	279	9	96.8%	6	0	100.0%	278	36	87.1%
335		6	0	100.0%	279	30	89.2%	6	2	66.7%	277	45	83.8%
336		6	1	83.3%	279	9	96.8%	6	0	100.0%	277	25	91.0%
337		6	1	83.3%	279	18	93.5%	6	1	83.3%	275	34	87.6%
338		6	2	66.7%	279	43	84.6%	6	1	83.3%	277	82	70.4%
339		6	1	83.3%	279	47	83.2%	6	1	83.3%	279	49	82.4%
341		6	1	83.3%	268	36	86.6%	6	1	83.3%	263	36	86.3%
342		6	0	100.0%	279	21	92.5%	6	0	100.0%	277	53	80.9%
350	Cncld	6	0	100.0%	260	17	93.5%	5	4	20.0%	254	140	44.9%
351	339	6	1	83.3%	262	26	90.1%	6	2	66.7%	260	70	73.1%
352	114	6	0	100.0%	246	20	91.9%	6	4	33.3%	240	75	68.8%
353	166	5	0	100.0%	220	12	94.5%	5	1	80.0%	214	36	83.2%
354	102	6	2	66.7%	260	30	88.5%	6	5	16.7%	256	94	63.3%
355	128	6	1	83.3%	273	28	89.7%	6	6	0.0%	266	91	65.8%
364	18	6	1	83.3%	268	61	77.2%	6	5	16.7%	262	95	63.7%
365	32	6	1	83.3%	267	11	95.9%	6	5	16.7%	265	97	63.4%
370		6	1	83.3%	270	34	87.4%	5	1	80.0%	262	66	74.8%
371		5	0	100.0%	264	8	97.0%	5	1	80.0%	263	28	89.4%
380		6	0	100.0%	265	24	90.9%	6	3	50.0%	265	52	80.4%
381		6	0	100.0%	279	11	96.1%	6	2	66.7%	278	50	82.0%
382		6	1	83.3%	278	17	93.9%	6	3	50.0%	278	87	68.7%
383	Cncld	6	1	83.3%	268	26	90.3%	5	2	60.0%	265	107	59.6%
390	18	6	0	100.0%	261	17	93.5%	6	3	50.0%	260	66	74.6%
391		6	1	83.3%	264	9	96.6%	6	3	50.0%	261	68	73.9%
392	20	6	0	100.0%	278	5	98.2%	6	5	16.7%	276	83	69.9%
393		6	0	100.0%	279	16	94.3%	6	4	33.3%	276	81	70.7%
417		3	1	66.7%	183	39	78.7%	3	0	100.0%	174	17	90.2%
425		3	0	100.0%	185	6	96.8%	3	0	100.0%	185	7	96.2%
448		6	2	66.7%	209	40	80.9%	6	3	50.0%	207	71	65.7%
449		6	1	83.3%	207	31	85.0%	6	4	33.3%	207	40	80.7%
470		3	1	66.7%	196	35	82.1%	3	0	100.0%	190	23	87.9%
471	23	3	1	66.7%	186	7	96.2%	3	1	66.7%	186	3	98.4%
473		3	0	100.0%	192	13	93.2%	3	0	100.0%	189	8	95.8%
474	18	3	0	100.0%	187	51	72.7%	3	3	0.0%	175	50	71.4%
475		3	0	100.0%	190	5	97.4%	3	1	66.7%	190	11	94.2%
478		3	2	33.3%	184	29	84.2%	3	0	100.0%	182	20	89.0%
479	16	3	2	33.3%	191	31	83.8%	3	3	0.0%	189	25	86.8%
486		3	1	66.7%	195	29	85.1%	3	2	33.3%	189	52	72.5%
494		3	0	100.0%	196	35	82.1%	3	2	33.3%	190	46	75.8%
495		3	0	100.0%	181	3	98.3%	3	0	100.0%	179	3	98.3%
500		6	1	83.3%	270	16	94.1%	5	0	100.0%	267	32	88.0%
502		6	1	83.3%	277	16	94.2%	5	0	100.0%	273	56	79.5%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
503	33	6	1	83.3%	275	26	90.5%	6	4	33.3%	269	78	71.0%
504		6	0	100.0%	279	17	93.9%	6	2	66.7%	277	84	69.7%
505	17	6	1	83.3%	277	37	86.6%	5	3	40.0%	272	76	72.1%
506	42	6	1	83.3%	274	39	85.8%	6	2	66.7%	269	43	84.0%
507		6	1	83.3%	279	35	87.5%	6	2	66.7%	279	90	67.7%
508		6	0	100.0%	274	39	85.8%	6	0	100.0%	271	62	77.1%
509		6	0	100.0%	276	12	95.7%	6	0	100.0%	276	63	77.2%
511	30	6	1	83.3%	271	22	91.9%	6	1	83.3%	270	46	83.0%
516		6	1	83.3%	271	28	89.7%	6	2	66.7%	270	125	53.7%
517	21	6	0	100.0%	279	8	97.1%	6	5	16.7%	275	113	58.9%
518	42	6	0	100.0%	279	35	87.5%	6	4	33.3%	277	187	32.5%
519		6	0	100.0%	271	9	96.7%	6	1	83.3%	269	64	76.2%
520		4	0	100.0%	154	24	84.4%	4	0	100.0%	151	9	94.0%
521	31	4	0	100.0%	192	7	96.4%	4	2	50.0%	192	25	87.0%
522		4	0	100.0%	192	36	81.3%	4	0	100.0%	189	18	90.5%
523		4	0	100.0%	192	6	96.9%	4	0	100.0%	191	22	88.5%
524		4	1	75.0%	192	12	93.8%	4	0	100.0%	190	20	89.5%
525		4	1	75.0%	190	13	93.2%	4	0	100.0%	187	13	93.0%
526		4	1	75.0%	166	30	81.9%	4	1	75.0%	163	13	92.0%
527		4	0	100.0%	192	9	95.3%	4	0	100.0%	191	32	83.2%
528		4	0	100.0%	192	15	92.2%	4	0	100.0%	191	29	84.8%
529		4	0	100.0%	192	11	94.3%	4	0	100.0%	191	50	73.8%
530		4	0	100.0%	146	14	90.4%	4	1	75.0%	146	27	81.5%
531		4	0	100.0%	166	12	92.8%	4	1	75.0%	166	12	92.8%
532		4	2	50.0%	192	45	76.6%	4	2	50.0%	191	29	84.8%
534		4	0	100.0%	151	24	84.1%	4	0	100.0%	149	15	89.9%
535		4	1	75.0%	179	24	86.6%	4	0	100.0%	174	20	88.5%
536		4	1	75.0%	192	50	74.0%	4	0	100.0%	189	37	80.4%
537		4	0	100.0%	163	18	89.0%	4	0	100.0%	158	16	89.9%
538	99	4	0	100.0%	192	23	88.0%	4	2	50.0%	191	39	79.6%
539		4	1	75.0%	146	21	85.6%	4	1	75.0%	146	65	55.5%
540		3	1	66.7%	191	36	81.2%	3	0	100.0%	184	18	90.2%
541		4	0	100.0%	191	21	89.0%	4	1	75.0%	186	34	81.7%
542		4	0	100.0%	191	21	89.0%	4	2	50.0%	189	34	82.0%
543	48	4	0	100.0%	192	19	90.1%	4	3	25.0%	192	53	72.4%
544	23	4	0	100.0%	190	20	89.5%	4	1	75.0%	187	16	91.4%
545		4	1	75.0%	192	16	91.7%	4	0	100.0%	190	22	88.4%
547		4	0	100.0%	192	37	80.7%	4	0	100.0%	192	44	77.1%
548		3	0	100.0%	187	20	89.3%	3	0	100.0%	186	14	92.5%
549		4	0	100.0%	187	25	86.6%	4	0	100.0%	180	16	91.1%
550	19	4	0	100.0%	146	14	90.4%	4	1	75.0%	146	32	78.1%
551		4	0	100.0%	188	19	89.9%	4	0	100.0%	180	17	90.6%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		6	1	83.3%	271	22	91.9%	6	0	100.0%	268	29	89.2%
564		6	0	100.0%	271	17	93.7%	6	1	83.3%	263	31	88.2%
566		6	0	100.0%	269	17	93.7%	6	1	83.3%	266	33	87.6%
567		6	0	100.0%	156	8	94.9%	6	0	100.0%	154	6	96.1%
572		6	0	100.0%	266	22	91.7%	6	2	66.7%	261	67	74.3%
573		6	0	100.0%	269	40	85.1%	6	0	100.0%	262	44	83.2%
579		6	0	100.0%	156	8	94.9%	6	2	66.7%	151	28	81.5%
580		6	0	100.0%	271	14	94.8%	6	0	100.0%	266	21	92.1%
581		6	2	66.7%	271	45	83.4%	6	1	83.3%	269	55	79.6%
584		6	3	50.0%	155	20	87.1%	6	5	16.7%	151	87	42.4%
587		6	0	100.0%	266	15	94.4%	6	1	83.3%	257	39	84.8%
588		6	1	83.3%	156	13	91.7%	6	0	100.0%	155	22	85.8%
591		6	0	100.0%	270	18	93.3%	6	0	100.0%	264	29	89.0%
593		6	1	83.3%	265	38	85.7%	6	1	83.3%	247	28	88.7%
595		6	1	83.3%	266	42	84.2%	6	1	83.3%	263	47	82.1%
600	15	3	0	100.0%	200	9	95.5%	3	1	66.7%	198	16	91.9%
601		3	2	33.3%	183	74	59.6%	3	0	100.0%	180	23	87.2%
605		3	2	33.3%	190	120	36.8%	3	0	100.0%	186	19	89.8%
607	11	3	1	66.7%	199	25	87.4%	3	1	66.7%	196	23	88.3%
609		3	1	66.7%	190	23	87.9%	3	1	66.7%	189	16	91.5%
622		2	0	100.0%	105	30	71.4%	2	0	100.0%	103	5	95.1%
626		3	0	100.0%	104	12	88.5%	3	0	100.0%	102	15	85.3%
637		3	0	100.0%	57	6	89.5%	3	0	100.0%	57	4	93.0%
639		2	0	100.0%	170	37	78.2%	2	0	100.0%	169	19	88.8%
640	12	3	0	100.0%	190	7	96.3%	3	1	66.7%	188	77	59.0%
641		3	0	100.0%	172	34	80.2%	3	0	100.0%	172	25	85.5%
642		3	0	100.0%	188	9	95.2%	3	0	100.0%	187	23	87.7%
643		3	0	100.0%	202	39	80.7%	3	0	100.0%	199	32	83.9%
644	15	3	0	100.0%	194	27	86.1%	3	2	33.3%	192	50	74.0%
645		3	1	66.7%	202	39	80.7%	2	1	50.0%	199	40	79.9%
646		3	1	66.7%	191	47	75.4%	3	2	33.3%	189	91	51.9%
647		3	0	100.0%	202	31	84.7%	3	2	33.3%	201	45	77.6%
648		3	1	66.7%	198	51	74.2%	3	1	66.7%	198	32	83.8%
649		3	2	33.3%	203	39	80.8%	3	0	100.0%	200	31	84.5%
650		3	0	100.0%	202	39	80.7%	3	2	33.3%	199	32	83.9%
651		3	0	100.0%	202	16	92.1%	3	2	33.3%	200	41	79.5%
652		3	0	100.0%	203	27	86.7%	3	2	33.3%	199	34	82.9%
653		3	1	66.7%	191	31	83.8%	3	2	33.3%	188	36	80.9%
654		3	1	66.7%	192	37	80.7%	2	0	100.0%	188	16	91.5%
655		3	1	66.7%	200	70	65.0%	3	2	33.3%	198	70	64.6%
656	12	3	0	100.0%	202	45	77.7%	3	2	33.3%	201	23	88.6%
657		3	1	66.7%	191	27	85.9%	3	0	100.0%	190	28	85.3%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
658		3	0	100.0%	202	34	83.2%	3	0	100.0%	200	30	85.0%
680		4	2	50.0%	197	11	94.4%	4	0	100.0%	196	24	87.8%
681	14	4	0	100.0%	197	14	92.9%	4	2	50.0%	192	74	61.5%
682	11	4	0	100.0%	196	5	97.4%	4	1	75.0%	196	34	82.7%
683	22	4	0	100.0%	179	15	91.6%	4	4	0.0%	178	55	69.1%
684		4	2	50.0%	178	29	83.7%	4	1	75.0%	178	39	78.1%
685	50	4	2	50.0%	193	30	84.5%	4	4	0.0%	190	48	74.7%
686	21	4	0	100.0%	198	33	83.3%	4	4	0.0%	197	40	79.7%
687	38	4	2	50.0%	197	32	83.8%	4	3	25.0%	196	34	82.7%
688	30	4	2	50.0%	196	11	94.4%	4	3	25.0%	195	33	83.1%
699	15	2	0	100.0%	60	8	86.7%	2	1	50.0%	60	3	95.0%
701		6	1	83.3%	211	22	89.6%	6	0	100.0%	208	20	90.4%
702		6	0	100.0%	278	31	88.8%	6	1	83.3%	276	61	77.9%
703	Cncld	6	4	33.3%	279	81	71.0%	5	3	40.0%	277	73	73.6%
704	No OS	6	0	100.0%	210	32	84.8%	5	1	80.0%	204	39	80.9%
710		6	2	66.7%	279	71	74.6%	6	2	66.7%	275	75	72.7%
711		6	1	83.3%	270	29	89.3%	5	1	80.0%	252	46	81.7%
712		6	3	50.0%	276	74	73.2%	6	1	83.3%	268	88	67.2%
713		3	1	66.7%	149	15	89.9%	3	2	33.3%	136	58	57.4%
714	38	5	4	20.0%	160	62	61.3%	5	3	40.0%	148	61	58.8%
715		6	1	83.3%	278	59	78.8%	4	1	75.0%	257	126	51.0%
716		6	1	83.3%	279	108	61.3%	6	2	66.7%	274	104	62.0%
717		6	1	83.3%	265	63	76.2%	6	2	66.7%	247	72	70.9%
718	52	6	5	16.7%	279	141	49.5%	6	5	16.7%	277	96	65.3%
719	27	6	5	16.7%	279	93	66.7%	6	4	33.3%	265	76	71.3%
757		6	0	100.0%	64	3	95.3%	6	0	100.0%	63	4	93.7%
761		6	1	83.3%	275	12	95.6%	6	1	83.3%	272	35	87.1%
765		6	0	100.0%	275	24	91.3%	6	0	100.0%	275	36	86.9%
769		6	0	100.0%	275	25	90.9%	6	0	100.0%	269	49	81.8%
770	51	6	0	100.0%	275	21	92.4%	6	4	33.3%	273	78	71.4%
774	19	6	0	100.0%	275	16	94.2%	6	2	66.7%	274	58	78.8%
777		6	1	83.3%	160	10	93.8%	6	0	100.0%	159	34	78.6%
782		6	4	33.3%	160	60	62.5%	6	0	100.0%	155	15	90.3%
785		6	1	83.3%	275	18	93.5%	6	0	100.0%	275	46	83.3%
786		6	0	100.0%	64	16	75.0%	6	1	83.3%	63	28	55.6%
790		6	0	100.0%	275	26	90.5%	6	1	83.3%	272	33	87.9%
794		6	1	83.3%	275	32	88.4%	6	1	83.3%	272	56	79.4%
821		6	0	100.0%	273	6	97.8%	6	3	50.0%	273	106	61.2%
822	65	6	1	83.3%	275	15	94.5%	6	4	33.3%	273	122	55.3%
1333		6	2	66.7%	275	30	89.1%	6	2	66.7%	272	90	66.9%
1340		6	0	100.0%	274	5	98.2%	6	2	66.7%	274	44	83.9%
2102		3	0	100.0%	49	12	75.5%	3	0	100.0%	48	4	91.7%

Amtrak On Time Performance

Trains Arriving Through: 7/6/2026

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2103		3	0	100.0%	113	10	91.2%	3	0	100.0%	112	9	92.0%
2104		3	0	100.0%	139	9	93.5%	3	0	100.0%	137	10	92.7%
2107		3	1	66.7%	170	31	81.8%	3	0	100.0%	167	20	88.0%
2108		3	0	100.0%	170	25	85.3%	3	1	66.7%	164	18	89.0%
2109		3	0	100.0%	63	9	85.7%	3	0	100.0%	62	4	93.5%
2112		3	1	66.7%	10	3	70.0%	2	1	50.0%	8	1	87.5%
2113		3	1	66.7%	49	4	91.8%	3	0	100.0%	49	7	85.7%
2115		3	0	100.0%	49	5	89.8%	3	2	33.3%	48	6	87.5%
2116		3	0	100.0%	10	0	100.0%	3	2	33.3%	10	4	60.0%
2118	111	3	2	33.3%	10	2	80.0%	3	3	0.0%	10	5	50.0%
2119	19	3	0	100.0%	10	2	80.0%	3	3	0.0%	10	4	60.0%
2120	45	3	3	0.0%	10	6	40.0%	2	2	0.0%	9	5	44.4%
2123		3	1	66.7%	48	7	85.4%	2	1	50.0%	47	14	70.2%
2124	28	3	3	0.0%	142	26	81.7%	3	3	0.0%	140	16	88.6%
2127		3	2	33.3%	10	3	70.0%	3	2	33.3%	9	2	77.8%
2128	50	3	1	66.7%	10	1	90.0%	3	1	66.7%	10	1	90.0%
2131	42	3	2	33.3%	10	2	80.0%	3	1	66.7%	10	1	90.0%
2150	27	3	0	100.0%	163	22	86.5%	3	1	66.7%	160	68	57.5%
2151	200	3	0	100.0%	112	6	94.6%	3	1	66.7%	110	30	72.7%
2152	64	2	1	50.0%	70	4	94.3%	2	1	50.0%	69	27	60.9%
2154		2	0	100.0%	74	20	73.0%	2	0	100.0%	71	36	49.3%
2155	140	3	1	66.7%	172	15	91.3%	3	2	33.3%	168	92	45.2%
2158		3	0	100.0%	10	2	80.0%	3	2	33.3%	10	2	80.0%
2159	34	3	1	66.7%	165	12	92.7%	3	3	0.0%	163	51	68.7%
2160	Cncld	3	0	100.0%	10	0	100.0%	2	2	0.0%	9	6	33.3%
2162	72	3	0	100.0%	171	13	92.4%	3	2	33.3%	165	79	52.1%
2165	103	2	1	50.0%	9	1	88.9%	2	2	0.0%	9	4	55.6%
2167		2	0	100.0%	161	18	88.8%	2	0	100.0%	161	36	77.6%
2171	77	3	0	100.0%	99	8	91.9%	3	3	0.0%	96	21	78.1%
2190	152	2	1	50.0%	170	25	85.3%	2	1	50.0%	168	23	86.3%
2193	20	2	0	100.0%	167	23	86.2%	2	1	50.0%	165	46	72.1%
2264	19	1	0	100.0%	2	0	100.0%	1	1	0.0%	2	1	50.0%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2118	NYP	111	ITI	106	ITI	106	WAS-WAS	AM	Service, turn, or wye train, 2155
2119	WAS	19	SYS	16	SYS	13	BAL-BAL	AM	Re-crew / job briefing, HELD FOR RECREW CONDUCTOR. WILL RECREW AT BWI.
2120	NYP	45	ITI	21	ITI	21	WAS-WAS	AM	Service, turn, or wye train, 2159
2124	NYP	28	ITI	14	ITI	14	WAS-WAS	AM	Service, turn, or wye train, 2119
2128	NYP	50	DET	45	DET	45	WAS-WAS	AM	Catenary failure, Milepost, 99.64, 99.64, LATE 2190 DUE TO CATENARY ISSUES TURNED LATE FOR INBOUND 2165 WHICH DELAYED 2128
2131	WAS	42	ITI	44	ITI	44	NYP-NYP	AM	Service, turn, or wye train, 2118, LATE TURN OFF AM2118
2150	BOS	27	PTI	20	PTI	17	XNH-XGX	AM	Follow, 2190, Milepost, XGU, XGX, SIGNALS OF #2190 AHEAD, SINGLE TRK ACCOUNT OCS WIRE DOWN AT MP 99.64
2151	WAS	200	WTR	192	WTR	188	XGX-NHV	AM	Trees down, Milepost, OSB, OSB, Held at OSB a/c OCS wires down MP 99.64
2152	BOS	64	ENG	53	ENG	39	NHV-XGX	AM	Other electrical failure, 2035 LH LP, integrity failure at Branford HBD, STOPPED AND INSPECTED PLUS CAPPED AT 80MPH FAULT CUT OUT
2155	WAS	140	WTR	92	WTR	86	PVD-XGX	AM	Trees down, Milepost, KIN, KIN, Held at KIN a/c OCS wires down MP 99.64
2159	WAS	34	CTI	19	DMW	15	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2160	BOS	Trn Cancelled	SMW	13	PTI	7	NHV-XGX	AM	Follow, 94, Milepost w/Letters, NHV, XGU, AM2160 followed signals of AM94
2162	BOS	72	OTH	15	SMW	8	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT TO PELHAM BAY FOR SCHEDULED MAINTENANCE
2165	WAS	103	ITI	92	ITI	92	BOS-BOS	AM	Service, turn, or wye train, 2190, TURN OF LATE #2190
2171	WAS	77	ENG	85	ENG	38	WIL-XPV	AM	Cab signal failure, 2024 LH LP, CAB SIGNAL FAILURE. OPERATING 59MPH.
2190	BOS	152	WTR	154	WTR	154	NHV-NHV	AM	Trees down, Milepost, nhv, nhv, Held at NHV a/c OCS wires down MP 99.64
2193	NYP	20	CTI	19	CTI	17	RTE-PVD	AM	Follow, MBTA, 867, Milepost w/Letters, RTE, PVD, AM2193 followed signals of MT867, which was experiencing excessive wheel slip

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2264	BOS	19	SMW	9	SMW	5	NWK-NYP	AM	Scheduled in track usage program, Other, NO REPORTED DELAY	
66	BOS	160	WTR	176	WTR	150	NHV-NHV	AM	Trees down, Milepost, NHV, NHV, Held at NHV a/c OCS wires down MP 99.64	
86	BOS	94	ITI	68	ITI	68	NPN-NPN	CS	Service, turn, or wye train 9905	
93	NFK	70	WTR	40	FTI	23	ALX-QAN	CS	Follow 415, Milepost, 105.2, 89.9	
94	BOS	127	WTR	97	WTR	92	NLC-KIN	AM	Trees down, Milepost w/Letters, NLC, KIN, AM94 stopped adjacent to disabled AM2160 for a psngr transfer	
95	NFK	169	WTR	135	WTR	54	OSB-OSB	AM	Trees down, Milepost, osb, osb, Held at OSB a/c OCS wires down MP 99.64	
110	NYP	24	SVS	24	SVS	24	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from the yd.	
119	WAS	17	ITI	36	ITI	36	NYP-NYP	AM	Service, turn, or wye train, 130, LATE TURN OFF AM130	
125	NPN	21	OTH	75	OTH	49	WAS-XVG	AM	Lost time - N.A.R., TRAIN NOT TRACKING ON CSX	
128	NYP	148	WTR	109	WTR	94	NFK-X3V	NS	Heat order Milepost, 3.5, 52.0	
130	NYP	59	ENG	45	ENG	45	WAS-WAS	AM	Other electrical failure, 661 EX ES, LATE MTR FROM THE PIT	
131	WAS	42	SYS	41	SYS	41	NYP-NYP	AM	Delay in Block, ADDING ENG.663 TO WEST END	
138	NYP	49	DCS	49	DCS	49	ALX-XVG	CS	Restrictive signal(s) from unknown cause Stop, Control Point, Virginia	
139	WAS	31	WTR	23	PTI	15	XPV-BAL	AM	Cross over or go around, 128, Control Point, GUNPOW, OPR 3/A TRK AT GUNPOW. NOS 1 AND 2 TRKS O/S RIVER TO GUNPOW. LATE 128 ROUTED TO NO. 3 TRK THEN OPR A TO 1 TRACKS RIVER THEN 1/2 AT POINT	
151	RNK	19	PTI	25	PTI	25	CVS-LYH	NS	Cross over or go around 20, 178, Milepost, 129.1, 132.0, Milepost, 158, 164.2	
166	BOS	172	SYS	151	SYS	151	NYP-NYP	AM	Re-crew / job briefing, HELD IN STATION WAITING FOR ENGINEER.	
169	PHL	40	HLD	37	HLD	34	NYP-NYP	AM	Passenger and/or baggage, HELD FOR PASSENGERS LATE ARRIVING AM156.	
171	RNK	126	WTR	43	CAR	29	WAS-WAS	AM	Air / Brake / Wheel, 82634, SHOPPED 82634 FOR HOT JOURNAL, SET OFF CAR, NO REPLACEMENT.	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
172	BOS	60	SMW	26	SMW	19	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD F/AM2151-AM95 A/C 2 TRK OOS LEGGETT TO PELHAM BAY
173	WAS	38	POL	29	POL	29	BRP-BRP	MN	Suspicious bag or bomb threat A passenger dropped their rolling suitcase onto the seat, (forcefully) and left out of new haven. After searching the train, individual could not be found. For fear of unknown bag, I called MTA police to remove bag.
175	WAS	17	OTH	10	PTI	7	BBY-RTE	AM	Follow, 2171, Milepost w/Letters, BBY, RTE, AM175 followed signals of AM2171, which was delayed by MT949
176	BOS	79	WTR	49	WTR	33	OSB-OSB	AM	Trees down, Control Point, OSB, AM176 held at OSB a/c disabled AM2160 on trk 1
181	WAS	37	ENG	32	ENG	32	NWK-NWK	AM	Traction motor, 622 EX ES, LOST TRACTION POWER ON THE WAY TO NEWARK. ENGR INSPECTED TRAIN IN STATION AND FOUND A LOOSE COMMUNICATION HOSE.
183	WAS	35	ITI	44	ITI	44	NYP-NYP	AM	Service, turn, or wye train, 128, LATE F/SSYD LATE TURN OFF AM128
184	BOS	69	ENG	75	SMW	20	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT TO PELHAM BAY FOR SCHEDULED MAINTENANCE
186	PHL	88	DCS	60	DCS	60	WBG-RVM	CS	Restrictive signal(s) from unknown cause Stop , Control Point, fort lee
190	BOS	32	CTI	22	WTR	14	NHV-NHV	AM	Trees down, Milepost, NHV, NHV, Held at NHV a/c OCS wires down MP 99.64
193	WAS	56	DCS	18	DCS	18	MET-XHM	AM	Power switch failure, Other, HOLMES, HELD AT GRUNDY TO OPR 2 TRK A/C 34 SWITCH AT HOLMES FAILING REVERSED
197	WAS	30	PTI	18	DCS	17	NWK-XHM	AM	Power switch failure, Other, GRUNDY, HELD TO OPR 2 TRK A/C 34 SWITCH AT HOLMES FAILING REVERSED
471	NHV	23	ITI	23	ITI	23	HFD-HFD	AM	Service, turn, or wye train, 426, Late turn
474	SPG	18	SMW	11	SMW	11	WFD-MDN	AM	Scheduled in track usage program, Milepost w/Letters, WFD, MDN, Held for AM475 to clear a/c O/S track
479	NHV	16	CTI	10	CTI	10	WND-HFD	AM	Meet, CTRAIL, 4466, Milepost w/Letters, WND, HFD, AM479 waited for CT446 to clear single track

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
80	NYP	63	PTI	70	PTI	38	RMT-PTB	CS	Follow P04005, Milepost w/Letters, A 44.9, A 22.0	
600	NYP	15	CCR	19	CCR	19	PHL-XHM	AM	Electrical failure, NOCAR XX XX, Wye'd a/c no cab car.	
607	HAR	11	PTI	19	SVS	12	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE RELEASE BY COMMISSARY	
640	NYP	12	POL	8	POL	8	TRE-TRE	AM	Removal of passenger by police, PSGR FELL BETWEEN TRAIN & PLATFORM	
644	NYP	15	CTI	12	CTI	7	NWK-NYP	AM	Follow, NJT, NJ3834, Other, ERIE-NYP	
656	NYP	12	PTI	12	PTI	7	TRE-NWK	AM	Follow, AM136, Other, TRE-NWK	
19	NOL	No OS Rpt	WTR	307	WTR	292	WAS-WAS	AM	Heat order, Control Point, WAS, NO AVAILABLE DSLS DUE TO HIGH SHOP COUNT, NEC'Y TO USED DSL OFF LATE INBOUND TRAINS	
681	BRK	14	FTI	7	FTI	7	DOV-WEM	CS	Cross over or go around Control Point, Dover East, tie train	
682	BON	11	DCS	4	PTI	4	HHL-WOB	MT	Meet 682, Control Point, rockingham	
683	BRK	22	PTI	12	PTI	12	EXR-DHM	CS	Meet 684, Control Point, rockingham	
685	BRK	50	POL	27	POL	27	WOB-HHL	MT	Fire department hold At or near Sutton st	
686	BON	21	DCS	14	DCS	9	FRE-POR	CS	Issue with automatic road crossing protection Other, all xngs b/w Forest Ave PLD 10.01 and Revere PLD 10.21	
687	BRK	38	PTI	29	PTI	29	WOB-HHL	MT	Meet keolis 266, Control Point, CPF FR	
688	BON	30	PTI	15	PTI	15	WEM-DOV	CS	Meet Nothing on track two between rollingsford-oak. Dispatch put in signal and told us we need to copy an EC-1 before HA, after sitting 15 minutes, 687, Control Point, varney	
699	BRK	15	FTI	24	FTI	22	EXR-DHM	CS	Follow 426, Other, rockingham-durham	
63	TWO	63	SYS	29	SYS	21	NYP-NYP	AM	Other late crew, LATE F/SSYD A/C LATE CREW OFF AM89	
69	MTR	20	WTR	45	WTR	45	XLQ-SLQ	CN	Heat order Milepost, 1.2, 42.7	
233	ALB	67	ENG	30	ENG	30	CRT-POU	MN	Air / Brake Hose that feeds air to brakes on front axle of engine came unscrewed. Engineer and conductor were able to reattach hose and screw back together to get back on the move, 9707	
236	NYP	29	DSR	19	CTI	12	POU-CRT	MN	Meet metro, 813, Control Point, 46	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
237	ALB	133	RTE	107	RTE	107	CRT-POU	MN	Dispatcher hold Sat at cp 39 waiting for 3 south bound trains(2 metro north trains and Amtrak 244), and 6 northbound metro north trains(we were going north as well), Control Point, 39
239	ALB	67	WTR	71	WTR	69	CRT-POU	MN	Flood / washout Control Point, 46
240	NYP	21	CTI	12	CTI	12	POU-CRT	MN	Meet metro north, Control Point, 46
241	ALB	24	PTI	14	PTI	12	CRT-POU	MN	Cross over or go around Held at 53 to let the AMTK 239 and MN 869 pass us On track 1., 869, Control Point, 53
244	NYP	60	WTR	65	WTR	65	POU-CRT	MN	Flood / washout Single tracking 39 to 46 due to flooding under bear mtn bridge, Milepost w/Letters, cp46, cp39
71	CLT	25	PTI	26	PTI	20	KAN-CLT	NS	Wait for station track Account DMW on trk one, #AM19, Control Point, AT&O
74	RGH	15	DSR	15	DSR	11	HPT-GRO	NS	Per bulletin Milepost, 289.5, 284.6, 25, 1
76	RGH	79	DCS	59	DCS	59	KAN-GRO	NS	Block light out between Maybelle and Lake Control Point, Maybelle
77	CLT	67	DCS	47	DCS	43	HPT-SAL	NS	Restrictive signal(s) from known wayside signal failure Power outage, dark signals, Rest, Milepost, 307.7, 319.4
78	RGH	14	PTI	11	PTI	11	GRO-GRO	NS	Meet Amt79, Milepost, 0.0, 0.0
90	NYP	72	WTR	62	WTR	30	RMT-PTB	CS	High winds Milepost, 71.0, 39.7
97	MIA	No OS Rpt	ENG	524	ENG	524	WAS-WAS	AM	Air / Brake, 88, 182. 312, SHOPPED FOR MULTIPLE REASONS
98	NYP	48	ENG	54	ENG	54	WAS-WAS	AM	Other electrical failure, 644 EX ES, Late release of MTRS from the pit
55	WAS	85	MTI	37	MTI	37	WIL-XPV	AM	Disabled train ahead, Control Point, ., FOLLOWING 2171 WHO IS OPERATING 59 MPH A/C CAB SIGNAL FAILURE.
56	SAB	33	PTI	29	PTI	15	HFD-WNL	AM	Meet, 55, Milepost w/Letters, HFD, WNL, AM56 waited for AM55 to clear single track
40	CHI	31	WTR	111	INJ	24	RVR-XDJ	CS	Injured or sick passenger
41	MIA	No OS Rpt	ENG	246	ENG	163	JAX-JAX	CS	Swap engines due to PTC failure, trouble getting HEP up and running. 337, 14
23	NOL	69	FTI	74	FTI	74	BAS-XNO	CS	Meet Siding, Nicholson, Switching at port bienville was told it will be 8000 feet long after it's finished, l800
24	MOE	64	FTI	91	FTI	65	XNO-BAS	CS	Follow L800, Milepost, 766.3, 754.5

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
26	MOE	48	FTI	76	FTI	46	PAG-MOE	CS	Follow 60606, Milepost w/Letters, pay, 674
5	EMY	56	DCS	65	DCS	58	RNO-RNO	UP	PTC- Unplanned PTC system /server outage Other, reno station
521	SJC	31	MBO	26	MBO	26	SUI-MTZ	UP	For maritime traffic Bridge, Suisun
538	ARN	99	DCS	71	DCS	71	RLN-ARN	UP	Wayside detector failure including false actuation Carman came to us and inspected the high wide, there was nothing. They released us, Milepost, 111.0, 111.2
543	SJC	48	DTR	46	DTR	46	OAC-GAC	UP	Fire Milepost, 24.7, 24.7, OAC, GAC
544	SAC	23	POL	35	POL	27	GAC-FMT	UP	Fire department hold Held at Newark for 643. Change of plan and went to FMT. Fire at MP 24 on the Niles Sub.
550	SAC	19	PTI	12	PTI	9	FMT-HAY	UP	Meet 547, Control Point, shinn
51	CHI	174	WTR	133	PTI	70	XOR-CVS	BB	Cross over or go around BB16, Milepost, 177.5, 178.5
503	EUG	33	DCS	36	DCS	36	ALY-EUG	UP	Power switch failure Control Point, VP 668, Control Point, VP 666
505	PDX	17	FTI	20	FTI	20	VAN-PDX	BN	Meet up 7450, Control Point, north Portland
506	SEA	42	POL	28	POL	28	OLW-XNI	BN	Right of Way police hold MP 28.4 hold for unknown reason per dispatcher
511	PDX	30	PTI	10	PTI	10	TAC-TAC	ST	Meet sounder 905, amtrak 506, Control Point, tacoma dome
517	PDX	21	PTI	25	PTI	14	TAC-XNI	ST	Meet AMTK 504, Control Point, Rill
518	VAC	42	DMW	25	DMW	25	BEL-X8B	BN	Talk by red signal Control Point, Custer
822	OKC	65	FTI	53	FTI	28	FTW-GLE	BN	Meet Bnsf 4221, Siding, N.Metro
332	CHI	14	FTI	7	FTI	5	XRO-GLN	ME	Follow Waited for 448 to turn the corner at A20, CP 448, Control Point, A20
350	PNT	Trn Cancelled	FTI	139	FTI	139	BTL-BTL	CC	Freight train went into emergency west of the Battle Creek station. Train was quite long and blocked our route out of the Battle Creek station cn 3007, Control Point, rose
351	CHI	339	ENG	94	ENG	94	DET-DET	CC	HEP ID4613
352	PNT	114	ENG	61	RTE	25	JXN-JXN	MI	Dispatcher hold Control Point, jackson
353	CHI	166	SYS	100	SYS	79	DER-DER	MI	Blocked by or assisting another, disabled Amtrak train
354	PNT	102	PTI	51	PTI	51	KAL-XGO	MI	Meet amt355, Other, gord

Amtrak Endpoint OTP Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
355	CHI	128	ITI	125	ITI	125	DER-DER	MI	Service, turn, or wye train 350, Late inbound AMT 350. They took their pax's to DET to detrain then had to switch ends and come back to DER. Mechanical made sure train was set up right and pulled trash off cars before departure.
364	PTH	18	DSR	42	DSR	36	BTL-LNS	CC	Per bulletin Milepost, 176.86, 176.86, 25, 2, Milepost, 177.1, 177.1, 25, 1, Milepost, 180.91, 185.66, 30, 2, Milepost, 184.5, 188.4, 30, 1, Milepost, 192.68, 195, 10, 1, Milepost, 196.82, 196.82, 25, 2, Milepost, 196.9, 197.2, 30, all, Milepost, 201.75, 202.1, 30, main, Milepost, 202.25, 202.45, 25
365	CHI	32	DSR	39	DSR	29	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, 2, Milepost, 221.42, 221.42, 30, main, Milepost, 219.15, 219.5, 25, main, Milepost, 219, 218.5, 30, main, Milepost, 216.1, 215.79, 60, main, Milepost, 214.96, 214.96, 25, 2-mill west crossover, Milepost, 214.93, 214.93, 25, 1, Milepost, 210.40, 210.40, 30,
770	SAN	51	SYS	33	SYS	33	LAX-LAX	SC	PTC problem or failure (cause unknown) Control Point, Terminal
774	SAN	19	PTI	24	PTI	14	SNC-SNP	SC	Meet 777, Control Point, serra
703	SAC	Trn Cancelled	CON	24	CON	24	BFD-BFD	BN	Hold for thruway bus
704	BFD	No OS Rpt	FTI	171	FTI	171	XEC-LOD	UP	Hold due to freight derailment up 8100, Control Point, el pinal
714	BFD	38	TCC	49	TCC	25	OKJ-OKJ	UP	Door C8310, End Door not shut, no end door seal light.
718	BFD	52	ITI	39	ITI	39	EMY-EMY	UP	Service, turn, or wye train 713, Problems getting door light and air
719	OKJ	27	CON	27	CON	27	BFD-BFD	BN	Hold for thruway bus
300	CHI	20	FTI	15	FTI	15	SMT-XTF	CC	Cross Traffic unknown, Control Point, Brighton
301	STL	16	PTI	24	PTI	18	BNL-SPI	UP	Meet Amtk22, Siding, Ridgely
305	STL	34	MBO	28	MBO	28	CHI-XTF	AM	Bridge not working Control Point, 21st st
383	QCY	Trn Cancelled							
390	CHI	18	FTI	17	FTI	12	HMW-XCS	CC	Follow 337, Control Point, kelly
392	CHI	20	FTI	23	FTI	22	EFG-MAT	CC	Follow CN 8829, Milepost w/Letters, Effingham, Mattoon

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/6/2026

26-FOI-00580 00000008157 "UNCLASSIFIED" 7/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
318	CHI	3	SVS	20	SVS	20	STL-STL	TR	Unplanned Wye Other, STL station

Amtrak Initial Terminal Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/6/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	20	07/06	240	240	Water, commissary, toilet/trash dumping Servicing train equipment...
BOS	2155	07/06	16	16	Door, 3665 NG NB, Door issues
BOS	2165	07/06	92	92	Service, turn, or wye train, 2190, TURN OF LATE #2190
CLT	78	07/06	1		
HAR	648	07/06	1		
HFD	471	07/06	23	23	Service, turn, or wye train, 426, Late turn
MTR	68	07/06	2	2	Train not released to us until 4 minutes before departure. Then needed to charge air for brake test.
NFK	94	07/06	1		
NHV	470	07/06	6	6	Service, turn, or wye train, 471, TURN OF LATE #471
NHV	478	07/06	13	13	Pick up equipment, Equipment swap at NHV.
NPN	86	07/06	68	68	Service, turn, or wye train 9905
NYP	19	07/06	3	3	Passenger and/or baggage, BOARDING
NYP	63	07/06	21	21	Other late crew, LATE F/SSYD A/C LATE CREW OFF AM89
NYP	69	07/06	4	4	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	07/06	41	41	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR AM98 TO ADD THRE COACHES AND ONE SLEEPER TO COMPLETE CONSISTAND SERVICE.
NYP	113	07/06	18	18	Water, commissary, toilet/trash dumping, LATE ON-BOARD SERVICES.
NYP	119	07/06	36	36	Service, turn, or wye train, 130, LATE TURN OFF AM130
NYP	131	07/06	41	41	Delay in Block, ADDING ENG.663 TO WEST END
NYP	183	07/06	44	44	Service, turn, or wye train, 128, LATE F/SSYD LATE TURN OFF AM128
NYP	193	07/06	16	16	Engineer restroom break, LATE DEPARTURE A/C ENGINEER USING RESTROOM
NYP	233	07/06	15	15	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	239	07/06	2	2	Passenger and/or baggage, BOARDING
NYP	243	07/06	13	13	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	291	07/06	4	4	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	607	07/06	12	12	Water, commissary, toilet/trash dumping, LATE RELEASE BY COMMISSARY
NYP	609	07/06	3	3	Passenger and/or baggage, BOARDING
NYP	645	07/06	3	3	Passenger and/or baggage, BOARDING
NYP	653	07/06	2	2	Passenger and/or baggage, BOARDING

Amtrak Initial Terminal Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/6/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	657	07/06	9	9	Service, turn, or wye train, 654, LATE TURN OFF AM654
NYP	2113	07/06	3	3	Passenger and/or baggage, BOARDING
NYP	2131	07/06	44	44	Service, turn, or wye train, 2118, LATE TURN OFF AM2118
NYP	2190	07/06	8	8	Door, 3518 LH LC
PGH	42	07/06	10	10	Crew rest Late sign up due to late arrival of 43, Milepost, 353, 353
PHL	110	07/06	24	24	Planned set out / pick out of locomotives, cars or section of train, Late release from the yd.
PHL	601	07/06	1		
PHL	605	07/06	2	2	Passenger and/or baggage
RGH	77	07/06	8	8	Removal of passenger by police Claiming to have gun, made statements to multiple people, he was going to shoot several people. This all happened in RGH station, he was allowed to board, passenger alerted me of the situation.
RNK	66	07/06	(Trn Cxld)		Engine Issue
WAS	67	07/05	14	14	Water, commissary, toilet/trash dumping, Commissary late to train
WAS	130	07/06	45	45	Other electrical failure, 661 EX ES, LATE MTR FROM THE PIT
WAS	136	07/06	13	13	Other electrical failure, 633 AND 612, BOTH MTRS SHOPPED 633 BATTERY ISSUES AND 612 IO FAULTS
WAS	176	07/06	21	21	Other electrical failure, X, LATE MTRS DUE TO HIGH SHOP COUNT
WAS	198	07/06	186	186	Hold for bus with passengers from train, HELD FOR BUSES REPRESENTING CANCELED TRAIN 66(6). TRAIN WAS CANCELED DUE TO DSL PROBLEMS IN ROANOKE.
WAS	2118	07/06	106	106	Service, turn, or wye train, 2155
WAS	2120	07/06	21	21	Service, turn, or wye train, 2159
WAS	2124	07/06	14	14	Service, turn, or wye train, 2119
WAS	2128	07/06	45	45	Catenary failure, Milepost, 99.64, 99.64, LATE 2190 DUE TO CATENARY ISSUES TURNED LATE FOR INBOUND 2165 WHICH DELAYED 2128
WAS	2152	07/06	5	5	Delay in Block, AWAITING CREW
CHI	41	07/06	30	30	Door bypass cutout
CHI	354	07/06	120	120	Had to wait for 353 to come in and detach from 351 Other, union station
CHI	383	07/06	(Trn Cxld)		Car Issue
CHI	391	07/06	22	22	Electrical failure 31047, 32066, 32071, 33039, 34020, 34034, 35001, ID4626, Electrician shortage overnight whole Train bad
GBB	382	07/06	4	4	Other late crew Crew not moved up. Arrived GBB train at 640., Other, gbb depot

Amtrak Initial Terminal Details

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/6/2026

Terminal	Train	Date	Late	Delay	Cause
PNT	351	07/06	6	6	Back down to the station to pick up passengers and when doing so HEP went out through entire train. Mechanical called
PNT	355	07/06	(Trn Cxld)		Trespasser Strike
PTH	365	07/06	1		
STL	302	07/06	7	7	Late bulletins due to Amtrak cause Train annulled no train id for UP bulletins
STL	318	07/06	36	20	Unplanned Wye Other, STL station
BFD	703	07/06	24	24	Hold for thruway bus
BFD	719	07/06	27	27	Hold for thruway bus
GTA	782	07/06	1		
LAX	14	07/06	1	1	Follow "Ready to proceed" stated for all to hear for an on-time departure; no room to move on track 13 towards the red signal, per head end crew., 567, Control Point, terminal
LAX	562	07/06	4	4	Mechanical issues in yard equipment swap 562
LAX	584	07/06	1	1	Meet Amtk 581, Control Point, Terminal
OKJ	526	07/06	2	2	Meet 11, Control Point, King Street
OKJ	536	07/06	5	5	Loading problem Gremlins, C2101
OKJ	712	07/06	17	17	PTC back office issues C6962
OKJ	714	07/06	(Trn Cxld)	25	Third Party Cab Car Failure
OKJ	714	07/06	(Trn Cxld)	24	Third Party Cab Car Failure
OKJ	718	07/06	7	7	Meet 542, 545, Control Point, N. Jack London
SAC	525	07/06	5	5	Inability to contact dispatcher Train 11 unable to reach dispatcher to give back the signal after spotting for fuel, then signal in time., Control Point, Sacramento East Platform
SAN	581	07/06	14	14	Service, turn, or wye train 770
SAN	593	07/06	1	1	Passenger and/or baggage Pax Loading kids
SAN	777	07/06	3	3	On-train police or DEA activity Two families sitting in upstairs car 2 broke into a fight before departing San Diego. Started when a woman walking down the aisle turned around and her bag swung into the daughter of passenger Mkirtich Danilyelyan PNR 2A0342. Parties separated by APD.
SEA	507	07/06	3	3	HVAC blowing hot air 90253
SEA	511	07/06	30		
SJC	524	07/06	2	2	Meet CalTrain, 105, Other, SJC

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	98.4	94.8	342	3
CDOT	95.0	55.6	88.7	92.4	18	8
MARC	95.0	67.2	69.5	90.2	58	19
SEPTA	95.0	98.3	93.8	91.5	180	3
NJT-NED	95.0	98.9	88.7	88.6	278	3
NJT-SED	95.0	95.8	93.1	97.2	24	1

Operating Highlights

Train 2171(06) - Wilmington, DE - Engine Failure

07JUL26: Train 2171(06) was delayed on the Amtrak PW Line after power car 2024 experienced cab signal failure. The engineer could not rectify the issue and declared a failure en route. This restricted the train to 59MPH.
Train 55(06) was ordered to shadow train 2171(06) into WAS as contingency.

Train	Delay	Comment
2171(06)	1'25"	
55(06)	1'03"	

Train 41(04) - Tampa, FL - Engine Failure

07JUL26: Train 41(04) was delayed at Tampa Station after experiencing a mechanical problem. The crew consulted with CNOC Mechanical, and the Road Foreman to resolve the issue. While the crew was troubleshooting the issue, HEP was intermittent on the consist for about 30".

Train	Delay	Comment
41(04)	1'26"	

Train 2160(06) - East of Mystic, CT - Catenary or Wayside Failure

06JUL26: Train 2160(06) was cancelled with an emergency plate at MP 138.6 after an emergency plate was placed between Groton/MP 124.2 and High Street/MP 142.9 due to a possible exception to the OCS. Train 184(06) reported a burning branch near the right of way on No. 1 track, which triggered the emergency plate.

Train 2160(06) was terminated at MP 138.6.

Attempts to transfer the passengers from 2160(06) to Train 94(06) were hampered by both sets resting on a curve. Additionally, a torrential downpour made for slippery conditions. The remainder of the passengers were transferred to 2162(06). Service recovery was initiated on all trains involved and all trains that incurred delay.

Amtrak Management and ET Personnel responded to the scene.

Cause: Pending

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2160(06)	Term MP 138.6	
94(06)	1'32"	
179(06)	1'51"	
176(06)	49"	
2162(06)	1'13"	
178(06)	36"	

Train 237(06) - South of Poughkeepsie, NY - Weather

06JUL26: Train 237(06) was delayed on the Metro North Hudson Line at MP 39.5 due to flooding which placed both tracks over 2 inches below water at MP 44.7. The train was shoved back to MP 39.5 after encountering the flood condition at MP 44.7.

Trains 239(06) and 244(06) were also impacted and incurred delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
237(06)	1'47"	
239(06)	1'09"	
244(06)	1'05"	

Train 66(06) Roanoke, VA - Engine Failure

06JUL26: Due to E/310 upon arrival on train 151(06) into Roanoke shut down with a low hydrostatic oil fault. Mechanical/Rail plan was inspecting for active leaks. Due to this train 66(06) was cancelled from Roanoke to Boston with alternate buses from Roanoke to Washington. Train 198(06) was held in Washington for the arrival of the buses from Roanoke. Train 67(07) will originate in Washington and will be cancelled between Boston and Washington.

The NS did secure E/NS9934 to operate deadhead equipment of 66(06) Roanoke to Washington estimated to depart between 830P-930P-ET.

WBS#: B.TR.100150.6861

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66(06)	CANCELLED	BUSES RNK-WAS
67(07)	ORIG WAS	CANCELLED BOS-WAS
198(06)	3'07"	held for buses was

Train 68(06) South of St-Lambert, QC - Heat Orders/ Weather

06JUL26: Train 68(06) was delayed on the CN Rouses Point subdivision due to heat orders from MP 42.0 to MP 2.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(06)	48"	

Train 80(06) North of Rocky Mount, NC - Passenger Train Interference

06JUL26: Train 80(06) with E/355 and E/356 was delayed on the CSX North End A subdivision due to following 40(05) from MP 44.9 to MP 22.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
80(06)	38"	

Train 2152(06) New Haven, CT - Engine Failure

06JUL26: Legacy Train 2152(06) set 9 PC/2035, PC/2039 crew reported the hot journal no exceptions however they cut out the ITSU on PC/2035 due to faults. They were limited to 80MPH into Boston.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2152(06)	39"	

Train 131(06) New York, NY - Engine Failure

06JUL26: Train 131(06) was delayed departing New York due to turning off 112(06) and adding E/663.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
131(06)	41"	

Train 181(06) Newark, NJ - Engine Failure

06JUL26: Train 181(06) with E/622, E/623 and 9 cars was delayed on the New York to Philadelphia main line at Newark station due to losing traction power on lead E/622. The crew inspected the equipment and found loose communication hose. They were able to tighten the hose and proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
181(06)	32"	

Train 41(04) Jacksonville, FL - Engine Failure

06JUL26: Train 41(04) with E/337, E/14 and 10 cars was delayed operating from Hamlet to Jacksonville with PTC cut out and restricted to 59MPH. Upon arrival into Jacksonville the crew attempted to make repairs and initialize PTC but they were unsuccessful. It was determined they had to flat switch the engines. The crew was having problems due to the cables being too short to restore HEP crew was speaking with CNOC mechanical for assistance and was able to get a longer 480V cable.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(04)	3'09"	

CSX Heat Orders - Weather

06JUL26: Multiple trains were affected by CSX heat orders that were in place from 1300-1900 on the following subdivisions Kanawha, North End, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
98 (06)	40"	
125 (06)	24"	
53 (26)	29"	
95 (06)	05"	
90 (06)	26"	
89 (06)	49"	
80 (06)	41"	
52 (06)	14"	
138 (06)	20"	
97 (05)	33"	
40 (05)	28"	
20 (05)	02"	

Train 41(03) South of Sebring, FL - Freight Train Interference

06JUL26: Train 41(03) was delayed on the CSX Auburndale SX at MP 892.8 due to meeting CSX 452-06.

Train	Delay	Comment
41 (03)	1'32"	

New Haven to Boston main line- Tree in Wire/Catenary or Wayside Failure

06JUL26: At 613A-ET, Boston Chief reported that there was a tree in the wire on fire at MP 99.64 on the New Haven to Boston Main Line. ET supervisor was enroute. As of 623A-ET, ET Supervisor reported he was on scene and there was messenger wire down on track 1 and fouling track 2. There was no overhead catenary power between MP 90.4/Guilford and MP 101.2/Westbrook. As of 724A-ET Several trains were being held at stations for open track. As of 917A-ET, Boston Chief reported that track 2 should be returned in 20-30". It is heavy rain in the area making the process take longer. As of 943A-ET Boston Chief reported that track 2 between Guilford and Saybrook was restored. As of 258P-ET, Overhead Catenary was restored on track 1 between Guilford and Saybrook.

Train	Delay	Comment
2155 (06)	1'27"	KIN
2190 (06)	2'34"	NHV
66 (05)	2'25"	NHV
190 (06)	14"	NHV
2151 (06)	3'04"	OSB
3 CDOT'S	TERM	1604, 1637, 1606
1 CDOT	49"	1633
1 CDOT	BUS	1610
95 (06)	1'44"	OSB
171 (06)	32"	KIN
2150 (06)	09"	
2159 (06)	12"	
2165 (06)	1'32"	late turn off 2190 (06)
2118 (06)	1'46"	LATE TURN OFF 2155 (06)
2128 (06)	45"	Turn off 2165 (06)
2131 (06)	44"	Turn off 2118 (06)

Train 183(06) New York, NY - Late Turn of Equipment/Servicing

06JUL26: Train 183(06) was delayed departing New York due to the late turn off 128(05) that arrived at 312A-ET 2 hours and 28 minutes late.

Train 130(06) Washington, DC - Engine Failure

06JUL26: Train 130(06) was delayed departing Washington to the late release of E/661 from the yard.

Train	Delay	Comment
130(06)	45"	

Train 98(05) Washington, DC - Holding for Engine /Servicing

06JUL26: Train 98(05) was delayed departing Washington due to holding for E/644.

Train	Delay	Comment
98(05)	54"	

Train 19(05) Greensboro, NC - Recrew Engineer/System

06JUL26: Train 19(05) was delayed on the NS Danville District at Greensboro station due to holding for a recrew engineer.

Train	Delay	Comment
19(05)	1'48"	

Charlotte, NC - NS Freight Train Derailment

05JUL26: NS reported that NS freight train 12R derailed at the Charlotte, NC station on the NS Charlotte District. NS reported five cars derailed and were blocking both main tracks. NS personnel were on scene. There was an open route thru the yard and trains 20(04) and 19(04) were able to operate with NS Pilots. Both trains also had to shove

Train 80(05) is cancelled in its entirety due to no clear route. Train 79(05) was terminated in Raleigh.

Train 71(05) was terminated at Kannapolis and was attempting to source buses from Kannapolis to Charlotte. Train 71(05) equipment deadhead from Kannapolis to Charlotte and was routed thru the yard with NS Pilots for train 78(05).

Service recovery was enacted for Train 19(04) consisting of snack packs, bottled water, coffee, and tea for all coach customers. Lunch was extended for first class customers. Dominos Pizza was ordered in Atlanta to be distributed.

UPDATE: Train 80(06) will operate normal and train 79(06) will originate Raleigh to Charlotte. As of 450P-ET main 2 was open and NS estimates main 1 to be open around 630P-ET.

WBS#: B.TR.100150.6856

Train	Delay	Comment
20(04)	1'19"	
80(05)	CANCELLED	
79(05)	TERM RGH	
71(05)	TERM KAN	BUS KAN -CLT
19(04)	47"	
80(06)		OPERATING NORMAL
79(06)		ORIG RGH-CLT

Train 40(01) South of Hamlet, NC - Engine Failure

02JUL26: Train 40(01) 26-FP-00580 00000008157 UNCLASSIFIED 305/2026, 10 cars and 197 customers onboard was delayed 8 miles south of Hamlet at MP 266 on the CSX Hamlet subdivision due to locomotive E/305 experiencing mechanical issues with an I/O Station 45 Fault. The crew trouble shot the locomotive with CNOC Mechanical and were advised to advance to HAM and recycle the locomotive while making the crew change. Trail locomotive E/316 was able to supply HEP and tractive effort for the duration of the troubleshooting.

At Hamlet, the crew recycled the locomotive and were able to clear the stored I/O Station 45 fault allowing e/305 to restore tractive effort. After recycling the locomotive train 40(01) was able to proceed.

After departing Hamlet train 40(01) stopped again at MP 238 when the I/O Station fault returned. The crew working with CNOC Mechanical proceeded to set locomotive E/305 up as a control stand and have E/316 supply all tractive effort and HEP. After reconfiguring the locomotive train 40(01) was able to resume operation. At Raleigh, an Amtrak Road Foreman assisted the crew with replacing the comm and m/u cables between the locomotives to attempt to regain the communication between both units.

03JUL26: Train 40(01), E/305-E/316-9 Cars, was delayed at Pittsburgh, PA (MP353.1), on the NSRR Pittsburgh Line, due to cab signals issues. Permission was granted by Norfolk Southern to cutout cab signals in order to continue west. Service recovery was enacted due to lateness with complimentary coffee, tea, bottled water, coffee cakes, muffins, and bagels for breakfast then beef stew for lunch for all coach customers. First class customers received breakfast as normal from the dining car and a modified lunch service with cheeseburgers, artisan sandwiches, and hot dogs.

Train 41(02) was held 2 miles west of Pittsburgh, PA, on the NSRR Pittsburgh East Line at Penn (MP1.8) while waiting for Train 40(01) to clear the station track.

04JUL26: Train 41(03) was delayed departing Chicago, IL, due to the late turn of Train 40(01)'s equipment, which arrived at 9:40PM-CT, operating 12 hours and 55 minutes late. Additionally, sleeper car 62022 and diner car 68007 were bad ordered for HVAC failures and deadheaded in the consist without replacement equipment. As a result, affected sleeper customers were downgraded to coach accommodations, and all food service was provided from the Lounge car. Service recovery measures were implemented due to the extended delay. Coach customers received complimentary coffee, tea, snack packs, and bottled water, while first-class customers received breakfast meal service from the Lounge car. At 6:15AM-CT, Train 41(03) departed Chicago, IL, operating 11 hours and 35 minutes late. An additional 13-minute delay was incurred en route when the train was required to wye after departure. Service recovery continued in route with complimentary pizza and bottled water for dinner for the coach customers. First class customers received dinner (CMP meals) served from the dining car.

05JUL26: Train 40(06) was cancelled entirely with no alternate provided due to the late inbound Train 41(03)

WBS#: B.TR.100150.6845

Train	Delay	Comment
40(01)	29"	CAM-HAM
40(01)	44"	HAM-HAM
40(01)	38"	HAM-SOP
40(01)	14"	SOP-CYN
40(01)	1'05"	RMT-PTB
40(01)	41"	WAS
40(01)	52"	PGH
41(02)	44"	Penn
41(03)	13"	Wye
41(03)	11'35"	ITD CHI
40(06)	Cancelled Entirely	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00580a 00000008157 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
66 (6)	RNK	NS9934	E/310 hydraulic oil leak		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Western Region

Operating Highlights

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train 6(05) Denver, CO - System

06JUL26: Train 6(05) arrived Denver at 1218AM-MT and was delayed departing Denver due to the outbound crew signing up at 100AM-MT. Once the crew signed up, briefed, and boarded the train, 6(05) departed Denver at 144AM-MT, 6 hours, and 45 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(05)	54"	

Train 19(05) South of Meridian, MS - Freight Train Interference

06JUL26: Train 19(05) with 95 customers was delayed on the NS NO&NE district at Basic/MP 13.3 due to being tucked in the siding behind 131-06, who ran out of fuel. Train 19(05) met A01-06 at Basic and then shoved out and continued to Laurel.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(05)	1'15"	

Train 19(05) Meridian, MS - Servicing

06JUL26: Train 19(05) with 95 customers was delayed departing Meridian on the NS NO&NE district due to routine inspections. Train 19(05) departed Meridian at 1047PM-CT, 6 hours, and 28 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(05)	33"	

Train 538(06) East of Rocklin, CA - Wayside Detector Actuation

06JUL26: Train 538(06), operating with CC/C8302, four cars, locomotive E/C2012, and 12 customers onboard, was delayed on the Union Pacific Roseville Subdivision after activating the high-wide detector at MP 111.0. The crew stopped and conducted an inspection, finding no apparent defects or abnormalities. However, operating rules required a Union Pacific carman to inspect the train before it could proceed. A UP carman responded from Roseville and performed a thorough inspection, likewise finding no exceptions. Once the inspection was complete and the train was determined safe for operation, Train 538(06) was cleared to proceed through the tunnel and continued its trip without further incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
538(06)	1'11"	

Train 22(06) North of Marshall, TX - Freight Train Interference

06JUL26: Train 22(06) with 155 customers was delayed on the UPRR Little Rock subdivision starting 20 miles north of Marshall stopped behind MLDNL-05 at Payne/MP 44.3, who was inspecting a hot wheel. There were no exceptions taken to the hot wheel and 22(06) followed MLDNL-05 to Sulphur/MP 8.7.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(06)	48"	

Train 704(06) North of Stockton, CA - Freight Train Derailed

06JUL26: At approximately 06:16 on 07/06/26, Train 704(06), carrying 75 customers onboard, was stopped between Lodi, CA and Stockton ACE Station on the Union Pacific Fresno Subdivision due to a UP freight train (IOANP-06 with UP 8100 leading) derailment ahead at MP 82.65. Initial reports indicated one locomotive had derailed and damaged the track structure, requiring a response from a Union Pacific Track Inspector and the ordering of recovery equipment.

To accommodate customers, Train 704(06) was shoved back to Lodi Station, where two buses were secured to transport passengers to Stockton ACE Station and then onward to Stockton Amtrak Station, where Train 718(06) was used to provide continued service to Bakersfield, CA.

As a result of the derailment and track outage, Train 703(06) was terminated at Merced, CA, with customers transported by chartered bus from Merced to Sacramento. The equipment from Train 703(06) was then turned and operated as Train 704(06) between Merced and Bakersfield. Meanwhile, the original Train 704(06) equipment at Lodi was repositioned back to Sacramento to protect the following day's service schedule.

WBS#: B.TR.100150.6863

Train	Delay	Comment
704(06)	Cancel LOD-MCD	
718(06)	52"	SKN - pick up 704 customers
703(06)	Term MCD	
704(06)	2'22"	Customer delay from stop to boarding 718(06)
704(06)	1'08"	MCD-BFD section fueling S/ FNO

Train 4(05) East of Trinidad, CO - Temporary Speed Restrictions

06JUL26: Train 4(05) with 240 customers was delayed on the BNSF Raton subdivision starting 31 miles east of Trinidad between MP 605.0 and MP 581.9 due to temporary speed restrictions. Train 3(05) with 166 customers was delayed for the same reason.

Train	Delay	Comment
4(05)	30"	
3(05)	27"	

Train 26(06) East of Bay Saint Louis, MS - Freight Train Interference

06JUL26: Train 26(06) with 90 customers was delayed on the CSX NO&M subdivision between Bay St. Louis/MP 754.48 and MP 674.0 due to following M606-06.

Train	Delay	Comment
26(06)	1'05"	

Train 364(06) East of Battle Creek, MI - Temporary Speed Restrictions

06JUL26: Train 364(06) was delayed on the CN Flint subdivision starting one mile east of Battle Creek due to temporary speed restrictions between MP 176.86 through MP 202.45.

Train	Delay	Comment
364(06)	36"	

Train 355(06) East of Jackson, MI - Debris

06JUL26: Train 355(06) delayed holding at Jackson station/MP 37.5 due to a tree reported in a power line at MP 67.7 in the vicinity of the tracks. Consumers energy was on scene. NS B25 operated through the area at restricted speed and reported no obstructions. The track department cleared train movement for track speed. Train 352(06) was held at Jackson station/MP 75.5 and operated through the area once NS B25 was in the clear. Train 355(06) advanced to Chelsea/MP 56.0 and met train 352(06).

Train	Delay	Comment
355(06)	26"	ARB
352(06)	25"	JXN
355(06)	17"	Meet 352(06)
352(06)	11"	Follow NS to CP 72
352(06)	10"	Meet 355(06)

Train 41(06) Chicago, IL - Initial Terminal Delay

06JUL26: Train 41(06) with 275 customers was delayed departing Chicago due to late makeup and door bypass issues. The door bypass was cutout. Once the equipment was set in the station, the customers were welcomed aboard, and 41(06) departed Chicago at 710PM-CT, 30 minutes late.

Train	Delay	Comment
41(06)	30"	

Train 538(06) South of Hayward, CA - Fire by Tracks

06JUL26: Train 538(06), carrying 61 customers onboard, was delayed while holding north of Santa Clara-Great America Station at Newark (MP 31.4) on the Union Pacific Coast Subdivision due to a grass fire on the Union Pacific Niles Subdivision near MP 24.7, north of Fremont, CA. The fire resulted in a suspension of rail traffic through the affected area. Local fire departments responded; however, firefighting efforts were prolonged after responding crews reportedly exhausted available water supplies.

To mitigate delays, Train 538(06) was rerouted via the Coast Subdivision, bypassing the Fremont and Hayward station stops. Customers were offered mutual-aid transportation via BART, which honored Capitol Corridor tickets between Oakland Coliseum Airport Station and Berryessa/North San José Station.

Train 542(06) was also rerouted over the Coast Subdivision. Train 543(06) was initially unable to use the detour because its engineer was not qualified on the Coast route and was held at Elmhurst (MP 13.1) on the Niles Subdivision, just south of Oakland Coliseum. At a scheduled meet with Train 542(06), the engineers exchanged trains, allowing Train 543(06) to continue via the Coast Subdivision toward San José.

Train 544(06) was held at Newark (MP 31.3) pending an operating plan. It was ultimately routed over its normal alignment, making the scheduled stops at Fremont and Hayward.

As part of the service-recovery effort, all affected trains offered a 20% café discount to customers impacted by the disruption.

Train	Delay	Comment
538(06)	38"	Bypass FMT & HAY
542(06)	16"	Bypass FMT & HAY
543(06)	51"	Bypass FMT & HAY
544(06)	35"	

Train 383(06) Chicago, IL - Car Failure

06JUL26: Due to no available equipment at the time of the incident, a mechanical bad ordering the married pair replacement ID4212-4104 for 370(06). As a result, train 383(06) and 380(07) were cancelled entirely with this trainset utilized to operate train 370(06). Two buses were secured as alternate transportation for train 383(06) and two buses were sourced as alternate transportation for train 380(07). Trains 370(06) and 371(07) operated without food service.

WBS#: B.TR.100150.6862

Train 352(06) West of Michigan City, IN - System

06JUL26: Train 352(06) with E/319, five cars, and 235 customers was delayed on the Amtrak Michigan Line 10 miles west of Michigan City at CP 239 due to ITCS issues on E/319. The crew continued two miles east of Michigan City to CP 226 where ITCS was cut out and the crew was required to continue not exceeding 59mph per rule.

Train	Delay	Comment
352(06)	1'04"	

Train 3(06) West of Naperville, IL - Freight & Passenger Train Interference

06JUL26: Train 3(06) was delayed at Montgomery/MP41.4, 11 miles west of Naperville, IL, on the BNSF Mendota Subdivision, meeting Train 4(04) and eastbound freight traffic due to BNSF single tracking ahead between Bristol/MP45.8 and Electrics/MP80.5. Train 5(06) was delayed meeting BN 5188 at Aurora/MP 38.4, BN 6019 at Montgomery/MP 40.2, and following train 3(06) between Bristol/MP 45.8 through Zearings/MP 95.4.

Train	Delay	Comment
5(06)	40"	PTI
5(06)	33"	FTI
3(06)	36"	PTI
3(06)	51"	FTI

Train 14(05) North of Eugene, OR - Signal

06JUL26: Train 14(06), with 236 customers, was delayed between Swain / MP 659.1 and Alford / MP 667.6 on the Union Pacific Brooklyn Subdivision, starting 13 miles north of the Eugene, OR station, account of signal failure. The train crew was flagged through the area.

Train 503(06), with 81 customers, met MRVPT-05 (UPRR 7964) before traversing the signal failure.

Train	Delay	Comment
14(05)	20"	
503(06)	36"	

Train 714(06) Originate Emeryville, CA - Third Party Contractor Cab Car Failure

06JUL26: Train 714(06) originated with "UNCLASSIFIED" C8310 cars and Locomotive C2014, originated in Emeryville, CA account a late release of equipment from the Oakland Maintenance Facility. Cab Car C8310 experienced a bad end door seal and gauge issues. To minimize customer impact, the decision was made to originate Train 714(06) at Emeryville, CA.

The (20) affected customers at Oakland, CA were accommodated on Train 532(06) to Emeryville.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(06)	49"	ORIG EMY

Train 6(04) East of Princeton, IL - Freight Train Interference

06JUL26: Train 6(04) was delayed east of Princeton, IL/MP104.3, on the BNSF Mendota and Chicago Subdivision, following eastbound BNSF traffic between Samonauk/MP59.6 and Eola/MP35.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	30"	

Train 20(06) Late Departure New Orleans, LA - Turn of Equipment

06JUL26: Train 20(06), with 172 customers, was delayed departing New Orleans, LA, due to late turn of equipment off Train 19(04) which arrived at 439AM-CT, 7 hours and 27 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(06)	4'00"	

Train 4(05) East of Lamy, NM - Passenger Train Interference

06JUL26: Train 4(05) was delayed on the BNSF Glorieta subdivision 14 miles east of Lamy at Fox/MP 820.0 due to meeting train 3(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(05)	1'00"	

Train 1(06) North of New Orleans, LA - Signal and Switch Issues

06JUL26: Train 1(06), with 128 customers, was delayed beginning 4 miles north of New Orleans, LA, on the NOPB and UPRR Livonia Subdivision, due to power switch failure at East Bridge/MP3 and wayside PTC issues at West Bridge/MP10.2. Train 1(06) was delayed at East Bridge due to crew hand lining switches. Train 1(06) was further delayed at West Bridge due to the wayside PTC issues, PTC engaged but issues with a red fence. Crew contacted UPRR PTC and was able to proceed through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(06)	45"	MP3
1(06)	47"	MP10

Nationwide Positive Train Control Outage

06JUL26: At approximately 12:42 PM-EDT, "UNCLASSIFIED" cross-tie network experienced issues initializing Positive Train Control. Following an investigation, the issue was identified and resolved by Wabtec, which restored service by resetting the affected application. PTC was fully restored at 1:25 PM-EDT.

Train	Delay	Comment
97 (05)	51"	FLO
11 (05)	04"	SJC
5 (04)	58"	RNO
712 (06)	17"	OKJ
770 (06)	33"	LAX
350 (06)	25"	
281 (06)	42"	

Train 23(06) South of Bay Saint Louis, MS - Freight Train Interference

06JUL26: Train 23(06), with 107 customers, was delayed at Nicholson/MP756.3, 2 miles south of Bay Saint Louis, MS, on the CSX NO and M Subdivision, due to L800 switching ahead. Train 23(06) was delayed holding for L800 to complete switching move and then delayed meeting L800 and Train 24(06). Train 24(06), with 76 customers, was delayed following L800 between MP766.3 and MP745.1.

Train	Delay	Comment
23 (06)	1'14"	
24 (06)	1'16"	

Train 22(06) North of San Antonio, TX - Engine Issue

06JUL26: Train 22(06), E/315-E/171 & 6 cars, with 111 customers, was delayed at MP242.8, 19 miles north of San Antonio, TX, on the UPRR Austin Subdivision, due to hot bearing actuation on E/315 axle 3 fireman's side. Crew inspected and reported sticking brake on E/315, no other exceptions reported. The crew was in contact with mechanical and Amtrak road foreman was onboard. Train 22(06) advanced to MP231 to be met by Amtrak mechanical. Mechanical had difficulties releasing the brake and had to obtain additional tool from nearby hardware store to assist. Mechanical was then able to resolve the issue and Train 22(06) was able to proceed north.

Train	Delay	Comment
22 (06)	2'11"	

Train 504(06) Albany, OR - Freight Train Interference

06JUL26: Train 504(06) was delayed between Shedd / MP 679.2 and Hito / MP 740.9 on the Union Pacific Brooklyn Subdivision, starting 12 miles south of the Albany, OR station, following ZLCTM-05 (UPRR 5924). The freight train had actuated a wayside detector at MP 681.0 requiring the freight crew to inspect their equipment.

Train	Delay	Comment
504 (06)	29"	

Train 351(06) Detroit, MI - Engine Failure

Train 351(06), E/IDTX4613 & 50000008157, with 130 customers, was delayed at Detroit, MI/MP53.8, on the CN Shore Line, due to E/IDTX4613 with IO43 faults and no HEP. The weather was approximately 70 degrees and clear. Passengers had access to the Detroit station during this time. Mechanical forces responded from Pontiac to assist and Amtrak road foreman also responded. After troubleshooting mechanical was able to restore HEP.

Due to concerns over engine reliability, Train 351(06) advanced to Dearborn, MI/MP9.7, on the MDOT Michigan Line, and held for Train 353(06) to arrive and couple ahead. Train 353(06) and 351(06) operated combined to Chicago, IL. A mechanical rider remained onboard. Train 351(06) passengers were give the option to remain on the late combo train or to be reaccommodated on alternate bus transportation. Five busses were secured as available alternate transportation as follows: Bus 1: Ann Arbor to Chicago express. Bus 2: Dearborn-Ann Arbor-Chicago. Bus 3: Dearborn-Chicago. Bus 4: Dearborn-Jackson-Chicago. Bus 5: Dearborn to Chicago making all scheduled stops.

Train 350(06) was delayed at Kalamazoo, MI/MP143.4, on the MDOT Michigan Line, holding for outbound recrew to arrive in Battle Creek, MI. Train 350(06) was delayed at Battle Creek, MI, due a systemwide PTC issue and due to a CN trespasser strike just east of Battle Creek. At 127PM-ET, CN Z14931-05 struck a trespasser just east of Battle Creek, MI/MP175.74, on the CN South Bend Subdivision. The trespasser was not a fatality. Train 350(06) held at Battle Creek and Train 353/351(06) combo held at CP-Baron/MP176.7 for open route ahead. Due to the late operation of Train 350(06), the following service adjustments were in effect:

- Train 350(06) terminated at Detroit, MI, with one bus as alternate transportation between Detroit and Pontiac, MI. Equipment was then positioned at Dearborn, MI, for the origination of Train 355(06).

- Train 355(06) originated at Dearborn, MI, with two busses secured as alternate transportation between Pontiac and Dearborn.

Train 354(06) was delayed departing Chicago, IL, due to late turn of equipment off Train 353/351(06) combo and necessary to cut the 351(06) section from rear.

WBS B.TR.100150.6859

WBS#: B.TR.100150.6859

Train	Delay	Comment
351(06)	1'34"	DET
350(06)	1'19"	KAL
350(06)	Terminated	DET
350(06)	2'19"	BTL
353(06)	1'19"	DER, couple a/h of 351(06)
353/351(06)	43"	E/BTL, CN trespasser strike
354(06)	2'00"	CHI, late turn of equipment
354(06)	13"	CHI - wye on outbound
355(06)	2'05"	Originated DER

Train 6(05) - West of Salt Lake City, UT - Police Related

06JUL26: Train 6(05), with 135 customers, was delayed at MP 783.8 on the Union Pacific Lynndyl Subdivision, 1 mile west of the Salt Lake City, UT station, account local police placed a hold on rail traffic just ahead. They had been in pursuit of a suspect near the tracks.

Train	Delay	Comment
6(05)	58"	

UPRR Jefferson City Subdivision - Severe Weather

04JUL26: Due to extreme weather on the UPRR Jefferson City subdivision, between Jefferson City, MO and Hermann, MO. UPRR dispatched Maintenance of Way personnel to remove downed trees from several locations. UPRR personnel reported downed wires in several locations as well. While enroute to the original reported locations of the downed trees, MOW kept finding other trees on the tracks that needed to be removed. Train 316(04) held at Jefferson City, MO for an open route and train 319(04) was initially held East of Hermann, MO and then West of Hermann, MO. Due to the extended delay buses were secured to accommodate customers. Buses arrived at a crossing 1 mile east of Jefferson City for train 316(04) at approximately 2:50am-ct and all customers were safely transferred to buses. Amtrak Road Foreman arrived on location of 319(04) at approximately 3:50am-ct as well as the buses. At 3:45am-ct, UPRR reported that there was an 11 mile stretch with 40 trees across the tracks that required heavy equipment to remove. As a result the following service adjustments have been made:

- Train 316(04) was terminated at Jefferson City, MO with alternate buses provided.
- Train 319(04) was terminated at Hermann, MO with alternate buses provided.

05JUL26: At 10:00AM-CT, Main Track 1 was returned to service for 316(04) and 319(04)'s equipment to deadhead to their destination. At 12:30PM-CT, Main Track 2 was returned to service. Due to heavy freight interference from tied down equipment and lack of staffing, additional service adjustments were set in place:

- Train 311(05) was cancelled entirely with no alternate buses provided.
- Train 316(05) was cancelled entirely with three alternate buses provided.
- Train 318(05) originated at St. Louis, MO with no alternate buses provided. Inbound Train 319(05)'s equipment was turned at St. Louis to represent Train 318(05) which resulted in a departure delay.
- Train 319(05) terminated at St. Louis, MO with 8 buses secured between St. Louis and Kansas City.

06JUL26: UPRR advised that signal power issues and freight train interference continued on the Jefferson City subdivision between Jefferson City and Washington with one train tied down and flagging between MP 73.0 and MP 124.0. As a result, the following service adjustments were implemented:

- Train 311(06) was cancelled entirely with three alternate buses between St. Louis and Kansas City.
- Train 316(06) was cancelled entirely with one bus as alternate transportation between Kansas City and St. Louis.
- Train 319(06) terminated at St. Louis, with three busses as alternate transportation between St. Louis and Kansas City.
- Train 318(06) originated at St. Louis off train 319(06) equipment. No available alternate transportation.

It was necessary for Chicago to add an additional locomotive to send to St. Louis to fill out service for the Missouri River Runner service on July 7 due to E/ID4609 shopped for multiple faults and deadhead in trail back to Chicago on train 302(06).

07JUL26: UPRR reported improved conditions on the Jefferson City subdivision with some locations remaining on generator power with sporadic track lights and PTC issues. Amtrak planned to resume full service on the route.

WBS#: B.TR.100150.6855

Train	Delay	Comment
311(05)	Cancelled	
318(06)	36"	STL, turn of equipment off 319(06)
319(05)	Terminated STL	
316(05)	Cancelled	
316(04)	Terminated JEF	
319(04)	Terminated JEF	
318(05)	32"	STL, turn of equipment off 319(05)

to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. CN performed track inspections between Carbondale and New Orleans and no track defects were identified. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow the location of the issue. CN train inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

06JUL26: City of New Orleans service adjustments were updated as follows:

- Train 59(07) operated normal, Chicago, IL to New Orleans, LA.
- Train 58(07) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(08) cancelled entirely, no alternate transportation between Chicago and New Orleans.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated	JAN
58(27JUN-07JUL)	Cancelled	
59(27JUN-06JUL, 08JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located at mile 588.2 on the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL)	00"	BYPASS PSN
1 (01, 04JUL) / 421 (03JUL)	00"	BYPASS PSN

Maintenance of Way Highlights

BNSF Track Work West of Macomb, IL - Carl Sandburg Service

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th. To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL) and Train 382(13JUL-17JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL) and Train 381(13JUL-17JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has a replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
59 (29)	JAN	62		Wheels

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 318(06) Passenger Removal Bloomington-Normal, Illinois – Improper Conduct

06JUL26, Passenger on, PNR 7FD4E0 traveling from Saint Louis, MO to Chicago, IL reportedly passenger became aggressive when advised there were no smoke breaks. The Conductor made the decision to have the passengers removed at Bloomington-Normal, IL as the passenger was detained, he assaulted the Conductor with his bag. Local authorities were contacted but did not arrive on scene. Amtrak Police notified

Delay: 318 (06) 06"

Consist Deviations

26-FOI-00580

00000008157

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
93 (06)	BOS	43394 CAFE B/O HAND BRAKE INSPECTION BEST REPLACEMENT 48174 SPLIT CLUB	N/A	0	48174
137 (06)	BOS	SHORT 1 COACH	passengers being reaccommodated to business where available. Passenger notifications being sent for overcap.	71	NOCAR
383 (06)	CHI	383(6) will operate with no cafe or food service	passengers notified no food service.	0	NOCAR
370 (06)	CHI	370(6) NO FOOD SERVICE	Email sent for passengers notifications no food service	0	NOCAR
371 (07)	GRR	371(7) NO FOOD SERVICE	Email sent for passengers notifications no food service	0	NOCAR
600 (06)	HAR	NO CAB CAR, NO WIFI	email sent for passenger notifications	0	9632
622 (06)	HAR	622(06) will operate without a cab car to provide Wi-Fi. No impact to capacity.	NONE	0	
656 (06)	HAR	656(06) will operate with 5 coaches and cafe car to provide Wi-Fi. No available cab car.	NONE	0	43379
564 (06)	LAX	Consist changed again. No bike space, no wifi and reduced capacity due to cab 9700. Notify passengers.	NONE	0	9700
138 (07)	NFK	43394 CAFE B/O HAND BRAKE INSPECTION IN BOS, BEST REPLACEMENT 48174 SPLIT CLUB. ADDITIONALLY BUSINESS CLASS 81511 IN LIEU OF COACH.	NONE	0	43394
651 (06)	NYP	651(06) will operate without a cab car to	NONE	0	

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		provide Wi-Fi. No impact to capacity.			
609 (06)	NYP	609(06) will operate with 5 coaches and cafe car to provide Wi-Fi. No available cab car.	NOINE	0	43379
190 (06)	PHL	SHORT 1 COACH	Passengers reaccommodated to business where available. notification sent for overcapacity	42	NOCAR
380 (07)	QCY	train 380(7) will operate with no cafe or food service	noticfctions sent no food service.	0	NOCAR
777 (06)	SAN	Consist changed again. No bike space, no wifi and reduced capacity due to cab 9700. Notify passengers.	NONE	0	9700
785 (07)	SAN	NO BIKE SPACE OR WIFI	Email sent for passenger notificaton for no bike space and no wifi	5	90215
774 (07)	SLO	NO BIKE SPACE OR WIFI	Email sent for passenger notificaton for no bike space and no wifi	2	90215

Reverse Consists

Train Number	Station	Reason
111 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
113 (06)	NYP	Consist reversed Business class seat orientation may have changed At Rear
183 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
84 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (06)	NYP	Consist reversed Business class seat orientation may have changed At Rear
136 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front
182 (06)	WAS	Consist reversed Business class seat orientation may have changed At

Train Number	Station	Reason
		Rear
129 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
125 (07)	SPG	Consist reversed Business class seat orientation may have changed At Front