



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, July 08, 2026

Rules: 0-36



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/07/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	45	86.1%	2,082	345	83.4%	83,440	11,469	86.3%
Central Division	86.0%	73	8	89.0%	501	53	89.4%	20,540	1,871	90.9%
East Division	82.0%	175	26	85.1%	1,068	206	80.7%	43,629	6,814	84.4%
West Division	86.0%	76	11	85.5%	513	86	83.2%	19,271	2,784	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00590 00000008304 UNCLASSIFIED 7/15/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	103,306	33,915	67%	721,688	296,858	59%	27,669,012	6,771,144	76%
Northeast Corridor	81%	45,790	16,072	65%	301,436	140,148	54%	12,145,217	2,923,341	76%
Acela	83%	10,047	1,546	85%	64,061	28,188	56%	2,400,826	630,865	74%
Northeast Regional	79%	35,743	14,526	59%	237,375	111,960	53%	9,744,391	2,292,476	76%
Richmond / Newport News / Norfolk	77%	12,672	4,227	67%	74,219	41,019	45%	3,024,947	854,640	72%
Springfield Shuttles	89%	685	282	59%	5,111	1,840	64%	173,145	26,054	85%
Roanoke	79%	4,134	2,326	44%	21,693	12,860	41%	914,753	188,145	79%
On Spine Northeast Regional	80%	18,252	7,691	58%	136,352	56,241	59%	5,631,546	1,223,637	78%
State Supported	80%	42,671	8,550	80%	329,663	99,661	70%	12,115,711	2,462,025	80%
Borealis	80%	574	1	100%	4,034	1,134	72%	155,004	31,580	80%
Capitol Corridor	90%	4,037	43	99%	26,068	4,602	82%	1,027,287	133,798	87%
Carolinian	70%	472	0	100%	7,176	4,812	33%	317,150	120,718	62%
Cascades	75%	2,414	308	87%	22,730	6,647	71%	710,374	195,207	73%
Downeaster	82%	1,855	26	99%	12,105	3,897	68%	409,603	49,367	88%
Empire	78%	5,876	2,253	62%	41,634	16,394	61%	1,495,639	330,811	78%
Adirondack	72%	411	122	70%	3,185	1,649	48%	89,618	27,133	70%
Ethan Allen Express	70%	557	509	9%	3,915	2,385	39%	154,880	49,992	68%
Maple Leaf	70%	804	676	16%	6,142	3,036	51%	180,961	69,823	61%
New York - Albany	85%	2,864	581	80%	18,119	5,443	70%	695,284	109,343	84%
New York - Niagara Falls	75%	1,240	365	71%	9,298	3,090	67%	370,757	72,869	80%
Berkshire Flyer	60%	0	0	-	975	791	19%	4,139	1,651	60%
Gold Runner	73%	2,200	995	55%	19,579	7,539	61%	693,199	239,637	65%
Heartland Flyer	70%	174	84	52%	1,951	1,002	49%	57,656	21,495	63%
Hiawatha	90%	1,605	0	100%	13,319	856	94%	471,013	51,404	89%
Illinois	78%	2,392	836	65%	20,082	8,875	56%	682,237	184,919	73%
Carl Sandburg / Illinois Zephyr	85%	255	83	67%	3,609	1,240	66%	113,163	29,046	74%
Illini / Saluki	85%	795	126	84%	6,890	2,694	61%	240,552	56,721	76%
Lincoln Service	70%	1,342	627	53%	9,583	4,941	48%	328,522	99,152	70%
Keystone	92%	7,760	1,015	87%	43,680	9,800	78%	2,100,757	219,735	90%
Lincoln / Missouri	70%	323	134	59%	4,697	2,404	49%	213,216	106,220	50%
Mardi Gras Service	80%	417	236	43%	2,918	1,060	64%	113,866	23,521	79%
Michigan	70%	2,393	928	61%	17,237	9,649	44%	536,984	174,604	67%
Blue Water	70%	461	294	36%	4,052	3,286	19%	124,278	48,620	61%
Pere Marquette	85%	315	0	100%	2,065	491	76%	69,637	13,821	80%
Wolverine	70%	1,617	634	61%	11,120	5,872	47%	343,069	112,163	67%
Missouri	80%	108	98	9%	1,034	181	82%	60,270	13,421	78%
Pacific Surfliner	85%	7,421	717	90%	73,013	11,932	84%	2,155,537	339,094	84%
Pennsylvanian	80%	753	185	75%	6,356	3,036	52%	245,066	45,195	82%
Piedmont	80%	712	283	60%	2,905	1,564	46%	316,290	80,118	75%
Vermont	75%	1,185	408	66%	9,145	4,277	53%	354,563	101,181	71%
Long Distance	70%	14,845	9,293	37%	90,589	57,049	37%	3,368,817	1,383,315	59%
Auto Train	70%	822	0	100%	5,831	810	86%	214,675	71,638	67%
California Zephyr	70%	961	614	36%	7,243	4,202	42%	267,306	89,499	67%
Cardinal	70%	0	0	-	1,729	1,451	16%	65,403	31,693	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,364	49,617	72%
Coast Starlight	70%	1,248	151	88%	8,906	1,832	79%	313,670	106,284	66%
Crescent	70%	1,459	1,315	10%	6,814	5,513	19%	257,307	77,605	70%
Empire Builder	70%	1,386	684	51%	8,771	4,832	45%	261,832	123,584	53%
Floridian	60%	1,963	1,963	0%	10,912	10,865	0%	441,077	294,508	33%
Lake Shore Ltd	73%	1,182	8	99%	8,294	3,792	54%	259,931	75,402	71%
Palmetto	70%	1,483	950	36%	6,386	5,081	20%	254,159	71,179	72%
Silver Meteor	70%	1,738	1,620	7%	7,948	6,795	15%	280,329	116,947	58%
Southwest Chief	60%	1,105	966	13%	7,219	5,185	28%	225,869	143,597	36%
Sunset Ltd	70%	410	139	66%	2,351	1,232	48%	80,736	27,913	65%
Texas Eagle	70%	1,088	883	19%	8,185	5,459	33%	269,159	103,849	61%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00590 00000000004 "UNCLASSIFIED" 7/15/2020

Train Index Dates Through July 07, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	53,533	712,860	751	1,620,804	29,350,508	552

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,837	201,380	141	76,216	8,418,723	91
INFRASTRUCTURE PLANNED	135	2,928	201,380	145	81,886	8,418,723	97
FLEET RELIABILITY	90	10,604	712,860	149	263,639	29,350,508	90
TRAIN OPERATIONS	424	37,164	712,860	521	1,199,063	29,350,508	409

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/07/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	45	86.1%	2,082	345	83.4%	83,440	11,469	86.3%
Central Division	86.0%	73	8	89.0%	501	53	89.4%	20,540	1,871	90.9%
East Division	82.0%	175	26	85.1%	1,068	206	80.7%	43,629	6,814	84.4%
West Division	86.0%	76	11	85.5%	513	86	83.2%	19,271	2,784	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/07/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	45	86.1%	2,082	345	83.4%	83,440	11,469	86.3%
Central Division	86.0%	73	8	89.0%	501	53	89.4%	20,540	1,871	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	14	0	100.0%	531	18	96.6%
CHI	86.0%	28	2	92.9%	184	21	88.6%	7,423	885	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	14	0	100.0%	550	52	90.5%
FTW	92.5%	1	0	100.0%	7	1	85.7%	303	35	88.4%
GBB	-	1	1	0.0%	2	2	0.0%	3	3	0.0%
GRR	95.5%	1	0	100.0%	6	0	100.0%	265	8	97.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	2	0.0%	10	2	80.0%	548	42	92.3%
LAX	89.5%	1	0	100.0%	7	1	85.7%	269	41	84.8%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	41	3	92.7%	1,639	100	93.9%
MOE	97.5%	2	0	100.0%	14	1	92.9%	559	9	98.4%
MSP	96.5%	1	0	100.0%	7	0	100.0%	273	5	98.2%
NOL	94.5%	3	1	66.7%	24	5	79.2%	1,174	58	95.1%
OKC	97.0%	1	0	100.0%	7	0	100.0%	274	6	97.8%
PDX	86.0%	4	0	100.0%	28	3	89.3%	1,110	110	90.1%
PNT	88.0%	3	1	66.7%	20	3	85.0%	723	61	91.6%
PTH	93.0%	1	0	100.0%	7	1	85.7%	268	11	95.9%
QCY	91.0%	-	-	-	11	0	100.0%	541	39	92.8%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	7	0	100.0%	276	27	90.2%
SEA	85.0%	7	1	85.7%	49	7	85.7%	1,939	214	89.0%
STL	89.0%	4	0	100.0%	28	3	89.3%	1,085	93	91.4%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	14	0	100.0%	544	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	26	85.1%	1,068	206	80.7%	43,629	6,814	84.4%
ALB	88.5%	8	0	100.0%	54	2	96.3%	2,068	163	92.1%
BON	87.5%	5	0	100.0%	34	7	79.4%	1,346	147	89.1%
BOS	85.5%	17	2	88.2%	111	9	91.9%	4,751	571	88.0%
BRK	92.5%	5	1	80.0%	34	7	79.4%	1,335	91	93.2%
BTN	82.0%	1	0	100.0%	7	0	100.0%	266	39	85.3%
CLT	91.5%	5	0	100.0%	21	4	81.0%	1,362	136	90.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	14	2	85.7%	545	52	90.5%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/07/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	45	86.1%	2,082	345	83.4%	83,440	11,469	86.3%
East Division	82.0%	175	26	85.1%	1,068	206	80.7%	43,629	6,814	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	13	1	92.3%	67	8	88.1%	3,090	514	83.4%
HFD	-	2	0	100.0%	8	1	87.5%	155	9	94.2%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	7	0	100.0%	276	34	87.7%
MIA	89.5%	2	1	50.0%	13	3	76.9%	552	63	88.6%
MTR	79.0%	1	0	100.0%	7	2	71.4%	263	48	81.7%
NFK	84.5%	2	0	100.0%	14	6	57.1%	635	115	81.9%
NFL	93.5%	2	0	100.0%	14	1	92.9%	564	23	95.9%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	33	3	90.9%	1,439	226	84.3%
NPN	93.0%	2	0	100.0%	12	2	83.3%	525	37	93.0%
NYP	75.5%	50	17	66.0%	299	86	71.2%	11,353	2,547	77.6%
PGH	93.0%	1	0	100.0%	7	2	71.4%	278	21	92.4%
PHL	48.0%	5	2	60.0%	33	15	54.5%	1,433	692	51.7%
PIT	76.0%	-	-	-	2	2	0.0%	8	7	12.5%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	4	0	100.0%	14	1	92.9%	1,071	42	96.1%
RNK	83.5%	2	0	100.0%	14	4	71.4%	548	81	85.2%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	7	0	100.0%	266	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	273	10	96.3%
SFA	88.0%	1	0	100.0%	7	0	100.0%	276	37	86.6%
SPG	92.5%	5	0	100.0%	39	1	97.4%	1,691	93	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	7	0	100.0%	266	56	78.9%
WAS	84.0%	31	2	93.5%	183	37	79.8%	6,779	878	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	76	11	85.5%	513	86	83.2%	19,271	2,784	85.6%
ARN	92.0%	1	0	100.0%	7	2	71.4%	278	21	92.4%
BFD	79.0%	7	1	85.7%	46	15	67.4%	1,732	356	79.4%
EMY	72.0%	1	0	100.0%	7	3	57.1%	283	87	69.3%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	21	5	76.2%	837	119	85.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/07/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	45	86.1%	2,082	345	83.4%	83,440	11,469	86.3%
West Division	86.0%	76	11	85.5%	513	86	83.2%	19,271	2,784	85.6%
LAX	89.5%	9	0	100.0%	66	5	92.4%	2,480	241	90.3%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	5	61.5%	80	28	65.0%	2,979	764	74.4%
PDX	86.0%	1	0	100.0%	7	0	100.0%	262	59	77.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	3	81.3%	104	13	87.5%	3,908	423	89.2%
SAN	90.5%	13	0	100.0%	91	7	92.3%	3,335	301	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	0	100.0%	7	2	71.4%	259	105	59.5%
SJC	89.0%	7	1	85.7%	49	5	89.8%	1,956	187	90.4%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	21	1	95.2%	600	61	89.8%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	7	0	100.0%	273	20	92.7%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	76	3	1	66.7%	118	26	78.0%	3	1	66.7%	115	21	81.7%
3		7	0	100.0%	278	54	80.6%	7	1	85.7%	276	118	57.2%
4		7	0	100.0%	277	42	84.8%	7	4	42.9%	277	183	33.9%
5		7	1	85.7%	276	44	84.1%	6	3	50.0%	272	66	75.7%
6	371	7	3	57.1%	275	80	70.9%	7	5	28.6%	275	87	68.4%
7		7	1	85.7%	267	36	86.5%	7	1	85.7%	260	62	76.2%
8	63	7	2	71.4%	267	113	57.7%	7	4	42.9%	266	153	42.5%
11		7	2	71.4%	278	52	81.3%	7	0	100.0%	272	54	80.1%
14		7	1	85.7%	279	42	84.9%	7	0	100.0%	277	83	70.0%
19	38	7	5	28.6%	277	70	74.7%	7	7	0.0%	275	66	76.0%
20	134	7	4	42.9%	277	22	92.1%	7	6	14.3%	277	53	80.9%
21	51	7	0	100.0%	274	22	92.0%	7	5	28.6%	273	67	75.5%
22	76	7	0	100.0%	275	25	90.9%	7	4	42.9%	273	66	75.8%
23	37	7	1	85.7%	280	6	97.9%	7	4	42.9%	278	73	73.7%
24	53	7	1	85.7%	280	15	94.6%	7	3	57.1%	279	46	83.5%
25		7	0	100.0%	279	3	98.9%	7	2	71.4%	277	71	74.4%
26		7	0	100.0%	279	5	98.2%	7	2	71.4%	277	54	80.5%
27	66	7	2	71.4%	265	16	94.0%	7	2	71.4%	261	83	68.2%
28		7	0	100.0%	261	59	77.4%	7	1	85.7%	261	52	80.1%
40	820	6	2	66.7%	272	40	85.3%	7	7	0.0%	272	139	48.9%
42		7	2	71.4%	279	22	92.1%	7	3	57.1%	277	45	83.8%
43		7	0	100.0%	278	41	85.3%	7	5	28.6%	278	61	78.1%
48		7	2	71.4%	277	55	80.1%	7	2	71.4%	277	40	85.6%
49		7	3	57.1%	277	70	74.7%	7	2	71.4%	277	54	80.5%
52		7	0	100.0%	276	37	86.6%	7	0	100.0%	275	61	77.8%
53		7	0	100.0%	276	34	87.7%	7	2	71.4%	275	87	68.4%
55		4	0	100.0%	172	6	96.5%	4	2	50.0%	169	36	78.7%
56		4	0	100.0%	173	22	87.3%	4	3	25.0%	170	29	82.9%
63	73	7	4	42.9%	280	121	56.8%	7	6	14.3%	276	146	47.1%
64	27	7	0	100.0%	278	63	77.3%	7	4	42.9%	278	95	65.8%
66	Cncld	7	3	57.1%	277	57	79.4%	5	1	80.0%	273	50	81.7%
67	16	4	2	50.0%	191	13	93.2%	4	1	75.0%	191	32	83.2%
68		7	2	71.4%	280	57	79.6%	7	4	42.9%	280	107	61.8%
69	20	7	2	71.4%	267	61	77.2%	7	5	28.6%	263	37	85.9%
71	16	7	0	100.0%	275	3	98.9%	7	6	14.3%	274	72	73.7%
72		3	0	100.0%	271	29	89.3%	3	0	100.0%	270	55	79.6%
73	17	2	0	100.0%	274	16	94.2%	2	1	50.0%	272	127	53.3%
74		2	0	100.0%	272	30	89.0%	2	1	50.0%	270	95	64.8%
75	50	2	0	100.0%	272	14	94.9%	2	1	50.0%	267	126	52.8%
76	23	2	0	100.0%	272	26	90.4%	2	2	0.0%	264	106	59.8%
77		2	1	50.0%	271	18	93.4%	2	1	50.0%	269	109	59.5%
78	26	7	2	71.4%	275	22	92.0%	7	6	14.3%	274	56	79.6%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79	91	7	0	100.0%	277	55	80.1%	7	6	14.3%	276	90	67.4%
80		7	2	71.4%	277	30	89.2%	6	4	33.3%	274	53	80.7%
84		3	0	100.0%	165	11	93.3%	3	1	66.7%	163	36	77.9%
85		4	0	100.0%	174	16	90.8%	4	2	50.0%	174	63	63.8%
86	27	4	1	75.0%	174	15	91.4%	4	4	0.0%	173	104	39.9%
89	162	7	3	57.1%	275	61	77.8%	7	4	42.9%	273	74	72.9%
90		7	0	100.0%	275	10	96.4%	7	5	28.6%	274	42	84.7%
93		4	0	100.0%	173	18	89.6%	4	3	25.0%	172	40	76.7%
94		4	3	25.0%	204	53	74.0%	4	3	25.0%	202	72	64.4%
95		4	0	100.0%	173	3	98.3%	4	3	25.0%	173	62	64.2%
97	146	7	7	0.0%	277	180	35.0%	7	6	14.3%	275	82	70.2%
98	131	7	1	85.7%	277	22	92.1%	7	7	0.0%	275	87	68.4%
110		4	3	25.0%	170	99	41.8%	4	1	75.0%	167	17	89.8%
111		4	0	100.0%	164	32	80.5%	4	0	100.0%	162	20	87.7%
112		4	0	100.0%	164	16	90.2%	4	0	100.0%	163	17	89.6%
113		4	1	75.0%	95	23	75.8%	4	0	100.0%	94	11	88.3%
119		3	1	66.7%	163	44	73.0%	3	2	33.3%	161	22	86.3%
125		4	0	100.0%	174	8	95.4%	4	3	25.0%	174	69	60.3%
129		4	0	100.0%	173	44	74.6%	4	2	50.0%	173	25	85.5%
130		4	1	75.0%	164	17	89.6%	4	1	75.0%	162	16	90.1%
131		4	1	75.0%	166	48	71.1%	4	3	25.0%	166	32	80.7%
134		4	1	75.0%	174	22	87.4%	4	2	50.0%	173	28	83.8%
136	33	4	1	75.0%	174	21	87.9%	4	2	50.0%	172	19	89.0%
137	52	4	1	75.0%	171	31	81.9%	4	2	50.0%	171	54	68.4%
138		4	1	75.0%	174	36	79.3%	4	3	25.0%	173	30	82.7%
141		4	0	100.0%	173	3	98.3%	4	1	75.0%	172	29	83.1%
148		4	0	100.0%	173	17	90.2%	4	1	75.0%	171	31	81.9%
151		7	2	71.4%	276	88	68.1%	7	6	14.3%	275	90	67.3%
170		4	0	100.0%	169	12	92.9%	4	0	100.0%	168	29	82.7%
171		4	0	100.0%	174	10	94.3%	4	3	25.0%	174	64	63.2%
172	36	4	0	100.0%	173	14	91.9%	4	3	25.0%	171	58	66.1%
173	104	3	1	66.7%	168	24	85.7%	3	3	0.0%	167	76	54.5%
174		4	0	100.0%	174	20	88.5%	4	2	50.0%	174	40	77.0%
175	20	4	0	100.0%	174	21	87.9%	4	2	50.0%	174	57	67.2%
176		3	1	66.7%	168	15	91.1%	3	2	33.3%	166	17	89.8%
177		4	1	75.0%	174	25	85.6%	4	0	100.0%	174	44	74.7%
178	67	4	0	100.0%	174	24	86.2%	4	3	25.0%	172	26	84.9%
179	116	4	1	75.0%	174	20	88.5%	4	3	25.0%	173	61	64.7%
181	39	4	1	75.0%	170	55	67.6%	4	2	50.0%	168	14	91.7%
182		4	1	75.0%	164	29	82.3%	4	1	75.0%	162	17	89.5%
183	98	4	2	50.0%	173	50	71.1%	4	2	50.0%	171	35	79.5%
184		4	2	50.0%	174	31	82.2%	4	3	25.0%	173	26	85.0%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
185		4	0	100.0%	174	36	79.3%	4	0	100.0%	174	11	93.7%
186		4	0	100.0%	173	17	90.2%	4	2	50.0%	172	42	75.6%
190	37	4	1	75.0%	173	63	63.6%	4	2	50.0%	172	39	77.3%
192		4	2	50.0%	171	21	87.7%	4	1	75.0%	171	15	91.2%
193	36	3	2	33.3%	172	73	57.6%	3	3	0.0%	171	83	51.5%
196		3	0	100.0%	172	18	89.5%	3	0	100.0%	171	15	91.2%
197	27	4	1	75.0%	174	69	60.3%	4	4	0.0%	174	57	67.2%
198	220	4	2	50.0%	106	16	84.9%	4	1	75.0%	105	17	83.8%
230		7	0	100.0%	114	4	96.5%	7	0	100.0%	114	6	94.7%
232		7	0	100.0%	280	11	96.1%	7	0	100.0%	280	17	93.9%
233		5	1	80.0%	256	57	77.7%	5	2	60.0%	256	75	70.7%
234		7	1	85.7%	280	20	92.9%	7	0	100.0%	280	24	91.4%
235		7	0	100.0%	204	27	86.8%	7	3	57.1%	204	44	78.4%
236	18	7	0	100.0%	264	7	97.3%	7	2	71.4%	264	38	85.6%
237		7	0	100.0%	278	52	81.3%	7	3	57.1%	276	46	83.3%
238		7	0	100.0%	204	19	90.7%	7	0	100.0%	203	14	93.1%
239		7	2	71.4%	279	74	73.5%	7	3	57.1%	278	33	88.1%
240	23	7	0	100.0%	279	20	92.8%	7	3	57.1%	277	47	83.0%
241		7	2	71.4%	280	70	75.0%	7	2	71.4%	280	68	75.7%
243		7	4	42.9%	216	59	72.7%	7	3	57.1%	215	29	86.5%
244		5	0	100.0%	256	10	96.1%	5	3	40.0%	256	41	84.0%
245		7	2	71.4%	161	29	82.0%	7	1	85.7%	160	18	88.8%
280		7	1	85.7%	280	12	95.7%	7	0	100.0%	280	50	82.1%
281		7	1	85.7%	280	30	89.3%	7	3	57.1%	280	50	82.1%
283		7	2	71.4%	280	66	76.4%	7	3	57.1%	280	55	80.4%
284	37	7	0	100.0%	280	10	96.4%	7	3	57.1%	278	45	83.8%
290	60	7	0	100.0%	280	48	82.9%	7	5	28.6%	278	96	65.5%
291		7	3	57.1%	279	78	72.0%	7	3	57.1%	277	61	78.0%
300	51	7	0	100.0%	264	19	92.8%	7	5	28.6%	262	61	76.7%
301		7	0	100.0%	278	9	96.8%	7	3	57.1%	275	53	80.7%
302		7	1	85.7%	265	32	87.9%	7	2	71.4%	261	74	71.6%
305	47	7	0	100.0%	268	28	89.6%	7	6	14.3%	264	108	59.1%
306	31	7	0	100.0%	276	15	94.6%	7	4	42.9%	275	75	72.7%
307		7	0	100.0%	268	35	86.9%	7	2	71.4%	265	72	72.8%
311	279	5	0	100.0%	276	23	91.7%	5	1	80.0%	271	51	81.2%
316	264	5	1	80.0%	273	17	93.8%	4	2	50.0%	269	66	75.5%
318	No OS	7	3	57.1%	279	29	89.6%	7	5	28.6%	276	129	53.3%
319	127	7	0	100.0%	280	17	93.9%	5	3	40.0%	276	148	46.4%
329		5	0	100.0%	197	8	95.9%	5	0	100.0%	197	13	93.4%
330	13	6	0	100.0%	237	4	98.3%	6	1	83.3%	237	14	94.1%
331		7	0	100.0%	280	29	89.6%	7	0	100.0%	280	40	85.7%
332		7	0	100.0%	280	14	95.0%	7	2	71.4%	280	41	85.4%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		7	0	100.0%	280	9	96.8%	7	0	100.0%	279	36	87.1%
335		7	0	100.0%	280	30	89.3%	7	2	71.4%	278	45	83.8%
336		7	1	85.7%	280	9	96.8%	7	0	100.0%	278	25	91.0%
337		7	1	85.7%	280	18	93.6%	7	1	85.7%	276	34	87.7%
338	13	7	2	71.4%	280	43	84.6%	7	2	71.4%	278	83	70.1%
339		7	1	85.7%	280	47	83.2%	7	1	85.7%	280	49	82.5%
341		7	1	85.7%	269	36	86.6%	7	1	85.7%	264	36	86.4%
342		7	0	100.0%	280	21	92.5%	7	0	100.0%	278	53	80.9%
350		7	0	100.0%	261	17	93.5%	6	4	33.3%	255	140	45.1%
351	82	7	1	85.7%	263	26	90.1%	7	3	57.1%	261	71	72.8%
352		7	0	100.0%	247	20	91.9%	7	4	42.9%	241	75	68.9%
353		6	1	83.3%	221	13	94.1%	6	1	83.3%	215	36	83.3%
354	118	7	3	57.1%	261	31	88.1%	7	6	14.3%	257	95	63.0%
355		7	1	85.7%	274	28	89.8%	7	6	14.3%	267	91	65.9%
364		7	1	85.7%	269	61	77.3%	7	5	28.6%	263	95	63.9%
365	65	7	1	85.7%	268	11	95.9%	7	6	14.3%	266	98	63.2%
370		7	1	85.7%	271	34	87.5%	6	1	83.3%	263	66	74.9%
371		6	0	100.0%	265	8	97.0%	6	1	83.3%	264	28	89.4%
381		7	0	100.0%	280	11	96.1%	7	2	71.4%	279	50	82.1%
382	28	7	2	71.4%	279	18	93.5%	7	4	42.9%	279	88	68.5%
383	28	7	1	85.7%	269	26	90.3%	6	3	50.0%	266	108	59.4%
390		7	0	100.0%	262	17	93.5%	7	3	57.1%	261	66	74.7%
391		7	1	85.7%	265	9	96.6%	7	3	57.1%	262	68	74.0%
392	21	7	0	100.0%	279	5	98.2%	7	6	14.3%	277	84	69.7%
393		7	0	100.0%	280	16	94.3%	7	4	42.9%	277	81	70.8%
417	17	4	1	75.0%	184	39	78.8%	4	1	75.0%	175	18	89.7%
425		4	0	100.0%	186	6	96.8%	4	0	100.0%	186	7	96.2%
448		7	2	71.4%	210	40	81.0%	7	3	57.1%	208	71	65.9%
449		7	1	85.7%	208	31	85.1%	7	4	42.9%	208	40	80.8%
470		4	1	75.0%	197	35	82.2%	4	0	100.0%	191	23	88.0%
471		4	1	75.0%	187	7	96.3%	4	1	75.0%	187	3	98.4%
473		4	0	100.0%	193	13	93.3%	4	0	100.0%	190	8	95.8%
474	23	5	2	60.0%	189	53	72.0%	4	4	0.0%	176	51	71.0%
475	18	4	0	100.0%	191	5	97.4%	4	2	50.0%	191	12	93.7%
478		4	2	50.0%	185	29	84.3%	4	0	100.0%	183	20	89.1%
479		4	2	50.0%	192	31	83.9%	4	3	25.0%	190	25	86.8%
486		4	1	75.0%	196	29	85.2%	4	2	50.0%	190	52	72.6%
494	23	4	0	100.0%	197	35	82.2%	4	3	25.0%	191	47	75.4%
495		4	0	100.0%	182	3	98.4%	4	0	100.0%	180	3	98.3%
500		7	1	85.7%	271	16	94.1%	6	0	100.0%	268	32	88.1%
502		7	1	85.7%	278	16	94.2%	6	0	100.0%	274	56	79.6%
503		7	1	85.7%	276	26	90.6%	7	4	42.9%	270	78	71.1%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		7	0	100.0%	280	17	93.9%	7	2	71.4%	278	84	69.8%
505	19	7	1	85.7%	278	37	86.7%	6	4	33.3%	273	77	71.8%
506		7	1	85.7%	275	39	85.8%	7	2	71.4%	270	43	84.1%
507		7	1	85.7%	280	35	87.5%	7	2	71.4%	280	90	67.9%
508		7	0	100.0%	275	39	85.8%	7	0	100.0%	272	62	77.2%
509		7	0	100.0%	277	12	95.7%	7	0	100.0%	277	63	77.3%
511		7	1	85.7%	272	22	91.9%	7	1	85.7%	271	46	83.0%
516		7	1	85.7%	272	28	89.7%	7	2	71.4%	271	125	53.9%
517		7	0	100.0%	280	8	97.1%	7	5	28.6%	276	113	59.1%
518	146	7	0	100.0%	280	35	87.5%	7	5	28.6%	278	188	32.4%
519		7	0	100.0%	272	9	96.7%	7	1	85.7%	270	64	76.3%
520		5	0	100.0%	155	24	84.5%	5	0	100.0%	152	9	94.1%
521		5	0	100.0%	193	7	96.4%	5	2	60.0%	193	25	87.0%
522		5	0	100.0%	193	36	81.3%	5	0	100.0%	190	18	90.5%
523		5	0	100.0%	193	6	96.9%	5	0	100.0%	192	22	88.5%
524		5	1	80.0%	193	12	93.8%	5	0	100.0%	191	20	89.5%
525		5	1	80.0%	191	13	93.2%	5	0	100.0%	188	13	93.1%
526		5	1	80.0%	167	30	82.0%	5	1	80.0%	164	13	92.1%
527		5	0	100.0%	193	9	95.3%	5	0	100.0%	192	32	83.3%
528		5	0	100.0%	193	15	92.2%	5	0	100.0%	192	29	84.9%
529		5	0	100.0%	193	11	94.3%	5	0	100.0%	192	50	74.0%
530		5	0	100.0%	147	14	90.5%	5	1	80.0%	147	27	81.6%
531		5	0	100.0%	167	12	92.8%	5	1	80.0%	167	12	92.8%
532		5	3	40.0%	193	46	76.2%	5	2	60.0%	192	29	84.9%
534		5	0	100.0%	152	24	84.2%	5	0	100.0%	150	15	90.0%
535		5	1	80.0%	180	24	86.7%	5	0	100.0%	175	20	88.6%
536		5	1	80.0%	193	50	74.1%	5	0	100.0%	190	37	80.5%
537		5	1	80.0%	164	19	88.4%	5	0	100.0%	159	16	89.9%
538		5	0	100.0%	193	23	88.1%	5	2	60.0%	192	39	79.7%
539		5	1	80.0%	147	21	85.7%	5	1	80.0%	147	65	55.8%
540		4	2	50.0%	192	37	80.7%	4	0	100.0%	185	18	90.3%
541		5	1	80.0%	192	22	88.5%	5	1	80.0%	187	34	81.8%
542		5	0	100.0%	192	21	89.1%	5	2	60.0%	190	34	82.1%
543	27	5	0	100.0%	193	19	90.2%	5	4	20.0%	193	54	72.0%
544		5	0	100.0%	191	20	89.5%	5	1	80.0%	188	16	91.5%
545		5	1	80.0%	193	16	91.7%	5	0	100.0%	191	22	88.5%
547		5	0	100.0%	193	37	80.8%	5	0	100.0%	193	44	77.2%
548		4	0	100.0%	188	20	89.4%	4	0	100.0%	187	14	92.5%
549		5	0	100.0%	188	25	86.7%	5	0	100.0%	181	16	91.2%
550		5	1	80.0%	147	15	89.8%	5	1	80.0%	147	32	78.2%
551		5	0	100.0%	189	19	89.9%	5	0	100.0%	181	17	90.6%
562		7	1	85.7%	272	22	91.9%	7	0	100.0%	269	29	89.2%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		7	0	100.0%	272	17	93.8%	7	1	85.7%	264	31	88.3%
566		7	0	100.0%	270	17	93.7%	7	1	85.7%	267	33	87.6%
567		7	0	100.0%	157	8	94.9%	7	0	100.0%	155	6	96.1%
572	34	7	0	100.0%	267	22	91.8%	7	3	57.1%	262	68	74.0%
573		7	0	100.0%	270	40	85.2%	7	0	100.0%	263	44	83.3%
579		7	0	100.0%	157	8	94.9%	7	2	71.4%	152	28	81.6%
580		7	0	100.0%	272	14	94.9%	7	0	100.0%	267	21	92.1%
581		7	2	71.4%	272	45	83.5%	7	1	85.7%	270	55	79.6%
584	35	7	2	71.4%	156	19	87.8%	7	6	14.3%	152	88	42.1%
587	37	7	0	100.0%	267	15	94.4%	7	2	71.4%	258	40	84.5%
588		7	1	85.7%	157	13	91.7%	7	0	100.0%	156	22	85.9%
591		7	0	100.0%	271	18	93.4%	7	0	100.0%	265	29	89.1%
593		7	1	85.7%	266	38	85.7%	7	1	85.7%	248	28	88.7%
595		7	1	85.7%	267	42	84.3%	7	1	85.7%	264	47	82.2%
600		4	0	100.0%	201	9	95.5%	4	1	75.0%	199	16	92.0%
601		4	2	50.0%	184	74	59.8%	4	0	100.0%	181	23	87.3%
605		4	2	50.0%	191	120	37.2%	4	0	100.0%	187	19	89.8%
607	22	4	2	50.0%	200	26	87.0%	4	2	50.0%	197	24	87.8%
609		4	1	75.0%	191	23	88.0%	4	1	75.0%	190	16	91.6%
622		3	0	100.0%	106	30	71.7%	3	0	100.0%	104	5	95.2%
626	14	4	0	100.0%	105	12	88.6%	4	1	75.0%	103	16	84.5%
639		3	0	100.0%	171	37	78.4%	3	0	100.0%	170	19	88.8%
640		4	0	100.0%	191	7	96.3%	4	1	75.0%	189	77	59.3%
641		4	1	75.0%	173	35	79.8%	4	0	100.0%	173	25	85.5%
642		4	0	100.0%	189	9	95.2%	4	0	100.0%	188	23	87.8%
643		4	0	100.0%	203	39	80.8%	4	0	100.0%	200	32	84.0%
644	54	4	0	100.0%	195	27	86.2%	4	3	25.0%	193	51	73.6%
645	64	4	2	50.0%	203	40	80.3%	3	2	33.3%	200	41	79.5%
646		4	1	75.0%	192	47	75.5%	4	2	50.0%	190	91	52.1%
647		4	0	100.0%	203	31	84.7%	4	2	50.0%	202	45	77.7%
648		4	1	75.0%	199	51	74.4%	4	1	75.0%	199	32	83.9%
649	12	4	3	25.0%	204	40	80.4%	4	1	75.0%	201	32	84.1%
650		4	0	100.0%	203	39	80.8%	4	2	50.0%	200	32	84.0%
651		4	0	100.0%	203	16	92.1%	4	2	50.0%	201	41	79.6%
652		4	0	100.0%	204	27	86.8%	4	2	50.0%	200	34	83.0%
653		4	1	75.0%	192	31	83.9%	4	2	50.0%	189	36	81.0%
654		4	2	50.0%	193	38	80.3%	3	0	100.0%	189	16	91.5%
655		4	1	75.0%	201	70	65.2%	4	2	50.0%	199	70	64.8%
656		4	0	100.0%	203	45	77.8%	4	2	50.0%	202	23	88.6%
657	19	4	1	75.0%	192	27	85.9%	4	1	75.0%	191	29	84.8%
658		4	0	100.0%	203	34	83.3%	4	0	100.0%	201	30	85.1%
680		5	2	60.0%	198	11	94.4%	5	0	100.0%	197	24	87.8%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681		5	0	100.0%	198	14	92.9%	5	2	60.0%	193	74	61.7%
682		5	0	100.0%	197	5	97.5%	5	1	80.0%	197	34	82.7%
683	136	5	0	100.0%	180	15	91.7%	5	5	0.0%	179	56	68.7%
684		5	2	60.0%	179	29	83.8%	5	1	80.0%	179	39	78.2%
685		5	2	60.0%	194	30	84.5%	5	4	20.0%	191	48	74.9%
686		5	0	100.0%	199	33	83.4%	5	4	20.0%	198	40	79.8%
687		5	2	60.0%	198	32	83.8%	5	3	40.0%	197	34	82.7%
688		5	3	40.0%	197	12	93.9%	5	3	40.0%	196	33	83.2%
701		7	2	71.4%	212	23	89.2%	7	0	100.0%	209	20	90.4%
702	17	7	0	100.0%	279	31	88.9%	7	2	71.4%	277	62	77.6%
703	No OS	7	4	42.9%	280	81	71.1%	6	4	33.3%	278	74	73.4%
704		7	1	85.7%	211	33	84.4%	6	1	83.3%	205	39	81.0%
710	35	7	2	71.4%	280	71	74.6%	7	3	57.1%	276	76	72.5%
711		7	1	85.7%	271	29	89.3%	6	1	83.3%	253	46	81.8%
712		7	3	57.1%	277	74	73.3%	7	1	85.7%	269	88	67.3%
713		4	1	75.0%	150	15	90.0%	4	2	50.0%	137	58	57.7%
714	88	6	5	16.7%	161	63	60.9%	6	4	33.3%	149	62	58.4%
715		7	1	85.7%	279	59	78.9%	5	1	80.0%	258	126	51.2%
716		7	2	71.4%	280	109	61.1%	7	2	71.4%	275	104	62.2%
717		7	1	85.7%	266	63	76.3%	7	2	71.4%	248	72	71.0%
718	56	7	6	14.3%	280	142	49.3%	7	6	14.3%	278	97	65.1%
719		7	5	28.6%	280	93	66.8%	7	4	42.9%	266	76	71.4%
757		7	0	100.0%	65	3	95.4%	7	0	100.0%	64	4	93.8%
761		7	1	85.7%	276	12	95.7%	7	1	85.7%	273	35	87.2%
765		7	0	100.0%	276	24	91.3%	7	0	100.0%	276	36	87.0%
769		7	0	100.0%	276	25	90.9%	7	0	100.0%	270	49	81.9%
770		7	0	100.0%	276	21	92.4%	7	4	42.9%	274	78	71.5%
774		7	0	100.0%	276	16	94.2%	7	2	71.4%	275	58	78.9%
777		7	1	85.7%	161	10	93.8%	7	0	100.0%	160	34	78.8%
782	17	7	5	28.6%	161	61	62.1%	7	1	85.7%	156	16	89.7%
785		7	1	85.7%	276	18	93.5%	7	0	100.0%	276	46	83.3%
786		7	0	100.0%	65	16	75.4%	7	1	85.7%	64	28	56.3%
790		7	0	100.0%	276	26	90.6%	7	1	85.7%	273	33	87.9%
794		7	1	85.7%	276	32	88.4%	7	1	85.7%	273	56	79.5%
821		7	0	100.0%	274	6	97.8%	7	3	57.1%	274	106	61.3%
822	30	7	1	85.7%	276	15	94.6%	7	5	28.6%	274	123	55.1%
1333		7	2	71.4%	276	30	89.1%	7	2	71.4%	273	90	67.0%
1340		7	0	100.0%	275	5	98.2%	7	2	71.4%	275	44	84.0%
1689		2	0	100.0%	76	5	93.4%	2	0	100.0%	75	8	89.3%
2102		4	0	100.0%	50	12	76.0%	4	0	100.0%	49	4	91.8%
2103		4	0	100.0%	114	10	91.2%	4	0	100.0%	113	9	92.0%
2104		4	0	100.0%	140	9	93.6%	4	0	100.0%	138	10	92.8%

Amtrak On Time Performance

Trains Arriving Through: 7/7/2026

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107		4	2	50.0%	171	32	81.3%	4	0	100.0%	168	20	88.1%
2108		4	0	100.0%	171	25	85.4%	4	1	75.0%	165	18	89.1%
2109		4	0	100.0%	64	9	85.9%	4	0	100.0%	63	4	93.7%
2112		4	1	75.0%	11	3	72.7%	3	1	66.7%	9	1	88.9%
2113		4	2	50.0%	50	5	90.0%	4	0	100.0%	50	7	86.0%
2115		4	1	75.0%	50	6	88.0%	4	2	50.0%	49	6	87.8%
2116		4	0	100.0%	11	0	100.0%	4	2	50.0%	11	4	63.6%
2118		4	2	50.0%	11	2	81.8%	4	3	25.0%	11	5	54.5%
2119		4	0	100.0%	11	2	81.8%	4	3	25.0%	11	4	63.6%
2120		4	3	25.0%	11	6	45.5%	3	2	33.3%	10	5	50.0%
2123		4	1	75.0%	49	7	85.7%	3	1	66.7%	48	14	70.8%
2124		4	3	25.0%	143	26	81.8%	4	3	25.0%	141	16	88.7%
2127		4	2	50.0%	11	3	72.7%	4	2	50.0%	10	2	80.0%
2128		4	1	75.0%	11	1	90.9%	4	1	75.0%	11	1	90.9%
2131		4	2	50.0%	11	2	81.8%	4	1	75.0%	11	1	90.9%
2150	27	4	0	100.0%	164	22	86.6%	4	2	50.0%	161	69	57.1%
2151		4	0	100.0%	113	6	94.7%	4	1	75.0%	111	30	73.0%
2152		3	1	66.7%	71	4	94.4%	3	1	66.7%	70	27	61.4%
2154	38	3	0	100.0%	75	20	73.3%	3	1	66.7%	72	37	48.6%
2155		4	1	75.0%	173	15	91.3%	4	2	50.0%	169	92	45.6%
2158		4	0	100.0%	11	2	81.8%	4	2	50.0%	11	2	81.8%
2159	20	4	1	75.0%	166	12	92.8%	4	4	0.0%	164	52	68.3%
2160		4	0	100.0%	11	0	100.0%	3	2	33.3%	10	6	40.0%
2162		4	0	100.0%	172	13	92.4%	4	2	50.0%	166	79	52.4%
2165		3	1	66.7%	10	1	90.0%	3	2	33.3%	10	4	60.0%
2167		3	0	100.0%	162	18	88.9%	3	0	100.0%	162	36	77.8%
2171		4	0	100.0%	100	8	92.0%	4	3	25.0%	97	21	78.4%
2190		3	1	66.7%	171	25	85.4%	3	1	66.7%	169	23	86.4%
2193		3	0	100.0%	168	23	86.3%	3	1	66.7%	166	46	72.3%

Amtrak Endpoint OTP Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/7/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2150	BOS	27	CTI	18	SMW	7	NYP-XSH	AM	Scheduled in track usage program, Other, XGG-XSH, NO TIME LOST	
2154	BOS	38	ENG	15	CTP	14	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION BERGEN TO NYP A/C NJ6332 OPERATING WITH CAB SIGNAL FAILURE	
2159	WAS	20	SMW	15	BSP	11	XGX-NHV	AM	Bridge strike, Bridge, MONTEWESE AVE, MP 81.71	
66	BOS	Trn Cancelled								
67	NPN	16	OTH	23	OTH	8	XPV-BAL	AM	Lost time - N.A.R., pure run time	
86	BOS	27	FTI	24	FTI	19	WBG-RVM	CS	Follow csx unknown id, Other, ca76.2-84.7	
136	SPG	33	SMW	24	ENG	13	WAS-WAS	AM	Other electrical failure, 633 AND 612, BOTH MTRS SHOPPED 633 BATTERY ISSUES AND 612 IO FAULTS	
137	WAS	52	WTR	62	WTR	55	RTE-PVD	AM	Trees down, Milepost, rte, pvd, Branch in OCS trck 2 at Mp 202.5 (waiting for traffic to clear singles track)	
172	BOS	36	OTH	33	PTI	10	XPV-WIL	AM	Follow, 2104, Control Point, Bacon, Opr No.3 trk and held, Acela ahead No.2 trk	
173	WAS	104	ITI	57	ITI	53	BOS-BOS	AM	Service, turn, or wye train, 178, Late release from the yard account late #178	
175	WAS	20	CTI	29	CTI	19	NHV-STM	MN	Follow metro, Other, entoute	
178	BOS	67	WTR	44	WTR	36	NHV-NLC	AM	Trees down, Milepost, NHV, NLC	
179	PHL	116	WTR	111	WTR	111	KIN-XGX	AM	Trees down, Milepost, KIN, XGX	
181	WAS	39	DCS	27	DCS	27	NYP-NYP	AM	T.O.L, Other, NYP-NYP, DELAY A.C TOL AT Q	
183	WAS	98	ITI	109	ITI	109	NYP-NYP	AM	Service, turn, or wye train, 198, LATE F/SSYD A/C LATE TURN OFF AM198	
190	BOS	37	DCS	17	DCS	17	KIN-PVD	AM	Wayside detector failure including false actuation, Other, 168.7, stopped at CP 171.12 a/c Integrity failure hot box detector at Davisville	
193	WAS	36	PTI	17	DMW	11	NWK-EWR	AM	Held for or routed around MW work or equipment, Other, HUNTER, HELD A/C CONGESTION AHD DUE TO IMPOSED S/R DUE TO BROKEN FROG POINT	
197	WAS	27	CTI	18	CTI	15	BAL-XNY	AM	Follow, MARC, 455, Milepost, 97.7, 134.6	

Amtrak Endpoint OTP Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/7/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
198	NYP	220	CON	186	CON	186	WAS-WAS	AM	Hold for bus with passengers from train, HELD FOR BUSES REPRESENTING CANCELED TRAIN 66(6). TRAIN WAS CANCELED DUE TO DSL PROBLEMS IN ROANOKE.	
417	NHV	17	CTI	13	CTI	13	SPG-WNL	AM	Meet, CTRAIL, 4476, Milepost, xf3, xf3	
474	SPG	23	SMW	13	SMW	13	WFD-MDN	AM	Scheduled in track usage program, Control Point, Holt-Willow, Meet @ Holt w/ 475 a/c O/S track	
475	NHV	18	PTI	15	PTI	15	SPG-WNL	AM	Meet, 486, Milepost, xf3, xf3	
494	GFD	23	ENG	15	ENG	15	NHT-GFD	MA	Loading problem 105	
79	CLT	91	PTI	58	TRS	42	KAN-CLT	NS	Vehicle on track ahead Milepost, 362, 362	
607	HAR	22	DCS	41	DCS	41	NYP-NYP	AM	T.O.L, Other, NYP-NYP, LATE F/SSYD A/C TOL AT "Q" INT	
626	NYP	14	CCR	20	CCR	20	PHL-XHM	AM	Set out defective cab car, ., HAD TO WYE ON OUTBOUND A/C NO CAB CAR.	
644	NYP	54	CCR	46	CCR	35	PHL-XHM	AM	Electrical failure, NO CAB CAR, Wye'd a/c no cab car.	
645	HAR	64	ITI	52	ITI	52	NYP-NYP	AM	Service, turn, or wye train, 644, LATE TURN OFF AM644	
649	HAR	12	CCR	21	CCR	21	PHL-ARD	AM	Electrical failure, ., Necessary to WYE, no Cab Car	
657	HAR	19	ENG	20	ENG	20	TRE-XHM	AM	PTC - On Board Cab Signal or PTC Failure, 630, STOPPED AT GRUNDY WITH CAB SIGNAL FAILURE	
19	NOL	38	FTI	66	FTI	41	SDL-XEJ	NS	Follow 131, Control Point, ne tower	
20	NYP	134	SVS	240	SVS	240	NOL-NOL	AM	Water, commissary, toilet/trash dumping Servicing train equipment...	
683	BRK	136	TRS	132	TRS	132	FRE-BRK	CS	Trespasser strike Control Point, 2.5 bru	
63	TWO	73	DCS	33	DCS	33	NYP-NYP	AM	T.O.L, Other, NYP-NYP, LATE F/SSYD A/C TOL AT "Q" INT	
64	NYP	27	CTI	44	CTI	21	RHI-XCP	MN	Blocked from station track Both 857 and 863 were south of New Hamburg when 64 stopped at cp 75., metro north, 857, metro north, 863, metro north, 890, Control Point, cp 75	
69	MTR	20	WTR	40	WTR	40	XLQ-SLQ	CN	Heat order Milepost, 0, 43	
236	NYP	18	PTI	18	PTI	10	YNY-XSD	MN	Cross over or go around 281, Control Point, 12	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Region: ALL

Service: ALL

Arriving On: 7/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
240	NYP	23	DSR	25	DSR	25	POU-CRT	MN	Per bulletin Mobile unit 401, Milepost, 43.4, 41.9, 30, 1
284	NYP	37	FTI	29	DMW	26	POU-CRT	MN	Held for or routed around MW work or equipment Held at CP 46 for train 833 to go through mobile unit 401 working limits . Once they passed we went through after stopping at 30 mph MP 43.4-41.9, Control Point, 46
290	NYP	60	DMW	33	DMW	30	POU-CRT	MN	Held for or routed around MW work or equipment Held for multiple trains due to getting around work area, Control Point, 46
71	CLT	16	PTI	10	PTI	10	GRO-SAL	NS	Meet #AM80, Control Point, Elm
73	CLT	17	PTI	9	PTI	9	RGH-CYN	NS	Meet #AMTK80, Control Point, Boylan
75	CLT	50	FTI	35	FTI	35	SAL-KAN	NS	Meet High and Wide, #NSO53, Control Point, North Kannapolis
76	RGH	23	FTI	16	FTI	16	KAN-GRO	NS	Follow #NSO53, Control Point, Reed, High Wide
78	RGH	26	WTR	17	WTR	9	DNC-CYN	NS	Flash flood warning 40mph, Milepost, 49.0, 66.1
89	SAV	162	PTI	85	WTR	36	PTB-RMT	CS	High winds Milepost w/Letters, a39.7, a99.9
97	MIA	146	CAR	74	CAR	74	SAV-SAV	CS	HEP 61038, Had to short loop 5 cars one at a time to find out the problem
98	NYP	131	WTR	71	CTI	28	XDJ-ALX	CS	Follow Approach/ restricting, VRE, 310, Milepost w/Letters, CFP 72.5, CFP 86.5
40	CHI	820	WTR	650	WTR	460	COV-XFI	CS	Flood / washout Stopped at COV due to mudslide. Recrewed, Other, COV
23	NOL	37	FTI	47	FTI	19	MOE-PAG	CS	Meet 845, Siding, St Elmo
24	MOE	53	FTI	65	FTI	39	XNO-BAS	CS	Meet m605, Control Point, 754
6	CHI	371	TRS	290	TRS	204	DAV-DAV	UP	Trespasser strike 720 trespasser strikes, Control Point, Webster
543	SJC	27	PTI	18	CTI	13	GAC-SCC	UP	Meet ace, 8, Control Point, expressway
505	PDX	19	RTE	19	RTE	19	VAN-PDX	BN	Crossover(s) due to N.A.R. Back up at VAN to cross over to 1, 2-1, Control Point, VAN
518	VAC	146	TRS	105	TRS	79	SEA-EDM	BN	Sounder trespasser strike at blueridge. Held at 23rd ave until incident was cleared up Control Point, 23rd ave
8	CHI	63	DSR	63	CON	23	SPK-SPK	BN	Hold for connecting train 28
27	PDX	66	POL	62	POL	62	VAN-VAN	BN	Removal of passenger by police Alleged sexual assault

Amtrak Endpoint OTP Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	30	DSR	31	FTI	24	FTW-GLE	BN	Meet bnsf 6192 & 3856, Siding, valley view
330	CHI	13	CTI	28	CTI	18	GLN-XWA	ME	Follow Metra trains running behind schedule, Metra, 2112, Milepost, 17.4, 3.1
338	CHI	13	CTI	14	CTI	6	GLN-XWA	ME	Cross Traffic Multiple yard moves, Metra, Control Point, A3
351	CHI	82	SYS	45	ENG	26	DER-ARB	MI	PTC - On Board Cab Signal or PTC Failure No mode light. Stopped at CP9 to MTIE which was not successful. Reset breakers as well. Running 596 for 3 blocks to see if it will cut in. Unable to MTIE as no options were given as it would only show yard configs., 319
354	PNT	118	ITI	120	ITI	120	CHI-CHI	AM	Had to wait for 353 to come in and detach from 351 Other, union station, .
365	CHI	65	SYS	58	SYS	35	LNS-BTL	CC	Conductor working alone/crew shortage.
572	SAN	34	CTI	26	CTI	17	SOL-OLT	SN	Meet NCTD, 637, Control Point, skripps
584	SAN	35	PTI	28	PTI	20	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	37	CTI	36	CTI	16	OSD-X98	SC	Per Schedule metrolink, Control Point, songs
782	SAN	17	PTI	28	PTI	19	SNC-SNP	SC	Meet 785, Control Point, serra
702	BFD	17	FTI	27	FTI	15	MCD-MDR	BN	Meet Held at Planada due to BNSF being held on main track 1 and waiting for AMT 701 to pass on main track 2., Control Point, Planada, BNSF 8012
703	SAC	No OS Rpt	FTI	90	FTI	90	BFD-WAC	BN	Disabled BNSF (5094)freight train with broken air hoses bnsf 5094, Control Point, lopez
710	BFD	35	FTI	28	FTI	16	MOD-TRK	BN	Meet Shuffle E/E Denair behind AMTK 701 & BNSF 8012 W, Siding, Denair, BNSF 8012 W, ZWSPNBY
714	BFD	88	FTI	65	FTI	60	WAC-BFD	BN	FREIGHT VANDALIZED. WAITED FOR REPAIR Control Point, UNA, 5504
718	BFD	56	CON	52	CON	52	SKN-SKN	BN	Hold for thruway bus Hold two buses carrying cancelled 704.
2	NOL	76	DCS	160	DCS	77	XWB-XEB	UP	CTC system failure Control Point, opl010
21	SAS	51	FTI	96	ENG	45	AUS-SMC	UP	Air / Brake Brakes were not fully releasing. Had to dump air air do a class 2. Flip breaker for breaks and restart the computer. 2nd class 2 had to be done, 63, 48

Amtrak Endpoint OTP Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
22	CHI	76	ENG	131	ENG	131	SAS-SMC	UP	Air / Brake Tripped detector mp 243.6 sticky brake on locomotive 315, met with mechanical to fix the issue., 315
300	CHI	51	FTI	61	FTI	27	CRV-SPI	UP	Meet UP 8076 went into emergency while passing our train. They were able to find the separation and repair it., Control Point, Isles, UP 8076
305	STL	47	SYS	17	SYS	17	CHI-XTF	AM	Had to initialize XITCS
306	CHI	31	RTE	64	RTE	57	BNL-PON	UP	Line manual or spring switch Control Point, 93
382	CHI	28	SYS	20	SYS	20	GBB-GBB	BN	Late bulletins in West Quincy Yard. BNSF KC didn't have us in the system and no bulletins. Had to have them sent to Galesburg office and picked up. Other, West Quincy Yard
383	QCY	28	CTI	13	FTI	10	MAC-QCY	BN	Meet bnsf 7070, Siding, Mac
392	CHI	21	FTI	35	FTI	29	MAT-CHM	CC	Follow Milepost w/Letters, Humboldt, to tolongo, northbound cn
311	KCY	279	PTI	238	PTI	192	JEF-JEF	UP	Wait for route blocked by 318 Amtk 318, Other, Jeff City
316	STL	264	ITI	177	ITI	177	KCY-KCY	KC	Service, turn, or wye train 311
318	CHI	No OS Rpt	ENG	334	ENG	272	WAR-SED	UP	Failure of diesel engine ID4606
319	KCY	127	FTI	78	RTE	45	HEM-JEF	UP	Dispatcher hold Unknown, Control Point, ames

Amtrak Initial Terminal Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/7/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	20	07/07	199	200	Late turn over of equipment from Amtk 19
BOS	137	07/07	5	5	Service, turn, or wye train, 190, Late turn
BOS	173	07/07	53	53	Service, turn, or wye train, 178, Late release from the yard account late #178
BRK	688	07/07	17	17	RR blocked by trespasser or vehicle strike by another train. Waited for clearance from police from 683 trespasser strike
HAR	654	07/07	5	5	Meet, 609, Control Point, .
MIA	40	07/07	143	143	Service, turn, or wye train 41
NHV	474	07/07	8	6	Hold for connecting train
NHV	474	07/07	8	2	Hold for connecting train
NHV	474	07/07	8	6	Hold for connecting train
NHV	474	07/07	8	2	Hold for connecting train
NYP	19	07/07	20	20	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	63	07/07	33	33	T.O.L, Other, NYP-NYP , LATE F/SSYD A/C TOL AT "Q " INT
NYP	69	07/07	3	3	Meet, AM232, Other, NYP-NYP, HELD A/C AM232 XING AHEAD
NYP	89	07/07	7	7	T.O.L, Other, NYP-NYP, LATE F/SSYD A/C TOL AT "Q" INT
NYP	97	07/07	156	25	Service, turn, or wye train, 98, LATE TURN OFF AM98
NYP	97	07/07	156	131	Service, turn, or wye train, 98, LATE F/SSYD A/C LACK OF EQUIPMENT AVAILABLE AND TO MINIMIZE THE DRILLING OF EQUIPMENT, WE TURN INBOUND TRAIN 98 ENTIRE CONSIST FOR AM97.
NYP	181	07/07	27	27	T.O.L, Other, NYP-NYP, DELAY A.C TOL AT Q
NYP	183	07/07	109	109	Service, turn, or wye train, 198, LATE F/SSYD A/C LATE TURN OFF AM198
NYP	193	07/07	4	4	Follow, AM2167, Other, JO- F INT, HELD IN JO A/C TRACK SPACE DUE TO AM2167 XING AHD
NYP	281	07/07	2	2	Cross Traffic, NJT, NJ5126, Other, NYP-NYP, HELD A/C NJ5126 XING AHEAD
NYP	291	07/07	10	10	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	607	07/07	41	41	T.O.L, Other, NYP-NYP, LATE F/SSYD A/C TOL AT "Q" INT
NYP	641	07/07	12	13	T.O.L, Other, NYP-NYP, LATE F/SSYD A/C TOL AT "Q" INT
NYP	645	07/07	52	52	Service, turn, or wye train, 644, LATE TURN OFF AM644
NYP	649	07/07	2	2	Passenger and/or baggage, BOARDING
NYP	2107	07/07	3	3	T.O.L, Other, NYP-NYP , LATE F/SSTD A/C TOL AT "Q" INT
NYP	2113	07/07	2	2	Passenger and/or baggage, BOARDING

Amtrak Initial Terminal Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/7/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	2115	07/07	2	2	Passenger and/or baggage, LOADING
PHL	110	07/07	5	5	Passenger and/or baggage
PHL	190	07/07	2	2	High passenger count
WAS	182	07/07	13	13	Malfunction of platform structure at Amtrak station, Other, X, DUE TO 17/18 TK BEING OUT SERVICE NEC'Y TO ROUTE MARC TRN 13 TK THAT DIDN'Y CLEAR
WAS	184	07/07	10	10	Service, turn, or wye train, 183
CHI	48	07/07	45	45	Swapping engines 49
CHI	354	07/07	2	2	Door ID4009, Cars swapped and bad ordered. Com cable was missing from the rear car making the engine unable to read doors closed or give a load test. Cable was added after boarding and doors were tested and seen to be closed by engine sensors and we departed.
GBB	382	07/07	20	20	Late bulletins in West Quincy Yard. BNSF KC didn't have us in the system and no bulletins. Had to have them sent to Galesburg office and picked up. Other, West Quincy Yard
KCY	316	07/07	177	177	Service, turn, or wye train 311
KCY	318	07/07	5	5	Door ID4606, Showing doors open all doors closed cut out train line
PNT	353	07/07	2	1	Mobility Impaired Multiple ADA
PNT	353	07/07	2	1	Door ID4009, ID4102, ID4112, ID4206, ID4301, ID4630, Doors showed open. All doors closed
BFD	701	07/07	1	1	Wheelchair Interview pax traveling in power wheelchair with excess baggage and service animal to determine if travel would be denied after animal was observed barking at other pax on the platform. Ultimately allowed to travel. Used manual lift to board.
GTA	782	07/07	2	2	Wait for station track Waiting in siding at Elwood for Goleta station track on single Main Track., 14, Control Point, CO 358 South Elwood
OKJ	532	07/07	2	2	Wait for station track AMT537, Control Point, king st
OKJ	540	07/07	1		
OKJ	714	07/07	29	29	Planned Switch HAD TO WAIT FOR 711 EQUIPMENT TO SWITCH OVER
OKJ	716	07/07	2	2	Planned set out / pick out of locomotives, cars or section of train Unable to get load due to door light issue
OKJ	718	07/07	10	2	Meet 545, Control Point, north jack london
OKJ	718	07/07	10	8	Water, commissary, toilet/trash dumping Servicing train. Needed to water cab car and replace windshield wiper on locomotive 2006. Pulled out of yard at 540
SAC	537	07/07	2	2	Issue getting orders
SAC	541	07/07	1		

Amtrak Initial Terminal Details

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/7/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	704	07/07	2	2	Door C9807, B end door. No door light. Written up since December.
SEA	11	07/07	3	3	Passenger and/or baggage Pax PNR 295D29 booked in 1129/H; no car in consist; pax told to rebook inside SEA before departure; no available room for full trip; "Laura" in SEA told red cap to board passengers in 1131/15 with no ticket showing in system or paper copy
SJC	550	07/07	1		

Eastern Region

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	95.3	97.9	94.8	342	16
CDOT	95.0	70.0	85.7	92.4	20	6
MARC	95.0	81.0	71.8	90.2	58	11
SEPTA	95.0	96.8	94.4	91.5	216	7
NJT-NED	95.0	92.5	89.4	88.6	334	25
NJT-SED	95.0	100.0	94.2	97.2	24	0

Operating Highlights

Train 53(07) - South of Florence, SC - Freight Train Interference

08JUL26: Train 53(07) was delayed on the CSX Charleston Subdivision between MP 307.9 and MP 367.7 due to meeting CSX Trains M410, M38 and M491. Train 53(07) was diverted to the sidings at New Hope, West Branch and Hanahan.

Train	Delay	Comment
53 (07)	40"	

Train 79(07) - East of Charlotte, NC - Trespasser Incident

08JUL26: Train 79(07) was delayed on the Norfolk Southern Charlotte District Subdivision at MP 362.6 due to a vehicle stuck on the tracks ahead.

Train	Delay	Comment
79 (07)	42"	

Train 178(07) Burke Centre, VA - Freight Train Interference

07JUL26: Train 178(07) was delayed on the CSX RF& P due to crossing over and going around the IO135 at MP 103.9.

Train	Delay	Comment
178 (07)	31"	

Train 97(06) South of Palatka, FL - Passenger Train Interference

07JUL26: Train 97(06) was delayed on the CSX Sanford subdivision at MP 749.7 meeting 98(07).

Train	Delay	Comment
97 (06)	32"	

Train 75(07) South of Salisbury, NC - Freight Train Interference

07JUL26: Train 75(07) 25-FBI-00590/NC181009304 E/NC1001005 cars 7/15/2026 delayed on the NS Charlotte subdivision due to meeting NS 053-06 at MP 346.3.

Train	Delay	Comment
75(07)	35"	

Train 68(07) East of St-Lambert, QC -Heat Orders/Weather

07JUL26: Train 68(07) was delayed on the CN Rouses Point subdivision due to heat orders from MP 43.0 to MP 0.0.

Train	Delay	Comment
68(07)	45"	

Train 683(07) East of Freeport, ME - Trespasser Incident

07JUL26: At 310P-ET, Train 683(07) with E/94, CC/90224 and 4 cars with 20 customers onboard struck a trespasser at MP 2.6 on the CSX Portland BRU subdivision. The train was able to maintain HEP. Amtrak Assistant Superintendent of Operation was scene. Local Police and EMS were on scene. Amtrak Police were notified. This was a confirmed fatality. This occurred in Sagadahoc County, ME. Crew was requesting relief. Train 688(07) crew was used to recrew and bring train 683(07) into Brunswick. Train 688(07) may see some delay due to holding for the Funeral home to collect the body.

National Response Center Number: 1467214

Train	Delay	Comment
683(07)	2'10"	
688(07)	17"	

New Haven to Boston Main Line - Wire Down/ Catenary or Wayside Failure

07JUL26: At 157P-ET, Boston Chief reported wires down behind 333 School St between Mansfield MP 204.0 and Holden MP 198.1. The Mansfield Fire department requested a hold on all tracks. Power Director reported they could not hold power between Norton DED and Mansfield. As of 207P-ET, Mansfield Fire department reported a tree down between MP 202.48 and MP 202.50. Amtrak Road Foreman was enroute. Train 137(07) was held at MP 204.3 and was able to maintain HEP. As of 421P-ET, The branches were removed from MP 202.48-MP 202.50.

Train	Delay	Comment
137(07)	55"	

CSX Heat Orders - Weather

07JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Kanawha, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(07)	28"	
98(07)	37"	
52(07)	07"	
97(06)	30"	

Train 644(07) Philadelphia, PA - Cab Car Failure

07JUL26: Train 644(07) with E/664 and 5 "UNCLASSIFIED" due to operating without a cabcar making it necessary to wye the equipment after departing Philadelphia.

This also delayed train 645(07) in New York due to the late arrival and adding E/654.

Train	Delay	Comment
644 (07)	46"	
645 (07)	52"	

Train 173(07) Boston, MA - Servicing

07JUL26: Train 173(07) with E/636, E/658 and 10 cars with 231 customers onboard was delayed departing Boston due to the late release from the yard waiting on the engines.

Train	Delay	Comment
173 (07)	53"	

Train 40(07) Miami, FL - Servicing

07JUL26: Train 40(07) was delayed departing Miami due to the late turn off 41(04) that arrived at 655A-ET 12 hours and 46 minutes. Due to this service recovery was initiated in the station with snack packs and bottled water.

Additional Service Recovery was given for customer with all coach passengers offered beef stew, rice and bottled water and First Class passengers were served lunch from the diner as normal.

Train	Delay	Comment
40 (07)	2'24"	

Train 97(06) Savannah, GA - Car Failure

07JUL26: Train 97(06) with E/148, E/180 and 10 cars was delayed on the CSX Savannah subdivision at the station due to having trainline issues. The crew worked with CNOC Mechanical and were able to correct the problem by short looping the C/61039 baggage car.

Train	Delay	Comment
97 (06)	1'14"	

New York Initial Terminal Delays - Servicing

07JUL26: Several trains were delayed departing New York due to a TOL in the yard and late release of equipment.

Train	Delay	Comment
63 (07)	33"	
181 (07)	27"	
89 (07)	07"	
183 (07)	1'50"	
607 (07)	41"	
19 (07)	20"	
97 (07)	2'36"	

Train 52(07) - North of Florence, SC - Freight Train Interference

08JUL26: Train 52(07) delayed on the CSX North End subdivision at MP 247.9 due to CSX Train M410-07 being disabled ahead of it. CSX Mechanical was dispatched to the scene with an initial estimated arrival time of plus 90". CSX suggested Train 52(07) shove back to the previous CP to be routed around, but that was ruled out because the Conductor would have to hang from the last auto-carrier car to ride the point.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(07)	2'45"	Estimated

CSX Washout - East of Pittsburgh, PA - Mudslide/Washout

07JUL26: CSX reported a track washout on the Pittsburgh subdivision 7 miles west of Connellsville on main track 1 at MP 276.25 and main track 2 at MP 277.9 with no route or estimated time of opening. Heavy equipment was necessary to repair main track 1. CSX M/W was working to shovel main track 2 by hand and if the rock bed is solid enough with favorable conditions for train movement could possibly continue. As a result train 40(05) was shoved back to Connellsville station and held for disposition. Train 41(06) was held at Pittsburgh station for disposition. A potential bus bridge was set up with buses secured for customers between Connellsville and Pittsburgh. Busses were ordered for a possible bus bridge and arrived but were held until trains departed.

UPDATE: CSX Initially stated open track at 645A-ET. Then pushed open track until 8A-ET. Tracks were open at 810A-ET and both trains were able to operate thru the area at restricted speed.

Train 41(06) was further delayed due to meeting 40(05) at MP 16.9 on the CSX Pittsburgh BF subdivision.

WBS#: B.TR.100150.6864

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(06)	2'26"	
41(06)	1'04"	meeting 40(05)
40(05)	7'40"	

Train 66(06) Roanoke, VA - Engine Failure

06JUL26: Due to E/310 upon arrival on train 151(06) into Roanoke shut down with a low hydrostatic oil fault. Mechanical/Rail plan was inspecting for active leaks. Due to this train 66(06) was cancelled from Roanoke to Boston with alternate buses from Roanoke to Washington. Train 198(06) was held in Washington for the arrival of the buses from Roanoke. Train 67(07) will originate in Washington and will be cancelled between Boston and Washington.

The NS did secure E/NS9934 to operate deadhead equipment of 66(06) Roanoke to Washington estimated to depart between 830P-930P-ET.

UPDATE: The equipment did not depart Roanoke until 503A-ET on 7/7/26 12 hours and 40 minutes late. The equipment arrived into Washington at 1115A-ET. The NS E/9934 was planned to be returned to Roanoke on train 171(08).

WBS#: B.TR.100150.6861

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66(06)	CANCELLED	BUSES RNK-WAS
67(07)	ORIG WAS	CANCELLED BOS-WAS
198(06)	3'07"	held for buses was
66(06)	12'40"	DP RNK

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, 26-FCI-00390, 00000008304, UNCLASSIFIED, 7/16/2028 Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
66 (6)	RNK	NS9934	E/310 hydraulic oil leak		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train 50(07) Cincinnati, OH - Engine Failure

08JUL26: Train 50(07) with E/366, five cars, and 82 customers was delayed on the CSX Cincinnati Terminal subdivision due to E/366 with a fuel supply low pressure fault and a clogged fuel filter. As a result, a freight unit was requested through CSX and south facing CSX 5240 was delivered by a CSX yard crew, who assisted the Amtrak crew in tying on the locomotive to the lead of 50(07).

Train	Delay	Comment
50(07)	Est. 1'00"	

Train 703(07) Stockton, CA - Third Party Contractor Engine Failure

08JUL26: Train 703(07), operating with locomotive E/C2013 and six cars, was delayed at Stockton Downtown-ACE Station while the crew troubleshooted a main reservoir air issue. The locomotive was unable to maintain proper air pressure unless operating above throttle notch 1, prompting coordination with Mechanical personnel. After assessment, the train was permitted to continue to Sacramento, CA, where technicians were placed on standby to further inspect and address the issue.

Train	Delay	Comment
703(07)	34"	

Train 4(07) West of Needles, CA - Freight Train Interference

08JUL26: Train 4(07), carrying 203 customers onboard, was delayed west of Needles, CA, while holding at East Amboy (MP 660.2) on the BNSF Needles Subdivision due to congestion resulting from a freight train derailment ahead, 1 car that remained upright. The derailment blocked Main Track 2, requiring trains to operate through the area under single-track conditions. During the delay, Train 4(07) met BNSF 7843 and BNSF 8130 while awaiting a route through the affected territory.

Train	Delay	Comment
4(07)	34"	

Train 22(07)/422(05) North of Marshall, TX - Freight Train Interference

07JUL26: Train 22(07) with 240 customers was delayed on the UPRR Little Rock subdivision starting 28 miles north of Marshall between Kildare/MP 38.0 and Sulphur/MP 8.7 due to following MEGASX-06 and ZSAYC-07.

Train	Delay	Comment
22(07)/422(05)	39"	

Train 48/448(07) Chicago, IL - Initial Terminal Delay

07JUL26: Train 48/448(07) with 210 customers was delayed departing Chicago due to a late release account of replacement E/199 that was utilized off inbound train 4(05) that arrived Chicago at 354PM-CT, 25 minutes late. It was necessary to utilize E/199 due to E/106 held off 49/449(06) for train 41(07) account of a locomotive shortage. Once the equipment was released and set in the station, 48/448(07) departed Chicago at 1015PM-CT, 45 minutes late.

Union Pacific Railroad - CETC System

08JUL26: 1020PM-ET, UPRR Sedalia subdivision, the UNCLASSIFIED CETC system failure and unable to line signals. Several trains were delayed enroute until the issue was rectified.

Train	Delay	Comment
2 (05)	1'17"	W/NOL - West Bridge Jct./MP 10.2
22 (07) / 422 (05)	45"	S/TXA - Sulphur/MP 8.7
21 (06)	21"	N/SAS
21 (07)	16"	N/ACD
5 (06)	25"	E/HER

Train 355(07) West of Michigan City, IN - Trespasser Incident

07JUL26: Train 355(07) with E/ID4627, five cars, and E/58 was delayed on the Amtrak Michigan Line four miles west of Michigan City at MP 232.73 due to an engineer initiated emergency where the crew stopped and avoided striking a teenager standing in the right of way and filming the train. There were no reported injuries to the 259 customers or crew.

Train	Delay	Comment
355 (07)	12"	

Train 6(07) East of Winnemucca, NV - Heat Orders

07JUL26: Train 6(07), carrying 158 customers onboard, was delayed east of Winnemucca, NV, on the Union Pacific Elko Subdivision due to heat-related speed restrictions. The train was required to operate at reduced speeds between approximately MP 535.7 and MP 612 under heat order conditions.

Train	Delay	Comment
6 (07)	32"	

Train 316(07) West of Sedalia, MO - Freight Train Interference

07JUL26: Train 316(07) with 40 customers was delayed on the UPRR Sedalia subdivision 17 miles west of Sedalia at Dresden/MP 195.7 due to meeting Amtrak train 319(07) and MASNP-07. Further delay was accumulated 20 miles east of Sedalia at Dow/MP 165.2, meeting GME2GL-07 and IG4SIX-06 as well as meeting ZMNNP-07 and IG4LB-07 at Shell/MP 151.6. A final meet occurred with CWLNA9-05 at Centertown/MP 140.2.

Train	Delay	Comment
316 (07)	05"	Dresden - 319 (07)
316 (07)	35"	Dresden - MASNP-07
316 (07)	20"	Dow
316 (07)	15"	Shell
316 (07)	20"	Centertown

Train 19(06) North of New Orleans, LA - Freight Train Interference

07JUL26: Train 19(06) was delayed on the NS NO&NE district ten miles north of New Orleans due to meeting 131 at Northeast Tower/MP 193.5.

Train	Delay	Comment
19 (06)	41"	

Train 319(07) West of Sedalia, MO - Freight Train Interference

08JUL26: Train 319(07) with E/ID4630, five cars, and 147 customers was delayed on the UPRR Sedalia subdivision due to following unknown freight between Sedalia/MP 188.9 and Warrensburg/MP 218.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319 (07)	39"	

Train 703(07) West of Bakersfield, CA - Freight Train Interference

07JUL26: Train 703(07), carrying 48 customers onboard, was delayed west of Bakersfield, CA, while holding at Lopez (MP 892.3) on the BNSF Bakersfield Subdivision due to BNSF freight train ZSTOWSP507A (BNSF 5094) being stopped in emergency ahead. Investigation determined that multiple air hoses on the freight train had been cut by vandals, requiring replacement before the train could proceed. As a result, Train 714(07), carrying 39 customers onboard, was also delayed on the opposite side of the incident while awaiting clearance. Once the damaged air hoses were replaced and the freight train resumed movement, Train 703(07) continued westward, followed by Train 714(07) proceeding into Bakersfield Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703 (07)	1'30"	
714 (07)	1'00"	

Train 354(07) Albion, MI - Car Failure

07JUL26: Train 354(07) with E/ID4630, five cars, and 147 customers was delayed on the Amtrak Michigan Line at Albion/MP 95.7 due to the crew reporting a condemnable flat spot on C/ID4129 at the L3 position. An Amtrak road foreman responded to the scene to assist. The flat spot was confirmed condemnable and married pair C/ID4129-4306 was set out at Albion siding/MP 96.2. As a result, train 354(07) was terminated at Albion with three buses secured as alternate transportation. Buses arrived on scene at approximately 1230AM-ET to accommodate all customers. Once the married pair was set out at Albion, the equipment was moved to wye at Milwaukee Jct./MP 54.8. The equipment was restricted to 30mph over all crossings on CN territory due to axle count. After the equipment was through the wye it was deadhead back to Chicago. In conclusion, train 353(08) was cancelled between Pontiac and Chicago with five buses secured as alternate transportation for 240 customers enroute to Chicago.

WBS#: B.TR.100150.6866

Train 4(06) East of Trinidad, CO - Temporary Speed Restrictions

07JUL26: Train 4(06), carrying 213 customers onboard, was delayed east of Trinidad, CO, on the BNSF Raton Subdivision due to multiple temporary speed restrictions in the territory. The train operated at a maximum speed of 25 MPH between MP 605 and MP 595, with additional reduced-speed zones in effect between MP 591.1 and MP 598.8 and MP 582.7 and MP 581.9. Once clear of the temporary restrictions, Train 4(06) resumed normal operation and continued its eastbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4 (06)	30"	

Train 21(06) South of Austin, TX - Engine Failure

07JUL26: Train 21(06) 26-FOT-00595/600000093045 ix UNCLASSIFIED 79 7/15/2026 ers was delayed on the UPRR Austin subdivision one mile south of Austin at MP 180.31 due to air brake issues on E/63. The crew reset the air brake computer to rectify the issue and continued to San Marcos.

Train	Delay	Comment
21(06)	45"	

Train 306(07) South of Pontiac, IL - Signal

07JUL26: Train 306(07) was delayed just south of Pontiac on the UPRR Joliet subdivision due to switch issues at X093/MP 92.5. The crew took the switch in hand and continued to Pontiac.

Train	Delay	Comment
306(07)	57"	

Train 8(07) East of Seattle, WA - Sounder Trespasser Strike

07JUL26: At approximately 5:12 PM PT, Train 8(07), carrying 107 customers onboard, was delayed while holding at Blue Ridge (MP 9.1) on the BNSF Scenic Subdivision due to a trespasser fatality involving Sounder Train 1702 ahead at MP 10.4. All rail traffic in the area was halted while local authorities conducted their investigation. The incident was confirmed as a fatality, with the Medical Examiner arriving on scene at approximately 7:07 PM PT. As a result of the incident, Train 518(07), carrying 183 customers onboard, was initially held at Seattle, WA Station and later advanced to MP 4.7 on the BNSF Scenic Subdivision pending resolution of the incident. Once the investigation was completed and the scene was released by authorities, rail traffic resumed and both trains continued their respective trips.

Train	Delay	Comment
8(07)	2'46"	
518(07)	1'45"	

Train 50(07) East of Chicago, IL - Engine Failure

07JUL26: Train 50(07) with E/753, three cars, E/366, five cars, and 95 customers was delayed on the NS Chicago district five miles east of Chicago due to loading issues on E/753. The issues persisted enroute to Indianapolis. It was said that this issue was related to the new PTC software download that was not implemented on E/753.

Train	Delay	Comment
50(07)	2'08"	

Train 8/28(06) West of Glasgow, MT - Freight Train Interference

07JUL26: Train 8/28(06), carrying 232 customers onboard, was delayed while operating between Malta, MT, and Glasgow, MT, on the BNSF Milk River Subdivision due to a freight train meet. The train held at Hinsdale Siding (MP 304.7) to meet BNSF 7542.

Train	Delay	Comment
8/28(06)	45"	

Train 5(05) East of Sacramento, CA - Fire Near ROW

07JUL26: Train 5(05) with 131 customers was delayed just east of Sacramento, CA Station, while holding at MP 90.8 on the Union Pacific Martinez Subdivision due to a fire near the railroad right-of-way. The train remained stopped while the local fire department responded and worked to contain the fire. Once the area was secured and the track was released for service, Train 5(05) proceeded into Sacramento Station without further incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(05)	33"	

Train 319(07) East of Hermann, MO - Freight Train Interference

07JUL26: Train 319(07) with 131 customers was delayed on the UPRR Jefferson City subdivision eight miles east of Hermann due to meeting ITUG4-04 at Berger/MP 72.9.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(07)	34"	

Train 40(05) West of Sandusky, OH - Temporary Speed Restrictions

07JUL26: Train 40(05) with 241 customers was delayed on the NS Toledo District starting 22miles west of Sandusky due to temporary speed restrictions between MP 263.0 and MP 273.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(05)	32"	

Train 2(05) East of Lake Charles, LA - Signal

07JUL26: Train 2(05) was delayed on the BNSF Lafayette subdivision 28 miles east of Lake Charles due to signal issues at East Roanoke/MP 190.5

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(05)	37"	

Train 20(07) Picayune, MS - Police Related

07JUL26: Train 20(07), with 101 customers, was delayed at Picayune, MS/MP149.14, on the NS NO and NE District, due to a semi stuck on a crossing just north of Picayune. Train 20(07) was delayed holding for vehicle removal and track inspection ahead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(07)	36"	

Train 24(07) South of Bay Saint Louis, MS - Freight Train Interference

07JUL26: Train 24(07) was delayed at MP754, just south of Bay Saint Louis, MS, on the CSX NO&M Subdivision, meeting CSX M605.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(07)	39"	

Train 318(07) West of Sedalia, MO - Engine Failure

07JUL26: Train 318(07) E/IDTX4606, 1600000008304 cars, UNCLASSIFIED, 26-FOI-00590, 7/15/2028, was delayed at MP193.2, 5 miles west of Sedalia, MO, on the UPRR Sedalia Subdivision, due to air compressor issues on E/IDTX4606. Train maintained HEP. Crew contacted mechanical to troubleshoot. After working with mechanical and engine tech, air compressor issue was still unresolved. Mechanical forces from Kansas City and Road Foreman from St. Louis responded to assist. Train 311(07), with 83 customers, was delayed at Jefferson City, MO/MP125.5, on the UPRR Jefferson City Subdivision, due to Train 318(07) disabled ahead on the single Main. Due to the ongoing mechanical issues, five busses were secured as possible alternate transportation. A freight engine, E/UP8384 was cut off MASHN-06 at Smithton/MP184, advanced to MP193.2 and was added ahead of E/IDTX4606 on Train 318(07). Once freight engine was added, Train 318(07) resumed live operation to Chicago, IL. Passengers scheduled to board Train 318(07) between St. Louis, MO and Joliet, IL, were notified of the late operation and advised Train 306(07) was a possible alternate to Chicago. Train 311(07) held at Jefferson City for dispo of Train 318(07) and then further delayed at MP167 meeting Train 318(07). Train 316(07) was delayed departing Kansas City due to late turn of equipment off Train 311(07).

WBS B.TR.100150.6865

WBS#: B.TR.100150.6865

Train	Delay	Comment
318(07)	4'32"	
311(07)	3'15"	JEF, held for dispo of 318(07) a/h
311(07)	46"	W/JEF, MP166, meet 318(07)
316(07)	2'58"	KCY - late turn of equip 311(07)
318(07)	1'02"	Operating with freight locomotive

Train 27(05) Vancouver, WA - Police Related

07JUL26: Train 27(05) was delayed departing the Vancouver, WA station account of an investigation of an alleged assault that occurred on the train. One customer was removed from the train by local police.

Train	Delay	Comment
27(05)	1'02"	

Train 20(07) Late Departure New Orleans, LA - Turn of Equipment

07JUL26: Train 20(07), E/107-E/152 & 8 cars, with 89 customers, was delayed departing New Orleans, LA, due to late turn of equipment off Train 19(05) which arrived at 509AM-CT, 7 hours and 57 minutes late.

Train	Delay	Comment
20(07)	3'19"	

Train 21(06) South of Arcadia, MO - Signal Issues

07JUL26: Train 21(06) was delayed south of Arcadia, MO/MP88.8, on the UPRR DeSoto Subdivision, due to signal issues between Tip Top/MP91.4 and MP107.1. Train 21(06) was delayed operating through the affected area.

Train	Delay	Comment
21(06)	36"	

Train 329(07) West of Sturtevant, WI - Animal Strike

07JUL26: Train 329(07) with E/319, five cars, and 65 customers, was delayed at MP66.6, 3 miles west of Sturtevant, WI, on the CPKC C&M Subdivision, due to striking a horse on Main 1. There were no reported injuries to passengers or crew. The crew performed Class II brake test and Train 329(07) was able to proceed west.

Train	Delay	Comment
329(07)	11"	

Train 19(05) South of Hattiesburg, MS - Freight Train Interference

07JUL26: Train 19(05) with 91 customers was delayed on the NS NO&NE district nine miles south of Hattiesburg at Richburg/MP 94.5 due to meeting 346-06.

Train	Delay	Comment
19(05)	33"	

Train 4(06) West of Kingman, AZ - Passenger Train Interference

07JUL26: Train 4(06), with 222 customers, was delayed at East Griffith / MP 526.9 on the Burlington Northern Santa Fe Seligman Subdivision, 11 miles west of the Kingman, AZ station, meeting Train 3(05).

Train	Delay	Comment
4(06)	44"	

Train 352(06) West of Michigan City, IN - System

06JUL26: Train 352(06) with E/319, five cars, and 235 customers was delayed on the Amtrak Michigan Line 10 miles west of Michigan City at CP 239 due to ITCS issues on E/319. The crew continued two miles east of Michigan City to CP 226 where ITCS was cut out and the crew was required to continue not exceeding 59mph per rule.
07JUL26: Train 351(07), E/319 & five cars, was delayed enroute west of Dearborn, MI to Chicago, IL, operating reduced speed, 59MPH MAX, due to E/319 ITCS inoperative.

Train	Delay	Comment
352(06)	1'04"	
351(07)	1'24"	

UPRR Jefferson City Subdivision - Severe Weather

04JUL26: Due to extreme weather on the UPRR Jefferson City subdivision, between Jefferson City, MO and Hermann, MO. UPRR dispatched Maintenance of Way personnel to remove downed trees from several locations. UPRR personnel reported downed wires in several locations as well. While enroute to the original reported locations of the downed trees, MOW kept finding other trees on the tracks that needed to be removed. Train 316(04) held at Jefferson City, MO for an open route and train 319(04) was initially held East of Hermann, MO and then West of Hermann, MO. Due to the extended delay buses were secured to accommodate customers. Buses arrived at a crossing 1 mile east of Jefferson City for train 316(04) at approximately 2:50am-ct and all customers were safely transferred to buses. Amtrak Road Foreman arrived on location of 319(04) at approximately 3:50am-ct as well as the buses. At 3:45am-ct, UPRR reported that there was an 11 mile stretch with 40 trees across the tracks that required heavy equipment to remove. As a result the following service adjustments have been made:

- Train 316(04) was terminated at Jefferson City, MO with alternate buses provided.
- Train 319(04) was terminated at Hermann, MO with alternate buses provided.

05JUL26: At 10:00AM-CT, Main Track 1 was returned to service for 316(04) and 319(04)'s equipment to deadhead to their destination. At 12:30PM-CT, Main Track 2 was returned to service. Due to heavy freight interference from tied down equipment and lack of staffing, additional service adjustments were set in place:

- Train 311(05) was cancelled entirely with no alternate buses provided.
- Train 316(05) was cancelled entirely with three alternate buses provided.
- Train 318(05) originated at St. Louis, MO with no alternate buses provided. Inbound Train 319(05)'s equipment was turned at St. Louis to represent Train 318(05) which resulted in a departure delay.
- Train 319(05) terminated at St. Louis, MO with 8 buses secured between St. Louis and Kansas City.

06JUL26: UPRR advised that signal power issues and freight train interference continued on the Jefferson City subdivision between Jefferson City and Washington with one train tied down and flagging between MP 73.0 and MP 124.0. As a result, the following service adjustments were implemented:

- Train 311(06) was cancelled entirely with three alternate buses between St. Louis and Kansas City.
- Train 316(06) was cancelled entirely with one bus as alternate transportation between Kansas City and St. Louis.
- Train 319(06) terminated at St. Louis, with three busses as alternate transportation between St. Louis and Kansas City.
- Train 318(06) originated at St. Louis off train 319(06) equipment. No available alternate transportation.

It was necessary for Chicago to add an additional locomotive to send to St. Louis to fill out service for the Missouri River Runner service on July 7 due to E/ID4609 shopped for multiple faults and deadhead in trail back to Chicago on train 302(06).

07JUL26: UPRR reported improved conditions on the Jefferson City subdivision with some locations remaining on generator power with sporadic track lights and PTC issues. Amtrak planned to resume full service on the route.

WBS#: B.TR.100150.6855

Train	Delay	Comment
311(05)	Cancelled	
318(06)	36"	STL, turn of equipment off 319(06)
319(05)	Terminated	
	STL	
316(05)	Cancelled	
316(04)	Terminated	
	JEF	
319(04)	Terminated	
	JEF	
318(05)	32"	STL, turn of equipment off 319(05)
311(07)	35"	W/HEM, enroute signal issues

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans ~~26-FOI-09590~~ ~~100000108304~~ ~~UNCLASSIFIED~~ ~~7/15/2026~~ during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. CN performed track inspections between Carbondale and New Orleans and no track defects were identified. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

06JUL26: City of New Orleans service adjustments were updated as follows:

- Train 59(07) operated normal, Chicago, IL to New Orleans, LA.
- Train 58(07) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(08) cancelled entirely, no alternate transportation between Chicago and New Orleans.

59 (26) Terminated JAN
 58 (27JUN-07JUL) Cancelled
 59 (27JUN-06JUL, 08JUL) Cancelled

26-FOI-00590 00000008304 "UNCLASSIFIED" 7/15/2026

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station, located at MP 588.2 on the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV)/421 (14NOV)	Bypass PSN	
1 (18-21FEB)/421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30)/421 (29) (MAR)	Bypass PSN	
1 (01APR)/421 (31MAR)	Bypass PSN	
1 (04APR)/421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN)/421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL, 07JUL, 10JUL)	00"	BYPASS PSN
1 (01, 04, 08JUL)/ 421 (03, 07JUL)		BYPASS PSN

Maintenance of Way Highlights

BNSF Track Work West of Macomb, IL - Carl Sandburg Service

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th. To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL) and Train 382(13JUL-17JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL) and Train 381(13JUL-17JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has replaced the replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00590 k 000000083041ed "UNCLASSIFIED" C&M 7/15/2026 Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region**Equipment Set Out & Damage Disposition**

Train	Location	Eng	Car	Reason/Disposition
59 (29)	JAN	62		Wheels

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
318 (7)	SED	UP8384	E/4606 failed air compressor	CHI	7/8/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 318(07) Passenger Removal Boarding Jefferson City, Missouri – Improper Conduct***

07JUL26, Passenger on, PNR 17EC57 traveling from Kansas City, MO to Chicago, IL reportedly was severely intoxicated and being disorderly. He was talking on his phone threatening to get off the train to buy a gun and harm others. Conductor made the decision to contact local authorities to have him removed at Jefferson, Missouri. Passenger was removed by Jefferson City Police. Amtrak Police notified

Delay: 318 (07) 17"

Consist Deviations

26-FOI-00590

00000008304

"UNCLASSIFIED"

7/15/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
230 (07)	ALB	230(07) is operating with a club-dinette in lieu of a sleeper.	NONE	0	48172
7/27 (07)	CHI	SLEEPER REPLACED WITH CREW DORM	YES	8	39010
48 (07)	CHI	reported hot car, will deadhead in line. inv reduced	YES	3	25054
644 (07)	HAR	CAB CAR REPLACED WITH CAFE	NONE	0	43389
654 (07)	HAR	654(07) operating with 4 coaches and cafe for Wi-Fi, no cab car. No impact on passenger capacity.	NONE	0	43389
650 (07)	HAR	650(07) will operate with 5 coaches and a cafe for Wi-Fi services. There is no cab car and passenger capacity remains at 354.	NONE	0	43379
655 (07)	HAR	82517 shopped in NYP due B/O HVAC, consist now operating with 3 coaches and cab car. No impact to passengers.	NONE	0	82517
626 (07)	HAR	626(07) will operate with 5 coaches and no cab car. There will be no Wi-Fi services passenger capacity is increased 6 seats.	NONE	0	82764
138 (07)	NFK	138(07) operating with a Business Class car in lieu of a coach and a club-dinette in lieu of a cafe car.	yes	13	81511
645 (07)	NYP	645(07) operating with 4 coaches and cafe for Wi-Fi, no cab car. No impact on passenger capacity.	NONE	0	43389
639 (07)	NYP	639(07) operating with 4 coaches and cafe for Wi-Fi, no cab car. No impact on passenger capacity.	NONE	0	43389
641 (07)	NYP	641(07) will operate with 5 coaches and a cafe for Wi-Fi services. There is no cab car and passenger capacity remains at 354.	NONE	0	43379
653 (07)	NYP	653(07) will operate with 5 coaches and a cafe for Wi-Fi services. There is no cab car and passenger capacity remains at 354.	NONE	0	43379
69 (07)	NYP	230(07) is operating with a club-dinette in lieu of a sleeper.	NONE	0	48172
646 (07)	NYP	82517 shopped in NYP due B/O HVAC, consist now operating with 3 coaches and cab car. No impact to passengers.	NONE	0	82517

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
649 (07)	NYP	649(07) will operate with 5 coaches and no cab car. There will be no Wi-Fi services passenger capacity is increased 6 seats.	NONE	0	82764
601 (07)	PHL	CAB CAR REPLACED WITH CAFE	NONE	0	43389
178 (07)	RNK	178(07) will operate short a coach due to lack of equipment. There is no impact to passenger capacity.	none	0	
587 (07)	SAN	90215 cab car- no bikes, no WIFI. Notify passengers.	NONE	0	90215

Reverse Consists

Train Number	Station	Reason
183 (07)	NYP	Consist reversed Business class seat orientation may have changed At Front
86 (07)	NPN	Consist reversed Business class seat orientation may have changed At Front
190 (07)	PHL	Consist reversed Business class seat orientation may have changed At Front
136 (07)	WAS	Consist reversed Business class seat orientation may have changed At Front
179 (07)	BOS	Consist reversed Business class seat orientation may have changed At Front
137 (07)	BOS	Consist reversed Business class seat orientation may have changed At Front
125 (08)	SPG	Consist reversed Business class seat orientation may have changed At Front
86 (08)	NPN	Consist reversed Business class seat orientation may have changed At Front
179 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (07)	BOS	Business class change only Business class seating orientation may have changed At Rear