

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, January 07, 2026

Rules: 0-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-0022Initial Terminal Performance By Division

Scheduled Departure Date: 01/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/06/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	52	82.8%	1,752	252	85.6%	29,058	3,924	86.5%
Central Division	85.5%	66	9	86.4%	405	42	89.6%	6,487	709	89.1%
Northeast Division	80.0%	97	18	81.4%	556	87	84.4%	9,172	1,368	85.1%
Southeast Division	72.5%	70	10	85.7%	390	60	84.6%	6,737	937	86.1%
Southwest Division	77.0%	70	15	78.6%	401	63	84.3%	6,662	910	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00235 00000005580 UNCLASSIFIED Endpoint Arrival Dates through 1/6/26 1/14/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	72,209	10,255	86%	534,574	103,315	81%	9,829,950	2,139,880	78%
Northeast Corridor	81%	30,630	3,792	88%	228,796	45,675	80%	4,385,637	926,639	79%
Acela	83%	5,055	2,115	58%	40,398	12,783	68%	923,818	223,811	76%
Northeast Regional	79%	25,575	1,677	93%	188,398	32,892	83%	3,461,819	702,828	80%
Richmond / Newport News / Norfolk	77%	7,953	1,248	84%	58,430	11,637	80%	1,059,731	244,678	77%
Springfield Shuttles	89%	522	72	86%	3,858	451	88%	55,531	6,375	89%
Roanoke	79%	2,019	41	98%	14,442	1,304	91%	267,312	44,926	83%
On Spine Northeast Regional	80%	15,081	316	98%	111,668	19,500	83%	2,079,245	406,849	80%
State Supported	80%	31,809	5,006	84%	227,722	38,838	83%	4,196,465	801,079	81%
Borealis	60%	330	0	100%	2,640	278	89%	56,548	14,156	75%
Capitol Corridor	90%	3,489	526	85%	17,964	1,971	89%	337,581	35,731	89%
Carolinian	60%	796	6	99%	5,609	578	90%	112,839	30,909	73%
Cascades	63%	1,326	242	82%	14,376	2,102	85%	234,895	54,538	77%
Downeaster	82%	1,132	19	98%	6,666	246	96%	141,737	17,951	87%
Empire	78%	3,903	856	78%	31,789	6,688	79%	521,463	107,120	79%
Adirondack	72%	241	78	68%	2,593	907	65%	33,679	12,443	63%
Ethan Allen Express	70%	375	0	100%	3,161	603	81%	57,689	16,801	71%
Maple Leaf	70%	414	234	43%	4,232	2,566	39%	57,128	24,235	58%
New York - Albany	85%	1,888	518	73%	14,187	1,365	90%	239,124	31,548	87%
New York - Niagara Falls	75%	985	26	97%	7,616	1,247	84%	133,843	22,093	83%
Gold Runner	73%	1,915	766	60%	15,365	5,659	63%	248,204	90,616	63%
Heartland Flyer	65%	103	0	100%	1,194	141	88%	20,833	8,490	59%
Hiawatha	90%	1,100	411	63%	7,496	797	89%	166,927	20,366	88%
Illinois	78%	1,407	345	75%	12,654	1,491	88%	236,962	66,658	72%
Carl Sandburg / Illinois Zephyr	85%	230	68	70%	2,531	145	94%	41,658	10,448	75%
Illini / Saluki	85%	442	255	42%	4,114	811	80%	82,125	22,029	73%
Lincoln Service	70%	735	22	97%	6,009	535	91%	113,179	34,181	70%
Keystone	92%	7,856	495	94%	36,910	1,387	96%	781,630	75,801	90%
Lincoln / Missouri	60%	485	240	51%	4,591	564	88%	77,067	35,782	54%
Mardi Gras Service	80%	289	0	100%	2,506	203	92%	42,628	4,929	88%
Michigan	69%	1,590	594	63%	11,268	4,112	64%	192,710	59,697	69%
Blue Water	70%	321	0	100%	2,196	1,078	51%	46,793	14,947	68%
Pere Marquette	85%	168	136	19%	1,289	406	69%	25,745	4,714	82%
Wolverine	65%	1,101	458	58%	7,783	2,628	66%	120,172	40,036	67%
Missouri	80%	96	8	92%	1,345	160	88%	23,710	5,258	78%
Pacific Surfliner	85%	3,756	403	89%	37,205	10,409	72%	655,173	99,272	85%
Pennsylvanian	72%	707	0	100%	5,384	60	99%	91,040	9,803	89%
Piedmont	73%	624	95	85%	5,823	942	84%	123,689	28,635	77%
Vermont	75%	905	0	100%	6,937	1,050	85%	130,829	35,367	73%
Long Distance	56%	9,770	1,457	85%	76,413	18,802	75%	1,243,137	411,895	67%
Auto Train	57%	903	0	100%	6,200	0	100%	69,995	10,760	85%
California Zephyr	50%	1,006	68	93%	6,808	953	86%	93,463	25,793	72%
Cardinal	55%	0	0	-	1,474	477	68%	26,979	11,765	56%
City Of New Orleans	75%	489	223	54%	3,999	328	92%	69,733	14,759	79%
Coast Starlight	60%	406	119	71%	5,466	2,912	47%	115,067	37,640	67%
Crescent	70%	562	0	100%	5,356	225	96%	95,518	21,204	78%
Empire Builder	55%	949	425	55%	6,483	3,104	52%	100,359	38,958	61%
Floridian	40%	1,614	209	87%	10,729	4,962	54%	170,077	92,345	46%
Lake Shore Ltd	73%	834	8	99%	5,888	814	86%	95,409	19,806	79%
Palmetto	65%	672	23	97%	5,037	148	97%	94,714	15,387	84%
Silver Meteor	45%	830	276	67%	6,173	1,749	72%	102,754	32,720	68%
Southwest Chief	40%	761	77	90%	4,959	1,809	64%	81,634	47,991	41%
Sunset Ltd	70%	0	0	-	1,618	200	88%	28,325	6,367	78%
Texas Eagle	50%	744	29	96%	6,223	1,121	82%	99,110	36,400	63%
Seasonal Trains	%	0	0	-	1,643	0	100%	4,711	267	94%
Winter Park Express	75%	0	0	-	1,643	0	100%	4,711	267	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00205 00000005500 "UNCLASSIFIED" 1/14/2020

Train Index Dates Through January 06, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	32,074	629,476	510	560,350	10,489,867	534

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,292	176,983	73	22,031	3,058,960	72
INFRASTRUCTURE PLANNED	135	530	176,983	30	15,905	3,058,960	52
FLEET RELIABILITY	90	6,476	629,476	103	89,756	10,489,867	86
TRAIN OPERATIONS	424	23,776	629,476	378	432,658	10,489,867	412

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

26-FOI-0022Initial Terminal Performance By Division

Scheduled Departure Date: 01/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/06/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	52	82.8%	1,752	252	85.6%	29,058	3,924	86.5%
Central Division	85.5%	66	9	86.4%	405	42	89.6%	6,487	709	89.1%
Northeast Division	80.0%	97	18	81.4%	556	87	84.4%	9,172	1,368	85.1%
Southeast Division	72.5%	70	10	85.7%	390	60	84.6%	6,737	937	86.1%
Southwest Division	77.0%	70	15	78.6%	401	63	84.3%	6,662	910	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00241 Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/06/2026
Amtrak or Commuter: Amtrak

Location	Target	ITP 01/06/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	52	82.8%	1,752	252	85.6%	29,058	3,924	86.5%
Central Division	85.5%	66	9	86.4%	405	42	89.6%	6,487	709	89.1%
CDL	90.0%	2	0	100.0%	12	0	100.0%	167	8	95.2%
CHI	85.0%	28	7	75.0%	163	23	85.9%	2,629	302	88.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	3	0	100.0%	9	2	77.8%
EUG	86.5%	2	0	100.0%	12	2	83.3%	190	28	85.3%
GRR	98.0%	1	0	100.0%	6	0	100.0%	97	3	96.9%
KCY	84.5%	2	0	100.0%	12	0	100.0%	193	15	92.2%
MKE	86.5%	6	1	83.3%	35	1	97.1%	572	47	91.8%
MSP	94.0%	1	0	100.0%	5	0	100.0%	97	3	96.9%
PDX	78.0%	4	0	100.0%	29	3	89.7%	490	64	86.9%
PNT	91.5%	3	0	100.0%	18	1	94.4%	236	23	90.3%
PTH	93.0%	1	0	100.0%	6	1	83.3%	97	8	91.8%
QCY	87.5%	2	0	100.0%	12	1	91.7%	196	18	90.8%
SEA	80.0%	7	0	100.0%	47	7	85.1%	778	126	83.8%
SPK	92.0%	1	0	100.0%	6	1	83.3%	101	6	94.1%
STL	88.0%	4	1	75.0%	24	1	95.8%	387	39	89.9%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	12	0	100.0%	191	6	96.9%
WIP	-	-	-	-	3	1	66.7%	9	1	88.9%
Northeast Division	80.0%	97	18	81.4%	556	87	84.4%	9,172	1,368	85.1%
ALB	91.5%	8	1	87.5%	48	4	91.7%	663	50	92.5%
BON	43.5%	5	1	80.0%	30	2	93.3%	471	46	90.2%
BOS	86.5%	18	3	83.3%	105	20	81.0%	1,785	229	87.2%
BRK	88.0%	5	0	100.0%	30	2	93.3%	451	22	95.1%
BTN	48.0%	1	0	100.0%	6	0	100.0%	97	18	81.4%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	1	1	0.0%	11	2	81.8%	187	17	90.9%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	6	2	66.7%	98	19	80.6%
NFL	96.5%	2	0	100.0%	12	0	100.0%	197	8	95.9%
NHV	75.5%	6	2	66.7%	31	6	80.6%	510	87	82.9%
NYP	77.5%	42	8	81.0%	226	46	79.6%	3,854	809	79.0%
SAB	98.0%	1	0	100.0%	6	0	100.0%	96	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	2	66.7%	39	2	94.9%	600	26	95.7%
TWO	84.0%	1	0	100.0%	6	1	83.3%	96	20	79.2%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	70	10	85.7%	390	60	84.6%	6,737	937	86.1%
ATL	-	1	0	100.0%	1	0	100.0%	2	0	100.0%
CLT	92.0%	5	0	100.0%	30	1	96.7%	490	38	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	4	69.2%	60	23	61.7%	1,089	213	80.4%
LOR	69.5%	1	0	100.0%	6	0	100.0%	98	9	90.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/06/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	52	82.8%	1,752	252	85.6%	29,058	3,924	86.5%
Southeast Division	72.5%	70	10	85.7%	390	60	84.6%	6,737	937	86.1%
MIA	87.5%	2	0	100.0%	12	0	100.0%	196	19	90.3%
MOE	94.0%	2	0	100.0%	12	0	100.0%	196	3	98.5%
NFK	86.0%	3	0	100.0%	16	4	75.0%	274	32	88.3%
NOL	92.0%	3	0	100.0%	25	0	100.0%	432	20	95.4%
NPN	96.0%	2	0	100.0%	12	0	100.0%	171	10	94.2%
PGH	92.0%	1	0	100.0%	6	0	100.0%	98	3	96.9%
PHL	45.0%	5	2	60.0%	26	13	50.0%	449	227	49.4%
RGH	97.0%	4	0	100.0%	24	0	100.0%	388	9	97.7%
RNK	85.5%	2	0	100.0%	12	2	83.3%	195	23	88.2%
RVM	86.0%	1	0	100.0%	6	0	100.0%	108	13	88.0%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	6	0	100.0%	98	2	98.0%
SFA	70.5%	1	0	100.0%	6	1	83.3%	98	4	95.9%
WAS	70.0%	23	4	82.6%	130	16	87.7%	2,348	307	86.9%
Southwest Division	77.0%	70	15	78.6%	401	63	84.3%	6,662	910	86.3%
ARN	60.5%	-	-	-	5	0	100.0%	97	7	92.8%
BFD	75.5%	6	2	66.7%	41	7	82.9%	593	142	76.1%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	6	2	66.7%	105	38	63.8%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	6	0	100.0%	97	3	96.9%
GTA	72.5%	4	1	75.0%	19	2	89.5%	288	27	90.6%
LAX	77.5%	9	2	77.8%	56	8	85.7%	908	100	89.0%
OKC	96.0%	1	0	100.0%	6	0	100.0%	98	3	96.9%
OKJ	79.0%	11	2	81.8%	55	15	72.7%	1,054	257	75.6%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	16	4	75.0%	76	10	86.8%	1,293	139	89.2%
SAN	77.0%	12	0	100.0%	72	6	91.7%	1,129	97	91.4%
SAS	85.0%	1	1	0.0%	6	1	83.3%	98	5	94.9%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	2	71.4%	42	9	78.6%	684	68	90.1%
SLO	62.0%	1	0	100.0%	11	3	72.7%	189	18	90.5%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	Cncld	2	1	50.0%	42	9	78.6%	2	0	100.0%	41	6	85.4%
3		6	0	100.0%	98	12	87.8%	6	1	83.3%	97	37	61.9%
4		6	1	83.3%	97	15	84.5%	6	2	66.7%	97	61	37.1%
5		6	2	66.7%	97	17	82.5%	6	0	100.0%	95	13	86.3%
6		6	2	66.7%	96	31	67.7%	6	1	83.3%	96	28	70.8%
7		6	2	66.7%	98	12	87.8%	6	1	83.3%	94	16	83.0%
8	46	6	4	33.3%	98	43	56.1%	5	3	40.0%	97	48	50.5%
11	Cncld	6	1	83.3%	97	19	80.4%	4	2	50.0%	93	17	81.7%
14		6	2	66.7%	98	12	87.8%	6	3	50.0%	97	24	75.3%
19		6	1	83.3%	98	19	80.6%	6	0	100.0%	98	13	86.7%
20		6	0	100.0%	98	6	93.9%	6	0	100.0%	98	8	91.8%
21		6	0	100.0%	97	13	86.6%	6	0	100.0%	97	18	81.4%
22		6	1	83.3%	98	5	94.9%	6	1	83.3%	97	20	79.4%
23		6	0	100.0%	98	3	96.9%	6	1	83.3%	98	14	85.7%
24		6	0	100.0%	98	7	92.9%	6	0	100.0%	98	9	90.8%
25		6	0	100.0%	98	0	100.0%	6	1	83.3%	98	11	88.8%
26		6	0	100.0%	98	2	98.0%	6	0	100.0%	98	14	85.7%
27		6	3	50.0%	98	5	94.9%	6	2	66.7%	97	22	77.3%
28		5	1	80.0%	96	21	78.1%	6	1	83.3%	97	13	86.6%
40		6	0	100.0%	98	14	85.7%	6	1	83.3%	98	35	64.3%
41		6	2	66.7%	98	35	64.3%	6	4	33.3%	98	62	36.7%
42		6	0	100.0%	98	3	96.9%	6	0	100.0%	98	12	87.8%
43		6	0	100.0%	98	8	91.8%	6	0	100.0%	98	4	95.9%
48		6	1	83.3%	98	14	85.7%	6	0	100.0%	98	10	89.8%
49		6	2	66.7%	98	16	83.7%	6	1	83.3%	98	14	85.7%
52		6	1	83.3%	98	4	95.9%	6	0	100.0%	98	14	85.7%
53		6	0	100.0%	98	9	90.8%	6	0	100.0%	98	13	86.7%
55		3	0	100.0%	67	0	100.0%	3	0	100.0%	67	13	80.6%
56		3	1	66.7%	67	14	79.1%	3	0	100.0%	67	11	83.6%
58		6	0	100.0%	97	3	96.9%	6	0	100.0%	96	14	85.4%
59	85	6	1	83.3%	96	8	91.7%	6	1	83.3%	96	10	89.6%
63		6	5	16.7%	98	44	55.1%	6	3	50.0%	97	51	47.4%
64		6	1	83.3%	97	21	78.4%	6	0	100.0%	97	21	78.4%
66		6	2	66.7%	98	15	84.7%	6	1	83.3%	98	20	79.6%
67		4	0	100.0%	67	4	94.0%	3	0	100.0%	67	11	83.6%
68		6	2	66.7%	98	19	80.6%	6	3	50.0%	98	49	50.0%
69	37	6	1	83.3%	98	12	87.8%	6	1	83.3%	98	14	85.7%
71		6	0	100.0%	98	1	99.0%	6	0	100.0%	98	24	75.5%
72		6	0	100.0%	98	10	89.8%	6	0	100.0%	98	23	76.5%
73	42	6	0	100.0%	98	3	96.9%	6	4	33.3%	97	48	50.5%
74		6	0	100.0%	98	7	92.9%	6	1	83.3%	98	26	73.5%
75	18	6	0	100.0%	98	3	96.9%	6	3	50.0%	98	42	57.1%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		6	1	83.3%	98	5	94.9%	5	2	60.0%	97	37	61.9%
77		6	0	100.0%	98	4	95.9%	6	1	83.3%	98	32	67.3%
78		6	0	100.0%	98	5	94.9%	6	1	83.3%	98	13	86.7%
79		6	0	100.0%	98	21	78.6%	6	0	100.0%	97	15	84.5%
80		6	0	100.0%	98	11	88.8%	6	0	100.0%	97	10	89.7%
84	17	3	2	33.3%	67	5	92.5%	3	2	33.3%	67	14	79.1%
85		3	1	66.7%	67	4	94.0%	3	0	100.0%	67	24	64.2%
86		3	0	100.0%	67	5	92.5%	3	2	33.3%	66	35	47.0%
89		6	2	66.7%	98	20	79.6%	6	0	100.0%	98	15	84.7%
90		6	0	100.0%	98	2	98.0%	6	0	100.0%	98	9	90.8%
93		3	1	66.7%	67	11	83.6%	3	0	100.0%	66	13	80.3%
94		3	1	66.7%	67	17	74.6%	3	2	33.3%	66	20	69.7%
95	16	3	0	100.0%	67	2	97.0%	3	1	66.7%	67	20	70.1%
97		6	4	33.3%	98	45	54.1%	6	1	83.3%	98	20	79.6%
98	115	6	0	100.0%	98	5	94.9%	6	2	66.7%	98	26	73.5%
110		3	1	66.7%	67	32	52.2%	3	0	100.0%	67	7	89.6%
111		3	0	100.0%	67	12	82.1%	3	0	100.0%	67	9	86.6%
112		3	0	100.0%	67	7	89.6%	3	1	66.7%	67	10	85.1%
114		3	1	66.7%	67	14	79.1%	3	1	66.7%	66	3	95.5%
119		3	1	66.7%	67	16	76.1%	3	0	100.0%	67	8	88.1%
125		3	0	100.0%	67	2	97.0%	3	0	100.0%	67	15	77.6%
129		3	1	66.7%	67	25	62.7%	3	0	100.0%	67	9	86.6%
130		3	1	66.7%	67	6	91.0%	3	0	100.0%	67	6	91.0%
131		3	1	66.7%	67	11	83.6%	3	1	66.7%	67	6	91.0%
133	16	3	2	33.3%	67	30	55.2%	3	2	33.3%	67	28	58.2%
134		3	0	100.0%	67	6	91.0%	3	0	100.0%	67	12	82.1%
136		3	0	100.0%	67	7	89.6%	3	0	100.0%	67	5	92.5%
137		3	0	100.0%	65	14	78.5%	3	1	66.7%	65	19	70.8%
138		3	0	100.0%	67	9	86.6%	3	0	100.0%	67	5	92.5%
141		3	0	100.0%	67	3	95.5%	3	0	100.0%	67	15	77.6%
148		3	1	66.7%	67	7	89.6%	3	0	100.0%	66	10	84.8%
151		6	0	100.0%	98	27	72.4%	6	0	100.0%	97	25	74.2%
170		3	1	66.7%	64	7	89.1%	3	0	100.0%	64	21	67.2%
171		3	0	100.0%	67	5	92.5%	3	0	100.0%	67	12	82.1%
172		3	0	100.0%	67	9	86.6%	3	0	100.0%	65	24	63.1%
173		3	0	100.0%	67	8	88.1%	3	0	100.0%	67	27	59.7%
174		3	0	100.0%	67	3	95.5%	3	1	66.7%	67	14	79.1%
175		3	0	100.0%	67	10	85.1%	3	0	100.0%	67	19	71.6%
176		3	0	100.0%	67	5	92.5%	3	0	100.0%	67	4	94.0%
177		3	1	66.7%	67	15	77.6%	3	1	66.7%	67	28	58.2%
178		3	0	100.0%	67	10	85.1%	3	0	100.0%	67	9	86.6%
179		3	0	100.0%	67	6	91.0%	3	0	100.0%	67	14	79.1%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181		3	1	66.7%	67	16	76.1%	3	1	66.7%	66	4	93.9%
182		3	0	100.0%	67	12	82.1%	3	0	100.0%	67	5	92.5%
183		3	0	100.0%	67	19	71.6%	3	0	100.0%	67	10	85.1%
184		3	0	100.0%	67	12	82.1%	3	0	100.0%	67	11	83.6%
185		3	0	100.0%	67	13	80.6%	3	0	100.0%	67	4	94.0%
186		3	0	100.0%	67	9	86.6%	3	0	100.0%	67	15	77.6%
190		3	1	66.7%	67	28	58.2%	3	1	66.7%	67	16	76.1%
192		3	1	66.7%	65	9	86.2%	3	0	100.0%	65	2	96.9%
193		3	0	100.0%	67	21	68.7%	3	0	100.0%	67	23	65.7%
196		3	0	100.0%	67	1	98.5%	3	0	100.0%	67	3	95.5%
197		3	1	66.7%	67	25	62.7%	3	0	100.0%	67	14	79.1%
232		6	0	100.0%	98	2	98.0%	6	0	100.0%	98	6	93.9%
233		6	3	50.0%	98	27	72.4%	6	2	66.7%	98	22	77.6%
234	25	6	0	100.0%	98	4	95.9%	6	1	83.3%	98	4	95.9%
235		6	0	100.0%	37	5	86.5%	6	0	100.0%	37	6	83.8%
236	19	6	0	100.0%	98	1	99.0%	6	1	83.3%	98	17	82.7%
237		6	0	100.0%	97	15	84.5%	6	1	83.3%	96	8	91.7%
238		6	2	66.7%	37	8	78.4%	6	0	100.0%	37	3	91.9%
239		6	1	83.3%	97	25	74.2%	6	0	100.0%	97	4	95.9%
240		6	0	100.0%	98	9	90.8%	6	0	100.0%	98	12	87.8%
241		6	1	83.3%	98	25	74.5%	6	0	100.0%	98	14	85.7%
243		3	0	100.0%	67	22	67.2%	3	0	100.0%	68	12	82.4%
244		6	0	100.0%	98	5	94.9%	6	0	100.0%	98	18	81.6%
280		6	0	100.0%	98	4	95.9%	6	1	83.3%	98	18	81.6%
281		6	0	100.0%	98	9	90.8%	6	1	83.3%	98	11	88.8%
283		6	2	66.7%	98	22	77.6%	6	0	100.0%	98	15	84.7%
284		6	0	100.0%	98	3	96.9%	6	0	100.0%	97	7	92.8%
290		6	0	100.0%	98	19	80.6%	6	1	83.3%	97	32	67.0%
291		6	0	100.0%	98	18	81.6%	6	0	100.0%	98	15	84.7%
300		6	1	83.3%	98	11	88.8%	6	0	100.0%	97	25	74.2%
301		6	0	100.0%	96	2	97.9%	6	0	100.0%	95	16	83.2%
302		6	0	100.0%	95	11	88.4%	6	0	100.0%	93	27	71.0%
305		6	2	66.7%	98	14	85.7%	6	1	83.3%	96	36	62.5%
306		6	0	100.0%	96	6	93.8%	6	0	100.0%	95	20	78.9%
307		6	1	83.3%	97	12	87.6%	6	1	83.3%	96	21	78.1%
311		6	0	100.0%	97	10	89.7%	6	1	83.3%	96	21	78.1%
316		6	0	100.0%	96	5	94.8%	6	0	100.0%	96	18	81.3%
318	18	6	0	100.0%	98	11	88.8%	6	1	83.3%	97	38	60.8%
319		6	0	100.0%	98	4	95.9%	6	0	100.0%	98	48	51.0%
329		3	0	100.0%	67	3	95.5%	3	0	100.0%	67	5	92.5%
330		4	0	100.0%	81	2	97.5%	4	0	100.0%	81	5	93.8%
331		6	0	100.0%	98	11	88.8%	6	0	100.0%	98	14	85.7%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		6	0	100.0%	98	9	90.8%	6	0	100.0%	98	16	83.7%
334	37	6	0	100.0%	98	2	98.0%	6	2	66.7%	97	14	85.6%
335	57	6	1	83.3%	98	15	84.7%	6	1	83.3%	96	18	81.3%
336		6	0	100.0%	98	4	95.9%	6	0	100.0%	98	5	94.9%
337		6	0	100.0%	98	5	94.9%	6	1	83.3%	98	13	86.7%
338	49	6	1	83.3%	98	22	77.6%	6	1	83.3%	96	23	76.0%
339	37	6	2	66.7%	98	22	77.6%	6	4	33.3%	98	23	76.5%
341		6	0	100.0%	95	16	83.2%	5	0	100.0%	93	14	84.9%
342		6	0	100.0%	98	8	91.8%	5	0	100.0%	96	16	83.3%
350		6	1	83.3%	80	4	95.0%	6	4	33.3%	80	45	43.8%
351		6	1	83.3%	98	14	85.7%	6	0	100.0%	98	38	61.2%
352	21	6	0	100.0%	98	7	92.9%	6	3	50.0%	95	29	69.5%
353		6	0	100.0%	77	5	93.5%	6	0	100.0%	77	16	79.2%
354	30	6	1	83.3%	98	9	90.8%	6	5	16.7%	96	33	65.6%
355		6	0	100.0%	97	9	90.7%	6	2	66.7%	96	27	71.9%
364		6	1	83.3%	97	18	81.4%	6	2	66.7%	96	22	77.1%
365		6	1	83.3%	97	8	91.8%	6	3	50.0%	96	31	67.7%
370		6	2	66.7%	98	7	92.9%	6	2	66.7%	98	18	81.6%
371	37	6	0	100.0%	97	3	96.9%	6	1	83.3%	97	12	87.6%
380	19	6	1	83.3%	98	16	83.7%	6	1	83.3%	98	22	77.6%
381		6	0	100.0%	98	2	98.0%	6	0	100.0%	98	11	88.8%
382		6	0	100.0%	98	2	98.0%	6	0	100.0%	98	23	76.5%
383		6	0	100.0%	98	9	90.8%	6	0	100.0%	96	36	62.5%
390	214	6	0	100.0%	82	9	89.0%	6	2	66.7%	81	27	66.7%
391	108	6	0	100.0%	83	2	97.6%	6	1	83.3%	81	16	80.2%
392		6	0	100.0%	98	4	95.9%	6	1	83.3%	97	29	70.1%
393	107	6	1	83.3%	98	8	91.8%	6	2	66.7%	97	27	72.2%
417		3	1	66.7%	64	11	82.8%	3	0	100.0%	61	2	96.7%
448		6	1	83.3%	39	14	64.1%	6	1	83.3%	37	13	64.9%
449		6	0	100.0%	36	1	97.2%	6	0	100.0%	36	5	86.1%
470	47	3	1	66.7%	69	14	79.7%	3	1	66.7%	67	13	80.6%
473		3	0	100.0%	67	3	95.5%	3	0	100.0%	67	1	98.5%
474		3	1	66.7%	65	19	70.8%	3	1	66.7%	61	19	68.9%
475		3	0	100.0%	67	0	100.0%	3	0	100.0%	67	1	98.5%
478		3	1	66.7%	65	14	78.5%	3	0	100.0%	65	7	89.2%
479		3	1	66.7%	67	9	86.6%	3	0	100.0%	67	3	95.5%
486	31	3	1	66.7%	68	9	86.8%	3	2	33.3%	67	13	80.6%
490		3	0	100.0%	44	8	81.8%	3	0	100.0%	44	2	95.5%
494		3	0	100.0%	69	9	87.0%	3	1	66.7%	66	12	81.8%
495	16	3	1	66.7%	67	3	95.5%	3	1	66.7%	67	2	97.0%
500		6	0	100.0%	98	6	93.9%	6	0	100.0%	97	10	89.7%
502	20	6	2	66.7%	98	9	90.8%	5	1	80.0%	96	22	77.1%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
503		6	0	100.0%	95	11	88.4%	6	1	83.3%	94	23	75.5%
504		6	2	66.7%	98	10	89.8%	6	1	83.3%	97	26	73.2%
505		6	2	66.7%	98	18	81.6%	6	1	83.3%	96	18	81.3%
506		6	0	100.0%	97	14	85.6%	6	0	100.0%	96	13	86.5%
507		6	1	83.3%	98	12	87.8%	6	2	66.7%	98	34	65.3%
508		6	0	100.0%	96	20	79.2%	6	0	100.0%	96	22	77.1%
509	26	6	0	100.0%	98	7	92.9%	6	1	83.3%	98	26	73.5%
511		6	0	100.0%	98	10	89.8%	6	1	83.3%	98	18	81.6%
516	60	6	0	100.0%	96	9	90.6%	6	3	50.0%	96	41	57.3%
517		6	0	100.0%	98	2	98.0%	6	0	100.0%	97	31	68.0%
518	16	6	0	100.0%	98	13	86.7%	6	5	16.7%	98	59	39.8%
519		6	0	100.0%	96	4	95.8%	6	1	83.3%	96	15	84.4%
520		2	1	50.0%	57	9	84.2%	2	0	100.0%	55	3	94.5%
521		2	0	100.0%	64	0	100.0%	2	0	100.0%	64	4	93.8%
522		2	1	50.0%	64	10	84.4%	2	0	100.0%	63	6	90.5%
523		2	0	100.0%	64	0	100.0%	2	0	100.0%	64	8	87.5%
524		2	0	100.0%	64	2	96.9%	2	0	100.0%	64	4	93.8%
525		2	0	100.0%	63	3	95.2%	2	0	100.0%	62	6	90.3%
526	17	2	0	100.0%	64	10	84.4%	2	1	50.0%	63	7	88.9%
527		2	0	100.0%	64	1	98.4%	2	0	100.0%	64	3	95.3%
528		2	0	100.0%	64	6	90.6%	2	0	100.0%	64	13	79.7%
529	87	2	1	50.0%	64	5	92.2%	2	1	50.0%	64	14	78.1%
530	16	2	1	50.0%	18	3	83.3%	2	1	50.0%	18	2	88.9%
532		2	0	100.0%	64	5	92.2%	2	0	100.0%	64	8	87.5%
535		2	0	100.0%	57	6	89.5%	2	0	100.0%	56	4	92.9%
536		2	0	100.0%	64	10	84.4%	2	0	100.0%	62	3	95.2%
537		2	0	100.0%	62	5	91.9%	2	0	100.0%	60	2	96.7%
538		2	0	100.0%	64	10	84.4%	2	0	100.0%	64	9	85.9%
539		2	1	50.0%	18	3	83.3%	2	1	50.0%	18	10	44.4%
540		2	0	100.0%	64	7	89.1%	2	0	100.0%	61	2	96.7%
541		2	1	50.0%	64	9	85.9%	2	0	100.0%	64	15	76.6%
542	65	2	0	100.0%	64	5	92.2%	2	1	50.0%	63	12	81.0%
543		2	0	100.0%	64	6	90.6%	2	0	100.0%	64	15	76.6%
544		2	1	50.0%	63	7	88.9%	2	0	100.0%	62	7	88.7%
545		2	0	100.0%	64	6	90.6%	2	0	100.0%	63	5	92.1%
547		2	1	50.0%	64	7	89.1%	2	1	50.0%	64	15	76.6%
548		2	0	100.0%	64	10	84.4%	2	0	100.0%	64	6	90.6%
549		2	0	100.0%	61	13	78.7%	2	0	100.0%	58	7	87.9%
550		2	1	50.0%	18	4	77.8%	2	0	100.0%	18	2	88.9%
551		2	0	100.0%	61	7	88.5%	2	0	100.0%	59	7	88.1%
562	32	6	0	100.0%	96	11	88.5%	5	1	80.0%	94	10	89.4%
564		6	0	100.0%	96	9	90.6%	5	0	100.0%	91	12	86.8%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566		6	1	83.3%	96	7	92.7%	6	1	83.3%	93	9	90.3%
572		6	1	83.3%	95	8	91.6%	5	0	100.0%	92	18	80.4%
573		6	1	83.3%	96	13	86.5%	6	1	83.3%	94	11	88.3%
577		6	1	83.3%	94	8	91.5%	5	0	100.0%	89	8	91.0%
580		6	1	83.3%	96	3	96.9%	6	0	100.0%	96	9	90.6%
581		6	2	66.7%	96	12	87.5%	6	2	66.7%	96	18	81.3%
582		6	1	83.3%	96	7	92.7%	6	0	100.0%	94	7	92.6%
586		6	0	100.0%	96	19	80.2%	6	1	83.3%	91	12	86.8%
587		6	0	100.0%	96	5	94.8%	6	1	83.3%	92	12	87.0%
591		6	0	100.0%	96	2	97.9%	6	0	100.0%	95	8	91.6%
593		6	0	100.0%	96	14	85.4%	6	0	100.0%	88	9	89.8%
595		6	0	100.0%	95	19	80.0%	6	1	83.3%	94	15	84.0%
600		3	1	66.7%	67	3	95.5%	3	0	100.0%	67	5	92.5%
601		3	2	33.3%	67	38	43.3%	3	0	100.0%	67	15	77.6%
605		3	3	0.0%	67	44	34.3%	3	0	100.0%	66	6	90.9%
607		3	0	100.0%	67	4	94.0%	3	0	100.0%	66	4	93.9%
609		3	1	66.7%	66	6	90.9%	3	0	100.0%	66	4	93.9%
620		3	1	66.7%	66	20	69.7%	3	1	66.7%	64	4	93.8%
624		3	3	0.0%	67	22	67.2%	3	0	100.0%	67	14	79.1%
639		3	1	66.7%	67	19	71.6%	3	0	100.0%	67	7	89.6%
640		3	0	100.0%	67	5	92.5%	3	0	100.0%	66	32	51.5%
641		3	0	100.0%	67	14	79.1%	3	0	100.0%	67	12	82.1%
642		3	0	100.0%	66	4	93.9%	3	0	100.0%	66	8	87.9%
643		3	0	100.0%	67	14	79.1%	3	0	100.0%	66	10	84.8%
644		3	1	66.7%	67	11	83.6%	3	1	66.7%	67	15	77.6%
645	17	3	0	100.0%	67	8	88.1%	3	1	66.7%	67	12	82.1%
646		3	0	100.0%	67	16	76.1%	3	2	33.3%	66	39	40.9%
647		3	0	100.0%	67	7	89.6%	3	0	100.0%	67	16	76.1%
648		3	3	0.0%	67	17	74.6%	3	0	100.0%	67	10	85.1%
649		3	1	66.7%	67	12	82.1%	3	1	66.7%	66	10	84.8%
650		3	1	66.7%	67	15	77.6%	3	0	100.0%	67	15	77.6%
651		3	0	100.0%	67	5	92.5%	3	0	100.0%	67	18	73.1%
652		3	0	100.0%	67	12	82.1%	3	0	100.0%	66	12	81.8%
653	23	3	1	66.7%	67	13	80.6%	3	1	66.7%	67	18	73.1%
654		3	2	33.3%	67	17	74.6%	3	0	100.0%	67	5	92.5%
655	21	3	1	66.7%	65	19	70.8%	3	1	66.7%	64	20	68.8%
656		3	1	66.7%	67	18	73.1%	3	0	100.0%	67	5	92.5%
657	1435	3	0	100.0%	67	3	95.5%	2	1	50.0%	66	13	80.3%
658		3	2	33.3%	67	11	83.6%	3	0	100.0%	67	11	83.6%
680		4	1	75.0%	70	3	95.7%	4	1	75.0%	70	8	88.6%
681		4	0	100.0%	70	3	95.7%	3	0	100.0%	69	19	72.5%
682		4	0	100.0%	70	0	100.0%	4	1	75.0%	70	15	78.6%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
683		4	0	100.0%	53	4	92.5%	4	0	100.0%	53	16	69.8%
684		4	0	100.0%	51	9	82.4%	4	0	100.0%	51	14	72.5%
685		4	1	75.0%	68	10	85.3%	4	0	100.0%	68	17	75.0%
686		4	1	75.0%	70	16	77.1%	4	0	100.0%	70	15	78.6%
687		4	1	75.0%	70	10	85.7%	4	1	75.0%	70	12	82.9%
688		4	0	100.0%	70	1	98.6%	4	2	50.0%	70	16	77.1%
689	24	3	0	100.0%	57	5	91.2%	2	1	50.0%	55	5	90.9%
701		6	0	100.0%	30	6	80.0%	6	0	100.0%	30	2	93.3%
702		6	0	100.0%	98	17	82.7%	6	0	100.0%	97	24	75.3%
703		6	1	83.3%	98	25	74.5%	6	3	50.0%	98	27	72.4%
704		6	0	100.0%	30	3	90.0%	6	0	100.0%	29	5	82.8%
710		6	4	33.3%	98	39	60.2%	6	1	83.3%	98	35	64.3%
711		6	0	100.0%	92	8	91.3%	5	1	80.0%	84	13	84.5%
712	26	6	1	83.3%	98	23	76.5%	6	4	33.3%	96	37	61.5%
715	29	6	0	100.0%	98	30	69.4%	6	5	16.7%	91	48	47.3%
716	22	6	3	50.0%	98	43	56.1%	6	3	50.0%	96	44	54.2%
717	30	6	3	50.0%	89	26	70.8%	5	1	80.0%	81	29	64.2%
718		6	2	66.7%	98	41	58.2%	6	1	83.3%	97	30	69.1%
719		6	3	50.0%	98	38	61.2%	6	1	83.3%	96	33	65.6%
761	Cncld	6	0	100.0%	96	4	95.8%	4	3	25.0%	94	17	81.9%
765		6	0	100.0%	96	8	91.7%	6	2	66.7%	96	19	80.2%
769		6	1	83.3%	96	8	91.7%	6	2	66.7%	94	20	78.7%
770		6	0	100.0%	96	10	89.6%	6	3	50.0%	96	17	82.3%
774		6	2	66.7%	96	9	90.6%	6	4	33.3%	95	23	75.8%
779		6	1	83.3%	96	5	94.8%	6	3	50.0%	95	21	77.9%
784		6	1	83.3%	96	11	88.5%	6	3	50.0%	95	50	47.4%
785		6	0	100.0%	96	0	100.0%	6	1	83.3%	96	15	84.4%
790		6	0	100.0%	96	6	93.8%	5	0	100.0%	95	11	88.4%
794		6	2	66.7%	96	10	89.6%	6	2	66.7%	95	18	81.1%
821		6	0	100.0%	98	3	96.9%	6	0	100.0%	98	46	53.1%
822	15	6	0	100.0%	98	3	96.9%	6	2	66.7%	98	49	50.0%
1333		6	2	66.7%	98	12	87.8%	5	1	80.0%	96	37	61.5%
1340		6	0	100.0%	98	3	96.9%	6	0	100.0%	98	22	77.6%
2104		3	0	100.0%	37	7	81.1%	3	0	100.0%	36	5	86.1%
2107	17	3	1	66.7%	67	14	79.1%	3	1	66.7%	65	7	89.2%
2108	63	3	1	66.7%	66	7	89.4%	3	1	66.7%	64	3	95.3%
2117		3	1	66.7%	36	11	69.4%	3	0	100.0%	36	6	83.3%
2121		3	0	100.0%	64	8	87.5%	3	1	66.7%	64	7	89.1%
2122		3	0	100.0%	67	11	83.6%	3	0	100.0%	67	4	94.0%
2124		2	0	100.0%	48	7	85.4%	2	0	100.0%	48	3	93.8%
2150	99	3	1	66.7%	67	16	76.1%	3	3	0.0%	65	20	69.2%
2153		3	0	100.0%	67	9	86.6%	3	0	100.0%	67	15	77.6%

Amtrak On Time Performance

Trains Arriving Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2155	42	3	0	100.0%	67	5	92.5%	3	3	0.0%	65	25	61.5%
2159	29	3	0	100.0%	66	3	95.5%	3	1	66.7%	65	17	73.8%
2162	30	3	0	100.0%	67	2	97.0%	3	3	0.0%	65	20	69.2%
2163		3	1	66.7%	67	8	88.1%	3	2	33.3%	66	20	69.7%
2166		3	1	66.7%	67	8	88.1%	3	1	66.7%	65	13	80.0%
2167		3	1	66.7%	65	12	81.5%	3	1	66.7%	65	18	72.3%
2168		3	0	100.0%	65	4	93.8%	3	0	100.0%	65	9	86.2%
2170	29	3	2	33.3%	67	14	79.1%	3	1	66.7%	65	15	76.9%
2171		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
2190	21	3	2	33.3%	66	12	81.8%	3	2	33.3%	64	12	81.3%
2193	23	3	0	100.0%	66	3	95.5%	3	1	66.7%	66	22	66.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Region: ALL

Service: ALL

Arriving On: 1/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2107	WAS	17	POL	12	POL	12	WIL-XPV	AM	On-train police or DEA activity, OPERATE 1/2 TRACKS AROUND TOL 3 TRACK A/C VANDALISM
2108	NYP	63	ITI	45	ITI	45	WAS-WAS	AM	Service, turn, or wye train, 2107, ARRIVED LATE AND NEC'Y TO WYE DUE TO DNL ON 2124
2150	BOS	99	SYS	65	SYS	65	WAS-WAS	AM	Alleged crew rules violation
2155	WAS	42	ENG	15	DCS	12	XGX-NHV	AM	T.O.L, Bridge, Conn River, TOL on trk 1 at Conn River Bridge / will receive 241
2159	WAS	29	CAR	20	CAR	20	XCY-XHM	AM	Air / Brake / Wheel, 0000, SMOKE CONDITION ON TRAIN NO EXCEPTIONS
2162	BOS	30	DMW	13	DMW	13	XNY-BAL	AM	Held for or routed around MW work or equipment, Control Point, CARROLL, S/R 15/2 A/C BROKEN FROG
2170	BOS	29	ITI	23	ITI	23	WAS-WAS	AM	Service, turn, or wye train, 2155, SHORT TURN 2155 ARRIVED 38 MINS LATE AT 2:35PM
2190	BOS	21	SVS	28	SVS	28	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, LATE EQUIPMENT SWAP WITH AM2107 DUE TO MECHANICAL ISSUES
2193	NYP	23	DSR	16	DSR	14	XNH-STM	MN	Per bulletin Control Point, 274, 30, 1, Control Point, 248, 30, 1, Milepost, 42, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2, Milepost, 33.6, 32.3, 30, 2
84	NYP	17	FTI	9	FTI	9	WDB-ALX	CS	Follow 135, Milepost w/Letters, WDB, alx
95	NFK	16	PTI	38	FTI	25	FBG-RVR	CS	Follow M4095, Other, cfp11.4-4.6
133	WAS	16	PTI	8	PTI	8	WIL-XPV	AM	Cross over or go around, 2121, Milepost, 28.2, 38.4, opr 1 trk for 2121 on 3 trk
470	SPG	47	SVS	51	SVS	51	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, late release from the yard
486	GFD	31	PTI	31	PTI	31	WND-WNL	AM	Wait for station track, 475, Control Point, XHA, HELD FOR AM475 TO CLEAR A/C STOP & PROTECT AHEAD ON SINGLE TRACK
495	NHV	16	CON	11	CON	11	SPG-SPG	AM	Hold for thruway bus, Waited for bus connection a/c 425 cancelled @ Swenney track 2 los HEP needed to reset
645	HAR	17	DCS	8	DCS	8	PAO-PAO	AM	PTC system failure (wayside), Control Point, ., Could not pull up signal. Had to give 241

Amtrak Endpoint OTP Details

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
653	HAR	23	ENG	11	ENG	11	PHL-PHL	AM	Other electrical failure, E/656, engine was unable to take power
655	HAR	21	CAR	13	CAR	13	NWK-TRE	AM	Door, 82633 82745 82511 82501 , DOOR LIGHT IN ROUTE
657	HAR	1435	OTH	6	OTH	3	EXT-DOW	AM	Lost time - N.A.R., insufficient scheduling.
689	BRK	24	DCS	19	DCS	19	SAO-POR	CS	Power switch failure Put crossover switches back on power, Control Point, rigby east
69	MTR	-17	CUI	36	CUI	36	XLQ-XLQ	CN	Canada
234	NYP	25	CTI	19	CTI	19	POU-CRT	MN	Follow metro north, 824, Milepost, 72, 39
236	NYP	19	PTI	15	PTI	8	YNY-XSD	MN	Meet 281, Control Point, 12
73	CLT	42	FTI	30	FTI	30	GRO-HPT	NS	Meet Held at Elm due to track work ahead., #NS12r, Control Point, Elm
75	CLT	18	PTI	11	PTI	11	CYN-DNC	NS	Meet #Amt72, Control Point, D&S Jct
98	NYP	115	FTI	111	FTI	79	RMT-PTB	CS	Cross Traffic All stop waiting HOT BEARING CSX train over mile and a half long, Control Point, Empria, CSXT I03506, Intermodal
526	SAC	17	MBO	19	MBO	19	MTZ-SUI	UP	For maritime traffic Control Point, Vista
529	SJC	87	SVS	72	SVS	72	SAC-SAC	UP	529 canceled out of ARN . Originated in sac with new train set . Departure set at 853
530	SAC	16	POL	23	POL	23	SUI-FFV	UP	Right of Way police hold Police investigation at FFV - they had us hold outside of FFV.
542	SAC	65	TRS	64	TRS	64	OAC-OAC	UP	Vehicle on track ahead White truck fouling M2, Milepost, 10.9, 10.9
502	SEA	20	DMW	22	DMW	22	VAN-KEL	BN	Held for or routed around MW work or equipment Control Point, Fruit Valley
509	PDX	26	TRS	32	TRS	32	TAC-XNI	ST	Vehicle on track ahead Car on on tracks. Had to shove back to main 1 to get around car on main 2, Other, MP 10.9
516	VAC	60	FTI	41	FTI	29	BEL-X8B	BN	Freight crew switching on tracks ahead. BNSF 155, Control Point, North South BEL
518	VAC	16	MBO	19	MBO	19	XF2-X1J	BN	For maritime traffic Bridge, Fraser River Br.
59	NOL	85	ENG	104	ENG	66	HMD-XSU	CC	Unrecoverable penalty (PCS) 69
11	LAX	Trn Cancelled	PTI	59	DCS	25	KFS-DUN	UP	Restrictive signal(s) from unknown cause Flagged from S. Penoyer to N. Grass Lake., Stop, Restricted Proceed, Restricted Proceed, Control Point, S. Penoyer, Milepost, 374, 374, Milepost, 372.9, 372.9

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Region: ALL

Service: ALL

Arriving On: 1/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
8	CHI	46	SVS	131	SVS	104	SEA-SEA	BN	Water, commissary, toilet/trash dumping The toilet had to be replaced in car 32086
822	OKC	15	FTI	27	FTI	13	NOR-OKC	BN	Follow bnsf 6843, Other, nor-okc
334	CHI	37	CCR	30	CCR	9	MKE-MKA	CP	PTC - On Board Cab Signal or PTC Failure 90200, Speedometer is showing zero, had to cut-out PTC (59 mph) w/ CPKC rail and METRA
335	MKE	57	CCR	41	CCR	41	CHI-CHI	AM	PTC - On Board Cab Signal or PTC Failure 90200, 518, Added engine 518 13:06 arrived 13:10 clear of Passengers 13:14 joint made 13:40 mechanical dept. Clear 13:42 class II & PTC 13:46 departed
338	CHI	49	ITI	40	ITI	40	MKE-MKE	CP	Service, turn, or wye train 335
339	MKE	37	ITI	22	ITI	22	CHI-CHI	AM	Service, turn, or wye train 338
352	PNT	21	POL	24	POL	21	ARB-ARB	MI	Medical emergency for passenger
354	PNT	30	SYS	27	PTI	24	X90-KAL	AM	Meet 355, Control Point, 160
371	CHI	37	DCS	41	DCS	29	HOM-BAM	CS	Stop signal due to broken rail. Stopped and took EC-1 for annulled partial activation failure. Talked past stop signal and walked/talked over broken rail Milepost w/Letters, WE Wells, 48.6
562	SAN	32	PTI	13	SYS	9	X98-OSD	SN	PTC problem or failure (cause unknown) Red fence instruction to cut out, Control Point, stuart
761	SLO	Trn Cancelled	HLD	26	HLD	22	SBA-SBA	UP	Provide connection info/ unlift tickets for pax due to service disruption
712	BFD	26	PTI	31	PTI	28	HNF-COC	BN	Meet amtrak717, Control Point, east guernsey
715	OKJ	29	FTI	20	TRS	15	EMY-OKJ	UP	Vehicle on track ahead Milepost, 10.8, 10.9
716	BFD	22	RTE	34	RTE	31	WAC-BFD	BN	Dispatcher hold Unable to contact dispatcher. BNSF 3778 W went around through Shafter siding. Held at E BFD for unknown reason, Control Point, East Shafter, Control Point, Eas Bakersfield
717	OKJ	30	DCS	26	DCS	21	COC-HNF	BN	Restrictive signal(s) from known wayside signal failure E. Guernsey signal dropped to stop in our face., Stop , Control Point, E. Guernsey

Amtrak Endpoint OTP Details

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2	BMT	Trn Cancelled	ENG	565	ENG	219	ELP-ELP	UP	Pick up rescue locomotive due to mechanical failure Inbound engineers fail to troubleshoot AMTK 206 air issues. Add Up5931 at Elp depot, 206
380	CHI	19	FTI	26	FTI	25	MDT-PLO	BN	Meet CN 2944, Control Point, Earlville
390	CHI	214	FTI	228	FTI	226	MAT-MAT	CC	Wait on u763 to get repaired broken draw bar Other, mat station, cn 8408
391	CDL	108	RTE	124	RTE	121	CHM-CHM	CC	Dispatcher hold Held due to disabled UP Freight at Tuscola, Control Point, Champaign
393	CDL	107	ITI	112	ITI	112	CHI-CHI	AM	Service, turn, or wye train 390
318	CHI	18	FTI	34	PTI	18	SPI-LCN	UP	Meet Amtk 21, Control Point, Broadwell

Amtrak Initial Terminal Details

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/6/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	600	01/06	1		
HAR	624	01/06	1		
HAR	648	01/06	1		
HAR	658	01/06	1		
PHL	601	01/06	1		
PHL	605	01/06	5	3	Passenger and/or baggage, late travel, 637a
PHL	605	01/06	5	2	PTC - Stop Bypass Permission Required, Control Point, ., Stop bypass e/ 607
WAS	170	01/06	10	10	Alleged crew rules violation
WAS	2108	01/06	45	45	Service, turn, or wye train, 2107, ARRIVED LATE AND NEC'Y TO WYE DUE TO DNL ON 2124
WAS	2150	01/06	65	65	Alleged crew rules violation
WAS	2170	01/06	23	23	Service, turn, or wye train, 2155, SHORT TURN 2155 ARRIVED 38 MINS LATE AT 2:35PM
ALB	238	01/06	19	19	Pick up equipment Other, alb
BON	685	01/06	1		
BOS	85	01/06	4	4	Door, 82711, Door issues B end 82711 Engr. side
BOS	93	01/06	7	7	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
BOS	2171	01/06	3	3	Service, turn, or wye train, 2150, LATE TURN OF AM2150
GFD	479	01/06	3	3	Unrecoverable penalty (PCS) 9634
NHV	470	01/06	51	51	Planned set out / pick out of locomotives, cars or section of train, late release from the yard
NHV	486	01/06	14	14	Door, 9634, ISSUES WITH ACCESS ON CAB CAR AT YARD
NYP	49	01/06	4	4	Passenger and/or baggage, BOARDING
NYP	63	01/06	40	40	HEP, 100, UNSPECIFIED PROBLEM WITH ENG.100
NYP	89	01/06	7	7	Scheduled in track usage program, Other, NYP-NYP, LATE FROM SSYD A/C OPR IN LINE 4 A/C LINE 2 O/O/S FLWD LI807
NYP	133	01/06	5	5	Air / Brake, 614, RELEASING BRAKE ON REAR ENG.614
NYP	197	01/06	2	2	Passenger and/or baggage, BOARDING
NYP	233	01/06	3	3	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	283	01/06	3	3	Passenger and/or baggage, BOARDING
NYP	2190	01/06	28	28	Planned set out / pick out of locomotives, cars or section of train, LATE EQUIPMENT SWAP WITH AM2107 DUE TO MECHANICAL ISSUES

Amtrak Initial Terminal Details

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/6/2026

Terminal	Train	Date	Late	Delay	Cause
SPG	417	01/06	5	5	Unrecoverable penalty (PCS), 9691, HAD TO WYE EQUIPMENT ACCESS ISSUE CC/9691
SPG	495	01/06	11	11	Hold for thruway bus, Waited for bus connection a/c 425 cancelled @ Swenney track 2 los HEP needed to reset
CHI	5	01/06	3	3	Late release from the commissary
CHI	7	01/06	13	13	Pre departure issue 182
CHI	41	01/06	59	59	Late servicing of engine 153
CHI	335	01/06	41	41	PTC - On Board Cab Signal or PTC Failure 90200, 518, Added engine 518 13:06 arrived 13:10 clear of Passengers 13:14 joint made 13:40 mechanical dept. Clear 13:42 class II & PTC 13:46 departed
CHI	339	01/06	22	22	Service, turn, or wye train 338
CHI	370	01/06	24	24	Glasshouse just advised "Engine" 316
CHI	393	01/06	112	112	Service, turn, or wye train 390
MKE	338	01/06	40	40	Service, turn, or wye train 335
STL	300	01/06	1		
BFD	703	01/06	1		
BFD	717	01/06	5	5	Other late crew Wait for the crew Amtrak 14., Other, BFD Depot
EMY	6	01/06	1		
GTA	794	01/06	7	7	Restrictive signal(s) from unknown cause Control Point, south ellwood
LAX	4	01/06	5	5	Water, commissary, toilet/trash dumping Train spotted late due to late turn-around of equipment
LAX	14	01/06	(Trn Cxld)		Track Washout
OKJ	520	01/06	14	14	Door Car 8010 had no door lights, C8010
OKJ	522	01/06	9	9	TWO ENGINES ADDED LATE FOR TRANSPORT TO STOCKTON FACILITY. DELAYED IN YARD AWAITING LOAD TESTS. C2006, C2004
SAC	529	01/06	72	72	529 canceled out of ARN . Originated in sac with new train set . Departure set at 853
SAC	539	01/06	1	1	CSA looking for pax with lost bag from the RNO bus. Pax later found on board and her info related to Sac tix.
SAC	541	01/06	1		
SAC	547	01/06	1		

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/6/2026

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Terminal	Train	Date	Late	Delay	Cause
SAS	22	01/06	437	437	Hold for connecting train 2
SJC	530	01/06	1	1	Door C8028, Door light issue - Resolved
SJC	550	01/06	1		

Eastern Region

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.7	94.8	309	1
CDOT	95.0	90.0	93.5	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	95.0	94.4	93.8	361	18
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(06) - North of Rocky Mount, NC - Freight Train Interference

06JAN26: Train 53(06) was delayed on the CSX North End Subdivision between MP 81.7 and MP 86.0 due to following CSX Train L252-06.

Train	Delay	Comment
53(06)	43"	

Train 49(06) - Albany, NY - Car Failure

06JAN26: Train 49(06) was delayed at Albany-Rensselaer Station due to an electrical/trainline issue. The 480 cable on diner car 68008 melted and caused a surge which burnt out the cabling on coach car 25074, which was 4 cars away. The two cars were shopped as repairs were not going to be made within a few hours. The remainder of the train had to be pulled apart so each car could be individually reinspected for damage, before rebuilding the consist.

Arrangements were made for displaced passengers and downline food service.

Approximately 23 passengers were displaced and required reaccommodating.

Train	Delay	Comment
49(06)	3'04"	

Amtrak NYP Line West of Newark Liberty Airport, NJ - Bridge Strike

06JAN26: A bridge strike was reported on the Amtrak New York to Philadelphia main line one mile west of Newark Liberty Airport at McClellan Street/MP 12.37. Special Instruction 132-S2 was placed into effect, requiring restricted speed not exceeding 20 miles per hour until an inspection was performed.

The bridge was cleared for normal ops by B&B personnel at 7:20pm.

Train 284(06) Albany-Kenilworth, NY - Engine Failure

06JAN26: Train 284(06) with set 12, PC/2133-2124, was delayed departing Albany on the Amtrak Hudson line due to E/711 shopped for a battery charging issue and replaced with E/706. Once the train was made up and the passengers were on board, 284(06) departed Albany at 139PM-ET, 34 minutes late.

Train	Delay	Comment
284(06)	32"	

Train NextGen 2108(08) Washington, DC - Engine Failure

06JAN26: NextGen 2108(08) with set 12, PC/2133-2124, was delayed departing Washington due to it being necessary to loop account a do not lead on PC/2124 for propulsion. Once the equipment was looped and boarded, 2108(08) departed Washington at 1115AM-ET, 45 minutes late.

Train	Delay	Comment
NextGen 2108(08)	45"	

Amtrak PW Line New Carrollton, MD - Temporary Speed Restrictions

06JAN26: 924AM-ET, A 15/10 mph speed restriction was implemented on 2 track at Carrol/MP 127.0 due to a broken frog switch. Trains were delayed operating through the area until MOW was able to respond, take 2 track out of service, and make repairs. Once repairs were complete, 2 track was returned for normal speed and service.

Train	Delay	Comment
2162(06)	13"	
182(06)	11"	
114(06)	11"	
174(06)	03"	
MARC	15"	Multiple
98(05)	10"	
2108(06)	15"	
141(06)	09"	

Train 98(05) Washington, DC - Injured or Sick Passenger or Employee

06JAN26: Train 98(05) was delayed departing Washington due to a passenger needing medical assistance, who was removed by EMS. Train 98(05) departed Washington at 930AM-ET, 1 hour, and 37 minutes late.

Train	Delay	Comment
98(05)	38"	

Amtrak PW Line South of Newark, DE - Police Related

06JAN26: Trains were delayed on the Amtrak Philadelphia to Washington Main Line, 12 miles south of Newark, due to a report of stolen wire at Bacon/MP 51.0 that caused a TOL on three track. C&S was on scene and made repairs.

Train	Delay	Comment
111(06)	03"	
89(06)	06"	
79(06)	09"	
2107(06)	12"	
181(06)	04"	

Train 63/69(06) New York, NY - Initial Terminal Delay

06JAN26: Train 63/69(06) was delayed departing New York at 755AM-ET, 40 minutes late due to a late release from Sunnyside yard for a battery charger issues on E/711. Once the train was released and boarded, 63/69(06) departed New York at 755AM-ET, 40 minutes late.

Train	Delay	Comment
63/69(06)	40"	

Train 2150(06) Washington, DC - Catenary or Wayside Failure

06JAN26: Train 2150(06) was delayed departing Washington due to power outage making it necessary to swap set of equipment.

Train	Delay	Comment
2150(06)	1'05"	

Train 41(05) Pittsburgh, PA - Servicing

06JAN26: Train 41(05) was delayed at Pittsburgh on the NS Pittsburgh district due to a late arriving fuel truck. Once the fuel truck arrived, the train was fueled, and departed Pittsburgh at 604AM-ET, 39 minutes late.

Train	Delay	Comment
41(05)	39"	

Train 98(05) - South of Petersburg Station, VA - Freight Train Interference

06JAN26: Train 98(05) was delayed on the CSX North End Subdivision at MP 64.8 due to CSX Train I035-06 having a hot journal alarm triggered by a car a mile deep in its consist.

Train	Delay	Comment
98(05)	1'19"	

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Eastern Region

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 69(06) Passenger Removal at Rouses Point, New York – Customs***

06JAN26, Passenger on PNR 45C40A, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69(06) None

Train 69(06) Passenger Removal at Rouses Point, New York – Customs

06JAN26, Passenger on PNR 3645CF, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69(06) None

Operating Highlights

Train 4(05) West of Newton, KS - Passenger Train Interference

07JAN26: Train 4(05) was delayed at First St/MP185.4 0.3 miles west of Newton, KS/MP185.1 on the BNSF La Junta subdivision due to Amtrak train 3(06) blocking the station track. Once the route was clear, train 4(05) entered Newton, KS.

Train	Delay	Comment
4(05)	34"	

Train 58(06) North of Memphis, TN - Freight Train Interference

07JAN26: Train 58(06) was delayed at Tipton siding/MP365.1 33 miles north of Memphis, TN/MP391.8 on the CN Fulton subdivision meeting CN freight CN/3221. Once the route was clear, train 58(06) continued north.

Train	Delay	Comment
58(06)	35"	

Train 7/27(06) East of St. Paul-Minneapolis, MN - Freight Train Interference

07JAN26: Train 7/27(06) was delayed at St Croix/MP392.1 18 miles east of St Paul-Minneapolis, MN/MP410.3 on the CP Rive subdivision following CP freight 149. Once the route was clear train 7/27(06) continued west.

Train	Delay	Comment
7/27(06)	35"	

Train 7/27(05) West of Browning, MT - Freight Train Interference

07JAN26: Train 7/27(05) was delayed between Browning, MT/MP1123.9 and Essex, MT/MP1168.9 on the BNSF Hi Line subdivision following BNSF freight due to congestion caused by high wind warnings. Once clear of the affected area, train 7/27(05) continued west.

Train	Delay	Comment
7/27(05)	53"	

Train 307(06) North of Bloomington-Normal, IL - Air Hose Separation

06JAN26: Train 307(06) was delayed at mile post 113.2 11 miles north of Bloomington-Normal, IL/MP124.0 on the UP Joliet subdivision due to an air hose separation between cars IDTX4114 and IDTX4019. The crew reconnected the hoses, restored air pressure, and departed after a successful brake test. The hose separated again at mile post 147.5. The crew reconnected the hose and clipped it higher to avoid additional separations before departing again.

Train	Delay	Comment
307(06)	13"	
307(06)	14"	

Train 509(06) South of Tacoma, WA - Vehicle on Tracks

06JAN26: Train 509(06) was delayed departing Tacoma, WA. A vehicle was stuck on the tracks at Clover Creek SW Road crossing in Lakewood, WA (DOT# 085822W) MP 10.92, Lakewood Subdivision of the Sounder Railroad. The car was blocking main track #1, requiring train 509(06) shove back to cross tracks and continue past the car on track #2 then train 509(06) continued Olympia. Amtrak Police Notified

Train	Delay	Comment
509(06)	32"	

Train 41(06) Chicago, IL - Late Release

06JAN26: Train 41(06) was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late release of the equipment by mechanical due to a locomotive shortage. Once the equipment was made up complete, train 41(06) shoved into the depot, boarded passengers, and departed.

Train	Delay	Comment
41(06)	59"	

Train 542(06) – North of Oakland Coliseum, CA – Vehicle on Tracks

06JAN26: Train 542(06) was delayed at Oakland Coliseum station after a vehicle became stuck on the tracks at 50th Avenue (DOT# 749716B), MP 10.77, Niles Subdivision, Union Pacific Railroad. All tracks were blocked until a Union Pacific track inspector and tow truck removed the vehicle and confirmed the track was safe. Service then resumed. Amtrak Police were notified.

Service Recovery: Affected passengers offered 20% discount on cafe items

Mutual Aid: Bay Area Rapid Transit (BART) accepted Capitol Corridor tickets between Oakland Coliseum and Richmond until 7:30PM-PT

Train	Delay	Comment
542(06)	1'04"	

Train 717(06) – West of Corcoran, CA - Signal Integrity Failure

06JAN26: Train 717(06) was delayed near Guernsey (MP 959.4) on the BNSF Bakersfield Subdivision due to a loss of remote signal access. The engineer maintained verbal communication with the dispatcher and operated at restricted speed until reaching the next controlled signal. The train then resumed normal track speed to Hanford.

Train	Delay	Comment
717(06)	21"	Guernsey
712(06)	28"	Guernsey - Meet 717(06)

Train 59(05) South of Hammond, LA - Engine Failure

06JAN26: At 253P-CT, Train 59(05) operating with E/69, 7 cars and 69 passengers onboard, stopped at MP866.4 approximately 7 miles south of Hammond, LA Station on CN McComb Subdivision due to cab signal issues. Crew on the phone with CNOC Mechanical to rectify and back on the move 310P-CT. At 322P-CT Train 59(05) stopped again at MP874.6 due to a overspeed penalty. Working with CNOC Mechanical, they rectified and were on the move at 356P-CT. Train 59(05) stopped a third time at 4:17PM CT at MP889.1 but the engineer was able to clear the penalty and get back on the move at 4:24PM CT.

Train 58(06) was operating with E/122 was stopped at MP875.3 approximately 16 miles south of Hammond, LA waiting on Train 59(05) to clear.

Train	Delay	Comment
59(05)	1'06"	

Train 4(04) Chicago, IL - Commuter Train Interference

06JAN26: Train 4(04) 26-FOI-00235, 00000005580 car "UNCLASSIFIED" layer 1/14/2026 approximately 16 miles west of Chicago, IL on BNSF Chicago Subdivision following Train 6(04), met with 3 freights, and Metra.

Train	Delay	Comment
4(04)	39"	

Train 530(06) Fairfield - Vacaville, CA – Police Investigate Shooting Near Tracks

06JAN26: Trains 530(06) was delayed when rail tracks were closed in the vicinity of MP 53.84, Fairfield - Vacaville Station, Martinez Subdivision of the Union Pacific Railroad. This was to allow for local police to investigate reports of a shooting in the area (non-rail related) . Once the investigation was completed with all personnel clear, the tracks were re-opened allowing for trains to continue. Amtrak Police Notified.

Train	Delay	Comment
530(06)	23"	

Train 334(06) East of Milwaukee, WI - Cab Car Failure

06JAN26: Train 334(06) operating with CC/90200, 4 cars, E/IDTX4613 and 68 passengers onboard, stopped at MP 82.7 on CPKC C&S Subdivision approximately 3 miles east of the Milwaukee, WI Station due to a bad order speedometer. Train 334(06) cut out their PTC and operated 59 MPH to Chicago, IL. Upon arrival into Chicago, CC/90200 was capped with E/518, the equipment turned and operated as Train 335(06).

Train	Delay	Comment
334(06)	27"	CHI-MKE/PTC 59MPH
335(06)	41"	
338(06)	40"	
339(06)	22"	

Train 59(05) South of Marks, MS - Freight Train Interference

06JAN26: Train 59(05) was delayed south of Marks, MS/MP67.3, on the CN Yazoo Subdivision, following BNSF 3808 and CNG888 between North Swan Lake/MP92.7 and Greenwood/MP122.

Train	Delay	Comment
59(05)	33"	

Train 516(06) Bellingham, WA - Freight Train Interference

06JAN26: Train 516(06) was delayed at Bellingham, MP 93.4/BNSF Bellingham Subdivision, waiting on BNSF freight train LNWE626106T to clear ahead at MP 99 after stalling while climbing the grade.

Train	Delay	Comment
516(06)	29"	

05JAN26: Locomotive CDX 60236 reported "UNCLASSIFIED" issue with the fire alarm system and visible smoke in the engine room while equipment was on layover in Auburn, CA (ARN). There was no actual fire and locomotive was shut down as a precaution. To maintain service the following recovery plan was enacted:

- Three replacement buses secured to operate from Auburn, CA to Sacramento, CA.
- Train 529(05) Originate in Sacramento, CA.
- Train 531(05) Cancelled - passengers accommodated on later departures.
- An extra set of locomotives was attached to train 522(05) so that a light engine move could operate from SAC to ARN to rescue the disabled equipment and tow it to Oakland Yard for repairs.
- Train 534(06) was cancelled; passengers were reaccommodated onto Train 536(06).

WBS#: B.TR.100150.6374

Train	Delay	Comment
529(06)	Orig at SAC	Bus ARN-SAC
529(06)	1'12"	SAC
531(06)	Cancelled	
534(06)	Cancelled	

Train 390(06) South of Champaign-Urbana, IL - Freight Train Interference

06JAN26: At 958A-CT, Train 390(06) operating with E/316, 7 cars and 56 passengers onboard, was delayed south of Champaign, IL Station approximately AT 20 miles north of Mattoon, IL Station at MP 152.9 due to a freight train disabled at Tuscola (UP and CSX Crossing) at MP 149.8 on CN Champaign Subdivision. The freight train had a wrong end draw bar issues. Train 390(06) shoved back to Mattoon, IL and Train 391(06) operating with E/IDTX4608, 7 cars and 63 passengers onboard, was held at Champaign, IL Station for disposition.

Alternate transportation was secured, 3 buses for Train 390(06) at Mattoon, IL and 2 buses at Champaign, IL for Train 391(06). One bus arrived at Mattoon, IL and picked up passengers.

At 1215P-CT the freight train was cleared and the track inspector was on the scene. At 1230P-CT, the track inspector cleared the tracks for operation. Train 390(06) and Train 391(06) continue to their final destination delayed due to freight congestion.

Due to the late operation of train 390(06), train 393(06) was delayed departing Chicago Union Station, IL.

WBS#: B.TR.100150.6379

Train	Delay	Comment
391(06)	2'01"	
390(06)	3'46"	
393(06)	1'52"	

Train 8/28(05) Libby, MT - M of W Work

06JAN26: At 445A-MT, Train 8/28(05) operating with E/369, E/340, 10 cars and 117 passengers onboard, was delayed on BNSF Kootenai River Subdivision at MP1349 approximately 30 miles west of Libby, MT Station due to a broken rail at MP1345. BNSF track inspector arrived on the scene at approximately 518A-PT, inspected the track and Train 8/28(05) was on the move at approximately 616A-MT at restricted speeds.

Train	Delay	Comment
8/28(05)	1'37"	

06JAN26: Worsening winter weather conditions with up to 4 feet of snow forecast - on the Scenic Subdivision west of Spokane.

Road conditions were prohibitive for operating buses between Spokane and Seattle.

The following service alterations were implemented:

- Train 7(05) Terminates Spokane. All passengers travelling to Seattle were provided hotel accommodation at the Centennial Hotel in the City. Replacement bus service operated departing in the afternoon of 7th January, from Spokane express thru to Portland where passengers boarded next departure to destination. Train equipment turned in Spokane for 8(06).
- Train 27(05) Terminates in Spokane. Replacement buses operated to Pasco (PSC), Wishram (WIH), Bingham (BNG) and Vancouver, WA (VAN). An express bus operated from Spokane thru to Portland (PDX). Train equipment turned in Spokane for 28(06).
- Train 8(06) Originates Spokane, No replacement transport was offered from Seattle.
- Train 28(06) Originates Spokane. Replacement buses operated from Vancouver, WA (VAN), Bingham (BNG), Wishram (WIH), and Pasco (PSC) to Spokane (SPK). An express bus operated from Portland (PDX) thru to Spokane (SPK).
- Train 8/28(06) was delayed departing Spokane, servicing and turning equipment from 7/27(05).

WBS#: B.TR.100150.6381

Train	Delay	Comment
7(05)	Terminates Spokane	Passengers to Hotel
27(05)	Terminates Spokane	Passengers to Replacement Buses
8(06)	Originates Spokane	No Replacement Transport Offered
28(06)	Originates Spokane	Replacement Buses from Missed Stops

UNION PACIFIC RAILROAD SANTA BARBARA SUBDIVISION LANDSLIDE NORTH OF GOLETA, CA

06JAN26: At approximately 7:50AM-PT, UPRR reported a major landslide and resulting track damage at MP 342.25/UPRR Santa Barbara Subdivision, 15.85 miles north of Goleta. Estimates for track restoration were up to 4 to 7 days. As a result, the following immediate service alterations were placed in-effect:

PACIFIC SURFLINER

-Train 761(06) terminated at Goleta. Buses were sourced to operate Santa Barbara to San Luis Obispo.

-Train 774(06) initially held at Gaviota, MP 335.9, then reversed back to San Luis Obispo. Buses were sourced to operate San Luis Obispo to Santa Barbara, connecting with the next available train departure.

-An "on-time" section of Train 774(06) operated Los Angeles to San Diego using Comet equipment.

-Train 794(06) originated at Goleta. Buses were sourced to operate San Luis Obispo to Santa Barbara.

-Train 779(06) terminated at Goleta. Buses were sourced to operate Santa Barbara to San Luis Obispo.

COAST STARLIGHT

-Train 11(05) terminated at Emeryville. Passengers with destinations Santa Barbara through Los Angeles transferred to Train 712(06) then connecting Thruway Bus service from Bakersfield. Passengers with destinations Salinas through San Luis Obispo transferred to Thruway Schedule 4794(06). Passengers with final destination of San Jose transferred to Train 529(06).

-Train 14(06) originated at Emeryville. Passengers boarding at Los Angeles were reaccommodated onto Thruway Schedules 5717/5817(06) to Bakersfield then Train 717(06) to Martinez. Connection to Train 14(06) was made in Martinez. No alternate transportation was available between Los Angeles and Emeryville.

subdivision, leading to the following alteration to service:

- Train 11(06) terminates Emeryville. Alternate transportation was available between Emeryville and Los Angeles via Gold Runner train/bus service.
- Train 14(07) originates at Emeryville. Alternate transportation was available between Los Angeles and Emeryville via Gold Runner bus/train service.
- Train 761(07) Terminates Goleta, no alternate transport offered to missed stops.
- Train 779(07) Terminates Goleta, no alternate transport offered to missed stops.
- Train 774(07) Originates Terminates Goleta, no alternate transport offered from missed stops.
- Train 794(07) Originates Terminates Goleta, no alternate transport offered from missed stops.

Work Element WBS # B.TR.100150.6380

WBS#: B.TR.100150.6380

Train	Delay	Comment
774(06)	On-time section LAX-SAN	
761(06)	Term GTA	Buses SBA-SLO
794(06)	Orig GTA	Buses SLO-SBA
779(06)	Term GTA	Buses SBA-SLO
14(06-07)	Orig EMY	
11(05-06)	Term EMY	
761(07)	Terminates Goleta	No Replacement Service Offered
779(07)	Terminates Goleta	No Replacement Service Offered
774(07)	Originates Goleta	No Replacement Service Offered
794(07)	Originates Goleta	No Replacement Service Offered
774(06)		Returned to SLO then buses SLO-SBA

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated from Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

-Train 535(29) Cancelled - No alternate transportation.
 -Train 537(30) Cancelled - No alternate transportation.
 -Train 551(29-30) Cancelled - No alternate transportation. Comment "UNCLASSIFIED" amendment 1/14/2026
 26-FOI-00235 R09000006590

31DCE25

-Train 520(31) Cancelled - No alternate transportation.
 -Train 534(31) Cancelled - No alternate transportation.
 -Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.
 -Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-06MAR) Cancelled - No alternate transportation.
 - TRAIN 713(06JAN-07MAR) Cancelled - No alternate transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
714(23)	.	CANCELLED
713(24)	.	CANCELLED
535(24)	Cancelled	
520(24)	Cancelled	
534(24)	Cancelled	
736(25-28)	Cancelled	
737(25-28)	Cancelled	
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
551(29-30)	Cancelled	Replacement Bus SAC-OKJ
520(29-31)	Cancelled	No alternate transportation.
534(29-31)	Cancelled	No alternate transportation.
736(01JAN-04JAN)	Cancelled	No alternate transportation
737(01JAN-04JAN)	Cancelled	No alternate transportation
535(29)	Cancelled	No alternate transportation.
537(30-31)	Cancelled	No Alternate Transportation
713(06JAN-07MAR)	CANCELLED	No Alternate Transport Offered
714(05JAN-06MAR)	CANCELLED	No Alternate Transport Offered

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 352(06) Passenger Removal at Battle Creek, Michigan – Other

06JAN26, Passenger on PNR 4815C5, traveling from Chicago, IL to Detroit, MI was removed by Amtrak Police at Battle Creek, MI due to making threats toward the Conductor and she didn't want anyone to sit next to her. Amtrak Police notified.

Delay: 352 (06) 03"

Train 2(04) Passenger Removal at Alpine, Texas – Medical

06JAN26, Passenger on PNR 4653FC, traveling from Los Angeles, CA to Houston, TX was removed by EMS at Alpine, TX due to kidney pain. Amtrak Police notified.

Delay: 2 (04) 10"

Train 3(05) Passenger Removal at Grants, New Mexico – Improper Conduct

26-FOI-00235 00000005580 "UNCLASSIFIED" 1/14/2026

06JAN26, Both passengers were removed by the local police at Grants, NM (MP 96.4 on the BNSF Railroad on the Gallup Subdivision) due to being intoxicated and getting into a physical altercation. Amtrak Police notified.

Passenger on PNR 4844BA, traveling from Albuquerque, NM to Gallup, NM.

Passenger on PNR 497000, traveling from Albuquerque, NM to Gallup, NM.

Delay: 3(05) 23"

Train 352(06) Passenger Removal at Ann Arbor, Michigan – Medical

06JAN26, Passenger on PNR 43C1D9, traveling from Chicago, IL to Troy, MI was removed by EMS at Ann Arbor, MI due to being passed out in the vestibule between cars 4304 and 4120. He was not injured. Amtrak Police notified.

Delay: 352(06) 21"

Consist Deviations

26-FOI-00235

00000005580

"UNCLASSIFIED"

1/14/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
5 (06)	CHI	Transition Sleeper Car 32051 does not have a ADA/ H Room. Check War Reports and notify/reaccomodate affected passengers if needed.	NONE	0	32051
6 (06)	EMY	Transition Sleeper Car 32051 does not have a ADA/ H Room. Check War Reports and notify/reaccomodate affected passengers if needed.	NONE	0	32051
774 (06)	LAX	COMET SET- NO BUSINESS CLASS, CAFE OR BIKE SERVICE.			
98 (06)	MIA	view II sleeper in lieu of viw I sleeper	N/A	0	62518
98 (06)	MIA	Due to a change in equipment it was necessary to perform a schedule change on trains 98(06)-line 9811 and 97(08)-line 9711. Please utilize the WAR reports to ensure all passengers have been accommoda	PASSENGERS REACCOMODATED	0	62516
181 (06)	NYP	operating with 1 motor	N/A	0	606
111 (06)	NYP	operating ith 1 motor	N/A	0	626
151 (06)	PHL	82534 shopped due wheel shelling with no replacement, 151 operating with 3 coaches.	NONE	0	82534
66 (06)	RNK	82534 shopped due wheel shelling with no replacement, 66 operating with 3 coaches.	NONE	0	82534
587 (06)	SAN	COMET SET- NO BUSINESS CLASS, CAFE OR BIKE SERVICE.			
1 (07)	SAS	Due to needing single car air test, car cannot run and 1(07) is oversold.	ue to needing single car air test, car cannot run and 1(07) is oversold.	23	34063

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		inventory adjusted. Re-accommodate passengers to 421 section.	inventory adjusted. Re-accommodate passengers to 421 section.		
8 (06)	SPK	Sleeper canceled due to short turn of equipment. Check War Reports and re-accommodate as able.	Sleeper canceled due to short turn of equipment. Check War Reports and re-accommodate as able.	7	

Reverse Consists

Train Number	Station	Reason
173 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (06)	RVM	Consist reversed Business class seat orientation may have changed At Front
179 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
110 (06)	PHL	Consist reversed Business class seat orientation may have changed At Rear
185 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
234 (06)	ALB	Consist reversed Business class seat orientation may have changed At Rear
281 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front
2108 (06)	WAS	Acela consist reversed First class at Front
176 (06)	WAS	Consist reversed Business class seat orientation may have changed At Rear