

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, August 06, 2026

Rules: 0-44



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/05/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	52	83.7%	1,527	243	84.1%	92,471	12,796	86.2%
Central Division	86.0%	56	6	89.3%	283	36	87.3%	17,711	1,610	90.9%
East Division	82.0%	177	23	87.0%	827	116	86.0%	48,497	7,535	84.5%
West Division	86.0%	86	23	73.3%	417	91	78.2%	26,263	3,651	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00644 00000008493 "UNCLASSIFIED" 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	98,698	31,529	68%	539,866	152,316	72%	30,888,868	7,792,110	75%
Northeast Corridor	81%	42,930	11,892	72%	232,248	52,740	77%	13,542,961	3,309,306	76%
Acela	83%	9,964	690	93%	47,677	9,866	79%	2,708,589	711,303	74%
Northeast Regional	79%	32,966	11,202	66%	184,571	42,874	77%	10,834,372	2,598,003	76%
Richmond / Newport News / Norfolk	77%	9,677	4,082	58%	58,350	18,368	69%	3,364,549	980,784	71%
Springfield Shuttles	89%	636	47	93%	3,308	200	94%	192,045	30,287	84%
Roanoke	79%	3,416	934	73%	17,573	2,902	83%	1,023,085	221,363	78%
On Spine Northeast Regional	80%	19,237	6,139	68%	105,340	21,404	80%	6,254,693	1,365,569	78%
State Supported	80%	44,584	12,115	73%	242,284	62,406	74%	13,557,073	2,865,240	79%
Borealis	80%	548	32	94%	2,964	341	88%	172,617	35,988	79%
Capitol Corridor	90%	4,152	1,571	62%	17,836	3,448	81%	1,136,277	149,546	87%
Carolinian	70%	909	638	30%	5,441	2,081	62%	350,287	137,050	61%
Cascades	75%	1,202	695	42%	9,859	4,688	52%	793,379	219,791	72%
Downeaster	82%	1,875	0	100%	10,274	417	96%	470,485	56,242	88%
Empire	78%	6,153	1,587	74%	32,049	9,872	69%	1,676,491	393,719	77%
Adirondack	72%	390	6	98%	2,224	471	79%	102,227	31,334	69%
Ethan Allen Express	70%	535	430	20%	3,009	1,626	46%	171,953	62,002	64%
Maple Leaf	70%	812	331	59%	4,641	2,175	53%	205,585	79,317	61%
New York - Albany	85%	3,172	378	88%	14,431	3,740	74%	776,869	129,675	83%
New York - Niagara Falls	75%	1,244	442	64%	7,145	1,267	82%	411,137	86,982	79%
Berkshire Flyer	60%	0	0	-	599	593	1%	8,720	4,409	49%
Gold Runner	73%	2,312	1,445	38%	12,839	7,658	40%	768,374	277,804	64%
Heartland Flyer	70%	243	230	5%	1,430	1,264	12%	66,097	26,690	60%
Hiawatha	90%	1,768	0	100%	10,145	599	94%	531,421	58,327	89%
Illinois	78%	2,206	484	78%	13,187	3,550	73%	759,572	208,159	73%
Carl Sandburg / Illinois Zephyr	85%	484	233	52%	1,636	757	54%	126,497	34,938	72%
Illini / Saluki	85%	600	131	78%	4,344	1,606	63%	264,343	63,540	76%
Lincoln Service	70%	1,122	120	89%	7,207	1,187	84%	368,732	109,681	70%
Keystone	92%	9,217	484	95%	38,678	2,258	94%	2,334,123	241,438	90%
Lincoln / Missouri	70%	387	139	64%	4,130	2,433	41%	236,578	120,551	49%
Mardi Gras Service	80%	409	199	51%	1,925	669	65%	125,026	28,019	78%
Michigan	70%	2,320	996	57%	12,591	6,992	44%	610,185	199,375	67%
Blue Water	70%	620	427	31%	2,849	2,261	21%	142,427	57,977	59%
Pere Marquette	85%	178	0	100%	1,518	176	88%	79,959	15,297	81%
Wolverine	70%	1,522	569	63%	8,224	4,555	45%	387,799	126,101	67%
Missouri	80%	205	159	22%	1,483	473	68%	67,250	16,932	75%
Pacific Surfliner	85%	8,157	1,743	79%	51,916	11,277	78%	2,452,210	438,679	82%
Pennsylvanian	80%	713	390	45%	4,191	1,288	69%	270,067	52,206	81%
Piedmont	80%	607	163	73%	4,662	728	84%	344,898	89,297	74%
Vermont	75%	1,201	1,160	3%	6,684	2,370	65%	391,736	115,427	71%
Long Distance	70%	11,184	7,522	33%	65,334	37,170	43%	3,749,567	1,615,101	57%
Auto Train	70%	829	460	45%	4,343	917	79%	238,750	81,667	66%
California Zephyr	70%	993	655	34%	5,132	3,657	29%	296,461	110,097	63%
Cardinal	70%	248	20	92%	1,170	637	46%	72,734	36,227	50%
City Of New Orleans	75%	539	519	4%	3,254	2,577	21%	194,256	60,607	69%
Coast Starlight	70%	412	363	12%	5,370	2,546	53%	349,948	123,083	65%
Crescent	70%	661	119	82%	4,475	637	86%	283,876	86,426	70%
Empire Builder	70%	1,087	655	40%	4,961	4,221	15%	295,081	147,881	50%
Floridian	60%	799	588	26%	8,060	6,573	18%	485,814	333,601	31%
Lake Shore Ltd	73%	1,070	843	21%	6,144	2,302	63%	294,381	87,769	70%
Palmetto	70%	1,199	564	53%	5,089	2,077	59%	280,919	84,499	70%
Silver Meteor	70%	880	804	9%	5,115	3,620	29%	310,337	140,963	55%
Southwest Chief	60%	1,021	1,021	0%	5,255	3,560	32%	255,509	165,966	35%
Sunset Ltd	70%	370	222	40%	984	700	29%	89,384	33,436	63%
Texas Eagle	70%	1,076	689	36%	5,982	3,146	47%	302,117	122,879	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00044 00000000400 "UNCLASSIFIED" 8/7/2026

Train Index Dates Through August 05, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	32,106	536,100	599	1,821,901	32,484,116	561

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,821	161,073	113	87,731	9,358,076	94
INFRASTRUCTURE PLANNED	135	2,268	161,073	141	98,323	9,358,076	105
FLEET RELIABILITY	90	4,706	536,100	88	290,797	32,484,116	90
TRAIN OPERATIONS	424	23,311	536,100	435	1,345,050	32,484,116	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	08/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/05/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	52	83.7%	1,527	243	84.1%	92,471	12,796	86.2%
Central Division	86.0%	56	6	89.3%	283	36	87.3%	17,711	1,610	90.9%
East Division	82.0%	177	23	87.0%	827	116	86.0%	48,497	7,535	84.5%
West Division	86.0%	86	23	73.3%	417	91	78.2%	26,263	3,651	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-001100-2025-0001 Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/05/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	52	83.7%	1,527	243	84.1%	92,471	12,796	86.2%
Central Division	86.0%	56	6	89.3%	283	36	87.3%	17,711	1,610	90.9%
CDL	95.0%	2	0	100.0%	10	2	80.0%	586	27	95.4%
CHI	86.0%	25	4	84.0%	130	22	83.1%	8,180	989	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	5	0	100.0%	332	36	89.2%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	-	-	-	4	0	100.0%	292	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	10	1	90.0%	597	45	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	28	1	96.4%	1,808	115	93.6%
MOE	97.5%	2	0	100.0%	10	0	100.0%	615	9	98.5%
MSP	96.5%	1	0	100.0%	5	1	80.0%	302	7	97.7%
NOL	94.5%	5	0	100.0%	23	0	100.0%	1,296	60	95.4%
OKC	97.0%	1	0	100.0%	5	0	100.0%	303	6	98.0%
PNT	88.0%	3	1	66.7%	15	2	86.7%	802	66	91.8%
PTH	93.0%	1	0	100.0%	5	1	80.0%	297	12	96.0%
QCY	91.0%	2	0	100.0%	7	1	85.7%	584	44	92.5%
SAS	90.5%	1	0	100.0%	5	1	80.0%	306	34	88.9%
STL	89.0%	4	0	100.0%	20	3	85.0%	1,195	103	91.4%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	177	23	87.0%	827	116	86.0%	48,497	7,535	84.5%
ALB	88.5%	8	1	87.5%	39	3	92.3%	2,289	178	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	25	2	92.0%	1,491	160	89.3%
BOS	85.5%	18	2	88.9%	88	5	94.3%	5,251	609	88.4%
BRK	92.5%	5	0	100.0%	25	1	96.0%	1,477	103	93.0%
BTN	82.0%	1	0	100.0%	5	0	100.0%	295	41	86.1%
CLT	91.5%	5	0	100.0%	25	2	92.0%	1,502	152	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	10	0	100.0%	603	57	90.5%
GRO	-	2	0	100.0%	6	0	100.0%	39	10	74.4%
HAR	79.5%	13	1	92.3%	53	9	83.0%	3,417	557	83.7%
HFD	-	2	1	50.0%	6	2	66.7%	197	17	91.4%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	5	0	100.0%	305	38	87.5%
MIA	89.5%	2	0	100.0%	10	0	100.0%	610	68	88.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/05/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	52	83.7%	1,527	243	84.1%	92,471	12,796	86.2%
East Division	82.0%	177	23	87.0%	827	116	86.0%	48,497	7,535	84.5%
MTR	79.0%	1	0	100.0%	5	1	80.0%	292	53	81.8%
NFK	84.5%	2	0	100.0%	10	2	80.0%	693	125	82.0%
NFL	93.5%	2	0	100.0%	10	0	100.0%	622	29	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	24	2	91.7%	1,578	255	83.8%
NPN	93.0%	2	0	100.0%	10	2	80.0%	583	44	92.5%
NYP	75.5%	51	11	78.4%	229	54	76.4%	12,713	2,832	77.7%
PGH	93.0%	1	0	100.0%	5	1	80.0%	306	23	92.5%
PHL	48.0%	5	2	60.0%	23	12	47.8%	1,573	752	52.2%
PIT	76.0%	-	-	-	1	1	0.0%	16	13	18.8%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	2	0	100.0%	14	0	100.0%	1,172	49	95.8%
RNK	83.5%	2	0	100.0%	10	0	100.0%	606	87	85.6%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	6	4	33.3%
SAB	98.0%	1	0	100.0%	5	0	100.0%	292	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	302	10	96.7%
SFA	88.0%	1	0	100.0%	5	0	100.0%	305	41	86.6%
SPG	92.5%	5	0	100.0%	28	0	100.0%	1,835	105	94.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	5	1	80.0%	294	61	79.3%
WAS	84.0%	31	4	87.1%	141	16	88.7%	7,613	983	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	86	23	73.3%	417	91	78.2%	26,263	3,651	86.1%
ARN	92.0%	1	0	100.0%	5	0	100.0%	307	26	91.5%
BFD	79.0%	7	3	57.1%	34	10	70.6%	1,931	403	79.1%
EMY	72.0%	1	0	100.0%	5	1	80.0%	323	95	70.6%
EUG	86.5%	2	0	100.0%	10	0	100.0%	608	56	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	1	0	100.0%	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	15	5	66.7%	924	148	84.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	3	72.7%	51	6	88.2%	3,050	332	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	12	8	33.3%	55	26	52.7%	3,316	854	74.2%
PDX	86.0%	3	3	0.0%	16	9	43.8%	1,504	190	87.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/05/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	52	83.7%	1,527	243	84.1%	92,471	12,796	86.2%
West Division	86.0%	86	23	73.3%	417	91	78.2%	26,263	3,651	86.1%
SAC	88.5%	15	1	93.3%	70	6	91.4%	4,336	468	89.2%
SAN	90.5%	13	1	92.3%	64	6	90.6%	3,705	350	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	2	33.3%	26	12	53.8%	2,411	359	85.1%
SJC	89.0%	7	0	100.0%	34	4	88.2%	2,158	213	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	15	2	86.7%	687	67	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	3	1	66.7%	301	27	91.0%
VAC	97.0%	2	0	100.0%	10	0	100.0%	601	14	97.7%
VAN	-	1	1	0.0%	3	3	0.0%	3	3	0.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	611	3	0	100.0%	131	9	93.1%	1	1	0.0%	130	32	75.4%
3	62	5	1	80.0%	307	60	80.5%	5	3	40.0%	305	139	54.4%
4	131	5	0	100.0%	306	46	85.0%	5	3	40.0%	306	202	34.0%
5	105	5	1	80.0%	305	51	83.3%	5	5	0.0%	301	93	69.1%
6	229	5	1	80.0%	304	86	71.7%	5	4	20.0%	304	107	64.8%
7	69	5	2	60.0%	296	44	85.1%	4	4	0.0%	287	78	72.8%
8		5	5	0.0%	296	134	54.7%	5	4	20.0%	295	179	39.3%
11	218	5	3	40.0%	307	60	80.5%	5	1	80.0%	301	61	79.7%
14	60	5	2	60.0%	308	51	83.4%	4	4	0.0%	305	96	68.5%
19		5	1	80.0%	306	78	74.5%	5	0	100.0%	303	71	76.6%
20	41	5	0	100.0%	306	23	92.5%	5	1	80.0%	306	59	80.7%
21	34	5	2	60.0%	303	27	91.1%	5	2	60.0%	302	84	72.2%
22		5	1	80.0%	304	32	89.5%	5	0	100.0%	302	81	73.2%
23		5	0	100.0%	308	6	98.1%	5	2	60.0%	306	87	71.6%
24		5	0	100.0%	308	16	94.8%	5	3	40.0%	307	59	80.8%
25	30	5	0	100.0%	307	3	99.0%	5	2	60.0%	305	85	72.1%
26	61	5	0	100.0%	307	5	98.4%	5	1	80.0%	305	61	80.0%
27	No OS	3	3	0.0%	288	19	93.4%	2	2	0.0%	283	95	66.4%
40		5	0	100.0%	301	41	86.4%	5	2	60.0%	298	157	47.3%
41	No OS	5	3	40.0%	300	117	61.0%	5	5	0.0%	298	229	23.2%
42	163	5	1	80.0%	308	25	91.9%	5	2	60.0%	306	54	82.4%
43		5	0	100.0%	307	42	86.3%	5	0	100.0%	306	70	77.1%
48		5	1	80.0%	306	58	81.0%	5	0	100.0%	305	42	86.2%
49	45	5	3	40.0%	306	78	74.5%	5	1	80.0%	306	63	79.4%
50		2	0	100.0%	126	30	76.2%	2	1	50.0%	126	77	38.9%
52		5	0	100.0%	305	41	86.6%	5	0	100.0%	304	72	76.3%
53	33	5	0	100.0%	305	38	87.5%	5	2	60.0%	304	97	68.1%
55	32	3	0	100.0%	193	7	96.4%	3	1	66.7%	190	39	79.5%
56	100	3	1	66.7%	194	24	87.6%	3	2	33.3%	190	36	81.1%
58	40	5	0	100.0%	282	16	94.3%	4	4	0.0%	280	77	72.5%
59	165	5	4	20.0%	280	37	86.8%	5	4	20.0%	276	61	77.9%
63	69	5	2	60.0%	309	134	56.6%	5	5	0.0%	303	171	43.6%
64	31	5	1	80.0%	307	69	77.5%	5	4	20.0%	306	113	63.1%
66		5	0	100.0%	306	61	80.1%	5	1	80.0%	302	55	81.8%
67		4	1	75.0%	212	14	93.4%	3	1	66.7%	211	37	82.5%
68		5	1	80.0%	309	62	79.9%	5	1	80.0%	308	119	61.4%
69		5	3	40.0%	296	71	76.0%	5	2	60.0%	291	45	84.5%
71		5	0	100.0%	304	3	99.0%	5	0	100.0%	303	81	73.3%
72		5	1	80.0%	300	32	89.3%	5	2	60.0%	299	63	78.9%
73		5	0	100.0%	303	19	93.7%	5	1	80.0%	301	143	52.5%
74	14	5	0	100.0%	301	33	89.0%	5	2	60.0%	299	110	63.2%
75		5	0	100.0%	297	16	94.6%	5	0	100.0%	291	137	52.9%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	19	5	0	100.0%	297	29	90.2%	5	3	40.0%	288	120	58.3%
77		5	0	100.0%	299	20	93.3%	5	1	80.0%	297	124	58.2%
78		5	0	100.0%	303	25	91.7%	5	1	80.0%	302	64	78.8%
79		5	1	80.0%	306	57	81.4%	5	1	80.0%	305	102	66.6%
80	34	5	1	80.0%	306	34	88.9%	5	2	60.0%	303	65	78.5%
84	150	3	0	100.0%	184	14	92.4%	3	1	66.7%	182	44	75.8%
85		3	0	100.0%	195	16	91.8%	3	0	100.0%	195	70	64.1%
86	24	3	0	100.0%	195	15	92.3%	3	2	33.3%	194	117	39.7%
89	107	5	2	60.0%	304	67	78.0%	5	3	40.0%	302	88	70.9%
90		5	0	100.0%	304	10	96.7%	5	1	80.0%	303	52	82.8%
93		3	0	100.0%	194	19	90.2%	3	1	66.7%	193	48	75.1%
94	20	3	0	100.0%	225	55	75.6%	3	1	66.7%	223	84	62.3%
95		3	0	100.0%	194	4	97.9%	3	2	33.3%	194	71	63.4%
97	49	5	4	20.0%	306	202	34.0%	5	3	40.0%	304	103	66.1%
98	42	5	0	100.0%	306	26	91.5%	5	4	20.0%	304	112	63.2%
110		3	0	100.0%	191	102	46.6%	3	0	100.0%	188	19	89.9%
111		3	0	100.0%	185	35	81.1%	3	0	100.0%	183	21	88.5%
112		3	0	100.0%	185	18	90.3%	3	0	100.0%	184	19	89.7%
113		3	2	33.3%	116	27	76.7%	3	0	100.0%	115	14	87.8%
119	33	3	1	66.7%	182	46	74.7%	3	1	66.7%	180	23	87.2%
125		3	0	100.0%	195	11	94.4%	3	1	66.7%	195	75	61.5%
129	25	3	1	66.7%	194	48	75.3%	3	1	66.7%	194	29	85.1%
130		3	0	100.0%	185	18	90.3%	3	0	100.0%	183	16	91.3%
131		3	1	66.7%	187	54	71.1%	3	0	100.0%	187	35	81.3%
134	86	3	0	100.0%	195	27	86.2%	3	1	66.7%	194	37	80.9%
136		3	0	100.0%	195	24	87.7%	3	0	100.0%	193	25	87.0%
137	42	3	1	66.7%	192	36	81.3%	3	1	66.7%	192	59	69.3%
138		3	0	100.0%	195	39	80.0%	3	1	66.7%	194	35	82.0%
141		3	0	100.0%	194	3	98.5%	3	2	33.3%	193	35	81.9%
148		3	0	100.0%	194	20	89.7%	3	0	100.0%	192	36	81.3%
151		5	2	60.0%	305	97	68.2%	5	0	100.0%	304	95	68.8%
170		3	0	100.0%	190	12	93.7%	3	0	100.0%	189	29	84.7%
171	30	3	0	100.0%	195	11	94.4%	3	2	33.3%	195	77	60.5%
172	27	3	1	66.7%	194	16	91.8%	3	2	33.3%	192	64	66.7%
173	42	3	0	100.0%	187	24	87.2%	3	2	33.3%	186	80	57.0%
174		3	0	100.0%	195	20	89.7%	3	1	66.7%	195	49	74.9%
175		3	0	100.0%	195	22	88.7%	3	0	100.0%	195	62	68.2%
176	57	3	0	100.0%	187	15	92.0%	3	1	66.7%	185	25	86.5%
177		3	0	100.0%	195	27	86.2%	3	0	100.0%	195	46	76.4%
178		3	0	100.0%	195	26	86.7%	3	0	100.0%	193	31	83.9%
179		3	1	66.7%	195	24	87.7%	3	1	66.7%	194	71	63.4%
181		3	2	33.3%	191	61	68.1%	3	1	66.7%	189	16	91.5%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		3	0	100.0%	185	30	83.8%	3	0	100.0%	183	21	88.5%
183	19	3	3	0.0%	194	59	69.6%	3	2	33.3%	191	40	79.1%
184		3	1	66.7%	195	34	82.6%	3	0	100.0%	194	27	86.1%
185		3	0	100.0%	195	37	81.0%	3	0	100.0%	195	14	92.8%
186		3	2	33.3%	194	23	88.1%	3	1	66.7%	193	54	72.0%
190		3	2	33.3%	194	71	63.4%	3	1	66.7%	193	44	77.2%
192		3	0	100.0%	192	24	87.5%	3	1	66.7%	192	18	90.6%
193	45	3	1	66.7%	191	79	58.6%	3	1	66.7%	190	89	53.2%
196		3	0	100.0%	191	20	89.5%	2	0	100.0%	189	15	92.1%
197	24	3	1	66.7%	195	76	61.0%	3	2	33.3%	195	69	64.6%
198		3	0	100.0%	127	17	86.6%	3	0	100.0%	126	21	83.3%
230		5	0	100.0%	142	4	97.2%	5	0	100.0%	142	7	95.1%
232		5	0	100.0%	308	11	96.4%	5	1	80.0%	308	22	92.9%
233	25	4	1	75.0%	277	62	77.6%	4	3	25.0%	276	91	67.0%
234		5	0	100.0%	309	22	92.9%	5	0	100.0%	308	25	91.9%
235		5	3	40.0%	233	37	84.1%	5	1	80.0%	232	53	77.2%
236		5	0	100.0%	293	10	96.6%	5	2	60.0%	292	41	86.0%
237		5	0	100.0%	306	56	81.7%	5	0	100.0%	304	51	83.2%
238		5	2	60.0%	233	22	90.6%	5	1	80.0%	231	19	91.8%
239		5	0	100.0%	307	79	74.3%	5	0	100.0%	306	38	87.6%
240		5	0	100.0%	308	21	93.2%	5	2	60.0%	305	62	79.7%
241		5	1	80.0%	308	75	75.6%	5	1	80.0%	308	72	76.6%
243		5	1	80.0%	244	66	73.0%	5	1	80.0%	243	34	86.0%
244	17	4	0	100.0%	276	12	95.7%	4	3	25.0%	276	52	81.2%
245		5	0	100.0%	189	33	82.5%	5	2	60.0%	188	24	87.2%
280	33	5	0	100.0%	309	15	95.1%	5	1	80.0%	308	62	79.9%
281		5	0	100.0%	309	37	88.0%	5	0	100.0%	309	57	81.6%
283		5	2	60.0%	309	76	75.4%	5	1	80.0%	309	62	79.9%
284		5	0	100.0%	309	13	95.8%	5	0	100.0%	306	54	82.4%
290	29	5	0	100.0%	309	50	83.8%	5	3	40.0%	306	117	61.8%
291		5	4	20.0%	308	97	68.5%	5	1	80.0%	306	77	74.8%
300		5	1	80.0%	293	21	92.8%	5	1	80.0%	291	69	76.3%
301		5	0	100.0%	306	10	96.7%	5	1	80.0%	302	56	81.5%
302		5	0	100.0%	288	33	88.5%	5	0	100.0%	284	78	72.5%
306		5	1	80.0%	304	17	94.4%	5	0	100.0%	303	82	72.9%
307		5	1	80.0%	297	39	86.9%	5	1	80.0%	294	83	71.8%
311	209	5	1	80.0%	302	27	91.1%	5	1	80.0%	296	64	78.4%
316	129	5	1	80.0%	298	19	93.6%	5	3	40.0%	293	81	72.4%
318	285	5	0	100.0%	307	31	89.9%	5	3	40.0%	304	147	51.6%
319	55	5	0	100.0%	308	20	93.5%	5	5	0.0%	303	170	43.9%
329		3	0	100.0%	218	9	95.9%	3	0	100.0%	218	15	93.1%
330		4	0	100.0%	262	6	97.7%	4	0	100.0%	262	15	94.3%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		5	0	100.0%	309	33	89.3%	5	0	100.0%	309	44	85.8%
332		4	0	100.0%	308	17	94.5%	4	0	100.0%	308	43	86.0%
334		5	0	100.0%	309	10	96.8%	5	0	100.0%	308	40	87.0%
335		5	0	100.0%	309	34	89.0%	5	1	80.0%	307	52	83.1%
336		5	0	100.0%	309	10	96.8%	5	0	100.0%	307	28	90.9%
337		5	0	100.0%	309	18	94.2%	5	1	80.0%	305	37	87.9%
338		5	1	80.0%	309	48	84.5%	5	2	60.0%	307	96	68.7%
339		5	1	80.0%	309	51	83.5%	5	1	80.0%	309	54	82.5%
342		5	0	100.0%	309	24	92.2%	5	0	100.0%	307	60	80.5%
350	98	5	0	100.0%	286	18	93.7%	5	5	0.0%	279	156	44.1%
351		5	1	80.0%	292	28	90.4%	5	3	40.0%	290	81	72.1%
352		5	1	80.0%	276	22	92.0%	5	3	40.0%	270	84	68.9%
353		5	0	100.0%	247	13	94.7%	5	1	80.0%	241	39	83.8%
354	69	5	0	100.0%	290	35	87.9%	5	5	0.0%	283	106	62.5%
355	90	5	1	80.0%	299	32	89.3%	5	4	20.0%	292	103	64.7%
364		5	3	40.0%	298	68	77.2%	5	3	40.0%	292	110	62.3%
365	31	5	1	80.0%	297	12	96.0%	4	3	25.0%	294	112	61.9%
370		4	0	100.0%	299	35	88.3%	4	1	75.0%	289	70	75.8%
380		2	1	50.0%	291	28	90.4%	1	0	100.0%	290	63	78.3%
381	27	5	0	100.0%	307	12	96.1%	5	2	60.0%	306	62	79.7%
382		5	0	100.0%	306	27	91.2%	5	3	40.0%	306	103	66.3%
383	75	3	0	100.0%	296	26	91.2%	3	3	0.0%	293	126	57.0%
390		5	2	60.0%	291	21	92.8%	5	3	40.0%	290	76	73.8%
391		5	1	80.0%	292	12	95.9%	5	3	40.0%	288	79	72.6%
392	28	5	0	100.0%	305	10	96.7%	5	1	80.0%	302	91	69.9%
393		5	0	100.0%	309	18	94.2%	5	2	60.0%	306	93	69.6%
417		3	0	100.0%	205	44	78.5%	3	0	100.0%	196	22	88.8%
425		3	0	100.0%	207	6	97.1%	3	0	100.0%	207	7	96.6%
448	174	5	1	80.0%	239	44	81.6%	5	1	80.0%	236	81	65.7%
449	161	5	0	100.0%	236	32	86.4%	5	1	80.0%	236	43	81.8%
470		3	0	100.0%	218	37	83.0%	3	0	100.0%	212	24	88.7%
471		3	1	66.7%	208	12	94.2%	3	0	100.0%	208	5	97.6%
473		3	0	100.0%	214	15	93.0%	3	0	100.0%	211	10	95.3%
474		3	0	100.0%	212	63	70.3%	3	1	66.7%	197	64	67.5%
475		3	0	100.0%	212	6	97.2%	3	0	100.0%	212	15	92.9%
478		3	1	66.7%	206	33	84.0%	3	0	100.0%	204	27	86.8%
479		3	0	100.0%	213	34	84.0%	3	0	100.0%	211	31	85.3%
486		3	0	100.0%	217	31	85.7%	3	0	100.0%	211	58	72.5%
494		3	0	100.0%	219	41	81.3%	3	0	100.0%	212	57	73.1%
495		3	0	100.0%	202	4	98.0%	3	0	100.0%	200	3	98.5%
503	70	5	3	40.0%	305	30	90.2%	5	3	40.0%	298	90	69.8%
504		5	0	100.0%	309	19	93.9%	5	1	80.0%	307	91	70.4%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506	Cncld	5	4	20.0%	304	46	84.9%	3	1	66.7%	296	47	84.1%
507	94	5	3	40.0%	309	39	87.4%	5	4	20.0%	309	104	66.3%
508	39	5	0	100.0%	304	41	86.5%	5	4	20.0%	300	72	76.0%
516		5	3	40.0%	300	32	89.3%	5	3	40.0%	299	137	54.2%
517	30	5	0	100.0%	309	8	97.4%	5	3	40.0%	305	130	57.4%
518	145	5	3	40.0%	309	40	87.1%	5	5	0.0%	307	212	30.9%
519	22	5	0	100.0%	300	9	97.0%	5	2	60.0%	298	68	77.2%
520	Cncld	3	2	33.3%	176	27	84.7%	2	0	100.0%	172	9	94.8%
521	43	3	0	100.0%	214	7	96.7%	3	2	33.3%	214	29	86.4%
522		3	2	33.3%	214	41	80.8%	3	0	100.0%	211	20	90.5%
523	63	3	1	66.7%	214	8	96.3%	3	1	66.7%	213	23	89.2%
524	60	2	0	100.0%	213	16	92.5%	2	2	0.0%	210	25	88.1%
526	13	3	2	33.3%	188	36	80.9%	3	1	66.7%	185	16	91.4%
527	28	3	0	100.0%	214	10	95.3%	3	1	66.7%	213	38	82.2%
528	49	3	0	100.0%	214	17	92.1%	3	1	66.7%	213	31	85.4%
529	33	3	0	100.0%	214	12	94.4%	3	2	33.3%	213	60	71.8%
530	21	3	0	100.0%	168	16	90.5%	3	1	66.7%	168	33	80.4%
531		3	0	100.0%	188	13	93.1%	3	0	100.0%	188	13	93.1%
532		3	0	100.0%	214	51	76.2%	3	0	100.0%	213	31	85.4%
534		3	0	100.0%	173	25	85.5%	3	0	100.0%	171	16	90.6%
535	38	3	1	66.7%	201	26	87.1%	3	2	33.3%	196	25	87.2%
536		3	2	33.3%	214	57	73.4%	3	0	100.0%	210	38	81.9%
537		2	0	100.0%	183	22	88.0%	2	0	100.0%	177	20	88.7%
538	23	3	1	66.7%	214	25	88.3%	3	1	66.7%	213	44	79.3%
539	34	3	0	100.0%	168	24	85.7%	3	2	33.3%	168	73	56.5%
540		3	2	33.3%	213	40	81.2%	3	0	100.0%	205	18	91.2%
541	25	3	1	66.7%	213	23	89.2%	3	1	66.7%	207	37	82.1%
542		3	0	100.0%	213	24	88.7%	3	1	66.7%	210	38	81.9%
543	38	3	0	100.0%	214	24	88.8%	3	1	66.7%	214	64	70.1%
544		3	1	66.7%	212	21	90.1%	2	0	100.0%	208	20	90.4%
545		3	0	100.0%	214	17	92.1%	3	0	100.0%	211	24	88.6%
547		3	2	33.3%	214	43	79.9%	3	1	66.7%	214	48	77.6%
549		3	0	100.0%	209	26	87.6%	3	2	33.3%	201	19	90.5%
550	38	3	0	100.0%	168	18	89.3%	3	3	0.0%	168	39	76.8%
551		3	0	100.0%	210	22	89.5%	3	1	66.7%	200	21	89.5%
562		5	0	100.0%	300	23	92.3%	5	0	100.0%	296	35	88.2%
564		5	0	100.0%	301	19	93.7%	5	1	80.0%	293	39	86.7%
566	20	5	1	80.0%	299	26	91.3%	5	3	40.0%	296	48	83.8%
567		5	0	100.0%	186	10	94.6%	5	1	80.0%	184	10	94.6%
572		5	0	100.0%	296	24	91.9%	5	0	100.0%	289	83	71.3%
573		5	0	100.0%	298	40	86.6%	5	0	100.0%	291	51	82.5%
579	Cncld	5	1	80.0%	186	12	93.5%	4	2	50.0%	180	39	78.3%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
580		5	0	100.0%	301	16	94.7%	5	2	60.0%	294	30	89.8%
581	16	5	2	60.0%	301	52	82.7%	5	2	60.0%	299	66	77.9%
584	30	5	1	80.0%	185	26	85.9%	5	5	0.0%	180	113	37.2%
587		5	1	80.0%	294	17	94.2%	5	1	80.0%	285	54	81.1%
588		5	1	80.0%	186	19	89.8%	5	2	60.0%	185	35	81.1%
591		5	1	80.0%	298	22	92.6%	5	2	60.0%	292	41	86.0%
593		4	1	75.0%	294	48	83.7%	4	0	100.0%	273	37	86.4%
595	25	5	0	100.0%	296	53	82.1%	5	1	80.0%	293	61	79.2%
600		3	0	100.0%	222	9	95.9%	3	0	100.0%	220	19	91.4%
601		3	2	33.3%	205	85	58.5%	3	1	66.7%	202	26	87.1%
605		3	3	0.0%	212	133	37.3%	3	0	100.0%	208	22	89.4%
607		3	0	100.0%	221	30	86.4%	3	0	100.0%	218	25	88.5%
609		3	0	100.0%	212	23	89.2%	3	1	66.7%	211	20	90.5%
622		3	1	66.7%	123	33	73.2%	3	0	100.0%	121	5	95.9%
626		3	1	66.7%	126	17	86.5%	3	0	100.0%	124	18	85.5%
639		3	0	100.0%	192	38	80.2%	3	0	100.0%	191	19	90.1%
640	15	3	0	100.0%	212	7	96.7%	3	3	0.0%	210	83	60.5%
641		3	1	66.7%	194	39	79.9%	3	0	100.0%	194	26	86.6%
642		3	1	66.7%	210	10	95.2%	3	0	100.0%	209	26	87.6%
643		3	0	100.0%	224	44	80.4%	3	1	66.7%	221	37	83.3%
644		3	0	100.0%	216	28	87.0%	3	0	100.0%	214	52	75.7%
645		3	0	100.0%	224	41	81.7%	3	1	66.7%	221	47	78.7%
646	15	3	0	100.0%	213	51	76.1%	3	2	33.3%	211	103	51.2%
647		3	0	100.0%	224	32	85.7%	3	0	100.0%	223	49	78.0%
648		3	0	100.0%	220	56	74.5%	3	0	100.0%	220	34	84.5%
649		3	0	100.0%	225	42	81.3%	3	0	100.0%	222	34	84.7%
650		3	0	100.0%	224	41	81.7%	3	0	100.0%	221	36	83.7%
651	16	3	1	66.7%	224	17	92.4%	3	1	66.7%	222	43	80.6%
652	22	3	2	33.3%	225	31	86.2%	3	1	66.7%	221	38	82.8%
653		3	2	33.3%	213	35	83.6%	3	0	100.0%	210	39	81.4%
654		3	1	66.7%	214	41	80.8%	3	1	66.7%	210	19	91.0%
655		3	0	100.0%	222	72	67.6%	3	1	66.7%	220	74	66.4%
656		3	1	66.7%	224	48	78.6%	3	0	100.0%	223	30	86.5%
657		3	0	100.0%	213	27	87.3%	3	0	100.0%	212	29	86.3%
658		3	0	100.0%	224	35	84.4%	3	0	100.0%	222	33	85.1%
680		3	0	100.0%	219	12	94.5%	3	0	100.0%	218	27	87.6%
681		3	0	100.0%	219	17	92.2%	3	1	66.7%	213	87	59.2%
682		3	0	100.0%	218	6	97.2%	3	1	66.7%	218	39	82.1%
683	11	3	0	100.0%	201	17	91.5%	3	2	33.3%	200	69	65.5%
684		3	0	100.0%	200	32	84.0%	3	0	100.0%	200	45	77.5%
685		3	0	100.0%	215	31	85.6%	3	0	100.0%	212	53	75.0%
686		3	0	100.0%	220	37	83.2%	3	0	100.0%	219	47	78.5%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
687		3	0	100.0%	219	34	84.5%	3	0	100.0%	218	36	83.5%
688		3	0	100.0%	218	13	94.0%	3	0	100.0%	217	36	83.4%
701		5	0	100.0%	241	25	89.6%	5	0	100.0%	238	25	89.5%
702	18	5	0	100.0%	308	32	89.6%	5	3	40.0%	305	73	76.1%
703	No OS	5	4	20.0%	309	97	68.6%	5	3	40.0%	307	88	71.3%
704		5	0	100.0%	240	37	84.6%	5	1	80.0%	233	47	79.8%
710		5	0	100.0%	309	77	75.1%	5	2	60.0%	305	83	72.8%
711	21	5	0	100.0%	300	34	88.7%	5	4	20.0%	279	56	79.9%
712	132	5	2	60.0%	306	82	73.2%	5	4	20.0%	297	102	65.7%
713	16	4	0	100.0%	176	16	90.9%	3	2	33.3%	159	69	56.6%
714	79	5	5	0.0%	190	80	57.9%	4	4	0.0%	175	80	54.3%
715	48	5	1	80.0%	308	62	79.9%	4	3	25.0%	284	144	49.3%
716		5	4	20.0%	309	124	59.9%	5	4	20.0%	303	122	59.7%
717	17	5	2	60.0%	294	70	76.2%	3	2	33.3%	273	88	67.8%
718	24	5	3	40.0%	309	156	49.5%	5	4	20.0%	307	113	63.2%
719		5	3	40.0%	309	106	65.7%	4	3	25.0%	292	87	70.2%
757		5	0	100.0%	94	5	94.7%	5	0	100.0%	93	8	91.4%
761		5	0	100.0%	305	12	96.1%	5	0	100.0%	302	41	86.4%
765		5	0	100.0%	305	25	91.8%	5	1	80.0%	305	43	85.9%
769		5	0	100.0%	305	27	91.1%	5	1	80.0%	299	58	80.6%
770		5	1	80.0%	305	23	92.5%	5	2	60.0%	303	91	70.0%
774	18	5	0	100.0%	305	16	94.8%	5	1	80.0%	304	70	77.0%
777	50	5	0	100.0%	190	12	93.7%	5	2	60.0%	189	44	76.7%
782		5	4	20.0%	190	86	54.7%	5	2	60.0%	185	27	85.4%
785		5	0	100.0%	305	22	92.8%	5	1	80.0%	305	54	82.3%
786		5	1	80.0%	94	20	78.7%	4	1	75.0%	90	48	46.7%
790		5	0	100.0%	305	28	90.8%	5	0	100.0%	302	46	84.8%
794	25	5	1	80.0%	305	34	88.9%	5	1	80.0%	301	67	77.7%
821	26	5	0	100.0%	303	6	98.0%	5	5	0.0%	303	126	58.4%
822	27	5	0	100.0%	305	16	94.8%	5	5	0.0%	303	147	51.5%
1333		5	1	80.0%	305	33	89.2%	5	1	80.0%	302	100	66.9%
1340		5	1	80.0%	304	7	97.7%	5	0	100.0%	304	51	83.2%
1689		4	0	100.0%	99	5	94.9%	4	0	100.0%	98	11	88.8%
2102		3	1	66.7%	71	14	80.3%	3	0	100.0%	70	6	91.4%
2103		3	0	100.0%	135	12	91.1%	3	1	66.7%	134	10	92.5%
2104		3	0	100.0%	161	10	93.8%	3	0	100.0%	159	12	92.5%
2107		3	0	100.0%	192	34	82.3%	3	0	100.0%	189	20	89.4%
2108		3	1	66.7%	192	27	85.9%	3	1	66.7%	186	21	88.7%
2109		3	1	66.7%	85	12	85.9%	3	1	66.7%	83	5	94.0%
2112		3	0	100.0%	32	4	87.5%	3	0	100.0%	30	2	93.3%
2113		3	0	100.0%	71	8	88.7%	3	0	100.0%	71	10	85.9%
2115		3	0	100.0%	71	11	84.5%	3	0	100.0%	70	10	85.7%

Amtrak On Time Performance

Trains Arriving Through: 8/5/2026

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2116		3	0	100.0%	32	1	96.9%	3	0	100.0%	32	7	78.1%
2118		3	1	66.7%	32	3	90.6%	3	1	66.7%	32	10	68.8%
2119		3	1	66.7%	32	5	84.4%	2	0	100.0%	31	10	67.7%
2120	Cncld	3	2	33.3%	32	11	65.6%	2	2	0.0%	30	15	50.0%
2123		3	0	100.0%	70	8	88.6%	3	0	100.0%	69	15	78.3%
2124		2	0	100.0%	163	34	79.1%	2	0	100.0%	161	22	86.3%
2127		3	0	100.0%	32	7	78.1%	3	0	100.0%	31	7	77.4%
2128		3	0	100.0%	32	3	90.6%	3	1	66.7%	32	3	90.6%
2131		3	1	66.7%	32	7	78.1%	3	0	100.0%	32	3	90.6%
2150		3	0	100.0%	185	22	88.1%	3	1	66.7%	182	74	59.3%
2151		3	0	100.0%	134	6	95.5%	3	0	100.0%	132	37	72.0%
2152		3	0	100.0%	90	6	93.3%	3	0	100.0%	89	30	66.3%
2154		3	0	100.0%	93	23	75.3%	3	1	66.7%	89	43	51.7%
2155		3	0	100.0%	194	16	91.8%	3	2	33.3%	190	98	48.4%
2158		3	0	100.0%	31	4	87.1%	3	1	66.7%	31	13	58.1%
2159	54	3	0	100.0%	187	14	92.5%	3	2	33.3%	185	61	67.0%
2160		3	0	100.0%	32	2	93.8%	3	2	33.3%	31	20	35.5%
2162		3	0	100.0%	193	18	90.7%	3	1	66.7%	187	86	54.0%
2165	29	3	0	100.0%	29	2	93.1%	3	2	33.3%	29	15	48.3%
2167		3	0	100.0%	180	20	88.9%	3	0	100.0%	180	39	78.3%
2171		3	0	100.0%	121	10	91.7%	3	0	100.0%	117	23	80.3%
2190		3	0	100.0%	190	27	85.8%	3	1	66.7%	188	24	87.2%
2193		3	0	100.0%	185	25	86.5%	3	0	100.0%	183	49	73.2%

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2120	NYP	Trn Cancelled							
2159	WAS	54	ENG	39	ENG	39	PHL-PHL	AM	Other electrical failure, 2149 NG NP, TALKING WITH HSM A/C GROUNDING STRAP LOOSE ON PANTOGRAPHS
2165	WAS	29	DMW	28	DMW	22	NHV-STM	MN	Waiting for MW clearance Milepost, 50.5, 49.1
84	NYP	150	ENG	135	ENG	135	BAL-ABE	AM	Air / Brake, 620 EX ES, stopped with brake issues MP 77
86	BOS	24	OTH	18	SYS	9	RVR-ASD	CS	Copy authority / restriction Stop signal at Lakeside Lone Engineer copying an EC-1 Form., Milepost, 5.2, 5.2
94	BOS	20	RTE	25	SMW	9	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAMBAY 2 TRK DUE TO SCHEDULED MAINTENANCE
119	WAS	33	MTI	24	MTI	24	XPV-BAL	AM	Disabled train ahead, Milepost, 77, ., single tracking a/c 84 disabled on 2 track
129	WAS	25	POL	36	POL	36	PHL-WIL	AM	Right of Way police hold, T.O.L. NO 4 TRK JUST SOUTH OF PHIL A/C VANDALISM. A173 HOLDING AHEAD WAITING FOR A2162 COMING NORTH.
134	NYP	86	MTI	75	MTI	75	BAL-XPV	AM	Disabled train ahead, Milepost, 84, ., held for disposition a/c 84 disabled ahead at MP 77
137	WAS	42	SVS	43	SVS	43	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, AM137 depart Boston South Station 43" late. A/C AM190 eq GEO Cars being removed
171	RNK	30	OTH	16	TCD	9	BAL-BWI	AM	Elevator at Station, opr 1 track a/c elevators o/s in BWI
172	BOS	27	PTI	26	PTI	10	BAL-XPV	AM	Follow, 2104, Control Point, ., PER DSPR HEKD FOR AND FOLLOWED ACELA 2104
173	WAS	42	POL	35	POL	35	PHL-WIL	AM	Right of Way police hold, T.O.L. NO 4 TRK JUST SOUTH OF PHIL A/C VANDALISM. STOP BYPASS PERMISSION NEEDED LEADING TO A CONFLICTING MOVE WITH A2162 COMING NORTH.
176	BOS	57	DCS	42	DCS	20	PJC-MET	AM	Power switch failure, Other, MENLO, HELD TO OPR 1 TRK A/C 12 SW FAILING TO NORMAL AT UNION

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
183	WAS	19	SVS	25	SVS	25	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
193	WAS	45	ITI	40	ITI	40	NYP-NYP	AM	Service, turn, or wye train, 84, LATE TURN OFF AM84
197	WAS	24	ITI	13	ITI	13	NYP-NYP	AM	Service, turn, or wye train, 134, LATE TURN OFF AM134
53	SFA	33	PTI	48	FTI	25	XSE-XFL	CS	Meet M492, Control Point, Kay
80	NYP	34	FTI	72	FTI	37	RVR-FBG	CS	Follow E387, Milepost w/Letters, CFP 19.8, CFP 53.3
640	NYP	15	CTI	16	CTI	9	CWH-TRE	AM	Follow, SE, SE783, Other, CWH-TRE
646	NYP	15	OTH	8	SMW	3	ELT-MJY	AM	Scheduled in track usage program, Control Point, RHEEMS TO CORK, 1 TRACK O/S
651	HAR	16	SVS	14	SVS	14	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND
652	NYP	22	DCS	22	DCS	22	NBK-MET	AM	Power switch failure, Other, UNION 2 TRK, HELD TO OPR 1 TO 4 TRK A/C 12 SWITCH AT UNION FAILING TO NORMAL
20	NYP	41	DCS	54	DCS	49	MET-NWK	AM	Power switch failure, Other, METRO PARK, HELD TO OPR 1 TO 3 TRK A/C 12 SW FAILING TO NORMAL AT UNION
683	BRK	11	FTI	6	FTI	6	POR-FRE	CS	Meet y070, Control Point, Congress
63	TWO	69	FTI	14	SVS	8	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
64	NYP	31	CTI	29	CTI	22	POU-CRT	MN	Follow mnrr, local, Control Point, 58
233	ALB	25	PTI	16	PTI	16	RHI-HUD	AM	Meet 284, Control Point, 114
244	NYP	17	DMW	16	DMW	16	ALB-HUD	AM	Held for or routed around MW work or equipment Control Point, 124
280	NYP	33	FTI	26	FTI	18	SYR-ROM	CS	Follow M636, Milepost, 270, 254
290	NYP	29	CTI	28	CTI	26	POU-CRT	MN	Follow Followed from CP 72 to CP 33, MNR, 870, Control Point, 72
49	CHI	45	CAR	65	CAR	60	NYP-NYP	AM	Electrical failure, 68007 VY VF, LATE RELEASE F/SSYD A/C DOOR ISSUES
448	BOS	168	FTI	117	FTI	66	PIT-PIT	CS	Meet M425, Other, Pit
449	ALB	161	RTE	168	RTE	158	WOR-SPG	CS	Dispatcher hold Held at CP 96 while we waited for the gas pipe leak from the fuel plant between us and SPG to be cleaned up and it was safe to move forward., Control Point, 96

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
42	NYP	163	TRS	135	TRS	135	PGH-GNB	NS	Trespasser strike Milepost, 345.4, 345.4
74	RGH	14	PTI	31	PTI	19	KAN-SAL	NS	Meet #Amt75, Control Point, N. Kannapolis
76	RGH	19	PTI	21	PTI	12	DNC-CYN	NS	Meet #Am79, Control Point, Clegg
89	SAV	107	FTI	64	HLD	32	CHS-CHS	CS	Held by dispatchers. Freight train leaving the yard
97	MIA	49	SVS	81	SVS	81	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C NECESSARY TO WAIT FOR BAGGAGE CAR AND DINER CAR
98	NYP	42	FTI	95	FTI	45	CHS-KTR	CS	Follow 410, Control Point, Hanahan, Other, KTR STA
55	WAS	32	DCS	26	SMW	15	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAMBAY 2 TRK DUE TO SCHEDULED MAINTENANCE
56	SAB	100	ENG	43	ENG	43	WAS-WAS	AM	Other electrical failure, 618, SHOPPED MTR 618 REPLACED WITH MTR 652.
41	MIA	No OS Rpt	FTI	198	ENG	152	COV-CUM	CS	Other electrical failure Engine would not load or communicate with trail engine. Removed Comm and MU cables to resolve issue with communication faults on engine, 316
25	NOL	30	FTI	60	FTI	27	XNO-XEJ	NS	Follow y205, Control Point, 6.8
26	MOE	61	DCS	63	DCS	61	XNO-BAS	CS	Restrictive signal(s) from known wayside signal failure Stop , Milepost w/Letters, ealision fields, north gintilly
5	EMY	105	FTI	89	FTI	37	XAZ-ELK	UP	Blocked from station track Stopped on red at MP 559 waiting for freight train to clear MT 1., UP XXXX, Milepost, 559, 559
6	CHI	229	WTR	296	WTR	161	OMA-CRN	BN	Flash flood warning Milepost, 17.0, 11.0, Milepost, 9.0, 0.0, Milepost, 8.8, 7.0, Milepost, 462.0, 393.5
520	SAC	Trn Cancelled							
521	SJC	43	DCS	43	DCS	35	HAY-FMT	UP	Restrictive signal(s) from known wayside signal failure Stop, Restrict & Proceed, Restrict & Proceed, Restrict & Proceed, Stop, Control Point, S. HAY, Milepost, 23.1, 23.1, Milepost, 25.4, 25.4, Milepost, 27.4, 27.4, Control Point, Niles Jct
523	SJC	63	TRS	41	TRS	41	HAY-FMT	UP	Vandalism Flagged due to copper theft NI021-FO30, Control Point, NI021

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
524	SAC	60	DCS	71	DCS	59	FMT-HAY	UP	CTC system failure Wait for Amtk521 to flag from Hay Then we flagged from Niles to Mp 27.3, Other, Shinn
526	SAC	13	TSV	16	TSV	16	OKJ-OKJ	UP	Pick up equipment Picked up the train at OMF after deadhead from SAC.
527	SJC	28	DCS	36	DCS	25	HAY-FMT	UP	Restrictive signal(s) from unknown cause Flagging, Red, Control Point, NI 021
528	SAC	49	DCS	44	DCS	30	FMT-HAY	UP	Restrictive signal(s) from known wayside signal failure Authority 8-21, Stop, Authority, Control Point, Niles Jct
529	SJC	33	TRS	44	TRS	44	HAY-FMT	UP	Vandalism Flagging through affected area, Milepost, 21.0, 32.0
530	SAC	21	DCS	24	DCS	11	EMY-BKY	UP	Issue with automatic road crossing protection Milepost, 4.86, 4.72
535	OKJ	38	PTI	29	PTI	21	EMY-OKJ	UP	Wait for station track Waiting for Amt 11 and Amt 712 to finish station work at OKJ, Amt 11/Amt 712, Control Point, King St
538	ARN	23	TEN	20	TEN	18	RSV-RSV	UP	HEP Lost HEP Troubleshoot and reset breaker at Station with TASI Mechanical, JPBX922
539	SJC	34	PTI	22	PTI	18	FMT-GAC	UP	Meet Amt538, Control Point, Co035
541	OKJ	25	SYS	22	SYS	22	SAC-SAC	UP	PTC problem or failure (cause unknown)
543	SJC	38	CTI	21	PTI	18	GAC-SCC	UP	Meet 544, Control Point, expressway
550	SAC	38	DCS	23	PTI	13	FMT-HAY	UP	Meet 547, Control Point, shinn
503	EUG	Trn Cancelled	WTR	35	WTR	17	ALY-EUG	UP	Heat order Milepost, 690.8, 647.3
506	SEA								
507	EUG	94	ITI	69	ITI	69	PDX-PDX	UP	Service interruption between Seattle and Portland. Train 507 instructed to wait for all connecting passengers. Three busses. Bus 5616, 5604 & 5608 3
508	PDX	39	WTR	29	WTR	16	EUG-ALY	UP	Heat order Milepost, 647.3, 690.8
517	VAN	30	DCS	15	DCS	15	TAC-XNI	ST	Restrictive signal(s) from unknown cause Stop, Control Point, CP 188
518	VAC	80	PTI	37	PTI	37	EDM-EVR	BN	Meet 8, 519, Control Point, Howarth Park
519	SEA	22	DMW	24	DMW	24	BEL-MVW	BN	Waiting for MW clearance Hold at south bow for track and time at south bow, Control Point, south bow

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
58	CHI	40	FTI	55	PTI	49	FTN-CDL	CC	Meet amtk59, Control Point, anna
59	NOL	165	FTI	139	ITI	67	CHI-CHI	AM	Service, turn, or wye train 58, Bad order diner
11	LAX	218	FTI	91	FTI	27	KFS-DUN	UP	Cross over or go around Dragging equipment detector has train stopped, U.P. 5899, Milepost, 344.00, 338.00
14	PDX	60	WTR	61	SYS	30	KFS-KFS	UP	Crew rest Signed up 0850, Control Point, KFS
7	SEA	69	CAR	106	CAR	106	MKE-CBS	CP	Air / Brake / Wheel 34055
27	PDX	No OS Rpt							
821	FTW	26	DSR	41	DSR	31	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, m, Milepost, 407.4, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 394.1, 393.5, 60, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 389.2, 389.1, 50, m, Milepost, 38
822	OKC	27	DSR	27	DSR	21	FTW-GLE	BN	Per bulletin Milepost, 357.3, 357.6, 29, 2, Milepost, 364.3, 364.9, 15, 2, Milepost, 366.3, 367.8, 15, 2, Milepost, 368.6, 369.1, 15, M, Milepost, 383.4, 383.6, 30, M, Milepost, 385.3, 385.5, 30, M, Milepost, 389, 389.7, 25, M, Milepost, 396.2, 396.3, 30, M, Milepost, 400.2, 401, 25, M
350	PNT	98	DCS	79	DCS	55	X1W-DET	CC	Restrictive signal(s) from unknown cause Stop, Control Point, Federal Jct
354	PNT	69	DSR	55	DSR	27	TRM-PNT	CC	Per bulletin Milepost, 16.58, 20.5, 10, 1, Milepost, 19.2, 22.0, 30, 1
355	CHI	90	SVS	72	SVS	72	PNT-PNT	CC	Unplanned Wye
365	CHI	31	DSR	41	DSR	21	LNS-BTL	CC	Per bulletin Milepost, 221.42, 221.42, 30, Main, Milepost, 219, 218.5, 30, main, Milepost, 217.50, 216.00, 30, main, Milepost, 214.96, 214.96, 25, main two, Milepost, 210.40, 210.40, 30, main two, Milepost, 202.45, 202.25, 25, main, Milepost, 196, 195.32, 30, main one, Milepost, 191.73, 191.35, 30,
566	SAN	20	ITI	12	ITI	12	LAX-LAX	SC	Service, turn, or wye train 566, Late release from mechanical at 8th St. - 07:48.
579	LAX	Trn Cancelled							
581	LAX	16	DCS	10	DCS	10	SNP-SNC	SC	T.O.L Restricted Proceed signal at 2011., Other, 2011

Amtrak Endpoint OTP Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
584	SAN	30	CTI	25	CTI	12	OSD-SOL	SN	Meet Coaster, 648, Control Point, Farr
595	LAX	25	ADA	17	ADA	10	FUL-FUL	BN	Wheelchair Had to use mobile wheelchair ramp. Took extra time to unlock it and lock it back up.
774	SAN	18	PTI	27	PTI	14	SNC-SNP	SC	Meet 777, Control Point, serra
777	SLO	50	PTI	27	PTI	18	LPS-GUA	UP	Meet AMTK 11, Control Point, CPCO 294
794	SAN	25	SYS	30	SYS	30	LAX-LAX	SC	Other late crew Inbound 587 late, Other, LAX
702	BFD	18	PTI	12	PTI	8	FNO-HNF	BN	Meet Amtrak 713, Control Point, Anderson
703	SAC	No OS Rpt	ITI	106	ITI	106	BFD-BFD	BN	Service, turn, or wye train 712
711	OKJ	21	FTI	19	DCS	11	RIC-EMY	UP	Issue with automatic road crossing protection Two (2) 6.32.2 Procedure XG crossing warning notification @ MP 4.9 & MP 4.86, Other, 4.9, Other, 4.86
712	BFD	132	TEN	121	TEN	121	OKJ-OKJ	UP	Set out defective locomotive Tasi had the new unit on at 9 am, it took a hours before we got released then 62 had no rte for us, C2103
713	OKJ	16	FTI	29	FTI	10	WAC-COC	BN	Meet 8068, Control Point, SANDRINI
714	BFD	79	PTI	53	TSV	37	OKJ-OKJ	UP	Fuel Fuel and cleaning due to AMTK 714 taking over AMTK 711 equipment.
715	OKJ	48	PTI	57	PTI	20	WAC-COC	BN	Meet 702, Control Point, west Angiola
717	OKJ	17	TEN	16	TEN	14	BFD-BFD	BN	Other electrical failure Starter motor failure. Started by hand, C2004
718	BFD	24	PTI	21	PTI	14	SKN-MOD	BN	Meet 719, Control Point, east duffy
3	LAX	62	DSR	89	SVS	74	CHI-CHI	AM	Water, commissary, toilet/trash dumping Control Point, CHI
4	CHI	131	FTI	144	WTR	42	LSV-RAT	BN	High winds Wind gusts up to 60 mph = drops us down to 40mph, Milepost, 770, 744, Milepost, 726, 705, Milepost, 667, 660
1	LAX	611	FTI	624	FTI	155	LDB-BEN	UP	Follow UP 6294, Milepost, 1148, 1032
21	SAS	34	FTI	159	FTI	29	X55-CBR	BN	Follow Follow to CROWLEY, BN 7583, Control Point, T 756
381	QCY	27	DSR	17	RTE	12	NPV-PLO	BN	Dispatcher hold NAR, Control Point, Montgomery
383	QCY	75	FTI	60	FTI	60	NPV-PLO	BN	Meet BNSF 5791, Control Point, Bristol
392	CHI	28	PTI	23	PTI	19	KKI-HMW	CC	Meet Main 3 empty, AM 59, Siding, Peotone

Amtrak Endpoint OTP Details

26-FOI-0064400000008493"UNCLASSIFIED"8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
311	KCY	209	FTI	172	FTI	172	JEF-JEF	UP	Disabled Freight UP 7124, Siding, Centertown	
316	STL	129	ITI	109	ITI	109	KCY-KCY	KC	Service, turn, or wye train 311, Late 311 and wye train	
318	CHI	285	FTI	224	FTI	127	SED-JEF	UP	Meet 7124, Milepost w/Letters, SED, jef	
319	KCY	55	DSR	40	PTI	27	SED-WAR	UP	Meet 316, Siding, dresden	

Amtrak Initial Terminal Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/5/2026

Terminal	Train	Date	Late	Delay	Cause
TWO	64	08/05	6		
ALB	238	08/05	6	6	Loading problem 99
BOS	67	08/05	80	80	Planned set out / pick out of locomotives, cars or section of train, AM67 delayed out of BOS due to e/658 issues causing door issues throughout the whole consist, then RFE Mingione rpts AM67eq e/658 will be swapped in SHSY
BOS	137	08/05	43	43	Planned set out / pick out of locomotives, cars or section of train, AM137 depart Boston South Station 43" late. A/C AM190 eq GEO Cars being removed
HAR	626	08/05	1	1	Passenger and/or baggage
HFD	471	08/05	8	8	Service, turn, or wye train, 426, LATE ARRIVAL OF #426
NYP	19	08/05	20	20	Scheduled in track usage program, Other, NYP, LATE F/SSYD A/C SCHEDULED WORK IN SSYD
NYP	51	08/05	5	5	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	63	08/05	8	8	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	89	08/05	8	8	Mobility Impaired
NYP	97	08/05	33	33	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST
NYP	183	08/05	25	25	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	193	08/05	40	40	Service, turn, or wye train, 84, LATE TURN OFF AM84
NYP	197	08/05	13	13	Service, turn, or wye train, 134, LATE TURN OFF AM134
NYP	291	08/05	14	14	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	651	08/05	6	6	Delay due to mechanical problems on a Commuter train, DELAYED AT DEPARTURE A/C NJ3721 DISABLED IN NORTH TUBE
NYP	653	08/05	2	2	Passenger and/or baggage, BOARDING
PHL	190	08/05	3	3	High passenger count
PHL	605	08/05	1	1	Passenger and/or baggage
WAS	56	08/05	43	43	Other electrical failure, 618, SHOPPED MTR 618 REPLACED WITH MTR 652.
WAS	172	08/05	5	5	Electrical failure, 82603, SHOPPED CAR 82603 FROM S&I
WAS	184	08/05	14	14	Disabled train ahead, Control Point, WAS, 183 AR LATE DUE TO LATE REL FROM SUNNYSIDE
WAS	2120	08/05	(Trn Cxld)		Engine Issue
CHI	5	08/05	27	27	HEP 206
CHI	21	08/05	86	86	Planned set out / pick out of locomotives, cars or section of train Late arriving equipment, Control Point, CUS

Amtrak Initial Terminal Details

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/5/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	08/05	25	25	Dining car removed 68024
CHI	59	08/05	110	110	Set out defective car 37010
KCY	316	08/05	109	109	Service, turn, or wye train 311, Late 311 and wye train
PNT	355	08/05	72	72	Unplanned Wye
BFD	703	08/05	126	106	Service, turn, or wye train 712
BFD	703	08/05	126	20	Hold for thruway bus
BFD	717	08/05	14	14	Other electrical failure Starter motor failure. Started by hand, C2004
BFD	719	08/05	1	1	Door 9008, 9015, 9006
GTA	782	08/05	1		
LAX	2	08/05	(No OS)		
LAX	566	08/05	12	12	Service, turn, or wye train 566, Late release from mechanical at 8th St. - 07:48.
LAX	584	08/05	4	4	Meet Amtk 581, Control Point, Terminal
OKJ	520	08/05	(Trn Cxld)		Third Party Car Failure
OKJ	522	08/05	4	4	Meet Held at CP NI007 North Jack London, on the OKJ Depot Track, for Amtrak 521 to pass in front of us, MT2 to MT2., Amtrak 521, Control Point, CP NI007 North Jack London
OKJ	526	08/05	16	16	Pick up equipment Picked up the train at OMF after deadhead from SAC.
OKJ	540	08/05	1	1	Meet 523, Control Point, ni007
OKJ	712	08/05	121	121	Set out defective locomotive Tasi had the new unit on at 9 am, it took a hours before we got released then 62 had no rte for us, C2103
OKJ	714	08/05	67	13	Meet Held at CP Magnolia for 2 Capitols, AMTK 532, Control Point, Magnolia
OKJ	714	08/05	67	37	Fuel Fuel and cleaning due to AMTK 714 taking over AMTK 711 equipment.
OKJ	714	08/05	67	17	Meet Held at CP Magnolia for 2 Capitols, AMTK 537, Control Point, Magnolia
OKJ	716	08/05	6	6	PTC problem or failure (cause unknown) Logging in.
OKJ	718	08/05	7	7	Service, turn, or wye train 713
PDX	11	08/05	43	43	Hold to replace ditch light. Made aware we had to re-spot for water after work on the ditch light had already begun.
PDX	503	08/05	20		
PDX	507	08/05	69	69	Service interruption between Seattle and Portland. Train 507 instructed to wait for all connecting passengers. Three busses. Bus 5616, 5604 & 5608 3
SAC	541	08/05	22	22	PTC problem or failure (cause unknown)
SAN	579	08/05	(Trn Cxld)		PTC System Issues

Amtrak Initial Terminal Details

26-FOI-00644 00000008493 "UNCLASSIFIED" 8/7/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 8/5/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	8	08/05	153	153	Set out defective car 31032, 8/32 car had to be set out do to broken spring
SEA	518	08/05	70	5	PTC - Initializing PTC (no failure) Other, N Portal
SPK	27	08/03	(No OS)		
VAN	506	08/05	(Trn Cxld)		Car Issue

Eastern Region

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	33.2	98.3	342	0
CDOT	95.0	90	91.3	85.6	20	2
MARC	95.0	No Data	No Data	No Data	No Data	No Data
SEPTA	95.0	No Data	No Data	No Data	No Data	No Data
NJT-NED	95.0	95.8	94.5	88.4	357	15
NJT-SED	95.0	No Data	No Data	No Data	No Data	No Data

Operating Highlights

Train 97(05) North of Fayetteville, NC - Freight Train Interference

06AUG26: Train 97(05), operating with engines 381/330, 10 coaches, and 270 customers, was delayed 54 miles north of Fayetteville, NC, on CSX South End subdivision, due to meeting CSX M583 at control point Smithfield. Once the freight cleared and a route was made available, train 97(05) was able to proceed.

Train	Delay	Comment
97(05)	33"	

Train 52(05) Kingstree, SC - Freight Train Interference

06AUG26: Train 52(05), operating with engines 317/360, 42 coaches, and 394 customers, was delayed 30 miles south of Kingstree, SC, on CSX Charleston subdivision, due to meeting IO31 and IO37 at Pinopolis siding. Once the freight cleared and a route was made available, train 52(05) was able to proceed.

Train	Delay	Comment
52(05)	30"	

Train 56(05) North of White River Junction, VT - Debris

05AUG26: Train 56(05), operating with engine 129, 6 coaches, and 63 customers, was delayed 7 miles north of White River Junction, VT, on NERC Roxbury subdivision, due to debris blocking the route. Train 56(05) stopped until the debris was cleared and then proceeded at restricted speed in accordance with g-core rules.

Train	Delay	Comment
56(05)	35"	

Train 136(05) New Haven, CT - Engine Failure

05AUG26: Train 136(05), operating with engine 145, 8 coaches, and 66 customers, was delayed departing New Have, CT, on MNCW New Haven Line, due to mechanical issue on engine 100. That motor was swapped for engine 145 as a result.

Train	Delay	Comment
-------	-------	---------

TOL South of Philadelphia

05AUG26: Due to a Track Closed Incident (TOL) of Philadelphia caused by vandalism, multiple trains were delayed operating through the affected area until C&S could resolve the issue.

Train	Delay	Comment
85 (05)	3"	
173 (05)	31"	
2167 (05)	5"	
129 (05)	35"	
Septa	2"-11"	

Train 67(05) Boston, MA - Engine Failure

05AUG26: Train 67(05), operating with engine 635, 5 coaches, and 47 customers was delayed departing Boston, MA, on Amtrak NHB Line, due to swapping engine 658 for engine 635. Engine 658(05) was having issues with its communications cables that prevented the engine from communicating with the coach cars properly. As a result the engine was shopped and replaced. Mechanical had to perform its inspections on engine 635 before it could be added to train 67(05).

Train	Delay	Comment
67 (05)	1'20"	

Train 80(05) North of Richmond, VA - Freight Train Interference

05AUG26: Train 80(05) with E/381 and 7 cars was delayed on the CSX RF&P due to following CSX E387 from MP CFP 19.8 to MP CFP 53.3.

Train	Delay	Comment
80 (05)	37"	

Train 41(03) DeLand, FL - Sunrail Trespasser Strike/Trespasser Incident

05AUG26: Train 41(03) was held at MP A750.1/Deland station on the CFRC South due to a Sunrail P327-05 trespasser strike at Winter Park station. This was a confirmed fatality and they were waiting on the coroner. Once the coroner arrived and cleared the scene, train 41(03) was released and was able to proceed. Train 40(05) was held at Orlando for an open route.

Service recovery for train 41(03) was started. pizza was delivered to the train and snack packs and water was made available for all customers.

Train	Delay	Comment
41 (03)	2'20"	
40 (05)	13"	

Train 449(05) Springfield, MA - Police Related

05AUG26: Train 449(05) was held at the CSX Berkshire QB subdivision at MP QB95.3 due to a Fuel Plant with a gasoline leak ahead at MP QB 97.2 that has not been located. Train 448(04), operating with engines 107/101/124, 4 coaches and 130 customers, was delayed at Pittsfield, MA, due to CSX M425 being slow clear a grade at control point 140. 448(04) was forced to follow this freight due to the congestion caused by the gas leak. There were several fire departments on scene attempting to find the leak.

Train 49(05) was delayed at Albany, NY, due to holding for late 449(05).

Train	Delay	Comment
448(05)	58"	HOLD ALB
448(04)	1'06"	Hold at PIT
449(05)	2'38"	
49(05)	3'05"	

Train 98(05) Jacksonville, FL - Freight Train Interference

05AUG26: Train 98(05), operating with engines 324/366, 10 coaches and 213 customers, was delayed at Jacksonville, FL, on CSX Jacksonville Terminal subdivision, due to meeting CSX-M79505. Once the freight cleared and a route was made available, train 98(05) was able to proceed.

Train	Delay	Comment
98(05)	31"	

Train 97(04) South of DeLand, FL - Commuter Train Interference

05AUG26: Train 97(04) was delayed on the CFRC Orlando A subdivision due to meeting CFRC P316 and then following CFRC P321 into Winter Park station.

Train	Delay	Comment
97(04)	32"	

Train 97(05) New York, NY - Servicing

05AUG26: Train 97(05) was delayed departing New York due to the late release from yard due to needing equipment off late 98(04) that arrived at 1132A-ET 42 minutes late.

Train	Delay	Comment
97(05)	33"	

Train 2159(05) Philadelphia, PA - Engine Failure

05AUG26: Next Gen 2159(05) with PC/2149, PC/2152 was delayed on track 5 at Philadelphia due to reporting a loose grounding strap dangling from their rear pantograph. They reconfigured and an "A" man arrived and inspected the equipment. The equipment was okayed to depart.

Train	Delay	Comment
2159(05)	39"	

Train 137(05) Boston, MA - Servicing

05AUG26: Train 137(05) with E/623 and 8 cars was delayed departing Boston due to the late release from the yard removing the GEO equipment.

Train 41(03) South of Savannah, GA - Freight Train Interference

05AUG26: Train 41(03) 26-FD000644 00000008493 the "UNCLASSIFIED" 8/7/2026 the Nahunta subdivision due to following CSX I137 from MP 506 to MP 543.

Train	Delay	Comment
41(03)	1'02"	

Train 84(05) North of Baltimore, MD - Engine Failure

05AUG26: Train 84(05) with E/620, E/632 and 9 cars with 318 customers onboard was stopped on the Philadelphia to Washington main line at MP 77 with a parking brake issue on E/632. The crew was trouble shooting with the Road Foreman and CNOC Mechanical. They were able to clear the faults and proceed north. The faults reappeared when attempting to pull they then tried isolating the trail engine.

They stopped again at MP 75.7/Wood Interlocking with smoke coming from the rear engine. The crew was trouble shooting. It was determined to cut off rear E/632 and the KW908 crew would pick it up.

This also caused delay to train 134(05) that was held for possible passenger transfer.

As of 339P-ET the KW908 crew with E/72 coupled up to E/632 and was taking it back into Washington.

This also delayed Train 193(05) due to turning off late 84(05).

Train	Delay	Comment
134(05)	1'15"	
84(05)	2'15"	
193(05)	40"	

CSX Heat Orders - Weather

05AUG26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions North End, Peninsula, Nahunta and Savannah.

Train	Delay	Comment
52(05)	4"	
53(05)	11"	
79(05)	15"	
80(05)	16"	
89(05)	20"	
90(05)	20"	
95(05)	5"	
98(05)	29"	
138(05)	5"	
186(05)	14"	

Train 80(05) Raleigh, NC - Crew Rest/Miscellaneous Amtrak Responsible

05AUG26: Train 80(05) was delayed in Raleigh due to waiting on crew to sign up on rest at 1032A-ET.

Train	Delay	Comment
80(05)	28"	

Train 56(05) Washington, DC - Engine Failure

05AUG26: Train 56(05) 26-FDI-00644 00000008493 UNCLASSIFIED 8/7/2026
05AUG26: Train 56(05) delayed departure from Washington due to E/618 being shopped and replaced with E/652.

Train	Delay	Comment
56(05)	43"	

Train 42(05) East of Pittsburgh, PA - Trespasser Incident

05AUG26: At 743A-ET, Train 42(05) with E/104 and 7 cars with 140 customers onboard reported that they struck a trespasser on the NS Pittsburgh 72PT at MP 345.4. There was no reported injuries to customers or crew. This was a confirmed fatality a homeless person sleeping in the gauge. This did not occur at a crossing and was in Allegheny County, it was 77 degrees and cloudy. The train was able to maintain HEP. Local Police were on scene. Amtrak Road Foreman was enroute. Amtrak Police responded. At 955A-ET, The scene was released and the train was able to proceed east.

National Response Center Number: 1469848

Train	Delay	Comment
42(05)	2'15"	

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00644a 00000008493 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Train 6(05) East of Reno, NV - Heat Orders/ Weather

06AUG26: Train 6(05) was delayed beginning 52 miles east of Reno, NV, on the UPRR Nevada Subdivision between MP292 to MP417 operating reduced speeds due to heat orders.

Train	Delay	Comment
6(05)	46"	

Train 4(04) Las Vegas, NM - High Winds/Weather

06AUG26: Train 4(04) was delayed beginning 2 miles east of Las Vegas, NM, on the BNSF Raton Subdivision between MP769.8 to MP687 and MP671 to MP659.8 operating reduced speeds due to high wind warnings. Train was also delayed due to flash flood warnings from MP692 to MP680.3

Train	Delay	Comment
4(04)	53"	
4(04)	26"	Flash Flood Warnings

Train 3(04) West of Winslow, AZ - Freight Train Interference

06AUG26: Train 3(04) was delayed beginning 9.7 miles west of Winslow, AZ on the BNSF Seligman Subdivision due to following an Unknown BNSF freight between MP 295.2 and MP 340.6.

Train	Delay	Comment
3(04)	1'45"	

Train 8/28(04) West of Malta, MT - Freight Train Interference

06AUG26: Train 8/28(04) was delayed at Dodson / MP 359.3 on the Burlington Northern Santa Fe Milk River Subdivision, 16 miles west of the Malta, MT station, meeting BNSF 7767.

Train	Delay	Comment
8/28(04)	34"	

Train 8(05) Seattle, WA - Car Failure

06AUG26: Train 8(05) was delayed departing Seattle, WA due to needing to set-out sleeper car C/39034 due to a broken bolster spring that needed replacement. Once the car was removed from the consist and the train made whole and serviced, Train 8(05) departed Seattle.

Train	Delay	Comment
8(05)	2'33"	

Train 3(03) West of Riverside-Downtown, CA - Commuter Train Interference

06AUG26: Train 3(03) was delayed beginning "UNCLASSIFIED" west of Riverside, Ca on the BNSF San Bernardino Subdivision beginning at Arlington/ MP 15.1 until Atwood/ MP40.6 due to following a Metrolink train.

Train	Delay	Comment
3 (03)	35"	

Train 11(05) Portland, OR - Servicing

06AUG26: Train 11(05) was delayed departing Portland, OR due to repairing a ditch light prior to departure and needing to re-spot the train for water.

Train	Delay	Comment
11 (05)	43"	

Train 714(05) Oakland, CA - Servicing

06AUG26: Train 714(05) was delayed departing Oakland, CA due to needing to be fueled account of mechanical issues on original equipment and utilizing a different set of equipment from 711(05).

Train	Delay	Comment
714 (05)	37"	

Train 59(05) Chicago, IL - Car Failure

05AUG26: Train 59(05) was delayed departing initial terminal of Chicago IL station/MP0.0 due to a late release from the yard caused by a bad ordered car. Car 31010 that was intended for train 7/27(05) was bad ordered for HVAC. Car 31021 from 59(05) was used as the replacement for the bad ordered car on 7/27(05). Train 59(05) equipment replaced car 31021 with car 31006 from inbound train 22(04) that arrived to the yard at 324PM CT. Train 59(05) was made up complete in the yard at 620PM CT and released from the yard at 653PM CT. Train 59(05) arrived to the station at 722PM CT and began boarding. Train 59(05) departed Chicago IL Union station at 754PM CT with all 182 passengers on board.

Train	Delay	Comment
59 (05)	1'49"	

Train 307(05) Joliet, IL - Engine Failure

05AUG26: Train 307(05) delayed beginning at MP51.3, 32.8 miles north of Joliet station on the CN Joliet subdivision due to I043 faults on engine ID4607. Crew spoke with CNOC mechanical and was able to get the engine reset and was back on the move at 728PM CT. The faults came back for a second time enroute to Joliet and the crew was able to reset a second time. Train 307(05) arrived to Joliet station at 716PM CT and terminated at the station due to I043 faults coming back. Customer service sourced four buses to accommodate passengers from Joliet IL to St. Louis MO. The final bus departed Joliet station at 1118PM CT. Train 307(05) equipment shoved back to Chicago IL station and was shadowed by train 318(05).

Train 300(06) was cancelled as a result of the engine faults on ID4607 and the equipment shoving back to Chicago. Customer service secured six buses to accommodate 300(06) passengers from St. Louis MO. to Chicago IL. Bus one express St, Louis MO to Chicago IL. bus two all stops St. Louis MO to Chicago IL, bus three Springfield, IL to Bloomington Normal, IL, Joliet IL and Chicago IL, bus four express Bloomington Normal IL to Chicago IL, bus five Bloomington Normal IL to Pontiac IL, Joliet IL, Summit IL and Chicago IL, bus six Alton IL, to Springfield, IL to Bloomington Normal, IL, Pontiac, IL. Joliet IL and Chicago IL.

WBS#: B.TR.100150.7004

Train	Delay	Comment
318(05)	49"	Shadow 307(05)
307(05)	Term JOL	

Train 1(05) East of San Antonio, TX - Signal

05AUG26: Train 1(05) was delayed beginning at MP89.3, 123.4 miles east of San Antonio TX station on the UPRR Glidden subdivision due to restrictive signals from an unknown cause. Train 1(05) stopped and then proceeded through the signals at restricted speed until MP99.0.

Train	Delay	Comment
1(05)	39"	

Train 26(05) South of Bay Saint Louis, MS - Signal

05AUG26: Train 26(05) was delayed beginning at MP7.2, 50.10 miles south of Bay Saint Louis, MS station on the Norfolk Southern New Orleans Terminal subdivision due to restrictive signals caused by a wayside signal failure. Train 26(05) stopped and flagged through the signals at Elysiam Fields and North Gentilly.

Train 383(05) East of Plano, IL - Freight Train Interference

05AUG26: Train 383(05) was delayed holding at MP45.5, 7.19 miles east of Plano IL station on the BNSF Mendota subdivision for a meet with BNSF freight train 5791. Train 383(05) was back on the move at 752PM CT after the freight cleared.

Train	Delay	Comment
383(05)	1'00"	

Train 506(05) Vancouver, WA - Car Failure

05AUG26: Train 506(05) was delayed departing Vancouver, WA, (where it was to originate account of the ongoing warehouse fire near Portland, OR) due to a mechanical issue reportedly affecting the suspension on car C/7704. Unable to resolve the issue, the decision was made to cancel the train and secure alternate bus transportation for affected passengers. The bus secured was estimated to arrive at 8:50PM-PT. Busses arrived that were previously arranged to accommodate 508(06) passengers, prior to the bus secured for 506, and all passengers were accommodated onto that bus instead.

WBS#: B.TR.100150.7003

Train	Delay	Comment
506(05)	Cancelled	Alternate Bus Transportation provided

Train 22(05) West of Mineola, TX - Trespasser Incident

05AUG26:

At 6:01PM CT, train 22(05) with engines 62 and 69, 7 cars, and 118 customers onboard, stopped at mile post 191.28 56.39 miles east of Mineola, TX/MP136.1 on the UP Mineola subdivision after striking an occupied truck. The strike occurred at DOT #794797X, equipped signage. Weather conditions were sunny. Vehicle passenger was not injured. No injuries were reported by the customers or crew. The train crew did not request relief. Local police responded to the scene and conducted an investigation. Once the investigation was complete the track inspector released the tracks after his inspection was complete. Once the scene was released, train 22(05) was back on the move. NRC# 1469919

National Response Center Number: 1469919

Train	Delay	Comment
22(05)	1'48"	

Train 354(05) Kalamazoo, MI - Passenger Train Interference

05AUG26: Train 354(05) was delayed holding at Kalamazoo, MI station/MP143.4 on the Amtrak Michigan line for a meet with 355(05). Train 354(05) was able to depart at 931PM ET after train 355(05) arrived to the station.

Train	Delay	Comment
354(05)	32"	

Train 21(05) North of Springfield, IL - Passenger Train Interference

05AUG26: Train 21(05) was delayed holding at MP182.6, 4.10 miles North of Springfield IL station on the UPRR Springfield subdivision for a meet with Amtrak train 318(05). Train 21(05) was back on the move at 730PM CT after train 318(05) cleared to the north.

Train	Delay	Comment
21(05)	30"	

Train 1(05) East of Houston, TX - Weather

05AUG26: Train 1(05) was delayed at beginning of 297.6 miles east of Houston, TX station on the UPRR Lafayette subdivision due to heat orders. Train 1(05) operated through the heat orders until MP35.2 and resumed operating track speed once clear of the heat orders.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(05)	37"	

Train 41(05) Consist Deviation - No Diner

05AUG26: Train 41(05) departed Chicago, IL, without a diner due to diner C/68024 bad ordered for brakes and no available replacement. Train 41(05) operated Chicago, IL to Miami, FL with cafe C/28022 only.

WBS#: B.TR.100150.7001

Train 712(05) Oakland, CA - Third Party Contractor Engine Failure

05AUG26: Train 712(05), consisting of C2103 and cab car C8309, was delayed departing Oakland, CA, on the UPRR Niles Subdivision. Just prior to its scheduled departure, the crew reported that TASI Mechanical was still completing required pre-departure testing. TASI advised that they were finishing the air brake and load tests and that the train would be ready to depart upon completion.

When the equipment was ready to be released, an additional delay occurred as TASI personnel were unable to locate the required paperwork for the cab car and discovered that only the previous day's paperwork was onboard. Once the correct documentation was located, the train was cleared for service. Additionally, Train 712(05) was held in the yard awaiting the arrival of Train 711(05), contributing to the overall delay.

As a result, the equipment turn 703(05) was delayed departing Bakersfield and 14(05) was delayed at Sacramento waiting for connecting passengers.

B.TR.100150.7000

WBS#: B.TR.100150.7000

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(05)	2'01"	
703(05)	1'46"	BFD - Equip turn off 712
14(05)	1'49"	SAC- Held for 703's connections

Train 350(05) East of Dearborn, MI - Signal Issues

05AUG26: Train 350(05) was delayed at Federal Jct/MP50.38, 7 miles east of Dearborn, MI, on the CN Shore Line, due to C&S performing signal work in area and necessary to flag between MP50.38 and Detroit, MI/MP53.8. Train 350(05) was delayed operating through the affected area. Train 350(05) was further delayed east of Detroit, on the CN Holly Subdivision, operating through numerous slow orders following CN tie gang work in area. Train 355(05) was delayed departing Pontiac, MI, due to late turn off Train 350(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
350(05)	55"	E/DER
355(05)	1'12"	PNT, late turn off 350(05)
350(05)	21"	E/DET

Train 579(05) San Diego, CA - Cab Car Failure

05AUG26: Train 579(05) ~~26-FQI-006441~~ ~~00000008493~~ ~~03112,"UNCLASSIFIED"~~ ~~8/7/2026~~ canceled due to PTC issues involving cab car C6951. This equipment was originally scheduled to operate as Train 777(05). During pre-departure preparations, the engineer encountered difficulties establishing PTC functionality on the cab car, and Mechanical personnel were called to assist.

Troubleshooting determined that the PTC system was not communicating with the brake stand and incorrectly indicated that the brake stand was cut out when it was actually cut in. Despite Mechanical's efforts, the issue could not be resolved.

As a result, equipment swaps were made, and Train 579(05) was canceled. The affected equipment was then wyed and deadheaded back to 8th Street Yard for further inspection and repair.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
579(05)	canceled	

Train 21(05) Late Departure Chicago, IL - Car Failure

05AUG26: Train 21(05), E/311-E/315 & 7 cars, with 238 customers, was delayed departing Chicago, IL, due to late release after switching out a bad order car. C/34080 was shopped for HVAC and it was necessary to cut out car and replace with C/34066.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(05)	1'26"	

Train 521(05) South of Hayward, CA - Signal

05AUG26: Train 521(05) was delayed south of Hayward, CA, on the UPRR Niles Subdivision due to a TKO at Niles Junction. The outage was caused by thieves stealing approximately 500 feet of signal cable. Signal maintainers responded and conducted troubleshooting efforts, while trains were flagged through the affected territory at Hayward and Niles Junction until repairs were completed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
529(05)	44"	
521(05)	35"	
524(05)	59"	
527(05)	25"	
523(05)	41"	
528(05)	30"	

Train 58(05) North of Hammond, LA - Freight Train Interference

05AUG26: Train 58(05) was delayed at MP859, just north of Hammond, LA, on the CN McComb Subdivision, due to CN freight ahead with mechanical issues resulting in congestion through the area. Train 58(05) was delayed at Natalbany/MP856.3 meeting CN 3313 and further delayed following CN 2848 between MP856.3 and MP828. Train 58(05) was delayed at MP802.1, 4 miles north of McComb, MS, meeting southbound CN freight 3268.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(05)	20"	N/HMD, meet CN3313
58(05)	1'01"	N/HMD, following CN 2848
58(05)	51"	N/MCB

Train 3(03) West of Needles, CA - Freight Train Interference

05AUG26: Train 3(03) was delayed approximately 44 miles west of Needles, CA, on the BNSF Needles Subdivision. The train was required to follow a BNSF freight train for approximately 130 miles, from Milepost 609.2 to Milepost 731.2, resulting in significant delays to its operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(03)	44"	

UPRR Freight Derailment East of Glenwood Springs, CO - California Zephyr Service

05AUG26: Approximately 530AM-MT, UPRR reported MGJNY-04 (UP 7964) with 5 locos, 33 loads and 51 empties, derailed one axle on the 38th car, an empty, at MP359, just east of Glenwood Springs, CO, on the UPRR Glenwood Springs Subdivision. UPRR management and track/car departments were estimated to arrive on site at 830AM-MT. Initial estimate for open track was between 300PM-MT and 500PM-MT. Train 6(04), with 217 customers, was delayed at Glenwood Springs/MP360.1 holding for open route ahead. Train 5(04), with 242 customers, was delayed at Granby, CO/MP75.8, 75 miles west of Denver, CO, on the UPRR Moffat Tunnel Subdivision, holding at the depot for approximately two hours and then advanced towards derailment location to be in position for open route.

WBS#: B.TR.100150.6998

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	2'10"	GSC
5(04)	2'36"	GRA

Train 1(03)/421(02) Palm Springs, CA - Freight Train Interference

05AUG26: Train 1(03)/421(02), consisting of E/361, E/4, and carrying 217 customers, was delayed east of Palm Springs, CA, on the UPRR Yuma Subdivision after UP 6539 went into emergency on the single main track ahead of the train. While awaiting the freight crew's repair of a DPU issue, the crew on Train 1(03)/421(02) expired under Hours of Service regulations. A relief crew was transported to the train. Upon arrival, the crew found that the locomotives had shut down and would not restart. Working in coordination with CNOC Mechanical, the crew successfully troubleshot and resolved the issue. Train 1(03)/421(02) subsequently resumed its journey after a lengthy delay.

Train 1(03)/421(02) was further delayed following NS 9884 from Palm Springs to MP 525.6, then waited for the freight train to be routed into their yard track. Once a route was available, the train proceeded west.

WBS#: B.TR.100150.6999

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(03)/421(02)	2'11"	DISABLED FRT
1(03)/421(02)	30"	LOCO PROBLEMS
1(03)/421(02)	2'05"	NS 9884

Train 318(05) Sedalia, MO - Freight Train Interference

05AUG26: Train 318(05) was delayed at Sedalia, MO/MP188.9, on the UPRR Sedalia Subdivision, due to IG4SIB-04 (UP7124) stalled ahead at MP140, 11 miles west of Jefferson City, MO. Due to loco issues and in order to make the grade, UP 7124 set off the head 25 cars in the siding at Centertown/MP141.9 and then proceeded to Shell/MP151 with the remainder of train. Train 318(05) was delayed at Sedalia holding until set out at Centertown was complete and then advanced east. Train 311(05), with 75 customers, was delayed at Jefferson City/MP125.5, holding for open route ahead. After UP 7124 was back together, UPRR reported still unable to make the grade. UP 7124 attempted the grade one additional time and then shoved back to River Jct to clear the route.

Train 318(05) and 311(05) were further delayed holding for UP 7124 to clear. Train 316(05) was delayed departing Kansas City, MO, due to late turn of equipment off Train 311(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
311(05)	2'52"	JEF
318(05)	1'00"	SED
318(05)	2'07"	E/SED
316(05)	1'48"	KCY, late turn off 311(05)

Train 59(04) Memphis, TN - Freight Train Interference

05AUG26: Train 59(04) was delayed at Memphis, TN/MP391.8, on the CN Memphis Subdivision, holding for freight cross-traffic to clear CN Jct/MP392.5 ahead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(04)	39"	

Train 520(05) Oakland, CA - Third Party Contractor Car Failure

05AUG26: Train 520(05), consisting of locomotive C2123 and five cars, was delayed departing Oakland, CA, on the UPRR Niles Subdivision due to multiple reported door issues. TASI Mechanical personnel performed troubleshooting efforts but were unable to resolve the defects. As a result, Train 520(05) was canceled and deadheaded to Sacramento, CA, where it was turned for service as Train 531(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
520(05)	Canceled	

Train 6(03) East of Omaha, NE - Weather

05AUG26: Train 6(03) was delayed east of Omaha, NE/MP16.7 on the BNSF Omaha, Creston and Ottumwa Subdivisions, due to flash flood warnings in effect through numerous locations. Train 6(03) was delayed operating through flash flood warnings on the BNSF Omaha Subdivision between Omaha/MP16 and MP11; on the Creston Subdivision, beginning 38 miles east of Omaha, between MP462-MP453, MP436-MP422, MP404-MP393; and on the Ottumwa Subdivision between Creston/MP393-MP364, MP354-MP351 and between MP347-MP345. Train 6(03) was delayed operating through the affected areas.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(03)	3'33"	

Train 6(04) Diner Bad Order - Enroute Service Recovery

05AUG26: Train 6(04), 26-FOI-00644 / 170 car UNCLASSIFIED 8/7/2026 00000008493 car, diner C/38004 HVAC inoperative after departure from Emeryville, CA, and car bad ordered inline for remainder of trip to Chicago, IL. As enroute service recovery, on 04AUG lunch was added onboard in Truckee, CA and dinner added in Reno, NV. On 05AUG, breakfast planned to be added in Grand Junction, CO. lunch at Glenwood Springs, CO, and dinner in Denver, CO. Additional enroute service recovery planned to 06AUG for remainder of trip.
WBS B.TR.100.150.6995

WBS#: B.TR.100150.6995

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

Pere Marquette:

- Train 370(04) cancelled entirely, with alternate transportation between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with alternate transportation between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with alternate transportation between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with alternate transportation between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, sourcing alternate buses.

WBS#: B.TR.100150.6992

Train	Delay	Comment
370(04)	Cancelled	
371(05)	Cancelled	
305(05)	Cancelled	
302(06)	Cancelled	
352(06)	Cancelled	
351(07)	Cancelled	

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04,05,06,07) Cancelled entirely, No alternative Transportation.
- Train 502 (04,05,06, 07) Cancelled entirely. Will source alternate transportation.
- Train 504 (04,05,06,07) Will terminate in Portland, OR. Will source alternate transportation Portland, OR -Seattle, WA
- Train 518 (04,05,06,07) Cancelled Portland, OR-Seattle, WA. Will source alternate transportation.
- Train 517 (04,05,06,07) Will terminate in Vancouver, WA. No alternate Transportation from Vancouver, WA to Portland, OR.
- Train 506 (04,05,06,07) originating in Vancouver, WA. No alternate Transportation Portland, OR to Vancouver, WA.
- Train 508 (04,05,06,07) Will terminate Portland, OR. Will source alternate transportation Portland, OR-Seattle, WA.
- Train 503 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 505 (04,05,06,07) Cancelled entirely. Will source alternate transportation.
- Train 507 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 509 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 511 (04,05,06,07) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Will source alternate transportation. Train 27 (02,03,04,05) Spokane, WA to Portland, OR.
- Will source alternate transportation. Train 28 (04,05,06,07) Portland, OR to Spokane, WA

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

WBS#: B.TR.100150.6981

Train	Delay	Comment
-------	-------	---------

507(02)	1'41"	bus VAN-PDX	
506(02)	Canceled		
508(02)	45"	bus PDX-VAN	
509(02)	77"	couple 509-511(02)	
509(02)	75"	Detour through UP yard	26-F91400844 00000008496 "UNCLASSIFIED" 8/7/2026
511(02)	76"	Detour through UP yard	
500(03)	Canceled		
502(03)	Canceled		
511(03)	Canceled		
505(03)	Canceled		
518(03)	Canceled	between SEA-PDX	
507(03)	Canceled	between SEA-PDX	
508(03)	Term PDX		
504(03)	Term PDX		
509(03)	Canceled		
517(03)	Term VAN		
506(03)	Orig VAN		
503(03)	24"	canceled SEA-PDX	
507(03)	1'10"	waiting for bus at PDX	
14(02)	58"	detour	
11(03)	51"	detour	
14(04)	term PDX		
506(04)	1'03"	wait for inbound bus	
518(04)	1'27"	wait for inbound bus	
507(05)	1'09"	PDX- wait for inbound bus	

Maintenance of Way Highlights

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

-Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

-Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00644 00000008493 UNCLASSIFIED 8/7/2026racked scheduled C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
40 (20)	ABQ	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (4)	SEA	BNSF3929	E/193 B/O air compressor		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00644

00000008493

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
41 (05)	CHI	Train 41(05) car 68024 has been shopped an set out inn CHI with no replacement. This train will not have a diner. However it does have a cafe.			68024
622 (05)	HAR	622(05) will operate with 5 coaches and no cab car due cab car 9636 moved to PHL for a PM swap. 622(05) will not offer Wi-Fi services.			9636
584 (05)	LAX	COMET CARS BEING USED/ NO BIKE SPACE, NO WIFI, NO BUSINESS CLASS AND NO LOUNGE CAR.			C5004,C5007,C5001,C5002,C5006
651 (05)	NYP	651(05) will operate with 5 coaches and no cab car due cab car 9636 moved to PHL for a PM swap. 651(05) will not offer Wi-Fi services.			9636
595 (05)	SAN	COMET CARS BEING USED/ NO BIKE SPACE, NO WIFI, NO BUSINESS CLASS AND NO LOUNGE CAR.			C5006,C5002,C5001,C5007,C5004
8 (06)	SEA	Operating with Transition Dorm			39005

Train Number	Station	Reason	Customer Impact	Affected Pgr	Unit Number(s)
		in lieu of Transition sleeper. Schedule change made, check war reports for displaced passengers and re-accommodate as needed.			

Reverse Consists

Train Number	Station	Reason
85 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
111 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
110 (05)	PHL	Consist reversed Business class seat orientation may have changed At Rear
185 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
94 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front
182 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
136 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
179 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (06)	NPN	Consist reversed Business class seat orientation may have changed At Front
125 (06)	SPG	Consist reversed Business class seat orientation may have changed At Front