



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, August 07, 2026

Rules: 0-45



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	08/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/06/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	56	82.3%	1,844	297	83.9%	92,788	12,849	86.2%
Central Division	86.0%	55	5	90.9%	338	41	87.9%	17,766	1,615	90.9%
East Division	82.0%	176	35	80.1%	1,003	151	84.9%	48,673	7,569	84.4%
West Division	86.0%	86	16	81.4%	503	105	79.1%	26,349	3,665	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00644 00000008492 "UNCLASSIFIED" 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	102,867	36,017	65%	646,388	189,786	71%	30,979,386	7,831,136	75%
Northeast Corridor	81%	43,155	13,030	70%	277,523	66,745	76%	13,579,036	3,322,773	76%
Acela	83%	9,983	3,319	67%	58,362	13,464	77%	2,718,786	715,015	74%
Northeast Regional	79%	33,172	9,711	71%	219,161	53,281	76%	10,860,250	2,607,758	76%
Richmond / Newport News / Norfolk	77%	10,077	4,869	52%	68,899	23,484	66%	3,368,875	984,945	71%
Springfield Shuttles	89%	649	226	65%	3,962	425	89%	191,689	30,293	84%
Roanoke	79%	2,479	701	72%	20,162	3,692	82%	1,025,446	222,348	78%
On Spine Northeast Regional	80%	19,967	3,915	80%	126,138	25,680	80%	6,274,240	1,370,172	78%
State Supported	80%	47,336	14,713	69%	291,146	77,609	73%	13,600,765	2,883,534	79%
Borealis	80%	589	124	79%	3,566	466	87%	173,192	36,098	79%
Capitol Corridor	90%	4,508	705	84%	22,474	4,222	81%	1,138,193	149,971	87%
Carolinian	70%	957	785	18%	6,443	2,906	55%	351,325	137,905	61%
Cascades	75%	1,407	1,071	24%	11,382	5,818	49%	794,632	220,854	72%
Downeaster	82%	1,954	0	100%	12,305	417	97%	472,618	56,372	88%
Empire	78%	6,161	2,337	62%	38,365	12,256	68%	1,682,078	395,715	76%
Adirondack	72%	485	483	0%	2,729	955	65%	102,692	31,800	69%
Ethan Allen Express	70%	586	537	8%	3,612	2,179	40%	172,520	62,528	64%
Maple Leaf	70%	847	402	53%	5,502	2,583	53%	205,851	79,426	61%
New York - Albany	85%	2,849	873	69%	17,354	4,625	73%	779,702	130,552	83%
New York - Niagara Falls	75%	1,394	42	97%	8,569	1,321	85%	412,601	87,002	79%
Berkshire Flyer	60%	0	0	-	599	593	1%	8,712	4,407	49%
Gold Runner	73%	2,024	787	61%	15,000	8,497	43%	770,566	278,950	64%
Heartland Flyer	70%	220	220	0%	1,663	1,496	10%	66,346	26,918	59%
Hiawatha	90%	2,378	240	90%	12,554	839	93%	533,473	58,536	89%
Illinois	78%	1,896	1,127	41%	15,193	4,709	69%	761,417	209,264	73%
Carl Sandburg / Illinois Zephyr	85%	509	255	50%	2,187	1,040	52%	126,987	35,198	72%
Illini / Saluki	85%	695	613	12%	5,072	2,222	56%	264,959	64,122	76%
Lincoln Service	70%	692	259	63%	7,934	1,447	82%	369,471	109,944	70%
Keystone	92%	9,275	372	96%	48,161	2,659	94%	2,330,280	242,205	90%
Lincoln / Missouri	70%	1,149	839	27%	5,287	3,273	38%	237,778	121,581	49%
Mardi Gras Service	80%	317	68	79%	2,257	747	67%	125,978	28,362	77%
Michigan	70%	2,296	496	78%	14,951	7,528	50%	612,376	199,949	67%
Blue Water	70%	694	0	100%	3,547	2,263	36%	143,205	58,091	59%
Pere Marquette	85%	148	0	100%	1,672	176	89%	80,106	15,300	81%
Wolverine	70%	1,454	496	66%	9,732	5,089	48%	389,065	128,558	67%
Missouri	80%	264	264	0%	1,767	757	57%	67,603	17,193	75%
Pacific Surfliner	85%	9,367	3,795	59%	61,560	15,067	76%	2,473,732	444,774	82%
Pennsylvanian	80%	860	125	85%	5,076	1,428	72%	270,878	52,505	81%
Piedmont	80%	419	74	82%	5,101	808	84%	345,375	89,460	74%
Vermont	75%	1,295	1,284	1%	8,041	3,716	54%	392,925	116,922	70%
Long Distance	70%	12,376	8,274	33%	77,719	45,432	42%	3,760,318	1,622,366	57%
Auto Train	70%	851	0	100%	5,192	917	82%	239,601	81,706	66%
California Zephyr	70%	1,005	918	9%	6,127	4,568	25%	297,721	111,225	63%
Cardinal	70%	313	250	20%	1,482	889	40%	72,963	36,432	50%
City Of New Orleans	75%	562	560	0%	3,816	3,137	18%	195,040	61,316	69%
Coast Starlight	70%	1,455	1,362	6%	6,851	3,906	43%	351,528	124,368	65%
Crescent	70%	764	183	76%	5,242	819	84%	284,895	86,802	70%
Empire Builder	70%	915	589	36%	5,826	4,753	18%	294,193	146,958	50%
Floridian	60%	2,288	1,113	51%	10,354	7,692	26%	488,120	334,734	31%
Lake Shore Ltd	73%	1,049	566	46%	7,169	2,878	60%	294,406	87,984	70%
Palmetto	70%	812	649	20%	5,909	2,722	54%	282,012	85,331	70%
Silver Meteor	70%	884	772	13%	5,985	4,379	27%	311,185	141,730	54%
Southwest Chief	60%	997	948	5%	6,246	4,509	28%	256,712	167,102	35%
Sunset Ltd	70%	0	0	-	981	697	29%	89,347	33,465	63%
Texas Eagle	70%	481	364	24%	6,539	3,566	45%	302,595	123,213	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00044 00000000402 "UNCLASSIFIED" 8/7/2026

Train Index Dates Through August 06, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	39,608	641,417	618	1,829,687	32,589,355	561

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,991	195,430	102	87,903	9,392,432	94
INFRASTRUCTURE PLANNED	135	2,937	195,430	150	98,992	9,392,432	105
FLEET RELIABILITY	90	5,847	641,417	91	291,987	32,589,355	90
TRAIN OPERATIONS	424	28,833	641,417	450	1,350,805	32,589,355	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/06/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	56	82.3%	1,844	297	83.9%	92,788	12,849	86.2%
Central Division	86.0%	55	5	90.9%	338	41	87.9%	17,766	1,615	90.9%
East Division	82.0%	176	35	80.1%	1,003	151	84.9%	48,673	7,569	84.4%
West Division	86.0%	86	16	81.4%	503	105	79.1%	26,349	3,665	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/06/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	56	82.3%	1,844	297	83.9%	92,788	12,849	86.2%
Central Division	86.0%	55	5	90.9%	338	41	87.9%	17,766	1,615	90.9%
CDL	95.0%	2	0	100.0%	12	2	83.3%	588	27	95.4%
CHI	86.0%	26	4	84.6%	156	26	83.3%	8,206	993	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	6	0	100.0%	333	36	89.2%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	5	0	100.0%	293	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	12	2	83.3%	599	46	92.3%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	34	1	97.1%	1,814	115	93.7%
MOE	97.5%	2	0	100.0%	12	0	100.0%	617	9	98.5%
MSP	96.5%	1	0	100.0%	6	1	83.3%	303	7	97.7%
NOL	94.5%	4	0	100.0%	27	0	100.0%	1,300	60	95.4%
OKC	97.0%	1	0	100.0%	6	0	100.0%	304	6	98.0%
PNT	88.0%	3	0	100.0%	18	2	88.9%	805	66	91.8%
PTH	93.0%	1	0	100.0%	6	1	83.3%	298	12	96.0%
QCY	91.0%	2	0	100.0%	9	1	88.9%	586	44	92.5%
SAS	90.5%	1	0	100.0%	6	1	83.3%	307	34	88.9%
STL	89.0%	2	0	100.0%	22	3	86.4%	1,197	103	91.4%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	35	80.1%	1,003	151	84.9%	48,673	7,569	84.4%
ALB	88.5%	8	0	100.0%	47	3	93.6%	2,297	178	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	30	3	90.0%	1,496	161	89.2%
BOS	85.5%	18	1	94.4%	106	6	94.3%	5,269	610	88.4%
BRK	92.5%	5	0	100.0%	30	1	96.7%	1,482	103	93.0%
BTN	82.0%	1	0	100.0%	6	0	100.0%	296	41	86.1%
CLT	91.5%	5	2	60.0%	30	4	86.7%	1,507	154	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	1	0	100.0%	11	0	100.0%	604	57	90.6%
GRO	-	2	0	100.0%	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	2	84.6%	66	11	83.3%	3,430	559	83.7%
HFD	-	2	0	100.0%	8	2	75.0%	199	17	91.5%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	6	0	100.0%	306	38	87.6%
MIA	89.5%	2	1	50.0%	12	1	91.7%	612	69	88.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/06/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	56	82.3%	1,844	297	83.9%	92,788	12,849	86.2%
East Division	82.0%	176	35	80.1%	1,003	151	84.9%	48,673	7,569	84.4%
MTR	79.0%	1	0	100.0%	6	1	83.3%	293	53	81.9%
NFK	84.5%	2	0	100.0%	12	2	83.3%	695	125	82.0%
NFL	93.5%	2	0	100.0%	12	0	100.0%	624	29	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	29	3	89.7%	1,583	256	83.8%
NPN	93.0%	2	0	100.0%	12	2	83.3%	584	43	92.6%
NYP	75.5%	50	13	74.0%	279	67	76.0%	12,763	2,845	77.7%
PGH	93.0%	1	0	100.0%	6	1	83.3%	307	23	92.5%
PHL	48.0%	5	3	40.0%	28	15	46.4%	1,578	755	52.2%
PIT	76.0%	-	-	-	1	1	0.0%	16	13	18.8%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	2	0	100.0%	16	0	100.0%	1,174	49	95.8%
RNK	83.5%	2	0	100.0%	12	0	100.0%	608	87	85.7%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	6	0	100.0%	293	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	6	0	100.0%	303	10	96.7%
SFA	88.0%	1	0	100.0%	6	0	100.0%	306	41	86.6%
SPG	92.5%	6	1	83.3%	34	1	97.1%	1,841	106	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	6	1	83.3%	295	61	79.3%
WAS	84.0%	31	10	67.7%	172	26	84.9%	7,644	993	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	86	16	81.4%	503	105	79.1%	26,349	3,665	86.1%
ARN	92.0%	1	0	100.0%	6	0	100.0%	308	26	91.6%
BFD	79.0%	7	0	100.0%	41	10	75.6%	1,938	403	79.2%
EMY	72.0%	1	0	100.0%	6	1	83.3%	324	95	70.7%
EUG	86.5%	2	0	100.0%	12	0	100.0%	610	56	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	18	6	66.7%	927	149	83.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	61	7	88.5%	3,060	333	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	2	84.6%	68	27	60.3%	3,329	855	74.3%
PDX	86.0%	3	3	0.0%	19	12	36.8%	1,507	193	87.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/06/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	56	82.3%	1,844	297	83.9%	92,788	12,849	86.2%
West Division	86.0%	86	16	81.4%	503	105	79.1%	26,349	3,665	86.1%
SAC	88.5%	16	3	81.3%	86	8	90.7%	4,352	470	89.2%
SAN	90.5%	13	1	92.3%	77	7	90.9%	3,718	351	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	3	0.0%	29	15	48.3%	2,414	362	85.0%
SJC	89.0%	7	0	100.0%	41	4	90.2%	2,165	213	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	18	3	83.3%	690	68	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	4	2	50.0%	302	28	90.7%
VAC	97.0%	2	0	100.0%	12	0	100.0%	603	14	97.7%
VAN	-	1	0	100.0%	4	3	25.0%	4	3	25.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	161	6	1	83.3%	308	60	80.5%	6	4	33.3%	306	140	54.2%
4	101	6	0	100.0%	307	46	85.0%	6	4	33.3%	307	203	33.9%
5	380	6	1	83.3%	306	51	83.3%	6	6	0.0%	302	94	68.9%
6	270	6	1	83.3%	305	86	71.8%	6	5	16.7%	305	108	64.6%
7		6	2	66.7%	297	44	85.2%	5	4	20.0%	288	78	72.9%
8	357	6	6	0.0%	297	135	54.5%	6	5	16.7%	296	180	39.2%
11		6	4	33.3%	308	61	80.2%	6	1	83.3%	302	61	79.8%
14	193	6	2	66.7%	309	51	83.5%	5	5	0.0%	306	97	68.3%
19		6	1	83.3%	307	78	74.6%	6	0	100.0%	304	71	76.6%
20		6	0	100.0%	307	23	92.5%	6	1	83.3%	307	59	80.8%
21	No OS	6	2	66.7%	304	27	91.1%	6	3	50.0%	303	85	71.9%
22	123	6	1	83.3%	305	32	89.5%	6	1	83.3%	303	82	72.9%
23		6	0	100.0%	309	6	98.1%	6	2	66.7%	307	87	71.7%
24		6	0	100.0%	309	16	94.8%	6	3	50.0%	308	59	80.8%
25	45	6	0	100.0%	308	3	99.0%	6	3	50.0%	306	86	71.9%
26		6	0	100.0%	308	5	98.4%	6	1	83.3%	306	61	80.1%
27	Cncld	3	3	0.0%	288	19	93.4%	2	2	0.0%	283	95	66.4%
40		6	1	83.3%	302	42	86.1%	6	2	66.7%	299	157	47.5%
41		6	3	50.0%	301	117	61.1%	6	5	16.7%	299	229	23.4%
42		6	1	83.3%	309	25	91.9%	6	2	66.7%	307	54	82.4%
43		6	0	100.0%	308	42	86.4%	6	0	100.0%	307	70	77.2%
48		6	2	66.7%	307	59	80.8%	6	0	100.0%	306	42	86.3%
49	120	6	3	50.0%	307	78	74.6%	6	2	66.7%	307	64	79.2%
51	51	2	1	50.0%	128	56	56.3%	3	2	33.3%	124	46	62.9%
52		6	0	100.0%	306	41	86.6%	6	0	100.0%	305	72	76.4%
53		6	0	100.0%	306	38	87.6%	6	2	66.7%	305	97	68.2%
55		4	0	100.0%	194	7	96.4%	4	1	75.0%	191	39	79.6%
56	41	4	2	50.0%	195	25	87.2%	4	3	25.0%	191	37	80.6%
58	177	6	0	100.0%	283	16	94.3%	5	5	0.0%	281	78	72.2%
59	76	6	5	16.7%	281	38	86.5%	6	5	16.7%	277	62	77.6%
63	65	6	3	50.0%	310	135	56.5%	6	6	0.0%	304	172	43.4%
64	96	6	1	83.3%	308	69	77.6%	6	5	16.7%	307	114	62.9%
66		6	0	100.0%	307	61	80.1%	6	1	83.3%	303	55	81.8%
67		5	1	80.0%	213	14	93.4%	4	1	75.0%	212	37	82.5%
68	53	6	1	83.3%	310	62	80.0%	6	2	66.7%	309	120	61.2%
69	112	6	4	33.3%	297	72	75.8%	6	3	50.0%	292	46	84.2%
71	Cncld	6	0	100.0%	305	3	99.0%	5	0	100.0%	303	81	73.3%
72	Cncld	6	2	66.7%	301	33	89.0%	5	2	60.0%	299	63	78.9%
73		6	0	100.0%	304	19	93.8%	6	1	83.3%	302	143	52.6%
74		6	0	100.0%	302	33	89.1%	6	2	66.7%	300	110	63.3%
75		6	0	100.0%	298	16	94.6%	6	0	100.0%	292	137	53.1%
76		6	0	100.0%	298	29	90.3%	6	3	50.0%	289	120	58.5%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	18	6	0	100.0%	300	20	93.3%	6	2	66.7%	298	125	58.1%
78		6	0	100.0%	304	25	91.8%	6	1	83.3%	303	64	78.9%
79		6	1	83.3%	307	57	81.4%	6	1	83.3%	306	102	66.7%
80	127	6	2	66.7%	307	35	88.6%	6	3	50.0%	304	66	78.3%
84	42	4	1	75.0%	185	15	91.9%	4	2	50.0%	183	45	75.4%
85		4	0	100.0%	196	16	91.8%	4	0	100.0%	196	70	64.3%
86	24	4	0	100.0%	196	15	92.3%	4	3	25.0%	195	118	39.5%
89		6	2	66.7%	305	67	78.0%	6	3	50.0%	303	88	71.0%
90	32	6	0	100.0%	305	10	96.7%	6	2	66.7%	304	53	82.6%
93	62	4	0	100.0%	195	19	90.3%	4	2	50.0%	194	49	74.7%
94		4	0	100.0%	226	55	75.7%	4	1	75.0%	224	84	62.5%
95	25	4	0	100.0%	195	4	97.9%	4	3	25.0%	195	72	63.1%
97	274	6	5	16.7%	307	203	33.9%	6	4	33.3%	305	104	65.9%
98	34	6	0	100.0%	307	26	91.5%	6	5	16.7%	305	113	63.0%
110		4	0	100.0%	192	102	46.9%	4	0	100.0%	189	19	89.9%
111		4	0	100.0%	186	35	81.2%	4	0	100.0%	184	21	88.6%
112		4	0	100.0%	186	18	90.3%	4	0	100.0%	185	19	89.7%
113		4	2	50.0%	117	27	76.9%	4	0	100.0%	116	14	87.9%
119		4	1	75.0%	183	46	74.9%	4	1	75.0%	181	23	87.3%
125		4	0	100.0%	196	11	94.4%	4	1	75.0%	196	75	61.7%
129		4	2	50.0%	195	49	74.9%	4	1	75.0%	195	29	85.1%
130		4	0	100.0%	186	18	90.3%	4	0	100.0%	184	16	91.3%
131		4	1	75.0%	188	54	71.3%	4	0	100.0%	188	35	81.4%
134	73	4	1	75.0%	196	28	85.7%	4	2	50.0%	195	38	80.5%
136	65	4	0	100.0%	196	24	87.8%	4	1	75.0%	194	26	86.6%
137		4	1	75.0%	193	36	81.3%	4	1	75.0%	193	59	69.4%
138		4	0	100.0%	196	39	80.1%	4	1	75.0%	195	35	82.1%
141		4	0	100.0%	195	3	98.5%	4	2	50.0%	194	35	82.0%
148		4	0	100.0%	195	20	89.7%	4	0	100.0%	193	36	81.3%
151		6	3	50.0%	306	98	68.0%	6	0	100.0%	305	95	68.9%
170		4	0	100.0%	191	12	93.7%	4	0	100.0%	190	29	84.7%
171	176	4	0	100.0%	196	11	94.4%	4	3	25.0%	196	78	60.2%
172		4	1	75.0%	195	16	91.8%	4	2	50.0%	193	64	66.8%
173	22	4	0	100.0%	188	24	87.2%	4	3	25.0%	187	81	56.7%
174	49	4	0	100.0%	196	20	89.8%	4	2	50.0%	196	50	74.5%
175	56	4	0	100.0%	196	22	88.8%	4	1	75.0%	196	63	67.9%
176		4	0	100.0%	188	15	92.0%	4	1	75.0%	186	25	86.6%
177		4	0	100.0%	196	27	86.2%	4	0	100.0%	196	46	76.5%
178		4	0	100.0%	196	26	86.7%	4	0	100.0%	194	31	84.0%
179		4	1	75.0%	196	24	87.8%	4	1	75.0%	195	71	63.6%
181		4	2	50.0%	192	61	68.2%	4	1	75.0%	190	16	91.6%
182		4	0	100.0%	186	30	83.9%	4	0	100.0%	184	21	88.6%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		4	3	25.0%	195	59	69.7%	4	2	50.0%	192	40	79.2%
184	35	4	2	50.0%	196	35	82.1%	4	1	75.0%	195	28	85.6%
185		4	0	100.0%	196	37	81.1%	4	0	100.0%	196	14	92.9%
186	39	4	2	50.0%	195	23	88.2%	4	2	50.0%	194	55	71.6%
190		4	2	50.0%	195	71	63.6%	4	1	75.0%	194	44	77.3%
192		4	0	100.0%	193	24	87.6%	4	1	75.0%	193	18	90.7%
193		4	2	50.0%	192	80	58.3%	4	1	75.0%	191	89	53.4%
196		4	0	100.0%	192	20	89.6%	3	0	100.0%	190	15	92.1%
197		4	1	75.0%	196	76	61.2%	4	2	50.0%	196	69	64.8%
198		4	0	100.0%	128	17	86.7%	4	0	100.0%	127	21	83.5%
230		6	0	100.0%	143	4	97.2%	6	0	100.0%	143	7	95.1%
232		6	0	100.0%	309	11	96.4%	6	1	83.3%	309	22	92.9%
233		5	1	80.0%	278	62	77.7%	5	3	40.0%	277	91	67.1%
234		6	0	100.0%	310	22	92.9%	6	0	100.0%	309	25	91.9%
235		6	3	50.0%	234	37	84.2%	6	1	83.3%	233	53	77.3%
236		6	0	100.0%	294	10	96.6%	6	2	66.7%	293	41	86.0%
237	52	6	0	100.0%	307	56	81.8%	6	1	83.3%	305	52	83.0%
238		6	2	66.7%	234	22	90.6%	6	1	83.3%	232	19	91.8%
239		6	0	100.0%	308	79	74.4%	6	0	100.0%	307	38	87.6%
240		6	0	100.0%	309	21	93.2%	6	2	66.7%	306	62	79.7%
241	23	6	1	83.3%	309	75	75.7%	6	2	66.7%	309	73	76.4%
243	19	6	2	66.7%	245	67	72.7%	6	2	66.7%	244	35	85.7%
244	41	5	0	100.0%	277	12	95.7%	5	4	20.0%	277	53	80.9%
245		6	1	83.3%	190	34	82.1%	6	2	66.7%	189	24	87.3%
280		6	0	100.0%	310	15	95.2%	6	1	83.3%	309	62	79.9%
281		6	0	100.0%	310	37	88.1%	6	0	100.0%	310	57	81.6%
283		6	2	66.7%	310	76	75.5%	6	1	83.3%	310	62	80.0%
284		6	0	100.0%	310	13	95.8%	6	0	100.0%	307	54	82.4%
290	19	6	0	100.0%	310	50	83.9%	6	4	33.3%	307	118	61.6%
291	21	6	4	33.3%	309	97	68.6%	6	2	66.7%	307	78	74.6%
301		6	0	100.0%	307	10	96.7%	6	1	83.3%	303	56	81.5%
305		5	0	100.0%	291	28	90.4%	5	0	100.0%	287	115	59.9%
306	24	6	1	83.3%	305	17	94.4%	6	1	83.3%	304	83	72.7%
307	Cncld	6	1	83.3%	298	39	86.9%	5	1	80.0%	294	83	71.8%
311	166	6	1	83.3%	303	27	91.1%	6	2	66.7%	297	65	78.1%
316	105	6	2	66.7%	299	20	93.3%	6	4	33.3%	294	82	72.1%
318	178	6	0	100.0%	308	31	89.9%	6	4	33.3%	305	148	51.5%
319		6	0	100.0%	309	20	93.5%	6	5	16.7%	304	170	44.1%
329		4	0	100.0%	219	9	95.9%	4	0	100.0%	219	15	93.2%
330		5	0	100.0%	263	6	97.7%	5	0	100.0%	263	15	94.3%
331		6	0	100.0%	310	33	89.4%	6	0	100.0%	310	44	85.8%
332		5	0	100.0%	309	17	94.5%	5	0	100.0%	309	43	86.1%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		6	0	100.0%	310	10	96.8%	6	0	100.0%	309	40	87.1%
335		6	0	100.0%	310	34	89.0%	6	1	83.3%	308	52	83.1%
336		6	0	100.0%	310	10	96.8%	6	0	100.0%	308	28	90.9%
337		6	0	100.0%	310	18	94.2%	6	1	83.3%	306	37	87.9%
338	23	6	1	83.3%	310	48	84.5%	6	3	50.0%	308	97	68.5%
339		6	2	66.7%	310	52	83.2%	6	1	83.3%	310	54	82.6%
341	15	5	1	80.0%	297	45	84.8%	5	1	80.0%	291	42	85.6%
342		6	0	100.0%	310	24	92.3%	6	0	100.0%	308	60	80.5%
350		6	0	100.0%	287	18	93.7%	6	5	16.7%	280	156	44.3%
351		6	1	83.3%	293	28	90.4%	6	3	50.0%	291	81	72.2%
353		6	0	100.0%	248	13	94.8%	6	1	83.3%	242	39	83.9%
354	64	6	0	100.0%	291	35	88.0%	6	6	0.0%	284	107	62.3%
355	33	6	1	83.3%	300	32	89.3%	6	5	16.7%	293	104	64.5%
364		6	3	50.0%	299	68	77.3%	6	3	50.0%	293	110	62.5%
365		6	1	83.3%	298	12	96.0%	5	3	40.0%	295	112	62.0%
370	30	5	0	100.0%	300	35	88.3%	5	2	60.0%	290	71	75.5%
371		5	0	100.0%	293	8	97.3%	5	0	100.0%	292	29	90.1%
380		3	1	66.7%	292	28	90.4%	2	0	100.0%	291	63	78.4%
381		6	0	100.0%	308	12	96.1%	6	2	66.7%	307	62	79.8%
382	28	6	0	100.0%	307	27	91.2%	6	4	33.3%	307	104	66.1%
383	48	4	0	100.0%	297	26	91.2%	4	4	0.0%	294	127	56.8%
390	19	6	2	66.7%	292	21	92.8%	6	4	33.3%	291	77	73.5%
391	18	6	1	83.3%	293	12	95.9%	6	4	33.3%	289	80	72.3%
392	17	6	0	100.0%	306	10	96.7%	6	2	66.7%	303	92	69.6%
393	23	6	0	100.0%	310	18	94.2%	6	3	50.0%	307	94	69.4%
417	39	4	1	75.0%	206	45	78.2%	4	1	75.0%	197	23	88.3%
425		4	0	100.0%	208	6	97.1%	4	0	100.0%	208	7	96.6%
448	97	6	1	83.3%	240	44	81.7%	6	2	66.7%	237	82	65.4%
449		6	0	100.0%	237	32	86.5%	6	1	83.3%	237	43	81.9%
470		4	0	100.0%	219	37	83.1%	4	0	100.0%	213	24	88.7%
471		4	1	75.0%	209	12	94.3%	4	0	100.0%	209	5	97.6%
473		4	0	100.0%	215	15	93.0%	4	0	100.0%	212	10	95.3%
474	74	4	0	100.0%	213	63	70.4%	4	2	50.0%	198	65	67.2%
475		4	0	100.0%	213	6	97.2%	4	0	100.0%	213	15	93.0%
478		4	1	75.0%	207	33	84.1%	4	0	100.0%	205	27	86.8%
479		4	0	100.0%	214	34	84.1%	4	0	100.0%	212	31	85.4%
486	28	4	1	75.0%	218	32	85.3%	4	1	75.0%	212	59	72.2%
494		4	0	100.0%	220	41	81.4%	4	0	100.0%	213	57	73.2%
495		4	0	100.0%	203	4	98.0%	4	0	100.0%	201	3	98.5%
503	58	6	4	33.3%	306	31	89.9%	6	4	33.3%	299	91	69.6%
504	18	6	0	100.0%	310	19	93.9%	6	2	66.7%	308	92	70.1%
506	No OS	6	4	33.3%	305	46	84.9%	4	2	50.0%	297	48	83.8%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507	86	6	4	33.3%	310	40	87.1%	6	5	16.7%	310	105	66.1%
508	49	6	0	100.0%	305	41	86.6%	6	5	16.7%	301	73	75.7%
516	22	6	4	33.3%	301	33	89.0%	6	4	33.3%	300	138	54.0%
517	25	6	0	100.0%	310	8	97.4%	6	4	33.3%	306	131	57.2%
518	48	6	4	33.3%	310	41	86.8%	6	6	0.0%	308	213	30.8%
519		6	0	100.0%	301	9	97.0%	6	2	66.7%	299	68	77.3%
520		4	2	50.0%	177	27	84.7%	3	0	100.0%	173	9	94.8%
521		4	0	100.0%	215	7	96.7%	4	2	50.0%	215	29	86.5%
522		4	2	50.0%	215	41	80.9%	4	0	100.0%	212	20	90.6%
523		4	1	75.0%	215	8	96.3%	4	1	75.0%	214	23	89.3%
524		3	0	100.0%	214	16	92.5%	3	2	33.3%	211	25	88.2%
525		3	0	100.0%	212	16	92.5%	3	0	100.0%	208	14	93.3%
526		4	2	50.0%	189	36	81.0%	4	1	75.0%	186	16	91.4%
527		4	0	100.0%	215	10	95.3%	4	1	75.0%	214	38	82.2%
528		4	0	100.0%	215	17	92.1%	4	1	75.0%	214	31	85.5%
529	24	4	0	100.0%	215	12	94.4%	4	3	25.0%	214	61	71.5%
530	19	4	0	100.0%	169	16	90.5%	4	2	50.0%	169	34	79.9%
531		4	0	100.0%	189	13	93.1%	4	0	100.0%	189	13	93.1%
532		4	0	100.0%	215	51	76.3%	4	0	100.0%	214	31	85.5%
534		4	0	100.0%	174	25	85.6%	4	0	100.0%	172	16	90.7%
535		4	1	75.0%	202	26	87.1%	4	2	50.0%	197	25	87.3%
536		4	2	50.0%	215	57	73.5%	4	0	100.0%	211	38	82.0%
537		3	0	100.0%	184	22	88.0%	3	0	100.0%	178	20	88.8%
538		4	1	75.0%	215	25	88.4%	4	1	75.0%	214	44	79.4%
539	11	4	0	100.0%	169	24	85.8%	4	3	25.0%	169	74	56.2%
540		4	1	75.0%	214	39	81.8%	4	0	100.0%	206	18	91.3%
541		4	1	75.0%	214	23	89.3%	4	1	75.0%	208	37	82.2%
542	28	4	0	100.0%	214	24	88.8%	4	2	50.0%	211	39	81.5%
543	23	4	1	75.0%	215	25	88.4%	4	2	50.0%	215	65	69.8%
544		4	1	75.0%	213	21	90.1%	3	0	100.0%	209	20	90.4%
545		4	0	100.0%	215	17	92.1%	4	0	100.0%	212	24	88.7%
547	37	4	2	50.0%	215	43	80.0%	4	2	50.0%	215	49	77.2%
548		3	0	100.0%	209	21	90.0%	3	1	66.7%	207	16	92.3%
549		4	0	100.0%	210	26	87.6%	4	2	50.0%	202	19	90.6%
550		4	0	100.0%	169	18	89.3%	4	3	25.0%	169	39	76.9%
551		4	0	100.0%	211	22	89.6%	4	1	75.0%	201	21	89.6%
552		1	0	100.0%	2	1	50.0%	1	0	100.0%	2	1	50.0%
562		6	0	100.0%	301	23	92.4%	6	0	100.0%	297	35	88.2%
564		6	0	100.0%	302	19	93.7%	6	1	83.3%	294	39	86.7%
566	44	6	2	66.7%	300	27	91.0%	6	4	33.3%	297	49	83.5%
567	31	6	0	100.0%	187	10	94.7%	6	2	66.7%	185	11	94.1%
572	25	6	0	100.0%	297	24	91.9%	6	1	83.3%	290	84	71.0%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573	37	6	0	100.0%	299	40	86.6%	6	1	83.3%	292	52	82.2%
579		6	1	83.3%	187	12	93.6%	5	2	60.0%	181	39	78.5%
580	17	6	0	100.0%	302	16	94.7%	6	3	50.0%	295	31	89.5%
581	16	6	2	66.7%	302	52	82.8%	6	3	50.0%	300	67	77.7%
584	42	6	1	83.3%	186	26	86.0%	6	6	0.0%	181	114	37.0%
587		6	1	83.3%	295	17	94.2%	6	1	83.3%	286	54	81.1%
588		6	1	83.3%	187	19	89.8%	6	2	66.7%	186	35	81.2%
591		6	1	83.3%	299	22	92.6%	6	2	66.7%	293	41	86.0%
593		5	1	80.0%	295	48	83.7%	5	0	100.0%	274	37	86.5%
595		6	0	100.0%	297	53	82.2%	6	1	83.3%	294	61	79.3%
600	37	4	0	100.0%	223	9	96.0%	4	1	75.0%	221	20	91.0%
601	12	4	3	25.0%	206	86	58.3%	4	2	50.0%	203	27	86.7%
605		4	4	0.0%	213	134	37.1%	4	0	100.0%	209	22	89.5%
607		4	0	100.0%	222	30	86.5%	4	0	100.0%	219	25	88.6%
609		4	0	100.0%	213	23	89.2%	4	1	75.0%	212	20	90.6%
622		4	1	75.0%	124	33	73.4%	4	0	100.0%	122	5	95.9%
626		4	2	50.0%	127	18	85.8%	4	0	100.0%	125	18	85.6%
639		4	0	100.0%	193	38	80.3%	4	0	100.0%	192	19	90.1%
640	15	4	0	100.0%	213	7	96.7%	4	4	0.0%	211	84	60.2%
641	23	4	1	75.0%	195	39	80.0%	4	1	75.0%	195	27	86.2%
642		4	1	75.0%	211	10	95.3%	4	0	100.0%	210	26	87.6%
643		4	0	100.0%	225	44	80.4%	4	1	75.0%	222	37	83.3%
644		4	0	100.0%	217	28	87.1%	4	0	100.0%	215	52	75.8%
645		4	0	100.0%	225	41	81.8%	4	1	75.0%	222	47	78.8%
646		4	0	100.0%	214	51	76.2%	4	2	50.0%	212	103	51.4%
647		4	0	100.0%	225	32	85.8%	4	0	100.0%	224	49	78.1%
648		4	0	100.0%	221	56	74.7%	4	0	100.0%	221	34	84.6%
649		4	0	100.0%	226	42	81.4%	4	0	100.0%	223	34	84.8%
650		4	0	100.0%	225	41	81.8%	4	0	100.0%	222	36	83.8%
651		4	1	75.0%	225	17	92.4%	4	1	75.0%	223	43	80.7%
652		4	2	50.0%	226	31	86.3%	4	1	75.0%	222	38	82.9%
653		4	2	50.0%	214	35	83.6%	4	0	100.0%	211	39	81.5%
654		4	1	75.0%	215	41	80.9%	4	1	75.0%	211	19	91.0%
655		4	1	75.0%	223	73	67.3%	4	1	75.0%	221	74	66.5%
656		4	2	50.0%	225	49	78.2%	4	0	100.0%	224	30	86.6%
657		4	0	100.0%	214	27	87.4%	4	0	100.0%	213	29	86.4%
658		4	0	100.0%	225	35	84.4%	4	0	100.0%	223	33	85.2%
680		4	0	100.0%	220	12	94.5%	4	0	100.0%	219	27	87.7%
681	11	4	0	100.0%	220	17	92.3%	4	2	50.0%	214	88	58.9%
682		4	0	100.0%	219	6	97.3%	4	1	75.0%	219	39	82.2%
683		4	1	75.0%	202	18	91.1%	4	2	50.0%	201	69	65.7%
684		4	0	100.0%	201	32	84.1%	4	0	100.0%	201	45	77.6%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685		4	0	100.0%	216	31	85.6%	4	0	100.0%	213	53	75.1%
686		4	0	100.0%	221	37	83.3%	4	0	100.0%	220	47	78.6%
687		4	0	100.0%	220	34	84.5%	4	0	100.0%	219	36	83.6%
688	13	4	0	100.0%	219	13	94.1%	4	1	75.0%	218	37	83.0%
701		6	0	100.0%	242	25	89.7%	6	0	100.0%	239	25	89.5%
702		6	0	100.0%	309	32	89.6%	6	3	50.0%	306	73	76.1%
703		6	4	33.3%	310	97	68.7%	6	3	50.0%	308	88	71.4%
704	31	6	1	83.3%	241	38	84.2%	6	2	66.7%	234	48	79.5%
710		6	0	100.0%	310	77	75.2%	6	2	66.7%	306	83	72.9%
711		6	0	100.0%	301	34	88.7%	6	4	33.3%	280	56	80.0%
712		6	3	50.0%	307	83	73.0%	6	4	33.3%	298	102	65.8%
713	Cncld	5	0	100.0%	177	16	91.0%	3	2	33.3%	159	69	56.6%
714	36	6	5	16.7%	191	80	58.1%	5	5	0.0%	176	81	54.0%
715	Cncld	6	1	83.3%	309	62	79.9%	4	3	25.0%	284	144	49.3%
716	22	6	4	33.3%	310	124	60.0%	6	5	16.7%	304	123	59.5%
717	90	6	2	66.7%	295	70	76.3%	4	3	25.0%	274	89	67.5%
718		6	4	33.3%	310	157	49.4%	6	4	33.3%	308	113	63.3%
719		6	3	50.0%	310	106	65.8%	5	3	40.0%	293	87	70.3%
757		6	0	100.0%	95	5	94.7%	6	0	100.0%	94	8	91.5%
761		6	0	100.0%	306	12	96.1%	6	0	100.0%	303	41	86.5%
765		6	0	100.0%	306	25	91.8%	6	1	83.3%	306	43	85.9%
769		6	0	100.0%	306	27	91.2%	6	1	83.3%	300	58	80.7%
770	20	6	1	83.3%	306	23	92.5%	6	3	50.0%	304	92	69.7%
774	24	6	0	100.0%	306	16	94.8%	6	2	66.7%	305	71	76.7%
777	39	6	0	100.0%	191	12	93.7%	6	3	50.0%	190	45	76.3%
782		6	5	16.7%	191	87	54.5%	6	2	66.7%	186	27	85.5%
785		6	1	83.3%	306	23	92.5%	6	1	83.3%	306	54	82.4%
786	47	6	2	66.7%	95	21	77.9%	5	2	60.0%	91	49	46.2%
790		6	0	100.0%	306	28	90.8%	6	0	100.0%	303	46	84.8%
794		6	1	83.3%	306	34	88.9%	6	1	83.3%	302	67	77.8%
821	32	6	0	100.0%	304	6	98.0%	6	6	0.0%	304	127	58.2%
822	45	6	0	100.0%	306	16	94.8%	6	6	0.0%	304	148	51.3%
1333		6	1	83.3%	306	33	89.2%	6	1	83.3%	303	100	67.0%
1340		6	1	83.3%	305	7	97.7%	6	0	100.0%	305	51	83.3%
1689		5	0	100.0%	100	5	95.0%	5	0	100.0%	99	11	88.9%
2102		4	1	75.0%	72	14	80.6%	4	0	100.0%	71	6	91.5%
2103		4	0	100.0%	136	12	91.2%	4	1	75.0%	135	10	92.6%
2104		4	0	100.0%	162	10	93.8%	4	0	100.0%	160	12	92.5%
2107	27	4	0	100.0%	193	34	82.4%	4	1	75.0%	190	21	88.9%
2108	67	4	1	75.0%	193	27	86.0%	4	2	50.0%	187	22	88.2%
2109		4	1	75.0%	86	12	86.0%	4	1	75.0%	84	5	94.0%
2112		4	1	75.0%	33	5	84.8%	4	0	100.0%	31	2	93.5%

Amtrak On Time Performance

Trains Arriving Through: 8/6/2026

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2113		4	1	75.0%	72	9	87.5%	4	0	100.0%	72	10	86.1%
2115		4	0	100.0%	72	11	84.7%	4	0	100.0%	71	10	85.9%
2116		4	0	100.0%	33	1	97.0%	4	0	100.0%	33	7	78.8%
2118		4	1	75.0%	33	3	90.9%	4	1	75.0%	33	10	69.7%
2119	55	4	2	50.0%	33	6	81.8%	3	1	66.7%	32	11	65.6%
2120	56	4	3	25.0%	33	12	63.6%	3	3	0.0%	31	16	48.4%
2123		4	0	100.0%	71	8	88.7%	4	0	100.0%	70	15	78.6%
2124	25	3	1	66.7%	164	35	78.7%	3	1	66.7%	162	23	85.8%
2127	76	4	1	75.0%	33	8	75.8%	4	1	75.0%	32	8	75.0%
2128		4	0	100.0%	33	3	90.9%	4	1	75.0%	33	3	90.9%
2131	81	4	2	50.0%	33	8	75.8%	4	1	75.0%	33	4	87.9%
2150		4	0	100.0%	186	22	88.2%	4	1	75.0%	183	74	59.6%
2151		4	0	100.0%	135	6	95.6%	4	0	100.0%	133	37	72.2%
2152	28	4	1	75.0%	91	7	92.3%	4	1	75.0%	90	31	65.6%
2154		4	0	100.0%	94	23	75.5%	4	1	75.0%	90	43	52.2%
2155		4	0	100.0%	195	16	91.8%	4	2	50.0%	191	98	48.7%
2158		4	1	75.0%	32	5	84.4%	4	1	75.0%	32	13	59.4%
2159	61	4	1	75.0%	188	15	92.0%	4	3	25.0%	186	62	66.7%
2160		4	0	100.0%	33	2	93.9%	4	2	50.0%	32	20	37.5%
2162	130	4	1	75.0%	194	19	90.2%	4	2	50.0%	188	87	53.7%
2165	29	4	0	100.0%	30	2	93.3%	4	3	25.0%	30	16	46.7%
2167		4	0	100.0%	181	20	89.0%	4	0	100.0%	181	39	78.5%
2171		4	0	100.0%	122	10	91.8%	4	0	100.0%	118	23	80.5%
2190		4	1	75.0%	191	28	85.3%	4	1	75.0%	189	24	87.3%
2193		4	0	100.0%	186	25	86.6%	4	0	100.0%	184	49	73.4%

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2107	WAS	27	CAR	17	CAR	17	BAL-XNY	AM	Air / Brake / Wheel, 3533 LH LC, ENGR REPORTED WHEELS SMOKING IN THIRD CAR.
2108	NYP	67	ENG	78	ENG	78	WIL-PHL	AM	Undesired emergency application, 2137 NG NP, STUCK PARKING BRAKE
2119	WAS	55	ITI	43	ITI	43	NYP-NYP	AM	Service, turn, or wye train, 2108, LATE TURN OFF AM2108
2120	NYP	56	MTI	30	MTI	30	WAS-WAS	AM	Disabled train ahead, Other, NYP, LATE TURN OFF OF 2159. 2159(06) OPERATING 1'07" LATE AFTER UNSPECIFIED MECHANICAL ISSUES IN NYP, EQUIPMENT WILL TURN FOR TRAIN 2120 (06)
2124	NYP	25	MTI	32	MTI	32	WAS-WAS	AM	Disabled train ahead, Other, NYP, LATE TURN OFF INITIAL IB TRN 2119. 2119(06) DEPARTED NYP 258PM-ET, OPERATING 43" LATE DUE TO THE NECESSARY EQUIPMENT SWAP
2127	WAS	76	ENG	64	ENG	64	NYP-NYP	AM	Other electrical failure, 2104 NG NP, LATE TURN OFF AM2116 DUE TO AM2118 BROKEN PANTOGRAPH
2131	WAS	81	ITI	87	ITI	87	NYP-NYP	AM	Service, turn, or wye train, 2120, LATE TURN OFF AM2120
2152	BOS	28	SMW	18	ENG	17	WAS-WAS	AM	Other electrical failure, 2035 LH LP, EMERGENCY POWER PLATE IN AFFECT FROM 1230AM TO 240AM
2159	WAS	61	CAR	28	ENG	26	NYP-NYP	AM	HEP, 2144, MECHANICAL REQUESTED FOR UNSPECIFIED ISSUE
2162	BOS	130	ENG	129	ENG	129	NYP-NYP	AM	Other electrical failure, 2121 NG NP, PAPER WORK ISSUES IN STATION. AM2124 CHANGED CONSIST FOR AM2162 IN STATION
2165	WAS	29	DMW	22	DMW	22	NHV-STM	MN	Waiting for MW clearance Milepost, 50.5, 49.1
84	NYP	42	ENG	23	ENG	23	WAS-WAS	AM	Set out defective locomotive, 609 EX ES, SHOPPED MTR 609 REPLACED WITH 669
86	BOS	24	CTI	27	CTI	11	PVD-RTE	AM	Follow, MBTA, 856, Milepost w/Letters, XMF, RTE, AM86 followed signals of MT856
93	NFK	62	PTI	33	FTI	32	FBG-ASD	CS	Follow m409, Milepost, 34.0, 15.2
95	NFK	25	WTR	33	DCS	24	FBG-RVR	CS	Wayside detector failure including false actuation Had to walk the train check for hot bearings, Other, cfp 32.6

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 8/6/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
134	NYP	73	CAR	48	CAR	48	WAS-WAS	AM	Set out defective car, 82655 AX AS, SHOPPED CAR IN S&I CAUSED LATE RELEASE	
136	SPG	65	ENG	52	ENG	52	NHV-NHV	AM	Other electrical failure, 100 DX BD, No. 136 will be delayed due to mechanical issues with engine 100. Mechanical is swapping engines	
171	RNK	176	DBS	172	DBS	172	MSS-CLP	NS	Debris strike Train went into emergency after hitting a tree. Crew members walked the train and noticed the "wasp" missing which was causing air to release. Road foreman and mechanical came out to seal the hole., Tree, Control Point, Mountain Run	
173	WAS	22	DSR	29	DSR	20	BRP-STM	MN	Per bulletin Working limits at MP 50.5, Milepost w/Letters, BRP, STM, 30, 3	
174	BOS	49	MTI	24	MTI	24	WIL-PHL	AM	Disabled train ahead, Control Point, HOOK, HELD FOR DISPOSITION A/C DISABLED 2108 AHEAD	
175	WAS	56	CTI	55	CTI	44	NHV-STM	MN	Follow metro, Other, enroute	
184	BOS	35	ENG	23	ENG	23	WAS-WAS	AM	HEP, 643 EX ES, MTR WENT INTO PTS WHILE GOING AROUND WYE	
186	PHL	39	WTR	23	FTI	12	ASD-FBG	CS	Follow 3/2 at 23.1, Csx 408, Milepost, 17.7, 23.1	
417	NHV	39	CTI	17	CTI	17	SPG-WNL	AM	Meet, CTRAIL, 4414, Milepost w/Letters, SPG, WNL, AM417 waited for CT4414 to clear single track	
474	SPG	74	CON	66	CON	66	NHV-NHV	AM	Hold for connecting train	
486	SPG	28	PTI	18	PTI	9	BER-HFD	AM	Meet, 55, Milepost w/Letters, BER, HFD, AM486 waited for AM55 to clear single track	
80	NYP	127	PTI	65	PTI	61	BNC-DNC	NS	Train 71 was held at DNC station due to striking a pedestrian. Crew of 71 was waiting to be relieved. 71, Milepost, 23.4, 49.8	
600	NYP	37	ENG	42	ENG	39	PHL-XHM	AM	Undesired emergency application, 9634 CB CC, OPERATING AS COACH, WYE OUTBOUND	
601	HAR	12	BSP	9	BSP	9	PAR-LNC	AM	Addition to TSRB a/c bridge strike, Milepost, 67.33, 67.33	
640	NYP	15	CTI	18	CTI	11	TRE-NWK	AM	Follow, NJT, NJ3926, Other, XCY-NWK	
641	HAR	23	PTI	31	PTI	15	PHL-PAO	AM	Follow, 600, Control Point, PHL TO OVERBROOK, FOLLOW 600 WHICH WYE OUTBOUND	
681	BRK	11	PTI	14	PTI	10	POR-FRE	CS	Meet 684, Control Point, Congress	

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
688	BON	13	PTI	6	PTI	4	FRE-POR	CS	Meet 685, Control Point, Mountain
63	TWO	65	CTI	10	DCS	7	SDY-XHF	AM	Issue with automatic road crossing protection Milepost, 166.4, 166.4
64	NYP	96	FTI	62	FTI	39	BUF-ROC	CS	Follow Control Point, 431, Control Point, 382, CSX
68	NYP	53	WTR	43	WTR	43	SLQ-RSP	CN	Heat order Milepost, 42.7, 0
69	MTR	112	CUI	40	CUI	40	XLQ-XLQ	CN	Canada
237	ALB	52	CTI	27	CTI	24	CRT-POU	MN	Meet mn, Control Point, 39
241	ALB	23	CTI	17	CTI	17	CRT-POU	MN	Follow mn, Control Point, 19
243	ALB	19	ITI	16	ITI	16	NYP-NYP	AM	Service, turn, or wye train, 244, LATE TURN OFF AM244
244	NYP	41	CTI	25	PTI	16	ALB-HUD	AM	Wait for station track amtrak 291, Control Point, 124
290	NYP	19	CTI	28	CTI	24	POU-CRT	MN	Follow metro north, Milepost, 72, 35
291	BTN	21	PTI	21	ENG	11	NYP-XSD	AM	PTC - On Board Cab Signal or PTC Failure, 703 DX DM, STOPPED AT INWOOD A/C CAB SIGNAL FAILURE
49	CHI	120	CON	185	CON	185	ALB-ALB	AM	Hold for connecting train 449
448	BOS	97	FTI	110	FTI	62	SPG-WOR	CS	Train crew outlawed while trying to resolve a PTC issue in cp 45 interlocking 462, Control Point, 48
71	CLT	Trn Cancelled	TRS	188	TRS	188	DNC-DNC	NS	Trespasser strike Milepost, 54.6, 54.7
72	GRO	Trn Cancelled							
77	CLT	18	FTI	13	FTI	13	KAN-CLT	NS	Meet #NS28R, Control Point, Adams
90	NYP	32	FTI	60	FTI	35	RVR-XDJ	CS	Follow Milepost w/Letters, cfp15.5, cfp35.8, 418
97	MIA	274	TRS	240	TRS	240	ORL-KIS	FR	Trespasser strike Fatality, Milepost, 794.2, 794.2
98	NYP	34	FTI	65	FTI	31	JAX-JAX	CS	Meet #CSM79505, Control Point, NE JAX STA
56	SAB	41	CTI	38	CTI	21	NCR-BWI	AM	Follow, MARC, 612, Control Point, .
25	NOL	45	DSR	35	DSR	33	BAS-XNO	CS	Per dispatcher (radio/phone) Restricted speed for unknown reason, Milepost, 787.2, 789.5, 15, Main

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
5	EMY	380	FTI	249	FTI	156	GRA-GRA	UP	Hold due to freight derailment UP XXXX, Other, GSC-Grizzly	
6	CHI	270	FTI	228	FTI	130	GSC-GSC	UP	Hold due to freight derailment Milepost, 360.00, 360.00, UP 7964	
529	SJC	24	PTI	35	PTI	20	FMT-GAC	UP	Meet AMTK 530, Siding, South Albrae	
530	SAC	19	PTI	12	DSR	6	FMT-HAY	UP	Per bulletin Milepost, 26.25, 26, 60, m, Milepost, 22.38, 22.30, 15, m	
539	SJC	11	PTI	9	PTI	9	GAC-SCC	UP	Meet Amt538, Control Point, Co045	
542	SAC	28	MBO	20	MBO	20	MTZ-SUI	UP	For maritime traffic Control Point, SUISUN BRIDGE	
543	SJC	23	CTI	18	CTI	18	GAC-SCC	UP	Meet Ace, ACE 8, Control Point, CO044	
547	SJC	37	CON	16	CON	16	EMY-EMY	UP	Hold for connecting train 715	
51	CHI	51	DSR	63	DSR	22	CVS-STA	BB	Per bulletin Milepost, 187.5, 194.8, 25, 1, Milepost, 208.5, 214.1, 25, 1, Milepost, 214.1, 214.4, 10, 1	
503	EUG		WTR	31	WTR	13	ALY-EUG	UP	Heat order Level 2 heat restriction in effect on the entire Brooklyn Subdivision, timetable speed reduced to 50 MPH., Other, Brooklyn Subdivision	
504	PDX	18	DCS	18	DCS	12	ORC-PDX	UP	Restrictive signal(s) from unknown cause Stop, Control Point, CP770	
506	SEA	No OS Rpt	ENG	156	ENG	156	VAN-KEL	BN	Air / Brake Bad air compressor, BNSF 5244 added at Toteff. Bad brake pipe hoses needed to be replaced., WS1403	
507	EUG	-4	CON	66	CON	66	PDX-PDX	UP	Hold for thruway bus	
508	PDX	49	WTR	31	WTR	15	EUG-ALY	UP	Heat order Level 2 heat restriction in effect on the entire Brooklyn Subdivision, timetable speed reduced to 50 MPH., Other, Brooklyn Subdivision	
516	VAC	22	DSR	19	DSR	12	XF2-X1J	BN	Per bulletin Multiple 25 and 30, Milepost, 146, 151, 25, main	
517	VAN	25	DCS	17	DCS	17	TAC-XNI	ST	Restrictive signal(s) from unknown cause Stop, Control Point, CP 188	
518	VAC	31	DSR	18	DMW	10	MVW-BEL	BN	Waiting for MW clearance Milepost, 79.0, 81.2	
58	CHI	177	FTI	166	FTI	61	HMD-MCB	CC	Follow CN 2848, Siding, Natalbany, Control Point, signal 828	
59	NOL	76	CAR	110	CAR	110	CHI-CHI	AM	Set out defective car 37010	

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
14	PDX	193	RTE	93	CON	86	SAC-SAC	UP	Hold for connecting train 703
8	CHI	357	ITI	245	ITI	245	SEA-SEA	BN	Service, turn, or wye train 7
27	PDX	Trn Cancelled							
821	FTW	32	DSR	26	DSR	20	GLE-FTW	BN	Per bulletin Milepost, 401, 400.2, 25, M, Milepost, 396.3, 396.2, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 385.5, 385.3, 30, M, Milepost, 383.6, 383.4, 30, M, Milepost, 365.1, 364.7, 45, 1, Milepost, 357.6, 357.3, 29, 2, Milepost, 354.1, 353.7, 30, M, Milepost, 350.4, 350, 30, 1
822	OKC	45	FTI	43	FTI	34	FTW-GLE	BN	Meet bn, Siding, valley view
338	CHI	23	CTI	22	CTI	15	GLN-XWA	ME	Cross Traffic METRA, Control Point, A5, Control Point, A2
341	MKE	15	ENG	13	ENG	13	CHI-CHI	AM	Add engine oil to engine 518 mechanical showed up at train at 7:58 pm 518
354	PNT	64	PTI	46	PTI	32	KAL-KAL	MI	Meet amt355, Other, kal
355	CHI	33	FTI	38	FTI	19	XPI-HMI	NS	Follow NS UNKNOWN, Milepost, 494, 503
370	GRR	30	FTI	7	FTI	4	XH6-XPI	NS	Cross over or go around NS, Control Point, 485
566	SAN	44	SVS	16	SVS	16	LAX-LAX	SC	Water, commissary, toilet/trash dumping Other, 8 st yard
567	LAX	31	FTI	32	FTI	30	FUL-XRJ	BN	Meet BNSF La Mirada Local, Control Point, Basta
572	SAN	25	CTI	19	CTI	15	XRJ-FUL	BN	Meet metrolink, 612, Control Point, norwalk
573	LAX	37	FTI	18	FTI	10	OSD-X98	SN	Meet Bnsf 4127, Control Point, Pulgas
580	SAN	17	PTI	28	PTI	16	X98-OSD	SN	Meet Waiting on 639 Deadhead to the yard at Westbrook, SCRRA, Control Point, EASTBROOK
581	LAX	16	DSR	16	SYS	7	FUL-XRJ	BN	PTC problem or failure (cause unknown) PTC went disengaged leaving FUL station. Got it to engage, but held at restricted speed to signal at 1621, Other, 1621
584	SAN	42	CTI	28	PTI	18	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
770	SAN	20	PTI	35	PTI	19	SNC-SNP	SC	Meet Control Point, Serra, 573
774	SAN	24	PTI	33	PTI	10	SNC-SNP	SC	Meet 777, Control Point, serra

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
777	SLO	39	CTI	36	CTI	12	LAX-LAX	SC	Cross Traffic Crew was ready at 1526 but metrolink said no route available. Held station platform, Metrolink, 7 trains, Control Point, Terminal
786	SAN	47	CTI	48	SYS	33	SLO-SLO	UP	Other late crew
704	BFD	31	FTI	30	FTI	24	XEC-LOD	UP	Follow UP 8612, Milepost, 50, 80
713	OKJ	Trn Cancelled	TEN	180	TEN	153	MCD-TRK	BN	PTC - On Board Cab Signal or PTC Failure Lost load and PTC. Code D09. Reverser Wiring Faulty. Tried various troubleshooting measures per Patrick Osei and TASI, including removing and replacing MU and Comm cables, which required shutting off HEP. Measures did not work., C2002
714	BFD	36	PTI	42	FTI	14	SKN-SKN	BN	Meet FREIGHT CROSSING AT KEDDIE JCT., Control Point, KEDDIE JCT, bnsf, bn
715	OKJ	Trn Cancelled	SYS	93	SYS	71	MCD-TRK	BN	Blocked by or assisting another, disabled Amtrak train 713 rescued, Control Point, west ballico
716	BFD	22	DCS	30	DCS	20	WAC-BFD	BN	Power switch failure Hand to hand throw switch, Control Point, Bakersfield lead
717	OKJ	90	TRS	103	TRS	103	XPR-MTZ	UP	Trespasser strike Other, mp 37.7
3	LAX	161	FTI	207	FTI	114	KNG-NDL	BN	Blocked from station track Freight stopped on MT 4, blocking crossing we need to use to load passengers from MT 3. 4456's rear DPU was inoperable., Control Point, Needles, BNSF 4456 E, Manifest
4	CHI	101	FTI	131	WTR	53	LSV-RAT	BN	High winds Milepost, 769.8, 757, Milepost, 758, 706, Milepost, 707, 687, Milepost, 671, 659.8
21	SAS	No OS Rpt	TRS	309	TRS	309	XOJ-TAY	UP	Vehicle on track ahead First Track warrant authority was up to mp 915 stopped until further instructions due to fire truck stuck near tracks. Second track warrant mp 915-cpq918. Instruction were walking speed at mp 918.17., Milepost, 915, 918
22	CHI	123	TRS	108	TRS	108	DAL-MIN	UP	Vehicle strike Train 22 struck a vehicle that went around the crossing gates that were in a downward position at MP 191.37, Milepost, 191.37, 191.37
306	CHI	24	PTI	45	PTI	15	LCN-BNL	UP	Follow Amtrak 318, Milepost w/Letters, McLean Siding, BNL Station
307	STL	Trn Cancelled	DSR	7	DSR	7	SMT-XUD	CC	Per bulletin Milepost, 25, 26, 10, 1

Amtrak Endpoint OTP Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/6/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
382	CHI	28	FTI	31	FTI	16	QCY-MAC	BN	Meet bnsf6986, Siding, golden
383	QCY	48	POL	38	POL	38	NPV-PLO	BN	Removal of passenger by police
390	CHI	19	DSR	25	FTI	7	HMW-XCS	CC	Meet CN 2836, Control Point, 39th St
391	CDL	18	FTI	21	FTI	13	MAT-EFG	CC	Meet CN Grain train, Milepost w/Letters, Mp 193, Effingham
392	CHI	17	TRS	22	TRS	22	DQN-CEN	CC	Person walking on track ahead Control Point, duquoin
393	CDL	23	TRS	35	TRS	35	HMW-KKI	CC	TRESPASSER ON THE TRACK Control Point, 34
311	KCY	166	DBS	58	PTI	41	JEF-SED	UP	Meet Shuffle Meet At Centertown with Amtrak 318, 318 Had To Hand Line Through, Amtrak 318, Siding, Centertown
316	STL	105	ITI	68	ITI	68	KCY-KCY	KC	Service, turn, or wye train 311
318	CHI	178	WTR	57	WTR	29	JEF-HEM	UP	Flash flood warning Milepost, 127, 93

Amtrak Initial Terminal Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/6/2026

Terminal	Train	Date	Late	Delay	Cause
BON	683	08/06	3	3	Restrictive signal(s) from unknown cause STOP, Control Point, station track six
BOS	2159	08/06	22	22	Door, 3277 NG NS, 2159 will be delayed departing BOS for a door issue Door 2 has been cut out.
CLT	72	08/06	(Trn Cxld)		Trespasser Strike
CLT	80	08/06	2	2	Copy authority / restriction Restrictions showed up in PTC at departure time., Milepost, 376.0, 376.0
HAR	626	08/06	1	1	Passenger and/or baggage
HAR	656	08/06	3	3	Door, ENTIRE TRAIN
MIA	40	08/06	59	60	Service, turn, or wye train 4103, Inbound train arrived almost 12 hours late and needed to be serviced
NHV	486	08/06	5	5	Delay in Block, Departure time for 486 was changed to 20" earlier unbeknownst to CETC, MNR and NHV terminals. Delayed for all involved to get on the same page.
NYP	63	08/06	3	3	Meet, AM230, Other, NYP, HELD F/INBOUND AM230
NYP	69	08/06	7	7	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	08/06	22	22	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SYYD A/C NECESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND SERVICE CARS
NYP	129	08/06	4	4	Door, 81522 AX AN, DELAYED AT DEPARTURE A/C DELAYED A,134 OPR AHD IN "A" INT DUE TO SHOPPED CAR IN WASHINGTON
NYP	193	08/06	10	10	Service, turn, or wye train, 84, LATE TURN OFF AM84
NYP	243	08/06	16	16	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	245	08/06	6	6	Service, turn, or wye train, 68
NYP	655	08/06	10	10	Follow, AM2160, Other, LOOPS, CONGESTION ON LOOPS A/C AM2160 OPR EAST IN THE LOOPS
NYP	2113	08/06	3	3	Passenger and/or baggage, LOADING
NYP	2119	08/06	43	43	Service, turn, or wye train, 2108, LATE TURN OFF AM2108
NYP	2127	08/06	64	64	Other electrical failure, 2104 NG NP, LATE TURN OFF AM2116 DUE TO AM2118 BROKEN PANTOGRAPH
NYP	2131	08/06	87	87	Service, turn, or wye train, 2120, LATE TURN OFF AM2120
NYP	2190	08/06	11	11	Loading problem, 2124 NG NP, LATE FROM SSYD A/C MECHANICAL ISSUES
PHL	151	08/06	1	1	Passenger and/or baggage
PHL	601	08/06	3	3	PTC - Stop Bypass Permission Required, Control Point, .
PHL	605	08/06	1	1	Passenger and/or baggage
SPG	417	08/06	16	16	Service, turn, or wye train, 474, late turn of 474

Amtrak Initial Terminal Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/6/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	56	08/06	20	20	Other electrical failure, 616 EX ES, Catenary emergency plate
WAS	84	08/06	23	23	Set out defective locomotive, 609 EX ES, SHOPPED MTR 609 REPLACED WITH 669
WAS	134	08/06	48	48	Set out defective car, 82655 AX AS, SHOPPED CAR IN S&I CAUSED LATE RELEASE
WAS	184	08/06	23	23	HEP, 643 EX ES, MTR WENT INTO PTS WHILE GOING AROUND WYE
WAS	2112	08/06	11	11	Tilt Failure, 3214 LH LF, SHOPPED LEGACY SET 10
WAS	2120	08/06	30	30	Disabled train ahead, Other, NYP, LATE TURN OFF OF 2159. 2159(06) OPERATING 1'07" LATE AFTER UNSPECIFIED MECHANICAL ISSUES IN NYP, EQUIPMENT WILL TURN FOR TRAIN 2120(06)
WAS	2124	08/06	32	32	Disabled train ahead, Other, NYP, LATE TURN OFF INITIAL IB TRN 2119. 2119 (06) DEPARTED NYP 258PM-ET, OPERATING 43" LATE DUE TO THE NECESSARY EQUIPMENT SWAP
WAS	2152	08/06	17	17	Other electrical failure, 2035 LH LP, EMERGENCY POWER PLATE IN AFFECT FROM 1230AM TO 240AM
WAS	2158	08/06	5	5	HEP, 2016, #2107 legacy equipment 10 shopped thus a swap to #2109 equipment; short turn
WAS	2162	08/06	2	2	Door, 3372 NG ND
CHI	48	08/06	26	26	Dinning car refrigerators not working 68015
CHI	59	08/06	3	3	Air / Brake Head brake problem, 139
CHI	339	08/06	7	7	Service, turn, or wye train 338
CHI	341	08/06	13	13	Add engine oil to engine 518 mechanical showed up at train at 7:58 pm 518
KCY	316	08/06	68	68	Service, turn, or wye train 311
GTA	782	08/06	10	10	Meet 14, Control Point, CO 358
LAX	566	08/06	16	16	Water, commissary, toilet/trash dumping Other, 8 st yard
OKJ	712	08/06	3	3	PTC - Initializing PTC (no failure) Departed yard late, waiting for train 11 and 528 to do their station work., Other, Oakland Station
OKJ	718	08/06	(Trn Cxld)	200	Third Party Engine Failure
PDX	11	08/06	2		
PDX	503	08/06	6		
PDX	507	08/06	66	66	Hold for thruway bus
SAC	543	08/06	1	1	Door C8805, No door light—service door in cafe
SAC	547	08/06	1		
SAC	704	08/06	1	1	Door C9301, Door would not close via trainline. Had to walk length of train to close it locally.

Amtrak Initial Terminal Details

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/6/2026

Terminal	Train	Date	Late	Delay	Cause
SAN	785	08/06	1		
SEA	8	08/06	47	17	Fuel
SEA	8	08/06	47	30	Routine inspections
SEA	516	08/06	2	2	SEA station no check baggage due to short stuffing. Over 150 passengers got on with 2 plus luggages as carry on
SEA	518	08/06	21	4	Wait for station track amtk 8, Control Point, king street
SLO	786	08/06	33	33	Other late crew
SPK	27	08/04	(No OS)		

Eastern Region

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.3	98.3	342	1
CDOT	95.0	90	91.1	85.6	20	2
MARC	95.0	No Data	No Data	No Data	No Data	No Data
SEPTA	95.0	No Data	No Data	No Data	No Data	No Data
NJT-NED	95.0	96.6	94.9	88.4	354	12
NJT-SED	95.0	No Data	No Data	No Data	No Data	No Data

Operating Highlights

Train 93(06) South of Fredericksburg, VA - Freight Train Interference

07AUG26: Train 93(06), operating with engine 132, coaches, and 285 customers, was delayed 25 miles south of Fredericksburg, VA, on CSX Richmond Fredericksburg subdivision, due to following freight train M409 from milepost 340 to milepost 15.2.

Train	Delay	Comment
93(06)	32"	

Train 448(05) East of Pittsfield, MA - Freight Train Interference

07AUG26: Train 448(05), operating with engines 127/98, 5 coaches, 101 customers, was delayed 8 miles east of Pittsfield, MA, on CSX BERKSHIRE QB subdivision due to meeting CSX 425 at control point 140. Once the freight cleared and a route was mad available, train 448(05) was able to proceed.

Train 448(05) was further delayed 4 miles west of Worcester, MA, due to the same freight train crew running out of hours of service trying to resolve a PTC issue. Train 448(05) waited until the freight was recrewed and cleared.

Train	Delay	Comment
448(05)	1'02"	W/WOR
448(05)	48"	E/PIT

Train 175(06) West of New Haven, CT - Commuter Train Interference

06AUG26: Train 175(06), operating with engine 616/629, 10 coaches, and 586 customers, was delayed 11 miles west of New Haven, CT on MNCW New Haven Line, due to following a Metro Commuter train from milepost 60.1 TO milepost 41.

Train	Delay	Comment
175(06)	44"	

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

26-FOI-00544 00000008492 engine UNCLASSIFIED 705,8/7/2026

Train 171(06) North of Culpeper, VA - Tree Strike

06AUG26:

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train 171(06), operating with Engine 307, nine coaches, and approximately 305 passengers, was stopped north of Culpeper, VA at Milepost 66.2, on NS Alexandria-Montview subdivision, after striking a tree that had fallen onto the tracks. At the time of the incident, the engineer was performing the required running brake test when the train went into emergency. Although Head End Power (HEP) remained active, the crew was unable to recover the air system. After conducting a walking inspection of the train, the crew identified an air leak on the B-end of Coach 82625 and began troubleshooting the issue in coordination with CNOC Mechanical personnel. Amtrak Road Foreman (RFE) was dispatched to the scene with an estimated arrival time of one hour.

Upon arrival, RFE brought a run-around hose intended to bypass the affected equipment and resolve the air leak issue. If the hose installation had been required, Train 171(06) would have been restricted to operating at freight speeds. At that point, the train had accumulated a delay of 1 hour and 47 minutes.

Following further troubleshooting efforts, the crew successfully plugged the air leak on Coach 82625 and restored the train's brake system to 100 percent functionality. With full braking capability reestablished, Train 171(06) resumed normal operations and continued its route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
171(06)	2'52"	

Train 19(05) West of Meridian, MS - Freight Train Interference

06AUG26: Train 19(05), operating with 46/130, eight coaches, and 131 customers, was delayed 4 miles west of Meridian, MS, on NS NO&NE subdivision, due to meeting NSA59 at control point Flintco. Once the freight cleared and a route was made available, train 19(05) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(05)	30"	

Train 69(06) North of Rouses Point, NY - Customs and Immigration

06AUG26: Train 69(06) operating with engine 112, five coaches, and 169 customers was delayed at Canadian customs on CN Rouse Point subdivision at milepost 1.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
69(06)	40"	

Train 90(06) North of Richmond, VA - Freight Train Interference

06AUG26: Train 90(06), operating with engine 61, seven coaches and 244 customers, was delayed 10 miles north of Richmond, VA, on CSX Richmond Fredericksburg subdivision, due to following CSX418 from milepost 15.5 to milepost 35.8.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(06)	35"	

Train 178(06) Alexandria, VA - PTC Wayside Failure

06AUG26: Train 178(06) 26-FOF00644 00000008492 UNCLASSIFIED 339,877/2026 operating with locomotive 178, 5 cars and 300 customers onboard was delayed 6 miles west of Alexandria at MP 18 on the NS Hagerstown division due to a wayside PTC failure. Once the crew was able to secure PTC initialization train 178(06) was able to continue.

Train	Delay	Comment
178(06)	45"	

Train 64(06) East of Buffalo, NY - Freight Train Interference

06AUG26: train 64(06) operating with locomotive 64(06), 5 cars and 255 customers was delayed just after departing Buffalo at MP 431 on the CSX Buffalo Terminal subdivision for freight train interference following a CSX freight from MP 431 to MP 382. After the freight cleared the main line train 64(06) was able to continue without further delay.

Train	Delay	Comment
64(06)	39"	

Train 68(06) Rouses Point, NY - Freight Train Interference

06AUG26: train 68(06) operating with locomotive 118, 5 cars and 126 customers was delayed at the Rouses Point Station on the Cn Rouses Point subdivision due to freight train interference meeting 323-06 at the siding at St. Jean. After train 323-06 passed an open route was established at train 68(06) was able to proceed without further delay.

Train	Delay	Comment
68(06)	40"	

Train 68(06) South of St-Lambert, QC - Weather

06AUG26: Train 68(06) was delayed by Cn heat orders between MP2 and MP 42 on the Cn Rouses Point subdivision.

Train	Delay	Comment
68(06)	43"	

Train 600(06) Philadelphia, PA - Cab Car Failure

06AUG26: Train 600(06) operating with locomotive 668, 4 cars, cab car 9634 and 240 customers was delayed after departing Philadelphia due to needing to wye the train consist as a result of a bad wiper motor on cab car 9634. After the equipment was wyeed train 600(06) was able to continue to New York.

As a result of the bad wiper motor trains 600(06), 651(06) and 622(06) all needed to wye for the remainder of the taking associated delays when doing so.

Train	Delay	Comment
600(06)	39"	Wye at PHL
651(06)	07"	

Train 2159(06) Boston, MA - Initial terminal Delay - Mechanical

06AUG26: Next Gen Acela train 2159(06) operating with TS-28 was delayed at the initial terminal due to door issues with car number 3. HSR Mechanical responded and cut out the door to allow train 2159(06) to depart Boston.

Train 2159(06) was further delayed east of Norwalk due to a MOW hold for a defect repair. Once the hold was released train 2159(06) was able to continue toward Stamford.

Train 2159(06) was further delayed at New York due to unspecified mechanical requiring HSR Mechanical to respond and assist. Once NSR resolved the mechanical issues train 2159(06) was able to depart New York.

Train	Delay	Comment
2159(06)	22"	BOS Doors
2159(06)	22"	MOW Hold
2159(06)	26"	NYP Mechanical Assist

Train 2124(06) Washington, DC - Initial terminal Delay

06AUG26: Next gen Acela train 2124(06) was delayed at the initial terminal of Washington due to a late arrival of train 2119(06) operating with TS-10. After the train arrived the equipment was serviced and train 2124(06) was able to board their customers and depart Washington.

Train	Delay	Comment
2124(06)	32"	

Train 2120(06) Washington, DC - Initial Terminal Delay

06AUG26: Next Gen Acela train 2120(06) was delayed at the initial terminal of Washington due to a late arrival of train 2159(06) operating with Next Gen TS-28. Train 2159(06) was 1'00" late arriving into Washington, DC After the train arrived the equipment was serviced and train 2120(06) was ready to board the customers and depart Washington.

Train	Delay	Comment
2120(06)	30"	

Train 134(06) Washington, DC - Car Failure

06AUG26: Train 134(06) operating with locomotive 615, 10 cars and 326 customers was delayed at the initial terminal of Washington due to car 82655 shopping out needing replacement. Once the car was replaced and the necessary servicing and inspections were complete train 134(06) was positioned in the station, the 326 customers were boarded and train 134(06) was able to depart Washington.

Train	Delay	Comment
134(06)	48"	

Train 2119(06) New York, NY - Initial terminal Delay - Engine Failure

06AUG26: Next Gen Acela 2119(06) was delayed at the initial terminal of New York due inbound train 2108(06) TS-17 shopping out for parking brake issues requiring TS-10 to be utilized off the successful test run from Washington. Once the set was stocked and available for service the customers were boarded and train 2119(06) was able to depart New York.

Train	Delay	Comment
2119(06)	43"	

Train 2108(06) Philadelphia, PA - Engine Failure

06AUG26: Next Gen Acela 2108(06) operating with locomotives 330-381, 11 cars and 178 customers onboard was delayed 11 miles south of Philadelphia at MP 11 on the Amtrak PW Line after receiving a stuck parking brake fault on the trainset. The crew worked with HSR Mechanical and an onboard tech to de-prepare and re-prepare the trainset and were unable to resolve and release the parking brake. It was necessary to manually cut out the truck to allow the parking brake to release and proceed. After the brakes were fully released train 2108(06) was able to proceed toward Philadelphia.

Train	Delay	Comment
2108(06)	1'18"	

Train 97(05) South of Orlando, FL - Trespasser Incident

06AUG26: Train 97(05) operating with locomotives 330-381, 11 cars and 178 customers onboard was delayed 4 miles south of Orlando at MP 794 on the CFRC Orlando subdivision after striking a trespasser resulting in a confirmed fatality. The incident occurred on the No.2 track in the town of Pine Castle, Florida in Orange County and did not occur at a grade crossing. The weather was light rain and clear visibility. There were no reported injuries to crew or customers and there was no damage to equipment or infrastructure affecting operations. Local resources responded to the scene and an Amtrak Road Foreman and Trainmaster responded to help expedite the release of the scene. The engineer and conductor did request relief from their assignment at the scene and a recrew engineer was placed on duty at Sanford to report to the scene with a promotable assistant conductor onboard who stepped up to assume the conductor responsibilities. The Coroner and investigators released the scene at 6:26pm-et and train 97(05) was able to proceed after proper brake tests.

NRC Number: 1470008

National Response Center Number: 1470008

CSX Derailment Kanawha Subdivision, West of Charleston - Freight Train Interference

06AUG26: At 10:50 am-et CSX reported freight G229-03 derailed 17 loaded grain cars 3 miles west of Charleston, WV at MP 456.98 on the CSX Kanawha subdivision. The 17 cars were on their sides and bunched up accordion style across both main line tracks with no accessible route available. CSX contracted wrecking services responded to the scene at 5pm to begin restoration operations. CSX reports the repairs are extensive including 29 track panels, 450 ties, 4 switches to and 1 turnout needing replacement.

As a result of the damages, trains 50(06) and 51(07) are cancelled in their entirety with a non-revenue move replacing 50(06) between Chicago and Beach Grove to facilitate equipment movement needs.

Amtrak and CSX are continued to be engaged with status updates to repair plans and progress and will work to restore operations at the earliest opportunity.

Train 40(06) Miami, FL - Initial Terminal Delay

06AUG26: train 40(06) operating with locomotives 88-152, 11 cars and 62 customers onboard was delayed at the initial terminal of Miami due to a late arrival of inbound train 41(03) arriving Miami 11'54" late. After the train arrived, went through inspections and servicing the equipment was released and positioned in the station where 62 customers were boarded and train 40(06) was able to depart Miami.

Train	Delay	Comment
40(06)	59"	

CSX Heat Orders - Weather

06AUG26: CSX has imposed heat orders effective between 1pm and 7pm for the following subdivision: Baltimore Terminal, Capital, Cumberland, Metropolitan, Old Main Line, Peninsula, RF&P, Richmond Terminal and North End.

Train	Delay	Comment
53(06)	18"	
79(06)	1'00"	
80(06)	54"	
89(06)	43"	
90(06)	34"	
95(06)	20"	
125(06)	9"	
138(06)	28"	
171(06)	3"	
178(06)	6"	
186(06)	21"	

Train 71(06) East of Durham, NC - Trespasser Incident

06AUG26: Train 71(06) operating with locomotives, NC1894-NC1893-NC1755, 9 cars and 80 customers onboard was delayed just outside Durham Station at MP 54 on the NS Piedmont Division due to a trespasser strike. Train 71(06) struck a trespasser as it was approaching the Durham Station and came to a stop with only the locomotive on the station platform. This incident did not occur at a grade crossing and resulted in a non-fatal strike with the trespasser being transported to a local hospital for care. There were no injuries reported to the crew or customers and the crew did request relief at the scene. The strike did not result in damage to equipment or infrastructure that would impact operations. This incident did occur in the city of Durham, NC, in the county of Durham, with clear skies and an ambient temperature of 79 degrees. As a result of the trespasser strike, train 71(06) was terminated at Greensboro, NC and the equipment represented train 73(06) as previously planned with the customers remaining on the set and operating to their final destinations on the train 73(05) schedule. Alternate busing was secured for train 72(06) Charlotte to Greensboro and continuation Greensboro to Raleigh as planned due to scheduled trackwork.

NRC Number: 1469947

WBS#: B.TR.100150.7005

National Response Center Number: 1469947

Train	Delay	Comment
72(06)	Cancelled	
71(06)	Term GRO	
80(06)	1'01"	Holding west of DNC
71(06)	3'08"	DNC

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00644a 00000008492 in "UNCLASSIFIED" operation 18/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train 4(06) East of Barstow, CA - Freight Train Interference

07AUG26: Train 4(06) was delayed beginning at E. Pisgah /MP 705.2 on the BNSF Needles Subdivision, 40.6 miles east of Barstow, CA due to meeting BNSF8931 and freight cross traffic at Cadiz/ MP 647.2 and Ibis/ MP 592.2

Train	Delay	Comment
4(06)	36"	

Train 7/27(05) East of Havre, MT - Freight Train Interference

07AUG26: Train 7/27(05) was delayed at Chinook/ MP 408 on the BNSF Milk River Subdivision, 22.3 miles east of Havre, MT station due to meeting BNSF 7165.

Train	Delay	Comment
7/27(05)	34"	

Train 4(05) West of Garden City, KS - Signal

07AUG26: Train 4(05) was delayed beginning at MP443, 44.6 miles west of Garden City KS station on the BNSF La Junta subdivision due to restrictive signals. At the first signal crew had to wait for dispatcher to proceed through the signal. At the subsequent signals train 4(05) proceeded through at restricted speed. Train 4(05) resumed operating track speed at MP422 after they were clear of all the restrictive signals.

Train	Delay	Comment
4(05)	1'09"	

Train 58(06) South of Memphis, TN - Freight Train Interference

07AUG26: Train 58(06) was delayed beginning at MP5.5, 6.9 miles south of Memphis, TN station on the CN Shelby subdivision routing around freights. After train 58(06) routed around the trains at Y & MV junction/MP394.3 they had to line 5 switches.

Train	Delay	Comment
58(06)	37"	

Train 393(06) South of Homewood, IL - Trespasser Incident

07AUG26: Train 393(06) was delayed holding at MP31.8, 11.5 miles south of Homewood IL station on the CN Chicago subdivision due to a trespasser reported on the tracks ahead. Tracks were released and train 393(06) was back on the move at 531PM CT.

Train	Delay	Comment
393(06)	35"	

Train 506(06) North of Vancouver, WA - Engine Failure

07AUG26: Train 506(06) 5/481403 12 cars, 86 passengers onboard, was delayed 22.7 miles north of Vancouver, WA station, at MP113.8 on the BNSF Seattle Subdivision. Crew reported the Main Compressor on the engine shut down, with unrecoverable faults. Crew initially worked with CNOC mechanical and a Siemens technician in order to troubleshoot the issue. Unable to resolve, the decision was made to secure a freight locomotive from BNSF to rescue the train and continue. Once engine BN 5244 was identified, the train made an attempt to proceed toward Kalama where the freight was located, in order to minimize passengers delay. The train made it to MP109.2 before the compressor died again, and then remained there until the freight arrived. Once the BNSF locomotive was added ahead, and safety checks complete, Train 506(06) was able to proceed.

Train 506(06) was further delayed at Kent/ MP 16.1 on the BNSF Seattle Subdivision, where mechanical met the train in order to bad order the locomotive in trail.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
506(06)	2'36"	
506(06)	39"	Kent

Train 48/448(06) West of South Bend, IN - Freight Train Interference

07AUG26: Train 48/448(06) was delayed beginning at MP502, 65.3 miles west of South Bend IN. station on the Norfolk Southern Chicago 76 subdivision following Norfolk Southern Freight train 502(07).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448(06)	1'35"	

Train 717(06) East of Martinez, CA - Non-Fatal Trespasser Strike

07AUG26: At approximately 7:19PM-PT Train 717(06) operating westbound with E/C2103, 7 cars, and CC/C8309, struck a trespasser at MP 37.76 on the Union Pacific Railroad Tracy Subdivision, east of Martinez in Vine Hill, CA, in Contra Costa County. The incident did not occur at a crossing. Trespasser was a non-fatality and taken by EMS to the local hospital. There were no injuries reported to the crew or (90) passengers on board. Crew did request relief. Weather reported as 84 degrees and sunny. Local authorities responded to the scene. Once the investigation was complete, the train was released to continue to Martinez. Amtrak Police Notified.

National Response Center Number: 1470036

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
717(06)	1'43"	

Train 8/28(05) East Havre, MT - Passenger Train Interference

07AUG26: Train 8/28(05) was delayed at Havre East/MP427.4 on the BNSF Milk River Subdivision 2.9 miles east of Havre, MT station, due to meeting Train 7/27(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(05)	38"	

Train 822(06) South of Gainesville, TX - Freight Train Interference

07AUG26: Train 822(06) was delayed holding at MP401.3, 9.30 miles south of Gainesville TX. station on the BNSF Fort Worth subdivision meeting BNSF Freight train Z WSPALT3 05U. Train 822(06) was back on the move at 710PM CT after the freight cleared.

Train 11(06) North of Eugene, OR - Freight Train Interference

07AUG26: Train 11(06) was delayed beginning at Eugene station on the UPRR Brooklyn Subdivision, 0.3 miles north of Eugene, OR station, due to being blocked from going into the station by UP 7780. Once freight cleared the route, Train 11(06) was able to proceed into Eugene station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(06)	32"	

Train 5(05) East of Grand Junction, CO - Heat Order

06AUG26: Train 5(05) was delayed beginning at MP371, 79.20 miles east of Grand Junction, CO. station on the UPRR Glenwood Springs subdivision operating through heat orders until MP391.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(05)	1'01"	

Train 22(06) Marshall, TX - Freight Train Interference

06AUG26: Train 22(06) was delayed holding at Marshall TX station on the UPRR Little Rock subdivision due to UPRR freight train 5680 stopped ahead at Woodland/MP59.5 with a distributed power unit failure. UPRR management arrived on scene to assist the crew with splitting the train. Once the train was split the train was pulled into the siding at Jefferson/MP51.1 to clear a route for train 22(06). Train 22(06) departed Marshall TX station at 932PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(06)	1'49"	

Train 383(06) East of Plano, IL - Police Related

06AUG26: Train 383(06) was delayed holding at MP40.2, 11.52 miles east of Plano IL station on the BNSF Chicago subdivision meeting local police to remove an unruly passengers. Train 383(06) was back on the move at 730PM CT after the police removed the passenger and questioned witnesses to the incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(06)	38"	

Train 1(05)/421(04) East of Deming, NM - Heat Orders

06AUG26: Train 1(05)/421(04) were delayed beginning at MP1257.9, 51.8 miles east of Deming, TX station on the UPRR Lordsburg subdivision operating through heat orders until MP50.2.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(05)/421(04)	39"	

Train 19(05) North of Laurel, MS - Freight Train Interference

06AUG26: Train 19(05) was delayed holding at MP3.2 north of Laurel MS. station on the Norfolk Southern NO and NE subdivision for a meet with Norfolk Southern freight train A59.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 5(05) East of Glenwood Springs, CO - Passenger Train Interference

06AUG26: Train 5(05) was delayed holding at Eutaw siding/MP346.9, 1.40 miles east of Glenwood Springs, CO. station on the UPRR Glenwood Springs subdivision for a meet with Amtrak train 6(05). Train 5(05) was back on the move at 309PM MT after train 6(05) cleared to the east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(05)	52"	

Train 11(06) South of Portland, OR - Sick Passenger

06AUG26: Train 11(06) was delayed at Oregon City station stop, MP 756.4 on the UPRR Brooklyn Subdivision, 14.6 miles south of Portland, OR station, due to waiting for EMS to meet the train for a passenger onboard reportedly having a seizure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(06)	30"	

Train 8(06) Seattle, WA - Servicing

06AUG26: Train 8(06) was delayed departing Seattle, WA due to a delay in fueling the locomotives account of ongoing construction. Once the train was able to fuel, they then proceeded to the station to load 86 customers prior to departing.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(06)	47"	

Train 11(06) North of Salem, OR - Vehicle on Tracks

06AUG26: Train 11(06) was delayed at Coalca / MP751.9 on the UPRR Brooklyn Subdivision, 33.6 miles north of Salem, OR station, due to a vehicle on the tracks at MP745.19. Once the vehicle was removed and tracks inspected, Train 11(06) was able to proceed south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(06)	1'33"	

Train 19(05) North of Meridian, MS - Freight Train Interference

06AUG26: Train 19(05) was delayed holding at Eutaw siding/MP232.5, north of Meridian MS station on the Norfolk Southern AGS South subdivision due to a meet with train 20(06).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(05)	34"	

Train 6(04) East of Ottumwa, IA - Customer Medical Emergency

06AUG26: Train 6(04) was delayed 24.5 miles east of Ottumwa, IA (MP279.8), on the BNSF Ottumwa Subdivision, at Fairfield (MP255.3), to meet EMS for a customer medical emergency. The customer was experiencing difficulty breathing and was evaluated by EMS. After being examined, the customer was cleared to continue to their final destination.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	33"	

Train 1(05)/421(04) East of El Paso, TX - Customer Medical Emergency

06AUG26: Train 1(05)/421(04) was delayed 40 minutes east of El Paso, TX (MP1296.0), on the UPRR Valentine Subdivision, at Tornillo (MP794.9), to meet EMS for a customer medical emergency. EMS responded and transported the customer for observation. After the police hold was released, additional delay was incurred while waiting for eastbound UP 5713 to clear before westward movement could resume.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(05)/421(04)	40"	

Train 58(06) North of McComb, MS - Freight Train Interference

06AUG26: Train 58(06) was stopped 5.2 miles north of McComb, MS (MP806.9) on the CNRR McComb Subdivision at Summit Jct (MP801.7) due to a disabled freight train ahead. CN C73891-05 experienced a broken wheel at MP797.5 and operated at walking speed 2 miles south to MP799 to perform a setout of the bad order car. A carman responded to assist the freight crew with the setout. Upon completion of the repair and setout operation, Train 58(06) was released to continue north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(06)	4'07"	

Train 713(06) Merced, CA - Third Party Contractor Engine Failure

06AUG26: Train 713(06), E/C2002-5 cars-CC/C8306, was delayed departing Merced, CA on the BNSF Stockton Subdivision due to locomotive issues on E/C2002. Upon inspecting the crew found faulty reverser wiring on E/C2002. The crew worked to resolve the issue with an Amtrak Road foreman and mechanical assistance. After performing a system reboot, the crew was able to login and restore tractive effort. Once all issues were resolved, Train 713(06) departed Merced.

Train 713(06) was further delayed at MP 1072.2 due to the same issue. The crew held while the Amtrak Road foreman responded to location to help troubleshoot. During this time, the train did lose head-end power for approximately 15 minutes. Unable to fully resolve the issue, the decision was made to couple the equipment to Train 715(06). Once equipment was coupled, the train continued to operate as a double-set into Emeryville where the combination train was terminated in order to bring the equipment into Oakland Maintenance Facility. Passengers destined Oakland were accommodated on 547(06) that was held at Emeryville for the train to arrive.

As a result, Train 718(06) was originated out of Emeryville and all passengers were accommodated on Train 544(06) between OKJ-EMY.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(06)	27"	MCD
715(06)	1'33"	Terminated EMY
713(06)	2'33"	Terminated EMY
547(06)	16"	EMY- 715/713 pax to OKJ
718(06)	3'22"	Originated EMY

Train 786(06) San Luis Obispo, CA - Crew Issue

06AUG26: Train 786(06), CC/C6951-5 cars-E/C2112 with 54 customers on board, was delayed departing San Luis Obispo, CA due to a crew issue. The conductor and assistant conductor held while an engineer was sourced to operate from San Luis Obispo to Los Angeles. Once the engineer arrived, the crew performed a job briefing and Train 786(06) was able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(06)	33"	

Train 5(04) East of Elko, NV - Heat Restrictions

06AUG26: Train 5(04) was delayed starting at Whirlwind/MP 612 to MP 291 on the UPRR Elko Subdivision due to heat restrictions placed on the UPRR Elko and Nevada Subdivisions. Due to the extreme heat, the UPRR placed 50 mph speed restrictions on the Elko and Nevada Subdivisions. Once through the affected area, the crew proceeded west at track speed. Train 6(06) was also delayed operating reduced speeds account of heat restrictions between MP249.38 and MP421.26

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(04)	1'28"	
6(06)	1'03"	

Train 5(04) East of Elko, NV - Signal Issues

06AUG26: Train 5(04) was delayed starting at Whirlwind/MP 612 on the UPRR Elko Subdivision due to signal issues. The crew was delayed flagging through signal issues from MP 612 to MP 627. Once through affected area, Train 5(04) proceeded at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(04)	36"	

Train 14(05) Klamath Falls, OR - Disabled Freight

06AUG26: Train 14(05) was delayed starting at MP 429.5/ Klamath Falls, OR due to disabled UP6409 ahead at Fields/MP 555.6. The UPRR dispatcher held them in Klamath Falls for disposition due to the disabled freight. Once a plan was in place to hold Train 14(05) in Chemult, OR, they were able to depart Klamath Falls.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(05)	43"	KFS

Train 567(06) West of Fullerton, CA - Freight Train Interference

06AUG26: Train 567(06) was delayed at Basta/ MP 163.0, 2 miles west of Fullerton, CA, on the BNSF San Bernardino Subdivision due to freight interference. The crew held for a local BNSF freight to clear route. Once route was clear, Train 567(06) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
567(06)	30"	

Train 7(04) East of Everett, WA - Freight Train Interference

06AUG26: Train 7(04) was delayed at MP 1756.5, 26 miles east of Everett, WA, on the BNSF Scenic Subdivision due to meet with BN6417 with locomotive issues. The crew held while freight crew worked to resolve issues. Due to the delay holding for the disabled freight, Train 7(04) was further delayed holding at MP 1756.5 for an engineer recrew due to a bad meet with the unexpected delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(04)	45"	

Train 2/422(05) West of Maricopa, AZ - Broken Rail

06AUG26: Train 2/422(05) was delayed starting at MP 847.50 miles west of Maricopa, AZ, on the UPRR Gila Subdivision due to a broken rail at MP 854.0. The crew was delayed flagging through area starting at at MP 847 until MP 854.0. Once through the affected area, Train 2/422(05) proceeded east at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(05)	40"	

Train 8/28(05) West of Whitefish, MT - Freight Train Interference

06AUG26: Train 8/28(05) was delayed starting at MP 1232.9, 13 miles west of Whitefish, MT, on the BNSF Kootenai Subdivision due to a broken rail. The freight crew BN7378 was expired on hours of service due to holding for the broken rail. The crew on Train 8/28(05) held while the freight crew was recreated and BNSF personnel worked to bar the broken rail. Once the freight train was recreated and the rail was barred, Train 8/28(05) followed BN7378 until Whitefish/MP 1219.2 where it was able to operate around.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(05)	1'16"	

Train 22(05) North of Arcadia, MO - M of W Work

06AUG26: Train 22(05) was delayed beginning 12.8 miles north of Arcadia, MO (MP88.8) on the UPRR Desoto Subdivision while following track inspectors between MP76 and MP43. The track inspectors were conducting flash flood inspections of the area following earlier severe weather conditions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(05)	51"	

Train 5(04) East of Elko, NV - Freight Train Interference

06AUG26: Train 5(04) was delayed at MP 603.9, 63 miles east of Elko, NV, on the UPRR Lakeside Subdivision due to freight interference. The crew held for UP7815 to clear route. Once route was clear, Train 5(04) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(04)	37"	

Train 3(04) East of Needles, CA - Freight Train Interference

06AUG26: Train 3(04) was delayed at MP 577.2, 1 miles east of Needles, CA, on the BNSF Seligman Subdivision due to freight interference. BN4456 was experiencing mechanical issues ahead with inoperable rear DPU blocking access to station. The crew on Train 3(04) held while the BN freight crew worked to resolve issue and clear crossing. Once the route was clear, Train 3(04) proceeded into station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(04)	1'54"	

Train 311(06) West of Kirkwood, MO - Weather

06AUG26: Train 311(06) was delayed beginning 28.6 miles west of Kirkwood, MO (MP13.4) on the UPRR Jefferson City Subdivision due to flash flood warnings in effect from MP46 to MP101. While operating through the warning area, Train 311(06), E/ID4609-7 Cars, struck a tree at 9:35AM-CT at MP50.3, approximately 1.5 miles east of Washington, MO (MP51.8). The impact caused a main reservoir and brake pipe separation between cars 48164 and ID4020. The crew repaired the affected hoses while HEP remained intermittent during the work. There were 106 customers onboard in 70-degree rainy conditions. Upon completion of repairs, air was restored, no injuries or equipment damage were reported, and Train 311(06) resumed westward movement at 9:55AM-CT.

Additional delay occurred at MP90.0, 8.9 miles west of Hermann, MO (MP81.1), when the train was held due to a reported large tree obstructing the track ahead. Maintenance of Way personnel already working in the area responded and removed the obstruction, after which Train 311(06) was released to continue westward.

Further delay occurred at Centertown (MP140.2), 14.7 miles west of Jefferson City, MO (MP125.5), on the Sedalia Subdivision while meeting Train 318(06). Flash flood warnings between MP149 and MP93 required both trains to operate at reduced speed through the affected territory. Train 318(06) hand-lined the switch to proceed eastward, and after Train 318(06) cleared, Train 311(06) reversed out of the siding and continued westward.

Train 316(06) was delayed departing Kansas City, MO (MP6.9), on the KCY Kansas City Terminal Subdivision, due to a late turn of Train 311(06)'s equipment that arrived at XXXXX, XX hours and XX minutes late.

Train	Delay	Comment
311(06)	25"	Tree Strike
311(06)	33"	Tree on Tracks W/HEM
311(06)	41"	Centertown
318(06)	15"	Centertown
311(06)	10"	Flash Flood MP128-MP149
311(06)	30"	Flash Flood Warning MP46-MP101
318(06)	57"	Flash Floods MP149-MP93
316(06)	1'08"	Late Turn 311(06)

Train 7/27(05) Grand Forks, ND - Passenger Train Interference

06AUG26: Train 7/27(05) held 13.6 miles west of Grand Forks, ND (MP97.9), on the BNSF Devils Lake Subdivision, at Emerado (MP13.6) in order to meet Train 8/28(04).

Train	Delay	Comment
7/27(05)	57"	

Train 3(05) West of Hutchinson, KS - Signal

06AUG26: Train 3(05) was delayed beginning 68 miles west of Hutchinson, KS (MP218.1) on the BNSF La Junta Subdivision due to a signal failure at Belpre (MP286.1). Operating speeds were restricted until a clear signal was received at MP293. Additional signal issues were encountered at Kinsley (MP318.4), resulting in further speed restrictions until a clear signal was reached at Offerle (MP323.4).

Train	Delay	Comment
3(05)	31"	West Kinsley
3(05)	27"	West Belpre

Train 2/422(05) Los Angeles, CA - Hold for Connection

06AUG26: Train 2/422(05) was delayed departing Los Angeles, CA holding for connecting passengers off late 11(04) that arrived 3 hours and 38 minutes late.

Train 1(05)/421(04) San Antonio, TX - Car Failure

06AUG26: Train 1(05)/421(04) was delayed at San Antonio, TX station/MP209.5 on the UPRR Del Rio Subdivision due to a broken knuckle between cars 33037 and 31041. San Antonio personnel responded and replaced the broken knuckle. Once repairs were complete, Train 1(05)/421(04) departed San Antonio, TX station at 4:11AM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(05)/421(04)	1'26"	

Train 3(06) West of Newton, KS - Engine Failure

07AUG26: Train 3(06) was delayed at MP58.3, 132.4 miles west of Newton, KS station on the BNSF Topeka subdivision due to main reservoir issues on lead engine 167. Crew worked with CNOC mechanical to attempt repairs but were unsuccessful. BNSF rapid responders were requested and arrived on scene at 137AM CT. Rapid responders extracted threads from the old pop valve but were unable to repair the reservoir. Kansas City mechanical arrived on scene at approximately 320AM CT to assist with repairs. Repairs were complete at 235AM CT but crew had issues with cab signal when attempting to depart. Crew called in and spoke with CNOC mechanical to troubleshoot the issues. Cab signals issues were resolved at 257AM CT and train 3(06) was back on the move at 314AM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(06)	3'27"	

UPRR Freight Derailment East of Glenwood Springs, CO - California Zephyr Service

05AUG26: Approximately 530AM-MT, UPRR reported MGJNY-04 (UP 7964) with 5 locos, 33 loads and 51 empties, derailed one axle on the 38th car, an empty, at MP359, just east of Glenwood Springs, CO, on the UPRR Glenwood Springs Subdivision. UPRR management and track/car departments were estimated to arrive on site at 830AM-MT. Initial estimate for open track was between 300PM-MT and 500PM-MT. Train 6(04), with 217 customers, was delayed at Glenwood Springs/MP360.1 holding for open route ahead. Train 5(04), with 242 customers, was delayed at Granby, CO/MP75.8, 75 miles west of Denver, CO, on the UPRR Moffat Tunnel Subdivision, holding at the depot for approximately two hours and then advanced towards derailment location to be in position for open route.

06AUG26: Train 6(06) was delayed departing Winnemucca, NV holding for crew rest. Train 5(04) arrived into Winnemucca at 11:43A, 5 hours and 56 minutes late. Train 6(06) held until the crew signed up on rest at 7:58P.

WBS#: B.TR.100150.6998

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	2'10"	GSC
5(04)	2'36"	GRA
6(06)	52"	WNN- Recrew

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

Pere Marquette:

- Train 370(04) cancelled entirely, with alternate transportation between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with alternate transportation between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with alternate transportation between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with alternate transportation between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with alternate transportation between Pontiac, MI and Chicago, IL.

06AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

Pere Marquette:

- Train 370(07,09) cancelled entirely, with alternate transportation between Chicago, IL and Grand Rapids, MI.
- Train 371(08,10) cancelled entirely, with alternate transportation between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(08) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with alternate transportation between St. Louis and Chicago.

Wolverine Service:

- Train 351(07) cancelled entirely, with alternate transportation between Pontiac, MI. and Chicago, IL.

Quincy Service:

- Train 381(10) cancelled entirely, with alternate transportation between Chicago, IL. and Quincy, IL.
- Train 382(10) cancelled entirely with alternate transportation between Quincy, IL and Chicago IL.

WBS#: B.TR.100150.6992

Train	Delay	Comment
370(04)	Cancelled	
371(05)	Cancelled	
305(05)	Cancelled	
302(06)	Cancelled	
352(06)	Cancelled	
351(07)	Cancelled	

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Fire fighting operations and personnel

at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04-10) Cancelled entirely, No alternate Transportation.
- Train 502 (04-10) Cancelled entirely. With alternate transportation.
- Train 504 (04-10) Will terminate in Portland, OR. With alternate transportation.
- Train 518 (04-07) Originates at Seattle, WA. 518 (08-10) Originates Vancouver, WA All with alternate transportation.
- Train 517 (04-10) Will terminate in Vancouver, WA. No alternate Transportation.
- Train 506 (04-10) Originates in Vancouver, WA. No alternate Transportation.
- Train 508 (04-10) Will terminate Portland, OR. With alternate transportation.
- Train 503 (04-10) Originates Portland, OR. With alternate transportation.
- Train 505 (04-07) Cancelled entirely. With alternate transportation. 505 (08-10) Will Terminate in Vancouver, WA, no alternate transportation.
- Train 507 (04-10) Originates Portland, OR. With alternate transportation.
- Train 509 (04-10) Cancelled entirely, with alternate transportation.
- Train 511 (04-10) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-08) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-10) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

- Train 14 (04-09) Will Terminate at Portland, OR, no alternate transportation provided.
- Train 11 (05-10) Will Originate at Portland, OR, no alternate transportation provided.

Train	Delay	Comment
507(02)	1'41"	bus VAN-PDX
506(02)	Canceled	
508(02)	45"	bus PDX-VAN
509(02)	77"	couple 509-511(02) "UNCLASSIFIED"
509(02)	75"	Detour through UP yard
511(02)	76"	Detour through UP yard
500(03)	Canceled	
502(03)	Canceled	
511(03)	Canceled	
505(03)	Canceled	
518(03)	Canceled	between SEA-PDX
507(03)	Canceled	between SEA-PDX
508(03)	Term PDX	
504(03)	Term PDX	
509(03)	Canceled	
517(03)	Term VAN	
506(03)	Orig VAN	
503(03)	24"	canceled SEA-PDX
507(03)	1'10"	waiting for bus at PDX
14(02)	58"	detour
11(03)	51"	detour
14(04)	term PDX	
506(04)	1'03"	wait for inbound bus
518(04)	1'27"	wait for inbound bus
507(05)	1'09"	PDX- wait for inbound bus
507(06)	1'06"	PDX- inbound bus

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26-FBI-00044 00000008482 "UNCLASSIFIED" 8/7/2023

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

-Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

-Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00644 00000008492 "UNCLASSIFIED" 8/7/2026racked scheduled C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (4)	SEA	BNSF3929	Air compressor E/193	chi	8/6/26
506 (6)	XRS	BNSF5244	Multiple faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00644

00000008492

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
392 (06)	CDL	392 WILL BE OPERATING WITHOUT FOOD SERVICE, DUE TO 35005 BEING SHOPPED. PLEASE NOTIFY PAX	n/a	0	35005
391 (06)	CHI	391 WILL BE OPERATING WITHOUT FOOD SERVICE, DUE TO 35005 BEING SHOPPED. PLEASE NOTIFY PAX	n/a	0	35005
2190 (06)	NYP	OPERATING NEX GEN EQUIPMENT IN LIEU OF LEGACY SET.	No data	0	
97 (05)	NYP	used AM 1 coach in lieu of AM 2 coach due to bad orders - no passenger impoact	no impacted pax	0	82612
785 (06)	SAN	DUE TO USE OF CAR 90215, THERE WILL BE NO BIKE SPACE AVAILABLE.	Passengers notified	2	90215
518 (06)	SEA	Due to 12-hr late inbound talgo set plus multiple defects needing to be addressed, 518(06) will operate with Amfleet set. Y/JY/IY/ZY reduced. heavily overcapacity. 4th coach unavailable for overflow.	no impacted pax car added	0	AMFLEET SET
774 (06)	SLO	DUE TO USE OF CAR 90215, THERE WILL BE NO BIKE SPACE AVAILABLE.	Passengers notified	3	90215
517 (07)	VAC	3-coach amfleet in lieu of talgo set. Y/JY/IY/ZY reduced.	NO IM PACTED PAX	0	AMFLEET SET

Reverse Consists

Train Number	Station	Reason
193 (05)	NYP	Consist reversed Business class seat orientation may have changed At Rear
197 (06)	NYP	Consist reversed Business class seat orientation may have changed At Rear
94 (07)	NFK	Consist reversed Business class seat orientation may have changed At Front
95 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
113 (06)	NYP	Consist reversed Business class seat orientation may have changed At Rear

Train Number	Station	Reason	
		26-FOI-00644	00000008492 "UNCLASSIFIED" 8/7/2026
93 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front	
138 (07)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 138(07)**	
111 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front	
190 (06)	PHL	Consist reversed Business class seat orientation may have changed At Front	
110 (06)	PHL	Consist reversed Business class seat orientation may have changed At Rear	
185 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front	
86 (07)	NPN	Consist reversed Business class seat orientation may have changed At Front	
174 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front	
84 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front	
193 (06)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
182 (06)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
129 (06)	NYP	Consist reversed Business class seat orientation may have changed At Front	