

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, August 08, 2026

Rules: 0-45



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/07/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	316	66	79.1%	2,148	363	83.1%	93,020	12,907	86.1%
Central Division	86.0%	55	8	85.5%	381	49	87.1%	17,737	1,615	90.9%
East Division	82.0%	174	36	79.3%	1,177	187	84.1%	48,847	7,605	84.4%
West Division	86.0%	87	22	74.7%	590	127	78.5%	26,436	3,687	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00671 00000008702 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/7/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	115,057	42,781	63%	765,887	234,007	69%	31,098,885	7,875,357	75%
Northeast Corridor	81%	50,382	17,287	66%	330,188	84,812	74%	13,631,701	3,340,840	75%
Acela	83%	12,470	2,748	78%	71,272	16,282	77%	2,731,696	717,833	74%
Northeast Regional	79%	37,912	14,539	62%	258,916	68,530	74%	10,900,005	2,623,007	76%
Richmond / Newport News / Norfolk	77%	11,702	6,179	47%	81,134	29,953	63%	3,381,110	991,414	71%
Springfield Shuttles	89%	892	362	59%	4,855	799	84%	192,582	30,667	84%
Roanoke	79%	4,103	1,882	54%	24,442	5,734	77%	1,029,726	224,390	78%
On Spine Northeast Regional	80%	21,215	6,116	71%	148,485	32,044	78%	6,296,587	1,376,536	78%
State Supported	80%	51,543	16,691	68%	344,701	94,851	72%	13,654,320	2,900,776	79%
Borealis	80%	644	202	69%	4,224	670	84%	173,850	36,302	79%
Capitol Corridor	90%	3,610	635	82%	26,211	4,859	81%	1,141,930	150,608	87%
Carolinian	70%	1,227	893	27%	7,724	3,846	50%	352,606	138,845	61%
Cascades	75%	1,409	755	46%	12,889	6,657	48%	796,139	221,693	72%
Downeaster	82%	2,152	216	90%	14,542	633	96%	474,855	56,588	88%
Empire	78%	6,805	3,304	51%	45,363	15,657	65%	1,689,076	399,116	76%
Adirondack	72%	486	417	14%	3,240	1,397	57%	103,203	32,242	69%
Ethan Allen Express	70%	661	324	51%	4,293	2,519	41%	173,201	62,868	64%
Maple Leaf	70%	900	64	93%	6,434	2,669	59%	206,783	79,512	62%
New York - Albany	85%	2,649	545	79%	20,071	5,202	74%	782,419	131,129	83%
New York - Niagara Falls	75%	1,541	1,394	10%	10,158	2,717	73%	414,190	88,398	79%
Berkshire Flyer	60%	568	560	1%	1,167	1,153	1%	9,280	4,967	46%
Gold Runner	73%	2,611	1,631	38%	17,775	10,205	43%	773,341	280,658	64%
Heartland Flyer	70%	316	215	32%	1,988	1,720	13%	66,671	27,142	59%
Hiawatha	90%	2,292	292	87%	14,901	1,141	92%	535,820	58,838	89%
Illinois	78%	3,113	1,345	57%	18,436	6,117	67%	764,660	210,672	72%
Carl Sandburg / Illinois Zephyr	85%	512	231	55%	2,749	1,283	53%	127,549	35,441	72%
Illini / Saluki	85%	1,019	105	90%	6,114	2,345	62%	266,001	64,245	76%
Lincoln Service	70%	1,582	1,009	36%	9,573	2,489	74%	371,110	110,986	70%
Keystone	92%	8,944	598	93%	57,393	3,272	94%	2,339,512	242,818	90%
Lincoln / Missouri	70%	976	431	56%	6,309	3,738	41%	238,800	122,046	49%
Mardi Gras Service	80%	205	5	98%	2,478	755	70%	126,199	28,370	78%
Michigan	70%	2,037	289	86%	17,216	7,821	55%	614,641	200,242	67%
Blue Water	70%	309	0	100%	3,873	2,263	42%	143,531	58,091	60%
Pere Marquette	85%	203	0	100%	2,073	176	92%	80,507	15,300	81%
Wolverine	70%	1,525	289	81%	11,270	5,382	52%	390,603	126,851	68%
Missouri	80%	319	0	100%	2,094	765	63%	67,930	17,201	75%
Pacific Surfliner	85%	11,572	5,108	56%	73,510	20,198	73%	2,485,682	449,905	82%
Pennsylvanian	80%	958	15	98%	6,058	1,449	76%	271,860	52,526	81%
Piedmont	80%	1,240	248	80%	6,371	1,061	83%	346,645	89,713	74%
Vermont	75%	1,113	509	54%	9,219	4,287	53%	394,103	117,493	70%
Long Distance	70%	13,132	8,803	33%	90,998	54,344	40%	3,773,597	1,631,278	57%
Auto Train	70%	830	466	44%	6,022	1,383	77%	240,431	82,172	66%
California Zephyr	70%	1,102	949	14%	7,230	5,518	24%	298,824	112,175	62%
Cardinal	70%	0	0	-	1,483	890	40%	72,964	36,433	50%
City Of New Orleans	75%	687	293	57%	4,515	3,442	24%	195,739	61,621	69%
Coast Starlight	70%	924	850	8%	7,808	4,789	39%	352,485	125,251	64%
Crescent	70%	863	94	89%	6,114	914	85%	285,767	86,897	70%
Empire Builder	70%	1,001	693	31%	6,833	5,452	20%	295,200	147,657	50%
Floridian	60%	1,742	1,539	12%	12,115	9,232	24%	489,881	336,274	31%
Lake Shore Ltd	73%	1,258	651	48%	8,444	3,534	58%	295,681	88,640	70%
Palmetto	70%	829	659	21%	6,753	3,396	50%	282,856	86,005	70%
Silver Meteor	70%	1,035	390	62%	7,047	4,796	32%	312,247	142,147	54%
Southwest Chief	60%	1,012	1,009	0%	7,261	5,521	24%	257,727	168,114	35%
Sunset Ltd	70%	369	260	30%	1,350	957	29%	89,716	33,725	62%
Texas Eagle	70%	1,480	950	36%	8,023	4,520	44%	304,079	124,167	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 00000000702 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 07, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	47,241	748,804	631	1,837,320	32,696,742	562

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,316	229,214	101	88,228	9,426,216	94
INFRASTRUCTURE PLANNED	135	3,605	229,214	157	99,660	9,426,216	106
FLEET RELIABILITY	90	7,293	748,804	97	293,433	32,696,742	90
TRAIN OPERATIONS	424	34,027	748,804	454	1,355,999	32,696,742	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/07/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	316	66	79.1%	2,148	363	83.1%	93,020	12,907	86.1%
Central Division	86.0%	55	8	85.5%	381	49	87.1%	17,737	1,615	90.9%
East Division	82.0%	174	36	79.3%	1,177	187	84.1%	48,847	7,605	84.4%
West Division	86.0%	87	22	74.7%	590	127	78.5%	26,436	3,687	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/07/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	316	66	79.1%	2,148	363	83.1%	93,020	12,907	86.1%
Central Division	86.0%	55	8	85.5%	381	49	87.1%	17,737	1,615	90.9%
CDL	95.0%	2	0	100.0%	14	2	85.7%	590	27	95.4%
CHI	86.0%	26	5	80.8%	176	31	82.4%	8,190	995	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	7	0	100.0%	334	36	89.2%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	6	0	100.0%	294	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	7	2	71.4%	564	44	92.2%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	2	66.7%	40	3	92.5%	1,820	117	93.6%
MOE	97.5%	2	0	100.0%	14	0	100.0%	619	9	98.5%
MSP	96.5%	1	0	100.0%	7	1	85.7%	304	7	97.7%
NOL	94.5%	4	0	100.0%	31	0	100.0%	1,304	60	95.4%
OKC	97.0%	1	0	100.0%	7	0	100.0%	305	6	98.0%
PNT	88.0%	2	0	100.0%	20	2	90.0%	807	66	91.8%
PTH	93.0%	1	0	100.0%	7	1	85.7%	299	12	96.0%
QCY	91.0%	2	0	100.0%	11	1	90.9%	588	44	92.5%
SAS	90.5%	1	1	0.0%	7	2	71.4%	308	35	88.6%
STL	89.0%	4	0	100.0%	26	3	88.5%	1,195	100	91.6%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	174	36	79.3%	1,177	187	84.1%	48,847	7,605	84.4%
ALB	88.5%	7	1	85.7%	54	4	92.6%	2,304	179	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	35	4	88.6%	1,501	162	89.2%
BOS	85.5%	18	1	94.4%	124	7	94.4%	5,287	611	88.4%
BRK	92.5%	5	0	100.0%	35	1	97.1%	1,487	103	93.1%
BTN	82.0%	1	0	100.0%	7	0	100.0%	297	41	86.2%
CLT	91.5%	5	0	100.0%	35	4	88.6%	1,512	154	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	-	-	-	11	0	100.0%	604	57	90.6%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	2	84.6%	79	13	83.5%	3,443	561	83.7%
HFD	-	2	1	50.0%	10	3	70.0%	201	18	91.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	7	0	100.0%	307	38	87.6%
MIA	89.5%	2	1	50.0%	14	2	85.7%	614	70	88.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/07/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	316	66	79.1%	2,148	363	83.1%	93,020	12,907	86.1%
East Division	82.0%	174	36	79.3%	1,177	187	84.1%	48,847	7,605	84.4%
MTR	79.0%	1	1	0.0%	7	2	71.4%	294	54	81.6%
NFK	84.5%	2	1	50.0%	14	3	78.6%	697	126	81.9%
NFL	93.5%	2	0	100.0%	14	0	100.0%	626	29	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	6	3	50.0%	35	6	82.9%	1,589	259	83.7%
NPN	93.0%	2	1	50.0%	14	3	78.6%	586	44	92.5%
NYP	75.5%	49	12	75.5%	328	79	75.9%	12,812	2,857	77.7%
PGH	93.0%	1	0	100.0%	7	1	85.7%	308	23	92.5%
PHL	48.0%	5	1	80.0%	33	16	51.5%	1,583	756	52.2%
PIT	76.0%	1	1	0.0%	2	2	0.0%	17	14	17.6%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	0	100.0%	20	0	100.0%	1,178	49	95.8%
RNK	83.5%	2	0	100.0%	14	0	100.0%	610	87	85.7%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	-	-	-	6	0	100.0%	293	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	7	0	100.0%	304	10	96.7%
SFA	88.0%	1	0	100.0%	7	0	100.0%	307	41	86.6%
SPG	92.5%	6	1	83.3%	40	2	95.0%	1,847	107	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	7	1	85.7%	296	61	79.4%
WAS	84.0%	31	8	74.2%	203	34	83.3%	7,675	1,001	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	87	22	74.7%	590	127	78.5%	26,436	3,687	86.1%
ARN	92.0%	1	0	100.0%	7	0	100.0%	309	26	91.6%
BFD	79.0%	7	2	71.4%	48	12	75.0%	1,945	405	79.2%
EMY	72.0%	1	0	100.0%	7	1	85.7%	325	95	70.8%
EUG	86.5%	2	0	100.0%	14	0	100.0%	612	56	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	21	7	66.7%	930	150	83.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	72	8	88.9%	3,071	334	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	8	38.5%	81	35	56.8%	3,342	863	74.2%
PDX	86.0%	3	3	0.0%	22	15	31.8%	1,510	196	87.0%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/07/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/07/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	316	66	79.1%	2,148	363	83.1%	93,020	12,907	86.1%
West Division	86.0%	87	22	74.7%	590	127	78.5%	26,436	3,687	86.1%
SAC	88.5%	16	4	75.0%	102	12	88.2%	4,368	474	89.1%
SAN	90.5%	13	2	84.6%	90	9	90.0%	3,731	353	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	0	100.0%	32	15	53.1%	2,417	362	85.0%
SJC	89.0%	7	0	100.0%	48	4	91.7%	2,172	213	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	21	3	85.7%	693	68	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	14	0	100.0%	605	14	97.7%
VAN	-	1	0	100.0%	5	3	40.0%	5	3	40.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	186	3	0	100.0%	131	9	93.1%	2	2	0.0%	131	33	74.8%
2	No OS	3	3	0.0%	132	34	74.2%	3	1	66.7%	127	25	80.3%
3	78	7	2	71.4%	309	61	80.3%	7	5	28.6%	307	141	54.1%
4	130	7	0	100.0%	308	46	85.1%	7	5	28.6%	308	204	33.8%
5	86	7	1	85.7%	307	51	83.4%	7	7	0.0%	303	95	68.6%
6	49	7	1	85.7%	306	86	71.9%	7	6	14.3%	306	109	64.4%
7		7	3	57.1%	298	45	84.9%	6	4	33.3%	289	78	73.0%
8	272	7	6	14.3%	298	135	54.7%	7	6	14.3%	297	181	39.1%
11	53	7	5	28.6%	309	62	79.9%	7	2	71.4%	303	62	79.5%
14	88	7	2	71.4%	310	51	83.5%	6	6	0.0%	307	98	68.1%
19		7	1	85.7%	308	78	74.7%	7	0	100.0%	305	71	76.7%
20		7	0	100.0%	308	23	92.5%	7	1	85.7%	308	59	80.8%
21		7	3	57.1%	305	28	90.8%	7	3	57.1%	304	85	72.0%
22	40	7	2	71.4%	306	33	89.2%	7	2	71.4%	304	83	72.7%
23		7	0	100.0%	310	6	98.1%	7	2	71.4%	308	87	71.8%
24		7	0	100.0%	310	16	94.8%	7	3	57.1%	309	59	80.9%
25	Cncld	7	0	100.0%	309	3	99.0%	6	3	50.0%	306	86	71.9%
26	Cncld	7	0	100.0%	309	5	98.4%	6	1	83.3%	306	61	80.1%
27	Cncld	3	3	0.0%	288	19	93.4%	2	2	0.0%	283	95	66.4%
40	88	7	2	71.4%	303	43	85.8%	7	3	57.1%	300	158	47.3%
41	201	7	3	57.1%	302	117	61.3%	7	6	14.3%	300	230	23.3%
42		7	1	85.7%	310	25	91.9%	7	2	71.4%	308	54	82.5%
43		7	0	100.0%	309	42	86.4%	7	0	100.0%	308	70	77.3%
48	105	7	2	71.4%	308	59	80.8%	7	1	85.7%	307	43	86.0%
49		7	3	57.1%	308	78	74.7%	7	2	71.4%	308	64	79.2%
52		7	0	100.0%	307	41	86.6%	7	0	100.0%	306	72	76.5%
53	93	7	0	100.0%	307	38	87.6%	7	3	57.1%	306	98	68.0%
55	35	5	1	80.0%	195	8	95.9%	5	2	60.0%	192	40	79.2%
56		5	2	60.0%	196	25	87.2%	5	3	40.0%	192	37	80.7%
58	309	7	0	100.0%	284	16	94.4%	6	6	0.0%	282	79	72.0%
59		7	6	14.3%	282	39	86.2%	7	5	28.6%	278	62	77.7%
63	64	7	4	42.9%	311	136	56.3%	7	7	0.0%	305	173	43.3%
64		7	1	85.7%	309	69	77.7%	7	5	28.6%	308	114	63.0%
66	36	7	0	100.0%	308	61	80.2%	7	2	71.4%	304	56	81.6%
67	25	5	1	80.0%	213	14	93.4%	5	2	60.0%	213	38	82.2%
68	31	7	2	71.4%	311	63	79.7%	7	3	57.1%	310	121	61.0%
69	52	7	5	28.6%	298	73	75.5%	7	4	42.9%	293	47	84.0%
71		7	0	100.0%	306	3	99.0%	6	0	100.0%	304	81	73.4%
72		7	2	71.4%	302	33	89.1%	6	2	66.7%	300	63	79.0%
73		7	0	100.0%	305	19	93.8%	7	1	85.7%	303	143	52.8%
74		7	0	100.0%	303	33	89.1%	7	2	71.4%	301	110	63.5%
75	33	7	0	100.0%	299	16	94.6%	7	1	85.7%	293	138	52.9%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		7	0	100.0%	299	29	90.3%	7	3	57.1%	290	120	58.6%
77		7	0	100.0%	301	20	93.4%	7	2	71.4%	299	125	58.2%
78	30	7	0	100.0%	305	25	91.8%	7	2	71.4%	304	65	78.6%
79	63	7	1	85.7%	308	57	81.5%	7	2	71.4%	307	103	66.4%
80	68	7	2	71.4%	308	35	88.6%	7	4	42.9%	305	67	78.0%
84	Cncld	5	2	60.0%	186	16	91.4%	4	2	50.0%	183	45	75.4%
85		5	0	100.0%	197	16	91.9%	5	0	100.0%	197	70	64.5%
86	27	5	0	100.0%	197	15	92.4%	5	4	20.0%	196	119	39.3%
89	60	7	3	57.1%	306	68	77.8%	7	4	42.9%	304	89	70.7%
90	33	7	0	100.0%	306	10	96.7%	7	3	57.1%	305	54	82.3%
93	25	5	0	100.0%	196	19	90.3%	5	3	40.0%	195	50	74.4%
94	36	5	1	80.0%	227	56	75.3%	5	2	60.0%	225	85	62.2%
95	29	5	0	100.0%	196	4	98.0%	5	4	20.0%	196	73	62.8%
97	39	7	6	14.3%	308	204	33.8%	7	5	28.6%	306	105	65.7%
98		7	0	100.0%	308	26	91.6%	7	5	28.6%	306	113	63.1%
110		5	0	100.0%	193	102	47.2%	5	0	100.0%	190	19	90.0%
111		5	0	100.0%	187	35	81.3%	5	0	100.0%	185	21	88.6%
112		5	1	80.0%	187	19	89.8%	5	0	100.0%	186	19	89.8%
113		5	3	40.0%	118	28	76.3%	5	0	100.0%	117	14	88.0%
119		5	1	80.0%	184	46	75.0%	5	1	80.0%	182	23	87.4%
125	34	5	0	100.0%	197	11	94.4%	5	2	60.0%	197	76	61.4%
129		5	2	60.0%	196	49	75.0%	5	1	80.0%	196	29	85.2%
130		5	0	100.0%	187	18	90.4%	5	0	100.0%	185	16	91.4%
131		5	1	80.0%	189	54	71.4%	5	0	100.0%	189	35	81.5%
134		5	2	60.0%	197	29	85.3%	5	2	60.0%	196	38	80.6%
136		5	0	100.0%	197	24	87.8%	6	1	83.3%	196	26	86.7%
136		5	0	100.0%	197	24	87.8%	6	1	83.3%	196	26	86.7%
137	32	5	1	80.0%	194	36	81.4%	5	2	60.0%	194	60	69.1%
138	51	5	0	100.0%	197	39	80.2%	5	2	60.0%	196	36	81.6%
141		5	0	100.0%	196	3	98.5%	5	2	60.0%	195	35	82.1%
148	21	5	1	80.0%	196	21	89.3%	5	1	80.0%	194	37	80.9%
151		7	3	57.1%	307	98	68.1%	7	0	100.0%	306	95	69.0%
170		5	0	100.0%	192	12	93.8%	5	0	100.0%	191	29	84.8%
171	110	5	0	100.0%	197	11	94.4%	5	4	20.0%	197	79	59.9%
172	34	5	1	80.0%	196	16	91.8%	5	3	40.0%	194	65	66.5%
173	104	5	1	80.0%	189	25	86.8%	5	4	20.0%	188	82	56.4%
174	27	5	1	80.0%	197	21	89.3%	5	3	40.0%	197	51	74.1%
175	82	5	0	100.0%	197	22	88.8%	5	2	60.0%	197	64	67.5%
176	31	5	1	80.0%	189	16	91.5%	5	2	60.0%	187	26	86.1%
177		5	0	100.0%	197	27	86.3%	5	0	100.0%	197	46	76.6%
178	32	5	0	100.0%	197	26	86.8%	5	1	80.0%	195	32	83.6%
179		5	1	80.0%	197	24	87.8%	5	1	80.0%	196	71	63.8%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181	Cncld	5	2	60.0%	193	61	68.4%	4	1	75.0%	190	16	91.6%
182		5	0	100.0%	187	30	84.0%	5	0	100.0%	185	21	88.6%
183		5	3	40.0%	196	59	69.9%	5	2	60.0%	193	40	79.3%
184		5	2	60.0%	197	35	82.2%	5	1	80.0%	196	28	85.7%
185		5	0	100.0%	197	37	81.2%	5	0	100.0%	197	14	92.9%
186	16	5	3	40.0%	196	24	87.8%	5	3	40.0%	195	56	71.3%
190		5	2	60.0%	196	71	63.8%	5	1	80.0%	195	44	77.4%
192		5	0	100.0%	194	24	87.6%	5	1	80.0%	194	18	90.7%
196	40	5	0	100.0%	193	20	89.6%	4	1	75.0%	191	16	91.6%
197		5	1	80.0%	197	76	61.4%	5	2	60.0%	197	69	65.0%
198		5	0	100.0%	129	17	86.8%	5	0	100.0%	128	21	83.6%
230		7	0	100.0%	144	4	97.2%	7	0	100.0%	144	7	95.1%
232		7	0	100.0%	310	11	96.5%	7	1	85.7%	310	22	92.9%
234		7	0	100.0%	311	22	92.9%	7	0	100.0%	310	25	91.9%
235		7	3	57.1%	235	37	84.3%	7	1	85.7%	234	53	77.4%
236		7	0	100.0%	295	10	96.6%	7	2	71.4%	294	41	86.1%
237		7	0	100.0%	308	56	81.8%	7	1	85.7%	306	52	83.0%
238		7	3	57.1%	235	23	90.2%	7	1	85.7%	233	19	91.8%
239		7	0	100.0%	309	79	74.4%	7	0	100.0%	308	38	87.7%
240		7	0	100.0%	310	21	93.2%	7	2	71.4%	307	62	79.8%
241	31	7	1	85.7%	310	75	75.8%	7	3	57.1%	310	74	76.1%
243		7	2	71.4%	246	67	72.8%	7	2	71.4%	245	35	85.7%
245		7	1	85.7%	191	34	82.2%	7	2	71.4%	190	24	87.4%
280	17	7	0	100.0%	311	15	95.2%	7	2	71.4%	310	63	79.7%
281	24	7	0	100.0%	311	37	88.1%	7	1	85.7%	311	58	81.4%
283	36	7	3	57.1%	311	77	75.2%	7	2	71.4%	311	63	79.7%
284	19	7	0	100.0%	311	13	95.8%	7	1	85.7%	308	55	82.1%
290		7	0	100.0%	311	50	83.9%	7	4	42.9%	308	118	61.7%
291	44	7	5	28.6%	310	98	68.4%	7	3	57.1%	308	79	74.4%
300		6	1	83.3%	294	21	92.9%	6	1	83.3%	292	69	76.4%
301	24	7	0	100.0%	308	10	96.8%	7	2	71.4%	304	57	81.3%
302	52	6	0	100.0%	289	33	88.6%	6	1	83.3%	285	79	72.3%
305		6	0	100.0%	292	28	90.4%	6	0	100.0%	288	115	60.1%
306	22	7	1	85.7%	306	17	94.4%	7	2	71.4%	305	84	72.5%
307	38	7	1	85.7%	299	39	87.0%	6	2	66.7%	295	84	71.5%
311		7	1	85.7%	304	27	91.1%	7	2	71.4%	298	65	78.2%
316		7	2	71.4%	300	20	93.3%	7	4	42.9%	295	82	72.2%
318		7	0	100.0%	309	31	90.0%	7	4	42.9%	306	148	51.6%
319	32	7	0	100.0%	310	20	93.5%	7	6	14.3%	305	171	43.9%
329		5	0	100.0%	220	9	95.9%	5	0	100.0%	220	15	93.2%
330		6	0	100.0%	264	6	97.7%	6	0	100.0%	264	15	94.3%
331		7	0	100.0%	311	33	89.4%	7	0	100.0%	311	44	85.9%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		6	0	100.0%	310	17	94.5%	6	0	100.0%	310	43	86.1%
334		7	0	100.0%	311	10	96.8%	7	0	100.0%	310	40	87.1%
335	21	7	0	100.0%	311	34	89.1%	7	2	71.4%	309	53	82.8%
336		7	0	100.0%	311	10	96.8%	7	0	100.0%	309	28	90.9%
337		7	0	100.0%	311	18	94.2%	7	1	85.7%	307	37	87.9%
338	15	7	2	71.4%	311	49	84.2%	7	4	42.9%	309	98	68.3%
339		7	2	71.4%	311	52	83.3%	7	1	85.7%	311	54	82.6%
341	14	6	2	66.7%	298	46	84.6%	6	2	66.7%	292	43	85.3%
342		7	1	85.7%	311	25	92.0%	7	0	100.0%	309	60	80.6%
350		7	0	100.0%	288	18	93.8%	7	5	28.6%	281	156	44.5%
352		6	1	83.3%	277	22	92.1%	6	3	50.0%	271	84	69.0%
353		7	0	100.0%	249	13	94.8%	7	1	85.7%	243	39	84.0%
354		7	0	100.0%	292	35	88.0%	7	6	14.3%	285	107	62.5%
355	21	7	1	85.7%	301	32	89.4%	7	6	14.3%	294	105	64.3%
364	30	7	3	57.1%	300	68	77.3%	7	4	42.9%	294	111	62.2%
365		7	1	85.7%	299	12	96.0%	6	3	50.0%	296	112	62.2%
371		6	0	100.0%	294	8	97.3%	6	0	100.0%	293	29	90.1%
380		4	1	75.0%	293	28	90.4%	3	0	100.0%	292	63	78.4%
381	23	7	0	100.0%	309	12	96.1%	7	3	57.1%	308	63	79.5%
382	33	7	0	100.0%	308	27	91.2%	7	5	28.6%	308	105	65.9%
383	22	5	0	100.0%	298	26	91.3%	5	5	0.0%	295	128	56.6%
390		7	2	71.4%	293	21	92.8%	7	4	42.9%	292	77	73.6%
391	19	7	1	85.7%	294	12	95.9%	7	5	28.6%	290	81	72.1%
392		7	0	100.0%	307	10	96.7%	7	2	71.4%	304	92	69.7%
393		7	0	100.0%	311	18	94.2%	7	3	57.1%	308	94	69.5%
417		5	1	80.0%	207	45	78.3%	5	1	80.0%	198	23	88.4%
448		7	1	85.7%	241	44	81.7%	7	2	71.4%	238	82	65.5%
449	49	7	0	100.0%	238	32	86.6%	7	2	71.4%	238	44	81.5%
470		5	0	100.0%	220	37	83.2%	5	0	100.0%	214	24	88.8%
471		5	2	60.0%	210	13	93.8%	5	0	100.0%	210	5	97.6%
473		5	0	100.0%	216	15	93.1%	5	0	100.0%	213	10	95.3%
474	52	5	0	100.0%	214	63	70.6%	5	3	40.0%	199	66	66.8%
475		5	0	100.0%	214	6	97.2%	5	0	100.0%	214	15	93.0%
478		5	1	80.0%	208	33	84.1%	5	0	100.0%	206	27	86.9%
479	51	5	1	80.0%	215	35	83.7%	5	1	80.0%	213	32	85.0%
486	28	5	2	60.0%	219	33	84.9%	5	2	60.0%	213	60	71.8%
494	43	5	1	80.0%	221	42	81.0%	5	1	80.0%	214	58	72.9%
495		5	0	100.0%	204	4	98.0%	5	0	100.0%	202	3	98.5%
503	46	7	5	28.6%	307	32	89.6%	7	5	28.6%	300	92	69.3%
504		7	0	100.0%	311	19	93.9%	7	2	71.4%	309	92	70.2%
506		7	4	42.9%	306	46	85.0%	5	2	60.0%	298	48	83.9%
507	100	7	5	28.6%	311	41	86.8%	7	6	14.3%	311	106	65.9%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508		7	0	100.0%	306	41	86.6%	7	5	28.6%	302	73	75.8%
516		7	4	42.9%	302	33	89.1%	7	4	42.9%	301	138	54.2%
517	25	7	0	100.0%	311	8	97.4%	7	5	28.6%	307	132	57.0%
518	24	7	4	42.9%	311	41	86.8%	7	7	0.0%	309	214	30.7%
519	35	7	0	100.0%	302	9	97.0%	7	3	57.1%	300	69	77.0%
520		5	2	60.0%	178	27	84.8%	4	0	100.0%	174	9	94.8%
521		5	0	100.0%	216	7	96.8%	5	2	60.0%	216	29	86.6%
522		5	2	60.0%	216	41	81.0%	5	0	100.0%	213	20	90.6%
523		5	1	80.0%	216	8	96.3%	5	1	80.0%	215	23	89.3%
524		4	0	100.0%	215	16	92.6%	4	2	50.0%	212	25	88.2%
525		4	0	100.0%	213	16	92.5%	4	0	100.0%	209	14	93.3%
526		5	2	60.0%	190	36	81.1%	5	1	80.0%	187	16	91.4%
527		5	0	100.0%	216	10	95.4%	5	1	80.0%	215	38	82.3%
528		5	0	100.0%	216	17	92.1%	5	1	80.0%	215	31	85.6%
529	18	5	0	100.0%	216	12	94.4%	5	4	20.0%	215	62	71.2%
530		5	0	100.0%	170	16	90.6%	5	2	60.0%	170	34	80.0%
531		5	0	100.0%	190	13	93.2%	5	0	100.0%	190	13	93.2%
532	13	5	1	80.0%	216	52	75.9%	5	1	80.0%	215	32	85.1%
534		5	1	80.0%	175	26	85.1%	5	0	100.0%	173	16	90.8%
535		5	1	80.0%	203	26	87.2%	5	2	60.0%	198	25	87.4%
536	19	5	3	40.0%	216	58	73.1%	5	1	80.0%	212	39	81.6%
537		4	0	100.0%	185	22	88.1%	4	0	100.0%	179	20	88.8%
538		5	1	80.0%	216	25	88.4%	5	1	80.0%	215	44	79.5%
539		5	1	80.0%	170	25	85.3%	5	3	40.0%	170	74	56.5%
540	Cncld	5	1	80.0%	215	39	81.9%	4	0	100.0%	206	18	91.3%
541		5	1	80.0%	215	23	89.3%	5	1	80.0%	209	37	82.3%
542		5	0	100.0%	215	24	88.8%	5	2	60.0%	212	39	81.6%
543		5	1	80.0%	216	25	88.4%	5	2	60.0%	216	65	69.9%
544		5	1	80.0%	214	21	90.2%	4	0	100.0%	210	20	90.5%
545	17	5	0	100.0%	216	17	92.1%	5	1	80.0%	213	25	88.3%
547	58	5	3	40.0%	216	44	79.6%	5	3	40.0%	216	50	76.9%
548		4	0	100.0%	210	21	90.0%	4	1	75.0%	208	16	92.3%
549	Cncld	5	1	80.0%	211	27	87.2%	4	2	50.0%	202	19	90.6%
550		5	0	100.0%	170	18	89.4%	5	3	40.0%	170	39	77.1%
551		5	0	100.0%	212	22	89.6%	5	1	80.0%	202	21	89.6%
562		7	0	100.0%	302	23	92.4%	7	0	100.0%	298	35	88.3%
564	17	7	0	100.0%	303	19	93.7%	7	2	71.4%	295	40	86.4%
566		7	2	71.4%	301	27	91.0%	7	4	42.9%	298	49	83.6%
567		7	0	100.0%	188	10	94.7%	7	2	71.4%	186	11	94.1%
572		7	0	100.0%	298	24	91.9%	7	1	85.7%	291	84	71.1%
573	24	7	0	100.0%	300	40	86.7%	7	2	71.4%	293	53	81.9%
579		7	1	85.7%	188	12	93.6%	6	2	66.7%	182	39	78.6%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
580	19	7	0	100.0%	303	16	94.7%	7	4	42.9%	296	32	89.2%
581	23	7	2	71.4%	303	52	82.8%	7	4	42.9%	301	68	77.4%
584	54	7	1	85.7%	187	26	86.1%	7	7	0.0%	182	115	36.8%
587	25	7	1	85.7%	296	17	94.3%	7	2	71.4%	287	55	80.8%
588		7	1	85.7%	188	19	89.9%	7	2	71.4%	187	35	81.3%
591		7	1	85.7%	300	22	92.7%	7	2	71.4%	294	41	86.1%
593		6	1	83.3%	296	48	83.8%	6	0	100.0%	275	37	86.5%
595	26	7	1	85.7%	298	54	81.9%	7	2	71.4%	295	62	79.0%
600		5	0	100.0%	224	9	96.0%	5	1	80.0%	222	20	91.0%
601		5	4	20.0%	207	87	58.0%	5	2	60.0%	204	27	86.8%
605		5	4	20.0%	214	134	37.4%	5	0	100.0%	210	22	89.5%
607		5	0	100.0%	223	30	86.5%	5	0	100.0%	220	25	88.6%
609		5	0	100.0%	214	23	89.3%	5	1	80.0%	213	20	90.6%
626		5	2	60.0%	128	18	85.9%	5	0	100.0%	126	18	85.7%
639		5	1	80.0%	194	39	79.9%	5	0	100.0%	193	19	90.2%
640		5	0	100.0%	214	7	96.7%	5	4	20.0%	212	84	60.4%
641		5	1	80.0%	196	39	80.1%	5	1	80.0%	196	27	86.2%
642		5	1	80.0%	212	10	95.3%	5	0	100.0%	211	26	87.7%
643	14	5	0	100.0%	226	44	80.5%	5	2	60.0%	223	38	83.0%
644	17	5	0	100.0%	218	28	87.2%	5	1	80.0%	216	53	75.5%
645	12	5	0	100.0%	226	41	81.9%	5	2	60.0%	223	48	78.5%
646		5	0	100.0%	215	51	76.3%	5	2	60.0%	213	103	51.6%
647		5	0	100.0%	226	32	85.8%	5	0	100.0%	225	49	78.2%
648	11	5	0	100.0%	222	56	74.8%	5	1	80.0%	222	35	84.2%
649		5	1	80.0%	227	43	81.1%	5	0	100.0%	224	34	84.8%
650		5	1	80.0%	226	42	81.4%	5	0	100.0%	223	36	83.9%
651		5	1	80.0%	226	17	92.5%	5	1	80.0%	224	43	80.8%
652		5	2	60.0%	227	31	86.3%	5	1	80.0%	223	38	83.0%
653		5	2	60.0%	215	35	83.7%	5	0	100.0%	212	39	81.6%
654		5	1	80.0%	216	41	81.0%	5	1	80.0%	212	19	91.0%
655		5	1	80.0%	224	73	67.4%	5	1	80.0%	222	74	66.7%
656		5	3	40.0%	226	50	77.9%	5	0	100.0%	225	30	86.7%
657		5	1	80.0%	215	28	87.0%	5	0	100.0%	214	29	86.4%
658		5	0	100.0%	226	35	84.5%	5	0	100.0%	224	33	85.3%
680		5	0	100.0%	221	12	94.6%	5	0	100.0%	220	27	87.7%
681		5	0	100.0%	221	17	92.3%	5	2	60.0%	215	88	59.1%
682		5	0	100.0%	220	6	97.3%	5	1	80.0%	220	39	82.3%
683		5	1	80.0%	203	18	91.1%	5	2	60.0%	202	69	65.8%
684		5	0	100.0%	202	32	84.2%	5	0	100.0%	202	45	77.7%
685		5	0	100.0%	217	31	85.7%	5	0	100.0%	214	53	75.2%
686	14	5	0	100.0%	222	37	83.3%	5	1	80.0%	221	48	78.3%
687	81	5	1	80.0%	221	35	84.2%	5	1	80.0%	220	37	83.2%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
688	12	5	0	100.0%	220	13	94.1%	5	2	60.0%	219	38	82.6%
701		7	0	100.0%	243	25	89.7%	7	0	100.0%	240	25	89.6%
702		7	0	100.0%	310	32	89.7%	7	3	57.1%	307	73	76.2%
703		7	5	28.6%	311	98	68.5%	7	3	57.1%	309	88	71.5%
704		7	2	71.4%	242	39	83.9%	7	2	71.4%	235	48	79.6%
710	41	7	1	85.7%	311	78	74.9%	7	3	57.1%	307	84	72.6%
711		7	0	100.0%	302	34	88.7%	7	4	42.9%	281	56	80.1%
712	76	7	4	42.9%	308	84	72.7%	7	5	28.6%	299	103	65.6%
713	32	6	0	100.0%	178	16	91.0%	4	3	25.0%	160	70	56.3%
714	37	7	6	14.3%	192	81	57.8%	6	6	0.0%	177	82	53.7%
715	30	7	1	85.7%	310	62	80.0%	5	4	20.0%	285	145	49.1%
716	Cncld	7	5	28.6%	311	125	59.8%	6	5	16.7%	304	123	59.5%
717	Cncld	7	2	71.4%	296	70	76.4%	4	3	25.0%	274	89	67.5%
718	181	7	5	28.6%	311	158	49.2%	7	5	28.6%	309	114	63.1%
719		7	4	42.9%	311	107	65.6%	6	3	50.0%	294	87	70.4%
757		7	0	100.0%	96	5	94.8%	7	0	100.0%	95	8	91.6%
761		7	1	85.7%	307	13	95.8%	7	0	100.0%	304	41	86.5%
765		7	0	100.0%	307	25	91.9%	7	1	85.7%	307	43	86.0%
769		7	0	100.0%	307	27	91.2%	7	1	85.7%	301	58	80.7%
770	16	7	1	85.7%	307	23	92.5%	7	4	42.9%	305	93	69.5%
774	16	7	0	100.0%	307	16	94.8%	7	3	57.1%	306	72	76.5%
777	73	7	0	100.0%	192	12	93.8%	7	4	42.9%	191	46	75.9%
782	31	7	6	14.3%	192	88	54.2%	7	3	57.1%	187	28	85.0%
785	25	7	1	85.7%	307	23	92.5%	7	2	71.4%	307	55	82.1%
786	38	7	2	71.4%	96	21	78.1%	6	3	50.0%	92	50	45.7%
790	16	7	0	100.0%	307	28	90.9%	7	1	85.7%	304	47	84.5%
794		7	1	85.7%	307	34	88.9%	7	1	85.7%	303	67	77.9%
821	23	7	0	100.0%	305	6	98.0%	7	7	0.0%	305	128	58.0%
822	12	7	0	100.0%	307	16	94.8%	7	7	0.0%	305	149	51.1%
1233	22	2	1	50.0%	17	5	70.6%	2	2	0.0%	17	10	41.2%
1246	31	2	2	0.0%	17	14	17.6%	2	2	0.0%	17	9	47.1%
1333		7	1	85.7%	307	33	89.3%	7	1	85.7%	304	100	67.1%
1340	28	7	1	85.7%	306	7	97.7%	7	1	85.7%	306	52	83.0%
1689	16	6	0	100.0%	101	5	95.0%	6	1	83.3%	100	12	88.0%
2102		5	1	80.0%	73	14	80.8%	5	0	100.0%	72	6	91.7%
2103		5	0	100.0%	137	12	91.2%	5	1	80.0%	136	10	92.6%
2104		5	0	100.0%	163	10	93.9%	5	0	100.0%	161	12	92.5%
2107		5	0	100.0%	194	34	82.5%	5	1	80.0%	191	21	89.0%
2108	17	5	1	80.0%	194	27	86.1%	5	3	40.0%	188	23	87.8%
2109		5	1	80.0%	87	12	86.2%	5	1	80.0%	85	5	94.1%
2112		5	1	80.0%	34	5	85.3%	5	0	100.0%	32	2	93.8%
2113		5	1	80.0%	73	9	87.7%	5	0	100.0%	73	10	86.3%

Amtrak On Time Performance

Trains Arriving Through: 8/7/2026

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2115		5	1	80.0%	73	12	83.6%	5	0	100.0%	72	10	86.1%
2116		5	0	100.0%	34	1	97.1%	5	0	100.0%	34	7	79.4%
2118		5	1	80.0%	34	3	91.2%	5	1	80.0%	34	10	70.6%
2119		5	2	60.0%	34	6	82.4%	4	1	75.0%	33	11	66.7%
2120	34	5	4	20.0%	34	13	61.8%	4	4	0.0%	32	17	46.9%
2123		5	0	100.0%	72	8	88.9%	5	0	100.0%	71	15	78.9%
2124		4	1	75.0%	165	35	78.8%	4	1	75.0%	163	23	85.9%
2127		5	1	80.0%	34	8	76.5%	5	1	80.0%	33	8	75.8%
2128		5	0	100.0%	34	3	91.2%	5	1	80.0%	34	3	91.2%
2131		5	2	60.0%	34	8	76.5%	5	1	80.0%	34	4	88.2%
2150		5	0	100.0%	187	22	88.2%	5	1	80.0%	184	74	59.8%
2151		5	0	100.0%	136	6	95.6%	5	0	100.0%	134	37	72.4%
2152		5	1	80.0%	92	7	92.4%	5	1	80.0%	91	31	65.9%
2154	23	5	0	100.0%	95	23	75.8%	5	2	60.0%	91	44	51.6%
2155		5	0	100.0%	196	16	91.8%	5	2	60.0%	192	98	49.0%
2158	26	5	1	80.0%	33	5	84.8%	5	2	60.0%	33	14	57.6%
2159		5	1	80.0%	189	15	92.1%	5	3	40.0%	187	62	66.8%
2160	21	5	0	100.0%	34	2	94.1%	5	3	40.0%	33	21	36.4%
2162		5	2	60.0%	195	20	89.7%	5	2	60.0%	189	87	54.0%
2165	27	5	0	100.0%	31	2	93.5%	5	4	20.0%	31	17	45.2%
2167		5	0	100.0%	182	20	89.0%	5	0	100.0%	182	39	78.6%
2171		5	0	100.0%	123	10	91.9%	5	0	100.0%	119	23	80.7%
2190		5	1	80.0%	192	28	85.4%	5	1	80.0%	190	24	87.4%
2193		5	0	100.0%	187	25	86.6%	5	0	100.0%	185	49	73.5%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	17	MTI	12	MTI	12	XNY-BAL	AM	Disabled train ahead, Control Point, ., SINGLE TRACKING ON 1TRK A/C 181 STOPPED ON 2TRK SOUTH OF GROVE WITH NO HEP / BRAKE LIGHT FOR REAR MOTOR FLASHING.
2120	NYP	34	ENG	26	ENG	26	WAS-WAS	AM	Other electrical failure, 2141 NG NP, NEEDING WYE DUE TO PC2141 INOPERABLE BELL
2154	BOS	23	DSR	21	PTI	12	XGX-PVD	AM	Follow, 172, Milepost w/Letters, XGX, XDR, AM2154 followed signals of AM172
2158	BOS	26	OTH	18	ENG	16	NYP-NYP	AM	Unrecoverable penalty (PCS), 2117, FAULTS ON PC2117
2160	BOS	21	DSR	15	ENG	11	NYP-NYP	AM	Unrecoverable penalty (PCS), 2152, FAULTS ON PC2152
2165	WAS	27	DMW	18	DMW	18	NHV-STM	MN	Waiting for MW clearance Milepost, 50.5, 49.1
66	BOS	36	CTI	29	DCS	17	NYP-XSH	AM	Signal suspension, Other, XGG-XPB, TRAFFIC SPLIT AT LEGGETT
67	NPN	25	FTI	32	FTI	27	RVR-RVM	CS	Meet Other, cfp1.8, csx v703
84	NYP	Trn Cancelled							
86	BOS	27	CTI	29	DMW	15	NYP-XSH	LG	Hold for defect repair, Other, XHR, HELD F/AM2159 A/C TRACK WORK AT HAROLD
93	NFK	25	CTI	31	CTI	10	ALX-QAN	CS	Follow VRE, 315, Milepost w/Letters, CFP 105.1, CFP 78.9
94	BOS	36	SMW	23	SMW	12	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD F/AM55 A/C 1 TRK OOS LEGGETT TO MANOR
95	NFK	29	FTI	43	FTI	27	FBG-RVR	CS	Follow IO31, Milepost, 59.3, 5.5
125	NPN	34	WTR	31	CAR	18	WAS-WAS	AM	HEP, 121, MECHANICAL SHORT STAFFED AND WORKING MULTIPLE TRAINS.
137	WAS	32	CTI	20	PTI	15	XPV-BAL	AM	Follow, 2171, Milepost, 71.6, 95.7
138	NYP	51	PTI	93	PTI	22	FBG-QAN	CS	Follow p040, Milepost, 61.1, 78.7
148	NHV	21	CAR	18	CAR	18	PHL-PHL	AM	Heat / AC, 82517 AX AS, MET WITH MECH A/C FAULTY AIR CONDITIONING
171	RNK	110	WTR	102	WTR	102	CLP-CVS	NS	Trees down Milepost, 119, 119
172	BOS	34	HLD	19	PTI	7	PVD-PVD	AM	Follow, 2154, Control Point, PVD, AM172 held to allow AM2154 to pass

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
173	WAS	104	CAR	50	CAR	27	PHL-PHL	AM	Heat / AC, MULTIPLE CARS, MET WITH MECHANICAL A/C HOT CARS #4 AND #8
174	BOS	27	MTI	33	MTI	33	WAS-WAS	AM	Disabled train ahead, Other, .. DISABLED TRAIN 181, TERM IN BAL.
175	WAS	82	SMW	57	SMW	39	XSH-NYP	AM	Scheduled in track usage program, Other, XM9, HELD F/AM176-AM2162-AM178 A/C 1 TRK OOS LEGGETT TO MANOR
176	BOS	31	DSR	20	CTI	14	NYP-XSH	AM	Cross Traffic, MN, MN, Other, XSH
178	BOS	32	DCS	49	DCS	45	BCV-ALX	NS	PTC system failure (wayside) Milepost, 17.8, 17.8
181	WAS	Trn Cancelled	ENG	25	ENG	25	XHM-PHL	AM	Other electrical failure, 637 EX ES, Train experienced a trailing fault on E/637.
186	PHL	16	WTR	28	WTR	9	WBG-RVM	CS	Heat order Other, WBG to RVM
196	NYP	40	SMW	30	SMW	12	WIL-PHL	AM	Scheduled in track usage program, Control Point, LANDLITH TO HOOK, HELD FOR 197 SOUTH. SINGLE TRACKING A/C 55HR OUTAGE - NO 4 TRK OOS; NO 3 TRK ALSO OOS HOOK TO BELL
474	SPG	52	CON	42	CON	42	NHV-NHV	AM	Hold for connecting train, late connection of AM174
479	NHV	51	OTH	36	OTH	36	SPG-SPG	AM	Lost time - N.A.R., Unknown WDI delay.
486	SPG	28	OTH	36	OTH	20	NHV-NHV	AM	Lost time - N.A.R., arrow indicated that AM486 departure time is 310P and the train left on time
494	SPG	43	ITI	34	ITI	34	NHV-NHV	AM	Service, turn, or wye train, 417, turn of AM417
53	SFA	93	FTI	64	DCS	47	XFL-XOU	CS	PTC- I-ETMS Red Fence/Signal Status Unknown Other, BTW North CHS & SY
79	CLT	63	PTI	45	PTI	35	FBG-RVR	CS	Follow Amtk 89, Control Point, Colemans Mill
80	NYP	68	WTR	58	FTI	25	RMT-PTB	CS	Cross Traffic M418, Other, A 74.0
643	HAR	14	CTP	20	CTP	16	PHL-PAO	AM	Delay due to mechanical problems on a Commuter train, Waited for 648 to proceed East a/c disabled Septa at Malvern.
644	NYP	17	PTI	8	DSR	5	TRE-NWK	AM	Per MW foreman, Other, HAM INT, 15, 2
645	HAR	12	OTH	8	OTH	3	EXT-DOW	AM	Lost time - N.A.R., INSUFFICIENT SCHEDULING.

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
648	NYP	11	CTP	18	CTP	18	LNC-PAO	AM	Delay due to mechanical problems on a Commuter train, FOLLOWED BEHIND DISABLED SE 9522; SMOKE SMELL COMING FROM 2ND CAR.
686	BON	14	DMW	9	DMW	6	WOB-BON	MT	Waiting for MW clearance Maintenance workers working on a switch, Control Point, front ladder
687	BRK	81	CTI	70	CTI	66	BON-BON	MT	Trespasser strike Held in north station for a trespasser strike. Ahead of us., keolis, Other, Andover Station
688	BON	12	DCS	9	DCS	9	HHL-WOB	MT	Issue with automatic road crossing protection Protect crossings per Line 12, Other, Essex and Pearson St
1689	BRK	16	WTR	9	WTR	3	POR-FRE	CS	Wet / slippery rail Other, por-fre
63	TWO	64	FTI	15	FTI	13	ROC-BUF	CS	Meet Wait for train crossing to west shore, csx, Control Point, 382
68	NYP	31	WTR	39	WTR	39	SLQ-RSP	CN	Heat order Milepost, 43, 0
69	MTR	52	WTR	49	WTR	49	XLQ-SLQ	CN	Heat order Milepost, 2, 42
241	ALB	31	CTI	34	CTI	22	YNY-CRT	MN	Follow mn, Control Point, 19
280	NYP	17	DSR	25	DSR	16	BUF-ROC	CS	Per MW foreman Milepost w/Letters, QC 385.3, QC 380.0, 25, 1
281	NFL	24	DMW	20	DMW	20	AMS-UCA	CS	Held for or routed around MW work or equipment Track inspector at cp 235, Control Point, 225
283	NFL	36	FTI	29	ITI	19	NYP-NYP	AM	Service, turn, or wye train, 236, LATE F/SSYD TURNED OFF AM236
284	NYP	19	PTI	21	PTI	21	ALB-HUD	AM	Meet 233, Control Point, 124
291	BTN	44	PTI	21	PTI	21	SAR-SAR	DH	Meet 69, Control Point, 37
1233	PIT	22	DSR	17	SVS	15	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
1246	NYP	31	CTI	20	SYS	17	PIT-PIT	CS	Re-crew / job briefing
48	NYP	105	FTI	149	FTI	95	XH6-XPI	NS	Follow Milepost, 502, 482, 5020
449	ALB	49	DMW	36	PTI	30	PIT-XRD	CS	Meet 448, Control Point, 177
75	CLT	33	FTI	32	FTI	27	DNC-BNC	NS	Meet #NSP07, Control Point, Merrill
78	RGH	30	POL	39	POL	39	GRO-BNC	NS	Right of Way police hold
89	SAV	60	FTI	51	FTI	25	DIL-FLO	CS	Meet CSXI031, Control Point, Mars Bluff

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
90	NYP	33	FTI	57	FTI	50	XDJ-ALX	CS	Follow CSX408, Control Point, Dahlgren Jct.
97	MIA	39	DCS	37	DCS	25	KIS-XP8	FR	PTC system failure PTC keeping to restricted departing KIS Amtrak, Permission by S KIS, PTC still keeping to restricted to Poinciana. Permission by the stop signal Poinciana, Other, Kis Amtrak-Poinciana
55	WAS	35	PTI	14	SMW	9	PHL-WIL	AM	Scheduled in track usage program, Control Point, LANDLITH TO HOOK, SINGLE TRACKING A/C 55HR OUTAGE. NO 4 TRK OOS; NO 3 TRK ALSO OOS HOOK TO BELL
40	CHI	88	DSR	67	RTE	13	ORL-ORL	FR	Dispatcher hold Other, Orlando Station
41	MIA	201	FTI	97	CAR	25	CHI-CHI	AM	Dining car removed 68024
25	NOL	Trn Cancelled	FTI	13	FTI	13	PAG-BIX	CS	Meet Take Siding, 602-08, Siding, Orangw Grove
26	MOE	Trn Cancelled	OTH	4	OTH	2	NOL-XEJ	AM	Lost time - N.A.R.
5	EMY	86	DSR	154	DSR	61	GSC-XAC	UP	Per bulletin Milepost, 371.0, 372.0, 25, m, Milepost, 374.25, 376.0, 25, m, Milepost, 375.85, 380.0, 25, m, Milepost, 380.05, 381.9, 25, m, Milepost, 382.15, 383.3, 25, m, Milepost, 384.95, 385.80, 25, m, Milepost, 386.3, 387.45, 25, m, Milepost, 389.95, 391.0, 25, m, Milepost, 387.5, 388.4, 25, m,
6	CHI	49	WTR	153	WTR	46	XMS-WNN	UP	Heat order Milepost, 292, 417
529	SJC	18	PTI	23	PTI	13	FMT-GAC	UP	Meet Amtk530north, Control Point, S Albrae
532	SAC	13	TEN	18	TEN	18	OKJ-OKJ	UP	Set out defective locomotive Removed CDTX 2009 which was on 531 on a test run, CDTX 2009
536	SAC	19	PTI	27	PTI	27	DAV-SAC	UP	Meet Amt 547 surpassed departure time from Sacramento due to mechanical issues. Causing delay., amt547, Control Point, w Sacramento
540	SAC	Trn Cancelled	DCS	5	DCS	3	EMY-BKY	UP	Issue with automatic road crossing protection Xh 4.86 MTZ sub, Milepost, 4.86, 4.86
545	OKJ	17	PTI	21	PTI	21	EMY-OKJ	UP	Meet Amtk 542, Amtk 716, Control Point, NI005
547	SJC	58	TEN	53	TEN	53	SAC-SAC	UP	HEP Loco shut down, equipment swap, JPBX922
549	OKJ	Trn Cancelled							

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
503	EUG		SYS	16	SYS	8	SLM-SLM	UP	Conductor working alone/crew shortage.
507	EUG		DSR	21	FTI	16	SLM-ALY	UP	Meet up5667, Siding, millersburg
517	VAN	25	DCS	21	DCS	14	TAC-XNI	ST	Restrictive signal(s) from unknown cause Stop, Control Point, CP 188
518	VAC	24	DSR	22	MBO	13	XF2-X1J	BN	For maritime traffic Bridge, Fraser
519	SEA	35	FTI	28	DCS	15	EDM-SEA	BN	Restrictive signal(s) from unknown cause Stop, Control Point, 16
58	CHI	309	FTI	305	FTI	247	MCB-BRH	CC	Held @ summit jct for freight to set out car with defective wheel. Control Point, summit jct, cn 3170
11	LAX	24	TRS	93	TRS	93	PDX-XH3	UP	Vehicle on track ahead Stopped at Coalca., Milepost, 745.19, 745.19
14	PDX	88	FTI	61	SYS	36	KFS-CMO	UP	Crew rest Crew rested at 9:15am.
8	CHI	272	FTI	217	CAR	153	SEA-SEA	BN	Set out defective car 31032, 8/32 car had to be set out do to broken spring
27	PDX	Trn Cancelled							
821	FTW	23	DSR	34	DSR	24	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, mt, Milepost, 407.4, 406.7, 60, mt, Milepost, 401, 400.2, 25, mt, Milepost, 396.3, 396.2, 30, mt, Milepost, 389.7, 389, 25, mt, Milepost, 385.5, 385.3, 30, mt, Milepost, 383.6, 383.4, 30, mt, Milepost, 383.1, 382.7, 50, mt, Milepost, 357.6, 357.3, 29, m2, Mil
822	OKC	12	DSR	24	DSR	19	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 353.7, 354.1, 30, 2, Milepost, 357.3, 357.6, 29, 2, Milepost, 364.7, 365.1, 45, 1, Milepost, 383.4, 383.6, 30, M, Milepost, 385.3, 385.5, 30, M, Milepost, 389, 389.7, 25, M, Milepost, 396.2, 396.3, 30, M, Milepost, 40
335	MKE	21	DMW	20	DMW	20	XWA-GLN	ME	Held for or routed around MW work or equipment Stopped at A5 while work was being completed., Control Point, A5
338	CHI	15	ITI	10	ITI	10	MKE-MKE	CP	Service, turn, or wye train 335
341	MKE	14	CTI	15	CTI	10	GLN-XRO	ME	Follow Metra, 2151, Control Point, XWA
355	CHI	21	FTI	31	FTI	15	TRM-ROY	CC	Blocked from station track Freight train making clearing up on one track to pick up passengers from track two, Milepost, 13.5, 13.5, 116

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
364	PTH	30	TRS	35	TRS	35	LPE-PTH	CC	Vehicle on track ahead Stop for car on Track at 331.54 mp Griswald Strret Amtrak was behind CN Eng 2796, Control Point, W. Tapon
564	SAN	17	DSR	12	CTI	11	SOL-OLT	SN	Meet coaster, Control Point, scripps
573	LAX	24	ADA	19	ADA	12	ANA-ANA	SC	Vision / hearing-impaired Assisted blind pax with mobility impairment to ANA station - no station agent present for meet and assist. Frederick Chambers PNR BBAA73
580	SAN	19	RTE	12	RTE	12	X98-OSD	SN	Line manual or spring switch Control Point, mesa
581	LAX	23	CTI	16	CTI	11	SOL-OSD	SN	Meet Stop signal at Swami, Coaster, 640, Control Point, swami
584	SAN	54	PTI	31	PTI	25	XRJ-FUL	BN	Follow 4, Control Point, east Norwalk, Control Point, basta
587	LAX	25	DCS	29	DCS	26	OSD-X98	SC	Power switch failure Control Point, Mesa
595	LAX	26	ITI	12	ITI	12	SAN-SAN	SN	Service, turn, or wye train 584, LATE 584 turn to 595
770	SAN	16	PTI	22	PTI	9	SOL-SOL	SN	Meet Amtk 770, Control Point, Valley
774	SAN	16	PTI	24	PTI	17	SNC-SNP	SC	Meet 777, Control Point, Serra
777	SLO	73	CTI	45	PTI	24	GTA-X3G	UP	Meet AMTK 11, Control Point, CPCO356
782	SAN	31	PTI	24	RTE	19	X98-OSD	SN	Line manual or spring switch HAD TO LINE MESA BY HAND, Control Point, MESA
785	GTA	25	PTI	29	PTI	21	OSD-OSD	SN	Meet 580, Control Point, shell
786	SAN	38	PTI	47	PTI	28	MPK-SIM	SC	Meet 777, Siding, Strathern
790	SAN	16	PTI	27	PTI	11	VEC-OXN	UP	Wait for station track 777, Control Point, South Ventura
710	BFD	41	TEN	33	TEN	29	MDR-MDR	BN	Loading problem Door issues on CDTX 8312. Doors on both Cab and Engine Cutout. No load. Switched out MU cable sides from fireman side to engineer side. Seems to have rectified issue., C2005
712	BFD	76	TSV	71	TSV	71	OKJ-OKJ	UP	Water, commissary, toilet/trash dumping
713	OKJ	32	PTI	39	PTI	14	SKN-ACA	BN	Wait for station track 714, Control Point, W SANDO
714	BFD	37	ITI	41	ITI	41	OKJ-OKJ	UP	Service, turn, or wye train 711
715	OKJ	30	PTI	37	PTI	14	HNF-FNO	BN	Meet amtrak 710, Control Point, calwa crossing

Amtrak Endpoint OTP Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/7/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
716	BFD	Trn Cancelled	TSV	187	TSV	187	OKJ-OKJ	UP	Planned set out / pick out of locomotives, cars or section of train Add Hold locomotive and venture car repairs
717	OKJ	Trn Cancelled	ADA	12	PTI	7	HNF-FNO	BN	Wait for station track 712, Other, FNO
718	BFD	181	TSV	200	TSV	200	OKJ-OKJ	UP	Wait for equipment
3	LAX	78	DSR	105	PTI	36	FLG-KNG	BN	Meet AMTK 4, Control Point, West Berry
4	CHI	130	DCS	69	DCS	69	LMR-GCK	BN	Restrictive signal(s) from unknown cause Wait for 5min ESS SUTTON (No answer from DS), inspect HW Bridges MP 433.6, 433.0 & 425.2., 4428-Appr Med, 4408 & W Sutton-Appr, E Sutton- Stop, 4342/4416/4294/4272- Restr, 4248- Dark (Restr), 4227- Clear, Milepost, 443.0, 422.6
1	LAX	186	FTI	131	SVS	88	SAS-SAS	UP	Cracked knuckles between car #33037 and car # 31041. Mechanical replaced knuckles on both cars.
2	NOL	No OS Rpt	CON	181	CON	181	LAX-LAX	SC	Hold for connecting train 11
22	CHI	40	FTI	193	FTI	109	MHL-MHL	UP	Freight train disabled in Woodlawn up 5680, Other, mhl
301	STL	24	PTI	23	FTI	14	XQT-STL	TR	Meet N/A, Control Point, N Approach
302	CHI	52	SYS	44	FTI	26	BNL-PON	UP	Meet UP 5857, Siding, Ballard
306	CHI	22	PTI	44	PTI	22	LCN-BNL	UP	Meet Shuffle, Amt 305, Siding, McLean
307	STL	38	PTI	34	PTI	18	DWT-PON	UP	Meet Amt 318, Siding, Odell
381	QCY	23	DSR	16	CAR	14	KEE-GBB	BN	Electrical failure ID4124, Car shut down and then recycled before coming back online
382	CHI	33	FTI	23	FTI	23	QCY-MAC	BN	Cross over or go around bnsf 4881, Siding, augusta
383	QCY	22	DSR	20	CTI	9	XUA-LAG	BN	Follow metra, Control Point, Congress Park
391	CDL	19	ADA	12	PTI	11	RTL-CHM	CC	Meet Three way meet, amtrak 390, Other, yard champagne
319	KCY	32	DSR	29	FTI	10	JOL-DWT	UP	Meet unknown, Control Point, X073
1340	CHI	28	CTI	25	CTI	25	GLN-XWA	ME	Follow Metra, 2150, Control Point, XWA

Amtrak Initial Terminal Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/7/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	238	08/07	14	14	Mechanical had to come and clear a penalty to leave the shop 704
BON	687	08/07	66	66	Trespasser strike Held in north station for a trespasser strike. Ahead of us., keolis, Other, Andover Station
BOS	173	08/07	23	23	Set out defective car, 81538 AX AN, LATE RELEASE FROM YARD ACCOUNT SHOPPED 2 COACH CARS 81538/82669
HAR	650	08/07	3	3	Door, 82701 AX AS
HAR	656	08/07	1	1	Passenger and/or baggage
HFD	471	08/07	5	5	Service, turn, or wye train, 426
MIA	40	08/07	1	1	Mechanical fixing doors in diner or lounge Control Point, MIA?
MTR	68	08/07	2	2	Late release Via top Other, MTR
NFK	94	08/07	2	2	For maritime traffic Bridge, 5
NHV	55	08/07	23		
NHV	486	08/07	20	20	Lost time - N.A.R., arrow indicated that AM486 departure time is 310P and the train left on time
NHV	494	08/07	34	34	Service, turn, or wye train, 417, turn of AM417
NPN	186	08/07	8	8	Hold for thruway bus Per Dean at CNOC.
NYP	63	08/07	2	2	Passenger and/or baggage, LOADING
NYP	69	08/07	4	4	Passenger and/or baggage, HEAVY LOADING
NYP	89	08/07	17	17	Routine inspections, LATE RELEASE BY MECHANICAL
NYP	97	08/07	10	10	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	113	08/07	3	3	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	283	08/07	19	19	Service, turn, or wye train, 236, LATE F/SSYD TURNED OFF AM236
NYP	291	08/07	11	11	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	639	08/07	3	3	Passenger and/or baggage, LOADING
NYP	649	08/07	3	3	Passenger and/or baggage, LOADING
NYP	657	08/07	2	2	Passenger and/or baggage, LOADING
NYP	1233	08/07	15	15	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	2115	08/07	2	2	Passenger and/or baggage, LOADING
PHL	601	08/07	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PIT	1246	08/07	17	17	Re-crew / job briefing

Amtrak Initial Terminal Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/7/2026

Terminal	Train	Date	Late	Delay	Cause
SPG	479	08/07	36	36	Lost time - N.A.R., Unknown WDI delay.
WAS	84	08/07	(Trn Cxld)		Engine Issue
WAS	112	08/07	2	2	High passenger count, 457 PAX BOARDING
WAS	134	08/07	2	2	Disabled train ahead, Other, ., DISABLED TRAIN 181, EQUIPMENT SWAPPED 113/134
WAS	148	08/07	10	10	Heat order, Other, ., TEMPERATURE RISING CAUSED ISSUES IN HVAC SYSTEM AND REQUIRED ADDITIONAL TROUBLESHOOTING.
WAS	174	08/07	33	33	Disabled train ahead, Other, ., DISABLED TRAIN 181, TERM IN BAL.
WAS	176	08/07	6	6	Alleged crew rules violation, RULE VIOLATION IN IVY CITY.
WAS	2120	08/07	26	26	Other electrical failure, 2141 NG NP, NEEDING WYE DUE TO PC2141 INOPERABLE BELL
WAS	2162	08/07	2	2	Cross over or go around, VRE, VRE309, Bridge, J, ARRIVING VRE309 PREVENTED 2162 DEP.
CHI	3	08/07	54	54	Planned set out / pick out of locomotives, cars or section of train Car 31039, Control Point, Chicago terminal
CHI	7	08/07	40	40	Refrigerators not working properly. 33031
CHI	21	08/07	259	259	Toilet 31023
CHI	59	08/07	15	15	Late bulletins due to Amtrak cause
CHI	341	08/07	3	3	Service, turn, or wye train 1340
MKE	338	08/07	10	10	Service, turn, or wye train 335
MKE	342	08/07	5	5	Door ID4106, Top outside stair would not retract in auto or manual mode
SAS	22	08/07	274	214	Hold for connecting train 2
SAS	22	08/07	274	60	Air / Brake 315
BFD	703	08/07	22	22	Service, turn, or wye train 712
BFD	719	08/07	5	5	Hold for thruway bus
GTA	782	08/07	1	1	Meet 14, Control Point, CO 358
LAX	2	08/07	34	17	Hold for connecting train 11
LAX	2	08/07	34	17	Hold for thruway bus Bus 5710, 5812, and 5712
OKJ	532	08/07	18	18	Set out defective locomotive Removed CDTX 2009 which was on 531 on a test run, CDTX 2009
OKJ	534	08/07	11	11	Air / Brake / Wheel C8806, Air leak on the brake pipe between 8806 and 8020. Issue has been fixed

Amtrak Initial Terminal Details

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/7/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	536	08/07	4	4	Door C8016, Late release of blue flags on equipment and track in yard. This caused a late arrival to jack London . Blue flags dropped on equipment at 235 dropped on 4 track at 244
OKJ	710	08/07	1	1	Meet AMTK 525, Other, Oakland/Jack London Square Station
OKJ	712	08/07	71	71	Water, commissary, toilet/trash dumping
OKJ	714	08/07	41	41	Service, turn, or wye train 711
OKJ	716	08/07	187	187	Planned set out / pick out of locomotives, cars or section of train Add Hold locomotive and venture car repairs
OKJ	718	08/07	40	40	Meet 542, 715, 716, 545, Control Point, north jack london
PDX	11	08/07	8	8	Water, commissary, toilet/trash dumping Re spot train after boarding to water last 3 coaches
PDX	503	08/07	33		
PDX	507	08/07	81		
SAC	539	08/07	1		
SAC	547	08/07	53	53	HEP Loco shut down, equipment swap, JPBX922
SAC	549	08/07	(Trn Cxld)		Third Party Engine Failure
SAC	704	08/07	1	1	Loading problem C2010
SAN	595	08/07	12	12	Service, turn, or wye train 584, LATE 584 turn to 595
SAN	761	08/07	4	4	Engineer delayed on way to work Delay caused by police shutdown for a freeway chase and standoff
SPK	27	08/05	(No OS)		

Eastern Region

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	No Data	No Data	No Data
CDOT	95.0	No Data	No Data	No Data	No Data	2
MARC	95.0	No Data	No Data	No Data	No Data	No Data
SEPTA	95.0	No Data	No Data	No Data	No Data	No Data
NJT-NED	95.0	88.9	94.9	94	323	36
NJT-SED	95.0	No Data	No Data	No Data	No Data	No Data

Operating Highlights

Train 66(07) Philadelphia, PA - Signal

08AUG26: Following an unsuccessful update of the CETC system, a system-wide outage occurred on the PH and PW lines, as well as on portions of the NYP Line between Girard and Holmes. To restore operations, the system was reverted to its previous configuration. As a result of the outage, Trains 66(07) and 65(07) were held in Philadelphia until the system issue was resolved. To support continued operations and ensure reliable control of the affected territory, maintainers were assigned to provide round-the-clock coverage at FRAZER and GLEN interlockings, where they operated the interlockings under local control.

Train	Delay	Comment
66(07)	1'02"	
65(07)	08"	

Train 687(07) Boston, MA - Commuter Train Interference

08AUG26: Train 687(07), operating with engine 96, 5 coaches, and 223 customers, was delayed departing Boston North Station, on MBTA Boston North Terminal District subdivision, due to a MBTA commuter train trespasser strike at Andover station. Train 687(07) held until the scene was released by police and coroner.

Train	Delay	Comment
687(07)	1'06"	

Train 78(07) West of Burlington, NC - Police Related

08AUG26: Train 78(07), operating with engines, NC1893/NC1984, 4 coaches, and 64 customers, was delayed 12 miles west of Burlington, NC, on NS Goldsboro-Greensboro-62NC subdivision, due to a police hold on all tracks for a trespasser. Once the police removed the trespassers they released their hold on the tracks.

Train	Delay	Comment
78(07)	39"	

Train 49(07) East of Amsterdam, NY - Trees on Tracks

07AUG26: Train 49(07), 26-FQI-00674, 00000008702 engine "UNCLASSIFIED" and 9/2/2026 11 coaches, and carrying 187 customers, was stopped east of Amsterdam, NY, on CSX Mohawk subdivision, due to trees obstructing the tracks at MP 177. CSX reported that Maintenance of Way personnel were on scene addressing the obstruction; however, no estimated time of reopening was available at that time. As a result, Train 49(07) remained stopped and held for the route to be cleared.

While the train continued to hold, CSX personnel worked to remove the trees from the tracks and restore safe operating conditions. Once the obstruction was cleared, Train 49(07) was released and resumed its trip. After departing the affected area, the train operated through flood-related speed restrictions for the next 10 miles, proceeding at a reduced speed of 40 MPH.

Train	Delay	Comment
49(07)	2'28"	

Train 66(07) South of Charlottesville, VA - Weather

07AUG26: Train 66(07), operating with engine 316, 5 coaches, and 113 customers was delayed south of Charlottesville, VA, at milepost 120.9 on NS Alexandria-Montview subdivision due to trees that have fallen across the tracks. NS Maintenance of Way (MOW) personnel responded to remove the debris from the tracks. Once MOW was able to clear track 1 train 66 was released and able to proceed.

Train 171(07) was also delayed north of Charlottesville, VA, at milepost 101.8. Once track 1 was open train 171(07) held for 66(07) to clear.

Train	Delay	Comment
66(07)	1'26"	
171(07)	1'42"	

Train 175(07) New Haven, CT - Wet/Slippery Rail

08AUG26: Train 175(07) operating with engine 633. 10 coaches and 558 customers, was delayed operating between New Haven, CT and Stamford, CT, on MNCW New Haven Line, due to wet and slippery rail preventing the train from reaching maximum authorized speed.

Train	Delay	Comment
175(07)	31"	

Train 90(07) South of Alexandria, VA - Freight Train Interference

08AUG26: Train 90(07), operating with engine 326, 8 coaches, and 228 customers, was delayed 44 miles south of Alexandria, VA, on CSX Richmond Fredericksburg subdivision, due to following CSX408 from Control Point Dahlgren Jct to Alexandria station. Once the freight cleared and a route was made available, train 90(07) was able to proceed.

Train	Delay	Comment
90(07)	50"	

Train 2116(06) New York, NY - Engine Failure

07AUG26: Train 2116(06) operating with locomotives 26/FOI-0067100000003702 UNCLASSIFIED 8/2/2026 and powercars 17/16, experienced a pantograph alarm prior to arriving to New York, NY Penn Station. This did not cause any type of delay, however, the train was shopped due to damage found on the pantograph. As a result train 2127(060), which was set to use train set 11 but was instead replaced by next gen trainset 26/Acela 2127(06). This affected multiple Acela turns.

2127(06) short turned for 2118(06)

2120(06) short turned for 2131(06)

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2131(06)	1'27"	

Train 48(06) West of Utica, NY - Signal

07AUG26: Train 48(06) operating with locomotives 93-87, 11 cars and 177 customers onboard was delayed 10 miles west of Utica at MP 248 on the CS Mohawk subdivision due to power switch failure at CP 248 requiring the crew to hand line the switches for their movement. Once the switches were lined and the route was confirmed train 48(06) was authorized to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48(06)	47"	

Train 68(07) South of St-Lambert, QC - Weather

07AUG26: Train 68(07) was delayed on the Cn Rouses Point subdivision south of St. Lambert, QC between MP2 and MP 42 due to heat restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(07)	39"	

Train 173(07) Boston, MA - Initial Terminal Delay - Car Failure

07AUG26: Train 173(07) operating with locomotive 639, 11 cars and 364 customers was delayed at the initial terminal of Boston due to shopping of cars 82669 and 81538 during servicing and inspection requiring replacement resulting in a late release from the yard. After train 173(07) was released the equipment was moved into the station for customer boarding and departed Boston.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
173(07)	23"	

Muttilpe Trains - CFRC PTC Outage - Signal

07AUG26: Multiple Amtrak trains were delayed due to a known PTC outage on the CFRC Orlando subdivision. Trains were granted permission to operate with a maximum authorized speed of 59 MPH due to inoperable PTC over the entire CFRC Orlando subdivision between MP 755 to MP 810.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(07)	58"	
97(06)	37"	
41(05)	48"	

Train 89(08) Philadelphia, PA - Engine Failure

07AUG26: Train 89(07) operating with locomotives 661-667, 100000008702, 611-637 cars and 187 customers was delayed at Philadelphia Station due to a hot journal alarm on locomotive 661 requiring Mechanical to meet the train and troubleshoot. Mechanical inspected the equipment and determined a faulty sensor to be present after validating axle temperatures to consistent throughout the locomotive and within tolerance for operating conditions. After Mechanical completed their inspection the train was released and authorized to proceed with no further restrictions.

Train 89(07) stopped a second time at MP 65.5 Aberdeen Station to allow the crew to inspect the equipment after a second on board hot journal alarm activation. The crew performed a temple stick evaluation and determined there the temperature of the axle was within tolerance allowing the train to continue.

Train 89(07) stopped a third time and CNOC Mechanical authorized them to proceed with a maximum authorized speed of 80 MPH and continue to Washington due to the know sensor failure.

Train	Delay	Comment
89(07)	24"	PHL - Mechanical inspect
89(07)	1'03"	ABE - Crew inspect equipment
89(07)	22"	BAL - Mechanical inspect
89(07)	07"	BAL-WAS - reduced speed
79(07)	35"	Following 89(07) FGB-RVR

Train 181(07) East of Philadelphia, PA - Engine Failure

07AUG26: Train 181(07) operating with locomotives 611-637, 9 cars and 357 customers was delayed east of Philadelphia due to trail locomotive 637 having a parking brake fault. The crew performed a hard reset and were able to clear all faults allowing train 181(07) to proceed to Philadelphia.

Train 181(07) reported a flashing parking brake light on trail motor 637 and would proceed at 50mph for remainder of trip to Washington. The crew brought the train to a stop a second time south of Grove interlocking on the no.2 track to perform a hard reset on motor 637. While performing the hard reset the knife switch handle on motor 637 broke resulting in the train becoming disabled without HEP and were unable to complete the motor reset to restore operations. As a result, train 181(07) was cancelled at its location and the customers were transferred to MARC 525 for travel to Washington. Rescue crew KW908 came out of Odenton and coupled to disabled train 181(07) to move to Washington for repairs.

As a result of the termination of train 181(07), trains 84(07) and 193(07) were both cancelled in their entirety to allow equipment to be moved up in WAS to represent train 174(07) for operation Washington to Boston. Due to the late move up of equipment train 174(07) took an initial terminal delay from Washington.

Trains operating between Washington and Baltimore during the disruption saw routing delays associated with reduced track availability.

Train	Delay	Comment
181(07)	25"	East of Philadelphia
181(07)	Terminate at location	
174(07)	33"	
79(07)	06"	
183(07)	04"	
MARC9525	43"	
2107(07)	10"	
2108(07)	12"	
182(07)	02"	
110(07)	04"	
2103(07)	04"	
607(07)	02"	
474(07)	42"	Hold for Connections from 174(07)

CSX Heat Orders - Weather

07AUG26: CSX has imposed a heat order effective between 4pm and 7pm for the following subdivisions: Baltimore Terminal, Capital, Cumberland, Metropolitan, Old Main Line, Peninsula, RF&P, Richmond Terminal, Nahunta, North End, Sanford, and Savannah.

Train	Delay	Comment
53(07)	24"	
79(07)	31"	
80(07)	58"	
89(07)	54"	
90(07)	29"	
95(07)	20"	
98(07)	28"	
125(07)	24"	
138(07)	3"	
178(07)	3"	
186(07)	20"	

Train 53(06) South of North Charleston, SC - PTC

07AUG26: Train 53(06), operating with engines 360-317, 42 coaches and 464 customers, was delayed 1 mile South of Charleston, NC, due to a PTC red fence causing a signal delay preventing the train from proceeding. Once the red fence was no longer holding the train 53(06) was able to proceed without further delay.

Train	Delay	Comment
53(06)	47"	

Train 93(06) South of Fredericksburg, VA - Freight Train Interference

07AUG26: Train 93(06), operating with engine 132, coaches, and 285 customers, was delayed 25 miles south of Fredericksburg, VA, on CSX Richmond Fredericksburg subdivision, due to following freight train M409 from milepost 340 to milepost 15.2.

Train	Delay	Comment
93(06)	32"	

Train 448(05) East of Pittsfield, MA - Freight Train Interference

07AUG26: Train 448(05), operating with engines 127/98, 5 coaches, 101 customers, was delayed 8 miles east of Pittsfield, MA, on CSX BERKSHIRE QB subdivision due to meeting CSX 425 at control point 140. Once the freight cleared and a route was made available, train 448(05) was able to proceed.

Train 448(05) was further delayed 4 miles west of Worcester, MA, due to the same freight train crew running out of hours of service trying to resolve a PTC issue. Train 448(05) waited until the freight was recrewed and cleared.

Train	Delay	Comment
448(05)	1'02"	W/WOR
448(05)	48"	E/PIT

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

25-F91-00870 00000008702 "UNCLASSIFIED" 1/4/2018

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00671a 00000008702 UNCLASSIFIED 19/2/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train 8/28(06) West of Glasgow, MT - Freight Train Interference

08AUG26: Train 8/28(06) was delayed beginning at Tampico / MP 288.0, on the Burlington Northern Santa Fe Milk River Subdivision, 11 miles west of the Glasgow, MT station, due to meeting BNSF 605. Train was further delayed in sidings at Whatley, Oswego, Kintyre and Blair siding/MP178.8 on the BNSF Glasgow Subdivision, meeting multiple BNSF freights (BNSF 5952, 7995, 7351, 7401, 8238)

Train	Delay	Comment
8/28(06)	1'57"	

Train 14(07) South of Paso Robles, CA - Passenger Train Interference

08AUG26: Train 14(07) was delayed at Templeton/MP218.6 on the UPRR Coast Subdivision, 5.5 miles south of Paso Robles, CA station due to meeting Train 11(06)

Train	Delay	Comment
14(07)	30"	

Train 6(07) East of Reno, NV - Weather

08AUG26: Train 6(07) was delayed beginning 52 miles east of Reno, NV, on the UPRR Nevada Subdivision between MP291 to MP585.8 operating reduced speeds due to heat orders.

Train	Delay	Comment
6(07)	1'12"	

Train 6(06) West of Glenwood Springs, CO - Weather

07AUG26: Train 6(06) was delayed beginning at MP406.5, 43.4 miles west of Glenwood Springs CO station on the UPRR Glenwood Springs subdivision operating through heat orders. Train 6(06) operated through the heat orders until MP375.85.

Train	Delay	Comment
6(06)	30"	

Train 364(07) Port Huron, MI - Trespasser Incident

07AUG26: Train 364(07) was delayed holding at West Tappen/MP329, 10.6 miles west of Port Huron MI station on the CN Flint subdivision due to a vehicle on the tracks at 331.54. A tow truck arrived on scene and removed the vehicle. Train 364(07) was back on the move at 1200AM ET after the track inspector released the tracks.

Train	Delay	Comment
364(07)	35"	

Train 22(07) South of Fort Worth, TX - Freight Train Interference

07AUG26: Train 22(07) was delayed holding at MP325.5, 21.30 miles south of Fort Worth TX on the BNSF Fort Worth subdivision meeting BNSF freight train 3321.. Train 22(07) was back on the move at 717PM CT after the freight cleared.

07AUG26: Train 26(07) ~~26-FOI-00671~~ ~~00000003702~~ "UNCLASSIFIED" ~~07/11, 9/2/2026~~ coaches, and 102 customers, struck a semi truck approximately 6 miles south of Bay Saint Louis, MS station on the CSX NO and M Subdivision at Milepost 760.23. At the time of the incident, there were no reported injuries to the crew or customers, and Head End Power (HEP) remained active. Weather conditions were reported as sunny with a temperature of 82 degrees. Damage was reported to the plow and windows of lead engine 180. The fuel tank of the semi trailer was stuck to the plow of the lead engine. The semi truck illegally crossed a low ground clearance crossing at Clermont Rd./DOT # 340092C and became struck on the tracks. The trailer was loaded and debris were scattered all over the tracks after the strike. The driver of the semi truck was not injured. Train 25(07) stopped at 756.2 and then reversed back to Bay Saint Louis MO station to wait for open tracks.

Two buses were secured to accommodate all passengers from the school to their final destination. First bus was express to Mobile AL and the second bus made all stops from Bay Saint Louis, MS. to Mobile AL. One bus was secured to accommodate train 25(07) from Bay Saint Louis MO station to New Orleans LA station.

WBS#: B.TR.100150.7008

Train	Delay	Comment
25(07)	Term BAS	
26(07)	Term BAS	
23(08)	Cancelled	

07AUG26: Train 5(06) was delayed beginning at MP1.0, 1 mile west of Denver CO station on the UPRR Moffat Tunnel subdivision operating through heat orders. Train 5(06) operated through the heat orders until MP451 on the Glenwood Springs subdivision.

Train	Delay	Comment
5 (06)	1'40"	

Train 540(07) West of Martinez, CA - Third Party Contractor Engine Failure

07AUG26: Train 540(07), CC/C8311-7 cars-E/C2104, was delayed west of Martinez, CA at MP282 on the UPRR Martinez Subdivision. Crew reported the engine lost load and they were without head-end power (HEP). The crew worked with mechanical in order to troubleshoot the issue. Unable to resolve, the decision was made to transfer all passengers to Train 542(07) via a train-to-train transfer and terminate the train. Once passengers were transferred, an Amtrak Road Foreman arrived to troubleshoot the issue further, and determined the train would not be able to proceed on own power and needed to be rescued into Oakland Maintenance Facility for repair.

Train 717(07) was the next train and was to couple to 540's equipment upon arrival. Once coupled to the equipment, there was a delay for reported air issues on E/C2104. Once resolved, the crew was unable to initialize PTC. Due to the lengthy delay, and hours of service concerns, Train 551(07) was held to be routed next to 717(07) and transfer all passengers. Train 717(07) was able to initialize and the plan was cancelled, allowing for 551(07) to proceed ahead. Upon pulling, Train 717(07) went into an undesired emergency brake application. Crew was able to recover and the train proceeded to the next crossing to pick up the relief engineer. Train 717(07) was then terminated at Emeryville, CA in order for the combined train to pull into Oakland Maintenance Facility. All passengers were accommodated on an alternate bus from Emeryville into Oakland.

Train	Delay	Comment
717(07)	2'15"	Coupling to 540 Equip
551(07)	05"	
540(07)	Terminated MP28.2	
549(07)	Cancelled	
542(07)	09"	Rescued 540's pax

Train 547(07) Sacramento, CA - Third Party Contractor Engine Failure

07AUG26: Train 547(07) was delayed departing Sacramento, CA due to a late release from mechanical due to HEP issues on engine E/JPBX922. Train 536(07) was initially held outside the station waiting for 547(07) to depart, however was brought in and utilized to represent 547(07) due to the lengthy delay. Once the passengers were boarded onto the new set of equipment, the train was further delayed unable to log into PTC. Once able to resolve and initialize PTC, Train 547(07) departed Sacramento.

Train	Delay	Comment
547(07)	53"	
536(07)	27"	

Train 710(07) Merced, CA - Third Party Contractor Engine Failure

07AUG26: Train 710(07), CC/C8312-7 cars-E/C2005, was delayed starting at Merced, CA on the BNSF Stockton Subdivision due to door issues on C/C9023 not closing on trainline. The crew was able to resolve issue and departed Merced. Once in Madera, CA, the crew experience loading issues on CC/C8312. The loading issues persisted after cutting out the door on both the cab car and the locomotive. After swapping out the M/U cables, the issue was resolved and Train 710(07) departed Merced.

Train	Delay	Comment
710(07)	02"	MCD
710(07)	29"	MDR

Train 7/27(07) Chicago, IL - Car Failure

07AUG26: Train 7/27(07) ~~26-FOI-00871~~ ~~00000008702~~ ~~UNCLASSIFIED~~ ~~1972/2026~~ departed initial terminal of Chicago IL Union station/MP0.0 due to reefer issues on car 33031. Car 33031 was reported to have reefer issues at 1255PM CT. Mechanical responded, was able to make repairs to the reefer and train 7/27(07) at 258PM CT. Train 7/27(07) arrived to the station at 308PM CT to begin boarding. Train 7/27(07) departed Chicago Union station at 345PM CT with 200 passengers on board.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(07)	40"	

Train 21(07) Chicago, IL - Car Failure

07AUG26: Train 21(07), E/62-E/69-9 Cars, was delayed in Chicago, IL, due to toilet issues in coach car 31023. Chicago Mechanical responded with a replacement vacuum and completed repairs. Once the car was working as intended, Train 21(07) departed Chicago Union Station at 629PM-CT, operating 04 hours and 19 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(07)	4'19"	

Train 2(05) East of San Antonio, TX - Engine Failure

07AUG26: Train 2(05), E/361-E/199-7 Cars and carrying 122 customers, stopped at 1:17PM-CT on the UPRR Glidden Subdivision at MP105.8, approximately 103.7 miles east of San Antonio, TX (MP209.5). The train stopped after lead engine 361 shut down and lost head end power. At 1:30PM-CT, the engine was restarted and HEP was restored. The crew contacted CNOC Mechanical for troubleshooting and determined a defective M/U cable was causing the issue. The crew replaced the cable using a spare on hand, and after repairs were completed, Train 2(05) resumed operation eastbound at 2:12PM-CT.

Train 2(05) was stopped again at MP277.8, 105.8 miles east of Lake Charles station on the UPRR Lafayette subdivision with lead engine 361 shut down. The train lost head end power and contacted CNOC Mechanical to troubleshoot. Crew worked with CNOC Mechanical and were able to remove the MU cables from between the engines and isolate it. After isolating the engine the crew was able to restore head end power and was back on the move at 807PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(05)	58"	
2(05)	43"	E/LCH

Train 3(07) Chicago, IL - Car Failure

07AUG26: Train 3(07), operating with E/22-E/204 and 10 cars, was delayed departing Chicago, IL due to HVAC issues on coach car 31039 while in the yard. After repairs were completed, the equipment was set in the station at 1:41PM-CT to board 238 customers. At 2:24PM-CT, Train 3(07) departed Chicago Union Station operating 54 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(07)	54"	

Gold Runner Service - Equipment Servicing/ Repair Issues

07AUG26: Train 712(07) 26-FOI-00671 00000008702- UNCLASSIFIED 9/2/2026 was delayed departing Oakland, CA due to a late release from mechanical. Equipment arrived into the maintenance facility at 7:28P-PT on August 6th from Train 715(06). With the equipment still not fully serviced, at 10:00A-PT, mechanical estimated another twenty minutes were needed for servicing the equipment. Once equipment was serviced, it departed the maintenance facility at 11:14A-PT en route to Oakland Station for boarding. Once all customers were boarded, Train 712(07) was able to depart at 11:29A-PT.

Train 714(07), E/C2013-8 cars-E/C2014, was delayed departing Oakland, CA due to the late turn of equipment arriving on Train 711(07). The equipment, E/C2012-6 cars-CC/C6962, arrived to the maintenance facility from Train 719(06) at 11:05P-PT on August 6th and was not ready for departure. To avoid a lengthy delay, the inbound Train 711(07) equipment was turned for Train 714(07). Once Train 711(07) arrived into the maintenance facility at 11:30A-PT the equipment was serviced and fueled and it departed at 12:47P-PT for Oakland station for boarding. Once all customers were on board, Train 714(07) departed at 12:59P-PT.

Train 532(07) was delayed departing Oakland, CA due to the congestion in the yard from the Gold Runner service being serviced. Once Train 714(07) cleared yard and worked the Oakland station, the crew on Train 532(07) was able to head to station for boarding.

Train 716(07), CC/C8309-8 cars-E/C2012, was delayed departing Oakland, CA due to a late release from mechanical. At 2:00P-PT, mechanical estimated another thirty minutes were needed for servicing the equipment. The train was released and departed the yard at 500P-PT. After arriving at the station, crew was unable to log into PTC causing further delay. Due to the extended delay, and closing in on the departure time for Train 718, the decision was made to cancel Train 716(07) and deadhead the equipment to Bakersfield. The Union Pacific dispatcher did not receive the information in time and allowed 716(07) to depart Oakland as soon as they were able to initialize PTC. Train 716(07) was then terminated at Emeryville, where all passengers detrained and were accommodated on train 718(07).

Train 718(07) was then delayed departing Oakland, CA due to trains 542, 715, 716 and 545(07) all arriving causing congestion.

Train	Delay	Comment
712(07)	1'11"	
714(07)	41"	
532(07)	18"	yard congestion
716(07)	3'07"	Terminated EMY
716(07)	37"	OKJ- PTC
718(07)	40"	

Train 3(06) West of Dodge City, KS - Signal

07AUG26: Train 3(06) was delayed beginning 36.9 miles west of Dodge City, KS (MP352.5) on the BNSF La Junta Subdivision due to signal issues originating at MP389.4. Operating speeds were restricted through the affected territory until a clear signal was reached at Garden City (MP401.1).

Train	Delay	Comment
3(06)	33"	

Train 4(05) East of Newton, KS - Passenger Train Interference

07AUG26: Train 4(05) was held 15.1 miles east of Newton, KS (MP185.1) on the BNSF La Junta Subdivision in order to meet Train 3(06) at Peabody (MP170.0).

Train 3(05) East of Kingman, AZ - Passenger Train Interference

07AUG26: Train 3(05) was delayed at MP511.3, 132.4 miles east of Kingman, AZ, on the BNSF Seligman Subdivision due to meeting Train 4(06). The crew held until Train 4(06) cleared route then proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(05)	36"	

Train 3(06) West of Newton, KS - Engine Failure

07AUG26: Train 3(06) was delayed at MP58.3, 132.4 miles west of Newton, KS, due to main reservoir issues on lead engine 167. The crew worked with CNOC Mechanical to troubleshoot and repair the issue but was unsuccessful. BNSF Rapid Responders were requested and arrived on scene at 1:37AM-CT. Rapid Responders extracted the threads from the old pop valve but were unable to complete the repair. Kansas City Mechanical arrived on scene at approximately 3:20AM-CT to assist. Repairs to the main reservoir were completed at 2:35AM-CT; however, the crew encountered cab signal issues when attempting to depart. The crew contacted CNOC Mechanical for troubleshooting assistance, and the cab signal issues were resolved at 2:57AM-CT. Train 3(06) resumed movement at 3:14AM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(06)	3'45"	

Train 21(05) Taylor, TX - Freight Train Interference

07AUG26: Train 21(05) was delayed holding at MP914.7, approximately 5.68 miles north of Taylor, TX, on the UPRR Waco Subdivision due to a truck stuck on the tracks at MP918.4. A tow truck responded to the scene but was unable to access the vehicle due to its location on the track. Material was brought to the site and a slope was constructed to provide access for the tow truck. The slope was completed and the truck was removed at 12:34AM-CT. Following inspection, the track was released for service and Train 21(05) resumed movement at 12:46AM-CT. Train 21(05) arrived at Taylor, TX, at 1:10AM-CT and was further delayed awaiting an Amtrak re-crew and a UPRR pilot engineer. Once the re-crew and pilot engineer were on board, Train 21(05) departed southbound at 3:51AM-CT.

Train 22(07)/422(05), E/311-E/315-8 Cars, was delayed departing San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision due to a late turn of equipment and air brake issues. Inbound Train 2/422(05) arrived at San Antonio 3 hours and 41 minutes late, and inbound Train 21(05) arrived 8 hours and 43 minutes late, delaying the availability of equipment for Train 22(07)/422(05). After the equipment moves were completed, additional delay was incurred due to air brake issues on engine 315. San Antonio Mechanical corrected the issue, and Train 22(07)/422(05) departed San Antonio at 11:22AM-CT, operating 4 hours and 34 minutes late. Nine customers onboard Train 22(07)/422(05) missed their connection at Fort Worth to Train 822(07). The misconnected customers were provided two SUVs for transportation to their final destinations.

Train 2(05) was also delayed in San Antonio due to switching moves and departed at 10:58AM-CT, operating 4 hours and 33 minutes late.

WBS#: B.TR.100150.7006

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(05)	5'09"	
21(05)	2'40"	Re-crew TAY
22(07)	4'34"	Late Turn
2(06)	52"	Hold Connections

Train 7/27(06) Browning, MT - Freight Train Interference

08AUG26: Train 7/27(06) was delayed at Browning, MT station/MP1123.9 on the BNSF Hi Line, due to meeting stalled BNSF 7021 ahead at Grizzly/MP1136.1. Once the freight swapped out their power and cleared the route, Train 7/27(06) was able to proceed.

Train 22(07) Austin, TX - Engine Failure

07AUG26: Train 22(07) was delayed at Austin, TX station/MP179.4 on the UPRR Austin subdivision due to engine 315 shutting down. Crew attempted to get engine 315 restarted at Austin but were unsuccessful. Crew proceeded to Fort Worth TX station/mp346.2 operating with a single engine. Crew was met by mechanical and spoke with CNOC mechanical to troubleshoot but could not get engine 315 restarted. Train 22(07) operated single engine to Marith/MP198.6 where they added UPRR freight engine 6761. Train 22(07) was back on the move at 134M CT after adding the freight engine.

Train	Delay	Comment
22(07)	07"	AUS
22(07)	54"	FTW
22(07)		Add Freight

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG:

Pere Marquette:

- Train 370(04, 07, 09, 13, 16, 20) cancelled entirely, with alternate transportation between Chicago, IL and Grand Rapids, MI.
- Train 371(05, 08, 10, 14, 17, 21) cancelled entirely, with alternate transportation between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05, 08) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 300(09) cancelled entirely, with alternate transportation between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with alternate transportation between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with alternate transportation between Pontiac, MI and Chicago, IL.
- Train 350(11, 15, 18) cancelled entirely, with alternate transportation between Chicago and Pontiac, MI.
- Train 355(11, 15, 18) cancelled entirely, with alternate transportation between Pontiac, MI and Chicago, IL.

Quincy Service:

- Train 381(10, 14, 17, 21) cancelled entirely, with alternate transportation between Chicago, IL and Quincy, IL.
- Train 382(10, 14, 17, 21) cancelled entirely, with alternate transportation between Quincy, IL and Chicago IL.

Saluki/Illini Service

- Train 391(12, 19) cancelled entirely, with alternate transportation between Chicago, IL and Carbondale, IL.
- Train 392(12, 19) cancelled entirely, with alternate transportation between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided. 26-FOI-00671 00000008702 "UNCLASSIFIED" 9/2/2026
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04-10) Cancelled entirely, No alternate Transportation.
- Train 502 (04-10) Cancelled entirely. With alternate transportation.
- Train 504 (04-10) Will terminate in Portland, OR. With alternate transportation.
- Train 518 (04-07) Originates at Seattle, WA. 518 (08-10) Originates Vancouver, WA All with alternate transportation.
- Train 517 (04-10) Will terminate in Vancouver, WA. No alternate Transportation.
- Train 506 (04-10) Originates in Vancouver, WA. No alternate Transportation.
- Train 508 (04-10) Will terminate Portland, OR. With alternate transportation.
- Train 503 (04-10) Originates Portland, OR. With alternate transportation.
- Train 505 (04-07) Cancelled entirely. With alternate transportation. 505 (08-10) Will Terminate in Vancouver, WA, no alternate transportation.
- Train 507 (04-10) Originates Portland, OR. With alternate transportation.
- Train 509 (04-10) Cancelled entirely, with alternate transportation.
- Train 511 (04-10) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-08) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-10) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

- Train 14 (04-09) Will Terminate at Portland, OR, no alternate transportation provided.
- Train 11 (05-10) Will Originate at Portland, OR, no alternate transportation provided.

WBS#: B.TR.100150.6981

Train	Delay	Comment
-------	-------	---------

507(02)	1'41"	bus VAN-PDX	
506(02)	Canceled		
508(02)	45"	bus PDX-VAN	
509(02)	77"	couple 509-511(02)	
509(02)	75"	detour through UP yard	26-59400671 00000008702 "UNCLASSIFIED" 9/2/2026
511(02)	76"	Detour through UP yard	
500(03)	Canceled		
502(03)	Canceled		
511(03)	Canceled		
505(03)	Canceled		
518(03)	Canceled	between SEA-PDX	
507(03)	Canceled	between SEA-PDX	
508(03)	Term PDX		
504(03)	Term PDX		
509(03)	Canceled		
517(03)	Term VAN		
506(03)	Orig VAN		
503(03)	24"	canceled SEA-PDX	
507(03)	1'10"	waiting for bus at PDX	
14(02)	58"	detour	
11(03)	51"	detour	
14(04)	term PDX		
506(04)	1'03"	wait for inbound bus	
518(04)	1'27"	wait for inbound bus	
507(05)	1'09"	PDX- wait for inbound bus	
507(06)	1'06"	PDX- inbound bus	
503(07)	33"	PDX- inbound bus	
507(07)	1'21"	PDX- inbound bus	

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26-FOI-00071 00000008702 "UNCLASSIFIED" 9/2/2009

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple trackwork projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
506 (6)	SEA	BNSF5244	E/WS1403 unrecoverable faults	SEA	8/8/26
22 (7)	XMH	UPRR6761	E/315 multiple faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(12)	STL	1	Carried passenger to ALN to wait for Train 21	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008702

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2159 (07)	BOS	Reversed consist due to 2141 DNL. diagram change has been performed.	NO IMPACTED PAX	0	2141
449 (07)	BOS	VIEW 2 SLEEPER IN LIEU OF VIEW 1 SLEEPER	NO IMPACTED PAX	0	62018
3 (07)	CHI	no lower level seating in the 0310 car due to b/o equipment swap. please move affected pax to Y. XY/WY also reduced with no overage.	no impacted pax	0	31039
5 (07)	CHI	0540(07) CAR SCHEDULE CHANGED, SLEEPER IN LIEU OF DORM. CHECK WAR REPORT. REOPEN H-ROOM. BLOCK ALL FS AND DS ROOMS ON THE 0540 CAR.	no impacted pax	0	32047
6 (10)	EMY	0640(10) CAR SCHEDULE CHANGED, SLEEPER IN LIEU OF DORM. CHECK WAR REPORT. REOPEN H-ROOM. BLOCK ALL FS AND DS ROOMS ON THE 0640 CAR.	no impacted pax	0	32047
564 (08)	LAX	Consist changed again. No bike space, no wifi and reduced capacity due to cab 9700. Notify passengers.			90225
40 (07)	MIA	VIEW LINER II IN LIEU OF VIEW LINER I. SCHEDULE CHANGE COMPLETED.	No impact	0	62501
98 (08)	MIA	DUE TO LACK OF EQUIPMENT, 98(08) WILL OPERATE WITH A CAFE/LOUNGE IN LIEU OF A DINER. PLEASE COORDINATE TO ACCOMMODATE SERVICE NEEDS.			28024
284 (07)	NFL	Car 82808 DHD inline byd for HVAC. car 82660 will be added in ALB for ridership.	-26 overcapacity at SYR	26	82808
119 (07)	NYP	biz car 81547 being used in lieu coach	NO IMPACTED PAX	0	81547
113 (07)	NYP	short 1 coach per consist plan.	No impacted pax	0	81520
193 (07)	NYP	short 1 coach per consist plan.	no impacted pax	0	81520

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
11 (07)	PDX	11(07) car 34510 has no hvac - conductor requested it DH due to excessive heat. Y/LY/XY/WY reduced. heavily overcapacity SBA-LAX.			34510
777 (08)	SAN	Consist changed again. No bike space, no wifi and reduced capacity due to cab 90225. Notify passengers.			90225
196 (07)	WAS	biz car 81547 bein used in lieu of coach	no impacted pax	0	81547
130 (07)	WAS	using car 81547 in lieu of coach. no impact to ridership	NO IMPACTED PAX	0	81547
84 (07)	WAS	short 1 coach per consist plan.	NO IMPACTED PAX	0	81520

Reverse Consists

Train Number	Station	Reason
95 (07)	BOS	Consist reversed Business class seat orientation may have changed At Front
158 (08)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 158(08)**
110 (07)	PHL	Consist reversed Business class seat orientation may have changed At Rear
185 (07)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (07)	PHL	Consist reversed Business class seat orientation may have changed At Front
183 (07)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (07)	NYP	Consist reversed Business class seat orientation may have changed At Front
137 (07)	BOS	Consist reversed Business class seat orientation may have changed At Front
179 (07)	BOS	Consist reversed Business class seat orientation may have changed At Front
182 (07)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (07)	NYP	Consist reversed Business class seat orientation may have changed At Front